PETRA
Environmental Division

PHASE I
ENVIRONMENTAL SITE ASSESSMENT

Colton Super Block,
Approximately 353 Acre Site Roughly
Bounded by San Bernardino Avenue,
Riverside Avenue, I-10 Freeway,
and Hermosa Avenue,
City of Colton and City of Rialto,
County of San Bernardino, California

Final Report

Prepared For:

MICHAEL BRANDMAN ASSOCIATES

May 30, 2008
J.N. 149-08

Orange County / Environmental / Corporate

3185-A Airway Avenue
Costa Mesa, California 92626
T: 714 549 8921 F: 714 549 1438

past + present + future
it's in our science
Engineers, Geologists
Environmental Scientists

May 30, 2008
J.N. 149-08

Ms. Nancy Ferguson
MICHAEL BRANDMAN ASSOCIATES
340 South Farrell Drive, Suite A-210
Palm Springs, California 92262

Subject: Phase I Environmental Site Assessment, Colton Super Block, Approximately 353 Acre Site Roughly Bounded by San Bernardino Avenue, Riverside Avenue, I-10 Freeway, and Hermosa Avenue, City of Colton and City of Rialto, County of San Bernardino, California

Dear Ms. Ferguson:

The Environmental Division of Petra Geotechnical, Inc. (Petra) is pleased to present this Phase I Environmental Site Assessment for the above-referenced site. This investigation has been conducted in accordance with our Proposal No. 1088-08, dated February 27, 2008, and in conformance with the scope and limitations of the standards set forth in the American Society for Testing and Materials (ASTM) Practice E 1527-05 and the EPA's All Appropriate Inquiry (AAI) regulations 40 CFR Part 312. This assessment has revealed potential recognized environmental conditions in connection with the subject site.

This opportunity to be of service to you is sincerely appreciated. Please do not hesitate to call this office if you have questions pertaining to this report.

Respectfully submitted,

Petra Geotechnical, Inc.
ENVIRONMENTAL DIVISION

Callie L. Cullum
Project Geologist
REA 7511

Brian Villalobos
Division Manager
CEG 1298

PROFESSIONAL GEOLOGIST
BRIAN A. VILLALOBOS
NO. 1298
CERTIFIED
ENGINEERING
GEOLOGIST
Exp 4/30/10
STATE OF CALIFORNIA

Registered Environmental Assessor I
CALLIE L. CULLUM
REA I 07511
Expires 6/30/09
STATE OF CALIFORNIA

<W:\ENVIRON\2008\149-08\149-08 Phase I report.wpd>

EXECUTIVE SUMMARY

PHASE I ENVIRONMENTAL SITE ASSESSMENT

Colton Super Block,
Approximately 353 Acre Site Roughly Bounded by San Bernardino Avenue, Riverside Avenue, I-10 Freeway, and Hermosa Avenue,
City of Colton and City of Rialto, County of San Bernardino, California

INTRODUCTION

The information presented in this report includes the results of our recent site reconnaissance, a review of pertinent literature, and recent federal, state, and local government agency records. Our field reconnaissance, data gathering and compilation was performed by Ms. Callie L. Cullum, Registered Environmental Assessor, with oversight by Mr. Brian Villalobos, Certified Engineering Geologist. At the client's request, the site structures and most of the site parcels were not entered into and the site reconnaissance was completed as a "drive-by/fence-line" investigation.

SITE DESCRIPTION AND GENERAL INFORMATION

1. The site is an irregular shaped parcel roughly bounded by San Bernardino Avenue to the north, city boundaries between Colton and Rialto to the west, by the I-10 freeway to the south, and by both Pepper Avenue and Hermosa Avenue to the east in the City of Colton, San Bernardino County, California. The subject site is comprised of approximately 353 acres. At the time of our investigation, the site consisted of vacant land, a golf course, residential homes, commercial/retail businesses, office complexes, and what appeared to be light industrial land use.

2. Based on information obtained during this investigation, the site appears to have been used for dry farming/grazing activities, possibly as early as the 1900's. Small groves were present on the southwestern, southeastern, and northeastern portions of the site in the 1930's. The southwestern grove was present until at least the mid-1950's. Morrow Field (a single runway airfield) was constructed on the subject site in 1942. The airfield was abandoned by 1980. The Colton Golf Club and the former Colton Recreational Lake were constructed on the site in the 1960's. The residential structures currently located on the northeastern portion of the site appear to have been present since at least the 1950's. In the 1960's, the far northeast corner of the site appeared to have been used for livestock corrals. Commercial-type structures

began appearing on the site in the 1950's, primarily south of W. Valley Boulevard. By the late-1980's most of the structures present today had been constructed. Historical information dating back to 1901 was reviewed during this investigation.

3. Several pole-mounted and pad-mounted transformers were observed on the site. It is unknown if the transformers contain polychlorinated biphenyls (PCBs).

4. Much of the site was vacant land. Miscellaneous debris was observed and included plastic, metal, wood, concrete, PVC pipes, a boat, tiles, furniture, landscape waste, carpet, dry wall, brick and other building materials, over 100 tires, asphalt, car parts, household items, motor oil bottles, five-gallon containers of paint, and trash. Two 55-gallon drums were observed in the former recreation pond. They were partially buried and appeared burnt from a recent small brush fire. The contents of the drums are unknown.

RECOGNIZED ENVIRONMENTAL CONDITIONS

Recognized environmental conditions (RECs) are defined by the American Society of Testing and Materials (ASTM) as any hazardous substance or petroleum product under conditions that indicate an existing, past, or material threat of release into the structures, ground, groundwater, or surface water at the subject site. If the presence of recognized environmental conditions are identified on a subject site, it may warrant additional research, site investigation, and/or action.

The following sites have had past releases which would catagorize them as recognized environmental conditions.

- 1600 W. Valley Boulevard, Former Shell/Valero Gas Station (part of the subject site). This facility had a reported release which has received agency closure.

- 2109/2111 W. Valley Boulevard, Price Club/Telco Foods (part of the subject site). This facility had a reported release which has received agency closure.

POTENTIAL ENVIRONMENTAL CONDITIONS

Potential environmental conditions pertain to any hazardous substance or petroleum product under conditions that suggest the possibility of an existing, past, or material threat of release into the structures, ground, groundwater, or surface water at the subject site, but for which not enough information was available through the means within the scope of this report. The identified presence of potential environmental conditions at the subject site may warrant additional research, site investigation, and/or action. Those items identified at the subject site or nearby properties, which are potential environmental conditions relative to the subject site are discussed below.

1. Although no obvious indications of recognized environmental conditions were identified, the following addresses are considered to be likely potential environmental concerns to the site due to the nature of the business or other observations made during Petra's site reconnaissance:

   - 401 Pepper Avenue, McNeilus Truck and Manufacturing
   - 791 Pepper Avenue, Bishop Central Storehouse-LDS Church.
   - 310 Rexford Street, Transport Components Rebuilder
   - 313 Rexford Street, Republic Machine and Fabrication
   - 319 Rexford Street, 5 Star Auto Body
   - 320 Rexford Street, AMCAl Machine Shop
   - 1313 W. Valley Boulevard, City Truck Yard
   - 1630 W. Valley Boulevard, Chadwick Auto Wholesale
   - 1700 W. Valley Boulevard, I-10 Auto Sales/ Budget Car Rental
   - 1849 W. Valley Boulevard, Stevens Transport
   - 1900 W. Valley Boulevard, Moss Bros Ford

- 2084 W. Valley Boulevard, PYP Hot Rod Shop/Ben Warner Towing
- 2111 W. Valley Boulevard, Telco Food Products
- Burned structures along W. Valley Boulevard (adjacent to "The Hub")

It is recommended that these facilities be inspected to confirm that they do not have the potential to adversely impact the subject site.

2. These sites have not had a reported release; however, the following facilities appear to have USTs and /or ASTs which could represent a potential concern should they have a release.

- 1500 W. San Bernardino Avenue, County of San Bernardino
- 791 N. Pepper Avenue, Bishop's Cental Stores / Colton Bishop Store House
- 1700 W. Valley Boulevard, California Auto Specialist/Inland Empire Toyota/Budget Truck Rental
- 1600 W. Valley Boulevard, Valero Service Station
- 1900 W. Valley Boulevard, Moss Bros. Ford
- 1988 W. Valley Boulevard, Grace WR & Co. Distribution Services/ Sammon's Trucking
- 1998 W. Valley Boulevard, Colton Auto Sales/Western Exterminator Company
- 2006 W. Valley Boulevard, Brad & Carol Larsen/Sierra Diesel Repair
- 2036 W. Valley Boulevard, Oroweat Foods Co/Bimbo Bakeries USA, Inc./Bestfoods Baking Company

It is recommended that these facilities be inspected. The ASTs should be inspected to confirm they are placed within secondary containment units.

The most current UST fit test documents should be reviewed to confirm the USTs have no indications of a release.

3. Based on information obtained from the agency database search, the following on-site facilities are listed as potential environmental concerns:

   - 401 N Pepper Avenue, McNeilus Truck & Manufacturing Inc. Although no releases have been reported from this site, it is listed on the CA WDS database as an industrial facility.

   - Moss Bros. Ford, 1900 W. Valley Boulevard. This facility reportedly has an above ground storage tank.

   - County of San Bernardino, 1500 W. San Bernardino Avenue. This facility may have had either a AST or UST.

   - Price Club/Telco Foods,, 2109/2111 W. Valley Boulevard. This facility had a reported release which has received agency closure. It is unknown if USTs are still present at this facility.

   It is recommended that these facilities be inspected to confirm that facility activities do not have the potential to adversely impact the subject site.

4. Groves were historically located on portions of the subject site. No information was obtained regarding pesticide and herbicide use in these areas.

   It is recommended that sampling of the near-surface soils should be conducted in the former grove areas to evaluate the potential for impact from past pesticide and herbicide use.

5. Based on information obtained from the agency database search, the following off-site facilities are listed as potential environmental concerns:

   - Arrowhead Regional Medical Center, 400 N. Pepper Avenue. This facility was included on the SLIC database. No additional information was obtained during this investigation to establish why it is on this database.

   - Chevron Station #9-6969, 101 Valley Boulevard (Rialto). This facility reportedly impacted drinking water. No additional

information was obtained during this investigation to determine the facility's potential impact to groundwater on the subject site.

It is recommended that a file review be conducted at the RWQCB and San Bernardino County Fire Department to obtain additional information regarding these facilities.

SITE CONSIDERATIONS

Items, if presented below, are not considered recognized environmental conditions in accordance with ASTM 1527-05. Although these items may warrant consideration in conjunction with any planned development activities, they are not recognized environmental conditions. The information regarding possible actions relative to these items has been provided as guidance.

1. Both pole-mounted and pad-mounted transformers were observed on the site. It is unknown if they contain polychlorinated biphenyls (PCBs).

   If the transformers are to be removed, it is recommended that the removal be completed by a licensed contractor or the utility company responsible for the transformers.

2. While the interior of the buildings were not observed, it is likely that they contain fluorescent light fixtures which may have ballasts containing PCBs. Additionally, fluorescent light tubes contain trace amounts of mercury.

   When these items are removed, they should be disposed of in accordance with current regulations.

3. Debris, including two partially buried drums, were observed on the site.

   It is recommended that the debris on the site be removed and disposed of in accordance with current regulations. The area under the debris should be reinpsected for staining.

4. While the structures were not inspected for asbestos-containing materials and lead-based paints, it is likely that the older (pre-1980's) structures contain these materials.

   It is recommended that the buildings be assessed for asbestos-containing materials prior to any demolition. If present, asbestos-containing materials should be abated prior to demolition in accordance with current regulations. The soil drip-lines of any structures should also be tested for lead-based paints.

5. Due to the historical presence of groves located on the site, it is possible that underground transite (asbestos-containing) irrigation pipes are present.

   If any transite pipes are encountered during grading, they should be removed intact and disposed of in accordance with current regulations.

6. It is unknown if septic tanks were historically present on the site.

   If encountered during grading operations, they should be removed and disposed of in accordance with current regulations.

TABLE OF CONTENTS

Page

1.0 INTRODUCTION 1
- 1.1 Purpose 1
- 1.2 Involved Parties 2

2.0 SCOPE OF INVESTIGATION 2

3.0 SITE OVERVIEW 4

4.0 PREVIOUS LAND USE 5

5.0 PREVIOUS REPORTS 6

6.0 ENVIRONMENTAL SETTING 6
- 6.1 Geology 6
- 6.2 Surface and Groundwater Conditions 7
  - 6.2.1 Surface Water 7
  - 6.2.2 Groundwater 7

7.0 RESULTS OF INVESTIGATION 7
- 7.1 Site Inspection 14
- 7.2 Adjacent Site and Vicinity Observations 14
- 7.3 Government Agency Database Research 15
  - 7.3.1 Results of Agency Records Search 15
  - 7.3.2 Local Agencies 30
  - 7.3.3 Evaluation of Records Search Results 32
- 7.4 Results of Aerial Photo Analysis 34
- 7.5 Historical USGS Topographic Maps 37
- 7.6 Environmental Liens & Activity and Use Limitations 38
- 7.7 Fire Insurance Maps and City Directories 38
- 7.8 Interviews 39
- 7.9 Data Failures and Data Gaps 39

8.0 DISCUSSION OF POTENTIAL ENVIRONMENTAL CONCERNS .. 40
- 8.1 Regulatory Actions 40
- 8.2 Adjacent and Nearby Properties 40
- 8.3 Polychlorinated Biphenyls 41
- 8.4 Underground Storage Tanks and Above Ground Storage Tanks 41
- 8.5 Storm Water/Waste Water Discharge 42

TABLE OF CONTENTS
(cont'd)

Page

8.6 Pesticide and Herbicide Residues 42
8.7 Asbestos-Containing Materials and Lead-Based Paints 42
8.8 Landfills 43
8.9 Waste Generation and Storage 43

9.0 CONCLUSIONS 44
9.1 General Site Information 44
9.2 Recognized Environmental Conditions 45
9.3 Potential Environmental Conditions 45
9.4 Site Considerations 49

10.0 LIMITATIONS 50

11.0 QUALIFICATIONS 51

12.0 REFERENCES 52

FIGURES

PLATE A
SITE PHOTOGRAPHS

APPENDIX A
SITE INSPECTION CHECKLIST

APPENDIX B
AGENCY DATABASE RESULTS

APPENDIX C
NON-DATABASE SEARCH RESULTS

APPENDIX D
EDR HISTORICAL REPORTS

APPENDIX E
RESUMES

PHASE I ENVIRONMENTAL SITE ASSESSMENT

Colton Super Block,
Approximately 353 Acre Site Roughly Bounded by San Bernardino Avenue,
Riverside Avenue, I-10 Freeway, and Hermosa Avenue,
City of Colton and City of Rialto, County of San Bernardino, California

1.0 INTRODUCTION

The information presented in this report includes the results of our recent field reconnaissance, a thorough review of various federal, state, and local government agency database records, and a review of historic aerial photographs and topographic maps for the site vicinity. This report includes a summary of our findings, our opinion as to the current environmental condition of the site, and recommendations for additional work if needed. At the client's request, all of the site structures and most of the site parcels were not entered into and the site reconnaissance was completed as a "drive-by/fence-line" investigation.

1.1 Purpose

This investigation was conducted to determine if any recognized environmental conditions exist on the subject site. Recognized environmental conditions are defined by the American Society for Testing and Materials (ASTM) as any hazardous substance or petroleum product under conditions that indicate an existing, past, or material threat of release into the structures, ground, groundwater, or surface water at the subject site.

This investigation is also intended to satisfy the requirement for conducting all appropriate inquiries into the previous ownership and uses of a property for the purposes of meeting the all appropriate inquiries provisions necessary to qualify for certain landowner liability protections under the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA).

We have performed this investigation in conformance with the scope and limitations of the standards set forth in the ASTM Practice E 1527-05 and the EPA's All Appropriate Inquiry (AAI) regulations 40 CFR Part 312.

1.2 Involved Parties

This report was prepared by the Environmental Division of Petra Geotechnical, Inc. (Petra), at the request of Michael Brandman Associates, for their exclusive use. Use of this report or reliance thereon by other parties or projects is not authorized. The report may not be suitable for other parties or other purposes.

2.0 SCOPE OF INVESTIGATION

The scope of this investigation included the following:

1. Performing a site reconnaissance to identify the current conditions and land use of the subject site and adjoining properties. Visual evidence of prior uses of the subject site and adjoining properties were noted. The site reconnaissance included a visual inspection of the site surface, where possible, and the site perimeter. At the client's request, the site structures and most of the site parcels were not entered into and the site reconnaissance was completed as a "drive-by/fence-line" investigation.

2. Researching historical land use of the subject site and vicinity by reviewing available historical aerial photographs, United States Geologic Survey (USGS) topographic maps, fire insurance maps, city directories, and maps and data provided by the client.

3. Performing a literature study to identify local and regional geological conditions.

4. Obtaining and reviewing a search of pertinent federal, state, and local regulatory agency databases concerning environmental conditions on and in the vicinity of the site. As specified in the ASTM and AAI standards, the following databases were searched using, at a minimum, the recommended search radius:

- Federal National Priority List (NPL) site list,
- Federal Delisted NPL site list,
- Federal Comprehensive Environmental Response, Compensation, and Liability Information System (CERCLIS) site list,
- Federal CERCLIS- No Further Remedial Action Planned (CERC-NFRAP) site list,
- Federal Resource Conservation and Recovery Act Information (RCRA) Corrective Action Report (CORRACTS) facilities list,
- Federal RCRA non-CORRACTS Treat, Store and Dispose (RCRA-TSD) facilities list,
- Federal RCRA generators list,
- Federal institutional control/engineering control registries,
- Federal Emergency Response Notification System (ERNS) list,
- State and tribal lists of hazardous waste sites identified for investigation or remediation including: State- and tribal-equivalent NPL, State, and tribal-equivalent CERCLIS lists,
- State and tribal landfill and/or solid waste disposal site lists,
- State and tribal leaking storage tank lists,
- State and tribal registered storage tank lists,
- State and tribal institutional control/engineering control registries,
- State and tribal voluntary cleanup sites, and
- State and tribal Brownfield sites.

In the interest of thoroughness, numerous non-ASTM and non-AAI required databases were also searched. These databases are listed and discussed in the database search included within this Phase I report.

5. Evaluating the presence of recognized environmental conditions at the subject site through visual observation and research of reasonably ascertainable records. Recognized environmental conditions may include the presence of hazardous materials, petroleum products, underground storage tanks (USTs), above ground storage tanks (ASTs), drums, chemical containers, polychlorinated biphenyls, liquid or solid wastes, oil wells, and areas indicative of potential contamination including stained soils and/or pavement, stressed vegetation, drains, sumps, pits, ponds, lagoons, odors, and septic systems.

6. Non-Scope Items. In addition to those items discussed above, several items outside the scope of ASTM Practice E 1527-05 and EPA regulation 40 CFR

Part 312 have been addressed in this investigation. The non-scope items include:

- Visual examination of the site for the potential presence of asbestos containing materials, and
- Visual examination of the site for the potential presence of lead-based paint.

7. Preparing a report presenting the results of our investigation.

Unless otherwise stated in this section, no other services, assessments, or testing were included in this study. This investigation did not included conducting a search for environmental liens and Activities and Use Limitations (AULs) for the property or completion of a file review at the local oversight agencies.

3.0 SITE OVERVIEW

According to the 1967 (photorevised 1980) topographic map of the San Bernardino South, California, Quadrangle, prepared by the USGS, the site is located in the northern portion of Section 24 and the northeastern portion of Section 23, Township 1 South, Range 5 West, as well as in the northwestern portion of Section 19, Township 1 South, Range 4 West, San Bernardino Base and Meridian. The site elevation ranges from approximately 1,040 feet above mean sea level (msl) in the south to 1,120 feet above msl in the north. A site vicinity map is included as Figure 1.

The site is an irregular shaped parcel roughly bounded by San Bernardino Avenue to the north, city boundaries between Colton and Rialto to the west, by the I-10 freeway to the south, and by both Pepper Avenue and Hermosa Avenue to the east in the city of Colton, San Bernardino County, California. The subject site is comprised of approximately 353 acres. At the time of our investigation, the site consisted of vacant land, a golf course, residential homes, commercial/retail stores, office complexes, and

what appeared to be light industrial land use. A plan showing the current configuration of the site is included as Figure 2.

4.0 PREVIOUS LAND USE

Based on information obtained during this investigation, the site appears to have been used for dry farming/grazing activities, possibly as early as the 1900's. On the 1901 topographical map, a single structure is shown on the site in the location of a small grove visible on the southeastern portion of the site on the 1930 aerial. Small groves are present on the southwestern, southeastern, and northeastern portions of the site in the 1930's. The southwestern grove was present until at least the mid-1950's.

Based on information provided by www.airfields-freeman.com regarding abandoned airfields in Western San Bernardino County, Morrow Field was constructed on the subject site in 1942. Morrow Field consisted of a single northeast/southwest runway with a ramp and single hanger. The runway was also reportedly used for drag racing. In the 1960's, on the properties south of the airfield, the owner of the airfield built a golf course (now call Colton Golf Club) and shallow lake (Colton Recreational Lake) used to tow water skiers. It appears that the airfield was abandoned by 1980 and the lake may have no longer been in use by the mid-1970's. The golf course is still present.

The residential structures currently located on the northeastern portion of the site appear to have been present since at least the 1950's. In the 1960's, the far northeast corner of the site appeared to have been livestock corrals.

Commercial-type structures began appearing on the site in the 1950's, primarily south of West Valley Boulevard. By the late-1980's most of the structures present today had been constructed.

Historical information reviewed during this investigation includes aerial photographs (dating back to 1930), USGS topographical maps (dating back to 1901), and city directories (dating back to 1922). EDR reports that there is no Sanborn™ Map coverage for the site vicinity.

5.0 PREVIOUS REPORTS

No reports were provided by the client for review. It should be noted that Petra's geotechnical division has prepared a due diligence geotechnical assessment report of their findings, dated April 28, 2008.

6.0 ENVIRONMENTAL SETTING

The following sections provide an overview of the regional and local geologic setting and includes information pertaining to groundwater conditions in the vicinity of the subject site. Geotechnical hazard information (faults, landslides, etc.) is not part of this investigation. This section does not constitute a geotechnical investigation of the subject site and should not be taken as such.

6.1 Geology

The subject site is located within the Peninsular Ranges Geomorphic Province that extends from the southern San Gabriel Mountains to the tip of Baja California. Tectonically, the property is located within the Perris Block bounded by the east-west trending Cucamonga fault to the north, and the northwest trending San Jacinto and Elsinore Fault Zones to the east and west respectively (Morton and Miller, 2006). The property exists on the geomorphic Rialto-Colton Terrace that extends from the San Gabriel Mountains in the north to the Santa Ana River Valley to the south. The Rialto-Colton Terrace is underlain by late Pleistocene to Holocene sand dune and fluvial

deposits (Morton and Miller, 2006). The property dominantly contains late Pleistocene sediments composed of slightly to moderately consolidated, fine to medium grained sand and lesser amounts of silty sand and slightly gravelly sand (Morton and Miller, 2006). The major active fault zone near the property is the San Jacinto fault located approximately two miles northeast of the eastern edge of the property (Hart and Bryant, 1997; Jennings, 1994). The Rialto-Colton fault represents a fault branch emanating northwest from the San Jacinto Fault Zone and is primarily concealed by Holocene sediments approximately one-half mile northeast of the site (Hart, 1977; Stephenson, et. al., 2002). The San Jacinto and Rialto-Colton faults act as groundwater barriers (Hart, 1977; DWR, 2004).

6.2 Surface and Groundwater Conditions

6.2.1 Surface Water

No indication of surface water was observed on the site at the time of this investigation. The topographic maps and aerial photographs show two small lakes on the golf course; however, Petra was not provided access to this property.

6.2.2 Groundwater

The subject site is located within the Upper Santa Ana Valley Groundwater Basin and appears to be located in the Riverside-Arlington Subbasin (California Department of Water Resources, 2003). According to the California Department of Water Resources, Historical Data by Well Retrieval Website, two wells appear to be within the same township, range and sections as the subject site. Well number 01S05W24H002S, located on or within 500 feet of the southern portion of the subject site, was last measured in April of 2000 at 173.6 feet below the ground surface. Well number 01S04W19E001S, located

on or within 1,200 feet of the southwestern portion of the subject site, was last measured in October of 1997 at 162.8 feet below the ground surface. Water-bearing deposits in the subbasin consist of sand, gravel, silt and clay deposited by the Santa Ana River and its tributaries. From 1985 through 2001, groundwater levels in the northeastern part of the subbasin, near the Santa Ana River, fluctuated approximately 20 feet. During 1995 to 2000, water level in the same area found to have declined 10 feet.

Groundwater gradient beneath the site varies due to a number of factors. As previously mentioned, the Rialto-Colton Fault is located approximately 1/4-mile northeast of the site. This fault acts as a barrier to the natural flow of groundwater in the region (Department of Interior, 1963). Also, the seasonal fluctuation of the Santa Ana River located to the southeast of the site can influence the flow of groundwater. According to Sam Fuller of the San Bernardino Valley Municipal Water District, high water in the river tends to cause groundwater beneath the site to flow towards the northwesterly direction (away from the river). In addition, the site is located in a "groundwater divide" with the large Chino groundwater basin on the western side. A "groundwater divide" is defined as an area between two adjacent groundwater basins, hence, the flow of groundwater can be affected by pumping demand from water wells located in the general area, and wells located in the Chino basin. At times, groundwater may flow towards the west due to pumping in the Chino basin.

7.0 RESULTS OF INVESTIGATION

The results of our site reconnaissance and inspection of adjacent sites, agency database review, and historical land use study are presented in the following sections.

7.1 Site Inspection

Petra conducted a reconnaissance of the subject site on April 30, 2008. Site photographs are included as Plate A and a completed Site Inspection Checklist is located in Appendix A. Per the client's request, none of the occupied properties or facilities were entered nor were the owners contacted. The findings of this report are based on a "drive-by/fence- line" observations of the site.

In general, the types of property observed included the following: manufacturing/office buildings, retail/food business, recreational facility, residential, and vacant land. If visible, a street address was obtained. Our site observations are summarized below.

General

- Electrical transmission lines were observed across portions of the site, near the residences along C Street, across the vacant parcels in the central portion of the site, east of the golf course, and in the general area of businesses located off of West Valley Boulevard. They appear to range from 66 kilovolts (kV) to 115 kV in capacity.

- Several pole-mounted and pad-mounted transformers were observed on the site. The pole-mounted transformers were located in the same areas as the transmission lines, and the pad- mounted transformers were observed at the World Prophetic Ministry Church, an unmarked structure (possibly Telco Food Products), and along the southern side of West Valley Boulevard. It is unknown if the transformers contain polychlorinated biphenyls (PCBs).

- Approximately 60 percent of the site was vacant land. Miscellaneous debris was observed on vacant land and included plastic, metal, wood, concrete, PVC pipes, a boat, tiles, furniture, landscape waste, carpet, dry wall, brick and other building materials, over 100 tires, asphalt, car parts, household items, motor oil bottles, five-gallon containers of paint, and trash. Two 55-gallon drums were observed in the area of the former recreation lake. They were partially buried and appeared burnt from a recent small brush fire. The contents of the drums are unknown.

- While the structures were not inspected for asbestos-containing materials and lead-based paints, it is likely that the older (pre-1980's) structures contain these materials.

- A concrete drainage was observed on the southeastern area of George E. Brown Jr. Park located on the north-central portion of the subject site. At the time of our site inspection, the drainage appeared to be dry.

Site Specific

Facilities on the site include both manufacturing and vehicle repair. Although these facilities were not inspected, the following concerns should be noted

- Items often found at manufacturing facilities may include (but not limited to) the following: clarifiers, USTs, ASTs, chemical storage, waste material storage, and solvent cleaning stations.

- Items often found at vehicle repair facilities may include (but not limited to) the following: clarifiers, USTs, ASTs, chemical storage, waste material storage, solvent cleaning stations, and hoists.

The table below discuss site specific observations.

Address	**Type of Use (name of business)**	**RECs**
Wildrose Avenue	Colton Recreational Lake.	Unknown, two partially buried drums (contents unknown), two structures.
491 Wildrose Avenue	EJK Center: Dannybuilt Truckmounts, Snap-on Auto Training Academy, M & B Cooling Specialists, Digital Printing, Javco Ornamental Works, Tata Bouncers, Designs by Davis Furniture	Unknown

Address	Type of Use (name of business)	RECs
unlisted address-San Bernardino Avenue	Portable-type buildings for Arrowhead Regional Medical Center (ARMC Village)	Unlikely
1750 San Bernardino Avenue	Carpenters Union Membership Training Center (Vacant)	Unlikely
625, 635, 645, 1225, 1227, 1245, and 1265 "C" Street	Residential	Unlikely
1275 "C" Street	RAI Care Center-outpatient dialysis facility	Unknown
401 Pepper Avenue	McNeilus Truck and Manufacturing, manufacture of cement trucks	Likely (See Note 1 above)
791 Pepper Avenue	Bishop Central Storehouse-LDS Church	Likely-large ASTs in back of property, one appeared to have a sign marked "phosphine gas" which is typically used as an indoor pesticide.
1099 San Bernardino Avenue	World Prophetic Ministry Church	Unknown, two pad-mounted transformers were present.
220 Rexford Street	Auction Meat and Seafood	Unknown
299 Rexford Street	unknown	Unknown
310 Rexford Street	Transport Components Rebuilder	Likely (See Note 2 above)

Address	Type of Use (name of business)	RECs
313 Rexford Street	Republic Machine and Fabrication	Likely (See Note 1 above)
319 Rexford Street	5 Star Auto Body	Likely (See Note 2 above)
320 Rexford Street	AMCAl Machine Shop	Likely, at least one hoist was visible. (See Note 2 above)
295 Hermosa Avenue	Acacia RV Performance Center	Likely (See Note 2 above)
325 Hermosa Avenue	Slover Mountain High School	Unlikely
345 Hermosa Avenue	residence	Unlikely
2040 Woodpine Avenue	County of San Bernardino Department of Public Social Services	Unlikely
1205 W. Valley Boulevard	Vacation Station RV	Likely (See Note 2 above)
1295 W. Valley Boulevard	Spas & Pools	Unknown
1313 W. Valley Boulevard	City Truck Yard	Likely, appears to have a maintenance area (See Note 2 above)
1405 W. Valley Boulevard	Colton Music Center (Piano City)	Unlikely
1600 W. Valley Boulevard	Valero Gas Station	Likely (See Note 2 above)
1620 W. Valley Boulevard	Baker's Tacos	Unlikely

Address	Type of Use (name of business)	RECs
1630 W. Valley Boulevard	Chadwick Auto Wholesale	Likely (See Note 2 above)
1700 W. Valley Boulevard	I-10 Auto Sales/ Budget Car Rental	Likely (See Note 2 above)
1759 W. Valley Boulevard	Auction Meats	Unknown
1763 W. Valley Boulevard	Auction Meats and Seafood	Unknown
1849 W. Valley Boulevard	Stevens Transport	Likely (See Note 2 above)
1900 W. Valley Boulevard	Moss Bros Ford	Likely (See Note 2 above)
1901 W. Valley Boulevard	Colton Golf Club	Unknown, maintenance shed and pole-mounted transformers present
2001 W. Valley Boulevard	The Hub Cocktail	Unlikely
W. Valley Boulevard (adjacent west of The Hub)	Appears to have been storage units. Several burned structures, debris, tires.	Likely-Dioxin (cancer causing) is typically associated with burnt debris.
2010 W. Valley Boulevard	Antique Furniture Auction	Unlikely
2012 W. Valley Boulevard	Marques Signs	Unknown
2014, 2016, 2018 W. Valley Bl.	residences	Unlikely

Address	Type of Use (name of business)	RECs
2036 W. Valley Boulevard	Oroweat/Entenmann's Bakery Outlet	Unknown (See Note 1 above)
2042 W. Valley Boulevard	Rodeway Motel	Unlikely
2048 W. Valley Boulevard	Landjet Motor Carriers	Unknown
2084 W. Valley Boulevard	PYP Hot Rod Shop, Hot Rod and Race Car Fabrication, Shoes, Ben Warner Towing	Likely (See Note 2 above)
2111 W. Valley Boulevard	Unmarked Structure (possibly Telco Food Products)	Likely, ASTs, pad mounted transformers, and sign marking "ammonia" observed
2245 W. Valley Boulevard	Contractor's Warehouse	Unknown
Sycamore Avenue	Water Well 18A	Unknown

7.2 Adjacent Site and Vicinity Observations

The site is situated in an area comprised of mix land use. Our specific observations are noted below:

North - Single-family homes and apartments were present north of the site beyond San Bernardino Avenue. A vacant lot and a retail center were present northeast of San Bernardino Avenue and Pepper Avenue. A park, Rialto Playhouse, and Rialto Fitness Center were located northwest of San Bernardino Avenue and Sycamore Avenue. Another water well was noted approximately two blocks north of San Bernardino Avenue and Meridian Avenue.

West - A mix of vacant land, an endangered species area, retail/commercial use, residential, a church, and a water well (Well #49?) were present west of the subject site.

East - A cemetery, the Arrowhead Regional Medical Center, and vacant land was present east of the site. Railroad tracks, a storage facility, and residences were present east beyond Hermosa Avenue.

South - A vacant strip of land, and the I-10 Freeway were present south of the site. Beyond the I-10 Freeway was a railroad yard and Slover Mountain, a quarry.

7.3 Government Agency Database Research

A search of federal, state, and local government listings was performed by Environmental Data Resources, Inc. (EDR) for the purposes of this report. The search radius used for all government databases meets or exceeds the standard search distance adopted by ASTM and AAI.

7.3.1 Results of Agency Records Search

A data search of the various government agency records listed in Appendix B revealed 57 listings for the subject site. Thirty-seven orphan sites (sites with inadequate address information to be mapped by EDR) were identified during the agency database search. Refer to the EDR Report in Appendix B for the search radii completed for this investigation. A brief description of the sites listed in the EDR report with addresses identified for the subject site is provided below. Additional sites with release within ¼-mile, or of concern due to the nature of their listings, are also discussed. Please note that the database information was reviewed for potential recognized environmental conditions based solely on the data provided in the EDR report. The condition of these sites could not be confirmed by a site visit.

Addresses Associated with the Subject Site

Site A1
Republic Machine & Fabrication, 313 Rexford Street, Colton, CA

This facility is located on the south-central portion of the subject site. It is listed on the Hazardous Waste Information System/ Facility and Manifest Data (HAZNET) and the San Bernardino County Fire Department Hazardous Materials Permits (San Bern. Co. Permit) databases. The HAZNET listing is for a site which generates, handles, or ships material requiring a waste manifest. No information which would indicate that this site presents a recognized environmental condition relative to the subject site was presented in the EDR report.

Sites B2, B3, C5 and C6
Alliance Colton - Drews Substation, 559 Pepper Avenue, Colton, CA

This facility is located near the east-central portion of the subject site. It was not observed during the site reconnaissance and may be located south of the Arrowhead Regional Medical Center in an area that was not accessible due to road construction. The facility was listed on the Facility Index System/Facility Registry System (FINDS), Aerometric Information Retrieval System (AIRS), and the Integrated Compliance Information System (ICIS) databases. This site appears to be a power substation which has permits from the Air Quality Management District (AQMD). Violations reported for this site appear to be for "non-penalty" compliance orders. No information which would indicate that this site presents a recognized environmental condition relative to the subject site was presented in the EDR report.

Site A4
Universal Mack Sales Service, 220 N. Rexford Street, Colton, CA

This facility is located on the south-central portion of the subject site. The address for the site was identified during the site reconnaissance as being associated with Auction Meat. The facility is listed on the Resource Conservation and Recovery Act Information, Small Quantity Generator (RCRA-SQG) and FINDS databases for a facility that generates and/or handle small quantity of hazardous material. No violations were reported. No information which would indicate that this site presents a recognized environmental condition relative to the subject site was presented in the EDR report.

Site D7, D8, and D9
California Auto Specialist/Inland Empire Toyota/Budget Truck Rental, 1700 W. Valley Boulevard, Colton, CA

This facility is located on the southern portion of the subject site. It is listed on the HAZNET, Statewide Environmental Evaluation and Planning System (SWEEPS UST), Hazardous Substance Storage Container (HIST UST), HAZNET, RCRA-SQG, FINDS, and San Bern. Co. Permit databases. The HAZNET listing is for a site which generates, handles, or ships material requiring a waste manifest. The FINDS and RCRA-SQG listings are for generation of small quantity of hazardous waste. No violations are reported for the RCRA-SQG listing. The HIST UST, SWEEP UST and San Bern. Co. Permit listings are for five onsite USTs that contain waste oil and gasoline. No releases have been reported from these tanks. However, due to the presence of USTs, this site is considered a potential environmental concern for the subject site.

Sites C10 and C11
McNeilus Truck & Manufacturing Inc., 401 N Pepper Avenue, Colton, CA

This facility is located on the east-central portion of the subject site. It is listed on the Toxic Chemical Release Inventory System (TRIS), Waste Discharge System (CA WDS), AIRS, FINDS and San Bern. Co. Permit databases. The San Bern. Co. Permit listing is for a facility that generates and/or handles hazardous material. The FINDS and AIRS listings are for emission of total organic hydrocarbon gases. The TRIS listing is for a facility that release toxic chemicals to the air, water and land in reportable quantities. The CA WDS listing is for a facility that has been issued waste discharge requirements. No violations are reported. However, due to the site listed on the CA WDS listing as an industrial facility, this site is considered a potential environmental concern for the subject site.

Sites E12 and E13, 43
Bishop's Cental Stores / Colton Bishop Store House, 791 N. Pepper Avenue, Colton, CA

This facility is located on the east-central portion of the subject site. It is listed on the UST, San Bern. Co. Permit, HAZNET, SWEEPS UST, and HIST UST databases. This facility reportedly has four USTs and appears to

also be permitted for ASTs. No releases were reported. However, due to the presence of USTs and ASTs, this site is considered a potential environmental concern for the subject site. The address provided by EDR for Site 43 appears to be incorrect.

Sites F19, F20, and F21
Auto Centro / B&G Auto Sales, 1630 W. Valley Boulevard, Colton, CA

This facility is located on the southern portion of the subject site. It is listed on the RCRA-SQG, FINDS, HAZNET, and San Bern. Co. Permit databases for a facility that generates and/or handle hazardous material, with listed substances including tetrachloroethylene and aqueous solution. No releases or violations are reported. No information which would indicate that this site presents a recognized environmental condition relative to the subject site was presented in the EDR report.

Sites G22 -G25
CC Western/Central Transport Inc., 1849 W. Valley Boulevard, Colton, CA

This facility is located on the south-central portion of the subject site. It is listed on the Hazardous Materials Information Reporting System (HMIRS) and HAZNET databases. The HAZNET listing is for a facility that generates and/or handle organic liquid mixture, acidic liquids with metals and other organic solids. No violations are reported for the HAZNET listings. The HMIRS listings are for a spillage of 0.5 gallon of isobutanol in 1995, one-gallon of trichloroethane in 1994, and five-gallons of styrene monomer in 1995. Due to the nature of the incidents and the small quantities released, these releases do not appear to present a recognized environmental condition relative to the subject site.

Sites F26 -F29
Orange Shell - Colton / Zakaria Haggag / Shell Service Station, 1600 W. Valley Boulevard, Colton, CA

This facility is located on the southern portion of the subject site. It is listed on the UST, HIST UST, San Bern. Co. Permit, Leaking Underground Storage Tank (LUST), RCRA-SQG, FINDS, HAZNET, and SWEEPS UST databases. The UST, HIST UST, San Bern. Co. Permit and SWEEPS UST listings are for five onsite underground storage tanks used for storage of waste oil and gasoline. The LUST listing is for a reported leak in March of

2003. The leak impacted soil only and received case closure in 2005. However, due to the presence of USTs and the facility having a reported release, this site is considered a potential environmental concern for the subject site.

Sites F31 and F32
Don Morrison /California Auto Specialities, 1595 W. Valley Boulevard, Colton, CA

This address was not identified during the site reconnaissance; however, based on the address it should be located on the southern portion of the subject site. It is listed on the HAZNET database for a facility that generates and/or handles materials requiring a waste manifest. No violations or releases are reported. No information which would indicate that this site presents a recognized environmental condition relative to the subject site was presented in the EDR report.

Sites H33 and H36
Colton Golf Course, 1901 Valley Boulevard, Colton, CA

This facility is located on the central portion of the subject site. It is listed on the San Bern. Co. Permit and HAZNET databases for a facility that generates and/or handle hazardous material such as waste oil and mixed oil, and off-specification, aged or surplus organics. No releases or violations are reported. No information which would indicate that this site presents a recognized environmental condition relative to the subject site was presented in the EDR report.

Sites H34 and H35
Moss Bros. Ford, 1900 W. Valley Boulevard, Colton, CA

This facility is located on the southern portion of the subject site. It is listed on the FINDS, HAZNET and San Bern. Co. Permit databases for an onsite above ground storage tank and a facility that generates and/or handle unspecified solvent mixture waste, waste oil and mixed oil, and aqueous solution with less than 10% total organic residues. No releases or violations are reported. However, due to the presence of a AST, this site is considered a potential environmental concern for the subject site.

Site 37
Carpenters Joint Apprent & Trng., 1750 San Bernardino Avenue, Colton, CA

This facility is located on the southern portion of the subject site. It is listed on the San Bern. Co. Permit database for generation and handling of hazardous materials. The site facility status is currently listed as inactive under both their handler and generator permits. The generator permit is listed as expired in 2004. During our site reconnaissance, the facility appeared to be closed and currently vacant. No information which would indicate that this site presents a recognized environmental condition relative to the subject site was presented in the EDR report.

Site 38
Corner of Pepper / San Bernardino Avenue, Colton, CA

This listing appears to be for a one-time release at the intersection. It is listed on the California Hazardous Material Incident Report System (CHMIRS) database. A reported incident date of February 1988 was listed but the nature of the incident was not reported. According to the time of incident provided in the EDR, it appears that this incident was reported and completed within two hours. This may have been a traffic accident occurring at the intersection of the two streets involving spillage and clean up of hazardous material. Due to the one-time nature of the release and length of time since the incident, this listing does not appear to present a recognized environmental condition relative to the subject site.

Sites J41 and J42
Grace WR & Co. Distribution Services / Sammon's Trucking, 1988 W. Valley Boulevard, Colton, CA

This address was not identified during the site reconnaissance; however, based on the address it should be located on the southern portion of the subject site. It is listed on the SWEEPS UST, FINDS and RCRA-NonGen databases. The SWEEPS UST listing is for an underground storage tank. The FINDS and RCRA-NonGen listings are for a facility that does not currently generate hazardous waste. No releases or violations are reported. However, due to the presence of a UST, this site is considered a potential environmental concern for the subject site.

Site K44
World Prophetic Ministry, 1099 N. Pepper Avenue, Colton, CA

This facility is located on the northern portion of the subject site. It is listed on the HAZNET, FINDS and RCRA-SQG databases for a facility that generates and/or handle small quantity of hazardous material. Listed materials included benzene, tetrachloroethylene, trichloroethylene, liquids with halogenated organic compounds greater than 1,000 mg/l, waste oil and mixed oil. No violations or releases are reported. No information which would indicate that this site presents a recognized environmental condition relative to the subject site was presented in the EDR report. However, due to the nature of the listings in comparison with the type of business (church), additional information regarding the operations and historical operations for this site should be investigated.

Sites J45 and J46
Colton Auto Sales / Western Exterminator Company, 1998 W. Valley Boulevard, Colton, CA

This address was not identified during the site reconnaissance; however, based on the address it should be located on the southern portion of the subject site. It is listed on the HIST UST and HAZNET databases for an underground storage tank containing gasoline, and a facility that generates and/or handle hazardous material such as waste oil and mixed oil. No violations or releases are reported. However, due to the presence of a UST, this site is considered a potential environmental concern for the subject site.

Sites J49 and J50
Brad & Carol Larsen / Sierra Diesel Repair, 2006 W. Valley Boulevard, Colton, CA

This facility is located on the southern portion of the subject site. It is listed on the SWEEPS UST, San Bern. Co. Permit and HAZNET databases. The SWEEPS UST listing is for an onsite underground storage tank. The San Bern. Co. Permit listing is for an aboveground storage tank and a facility that generates and/or handle hazardous material. The HAZNET listing is for a facility that generates and/or handle hazardous material such as photo-chemicals and photo-processing waste. No violations or releases are reported. However, due to the presence of both a AST and UST, this site is considered a potential environmental concern for the subject site.

Site 53
1X County of San Bernardino, 1500 W. San Bernardino Avenue, Colton, CA

This address was not identified during the site reconnaissance; however, based on the address it should be located on the northern portion of the subject site. It is listed on the HAZNET database for a facility that generates and/or handle hazardous material, listed in the EDR report as tank bottom waste. No violations or releases are report. There was no additional information in the EDR report to confirm if there was a tank on this site. However, due to the potential presence of either a AST or UST, this site is considered a potential environmental concern for the subject site.

Sites N56 and N58, AG129
Oroweat Foods Co/Bimbo Bakeries USA, Inc./Bestfoods Baking Company, 2036 W. Valley Boulevard, Colton / Rialto, CA

This facility is located on the southern portion of the subject site. It is listed on the SWEEPS UST, San Bern. Co. Permit and HAZNET databases. The San Bern. Co. Permit listings is for two permits for a facility that generates and/or handle hazardous material, which both expired in 2007. The SWEEPS UST listing is for an underground storage tank. The HAZNET listing is for generation and handling of unspecified organic liquid mixture. No violations or releases are reported. However, due to the presence of a UST, this site is considered a potential environmental concern for the subject site.

Site N61
Landjet Motor Carriers, 2048 W. Valley Boulevard, Colton, CA

This facility is located on the southern portion of the subject site. It is listed on the San Bern. Co. Permit database for a facility that generates and/or handle hazardous material. No violations or releases are reported. No information which would indicate that this site presents a recognized environmental condition relative to the subject site was presented in the EDR report.

Sites P65, P66 and P68
Colton Joint Unified School District/Warehouse, 1313 W. Valley Boulevard, Colton, CA

This facility is located on the southern portion of the subject site. It is listed on the HAZNET, San Bern. Co. Permit, FIFRA/ TSCA Tracking System (FTTS INSP), and Historical FIFRA/ TSCA Tracking System (HIST FTTS) databases. The HAZNET and San Bern. Co. Permit listings are for a facility that generates and/or handle hazardous materials. Listed materials included unspecified organic liquid mixture, polychlorinated biphenyls and material containing PCBs, unspecified aqueous solution, and unspecified solvent mixture waste. The FTTS INSP and HIST FTTS listings are for a facility that undergoes inspections and enforcements per the Federal Insecticide, Fungicide & Rodenticide Act and Toxic Substance Control Act. No information which would indicate that this site presents a recognized environmental condition relative to the subject site was presented in the EDR report.

Site Q67, Q69, Q70, and R-72 -R77
Price Club/Telco Foods., 2109/2111 W. Valley Boulevard, Colton, CA

This facility is located on the south-western portion of the subject site. It is listed on the SWEEPS UST, Emergency Response Notification System (ERNS), CHMIRS, AIRS, San Bern. Co. Permit, HAZNET, and LUST databases. The SWEEPS UST listing is for the location of three USTs. The CHMIRS and ERNS listings are for a leak of ammonia into the atmosphere caused by failure of equipment in 2002. Four permits were listed for the site under the San Bern. Co. Permit database. The permits are for a risk management plan - level III, CALARP facility, EPCRA facility and handling of hazardous material. The HAZNET listing is for generation of hazardous material such as metal sludge, inorganic solid waste, unspecified oil-containing waste, waste oil and mixed oil. AIRS listing is for emission of carbon monoxide. The LUST listing is for a reported leak of gasoline in 1997. The LUST listing received case closure in July of 2007. It is unknown if USTs are still present at this facility. Therefore, due to the potential presence of USTs and the facility having a reported release, this site is considered a potential environmental concern for the subject site.

Sites U86 and U87
Slover Mountain High School, 325 Hermosa Avenue, Colton, CA

This facility is located on the eastern portion of the subject site. It is listed on the HAZNET and FINDS databases for a facility that generates and/or handle hazardous material such as asbestos-containing waste. No violations or releases are reported. No information which would indicate that this site presents a recognized environmental condition relative to the subject site was presented in the EDR report.

Site W92
AT&T Mobility Colton #13829, 1205 ½ W/ Valley Boulevard, Colton, CA

This facility is located on the south-central portion of the subject site. It is listed on the San Bern. Co. Permit database for being a un-staffed remote facility that handles hazardous material. No violations or releases are reported. No information which would indicate that this site presents a recognized environmental condition relative to the subject site was presented in the EDR report.

Site W93
Parkhouse Tire, 1205 W. Valley Boulevard, Colton, CA

This facility is located on the eastern portion of the subject site. It is listed on the HAZNET database for a facility that generates and/or handle hazardous material such as oil/water separation sludge and aqueous solution with 10% or more total organic residues. No violations or releases are reported. No information which would indicate that this site presents a recognized environmental condition relative to the subject site was presented in the EDR report.

Addresses Located within 1/4-Mile of the Subject Site with Releases

Sites C14 - C18
Arrowhead Regional Medical Center, 400 N. Pepper Avenue, Colton, CA

This site is located adjacent to the east-central portion of the subject site. It is listed on the Spills, Leaks, Investigations and Cleanups (SLIC), FINDS, UST, CA WDS, HAZNET, AIRS, San Bern. Co. Permit and CHMIRS databases. Details associated with the SLIC listing are not reported on the

EDR search. The CHMIRS listing is for a spilled bottle of potassium hydroxide. The UST listing is for an underground storage tank on site. The AIRS listing is for emission of carbon monoxide under permits issued by the AQMD. The rest of the listings are for generating and handling of medical/organic waste. Due to the presences of USTs and the facility being on the SLIC database, this site is considered a potential environmental concern for the subject site.

Site F30
1599 Valley Boulevard, Fontana, CA

This site is located adjacent to the east of the subject site. It is listed on the database for a diesel fuel release that occurred in 2000 after a semi-truck accident. The listing stated that the incident occurred on the roadway and that the spill was contained. Due to the nature of the release, the listing does not appear to present a recognized environmental condition relative to the subject site.

Site AA113, AD123-AD, AG133
10-10 Truck Stop, 195 E. Valley Boulevard, Rialto, CA

This site is located approximately ⅛-mile to the west of the subject site. It is listed on the ERNS, UST, LUST, and HIST UST databases. The ERNS listing is for an emergency release of 100 gallons of diesel fuel in 1991. The release impacted soil only. The UST listing is for the location of a UST. The LUST listing is for a release in 1998 that impacted soil only and received agency closure in 2007. The HIST UST is for a site which historically had at least five USTs. Due to the releases impacting soil only and the LUST listing having received closure, this facility does not appear to present a recognized environmental condition relative to the subject site.

Sites AF127 and AF128
Southern Pacific Rail Yard / Union Pacific Railroad Co., 200 Marion Way, Bloomington, CA

This site is located approximately ¼-mile southwest, downgradient, of the subject site. It is listed on the LUST, San Bern. Co. Permit, DTSC's Hazardous Waste and Substances Site List (CORTESE), Toxic Pits Cleanup Act Sites (Toxic Pits), AIRS, and SWEEPS UST databases. The San Bern. Co. Permit listing is for a facility that generates and handles hazardous

materials. The LUST and SWEEPS UST listings are for a release of diesel fuel from an underground storage tank in 1988. The release impacted soil only and the site received case closure in 1991. The AIRS listing is for operating a facility that has emission under AQMD permits. The CORTESE listing is for a facility which has operational criteria from government databases. The Toxic Pits listing is for the past operation of a toxic pit on the site which ceased operation in 1991. Due to the distance from the subject site, the LUST listing impacting soil only and receiving agency closure, this facility does not appear to present a recognized environmental condition relative to the subject site.

Sites AG134 -AG140
Chevron Station No.96969 / #9-6969 / #6969, 101 Valley Boulevard, Rialto, CA

This site is located approximately ⅛-mile to the west of the subject site. It is listed on the RCRA-SQG, RCRA-LQG, FINDS, HAZNET, UST, HIST UST, SWEEPS UST, San Bern. Co. Permit, LUST, California Facility Index/ Facility Inventory Database (CA FID UST) databases. The RCRA-SQG, RCRA-LQG, FINDS and HAZNET listings are for generation and handling of small and large quantities of hazardous material. The UST, HIST UST, CA FID UST, and SWEEPS UST listings are for at least four underground storage tanks. The San Bern. Co. Permit listing is for handling of hazardous material and owning and operating underground storage tanks. The LUST listing is for a product released discovered during a tank closure in 1993. The release reportedly impacted drinking water wells but received agency closure in 2000. No additional information could be obtained regarding the impacted groundwater from this site; therefore, this site is considered a potential environmental concern for the subject site.

Site AG141 City of Rialto Texaco, 102 Valley Boulevard, Rialto, CA

This site is located approximately ⅛-mile to the west of the subject site. It is listed on the LUST and CORTESE databases. The CORTESE listing is for a facility which has operational criteria from government databases. The LUST listing is for a product released discovered during a tank closure in 1991. The release impacted soil only and the site received case closure in 1992. Due to the release impacting soil only and the case receiving closure, this facility does not appear to present a recognized environmental condition relative to the subject site.

Site AG142 through AG146, AI150
Thrifty Oil Co. #323 / Arco #09695, 111 Valley Boulevard, Rialto, CA

This site is located approximately ⅛-mile to the west of the subject site. It is listed on the RCRA-SQG, FINDS, UST, HAZNET, CA FID UST, SWEEPS UST, San Bern. Co. Permit, HIST UST and LUST databases. The RCRA-SQG, FINDS and HAZNET listings are for generation of small quantity of hazardous materials such as benzene and other organic solids. The San Bern. Co. Permit listing is for handling and generating hazardous materials, and ownership and operation of four underground storage tanks. The CA FID UST, HIST UST, and SWEEPS UST listings are for five underground storage tanks used for storing petroleum product and waste oil. The LUST listing is for a product released discovered in 1997. The release impacted soil only and the site is reportedly undergoing preliminary assessment. Due to the release impacting soil only, this facility does not appear to represent a recognized environmental condition with regards to the subject site.

Site AI153
Texaco Service Station, 120 Valley Boulevard, Rialto, CA

This site is located over ⅛-mile to the west of the subject site. It is listed on the LUST and CORTESE databases for a release of waste oil discovered in 1996. The release impacted soil only and case closure was granted in 1997. Due to the release impacting soil only and the case receiving closure, this facility does not appear to present a recognized environmental condition relative to the subject site.

Sites Y97 - Y102, AE120-122
Cal Nev Pipeline Colton / Cal Nev Colton Terminal, 2051 Slover Avenue, Colton / Bloomington, CA

This site is located approximately ½-mile south of the subject site. It is listed on the San Bern Co. Permits, CHMIRS, ERNS, SLIC, HAZNET, RCRA-LQG, SWEEPS UST, UST, and AST databases. The San Bern. Co. Permit listings are for a AST, a Emergency Planning and Community Right To-Know Act (EPCRA) facility. The CHMIRS listing is for cleanup of a spill in 1989 and 1995. The ERNS listing is for diesel spills in 1990 and 1992. The SLIC listing is for jet fuel, no other information was provided. The HAZNET listing were for generation or handling of material requiring a waste manifest. The RCRA-LQG was for a handler/generator of 1,000

kilograms or more of hazardous waste during any month. Waste types listed included batteries, lamps, pesticides, thermostats, and ignitable hazardous wastes. The SWEEPS UST and UST listings are for at least one UST at the facility. The AST listing is for at least one AST at the facility. Petra reviewed documents for this facility, and another "Colton Terminal" listed for 2359 Slover Avenue, on the Geotracker website. These documents show groundwater gradient to be toward the south, away from the subject site. Due to the distance from the subject site and the groundwater gradient away from the subject site, this facility does not appear to present a recognized environmental condition relative to the subject site.

Sites Z103-Z108 and AC117
General American Transportation Corp. / GATX Rail, Pepper Avenue / Slover Street, Colton, CA

This site is located approximately ½-mile south of the subject site. It is listed on the AIRS, HAZNET, CHMIRS, FINDS, RCRA-LQG, HIST UST, Corrective Action Report (CORRACTS), Resource Conservation and Recovery Act Information, Treat, Store and Dispose (RCRA-TSDF), and CERCLIS- No Further Remedial Action Planned (CERC-NFRAP), and San Bern Co. Permit databases. The AIRS listing is for a facility under jurisdiction of the AQMD. The HAZNET listing is for generating and handling of organic solids, and unspecified solvent mixture waste. There are two CHMIRS listings. One listing is for discovery of six 5-gallon paint containers abandoned on the rail yard. The second listing is for illegal dumping of 30 gallons of acid in 1994. The RCRA-LQG and RCRA-TSDF listings are for generation, treating and storing of large quantity of hazardous materials. The HIST UST listing is for four underground storage tanks used for petroleum products and waste oil. The CORRACTS listing is for violations in areas such as contingency plan and emergency procedures, container use and management, general facility standards, financial requirements, closure/post-closure, and generators dating back to 1987. The facility was assigned a low corrective action priority. The CERCLIS-NFRAP assessment history listed the site's priority level as "no further remedial action planned." The San Bern Co. Permits is for a site with ASTs, USTs, and a "Right to Know" plan in place. Although gradient direction maps could not be found for this facility, it is located in the same general area as the Colton Terminal, discussed above as Sites Y97 - Y102, and AE120-122 and is expected to have a similar groundwater gradient. Therefore, due to the distance from the subject site, the CERCLIS status as "no further remedial action planned," and the expected groundwater gradient away from the

subject site, this facility does not appear to present a recognized environmental condition relative to the subject site.

Site AK-160
Colton Terminal / Conoco Phillips Colton Terminal East, 271 E. Slover Avenue, Rialto, CA

This site is located approximately ½-mile south of the subject site. It is listed on the HIST UST, CA WDS, AST, RCRA-SQG, FINDS, HAZNET and SLIC databases. The HIST UST and AST listings are for at least two aboveground and/or underground storage tanks used for storing diesel fuel and waste. The CA WDS listing is for a facility that treats and/or disposes of liquid or semisolid wastes from servicing, producing, manufacturing or processing operations. The facility is categorized with "Minor Threat to Water Quality," and is also on a bimonthly self-monitoring program. The RCRA-SQG, FINDS and HAZNET listings are for generating and handling of small quantity of hazardous materials such as lead, benzene and other organic solids. The facility is classified as a SLIC site under the SLIC database however no other information on spills or cleanups were listed. Although gradient direction maps could not be found for this facility, it is located in the same general area as the Colton Terminal, discussed above as Sites Y97 - Y102, and AE120-122 and is expected to have a similar groundwater gradient. Due to the distance from the subject site and the expected gradient direction away from the subject site, this facility does not appear to present a recognized environmental condition relative to the subject site.

Orphan Sites

Orphan sites are unable to be located due to lack of complete address information. Thirty-eight orphan sites are listed in the EDR report. Orphan sites may appear on more than one database. A summary of the orphan sites is provided below.

- Thirteen sites are listed on the San Bern. Co. Permit database,
- ten sites are listed on the HAZNET database,
- two sites are listed on the Clandestine Drug Lab (CDL) database,
- four sites are listed on the LUST database,
- one site is listed on the ERNS database,

- one site is listed on the DRYCLEANERS database,
- one site is listed on the FINDS database,
- one site is listed on the SLIC database,
- one site is listed on the CA FID UST database,
- one site is listed on the AIRS database,
- one site is listed on the CERC-NFRAP database,
- one site is listed on the DTSC's EnviroStor Database (ENVIROSTOR) database,
- one site is listed on the School Property Evaluation Program (SCH) database, and
- one site is listed on the CORTESE database.

Based on information contained in the EDR report, Pure Energy (Alliance Colton) is located on the subject site and has a FINDS listing. It is also listed on the EDR database as Sites B2, B3, C5 and C6. Entenmann's Oroweat is listed on the EDR database as Sites N56 and N58 and has a CAL FID and SWEEPS UST listing. Melchor Briceoceno, which has a HAZNET listing, may also be located on the southern portion of the subject site. 10-10 Truck Stop, also listed as AA-113, is located approximately ⅛-mile from the subject site and has a SWEEPS UST listing. The Arco Products Co. site appears to be located within ½-mile of the subject site and has a HAZNET listing. All other listings on the orphan sites appear to be located over ½-mile from the subject site. Based on the nature of the listings and/or the distance of the orphan sites from the subject site, none of the orphan sites appear to present a recognized environmental condition with respect to the subject site.

7.3.2 Local Agencies

Petra reviewed information held by the agencies listed below during the course of this investigation.

A. San Bernardino County Fire Department Hazardous Materials Division

The San Bernardino County Fire Department Hazardous Materials Management Division maintain records related to underground storage tanks and medical waste, hazardous materials, hazardous waste and waste oil generators/handlers in the County of San Bernardino. Records held by these agencies were accessed by EDR during the government database search. Sites with listings of concern were discussed above.

B. California Regional Water Quality Control Board

The California Regional Water Quality Control Board - Santa Ana Region (RWQCB) maintains records of leaking underground storage tanks sites and groundwater cleanups for sites in the City of Colton in San Bernardino County. Records held by the CRWQCB were accessed by EDR during the government database search. Sites with listings of concern were discussed above.

C. Geotracker

The Geotracker website maintains a record of environmental data for regulated facilities in California. Three database listings for the subject site were reported on Geotracker. The listed sites were for the gas station located at 1600 Valley Boulevard, Telco Foods at 2111 W. Valley Boulevard, and Bishop's Central Stores at 791 N. Pepper Avenue. A discussion of these sites follows:

- The gas station at 1600 Valley Boulevard is listed as a former Shell Station (it is currently a Valero station). The station has a permitted UST. It also had a release that impacted soil only and has received agency closure. According to the closure report, groundwater was not encountered up to the total depth drilled of 136 feet below grade.

- The Telco Foods listing is for the removal of three 20,000-gallon tanks with agency closure. No remediation was required for the site.

- The Bishop's Center Store listing is for the location of a permitted UST.

Based on information presented on the Geotracker website, no vicinity sites appear to represent a recognized environmental condition with regards to the subject site.

Petra attempted to find additional information to evaluate the following vicinity sites with regards to impacting the subject site, but no useful information was obtained:

- Arrowhead Medical Center at 400 N. Pepper Avenue
- Chevron Station #9-6969, 101 Valley Boulevard (Rialto)

Selected information from the Geotracker website is include in Appendix C.

D. Federal Emergency Management Agency

According to the Federal Emergency Management Agency (FEMA) Flood Map Panel 06071C8678F, dated March 18, 1996, the subject site is designated as Zone X (unshaded). Unshaded Zone X is designated as areas determined to be outside the 500-year floodplain. The memorandum documenting this inquiry is included in Appendix B.

E. California Division of Oil, Gas, and Geothermal Resources

According to the California Division of Oil, Gas, and Geothermal Resources (DOGGR) Wildcat Maps W1-4 and W1-7 (2000), there are no active or abandoned oil, gas, water flood, water disposal, or steam wells located on the subject site. Further, there were no indications of any such wells found during our reconnaissance of the subject site. The memorandum documenting this inquiry is included in Appendix B.

7.3.3 Evaluation of Records Search Results

In summary, 12 sites were identified in our search of various government agency database records which may have impacted the soils or groundwater beneath the subject site or have the potential to impact the subject site. These facilities are as follows:

- California Auto Specialist/Inland Empire Toyota/Budget Truck Rental, 1700 W. Valley Boulevard. Due to this facility having USTs, it is considered a potential environmental concern for the subject site.

- McNeilus Truck & Manufacturing Inc., 401 N Pepper Avenue. Due to this facility being listed on the CA WDS database, it is considered a potential environmental concern for the subject site.

- Bishop's Cental Stores / Colton Bishop Store House, 791 N. Pepper Avenue. Due to this site having USTs and ASTs, it is considered a potential environmental concern for the subject site.

- Orange Shell - Colton / Zakaria Haggag / Shell Service Station, 1600 W. Valley Boulevard. Due to a former release and this facility having USTs, it is considered a potential environmental concern for the subject site.

- Moss Bros. Ford, 1900 W. Valley Boulevard. Due to this facility having ASTs, it is considered a potential environmental concern for the subject site.

- Grace WR & Co. Distribution Services / Sammon's Trucking, 1988 W. Valley Boulevard. Due to this facility having a UST, it is considered a potential environmental concern for the subject site.

- Colton Auto Sales / Western Exterminator Company, 1998 W. Valley Boulevard. Due to this facility having a UST, it is considered a potential environmental concern for the subject site.

- Brad & Carol Larsen / Sierra Diesel Repair, 2006 W. Valley Boulevard. Due to this site having both a AST and UST, it is considered a potential environmental concern for the subject site.

- County of San Bernardino, 1500 W. San Bernardino Avenue. Due to the potential presence of either a AST or UST, this site is considered a potential environmental concern for the subject site.

- Oroweat Foods Co/Bimbo Bakeries USA, Inc./Bestfoods Baking Company, 2036 W. Valley Boulevard. Due to the presence of a UST, this site is considered a potential environmental concern for the subject site.

- Price Club/Telco Foods,, 2109/2111 W. Valley Boulevard. Due to the potential presence of USTs and the facility having a reported release, this site is considered a potential environmental concern for the subject site.

- Arrowhead Regional Medical Center, 400 N. Pepper Avenue. Due to the presences of USTs and the facility being on the SLIC database, this site is considered a potential environmental concern for the subject site.

- Chevron Station #9-6969, 101 Valley Boulevard (Rialto). Due to the LUST listing showing drinking water to have been impacted, and the lack of information regarding this impact, this site is considered a potential environmental concern for the subject site.

7.4 Results of Aerial Photo Analysis

Although aerial photographs can often be a valuable source of information in the assessment of historical land usage, it should be understood that information extrapolated from photographic images is strictly interpretation and not necessarily fact. For this reason, it may not be appropriate to draw conclusions regarding previous site activities based solely upon aerial photograph analysis.

In order to provide a complete updated assessment of historical land usage on and in the vicinity of the subject site, aerial photographs with coverage of the subject site and vicinity were obtained from EDR and viewed by a representative of this firm. Photographs from the years 1930, 1938, 1953, 1966, 1978, 1999, 1995, and 2002 were provided by EDR. A summary of the information obtained during the aerial photograph review follows. Copies of the aerial photographs obtained from EDR are included in Appendix C.

1930 and 1938

In the 1930 photograph, the majority of the site appears as vacant, disced land, possibly used for dry farming and/or grazing activities. West Valley Boulevard is present

crossing from east to west on the southern portion of the site. Dirt roads are visible crossing the site from the north to the south, and from the northwest to the southeast. Groves(possibly citrus) are present on the northeastern portion and parts of the eastern portion of the site. At least two structures are visible in the areas of the groves located on the eastern portion of the site. The westernmost portion of the site does not appear on the 1930 photograph. Similar land use is visible adjacent to the north, south, and east.

On the 1938 photograph, the site appears similar to that observed on the 1930 photograph. Groves are visible on the southwestern portion of the site. A structure is visible in the center of the site.

1953

In the 1953 photograph, the only agricultural land use on the site appears to be a grove on the southwest corner and possibly a small area on the northeast corner of the site. A small airfield is present on the western portion of the site (Morrow Field). The airstrip crosses from off-site onto the western portion of the site. Structures associated with the airfield are present on the western portion of the site, south of the runway. Additional structures are visible along the southern and eastern portions of the site. There is an increase in dirt roads crossing the site.

The I-10 freeway is visible along the southern boundary of the subject site. The agricultural land located east of the site has been replaced with residential tracts.

1966

In the 1966 photograph, a rectangular man-made water feature appears on the western portion of the site (Colton Recreational Lake), south of the airstrip. A golf course with two small ponds is visible to the east of the water feature. A large structure (warehouse-type) has been constructed at the 2245 W. Valley Boulevard address, replacing the grove previously located there. The northeast corner of the site appears to be divided up into small sections as if to contain livestock. There are a few areas that have been cleared of vegetation, primarily on the southern and western portions of the site. Additional structures and development appears south of West Valley Boulevard and in the southeastern corner of the site.

Commercial or light industrial development is visible to the west of the southwestern portion of the site. San Bernardino Avenue, located adjacent to the northern boundary of the site, appears to be paved.

1978

In the 1978 photograph, the site and vicinity appear similar to that observed on the 1966 photograph; with the exception of a slight increase in the number of structures and development located south of W. Valley Boulevard. The structure at 2245 W. Valley Boulevard has been expanded. Additional structures have been constructed primarily on the southern and eastern portions of the site. The structure at 791 Pepper Avenue has been constructed. The outline of the rectangular water feature is present but no water is visible. What appears to be rows of structures are present south of the former lake. North Pepper Avenue which runs adjacent to the central eastern border appears paved in this photograph. High density residential development is observed approximately 600 feet northwest of the subject site.

1989

In the 1989 photograph, the airfield has been removed. The large structures at 2111 W. Valley Boulevard and 401 Pepper Avenue, as well as several smaller structures across the site, have been constructed. Wildrose Avenue, Woodpine Avenue, and Indigo Avenue have been constructed. High density residential tracts and apartment buildings are visible north of the site, beyond San Bernardino Avenue.

1995

In the 1995 photograph, the site and vicinity appear similar to that observed on the 1989 photograph. The Arrowhead Regional Medical Center is being constructed off-site to the east of the east-central portion of the site.

2002

In the 2002 photograph, the site and vicinity appears similar to that observed on the 1995 photograph. The structures, vacant areas, golf course, and former pond area that were observed during the site reconnaissance are present: the large warehouse-type structures on the western portion of the site are visible, the central portion of the subject site is occupied by a golf course, remnant of a dry lake, and undeveloped land, the southern edge of the site is occupied by structures and development, the eastern portion of the site is occupied by vacant land and commercial or light industrial land use, and the northern portion of the site appears mostly undeveloped.

The general vicinity of the area surrounding the site appears to be predominantly residential to the north and to the east. A medical center structure is visible across

North Pepper Avenue to the east of the east-central portion of the subject site. The I-10 freeway is located along the southern boundary of the site and San Bernardino Avenue is located along the northern boundary of the site.

7.5 Historical USGS Topographic Maps

Petra reviewed historical USGS topographic maps of the site and vicinity researched and provided by EDR (1901, 1954, 1967, 1973, and 1980). Copies of the maps reviewed are provided in Appendix C.

On the 1901 map, streets are shown crossing the general site area from north to south and east to west. Also, one structure is shown on the eastern portion, in the location of one of the groves areas, on the 1901map.

On the 1954 map, Morrow Field is shown crossing the western portion of the site. Groves are shown on the southwestern portion of the site. A few small individual structures are shown on the eastern edge, southwest portion, and center portion of the site. Several structures of various sizes are shown south of W. Valley Boulevard.

On the 1967 map, the golf course, Colton Recreational Lake, the larger structure at 2245 W. Valley Boulevard, and several smaller structures south of West Valley Boulevard are shown.

On the 1973 map, the structure at 2245 W. Valley Boulevard has been expanded and the number of structures south of West Valley Boulevard have increased.

On the 1980 map, the number of structures on the site have increased and Morrow Field is listed as abandoned. The Colton Recreational Lake is listed but not shown.

7.6 Environmental Liens & Activity and Use Limitations

Environmental Liens and Activity and Use Limitations (AUL) indicate restrictions on a property which may represent a recognized environmental condition for the subject site. A search for Environmental Liens and AULs was not conducted by Petra during this investigation. **This search should be conducted prior to the purchase of any of the site properties.**

7.7 Fire Insurance Maps and City Directories

Fire Insurance Maps provide information on structure locations and operations which were present at the time of the survey. These maps were completed for most major cities and metropolitan areas, dating from 1867, and provide information into past usage of buildings and how commercial and industrial zoning has changed over time. Sanborn™ Fire Insurance maps were requested for this study. EDR reports that no Sanborn™ Fire Insurance map coverage is available for the site. The memorandum documenting this inquiry is included in Appendix C.

City Directories provide information for a specific address at a specific time. The directories were searched back to 1922. Residential and commercial listings for the area start in 1941. An address locating website such as Google Map was used to determine the location of some addresses. Based on the age of these listings and new development which has taken place since the time of listings, it is difficult to determine the exact location of each listing. Since several site boundaries are marked by roads, please note that some listings mentioned below may or may not fall within the boundary of the subject site. A possible ranch, located along the eastern boundary (Hermosa Avenue) is listed in 1946. Two gas stations and a car dealership are listed in 1975 to be on the subject site, along West Valley Boulevard. A carpet and upholstery cleaning company is listed in 1990 to be located along San Bernardino

Avenue (the northern boundary). A tire company is listed to be located along Hermosa Avenue in 1991 (the eastern boundary). Three automotive body shops are listed in 2003 to be located on the subject site along Rexford Street.

7.8 Interviews

Since Petra was not granted access to the site structures, no managers or owners, were interviewed as part of this investigation.

7.9 Data Failures and Data Gaps

In the event that data gaps are identified, the Environmental Professional (EP) will endeavor to comment on the significance of those data gaps. However, the EP cannot, and does not warrant or guarantee that no significant events, releases, or conditions arose, during periods such as data gaps.

Petra reviewed several sources for historical information regarding the subject site. These sources included a government agency database search and a review of historical aerial photographs and historical USGS topographic maps. No fire insurance maps are reported to be available for the site.

Several areas of investigation had limited information which could be considered a data failure (lack of information in one particular area of historical research for the site). These areas include a reconnaissance of the facilities on the site, interviews with owners and managers of these facilities, a review of any documents at the local regulatory agencies for the site address such as the RWQCB or San Bernardino County Fire Department, and information regarding the nature of the SLIC listing for the Arrowhead Regional Medical Center. ***Due to these data failures, there is a data gap (lack of information in all areas of historical research for the site) with regards to***

confirming which sites would be considered a recognized environmental condition to the subject site.

8.0 DISCUSSION OF POTENTIAL ENVIRONMENTAL CONCERNS

The following discussions of potential environmental concerns are presented to inform the client as to the existence, or lack thereof, of recognized environmental conditions present on the subject site.

8.1 Regulatory Actions

Based upon a thorough search of available federal, state, and local records, current regulatory action pending with respect to the subject site appears to be limited to permits for various on-site activities.

8.2 Adjacent and Nearby Properties

The following two sites were identified which would indicate the presence of recognized environmental conditions adjacent to the subject site that are considered likely to pose a significant impact to soils or groundwater beneath the subject site:

- The Arrowhead Regional Medical Center, located at 400 N. Pepper Avenue, was listed on the SLIC database. No additional information was obtained during this investigation to establish why it is on this database.

- Chevron Station #9-6969, 101 Valley Boulevard (Rialto). A release which impacted groundwater was reported. Although the case received closure in 1993, no additional information was obtained during this investigation to determine the facility's potential impact to groundwater on the subject site.

It is recommended that a file review be conducted at the RWQCB and San Bernardino County Fire Department to obtain additional information regarding these facilities.

8.3 Polychlorinated Biphenyls

Both pole-mounted and pad-mounted transformers were observed on the site. It is unknown if they contain PCBs. If the transformers are to be removed, it is recommended that the removal be completed by a licensed contractor or the utility company responsible for the transformers.

While the interior of the buildings were not observed, it is likely that they contain fluorescent light fixtures which may have ballasts containing PCBs. Additionally, fluorescent light tubes contain trace amounts of mercury.

8.4 Underground Storage Tanks and Above Ground Storage Tanks

The following addresses were identified as currently or historically having UST or AST:

- 1500 W. San Bernardino Avenue, County of San Bernardino
- 791 N. Pepper Avenue, Bishop's Cental Stores / Colton Bishop Store House
- 1700 W. Valley Boulevard, California Auto Specialist/Inland Empire Toyota/Budget Truck Rental
- 1600 W. Valley Boulevard, Valero Service Station
- 1900 W. Valley Boulevard, Moss Bros. Ford
- 1988 W. Valley Boulevard, Grace WR & Co. Distribution Services/Sammon's Trucking
- 1998 W. Valley Boulevard, Colton Auto Sales/Western Exterminator Company
- 2006 W. Valley Boulevard, Brad & Carol Larsen/Sierra Diesel Repair

- 2036 W. Valley Boulevard, Oroweat Foods Co/Bimbo Bakeries USA, Inc./Bestfoods Baking Company
- 2109/2111 W. Valley Boulevard, Price Club/Telco Foods

It is recommended that these facilities be inspected. The ASTs should be inspected to confirm they are placed within secondary containment units. The most current UST fit test documents should be reviewed to confirm the USTs have not had any indications of a release.

8.5 Storm Water/Waste Water Discharge

Storm water/waste water discharge from the site appears to be limited to surface water storm runoff and human sewage. However, the site facilities should be inspected to confirm there is no other waste water discharge. It is also unknown if septic tanks were historically present on the site. If encountered during grading operations, they should be removed and disposed of in accordance with current regulations.

8.6 Pesticide and Herbicide Residues

Groves were historically located on portions of the subject site. No information was obtained regarding pesticide and herbicide use in these areas. Therefore, pesticide and herbicide residues present a potential environmental concern with regards to the subject site. Sampling of the near-surface soils should be conducted in these areas to evaluate the potential for impact from past pesticide and herbicide use.

8.7 Asbestos-Containing Materials and Lead-Based Paints

While the structures were not inspected for asbestos-containing materials and lead-based paints, it is likely that the older (pre-1980's) structures contain these materials. It is recommended that the buildings be assessed for asbestos-containing materials prior to any demolition. If present, asbestos-containing materials should be abated prior to

demolition in accordance with current regulations. The soil drip-lines of any structures should also be tested for lead-based paints.

Due to the historical presence of groves located on the site, it is possible that underground transite (asbestos-containing) irrigation pipes are present. If any transite pipes are encountered during grading, they should be removed intact and disposed of in accordance with current regulations.

8.8 Landfills

The EDR report does not list any known landfills on the subject site. Landfills identified off the site do not appear to represent a recognized environmental condition with regards to the subject site.

8.9 Waste Generation and Storage

Miscellaneous debris was observed and included plastic, metal, wood, concrete, PVC pipes, a boat, tiles, furniture, landscape waste, carpet, dry wall, brick and other building materials, over 100 tires, asphalt, car parts, household items, motor oil bottles, five-gallon containers of paint, and trash. Two 55-gallon drums were observed in the former recreation pond. They were partially buried and appeared burnt from a recent small brush fire. The contents of the drums are unknown. It is recommended that the debris on the site be removed and disposed of in accordance with current regulations. The area under the debris should be inspected for staining.

9.0 CONCLUSIONS

At the client's request, the site structures and most of the site parcels were not entered into and the site reconnaissance was completed as a "drive-by/fence-line" investigation. The conclusions discussed in this section are based on limited available information;

it is possible that a reconnaissance of the interior of the properties will change these conclusions.

9.1 General Site Information

1. The site is an irregular shaped parcel roughly bounded by San Bernardino Avenue to the north, city boundaries between Colton and Rialto to the west, by the I-10 freeway to the south, and by both Pepper Avenue and Hermosa Avenue to the east in the City of Colton, San Bernardino County, California. The subject site is comprised of approximately 353 acres. At the time of our investigation, the site consisted of vacant land, a golf course, residential homes, commercial/retail businesses, office complexes, and what appeared to be light industrial land use.

2. Based on information obtained during this investigation, the site appears to have been used for dry farming/grazing activities, possibly as early as the 1900's. Small groves were present on the southwestern, southeastern, and northeastern portions of the site in the 1930's. The southwestern grove was present until at least the mid-1950's. Morrow Field (a single runway airfield) was constructed on the subject site in 1942. The airfield was abandoned by 1980. The Colton Golf Club and the former Colton Recreational Lake were constructed on the site in the 1960's. The residential structures currently located on the northeastern portion of the site appear to have been present since at least the 1950's. In the 1960's, the far northeast corner of the site appeared to have been used for livestock corrals. Commercial-type structures began appearing on the site in the 1950's, primarily south of W. Valley Boulevard. By the late-1980's most of the structures present today had been constructed. Historical information dating back to 1901 was reviewed during this investigation.

3. Several pole-mounted and pad-mounted transformers were observed on the site. It is unknown if the transformers contain polychlorinated biphenyls (PCBs).

4. Much of the site was vacant land. Miscellaneous debris was observed and included plastic, metal, wood, concrete, PVC pipes, a boat, tiles, furniture, landscape waste, carpet, dry wall, brick and other building materials, over 100 tires, asphalt, car parts, household items, motor oil bottles, five-gallon containers of paint, and trash. Two 55-gallon drums were observed in the

former recreation pond. They were partially buried and appeared burnt from a recent small brush fire. The contents of the drums are unknown.

9.2 Recognized Environmental Conditions

Recognized environmental conditions are defined by the American Society of Testing and Materials (ASTM) as any hazardous substance or petroleum product under conditions that indicate an existing, past, or material threat of release into the structures, ground, groundwater, or surface water at the subject site. If the presence of recognized environmental conditions are identified on a subject site, it may warrant additional research, site investigation, and/or action.

The following sites have had past releases which would catagorize them as recognized environmental conditions.

- 1600 W. Valley Boulevard, Former Shell/Valero Gas Station (part of the subject site). This facility had a reported release which has received agency closure.
- 2109/2111 W. Valley Boulevard, Price Club/Telco Foods (part of the subject site). This facility had a reported release which has received agency closure.

9.3 Potential Environmental Conditions

Potential environmental conditions pertain to any hazardous substance or petroleum product under conditions that suggest the possibility of an existing, past, or material threat of release into the structures, ground, groundwater, or surface water at the subject site, but for which not enough information was available through the means within the scope of this report. The identified presence of potential environmental conditions at the subject site may warrant additional research, site investigation, and/or action. Those items identified at the subject site or nearby properties, which are potential environmental conditions relative to the subject site are discussed below.

1. Although no obvious indications of recognized environmental conditions were identified, the following addresses are considered to be likely potential environmental concerns to the site due to the nature of the business or other observations made during Petra's site reconnaissance:

   - 401 Pepper Avenue, McNeilus Truck and Manufacturing
   - 791 Pepper Avenue, Bishop Central Storehouse-LDS Church.
   - 310 Rexford Street, Transport Components Rebuilder
   - 313 Rexford Street, Republic Machine and Fabrication
   - 319 Rexford Street, 5 Star Auto Body
   - 320 Rexford Street, AMCAl Machine Shop
   - 1313 W. Valley Boulevard, City Truck Yard
   - 1630 W. Valley Boulevard, Chadwick Auto Wholesale
   - 1700 W. Valley Boulevard, I-10 Auto Sales/ Budget Car Rental
   - 1849 W. Valley Boulevard, Stevens Transport
   - 1900 W. Valley Boulevard, Moss Bros Ford
   - 2084 W. Valley Boulevard, PYP Hot Rod Shop/Ben Warner Towing
   - 2111 W. Valley Boulevard, Telco Food Products
   - Burned structures along W. Valley Boulevard (adjacent to "The Hub").

   It is recommended that these facilities be inspected to confirm that they do not have the potential to adversely impact the subject site.

2. These sites have not had a reported release; however, the following facilities appear to have USTs and /or ASTs which could represent a potential concern should they have a release.

- 1500 W. San Bernardino Avenue, County of San Bernardino
- 791 N. Pepper Avenue, Bishop's Cental Stores / Colton Bishop Store House
- 1700 W. Valley Boulevard, California Auto Specialist/Inland Empire Toyota/Budget Truck Rental
- 1600 W. Valley Boulevard, Valero Service Station
- 1900 W. Valley Boulevard, Moss Bros. Ford
- 1988 W. Valley Boulevard, Grace WR & Co. Distribution Services/ Sammon's Trucking
- 1998 W. Valley Boulevard, Colton Auto Sales/Western Exterminator Company
- 2006 W. Valley Boulevard, Brad & Carol Larsen/Sierra Diesel Repair
- 2036 W. Valley Boulevard, Oroweat Foods Co/Bimbo Bakeries USA, Inc./Bestfoods Baking Company

It is recommended that these facilities be inspected. The ASTs should be inspected to confirm they are placed within secondary containment units. The most current UST fit test documents should be reviewed to confirm the USTs have no indications of a release.

3. Based on information obtained from the agency database search, the following on-site facilities are listed as potential environmental concerns:

- 401 N Pepper Avenue, McNeilus Truck & Manufacturing Inc. Although no releases have been reported from this site, it is listed on the CA WDS database as an industrial facility.

- Moss Bros. Ford, 1900 W. Valley Boulevard. This facility reportedly has an above ground storage tank.

- County of San Bernardino, 1500 W. San Bernardino Avenue. This facility may have had either a AST or UST.

- Price Club/Telco Foods,, 2109/2111 W. Valley Boulevard. This facility had a reported release which has received agency closure. It is unknown if USTs are still present at this facility.

It is recommended that these facilities be inspected to confirm that facility activities do not have the potential to adversely impact the subject site.

4. Groves were historically located on portions of the subject site. No information was obtained regarding pesticide and herbicide use in these areas.

It is recommended that sampling of the near-surface soils should be conducted in the former grove areas to evaluate the potential for impact from past pesticide and herbicide use.

5. Based on information obtained from the agency database search, the following off-site facilities are listed as potential environmental concerns:

- Arrowhead Regional Medical Center, 400 N. Pepper Avenue. This facility was included on the SLIC database. No additional information was obtained during this investigation to establish why it is on this database.

- Chevron Station #9-6969, 101 Valley Boulevard (Rialto). This facility reportedly impacted drinking water. No additional information was obtained during this investigation to determine the facility's potential impact to groundwater on the subject site.

It is recommended that a file review be conducted at the RWQCB and San Bernardino County Fire Department to obtain additional information regarding these facilities.

9.4 Site Considerations

Items, if presented below, are not considered recognized environmental conditions in accordance with ASTM 1527-05. Although these items may warrant consideration in conjunction with any planned development activities, they are not recognized environmental conditions. The information regarding possible actions relative to these items has been provided as guidance.

1. Both pole-mounted and pad-mounted transformers were observed on the site. It is unknown if they contain polychlorinated biphenyls (PCBs).

   If the transformers are to be removed, it is recommended that the removal be completed by a licensed contractor or the utility company responsible for the transformers.

2. While the interior of the buildings were not observed, it is likely that they contain fluorescent light fixtures which may have ballasts containing PCBs. Additionally, fluorescent light tubes contain trace amounts of mercury.

   When these items are removed, they should be disposed of in accordance with current regulations.

3. Debris, including two partially buried drums, were observed on the site.

   It is recommended that the debris on the site be removed and disposed of in accordance with current regulations. The area under the debris should be reinpsected for staining.

4. While the structures were not inspected for asbestos-containing materials and lead-based paints, it is likely that the older (pre-1980's) structures contain these materials.

   It is recommended that the buildings be assessed for asbestos-containing materials prior to any demolition. If present, asbestos-containing materials should be abated prior to demolition in accordance with current regulations. The soil drip-lines of any structures should also be tested for lead-based paints.

5. Due to historical presence of groves located on the site, it is possible that underground transite (asbestos-containing) irrigation pipes are present.

If any transite pipes are encountered during grading, they should be removed intact and disposed of in accordance with current regulations.

6. It is unknown if septic tanks were historically present on the site.

If encountered during grading operations, they should be removed and disposed of in accordance with current regulations.

10.0 LIMITATIONS

This investigation is based upon the project as described and the environmental data obtained from the field reconnaissance and research performed as outlined in this report. This report has not been prepared for use by parties or projects other than those named or described in this report, additional studies may be required.

Since our investigation is based upon a review of available data and inspection of the site, without any invasive investigation, the conclusions presented herein are professional opinions. These opinions have been derived in accordance with current standards of practice, and no warranty is expressed or implied.

This firm's evaluation of previous reports and/or subconsultant reports focuses on the completeness of the information presented in the document, in accordance with applicable rules and regulations, and does not include the establishment of data sufficiency or accuracy.

11.0 QUALIFICATIONS

Resumes for the staff who contributed to this report are presented in Appendix E.

"We the undersigned declare that, to the best of our professional knowledge and belief, we meet the definition of Environmental Professional as defined in § 312.10 of 40 CFR 312. We have the specific qualification based on education, training, and experience to assess a property of the nature, history, and setting of the subject site. We have developed and performed the all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312."

Callie L. Cullum
Project Geologist
REA 7511

Brian Villalobos
Division Manager
CEG 1298

12.0 REFERENCES

CALIFORNIA DEPARTMENT OF CONSERVATION, DIVISION OF OIL, GAS, AND GEOTHERMAL RESOURCES, 2000, Wildcat Map W1-7.

CALIFORNIA DEPARTMENT OF WATER RESOURCES, 2008, http://wdl.water.ca.

ENVIRONMENTAL DATA RESOURCES, INC., 2008, " EDR Aerial Photo Decade Package, Colton Super Block, San Bernardino Avenue/North Pepper, Colton CA, 92324," (Inquiry No. 2165111.5).

ENVIRONMENTAL DATA RESOURCES, INC., 2008, "EDR Certified Sanborn® Map Report, Colton Super Block, San Bernardino Avenue/North Pepper, Colton CA, 92324," (Inquiry No. 2165111.3s)

ENVIRONMENTAL DATA RESOURCES, INC., 2008, "EDR City Directory Abstract, Colton Super Block, San Bernardino Avenue/North Pepper, Colton CA, 92324," (Inquiry No. 2165111.6)

ENVIRONMENTAL DATA RESOURCES, INC., 2008, "EDR Historical Topographic Map Report, Colton Super Block, San Bernardino Avenue/North Pepper, Colton CA, 92324," (Inquiry No. 2165111.4)

ENVIRONMENTAL DATA RESOURCES, INC., 2008, "EDR Radius Map, Colton Super Block, San Bernardino Avenue/North Pepper, Colton CA, 92324," (Inquiry No. 2165111.5)

FEDERAL EMERGENCY MANAGEMENT AGENCY (FEMA), 2008, "Flood Insurance Rate Maps (FIRM)," http://msc.fema.gov

GEOTRACKER, 2008, http://geotracker.swrcb.ca.gov/

MORTON, D.M., MILLER, F.K.; 2006, "Geologic m ap of the San Bernardino and Santa Ana 30' x 60' Quadrangles, California, Open File Report 20006-1217."

UNITED STATES GEOLOGICAL SURVEY, 1963, "Geologic and Hydrologic Features of the San Bernardino Area, California, Geological Survey Water Supply Paper 1419, Prepared in cooperation with the San Bernardino County Flood Control District."

UNITED STATES GEOLOGICAL SURVEY, 1967 (photorevised 1980), 7.5 Minute Topographic Map, San Bernardino South, California, Quadrangle.

FIGURES

PETRA



SITE LOCATION MAP

Ref: Portion of USGS SAN BERNARDINO SOUTH QUADRANGLE,
7.5 Minute Topographic Series 1967,
(Photorevised 1980)
SCALE: 1 inch = 2000 feet

PETRA
Environmental Division

JN 149-08

FIGURE 1



SITE MAP

PETRA
Environmental Division

JN 149-08
FIGURE 2

PLATE A

SITE PHOTOGRAPHS

PETRA

Facility located at 491 Wildrose Avenue.

Facility Located at 2040 Woodpine Avenue.

View Southwest Across Historical Recreation Pond Area, Note Shacks.

Two 55-gallon Drums Located in the Parcel Adjacent to the South of 2040 Woodpine Avenue.

View West Across George E. Brown Jr. Park Located Along the Northern Boundary of the Site.

View of Drainage Area at the Southeastern Corner of the Park.

View South Down a Dirt Road Located Along the Eastern Edge of the Park and Golf Course.

Debris Located in the Vacant Area of the Site, East of the Golf Course.

Tires Located on the Burnt Area Adjacent to the West of 2001 W. Valley Boulevard.

Debris Pile Located on the Burnt Area Adjacent to the West of 2001 W. Valley Boulevard.

Arrowhead Regional Medical Center Village Located Southeast of Pepper Avenue and San Bernardino Avenue.



View East Along West C Street from the intersection of West C Street and Meridian Avenue.



View of 791 Pepper Avenue.

View of Concrete Barrels Located at the Rear of 401 Pepper Avenue.

View of the Eastern Side of Rexford Street From Valley Boulevard.

View North Along an Un-named Street With Joint School District Yard Located on the West.



Well Structure Located on the Southwestern Corner of the Site.

Valley Truck, Filters and Parts Located at 2006 W. Valley Boulevard.

Residences and Businesses Located at 2012-2018 W. Valley Boulevard.

View South From the Southwestern Corner of the Intersection of Valley Boulevard and Pepper Avenue, Note Valero Station.

APPENDIX A

SITE INSPECTION CHECKLIST

PETRA

PETRA GEOTECHNICAL, INC.
Environmental Division
3185-E Airway Avenue, Costa Mesa, CA 92626 * Phone (714) 549-8921 * Fax (714) 540-7572

PHASE I ESA SITE INSPECTION CHECKLIST

J.N. 149-08 **Start: Time**_____ **Miles**_____

Date: 4/30/08 **Finish: Time**_____ **Miles**_____

1. **Site Information** San Bern Ave (N), Riverside (W), I-10 (S)
   - Address: Hermosa (E), Colton, CA
   - Parcel Size: ≈ 253 acres
   - Facility Size: various
   - Map Reference: Thom. Bros. Pg 605+606
   - Owner: various

2. **Site Description**
   - Topographic Conditions: overall slope to south
   - Obvious Geologic Features: —
   - Estimated % of Site Covered by Buildings and Pavement: < 20%
   - Ground Cover: mix vegetation
   - Type and Condition of Pavement: asphalt - mod to good
   - Roads and Parking Facilities: numerous dirt + paved roads, parking lots for businesses.
   - Structures: see attached list
   - Description of Obstructions: not allowed on properties

3. **Indications of Current Site Use(s)**
   - ☐ Agriculture ☒ Industrial ? ☒ Commercial/Retail
   - ☐ Residential ☐ Undeveloped ☐ No indications of current use
   - ☒ Other: golf course, vacant land, residential

4. **Indications of Previous Site Use(s)**
   - ☐ Agriculture ☐ Industrial ☐ Commercial/Retail
   - ☐ Residential ☒ Undeveloped ☐ No indications of prior use
   - ☒ Other: pond area (Colton Res. Lake)
     No obvious signs of oil fields

PHASE I ESA SITE INSPECTION CHECKLIST

PAGE NOT APPLICABLE ☐

5. **Indications of Current Adjacent Land Use**

North: ~~vacant~~ San Bernardino Ave

South: I-10 Freeway

East: A.R.M.C., Hermosa Cemetery, self storage, Railroad tracks

West: Residential, Endangered species area, Retail

6. **Indications of Previous Adjacent Land Use**

North: _____

South: none

East: ~~Residential~~

West: _____

7. **Indications of Vicinity Adjacent Land Use**

North: Residential, Retail, Park, Water Well

South: Railroad, Industrial

East: Residential

West: Commercial, lt. industrial, Retail

8. **Potential Sensitive Receptors (Wells, Streams, Schools, etc.) and Location Relative to the Site**

several wells on & near site

PHASE I ESA SITE INSPECTION CHECKLIST

PAGE NOT APPLICABLE ☐

9. **Tanks/Containers (include tanks, drums, labeled and unlabeled containers)**

Approximate Capacity	Contents	Tank Composition	Location on Site
6 - ≥20,000gal	?	Steel?	791 Pepper
"	"	"	401 Pepper
2 - ≥10,000gal	"	"	1111 Valley
More likely to be present			

10. **Indications of USTs (fill pipes, vents, etc.)** ☐ Yes ☐ No

Unable to access properties - likely to be present. Expect Valero gas station to have them.

11. **Indications of Other Underground Structures (e.g. clarifiers, wells, dry wells, septic systems, etc.)** ☐ Yes ☐ No

Unable to access properties

12. **Indications of PCB-containing equipment or potential PCBs-containing equipment (e.g. electrical equipment, hydraulic equipment, transformers, etc.)** ☒ Yes ☐ No

Numerous pole- & pad-mounted transformers on site

PAGE NOT APPLICABLE ☐

13. **Surface Staining (appearance, location, approximate size)** ☐ Yes ☐ No

Not in areas observed

14. **Pits, Ponds, Lagoons, Pools of Liquid (description/location)** ☐ Yes ☐ No

Not in areas observed

15. **Odors** ☐ Yes ☒ No

16. **Stressed Vegetation (from something other than insufficient water)** ☐ Yes ☒ No

17. **Solid Waste/Refuse/Evidence of Dumping (description, location, approximate amount)** ☒ Yes ☐ No

Primarily in vacant areas near roads.

May contain ACMs + LBPs

PHASE I ESA SITE INSPECTION CHECKLIST

PAGE NOT APPLICABLE ☐

18. **Evidence of Hazardous Materials, Hazardous Waste, or Petroleum Products** ☒ Yes ☐ No

a few cans of paints & motor oil

19. **Public Services**

a. Potable Water Supply: City

b. Sewage Disposal System: City

c. Storm Water Runoff: into gutters & soil

d. Waste Water: unknown

20. **Site Observations**

See attached list

21. **Site Sketch**



491 Wildrose Avenue - EJK Center
Unit A - Dannybuilt Truckmounts
Unit C - Snap-On Auto Training Academy
Unit D - M & B Cooling Specialists
Unit E - Digital Printing
Unit G - Javco Ornamental Works
Unit I - Tata Bouncers
Unit J - Rental Office
Unit M or N - Designs by Davis Furniture
front of building sign (with no specific suite number) - Sheet Metal Work

1750 San Bernardino Avenue - Carpenters Union Membership Training Center
(structure is vacant, for sale sign outside)
San Bernardino Avenue/ Pepper Avenue - Arrowhead Regional Medical Center (ARMC)
Village (portable buildings)

C Street - 625, 635, 645, 1225, 1227, 1245, 1265 all residences
1275 W. C Street - RAI Care Center

791 Pepper Avenue - Bishop Central Storehouse, LDS Church (phosphine? gas tank in back of property)
401 Pepper Avenue - McNeilus Truck & Manufacturing (MTM) (manufacturer of cement trucks?-cement truck barrels in back) (Note: large AST in back may be part of LDS property)
1099 Pepper Avenue - World Prophetic Ministry Church
(The King is Coming Auditorium, 2 pad mounted transformers)

220 Rexford - Auction Meat and Seafood
299 Rexford - vacant?
310 Rexford - Transport Components Rebuilder
313 Rexford - Republic Machine and Fabrication
319 Rexford - 5 Star Auto Body
320 Rexford - AMCAL Machine Shop (at least one hoist in back)

235 Hermosa Avenue - ? RV related business
295 Hermosa Avenue - Acacia RV Performance Center
325 Hermosa Avenue - Slover Mountain High School
345 Hermosa Avenue - residence (another 3 residences adjacent, no addresses)

2040 Woodpine Avenue - County of San Bernardino Department of Public Social Services

1205 W. Valley Boulevard - Vacation Station RV
1295 W. Valley Boulevard - Spas & Pools
1313 W. Valley Boulevard - City Truck Yard
1405 W. Valley Boulevard - Colton Music Center (Piano City)
1600 W. Valley Boulevard - Valero
1620 W. Valley Boulevard - Baker's
1630 W. Valley Boulevard - Chadwick Auto Wholesale
1700 W. Valley Boulevard - I-10 Auto Sales/ Budget Car Rental
1759 W. Valley Boulevard - Auction Meats
1763 W. Valley Boulevard - Auction Meats and Seafood
1849 W. Valley Boulevard - Stevens Transport
1900 W. Valley Boulevard - Moss Bros Ford
1901 W. Valley Boulevard - Colton Golf Club
2001 W. Valley Boulevard - Hub Cocktail
Burned area adjacent to west of the Hub, possibly former storage area???
2006 W. Valley Boulevard - Valley Truck Filters and Parts, Engine Overhaul
2010 W. Valley Boulevard - Antique Furniture Auction
2012 W. Valley Boulevard - Marques Signs
2014, 2016, 2018 W. Valley Boulevard - residences
2036 W. Valley Boulevard - Oroweat/Entenmann's Bakery Outlet
2042 W. Valley Boulevard - Rodeway Motel
2048 W. Valley Boulevard - Landjet Motor Carriers
2084 W. Valley Boulevard - PYP Hot Rod Shop, Hot Rod and Race Car Fabrication, Shoes, Ben Warner Towing, Well 18A
2111 W. Valley Boulevard - Bakery (Telco Foods), ASTs, pad mounted transformers, ammonia
2245 W. Valley Boulevard - Contractor's Warehouse

APPENDIX B

AGENCY SEARCH RESULTS

PETRA

The EDR Radius Map
with GeoCheck®

Colton Super Block
San Bernardino Avenue/North Pepper Avenue
Colton, CA 92324

Inquiry Number: 02165111.2r

March 12, 2008

EDR® Environmental
Data Resources Inc

The Standard in Environmental Risk Information

440 Wheelers Farms Road
Milford, Connecticut 06461

Nationwide Customer Service

Telephone: 1-800-352-0050
Fax: 1-800-231-6802
Internet: www.edrnet.com

FORM-STD-LAR

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	6
Orphan Summary	248
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting SSURGO Soil Map	A-6
Physical Setting Source Map	A-9
Physical Setting Source Map Findings	A-10
Physical Setting Source Records Searched	A-35

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2008 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-05) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

SAN BERNARDINO AVENUE/NORTH PEPPER AVENUE
COLTON, CA 92324

COORDINATES

Latitude (North):	34.073300 - 34° 4' 23.9"
Longitude (West):	117.355430 - 117° 21' 19.5"
Universal Tranverse Mercator:	Zone 11
UTM X (Meters):	467204.2
UTM Y (Meters):	3770145.8
Elevation:	1083 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	34117-A3 SAN BERNARDINO SOUTH, CA
Most Recent Revision:	1980
West Map:	34117-A4 FONTANA, CA
Most Recent Revision:	1980

TARGET PROPERTY SEARCH RESULTS

The target property was not listed in any of the databases searched by EDR.

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

FEDERAL RECORDS

NPL..... National Priority List
Proposed NPL..... Proposed National Priority List Sites
Delisted NPL..... National Priority List Deletions
NPL LIENS..... Federal Superfund Liens
CERCLIS..... Comprehensive Environmental Response, Compensation, and Liability Information System
LIENS 2..... CERCLA Lien Information
RCRA-CESQG..... RCRA - Conditionally Exempt Small Quantity Generator

EXECUTIVE SUMMARY

US ENG CONTROLS..... Engineering Controls Sites List
US INST CONTROL..... Sites with Institutional Controls
DOT OPS..... Incident and Accident Data
US CDL..... Clandestine Drug Labs
US BROWNFIELDS..... A Listing of Brownfields Sites
DOD..... Department of Defense Sites
FUDS..... Formerly Used Defense Sites
LUCIS..... Land Use Control Information System
CONSENT..... Superfund (CERCLA) Consent Decrees
ROD..... Records Of Decision
UMTRA..... Uranium Mill Tailings Sites
ODI..... Open Dump Inventory
DEBRIS REGION 9..... Torres Martinez Reservation Illegal Dump Site Locations
MINES..... Mines Master Index File
TSCA..... Toxic Substances Control Act
SSTS..... Section 7 Tracking Systems
PADS..... PCB Activity Database System
MLTS..... Material Licensing Tracking System
RADINFO..... Radiation Information Database
RAATS..... RCRA Administrative Action Tracking System

STATE AND LOCAL RECORDS

HIST Cal-Sites..... Historical Calsites Database
CA BOND EXP. PLAN..... Bond Expenditure Plan
SCH..... School Property Evaluation Program
LIENS..... Environmental Liens Listing
Notify 65..... Proposition 65 Records
DEED..... Deed Restriction Listing
VCP..... Voluntary Cleanup Program Properties
DRYCLEANERS..... Cleaner Facilities
WIP..... Well Investigation Program Case List
RESPONSE..... State Response Sites
HAULERS..... Registered Waste Tire Haulers Listing

TRIBAL RECORDS

INDIAN RESERV..... Indian Reservations
INDIAN ODI..... Report on the Status of Open Dumps on Indian Lands
INDIAN LUST..... Leaking Underground Storage Tanks on Indian Land
INDIAN UST..... Underground Storage Tanks on Indian Land

EDR PROPRIETARY RECORDS

Manufactured Gas Plants... EDR Proprietary Manufactured Gas Plants
EDR Historical Auto StationsEDR Proprietary Historic Gas Stations
EDR Historical Cleaners.... EDR Proprietary Historic Dry Cleaners

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

EXECUTIVE SUMMARY

FEDERAL RECORDS

CERC-NFRAP: Archived sites are sites that have been removed and archived from the inventory of CERCLIS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

A review of the CERC-NFRAP list, as provided by EDR, and dated 12/03/2007 has revealed that there is 1 CERC-NFRAP site within approximately 1.25 miles of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
GATX RAIL	*20878 SLOVER STREET*	*1/2 - 1 S*	*Z108*	*103*

CORRACTS: CORRACTS is a list of handlers with RCRA Corrective Action Activity. This report shows which nationally-defined corrective action core events have occurred for every handler that has had corrective action activity.

A review of the CORRACTS list, as provided by EDR, and dated 12/12/2007 has revealed that there are 2 CORRACTS sites within approximately 1.75 miles of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
GATX RAIL	*20878 SLOVER STREET*	*1/2 - 1 S*	*Z108*	*103*
FILTER RECYCLING SERVICES INC	*180 W MONTE AVE*	*1 - 2 SW*	*AM173*	*220*

RCRA-TSDF: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

A review of the RCRA-TSDF list, as provided by EDR, and dated 09/11/2007 has revealed that there is 1 RCRA-TSDF site within approximately 1.25 miles of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
GATX RAIL	*20878 SLOVER STREET*	*1/2 - 1 S*	*Z108*	*103*

RCRA-LQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, and dated 09/11/2007 has revealed that there are 3 RCRA-LQG sites within approximately 1 mile of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
GATX RAIL	*20878 SLOVER STREET*	*1/2 - 1 S*	*Z108*	*103*
CALNEV PIPE LINE COMPANY COLTO	*2051 E SLOVER AVE*	*1/2 - 1 SSW*	*AE121*	*137*
Not reported	101 E VALLEY BLVD.	1/2 - 1 WSW	AG138	163

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 09/11/2007 has revealed that there are 12 RCRA-SQG sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
WORLD PROPHETIC MINISTRY	*1099 N PEPPER AVE*	*1/4 - 1/2 NNE*	*K44*	*54*

Lower Elevation	Address	Dist / Dir	Map ID	Page
UNIVERSAL MACK SALES SERVICE	*220 N REX FORD*	*1/8 - 1/4 S*	*A4*	*8*
INLAND EMPIRE TOYOTA	*1700 VALLEY RD*	*1/8 - 1/4 S*	*D8*	*11*
B AND G AUTO SALES	*1630 W VALLEY BLVD*	*1/8 - 1/4 SSE*	*F21*	*30*
SHELL SERVICE STATION	*1600 W VALLEY*	*1/4 - 1/2 SSE*	*F29*	*38*
INLAND EMPIRE EQUIPT, INC	*1762 S SYCAMORE*	*1/2 - 1 WSW*	*V90*	*85*
P S TRUCK SUPPLY INC	*245 E VALLEY BLVD*	*1/2 - 1 WSW*	*AD118*	*134*
CIRCLE K STORE #627	*990 VALLEY BLVD*	*1/2 - 1 ESE*	*126*	*148*
CHEVRON STATION NO 96969	*101 E VALLEY BLVD*	*1/2 - 1 WSW*	*AG134*	*160*
ARCO FACILITY NO 09695	*111 W VALLEY BLVD*	*1/2 - 1 WSW*	*AG143*	*171*
DALE JONES PHOTOGRAPHY	*915 W C ST*	*1/2 - 1 E*	*159*	*197*
CONOCO PHILLIPS COLTON TERMINA	*271 E SLOVER AVE*	*1/2 - 1 SW*	*AK162*	*200*

RCRA-NonGen: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA-NonGen list, as provided by EDR, and dated 09/11/2007 has revealed that there is 1 RCRA-NonGen site within approximately 0.75 miles of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
GRACE WR & CO DISTRIB SVCS	*1988 W VALLEY BLVD*	*1/4 - 1/2 WSW*	*J41*	*51*

ERNS: The Emergency Response Notification System records and stores information on reported releases of oil and hazardous substances. The source of this database is the U.S. EPA.

A review of the ERNS list, as provided by EDR, and dated 12/31/2006 has revealed that there are 5 ERNS sites within approximately 0.75 miles of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
2111 WEST VALLEY BLVD	2111 WEST VALLEY BLVD	1/2 - 1 WSW	R72	72

Lower Elevation	Address	Dist / Dir	Map ID	Page
2051 SLOVER AVE	2051 SLOVER AVE	1/2 - 1 S	Y99	95
2051 W. SLOVER AVENUE	2051 W. SLOVER AVENUE	1/2 - 1 S	Y100	95
2051 SLOVER AVE	2051 SLOVER AVE	1/2 - 1 S	Y101	95
195 E VALLEY BLVD	195 E VALLEY BLVD	1/2 - 1 WSW	AA113	126

HMIRS: The Hazardous Materials Incident Report System contains hazardous material spill incidents reported to the Department of Transportation. The source of this database is the U.S. EPA.

A review of the HMIRS list, as provided by EDR, and dated 10/01/2007 has revealed that there are 5 HMIRS sites within approximately 0.75 miles of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
Not reported	1849 W VALLEY BLVD	1/4 - 1/2 SW	G23	33
Not reported	1849 WEST VALLEY BLVD	1/4 - 1/2 SW	G24	33
Not reported	1849 W VALLEY BLVD	1/4 - 1/2 SW	G25	34
Not reported	1900 SLOVER AVE	1/2 - 1 SSW	AB111	125
Not reported	1900 SLOVER AVE	1/2 - 1 SSW	AB112	126

TRIS: The Toxic Chemical Release Inventory System identifies facilities that release toxic chemicals to the air, water, and land in reportable quantities under SARA Title III, Section 313. The source of this database is the U.S. EPA.

A review of the TRIS list, as provided by EDR, and dated 12/31/2005 has revealed that there is 1 TRIS site within approximately 0.75 miles of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
MCNEILUS TRUCK & MANUFACTURING	***401 N PEPPER AVE***	***1/8 - 1/4 SE***	***C10***	***16***

FTTS: FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act) over the previous five years. To maintain currency, EDR contacts the Agency on a quarterly basis.

A review of the FTTS list, as provided by EDR, and dated 01/15/2008 has revealed that there is 1 FTTS site within approximately 0.75 miles of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
COLTON JOINT UNIFIED SCHOOL DI	***1313 W VALLEY BLVD***	***1/2 - 1 ESE***	***P68***	***70***

HIST FTTS: A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

A review of the HIST FTTS list, as provided by EDR, and dated 10/19/2006 has revealed that there is 1

EXECUTIVE SUMMARY

HIST FTTS site within approximately 0.75 miles of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
COLTON JOINT UNIFIED SCHOOL DI	***1313 W VALLEY BLVD***	***1/2 - 1 ESE***	***P68***	***70***

ICIS: The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

A review of the ICIS list, as provided by EDR, and dated 07/27/2007 has revealed that there is 1 ICIS site within approximately 0.75 miles of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
ALLIANCE COLTON - DREWS SUBSTA	559 PEPPER AVE	1/8 - 1/4 SE	C5	9

FINDS: The Facility Index System contains both facility information and "pointers" to other sources of information that contain more detail. These include: RCRIS; Permit Compliance System (PCS); Aerometric Information Retrieval System (AIRS); FATES (FIFRA [Federal Insecticide Fungicide Rodenticide Act] and TSCA Enforcement System, FTTS [FIFRA/TSCA Tracking System]; CERCLIS; DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes); Federal Underground Injection Control (FURS); Federal Reporting Data System (FRDS); Surface Impoundments (SIA); TSCA Chemicals in Commerce Information System (CICS); PADS; RCRA-J (medical waste transporters/disposers); TRIS; and TSCA. The source of this database is the U.S. EPA/NTIS.

A review of the FINDS list, as provided by EDR, and dated 01/04/2008 has revealed that there are 14 FINDS sites within approximately 0.75 miles of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
WORLD PROPHETIC MINISTRY	***1099 N PEPPER AVE***	***1/4 - 1/2 NNE***	***K44***	***54***
JEHUE (WILLIAM G.) MIDDLE	1500 N. EUCALYPTUS AVE.	1/2 - 1 N	114	126

Lower Elevation	Address	Dist / Dir	Map ID	Page
ALLIANCE COLTON - DREWS SUBSTA	559 PEPPER AVE	1/8 - 1/4 E	B2	6
UNIVERSAL MACK SALES SERVICE	***220 N REX FORD***	***1/8 - 1/4 S***	***A4***	***8***
INLAND EMPIRE TOYOTA	***1700 VALLEY RD***	***1/8 - 1/4 S***	***D8***	***11***
MCNEILUS TRUCK & MFG. INC.	401 N. PEPPER AVE.	1/8 - 1/4 SE	C11	19
ARROWHEAD REGIONAL MEDICAL CEN	400 NORTH PEPPER	1/8 - 1/4 SE	C15	22
B AND G AUTO SALES	***1630 W VALLEY BLVD***	***1/8 - 1/4 SSE***	***F21***	***30***
SHELL SERVICE STATION	***1600 W VALLEY***	***1/4 - 1/2 SSE***	***F29***	***38***
MOSS BROS FORD	***1900 W VALLEY BLVD***	***1/4 - 1/2 SW***	***H34***	***45***
GRACE WR & CO DISTRIB SVCS	***1988 W VALLEY BLVD***	***1/4 - 1/2 WSW***	***J41***	***51***
SLOVER MOUNTAIN HIGH (CONT.)	325 HERMOSA AVE.	1/2 - 1 ESE	U87	84
CLARKLIFT OF CALIFORNIA INC	1762 S SYCAMORE	1/2 - 1 WSW	V89	85
GATX RAIL	***20878 SLOVER STREET***	***1/2 - 1 S***	***Z108***	***103***

EXECUTIVE SUMMARY

STATE AND LOCAL RECORDS

Toxic Pits: The Toxic Pits Cleanup Act Sites database identifies sites suspected of containing hazardous substances where cleanup has not yet been completed. The data come from the State Water Resources Control Board.

A review of the Toxic Pits list, as provided by EDR, and dated 07/01/1995 has revealed that there is 1 Toxic Pits site within approximately 1.75 miles of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
SOUTHERN PACIFIC RAILYARD Closure Date: 02/21/91	***200 MARION WAY***	***1/2 - 1 SW***	***AF127***	***150***

SWF/LF: The Solid Waste Facilities/Landfill Sites records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. The data come from the Integrated Waste Management Board's Solid Waste Information System (SWIS) database.

A review of the SWF/LF list, as provided by EDR, and dated 12/12/2007 has revealed that there are 2 SWF/LF sites within approximately 1.25 miles of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
FILTER RECYCLING SERVICES, INC	180 WEST MONTE AVENUE	1 - 2 SW	AM174	240
INLAND COMPOSTING AND ORGANIC	2300 SOUTH RIVERSIDE AV	1 - 2 SW	AO177	241

CA WDS: California Water Resources Control Board - Waste Discharge System.

A review of the CA WDS list, as provided by EDR, and dated 06/19/2007 has revealed that there are 2 CA WDS sites within approximately 0.75 miles of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
MCNEILUS TRUCK & MANUFACTURING	***401 N PEPPER AVE***	***1/8 - 1/4 SE***	***C10***	***16***
CO-ARROWHEAD REG.MED.CTR	***400 N PEPPER AVE***	***1/8 - 1/4 SE***	***C16***	***22***

WMUDS/SWAT: The Waste Management Unit Database System is used for program tracking and inventory of waste management units. The source is the State Water Resources Control Board.

A review of the WMUDS/SWAT list, as provided by EDR, and dated 04/01/2000 has revealed that there is 1 WMUDS/SWAT site within approximately 1.25 miles of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
BRINE FAC,COLTON		***1/2 - 1 SSE***	***AC116***	***127***

Cortese: The sites for the list are designated by the State Water Resource Control Board (LUST), the Integrated Waste Board (SWF/LS), and the Department of Toxic Substances Control (Cal-Sites). This listing is no longer updated by the state agency.

A review of the Cortese list, as provided by EDR, and dated 04/01/2001 has revealed that there are 6

Cortese sites within approximately 1.25 miles of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
SOUTHERN PACIFIC RAILYARD	***200 MARION WAY***	***1/2 - 1 SW***	***AF127***	***150***
RIALTO, CITY OF (TEXACO)	***102 VALLEY BLVD***	***1/2 - 1 WSW***	***AG141***	***168***
TEXACO SERVICE STATION	***120 VALLEY BLVD***	***1/2 - 1 WSW***	***AI153***	***188***
TERMINAL	2237 RIVERSIDE AVE	1 - 2 SW	AM169	211
ARCO #1569	***792 VALLEY BLVD***	***1 - 2 ESE***	***AN171***	***214***
GW CLEANUP-COLTON TERMINA	2301 RIVERSIDE	1 - 2 SW	AO176	241

SWRCY: A listing of recycling facilities in California.

A review of the SWRCY list, as provided by EDR, and dated 01/07/2008 has revealed that there is 1 SWRCY site within approximately 1.25 miles of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
TOMRA PACIFIC INC/FOOD 4 LESS	1150 N PEPPER AVE	1/2 - 1 NNE	T80	80

LUST: The Leaking Underground Storage Tank Incident Reports contain an inventory of reported leaking underground storage tank incidents. The data come from the State Water Resources Control Board Leaking Underground Storage Tank Information System.

A review of the LUST list, as provided by EDR, and dated 01/07/2008 has revealed that there are 15 LUST sites within approximately 1.25 miles of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
SHELL SERVICE STATION Facility Status: Case Closed	1600 VALLEY BOULEVARD W	1/4 - 1/2 SSE	F28	36
TELCO FOODS Facility Status: Case Closed	2111 VALLEY BOULEVARD W	1/2 - 1 WSW	Q70	71
I-10 TRUCK STOP Facility Status: Case Closed	195 VALLEY BOULEVARD EA	1/2 - 1 WSW	AD124	143
SOUTHERN PACIFIC RAILYARD Facility Status: Case Closed	***200 MARION WAY***	***1/2 - 1 SW***	***AF127***	***150***
CHEVRON #9-6969 Facility Status: Case Closed	101 VALLEY BLVD	1/2 - 1 WSW	AG140	166
RIALTO, CITY OF (TEXACO) Facility Status: Case Closed	***102 VALLEY BLVD***	***1/2 - 1 WSW***	***AG141***	***168***
THRIFTY OIL #323/ ARCO #9695 Facility Status: Preliminary site assessment underway	111 VALLEY BLVD	1/2 - 1 WSW	AI150	185
TEXACO SERVICE STATION Facility Status: Case Closed	***120 VALLEY BLVD***	***1/2 - 1 WSW***	***AI153***	***188***
CLEM TRANS INC Facility Status: Case Closed	213 VALLEY BLVD.	1 - 2 W	166	205
POMA AUTOMATED FUELING, INC. Facility Status: Case Closed	2095 RIVERSIDE AVE	1 - 2 SW	167	207
TERMINAL (EQUILON ENTERPRISES) Facility Status: Preliminary site assessment underway	2237 RIVERSIDE AVE	1 - 2 SW	AM168	209
FORMER ARCO STATION #1569 Facility Status: Pollution Characterization	792 VALLEY BOULEVARD WE	1 - 2 ESE	AN170	212

EXECUTIVE SUMMARY

Lower Elevation	Address	Dist / Dir	Map ID	Page
ARCO #1569	***792 VALLEY BLVD***	***1 - 2 ESE***	***AN171***	***214***
Facility Status: Case Closed				
COLTON UNIFIED SCHOOL DISTRICT	***777 VALLEY BLVD***	***1 - 2 ESE***	***AN172***	***216***
Facility Status: Case Closed				
MOBIL FAC. #04-086 /COLTON TER	2305 RIVERSIDE AVE	1 - 2 SW	AO178	242
Facility Status: Remedial action (cleanup) Underway				

CA FID UST: The Facility Inventory Database contains active and inactive underground storage tank locations. The source is the State Water Resource Control Board.

A review of the CA FID UST list, as provided by EDR, and dated 10/31/1994 has revealed that there are 6 CA FID UST sites within approximately 1 mile of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
INLAND EMPIRE EQUIPT, INC	***1762 S SYCAMORE***	***1/2 - 1 WSW***	***V90***	***85***
CUMMINS WEST INC	***161 E VALLEY BLVD***	***1/2 - 1 WSW***	***AD125***	***145***
JUST GAS INC	***102 E VALLEY BLVD***	***1/2 - 1 WSW***	***AG132***	***156***
CHEVRON STATION #6969	101 E VALLEY BLVD	1/2 - 1 WSW	AG137	163
THRIFTY OIL CO #323	***111 W VALLEY***	***1/2 - 1 WSW***	***AG146***	***176***
PAUL HUBBS CONSTRUCTION CO.	***140 W VALLEY BLVD***	***1/2 - 1 WSW***	***AI157***	***194***

SLIC: SLIC Region comes from the California Regional Water Quality Control Board.

A review of the SLIC list, as provided by EDR, and dated 01/07/2008 has revealed that there are 5 SLIC sites within approximately 1.25 miles of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
ARROWHEAD REGIONAL MEDICAL CEN	400 N PEPPER	1/8 - 1/4 SE	C14	21
CALNEV PIPE LINE COMPANY	2051 E SLOVER AVE	1/2 - 1 SSW	AE120	137
SANTA FE PACIFIC PIPE LINE	2720 SLOVER	1/2 - 1 SW	AJ155	192
CONOCO COLTON TERMINAL - EAST	271 E. SLOVER AVE	1/2 - 1 SW	AK163	202
Facility Status: Verification Monitoring Underway				
CHEVRON COLTON TERMINAL	2297 RIVERSIDE AVE S	1 - 2 SW	AO175	241
Facility Status: Feasibility Study for Remedial Action Plan				

UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the State Water Resources Control Board's Hazardous Substance Storage Container Database.

A review of the UST list, as provided by EDR, and dated 01/07/2008 has revealed that there are 6 UST sites within approximately 1 mile of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
BISHOP'S CENTRAL STORES	***791 N PEPPER AVE***	***1/8 - 1/4 NE***	***E12***	***19***
CO-ARROWHEAD REG.MED.CTR	***400 N PEPPER AVE***	***1/8 - 1/4 SE***	***C16***	***22***
ORANGE SHELL - COLTON	1600 W VALLEY BLVD	1/4 - 1/2 SSE	F26	34
I-10 TRUCK STOP	195 E VALLEY BLVD	1/2 - 1 WSW	AD123	143
CHEVRON STATION #6969	101 E VALLEY BLVD	1/2 - 1 WSW	AG135	162

Lower Elevation	Address	Dist / Dir	Map ID	Page
ARCO #9695	111 W VALLEY BLVD	1/2 - 1 WSW	AG142	171

HIST UST: Historical UST Registered Database.

A review of the HIST UST list, as provided by EDR, and dated 10/15/1990 has revealed that there are 16 HIST UST sites within approximately 1 mile of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
INLAND EMPIRE TOYOTA	***1700 VALLEY RD***	***1/8 - 1/4 S***	***D8***	***11***
ZAKARIA HAGGAG	***1600 W VALLEY BLVD***	***1/4 - 1/2 SSE***	***F27***	***34***
BISHOPS CENTRAL STORES	***9908 PEPPER AVE***	***1/4 - 1/2 SSE***	***43***	***52***
WESTERN EXTERMINATOR COMPANY	1998 W VALLEY BLVD	1/4 - 1/2 WSW	J46	58
INLAND EMPIRE EQUIPT, INC	***1762 S SYCAMORE***	***1/2 - 1 WSW***	***V90***	***85***
GATX RAIL	***20878 SLOVER STREET***	***1/2 - 1 S***	***Z108***	***103***
CUMMINS WEST INC	***161 E VALLEY BLVD***	***1/2 - 1 WSW***	***AD125***	***145***
CIRCLE K STORE #627	***990 VALLEY BLVD***	***1/2 - 1 ESE***	***126***	***148***
10-10 TRUCK STOP	195 E VALLEY RIALTO, CA	1/2 - 1 WSW	AG133	159
96969	101 E VALLEY BLVD	1/2 - 1 WSW	AG136	162
ARCO STN. #323	***111 W VALLEY BLVD***	***1/2 - 1 WSW***	***AG145***	***174***
DUNCAN BROS., INC.	***1966 S DATE AVE***	***1/2 - 1 SW***	***AH149***	***184***
RIALTO RUBBISH	210 CAMERON WAY	1/2 - 1 SW	AH151	187
COLTON TERMINAL	1901 SLOVER AVENUE	1/2 - 1 SW	AJ154	191
PAUL HUBBS CONSTRUCTION CO.	140 W VALLEY BLVD	1/2 - 1 WSW	AI158	196
COLTON TERMINAL	***271 E. SLOVER AVENUE***	***1/2 - 1 SW***	***AK160***	***198***

AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the State Water Resources Control Board's Hazardous Substance Storage Container Database.

A review of the AST list, as provided by EDR, and dated 11/01/2007 has revealed that there are 2 AST sites within approximately 1 mile of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
CALNEV COLTON TERMINAL	2051 E. SLOVER AVE.	1/2 - 1 SSW	AE122	143
COLTON TERMINAL, EAST	271 E. SLOVER AVE.	1/2 - 1 SW	AK161	200

SWEEPS UST: Statewide Environmental Evaluation and Planning System. This underground storage tank listing was updated and maintained by a company contacted by the SWRCB in the early 1990's. The listing is no longer updated or maintained. The local agency is the contact for more information on a site on the SWEEPS list.

A review of the SWEEPS UST list, as provided by EDR, and dated 06/01/1994 has revealed that there are 20 SWEEPS UST sites within approximately 1 mile of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
INLAND EMPIRE TOYOTA	***1700 VALLEY RD***	***1/8 - 1/4 S***	***D8***	***11***
BISHOP'S CENTRAL STORES	***791 N PEPPER AVE***	***1/8 - 1/4 NE***	***E12***	***19***
SHELL SERVICE STATION	***1600 W VALLEY***	***1/4 - 1/2 SSE***	***F29***	***38***
SAMMON'S TRUCKING	1988 W VALLEY BLVD	1/4 - 1/2 WSW	J42	52
BISHOPS CENTRAL STORES	***9908 PEPPER AVE***	***1/4 - 1/2 SSE***	***43***	***52***
LARSEN, BRAD & CAROL	***2006 W VALLEY BLVD***	***1/4 - 1/2 WSW***	***J49***	***59***

EXECUTIVE SUMMARY

Lower Elevation	Address	Dist / Dir	Map ID	Page
OROWEAT FOODS CO/RIALTO	***2036 W VALLEY BLVD***	***1/4 - 1/2 WSW***	***N56***	***63***
PRICE CLUB	2109 W VALLEY	1/2 - 1 WSW	Q67	69
INLAND EMPIRE EQUIPT, INC	***1762 S SYCAMORE***	***1/2 - 1 WSW***	***V90***	***85***
10-10 TRUCK STOP	***195 E VALLEY BLVD***	***1/2 - 1 WSW***	***AA109***	***121***
CALNEV PIPE LINE COMPANY COLTO	***2051 E SLOVER AVE***	***1/2 - 1 SSW***	***AE121***	***137***
CUMMINS WEST INC	***161 E VALLEY BLVD***	***1/2 - 1 WSW***	***AD125***	***145***
SOUTHERN PACIFIC RAILYARD	***200 MARION WAY***	***1/2 - 1 SW***	***AF127***	***150***
JUST GAS INC	***102 E VALLEY BLVD***	***1/2 - 1 WSW***	***AG132***	***156***
CHEVRON STATION #6969	***101 E VALLEY BLVD***	***1/2 - 1 WSW***	***AG139***	***164***
THRIFTY OIL CO #323	***111 W VALLEY***	***1/2 - 1 WSW***	***AG146***	***176***
DUNCAN BROS INC	***1966 S DATE ST***	***1/2 - 1 SW***	***AH148***	***179***
CIRCLE K #627	***990 VALLEY BLVD***	***1/2 - 1 ESE***	***156***	***192***
PAUL HUBBS CONSTRUCTION CO.	***140 W VALLEY BLVD***	***1/2 - 1 WSW***	***AI157***	***194***
RIALTO RUBBISH	***210 E CAMERON***	***1/2 - 1 SW***	***AL165***	***203***

CHMIRS: The California Hazardous Material Incident Report System contains information on reported hazardous material incidents, i.e., accidental releases or spills. The source is the California Office of Emergency Services.

A review of the CHMIRS list, as provided by EDR, and dated 12/31/2005 has revealed that there are 9 CHMIRS sites within approximately 0.75 miles of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
Not reported	400 N. PEPPER AVE	1/8 - 1/4 SE	C18	27
Not reported	1599 VALLEY BLVD	1/4 - 1/2 SSE	F30	42
Not reported	CORNER OF PEPPER/SAN BE	1/4 - 1/2 NNE	38	48
Date Completed: 20-FEB-88				
Not reported	2111 W. VALLEY BLVD	1/2 - 1 WSW	R73	72
Not reported	2111 W. VALLEY BLVD.	1/2 - 1 WSW	R74	74
Not reported	2051 W. SLOVER AVE	1/2 - 1 S	Y98	93
Date Completed: 31-AUG-89				
Not reported	CAL NEV COLTON TERMINAL	1/2 - 1 S	Y102	95
Not reported	PEPPER / SLOVER AVE.	1/2 - 1 S	Z103	97
GENERAL AMERICAN TRANSPORTATIO	***PEPPER / SLOVER ST***	***1/2 - 1 S***	***Z105***	***99***

CDL: A listing of drug lab locations. Listing of a location in this database does not indicate that any illegal drug lab materials were or were not present there, and does not constitute a determination that the location either requires or does not require additional cleanup work.

A review of the CDL list, as provided by EDR, and dated 09/30/2007 has revealed that there are 4 CDL sites within approximately 0.75 miles of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
Not reported	1610 NORTH BENT RAIL CI	1/4 - 1/2 NNE	M60	65
Not reported	987 N CYPRESS ST	1/2 - 1 ENE	71	72
Not reported	1822 W ADMIRALTY ST	1/2 - 1 N	81	81

Lower Elevation	Address	Dist / Dir	Map ID	Page
Not reported	1601 SLOVER AVE	1/2 - 1 S	Z106	102

EXECUTIVE SUMMARY

San Bern. Co. Permit: San Bernardino County Fire Department Hazardous Materials Division.

A review of the San Bern. Co. Permit list, as provided by EDR, and dated 12/28/2007 has revealed that there are 36 San Bern. Co. Permit sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
REPUBLIC MACHINE & FABRICATION	***313 REXFORD ST***	***1/8 - 1/4 S***	***A1***	***6***
CARPENTERS JOINT APPRENT & TRN	1750 SAN BERNARDINO AVE	1/4 - 1/2 NNW	37	48
KRAGEN AUTO PARTS #4298	1100 N PEPPER AVE	1/4 - 1/2 NNE	K51	60
FOOD 4 LESS GAS STATION	1170 N PEPPER AVE	1/2 - 1 NNE	T82	81
RIALTO MED SUPPLIES INC	1517 S RIVERSIDE AVE	1/2 - 1 W	130	156

Lower Elevation	Address	Dist / Dir	Map ID	Page
INLAND EMPIRE TOYOTA	***1700 VALLEY RD***	***1/8 - 1/4 S***	***D8***	***11***
MCNEILUS TRUCK & MANUFACTURING	***401 N PEPPER AVE***	***1/8 - 1/4 SE***	***C10***	***16***
BISHOP'S CENTRAL STORES	***791 N PEPPER AVE***	***1/8 - 1/4 NE***	***E12***	***19***
ARROWHEAD REGIONAL MED CTR	***400 N PEPPER AVE***	***1/8 - 1/4 SE***	***C17***	***23***
AUTO CENTRO	1630 W VALLEY BLVD	1/8 - 1/4 SSE	F19	28
B & G AUTO SALES	***1630 W VALLEY BLVD***	***1/8 - 1/4 SSE***	***F20***	***29***
ZAKARIA HAGGAG	***1600 W VALLEY BLVD***	***1/4 - 1/2 SSE***	***F27***	***34***
COLTON GOLF COURSE	1901 VALLEY BLVD	1/4 - 1/2 SW	H33	44
MOSS BROS FORD.	1900 W VALLEY BLVD	1/4 - 1/2 SW	H35	46
LARSEN, BRAD & CAROL	***2006 W VALLEY BLVD***	***1/4 - 1/2 WSW***	***J49***	***59***
OROWEAT FOODS CO/RIALTO	***2036 W VALLEY BLVD***	***1/4 - 1/2 WSW***	***N56***	***63***
LANDJET MOTOR CARRIERS	2048 W VALLEY BLVD	1/4 - 1/2 WSW	N61	65
COLTON JT USD/WAREHOUSE	***1313 W VALLEY BLVD***	***1/2 - 1 ESE***	***P65***	***67***
TELCO FOOD PRODUCTS, INC.	2111 W VALLEY BLVD	1/2 - 1 WSW	R75	75
INLAND EMPIRE EQUIPT, INC	***1762 S SYCAMORE***	***1/2 - 1 WSW***	***V90***	***85***
CLUTCH MASTERS	267 E VALLEY BLVD	1/2 - 1 WSW	91	89
AT&T MOBILITY COLTON #13829	1205 1/2 W VALLEY BLVD	1/2 - 1 ESE	W92	90
CAL NEV PIPELINE COLTON	2051 W SLOVER AVE	1/2 - 1 S	Y97	92
10-10 TRUCK STOP	***195 E VALLEY BLVD***	***1/2 - 1 WSW***	***AA109***	***121***
GEN AMERICAN TRANSPORTATION CO	***20878 SLOVER***	***1/2 - 1 SSE***	***AC117***	***129***
LUCKY FARMS	245 E VALLEY BLVD	1/2 - 1 WSW	AD119	137
CUMMINS WEST INC	***161 E VALLEY BLVD***	***1/2 - 1 WSW***	***AD125***	***145***
UNION PACIFIC RAILROAD CO	200 MARION WAY	1/2 - 1 SW	AF128	153
BESTFOODS BAKING COMPANY	***2036 W VALLEY BLVD***	***1/2 - 1 WSW***	***AG129***	***154***
VULCAN STEEL CO	270 E CAMERON WAY	1/2 - 1 SW	AF131	156
CHEVRON STATION #6969	***101 E VALLEY BLVD***	***1/2 - 1 WSW***	***AG139***	***164***
ARCO #09695	111 W VALLEY BLVD	1/2 - 1 WSW	AG144	173
DUNCAN BROS INC	1966 S DATE	1/2 - 1 SW	AH147	178
DUNCAN BROS., INC.	***1966 S DATE AVE***	***1/2 - 1 SW***	***AH149***	***184***
VALLEY ANIMAL HOSPITAL	***127 W VALLEY BLVD***	***1/2 - 1 WSW***	***AI152***	***188***
RIALTO RUBBISH SERVICES INC	210 E CAMERON WAY	1/2 - 1 SW	AL164	203

HAZNET: The data is extracted from the copies of hazardous waste manifests received each year by the DTSC. The annual volume of manifests is typically 700,000-1,000,000 annually, representing approximately 350,000-500,000 shipments. Data from non-California manifests & continuation sheets are not included at the present time. Data are from the manifests submitted without correction, and therefore many contain some invalid values for data elements such as generator ID, TSD ID, waste category, & disposal method. The source is the Department of Toxic Substance Control is the agency

A review of the HAZNET list, as provided by EDR, and dated 12/31/2006 has revealed that there are 49

EXECUTIVE SUMMARY

HAZNET sites within approximately 0.75 miles of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
REPUBLIC MACHINE & FABRICATION	***313 REXFORD ST***	***1/8 - 1/4 S***	***A1***	***6***
HUD IN TOWN PROPERTIES	1065 AGUA CALIENTE LN	1/4 - 1/2 N	I39	50
INTOWN PROPERTIES INC/HUD	1001 WHISTLE STOP DR	1/4 - 1/2 N	40	50
WORLD PROPHETIC MINISTRY	***1099 N PEPPER AVE***	***1/4 - 1/2 NNE***	***K44***	***54***
INTOWN PROPERTIES INC	1081 TRUJILLO LN	1/4 - 1/2 N	47	58
HUD INTOWN PROPERTIES	1801 DE CARMEN DR	1/4 - 1/2 N	I48	59
HUD INTOWN PROPERTIES	1897 DE CARMEN DR	1/4 - 1/2 NNW	L52	61
1X COUNTY OF SAN BERNARDINO	1500 W SAN BERNARDINO A	1/4 - 1/2 NE	53	61
HUD INTOWN PROPERTIES	1174 EXPRESS CIR	1/4 - 1/2 N	M54	62
HUD INTOWN PROPERTIES	1187 EXPRESS CIR	1/4 - 1/2 N	M55	62
HUD	1927 DE CARMEN DR	1/4 - 1/2 NNW	L57	63
FOOD 4 LESS #786	1150 N PEPPER AVE	1/4 - 1/2 NNE	59	64
HUD	1641 IRON HORSE CIR	1/4 - 1/2 N	O62	66
ASSETT MANAGEMENT SPECIALIST	1620 IRON HORSE CIRCLE	1/4 - 1/2 N	O63	66
HUD	1851 GOLDEN SPIKE DR	1/4 - 1/2 N	64	67
HUD	1989 FIG TREE RD	1/2 - 1 NW	S78	79
HUN/INTOWN PROP	1994 FIG TREE RD	1/2 - 1 NW	S79	80
INTOWN PROPERTIES	1201 CANTARA ST	1/2 - 1 NNE	83	82
HUD	1918 QUARTERMASTER	1/2 - 1 NNW	84	82
INTOWN PROPERTIES, INC/HUD	1988 CLUSTER PINE RD	1/2 - 1 NW	85	83
INTOWN PROPERTIES INC	1761 W WIND ST	1/2 - 1 N	94	91
HUD	1365 CHRISTOBAL LN	1/2 - 1 NNW	X95	91
HUD INTOWN PROPERTIES	1365 CHRISTOBAL LN N	1/2 - 1 NNW	X96	92
INTOWN PROPERTIES INC/HUD	1355 WHITEOAK	1/2 - 1 NW	115	126

Lower Elevation	Address	Dist / Dir	Map ID	Page
CALIFORNIA AUTO SPECIALIST	1700 W VALLEY RD	1/8 - 1/4 S	D7	10
BUDGET TRUCK RENTAL	1700 W VALLEY BLVD	1/8 - 1/4 S	D9	16
COLTON BISHOP STORE HOUSE	791 NORTH_PEPPER AVENUE	1/8 - 1/4 NE	E13	21
ARROWHEAD REGIONAL MED CTR	***400 N PEPPER AVE***	***1/8 - 1/4 SE***	***C17***	***23***
B & G AUTO SALES	***1630 W VALLEY BLVD***	***1/8 - 1/4 SSE***	***F20***	***29***
B AND G AUTO SALES	***1630 W VALLEY BLVD***	***1/8 - 1/4 SSE***	***F21***	***30***
CC WESTERN/CENTRAL TRANSPORT I	1849 W VALLEY BLVD	1/4 - 1/2 SW	G22	32
SHELL SERVICE STATION	***1600 W VALLEY***	***1/4 - 1/2 SSE***	***F29***	***38***
DON MORRISON	1595 W. VALLEY BLVD	1/4 - 1/2 SSE	F31	43
CALIFORNIA AUTO SPECIALITIES	1595 W VALLEY BLVD	1/4 - 1/2 SSE	F32	44
MOSS BROS FORD	***1900 W VALLEY BLVD***	***1/4 - 1/2 SW***	***H34***	***45***
COLTON GOLF CLUB	1901 W VALLEY BLVD	1/4 - 1/2 SW	H36	47
COLTON AUTO SALES	1998 W. VALLEY BLVD	1/4 - 1/2 WSW	J45	56
SIERRA DIESEL REPAIR	2006 WEST VALLEY	1/4 - 1/2 WSW	J50	60
BIMBO BAKERIES USA INC	2036 W VALLEY BLVD	1/4 - 1/2 WSW	N58	64
COLTON JT USD/WAREHOUSE	***1313 W VALLEY BLVD***	***1/2 - 1 ESE***	***P65***	***67***
COLTON JOINT USD/WAREHOUSE	1313 W VALLEY BLVD	1/2 - 1 ESE	P66	68
PRICE CLUB # 106	2111 W VALLEY BLVD	1/2 - 1 WSW	R76	76
TALCO INC	2111 VALLEY BLVD	1/2 - 1 WSW	R77	78
SLOVER MT HIGH SCHOOL	325 HERMOSA	1/2 - 1 ESE	U86	83
INLAND EMPIRE EQUIPT, INC	***1762 S SYCAMORE***	***1/2 - 1 WSW***	***V90***	***85***
PARKHOUSE TIRE	1205 W. VALLEY BLVD.	1/2 - 1 ESE	W93	90
GENERAL AMERICAN TRANSPORTATIO	***PEPPER / SLOVER ST***	***1/2 - 1 S***	***Z105***	***99***
GATX RAIL	PEPPER / SLOVER ST	1/2 - 1 S	Z107	102
10-10 TRUCK STOP	***195 E VALLEY BLVD***	***1/2 - 1 WSW***	***AA109***	***121***

EXECUTIVE SUMMARY

AIRS: Toxics and criteria pollutant emissions data collected by the ARB and local air pollution agencies

A review of the AIRS list, as provided by EDR, and dated 12/31/2005 has revealed that there are 8 AIRS sites within approximately 0.75 miles of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
ALLIANCE COLTON, LLC	559 PEPPER AVE	1/8 - 1/4 E	B3	7
PURENERGY OPERATING SERVICES,	559 PEPPER AVE	1/8 - 1/4 SE	C6	10
MCNEILUS TRUCK & MANUFACTURING	***401 N PEPPER AVE***	***1/8 - 1/4 SE***	***C10***	***16***
ARROWHEAD REGIONAL MED CTR	***400 N PEPPER AVE***	***1/8 - 1/4 SE***	***C17***	***23***
TELCO FOOD PRODUCTS	2111 W VALLEY BLVD	1/2 - 1 WSW	Q69	70
INLAND EMPIRE EQUIP INC	1762 S. SYCAMORE	1/2 - 1 WSW	V88	84
GATX	PEPPER AV/SLOVER ST.	1/2 - 1 S	Z104	98
CALNEV PIPE LINE CO (NSR USE)	1901 SLOVER AVE.	1/2 - 1 SSW	AB110	125

ENVIROSTOR: The Department of Toxic Substances Control's (DTSC's) Site Mitigation and Brownfields Reuse Program's (SMBRP's) EnviroStor database identifes sites that have known contamination or sites for which there may be reasons to investigate further. The database includes the following site types: Federal Superfund sites (National Priorities List (NPL)); State Response, including Military Facilities and State Superfund; Voluntary Cleanup; and School sites. EnviroStor provides similar information to the information that was available in CalSites, and provides additional site information, including, but not limited to, identification of formerly-contaminated properties that have been released for reuse, properties where environmental deed restrictions have been recorded to prevent inappropriate land uses, and risk characterization information that is used to assess potential impacts to public health and the environment at contaminated sites.

A review of the ENVIROSTOR list, as provided by EDR, and dated 11/27/2007 has revealed that there is 1 ENVIROSTOR site within approximately 1.75 miles of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
CACTUS MIDDLE SCHOOL	***VALLEY BOULEVARD/CACTUS***	***1 - 2 W***	***179***	***244***
Facility Status: No Further Action				

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped:

Site Name	Database(s)
ENTENMANN'S OROWEAT	CA FID UST, SWEEPS UST
10-10 TRUCK STOP	SWEEPS UST
265 W G ST (CROSS-LACADENA)	CDL
935 SAGE ST	CDL
J & S FORKLIFT SERVICES INC	DRYCLEANERS
INLAND BEVERAGE COMPANY	LUST, Cortese
SECCOMBE LAKE STATE REC AREA	CERC-NFRAP
CIRCLE K # 5249	LUST
ECOLOGY AUTO WRECKING	LUST
CALTRANS PANARAMA PT.MAINT.ST.	LUST
ARCO PRODUCTS CO.	HAZNET
CALTRANS DIST 8/CONSTR/EA08-OC1804	HAZNET
SOUTHERN CALIFORNIA GAS CO COLTON	HAZNET
COLTON GARDEN APTS	HAZNET
HUD INTOWN PROPERTIES	HAZNET
ELIZABETH GILES DDS INC	HAZNET
CLARENCE E BAILEY	HAZNET
INTEGRITY TIRE	HAZNET
HUD	HAZNET
MELCHOR BRICEOCENO	HAZNET
COLTON YARD 19100 SLOVER AVE	ERNS
PUREENERGY (ALLIANCE COLTON)	FINDS
DANNY & J'S AUTO CARE	San Bern. Co. Permit
J&S FORKLIFT SERVICES, INC	San Bern. Co. Permit
IMAGO	San Bern. Co. Permit
JOAQUIN'S WELDING	San Bern. Co. Permit
JUARITOS CITRUS DISTRIBUTION	San Bern. Co. Permit
FREDDY'S IRONWORKS	San Bern. Co. Permit
JAT TRUCKING INC	San Bern. Co. Permit
SOUTHSIDE METAL	San Bern. Co. Permit
ALLIED STORAGE CONTAINERS	San Bern. Co. Permit
A & SONS TOWING	San Bern. Co. Permit
BISCOMERICA	San Bern. Co. Permit
RESIDENCE	San Bern. Co. Permit
JOHN M POWELL O.D.	SLIC
ARCO TANK FARM	SCH, ENVIROSTOR
JONES ELEMENTARY SCHOOL	AIRS
R & H FIBERGLASS	

OVERVIEW MAP - 02165111.2r

Rialto Ave
Merrill Ave
Slover Ave
Washington St
S Pepper Ave
S Cedar Ave
S Riverside Ave
S Locust Ave
S Linden Ave
S Eucalyptus Ave
S Juniper Ave
S Orange Ave
S Sycamore Ave
S Willow Ave
S Maple Ave
S Poplar Ave
S Alder Ave
S Elm Ave
S Date Ave
S Acacia Ave
S Beech Ave
S Fir Ave
S Hemlock Ave
S Ivy Ave
S Juniper Ave
S Larch Ave
S Myrtle Ave
S Oak Ave
S Palm Ave
S Redwood Ave
S Spruce Ave
S Tamarack Ave
S Walnut Ave
S Willow Ave
S Yucca Ave
S Zinnia Ave
S Aster Ave
S Begonia Ave
S Camellia Ave
S Daisy Ave
S Fuchsia Ave
S Gardenia Ave
S Hibiscus Ave
S Iris Ave
S Jasmine Ave
S Lilac Ave
S Magnolia Ave
S Narcissus Ave
S Orchid Ave
S Peony Ave
S Rose Ave
S Tulip Ave
S Violet Ave
S Wisteria

DETAIL MAP - 02165111.2r



- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- Sensitive Receptors
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- Power transmission lines
- Oil & Gas pipelines
- 100-year flood zone
- 500-year flood zone
- Areas of Concern

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: Colton Super Block ADDRESS: San Bernardino Avenue/North Pepper Avenue Colton CA 92324 LAT/LONG: 34.0733 / 117.3554	CLIENT: Petra Geotechnical Inc CONTACT: Callie Cullum INQUIRY #: 02165111.2r DATE: March 12, 2008 7:55 am

Copyright © 2008 EDR, Inc. © 2007 Tele Atlas Rel. 07/2006.

MAP FINDINGS SUMMARY

Database	Target Property	Search Distance (Miles)	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
FEDERAL RECORDS								
NPL		1.750	0	0	0	0	0	0
Proposed NPL		1.750	0	0	0	0	0	0
Delisted NPL		1.750	0	0	0	0	0	0
NPL LIENS		0.750	0	0	0	0	NR	0
CERCLIS		1.250	0	0	0	0	0	0
CERC-NFRAP		1.250	0	0	0	1	0	1
LIENS 2		0.750	0	0	0	0	NR	0
CORRACTS		1.750	0	0	0	1	1	2
RCRA-TSDF		1.250	0	0	0	1	0	1
RCRA-LQG		1.000	0	0	0	3	NR	3
RCRA-SQG		1.000	0	3	2	7	NR	12
RCRA-CESQG		1.000	0	0	0	0	NR	0
RCRA-NonGen		0.750	0	0	1	0	NR	1
US ENG CONTROLS		1.250	0	0	0	0	0	0
US INST CONTROL		1.250	0	0	0	0	0	0
ERNS		0.750	0	0	0	5	NR	5
HMIRS		0.750	0	0	3	2	NR	5
DOT OPS		0.750	0	0	0	0	NR	0
US CDL		0.750	0	0	0	0	NR	0
US BROWNFIELDS		1.250	0	0	0	0	0	0
DOD		1.750	0	0	0	0	0	0
FUDS		1.750	0	0	0	0	0	0
LUCIS		1.250	0	0	0	0	0	0
CONSENT		1.750	0	0	0	0	0	0
ROD		1.750	0	0	0	0	0	0
UMTRA		1.250	0	0	0	0	0	0
ODI		1.250	0	0	0	0	0	0
DEBRIS REGION 9		0.750	0	0	0	0	NR	0
MINES		1.000	0	0	0	0	NR	0
TRIS		0.750	0	1	0	0	NR	1
TSCA		0.750	0	0	0	0	NR	0
FTTS		0.750	0	0	0	1	NR	1
HIST FTTS		0.750	0	0	0	1	NR	1
SSTS		0.750	0	0	0	0	NR	0
ICIS		0.750	0	1	0	0	NR	1
PADS		0.750	0	0	0	0	NR	0
MLTS		0.750	0	0	0	0	NR	0
RADINFO		0.750	0	0	0	0	NR	0
FINDS		0.750	0	6	4	4	NR	14
RAATS		0.750	0	0	0	0	NR	0
STATE AND LOCAL RECORDS								
HIST Cal-Sites		1.750	0	0	0	0	0	0
CA BOND EXP. PLAN		1.750	0	0	0	0	0	0
SCH		1.000	0	0	0	0	NR	0
Toxic Pits		1.750	0	0	0	1	0	1
SWF/LF		1.250	0	0	0	0	2	2

MAP FINDINGS SUMMARY

Database	Target Property	Search Distance (Miles)	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
CA WDS		0.750	0	2	0	0	NR	2
WMUDS/SWAT		1.250	0	0	0	1	0	1
Cortese		1.250	0	0	0	3	3	6
SWRCY		1.250	0	0	0	1	0	1
LUST		1.250	0	0	1	7	7	15
CA FID UST		1.000	0	0	0	6	NR	6
SLIC		1.250	0	1	0	3	1	5
UST		1.000	0	2	1	3	NR	6
HIST UST		1.000	0	1	3	12	NR	16
AST		1.000	0	0	0	2	NR	2
LIENS		0.750	0	0	0	0	NR	0
SWEEPS UST		1.000	0	2	5	13	NR	20
CHMIRS		0.750	0	1	2	6	NR	9
Notify 65		1.750	0	0	0	0	0	0
DEED		1.250	0	0	0	0	0	0
VCP		1.250	0	0	0	0	0	0
DRYCLEANERS		1.000	0	0	0	0	NR	0
WIP		1.000	0	0	0	0	NR	0
CDL		0.750	0	0	1	3	NR	4
RESPONSE		1.750	0	0	0	0	0	0
San Bern. Co. Permit		1.000	0	7	8	21	NR	36
HAZNET		0.750	0	7	23	19	NR	49
AIRS		0.750	0	4	0	4	NR	8
HAULERS		0.750	0	0	0	0	NR	0
ENVIROSTOR		1.750	0	0	0	0	1	1
TRIBAL RECORDS								
INDIAN RESERV		1.750	0	0	0	0	0	0
INDIAN ODI		1.250	0	0	0	0	0	0
INDIAN LUST		1.250	0	0	0	0	0	0
INDIAN UST		1.000	0	0	0	0	NR	0
EDR PROPRIETARY RECORDS								
Manufactured Gas Plants		1.750	0	0	0	0	0	0
EDR Historical Auto Stations		0.250	0	0	NR	NR	NR	0
EDR Historical Cleaners		0.250	0	0	NR	NR	NR	0

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

A1 **REPUBLIC MACHINE & FABRICATION** **HAZNET S104769514**
South **313 REXFORD ST** **San Bern. Co. Permit N/A**
1/8-1/4 **COLTON, CA 92324**
0.126 mi.
665 ft. **Site 1 of 2 in cluster A**

Relative: **Higher**

Actual: **1084 ft.**

HAZNET:

Gepaid:	CAL000253695
Contact:	JOHN BARRETT
Telephone:	9093700555
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	313 REXFORD ST
Mailing City,St,Zip:	COLTON, CA 92324
Gen County:	San Bernardino
TSD EPA ID:	CAT080013352
TSD County:	Los Angeles
Waste Category:	Unspecified organic liquid mixture
Disposal Method:	Recycler
Tons:	0.22
Facility County:	Not reported

San Bern. Co. Permit:

Region:	SAN BERNARDINO
Facility ID:	FA0005670
Owner:	BARRETT, JOHN
Permit Number:	PT0000484
Permit Category:	SPECIAL GENERATOR(B)
Facility Status:	ACTIVE
Expiration Date:	7/31/2008 12:00:00AM

Region:	SAN BERNARDINO
Facility ID:	FA0005670
Owner:	BARRETT, JOHN
Permit Number:	PT0000483
Permit Category:	SPECIAL HANDLER
Facility Status:	ACTIVE
Expiration Date:	7/31/2008 12:00:00AM

B2 **ALLIANCE COLTON - DREWS SUBSTATION** **FINDS 1005692353**
East **559 PEPPER AVE** **110012174235**
1/8-1/4 **COLTON, CA 92324**
0.146 mi.
773 ft. **Site 1 of 2 in cluster B**

Relative: **Lower**

Actual: **1075 ft.**

FINDS:
Other Pertinent Environmental Activity Identified at Site

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and its Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also

ALLIANCE COLTON - DREWS SUBSTATION (Continued) **1005692353**

has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

B3 **ALLIANCE COLTON, LLC** **AIRS S106825644**
East **559 PEPPER AVE** **N/A**
1/8-1/4 **COLTON, CA 92324**
0.146 mi.
773 ft. **Site 2 of 2 in cluster B**

Relative:
Lower

Actual:
1075 ft.

EMI:

Year:	2002
Carbon Monoxide Emissions Tons/Yr:	36
Air Basin:	SC
Facility ID:	127380
Air District Name:	SC
SIC Code:	4911
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	24
Reactive Organic Gases Tons/Yr:	2
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	5
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	2
Part. Matter 10 Micrometers & Smllr Tons/Yr:	2

Year:	2003
Carbon Monoxide Emissions Tons/Yr:	36
Air Basin:	SC
Facility ID:	127380
Air District Name:	SC
SIC Code:	4911
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	24
Reactive Organic Gases Tons/Yr:	2
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	5
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	2
Part. Matter 10 Micrometers & Smllr Tons/Yr:	2

Year:	2004
Carbon Monoxide Emissions Tons/Yr:	36
Air Basin:	SC
Facility ID:	127380
Air District Name:	SC
SIC Code:	4911
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	23.756
Reactive Organic Gases Tons/Yr:	2.16
Carbon Monoxide Emissions Tons/Yr:	0.025535

ALLIANCE COLTON, LLC (Continued) **S106825644**

NOX - Oxides of Nitrogen Tons/Yr: 5.4872
SOX - Oxides of Sulphur Tons/Yr: 0.31573
Particulate Matter Tons/Yr: 1.9926
Part. Matter 10 Micrometers & Smllr Tons/Yr: 1.98

A4 **UNIVERSAL MACK SALES SERVICE** **RCRA-SQG 1000431647**
South **220 N REX FORD** **FINDS CAD982522609**
1/8-1/4 **COLTON, CA 92324**
0.179 mi.
947 ft. **Site 2 of 2 in cluster A**

Relative:
Lower

Actual:
1079 ft.

RCRA-SQG:
Date form received by agency: 04/05/1989
Facility name: UNIVERSAL MACK SALES SERVICE
Facility address: 220 N REX FORD
COLTON, CA 92324
EPA ID: CAD982522609
Mailing address: N REX FORD
COLTON, CA 92324
Contact: ENVIRONMENTAL MANAGER
Contact address: 220 N REX FORD
COLTON, CA 92324
Contact country: US
Contact telephone: (714) 825-8750
Contact email: Not reported
EPA Region: 09
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: UNIVERSAL MACK INC
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: Unknown
Mixed waste (haz. and radioactive): Unknown

UNIVERSAL MACK SALES SERVICE (Continued) **1000431647**

Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	Unknown
Furnace exemption:	Unknown
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No
Off-site waste receiver:	Commercial status unknown

Violation Status: No violations found

FINDS:
Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

C5 **ALLIANCE COLTON - DREWS SUBSTATION** **ICIS 1010273823**
SE **559 PEPPER AVE** **N/A**
1/8-1/4 **COLTON, CA 92324**
0.183 mi.
967 ft. **Site 1 of 9 in cluster C**

Relative:
Lower

Actual:
1073 ft.

ICIS:

Enforcement Action ID:	09-2001-0096
FRS ID:	110012174235
Program ID:	FRS 110012174235
Action Name:	ALLIANCE COLTON
Facility Name:	ALLIANCE COLTON - DREWS SUBSTATION
Facility Address:	559 PEPPER AVE COLTON, California 92324
Enforcement Action Type:	CAA 113A Admin Compliance Order (Non-Penalty)
Facility County:	SAN BERNARDINO
EPA Region #:	9
Program ID:	AIRS/AFS 06071CA183
Facility Name:	ALLIANCE COLTON - DREWS SUBSTATION
Address:	559 PEPPER AVE COLTON CA 92324
Tribal Indicator:	Not reported
Fed Facility:	Not reported
NAIC Code:	Not reported
SIC Code:	4911
Program ID:	FRS 110012174235
Facility Name:	ALLIANCE COLTON - DREWS SUBSTATION
Address:	559 PEPPER AVE COLTON CA 92324
Tribal Indicator:	No

ALLIANCE COLTON - DREWS SUBSTATION (Continued) **1010273823**

Fed Facility:	No
NAIC Code:	Not reported
SIC Code:	4911

C6 **PURENERGY OPERATING SERVICES, LLC** **AIRS S108432930**
SE **559 PEPPER AVE** **N/A**
1/8-1/4 **COLTON, CA 92324**
0.183 mi.
967 ft. **Site 2 of 9 in cluster C**

Relative:
Lower

Actual:
1073 ft.

EMI:

Year:	2005
Carbon Monoxide Emissions Tons/Yr:	36
Air Basin:	SC
Facility ID:	132192
Air District Name:	SC
SIC Code:	4911
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.02403
Reactive Organic Gases Tons/Yr:	.002196342
Carbon Monoxide Emissions Tons/Yr:	.001685
NOX - Oxides of Nitrogen Tons/Yr:	.651
SOX - Oxides of Sulphur Tons/Yr:	.1459
Particulate Matter Tons/Yr:	.1556
Part. Matter 10 Micrometers & Smllr Tons/Yr:	.1546664

D7 **CALIFORNIA AUTO SPECIALIST** **HAZNET S107148272**
South **1700 W VALLEY RD** **N/A**
1/8-1/4 **COLTON, CA 92324**
0.204 mi.
1077 ft. **Site 1 of 3 in cluster D**

Relative:
Lower

Actual:
1067 ft.

HAZNET:

Gepaid:	CAL000263127
Contact:	EDWARD BERKI
Telephone:	9092542886
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1700 W VALLEY RD
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	San Bernardino
TSD EPA ID:	CAD981696420
TSD County:	San Bernardino
Waste Category:	Waste oil and mixed oil
Disposal Method:	Recycler
Tons:	0.91
Facility County:	San Bernardino

Gepaid:	CAL000263127
Contact:	EDWARD BERKI
Telephone:	9092542886
Facility Addr2:	Not reported
Mailing Name:	Not reported

CALIFORNIA AUTO SPECIALIST (Continued) **S107148272**

Mailing Address:	1700 W VALLEY RD
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	San Bernardino
TSD EPA ID:	CAD982444481
TSD County:	San Bernardino
Waste Category:	Waste oil and mixed oil
Disposal Method:	Transfer Station
Tons:	1.31
Facility County:	San Bernardino

Gepaid:	CAL000263127
Contact:	EDWARD BERKI
Telephone:	9092542886
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1700 W VALLEY RD
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	San Bernardino
TSD EPA ID:	CAT000613927
TSD County:	San Bernardino
Waste Category:	Aqueous solution with less than 10% total organic residues
Disposal Method:	Transfer Station
Tons:	0.1
Facility County:	San Bernardino

Gepaid:	CAL000263127
Contact:	EDWARD BERKI
Telephone:	9092540436
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1370 N LACADENA
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	San Bernardino
TSD EPA ID:	CAD982444481
TSD County:	San Bernardino
Waste Category:	Aqueous solution with 10% or more total organic residues
Disposal Method:	Transfer Station
Tons:	0.45
Facility County:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional CA_HAZNET: record(s) in the EDR Site Report.

D8
South
1/8-1/4
0.204 mi.
1077 ft.

INLAND EMPIRE TOYOTA
1700 VALLEY RD
COLTON, CA 92324

Site 2 of 3 in cluster D

RCRA-SQG **1000151918**
FINDS **CAD982002883**
HIST UST
San Bern. Co. Permit
SWEEPS UST

Relative:
Lower

Actual:
1067 ft.

RCRA-SQG:

Date form received by agency:	06/01/1987
Facility name:	INLAND EMPIRE TOYOTA
Facility address:	1700 VALLEY RD COLTON, CA 92324
EPA ID:	CAD982002883
Mailing address:	VALLEY RD COLTON, CA 92324
Contact:	ENVIRONMENTAL MANAGER

INLAND EMPIRE TOYOTA (Continued) **1000151918**

Contact address:	1700 VALLEY RD COLTON, CA 92324
Contact country:	US
Contact telephone:	(714) 825-7777
Contact email:	Not reported
EPA Region:	09
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	DICK JOYCE
Owner/operator address:	NOT REQUIRED NOT REQUIRED, ME 99999
Owner/operator country:	Not reported
Owner/operator telephone:	(415) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	NOT REQUIRED
Owner/operator address:	NOT REQUIRED NOT REQUIRED, ME 99999
Owner/operator country:	Not reported
Owner/operator telephone:	(415) 555-1212
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	Unknown
Mixed waste (haz. and radioactive):	Unknown
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	Unknown
Furnace exemption:	Unknown
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No
Off-site waste receiver:	Commercial status unknown

Violation Status: No violations found

FINDS:
Other Pertinent Environmental Activity Identified at Site

INLAND EMPIRE TOYOTA (Continued) **1000151918**

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HIST UST:

Region:	STATE
Facility ID:	00000066383
Facility Type:	Other
Other Type:	AUTO DEALER
Total Tanks:	0005
Contact Name:	THOMAS TRACY V.P.
Telephone:	7148257777
Owner Name:	BILL N. ELLIS
Owner Address:	1700 W. VALLEY
Owner City,St,Zip:	COLTON, CA 92324
Tank Num:	001
Container Num:	3
Year Installed:	Not reported
Tank Capacity:	00000500
Tank Used for:	WASTE
Type of Fuel:	5
Tank Construction:	3 centimeters
Leak Detection:	None
Tank Num:	002
Container Num:	1
Year Installed:	Not reported
Tank Capacity:	00000500
Tank Used for:	PRODUCT
Type of Fuel:	06
Tank Construction:	Not reported
Leak Detection:	None
Tank Num:	003
Container Num:	2
Year Installed:	Not reported
Tank Capacity:	00000500
Tank Used for:	PRODUCT
Type of Fuel:	06
Tank Construction:	Not reported
Leak Detection:	None
Tank Num:	004
Container Num:	4
Year Installed:	Not reported
Tank Capacity:	00003000
Tank Used for:	PRODUCT
Type of Fuel:	REGULAR
Tank Construction:	Not reported
Leak Detection:	None
Tank Num:	005

1000151918

INLAND EMPIRE TOYOTA (Continued)

Container Num: 5
Year Installed: Not reported
Tank Capacity: 00003000
Tank Used for: PRODUCT
Type of Fuel: UNLEADED
Tank Construction: Not reported
Leak Detection: None

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0004328
Owner: MOSS BROS FORD INC.
Permit Number: PT0005717
Permit Category: SPECIAL GENERATOR(B)
Facility Status: INACTIVE
Expiration Date: 5/31/2003 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0004328
Owner: MOSS BROS FORD INC.
Permit Number: PT0005716
Permit Category: SPECIAL HANDLER
Facility Status: INACTIVE
Expiration Date: 5/31/2003 12:00:00AM

SWEEPS UST:
Status: Not reported
Comp Number: 8826
Number: Not reported
Board Of Equalization: 44-021441
Ref Date: Not reported
Act Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 36-000-008826-000001
Actv Date: Not reported
Capacity: 500
Tank Use: OIL
Stg: WASTE
Content: WASTE OIL
Number Of Tanks: 5

Status: Not reported
Comp Number: 8826
Number: Not reported
Board Of Equalization: 44-021441
Ref Date: Not reported
Act Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 36-000-008826-000002
Actv Date: Not reported
Capacity: 500
Tank Use: OIL

1000151918

INLAND EMPIRE TOYOTA (Continued)

Stg:	PRODUCT
Content:	NEW OIL
Number Of Tanks:	Not reported
Status:	Not reported
Comp Number:	8826
Number:	Not reported
Board Of Equalization:	44-021441
Ref Date:	Not reported
Act Date:	Not reported
Created Date:	Not reported
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	36-000-008826-000003
Actv Date:	Not reported
Capacity:	500
Tank Use:	PETROLEUM
Stg:	PRODUCT
Content:	TRAN. FLUID
Number Of Tanks:	Not reported
Status:	Not reported
Comp Number:	8826
Number:	Not reported
Board Of Equalization:	44-021441
Ref Date:	Not reported
Act Date:	Not reported
Created Date:	Not reported
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	36-000-008826-000004
Actv Date:	Not reported
Capacity:	3000
Tank Use:	M.V. FUEL
Stg:	PRODUCT
Content:	LEADED
Number Of Tanks:	Not reported
Status:	Not reported
Comp Number:	8826
Number:	Not reported
Board Of Equalization:	44-021441
Ref Date:	Not reported
Act Date:	Not reported
Created Date:	Not reported
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	36-000-008826-000005
Actv Date:	Not reported
Capacity:	3000
Tank Use:	M.V. FUEL
Stg:	PRODUCT
Content:	REG UNLEADED
Number Of Tanks:	Not reported

D9 **BUDGET TRUCK RENTAL** **HAZNET** **S108743562**
South **1700 W VALLEY BLVD** **N/A**
1/8-1/4 **COLTON, CA 92324**
0.204 mi.
1077 ft. **Site 3 of 3 in cluster D**

Relative: HAZNET:
Lower

Gepaid:	CAL000303183
Contact:	JOE UNGARO
Actual: Telephone:	9098242308
1067 ft. Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1700 W VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 923241809
Gen County:	San Bernardino
TSD EPA ID:	TXD077603371
TSD County:	99
Waste Category:	Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method:	H06
Tons:	0.3
Facility County:	San Bernardino

C10 **MCNEILUS TRUCK & MANUFACTURING INC.** **TRIS** **1005452064**
SE **401 N PEPPER AVE** **AIRS** **92324MCNLS40**
1/8-1/4 **COLTON, CA 92324** **San Bern. Co. Permit**
0.204 mi. **CA WDS**
1079 ft. **Site 3 of 9 in cluster C**

Relative: EMI:
Lower

Year:	1997
Carbon Monoxide Emissions Tons/Yr:	36
Actual: Air Basin:	SC
1071 ft. Facility ID:	83870
Air District Name:	SC
SIC Code:	3479
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	3
Reactive Organic Gases Tons/Yr:	2
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1998
Carbon Monoxide Emissions Tons/Yr:	36
Air Basin:	SC
Facility ID:	83870
Air District Name:	SC
SIC Code:	3479
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0

MCNEILUS TRUCK & MANUFACTURING INC. (Continued) **1005452064**

Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0
Year:	1999
Carbon Monoxide Emissions Tons/Yr:	36
Air Basin:	SC
Facility ID:	83870
Air District Name:	SC
SIC Code:	3479
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	3
Reactive Organic Gases Tons/Yr:	2
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0
Year:	2000
Carbon Monoxide Emissions Tons/Yr:	36
Air Basin:	SC
Facility ID:	83870
Air District Name:	SC
SIC Code:	3479
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	3
Reactive Organic Gases Tons/Yr:	2
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0
Year:	2001
Carbon Monoxide Emissions Tons/Yr:	36
Air Basin:	SC
Facility ID:	83870
Air District Name:	SC
SIC Code:	3479
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	3
Reactive Organic Gases Tons/Yr:	2
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

San Bern. Co. Permit:

Region:	SAN BERNARDINO
Facility ID:	FA0004643

MCNEILUS TRUCK & MANUFACTURING INC. (Continued) **1005452064**

Owner: OSHKOSH TRUCK CORPORATION
Permit Number: PT0005344
Permit Category: GENERATOR - 0-10 EMPLOYEES
Facility Status: ACTIVE
Expiration Date: 9/30/2008 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0004643
Owner: OSHKOSH TRUCK CORPORATION
Permit Number: PT0005343
Permit Category: HAZMAT HANDLER 0-10 EMPLOYEES (W/GEN PRMT)
Facility Status: ACTIVE
Expiration Date: 9/30/2008 12:00:00AM

CA WDS:
Facility ID: Santa Ana River 36I011331
Facility Type: Industrial - Facility that treats and/or disposes of liquid or semisolid wastes from any servicing, producing, manufacturing or processing operation of whatever nature, including mining, gravel washing, geothermal operations, air conditioning, ship building and repairing, oil production, storage and disposal operations, water pumping.
Facility Status: Active - Any facility with a continuous or seasonal discharge that is under Waste Discharge Requirements.
NPDES Number: CAS000001 The 1st 2 characters designate the state. The remaining 7 are assigned by the Regional Board
Subregion: 8
Facility Telephone: 9093702100
Facility Contact: TOM VATTER
Agency Name: MC NEILUS TRUCK & MFG INC
Agency Address: PO Box 70
Agency City,St,Zip: Dodge Center 559270070
Agency Contact: BRUCE NORTON
Agency Telephone: 5073746321
Agency Type: Private
SIC Code: 0
SIC Code 2: Not reported
Primary Waste: Not reported
Primary Waste Type: Not reported
Secondary Waste: Not reported
Secondary Waste Type: Not reported
Design Flow: 0
Baseline Flow: 0
Reclamation: Not reported
POTW: Not reported
Treat To Water: Minor Threat to Water Quality. A violation of a regional board order should cause a relatively minor impairment of beneficial uses compared to a major or minor threat. Not: All nurds without a TTWQ will be considered a minor threat to water quality unless coded at a higher Level. A Zero (0) may be used to code those NURDS that are found to represent no threat to water quality.
Complexity: Category C - Facilities having no waste treatment systems, such as cooling water dischargers or thosewho must comply through best management practices, facilities with passive waste treatment and disposal systems, such as septic systems with subsurface disposal, or dischargers having waste storage systems with land disposal such as dairy waste ponds.

C11
SE
1/8-1/4
0.204 mi.
1079 ft.

MCNEILUS TRUCK & MFG. INC.
401 N. PEPPER AVE.
COLTON, CA 92324

Site 4 of 9 in cluster C

FINDS **1005845561**
110008061970

Relative:
Lower

Actual:
1071 ft.

FINDS:
Other Pertinent Environmental Activity Identified at Site

TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

E12
NE
1/8-1/4
0.210 mi.
1111 ft.

BISHOP'S CENTRAL STORES
791 N PEPPER AVE
COLTON, CA 92324

Site 1 of 2 in cluster E

UST **U003971288**
San Bern. Co. Permit **N/A**
SWEEPS UST

Relative:
Lower

Actual:
1080 ft.

UST:
Local Agency: 36000
Facility ID: 87013607

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0001493
Owner: CHURCH OF JESUS CHRIST OF LATT
Permit Number: PT0011245
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 7/31/2008 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0001493
Owner: CHURCH OF JESUS CHRIST OF LATT
Permit Number: PT0003330
Permit Category: HAZMAT HANDLER - UST ONLY
Facility Status: ACTIVE
Expiration Date: 7/31/2008 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0001493
Owner: CHURCH OF JESUS CHRIST OF LATT
Permit Number: PT0003331
Permit Category: ABOVEGROUND PETROLEUM STORAGE (AST) (SPCC)
Facility Status: ACTIVE
Expiration Date: 7/31/2008 12:00:00AM

SWEEPS UST:
Status: A
Comp Number: 608
Number: 1
Board Of Equalization: Not reported

BISHOP'S CENTRAL STORES (Continued) **U003971288**

Ref Date:	03-23-92
Act Date:	03-23-92
Created Date:	03-28-90
Tank Status:	A
Owner Tank Id:	6D2
Swrcb Tank Id:	36-000-000608-000001
Actv Date:	03-28-90
Capacity:	6000
Tank Use:	M.V. FUEL
Stg:	P
Content:	DIESEL
Number Of Tanks:	4
Status:	A
Comp Number:	608
Number:	1
Board Of Equalization:	Not reported
Ref Date:	03-23-92
Act Date:	03-23-92
Created Date:	03-28-90
Tank Status:	A
Owner Tank Id:	6D5
Swrcb Tank Id:	36-000-000608-000002
Actv Date:	03-28-90
Capacity:	250
Tank Use:	M.V. FUEL
Stg:	P
Content:	DIESEL
Number Of Tanks:	Not reported
Status:	A
Comp Number:	608
Number:	1
Board Of Equalization:	Not reported
Ref Date:	03-23-92
Act Date:	03-23-92
Created Date:	03-28-90
Tank Status:	A
Owner Tank Id:	6D5
Swrcb Tank Id:	36-000-000608-000003
Actv Date:	03-28-90
Capacity:	12000
Tank Use:	M.V. FUEL
Stg:	P
Content:	DIESEL
Number Of Tanks:	Not reported
Status:	A
Comp Number:	608
Number:	1
Board Of Equalization:	Not reported
Ref Date:	03-23-92
Act Date:	03-23-92
Created Date:	03-28-90
Tank Status:	A
Owner Tank Id:	6D5
Swrcb Tank Id:	36-000-000608-000004

BISHOP'S CENTRAL STORES (Continued) **U003971288**

Actv Date:	03-28-90
Capacity:	500
Tank Use:	M.V. FUEL
Stg:	P
Content:	DIESEL
Number Of Tanks:	Not reported

E13 **COLTON BISHOP STORE HOUSE** **HAZNET** **S103958143**
NE **791 NORTH_PEPPER AVENUE** **N/A**
1/8-1/4 **COLTON, CA 92324**
0.210 mi.
1111 ft. **Site 2 of 2 in cluster E**

Relative: **Lower**

Actual: **1080 ft.**

HAZNET:

Gepaid:	CAL000124088
Contact:	LDS
Telephone:	0000000000
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	791 N PEPPER AVE
Mailing City,St,Zip:	COLTON, CA 923240002
Gen County:	San Bernardino
TSD EPA ID:	CAT080013352
TSD County:	Los Angeles
Waste Category:	Waste oil and mixed oil
Disposal Method:	Recycler
Tons:	2.9190
Facility County:	San Bernardino

Gepaid:	CAL000124088
Contact:	LDS
Telephone:	0000000000
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	791 N PEPPER AVE
Mailing City,St,Zip:	COLTON, CA 923240002
Gen County:	San Bernardino
TSD EPA ID:	CAD008364432
TSD County:	Los Angeles
Waste Category:	Unspecified oil-containing waste
Disposal Method:	Recycler
Tons:	2.1016
Facility County:	San Bernardino

C14 **ARROWHEAD REGIONAL MEDICAL CENTER** **SLIC** **S108542879**
SE **400 N PEPPER** **N/A**
1/8-1/4 **COLTON, CA**
0.223 mi.
1178 ft. **Site 5 of 9 in cluster C**

Relative: **Lower**

Actual: **1069 ft.**

SLIC:

Type:	ITEM #27
Facility Status:	A
Region:	8
Staff:	Ann Sturdivant, Tel 909-782-4904, LAND DISPOSAL
Description Information:	COLTON

ARROWHEAD REGIONAL MEDICAL CENTER (Continued) **S108542879**

Date: THRU
Order No: Not reported
Npdes No: Not reported
File Type: UNREG
Sequency: 01

C15 **ARROWHEAD REGIONAL MEDICAL CENTER** **FINDS 1005611485**
SE **400 NORTH PEPPER** **110000528769**
1/8-1/4 **COLTON, CA 92324**
0.223 mi.
1178 ft. **Site 6 of 9 in cluster C**

Relative: **Lower**

Actual: **1069 ft.**

FINDS:
Other Pertinent Environmental Activity Identified at Site

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

C16 **CO-ARROWHEAD REG.MED.CTR** **UST U003785473**
SE **400 N PEPPER AVE** **CA WDS N/A**
1/8-1/4 **COLTON, CA 92324**
0.224 mi.
1182 ft. **Site 7 of 9 in cluster C**

Relative: **Lower**

Actual: **1069 ft.**

UST:
Local Agency: 36000
Facility ID: 98046597

CA WDS:
Facility ID: Santa Ana River 362794001
Facility Type: Other - Does not fall into the category of Municipal/Domestic, Industrial, Agricultural or Solid Waste (Class I, II or III)
Facility Status: Active - Any facility with a continuous or seasonal discharge that is under Waste Discharge Requirements.
NPDES Number: CAG998001 The 1st 2 characters designate the state. The remaining 7 are assigned by the Regional Board
Subregion: 8
Facility Telephone: 9095800037
Facility Contact: MICHAEL HEINE
Agency Name: ARROWHEAD REG. MEDICAL CENTER
Agency Address: 400 N. PEPPER AVENUE
Agency City,St,Zip: COLTON 92324
Agency Contact: MICHAEL HEINE
Agency Telephone: 9095800037
Agency Type: Private
SIC Code: 0

CO-ARROWHEAD REG.MED.CTR (Continued) **U003785473**

SIC Code 2:	Not reported
Primary Waste:	Not reported
Primary Waste Type:	Not reported
Secondary Waste:	Not reported
Secondary Waste Type:	Not reported
Design Flow:	0
Baseline Flow:	0
Reclamation:	No reclamation requirements associated with this facility.
POTW:	The facility is not a POTW.
Treat To Water:	Minor Threat to Water Quality. A violation of a regional board order should cause a relatively minor impairment of beneficial uses compared to a major or minor threat. Not: All nurds without a TTWQ will be considered a minor threat to water quality unless coded at a higher Level. A Zero (0) may be used to code those NURDS that are found to represent no threat to water quality.
Complexity:	Category C - Facilities having no waste treatment systems, such as cooling water dischargers or thosewho must comply through best management practices, facilities with passive waste treatment and disposal systems, such as septic systems with subsurface disposal, or dischargers having waste storage systems with land disposal such as dairy waste ponds.

C17 **ARROWHEAD REGIONAL MED CTR** **HAZNET S104765310**
SE **400 N PEPPER AVE** **AIRS N/A**
1/8-1/4 **COLTON, CA 92324** **San Bern. Co. Permit**
0.224 mi.
1182 ft. **Site 8 of 9 in cluster C**

Relative:
Lower

Actual:
1069 ft.

HAZNET:

Gepaid:	CAL000214531
Contact:	MICHAEL HEINE/FACILITIES SUPT
Telephone:	9095800085
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	400 N PEPPER AVE
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	San Bernardino
TSD EPA ID:	CAD028409019
TSD County:	Los Angeles
Waste Category:	Off-specification, aged, or surplus organics
Disposal Method:	Transfer Station
Tons:	2.37
Facility County:	Not reported

Gepaid:	CAL000214531
Contact:	MICHAEL HEINE/FACILITIES SUPT
Telephone:	9095800085
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	400 N PEPPER AVE
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	San Bernardino
TSD EPA ID:	CAD028409019
TSD County:	Los Angeles
Waste Category:	Off-specification, aged, or surplus inorganics
Disposal Method:	Transfer Station
Tons:	0
Facility County:	San Bernardino

ARROWHEAD REGIONAL MED CTR (Continued) **S104765310**

Gepaid:	CAL000214531
Contact:	MICHEAL HEINE/MAINT SUPVR
Telephone:	9095800085
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	400 N PEPPER AVE
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	San Bernardino
TSD EPA ID:	Not reported
TSD County:	Los Angeles
Waste Category:	Off-specification, aged, or surplus organics
Disposal Method:	Transfer Station
Tons:	0.74
Facility County:	Not reported

Gepaid:	CAL000214531
Contact:	MICHEAL HEINE/MAINT SUPVR
Telephone:	9095800085
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	400 N PEPPER AVE
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	San Bernardino
TSD EPA ID:	Not reported
TSD County:	Los Angeles
Waste Category:	Liquids with mercury > 20 mg/l
Disposal Method:	Transfer Station
Tons:	0
Facility County:	Not reported

Gepaid:	CAL000214531
Contact:	MICHEAL HEINE/MAINT SUPVR
Telephone:	9095800085
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	400 N PEPPER AVE
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	San Bernardino
TSD EPA ID:	Not reported
TSD County:	Los Angeles
Waste Category:	Laboratory waste chemicals
Disposal Method:	Transfer Station
Tons:	0.38
Facility County:	Not reported

Click this hyperlink while viewing on your computer to access
28 additional CA_HAZNET: record(s) in the EDR Site Report.

EMI:

Year:	2002
Carbon Monoxide Emissions Tons/Yr:	36
Air Basin:	SC
Facility ID:	118379
Air District Name:	SC
SIC Code:	8062
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported

ARROWHEAD REGIONAL MED CTR (Continued) **S104765310**

Particulate Matter Tons/Yr: 1.12316
Part. Matter 10 Micrometers & Smllr Tons/Yr: 1.107656

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0002241
Owner: CO-SAN BDNO MEDICAL CTR
Permit Number: PT0010688
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 7/31/2008 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0002241
Owner: CO-SAN BDNO MEDICAL CTR
Permit Number: PT0009431
Permit Category: GENERATOR - 26-50 EMPLOYEES
Facility Status: ACTIVE
Expiration Date: 7/31/2008 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0002241
Owner: CO-SAN BDNO MEDICAL CTR
Permit Number: PT0010689
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 7/31/2008 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0002241
Owner: CO-SAN BDNO MEDICAL CTR
Permit Number: PT0009430
Permit Category: HAZMAT HANDLER 26-50 EMPLOYEES (W/GEN PRMT)
Facility Status: ACTIVE
Expiration Date: 7/31/2008 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0002241
Owner: CO-SAN BDNO MEDICAL CTR
Permit Number: PT0010684
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 7/31/2008 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0002241
Owner: CO-SAN BDNO MEDICAL CTR
Permit Number: PT0010685
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 7/31/2008 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0002241
Owner: CO-SAN BDNO MEDICAL CTR
Permit Number: PT0010686
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)

ARROWHEAD REGIONAL MED CTR (Continued) **S104765310**

Facility Status: ACTIVE
Expiration Date: 7/31/2008 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0002241
Owner: CO-SAN BDNO MEDICAL CTR
Permit Number: PT0010690
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 7/31/2008 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0002241
Owner: CO-SAN BDNO MEDICAL CTR
Permit Number: PT0010687
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 7/31/2008 12:00:00AM

C18 **CHMIRS** **S105669914**
SE **400 N. PEPPER AVE** **N/A**
1/8-1/4 **COLTON, CA 92324**
0.224 mi.
1182 ft. **Site 9 of 9 in cluster C**

Relative:
Lower

Actual:
1069 ft.

CHMIRS:

OES Incident Number:	01-7296
OES notification:	12/17/200104:47:40 PM
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported

(Continued) **S105669914**

Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	No
Waterway:	Not reported
Spill Site:	Not reported
Cleanup By:	Reporting Party
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	2001
Agency:	Arrowhead Regional Medical Center
Incident Date:	12/13/200112:00:00 AM
Admin Agency:	San Bernardino County Health Department
Amount:	Not reported
Contained:	Yes
Site Type:	Other
E Date:	Not reported
Substance:	Potassium Hydroxide;;;
Quantity Released:	Not reported
BBLS:	0
Cups:	0
CUFT:	0
Gallons:	0
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0.000000
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	A bottle of the substance was dropped and spilled on the floor.

F19 **AUTO CENTRO** **San Bern. Co. Permit** **S108536402**
SSE **1630 W VALLEY BLVD** **N/A**
1/8-1/4 **COLTON, CA 92324**
0.241 mi.
1271 ft. **Site 1 of 10 in cluster F**

Relative:
Lower

Actual:
1068 ft.

San Bern. Co. Permit:

Region:	SAN BERNARDINO
Facility ID:	FA0010926
Owner:	JEFF SCHWARTZ
Permit Number:	PT0018841
Permit Category:	SPECIAL GENERATOR(B)
Facility Status:	ACTIVE
Expiration Date:	5/31/2008 12:00:00AM

S108536402

AUTO CENTRO (Continued)

Region: SAN BERNARDINO
Facility ID: FA0010926
Owner: JEFF SCHWARTZ
Permit Number: PT0018842
Permit Category: SPECIAL HANDLER
Facility Status: ACTIVE
Expiration Date: 5/31/2008 12:00:00AM

F20
SSE
1/8-1/4
0.241 mi.
1271 ft.

B & G AUTO SALES
1630 W VALLEY BLVD
COLTON, CA 92324

HAZNET **S102038723**
San Bern. Co. Permit **N/A**

Site 2 of 10 in cluster F

Relative:
Lower

Actual:
1068 ft.

HAZNET:
Gepaid: CAL000060945
Contact: CHADWICK SHIRLEY
Telephone: 0000000000
Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: 1630 W VALLEY BLVD
Mailing City,St,Zip: COLTON, CA 923241807
Gen County: San Bernardino
TSD EPA ID: CAD028409019
TSD County: Los Angeles
Waste Category: Unspecified oil-containing waste
Disposal Method: Not reported
Tons: .1459
Facility County: San Bernardino

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0001283
Owner: CHADWICK, SHIRLEY
Permit Number: PT0005412
Permit Category: SPECIAL HANDLER
Facility Status: INACTIVE
Expiration Date: 4/30/2007 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0001283
Owner: CHADWICK, SHIRLEY
Permit Number: PT0005413
Permit Category: SPECIAL GENERATOR(B)
Facility Status: INACTIVE
Expiration Date: 4/30/2007 12:00:00AM

F21
SSE
1/8-1/4
0.241 mi.
1271 ft.

B AND G AUTO SALES
1630 W VALLEY BLVD
COLTON, CA 92324

RCRA-SQG 1004677065
FINDS CAR000092825
HAZNET

Site 3 of 10 in cluster F

Relative:
Lower

Actual:
1068 ft.

RCRA-SQG:

Date form received by agency:	05/21/2001
Facility name:	B AND G AUTO SALES
Facility address:	1630 W VALLEY BLVD COLTON, CA 92324
EPA ID:	CAR000092825
Mailing address:	P O BOX 590 COLTON, CA 92324
Contact:	SHIRLEY CHADWICK
Contact address:	P O BOX 590 COLTON, CA 92324
Contact country:	US
Contact telephone:	(909) 825-1173
Contact email:	Not reported
EPA Region:	09
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	SHIRLEY CHADWICK
Owner/operator address:	1630 W VALLEY BLVD P O BOX 590 COLTON, CA 92324
Owner/operator country:	Not reported
Owner/operator telephone:	(909) 825-1173
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	Unknown
Mixed waste (haz. and radioactive):	Unknown
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	Unknown
Furnace exemption:	Unknown
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No
Off-site waste receiver:	Commercial status unknown

B AND G AUTO SALES (Continued) **1004677065**

Hazardous Waste Summary:
Waste code: D039
Waste name: TETRACHLOROETHYLENE

Violation Status: No violations found

FINDS:
Other Pertinent Environmental Activity Identified at Site

California - Hazardous Waste Tracking System - Datamart

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZNET:
Gepaid: CAR000092825
Contact: –
Telephone: 9098232161
Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: 1630 W VALLEY BLVD
Mailing City,St,Zip: COLTON, CA 923260000
Gen County: San Bernardino
TSD EPA ID: Not reported
TSD County: San Bernardino
Waste Category: Aqueous solution with less than 10% total organic residues
Disposal Method: Transfer Station
Tons: 0.18
Facility County: Not reported

Gepaid: CAR000092825
Contact: –
Telephone: 9098232161
Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: 1630 W VALLEY BLVD
Mailing City,St,Zip: COLTON, CA 923260000
Gen County: San Bernardino
TSD EPA ID: Not reported
TSD County: San Bernardino
Waste Category: Aqueous solution with less than 10% total organic residues
Disposal Method: Transfer Station
Tons: 0.08
Facility County: Not reported

Gepaid: CAR000092825
Contact: SHIRLEY CHADWICK
Telephone: 9098251173
Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: PO BOX 590
Mailing City,St,Zip: COLTON, CA 923240000

1004677065

B AND G AUTO SALES (Continued)

Gen County:	San Bernardino
TSD EPA ID:	CAT000613927
TSD County:	San Bernardino
Waste Category:	Aqueous solution with less than 10% total organic residues
Disposal Method:	Transfer Station
Tons:	0.03
Facility County:	San Bernardino

G22 **CC WESTERN/CENTRAL TRANSPORT INC** HAZNET S106089842
SW **1849 W VALLEY BLVD** N/A
1/4-1/2 **COLTON, CA 92324**
0.251 mi.
1327 ft. **Site 1 of 4 in cluster G**

Relative:
Lower

Actual:
1070 ft.

HAZNET:

Gepaid:	CAC002558607
Contact:	CHRIS TRANBERG
Telephone:	9098747040
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1849 W VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 92324
Gen County:	San Bernardino
TSD EPA ID:	Not reported
TSD County:	99
Waste Category:	Unspecified organic liquid mixture
Disposal Method:	Recycler
Tons:	0.20
Facility County:	Not reported

Gepaid:	CAC002571114
Contact:	DAVE MATTHEWS
Telephone:	9098747040
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1849 W VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 923241810
Gen County:	San Bernardino
TSD EPA ID:	CAT080013352
TSD County:	San Bernardino
Waste Category:	Unspecified organic liquid mixture
Disposal Method:	Recycler
Tons:	0.2
Facility County:	San Bernardino

Gepaid:	CAC002571114
Contact:	DAVE MATTHEWS
Telephone:	9098747040
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1849 W VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 923241810
Gen County:	San Bernardino
TSD EPA ID:	CAT080033681
TSD County:	San Bernardino
Waste Category:	Liquids with pH <UN-> 2 with metals
Disposal Method:	Recycler
Tons:	0.03

CC WESTERN/CENTRAL TRANSPORT INC (Continued) **S106089842**

Facility County:	San Bernardino
Gepaid:	CAC002571114
Contact:	DAVE MATTHEWS
Telephone:	9098747040
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1849 W VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 923241810
Gen County:	San Bernardino
TSD EPA ID:	CAT080033681
TSD County:	San Bernardino
Waste Category:	Other organic solids
Disposal Method:	Disposal, Land Fill
Tons:	0.75
Facility County:	San Bernardino
Gepaid:	CAC002571114
Contact:	DAVE MATTHEWS
Telephone:	9098747040
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1849 W VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 923241810
Gen County:	San Bernardino
TSD EPA ID:	CAT080033681
TSD County:	San Bernardino
Waste Category:	Unspecified organic liquid mixture
Disposal Method:	Recycler
Tons:	0.2
Facility County:	San Bernardino

Click this hyperlink while viewing on your computer to access
2 additional CA_HAZNET: record(s) in the EDR Site Report.

G23 **HMIRS** **94030500**
SW **1849 W VALLEY BLVD** **N/A**
1/4-1/2 **COLTON, CA**
0.251 mi.
1327 ft. **Site 2 of 4 in cluster G**

Relative:
Lower

Click this hyperlink while viewing on your computer to access
additional HMIRS detail in the EDR Site Report.

Actual:
1070 ft.
G24 **HMIRS** **95060019**
SW **1849 WEST VALLEY BLVD** **N/A**
1/4-1/2 **COLTON, CA**
0.251 mi.
1327 ft. **Site 3 of 4 in cluster G**

Relative:
Lower

Click this hyperlink while viewing on your computer to access
additional HMIRS detail in the EDR Site Report.

Actual:
1070 ft.

HMIRS 95101485
N/A

G25
SW
1/4-1/2
0.251 mi.
1327 ft.

1849 W VALLEY BLVD
COLTON, CA

Site 4 of 4 in cluster G

Relative: Lower

Click this hyperlink while viewing on your computer to access additional HMIRS detail in the EDR Site Report.

Actual: 1070 ft.

UST U003784724
N/A

F26
SSE
1/4-1/2
0.262 mi.
1382 ft.

ORANGE SHELL - COLTON
1600 W VALLEY BLVD
COLTON, CA 92324

Site 4 of 10 in cluster F

Relative: Lower

UST:
Local Agency: 36000
Facility ID: 86008825

Actual: 1065 ft.

HIST UST U001574717
San Bern. Co. Permit N/A

F27
SSE
1/4-1/2
0.262 mi.
1382 ft.

ZAKARIA HAGGAG
1600 W VALLEY BLVD
COLTON, CA 92324

Site 5 of 10 in cluster F

Relative: Lower

Actual: 1065 ft.

HIST UST:
Region: STATE
Facility ID: 00000018463
Facility Type: Gas Station
Other Type: Not reported
Total Tanks: 0005
Contact Name: ZAKARIA HAGGAG
Telephone: 7148246372
Owner Name: SHELL OIL COMPANY
Owner Address: P.O. BOX 4848
Owner City,St,Zip: ANAHEIM, CA 92803

Tank Num: 001
Container Num: 1
Year Installed: 1966
Tank Capacity: 00000550
Tank Used for: WASTE
Type of Fuel: WASTE OIL
Tank Construction: 12 gauge
Leak Detection: Stock Inventor, 10

Tank Num: 002
Container Num: 2
Year Installed: 1966
Tank Capacity: 00008000
Tank Used for: PRODUCT
Type of Fuel: UNLEADED
Tank Construction: 1/4 inches
Leak Detection: Stock Inventor, 10

Tank Num: 003
Container Num: 3
Year Installed: 1966
Tank Capacity: 00005000

ZAKARIA HAGGAG (Continued) **U001574717**

Tank Used for: PRODUCT
Type of Fuel: PREMIUM
Tank Construction: 1/4 inches
Leak Detection: Stock Inventor, 10

Tank Num: 004
Container Num: 4
Year Installed: 1966
Tank Capacity: 00005000
Tank Used for: PRODUCT
Type of Fuel: PREMIUM
Tank Construction: 1/4 inches
Leak Detection: Stock Inventor, 10

Tank Num: 005
Container Num: 5
Year Installed: 1970
Tank Capacity: 00008000
Tank Used for: PRODUCT
Type of Fuel: REGULAR
Tank Construction: 1/4 inches
Leak Detection: Stock Inventor, 10

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0005114
Owner: ORANGE OIL CO. COLTON
Permit Number: PT0012135
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 7/31/2008 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0005114
Owner: ORANGE OIL CO. COLTON
Permit Number: PT0012134
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 7/31/2008 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0005114
Owner: ORANGE OIL CO. COLTON
Permit Number: PT0012136
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 7/31/2008 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0005114
Owner: ORANGE OIL CO. COLTON
Permit Number: PT0002229
Permit Category: HAZMAT HANDLER - UST ONLY
Facility Status: ACTIVE
Expiration Date: 7/31/2008 12:00:00AM

F28 **SHELL SERVICE STATION** **LUST** **S105850485**
SSE **1600 VALLEY BOULEVARD WEST** **N/A**
1/4-1/2 **COLTON, CA 92373**
0.262 mi.
1382 ft. **Site 6 of 10 in cluster F**

Relative:
Lower

Actual:
1065 ft.

LUST:

Region:	STATE
Case Type:	Soil only
Cross Street:	PEPPER AVENUE
Enf Type:	Not reported
Funding:	Not reported
How Discovered:	SAS
How Stopped:	Not reported
Leak Cause:	UNK
Leak Source:	UNK
Global Id:	T0607168722
Stop Date:	Not reported
Confirm Leak:	2003-03-20 00:00:00
Workplan:	Not reported
Prelim Assess:	2002-11-15 00:00:00
Pollution Char:	2003-06-06 00:00:00
Remed Plan:	Not reported
Remed Action:	2003-07-31 00:00:00
Monitoring:	Not reported
Close Date:	2005-07-27 00:00:00
Discover Date:	2003-03-20 00:00:00
Enforcement Dt:	Not reported
Release Date:	2003-03-20 00:00:00
Review Date:	Not reported
Enter Date:	Not reported
MTBE Date:	Not reported
GW Qualifier:	Not reported
Soil Qualifier:	=
Max MTBE GW ppb:	Not reported
Max MTBE Soil ppb:	5.0
County:	36
Org Name:	Not reported
Reg Board:	Santa Ana Region
Status:	Case Closed
Chemical:	8006619, MTB
Contact Person:	Not reported
Responsible Party:	BRAD BOSCHETTO
RP Address:	2225 ONTARIO STREET
Interim:	Not reported
Oversight Prgm:	LUST
MTBE Class:	*
MTBE Conc:	1
MTBE Fuel:	0
MTBE Tested:	MTBE Detected. Site tested for MTBE and MTBE detected
Staff:	CAB
Staff Initials:	LH6
Lead Agency:	Local Agency
Local Agency:	36000L
Hydr Basin #:	Not reported
Beneficial:	MUN
Priority:	A3
Cleanup Fund Id:	Not reported
Work Suspended:	Not reported

S105850485

SHELL SERVICE STATION (Continued)

Local Case #: 2003014
Case Number: Not reported
Qty Leaked: Not reported
Abate Method: Not reported
Operator: Not reported
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 0
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported
Summary: Not reported

LUST:
Region: 8
Case Type: Soil only
Cross Street: PEPPER AVENUE
Enf Type: Not reported
Funding: Not reported
How Discovered: SAS
How Stopped: Not reported
Leak Cause: UNK
Leak Source: UNK
Global ID: T0607168722
How Stopped Date: Not reported
Review Date: Not reported
Workplan: Not reported
Prelim Assess: Not reported
Pollution Char: 4/21/2003
Remed Plan: Not reported
Remed Action: Not reported
Monitoring: Not reported
Close Date: Not reported
Discover Date: 3/20/2003
Enforcement Date: Not reported
Review Date: Not reported
Enter Date: Not reported
MTBE Date: Not reported
GW Qualifies: Not reported
Soil Qualifies: =
Max MTBE GW: Not reported
Max MTBE Soil: 3900
County: San Bernardino
Operator: Not reported
Regional Board: 08
Facility Status: Pollution Characterization
Substance: 8006619, MTB
Facility Contact: Not reported
Interim: Not reported
Oversite Program: LUST
Latitude: 0
Longitude: 0
MTBE Concentration: 0
MTBE Fuel: 0
MTBE Tested: YES
Staff: CAB
Staff Initials: LH6
Lead Agency: Local Agency

SHELL SERVICE STATION (Continued) **S105850485**

Local Agency:	36000L
Hydr Basin #:	Not reported
Beneficial:	MUN
Priority:	A2
Cleanup Fund Id:	Not reported
Work Suspended:	Not reported
Local Case Num:	2003014
Case Number:	Not reported
Qty Leaked:	Not reported
Abate Method:	Not reported
MTBE Class:	*
Summary:	Not reported

F29 **SHELL SERVICE STATION** **RCRA-SQG 1006805337**
SSE **1600 W VALLEY** **FINDS CAR000125997**
1/4-1/2 **COLTON, CA 92324** **HAZNET**
0.262 mi. **SWEEPS UST**
1382 ft. **Site 7 of 10 in cluster F**

Relative:
Lower

Actual:
1065 ft.

RCRA-SQG:

Date form received by agency:	08/16/2002
Facility name:	SHELL SERVICE STATION
Facility address:	1600 W VALLEY S A P 135180 COLTON, CA 92324
EPA ID:	CAR000125997
Mailing address:	P O BOX 2648 HOUSTON, TX 772522648
Contact:	SONDRA BIENVENU
Contact address:	P O BOX 2648 HOUSTON, TX 772522648
Contact country:	US
Contact telephone:	(713) 241-5036
Contact email:	Not reported
EPA Region:	09
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	EQUILON ENTERPRISES L L C
Owner/operator address:	P O BOX 2648 HOUSTON, TX 77252
Owner/operator country:	Not reported
Owner/operator telephone:	(713) 241-5036
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	Unknown
Mixed waste (haz. and radioactive):	Unknown
Recycler of hazardous waste:	No

1006805337

SHELL SERVICE STATION (Continued)

Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	Unknown
Furnace exemption:	Unknown
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No
Off-site waste receiver:	Commercial status unknown

Hazardous Waste Summary:

Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D018
Waste name: BENZENE

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site

California - Hazardous Waste Tracking System - Datamart

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZNET:

Gepaid:	CAR000125997
Contact:	Sondra Bienvenu
Telephone:	7132415036
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	PO BOX 2648
Mailing City,St,Zip:	Houston, TX 772522648
Gen County:	San Bernardino
TSD EPA ID:	Not reported
TSD County:	Los Angeles
Waste Category:	Tank bottom waste
Disposal Method:	Treatment, Tank
Tons:	0.68
Facility County:	Not reported

SHELL SERVICE STATION (Continued) **1006805337**

Gepaid: CAR000125997
Contact: N CORTEZ/ENVT'L DATA ANALYST
Telephone: 2818742224
Facility Addr2: S A P 135180
Mailing Name: Not reported
Mailing Address: 12700 NORTHBOROUGH DRIVE MFT240-G
Mailing City,St,Zip: Houston, TX 770672508
Gen County: San Bernardino
TSD EPA ID: CAD028409019
TSD County: San Bernardino
Waste Category: Aqueous solution with less than 10% total organic residues
Disposal Method: Treatment, Tank
Tons: 0.91
Facility County: San Bernardino

Gepaid: CAR000125997
Contact: N CORTEZ/ENVT'L DATA ANALYST
Telephone: 2818742224
Facility Addr2: S A P 135180
Mailing Name: Not reported
Mailing Address: 12700 NORTHBOROUGH DRIVE MFT240-G
Mailing City,St,Zip: Houston, TX 770672508
Gen County: San Bernardino
TSD EPA ID: CAD982484933
TSD County: San Bernardino
Waste Category: Other empty containers 30 gallons or more
Disposal Method: Disposal, Other
Tons: 2
Facility County: San Bernardino

SWEEPS UST:
Status: A
Comp Number: 18463
Number: 9
Board Of Equalization: 44-020681
Ref Date: 07-28-92
Act Date: 07-28-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 1
Swrcb Tank Id: 36-000-018463-000001
Actv Date: 07-07-88
Capacity: 550
Tank Use: OIL
Stg: W
Content: WASTE OIL
Number Of Tanks: 5

Status: A
Comp Number: 18463
Number: 9
Board Of Equalization: 44-020681
Ref Date: 07-28-92
Act Date: 07-28-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 2

SHELL SERVICE STATION (Continued) **1006805337**

Swrcb Tank Id: 36-000-018463-000002
Actv Date: 07-07-88
Capacity: 8000
Tank Use: M.V. FUEL
Stg: P
Content: REG UNLEADED
Number Of Tanks: Not reported

Status: A
Comp Number: 18463
Number: 9
Board Of Equalization: 44-020681
Ref Date: 07-28-92
Act Date: 07-28-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 3
Swrcb Tank Id: 36-000-018463-000003
Actv Date: 07-07-88
Capacity: 5000
Tank Use: M.V. FUEL
Stg: P
Content: REG UNLEADED
Number Of Tanks: Not reported

Status: A
Comp Number: 18463
Number: 9
Board Of Equalization: 44-020681
Ref Date: 07-28-92
Act Date: 07-28-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 4
Swrcb Tank Id: 36-000-018463-000004
Actv Date: 07-07-88
Capacity: 5000
Tank Use: M.V. FUEL
Stg: P
Content: REG UNLEADED
Number Of Tanks: Not reported

Status: A
Comp Number: 18463
Number: 9
Board Of Equalization: 44-020681
Ref Date: 07-28-92
Act Date: 07-28-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 5
Swrcb Tank Id: 36-000-018463-000005
Actv Date: 07-07-88
Capacity: 8000
Tank Use: M.V. FUEL
Stg: P
Content: LEADED

SHELL SERVICE STATION (Continued) **1006805337**

Number Of Tanks: Not reported

F30 **CHMIRS** **S105663913**
SSE **N/A**
1/4-1/2 **1599 VALLEY BLVD**
0.262 mi. **FONTANA, CA**
1382 ft. **Site 8 of 10 in cluster F**

Relative:
Lower

Actual:
1065 ft.

CHMIRS:

OES Incident Number:	00-5999
OES notification:	12/18/200005:01:26 AM
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	No
Waterway:	Not reported
Spill Site:	Not reported
Cleanup By:	County Roads
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	2000
Agency:	CHP Inland

S105663913

(Continued)

Incident Date:	12/18/200012:00:00 AM
Admin Agency:	San Bernardino County Health Department
Amount:	Not reported
Contained:	Yes
Site Type:	Road
E Date:	Not reported
Substance:	Diesel fuel
Quantity Released:	Not reported
BBLS:	0
Cups:	0
CUFT:	0
Gallons:	68
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	Big rig punctured saddle tank.

HAZNET S103633549
N/A

F31
SSE
1/4-1/2
0.265 mi.
1400 ft.

DON MORRISON
1595 W. VALLEY BLVD
COLTON, CA 92324

Site 9 of 10 in cluster F

Relative:
Lower

Actual:
1065 ft.

HAZNET:

Gepaid:	CAC000977968
Contact:	DON MORRISON
Telephone:	0000000000
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1090 COLOMA RD.
Mailing City,St,Zip:	PLACERVILLE, CA 956670000
Gen County:	San Bernardino
TSD EPA ID:	CAT080033681
TSD County:	Los Angeles
Waste Category:	Unspecified aqueous solution
Disposal Method:	Recycler
Tons:	1.2510
Facility County:	San Bernardino

F32 **CALIFORNIA AUTO SPECIALITIES** **HAZNET** **S104567780**
SSE **1595 W VALLEY BLVD** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.265 mi.
1400 ft. **Site 10 of 10 in cluster F**

Relative:
Lower

Actual:
1065 ft.

HAZNET:

Gepaid:	CAC001432528
Contact:	ED KELLER
Telephone:	9098253911
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1595 W VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	San Bernardino
TSD EPA ID:	CAD982444481
TSD County:	San Bernardino
Waste Category:	Unspecified oil-containing waste
Disposal Method:	Recycler
Tons:	0.834
Facility County:	San Bernardino

Gepaid:	CAC001432528
Contact:	ED KELLER
Telephone:	9098253911
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1595 W VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	San Bernardino
TSD EPA ID:	CAD982444481
TSD County:	San Bernardino
Waste Category:	Other empty containers 30 gallons or more
Disposal Method:	Recycler
Tons:	0.5
Facility County:	San Bernardino

H33 **COLTON GOLF COURSE** **San Bern. Co. Permit** **S104765431**
SW **1901 VALLEY BLVD** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.297 mi.
1566 ft. **Site 1 of 4 in cluster H**

Relative:
Lower

Actual:
1067 ft.

San Bern. Co. Permit:

Region:	SAN BERNARDINO
Facility ID:	FA0002433
Owner:	H & H INVESTMENTS CO, INC.
Permit Number:	PT0008799
Permit Category:	SPECIAL GENERATOR(B)
Facility Status:	ACTIVE
Expiration Date:	4/30/2008 12:00:00AM

Region:	SAN BERNARDINO
Facility ID:	FA0002433
Owner:	H & H INVESTMENTS CO, INC.
Permit Number:	PT0008798
Permit Category:	SPECIAL HANDLER
Facility Status:	ACTIVE
Expiration Date:	4/30/2008 12:00:00AM

H34
SW
1/4-1/2
0.297 mi.
1566 ft.

MOSS BROS FORD
1900 W VALLEY BLVD
COLTON, CA 92324

Site 2 of 4 in cluster H

FINDS 1008153008
HAZNET 110018973388

Relative:
Lower

Actual:
1067 ft.

FINDS:
Other Pertinent Environmental Activity Identified at Site

California - Hazardous Waste Tracking System - Datamart

HAZNET:

Gepaid:	CAL000262514
Contact:	MIKE DAWE, DIRECTOR P/S
Telephone:	9098251212
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1900 W VALLEY
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	San Bernardino
TSD EPA ID:	CAD028409019
TSD County:	Los Angeles
Waste Category:	Unspecified solvent mixture Waste
Disposal Method:	Transfer Station
Tons:	0.45
Facility County:	Not reported

Gepaid:	CAL000262514
Contact:	MIKE DAWE, MGR
Telephone:	9098251212
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1900 W VALLEY
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	San Bernardino
TSD EPA ID:	CAD028409019
TSD County:	Los Angeles
Waste Category:	Unspecified solvent mixture Waste
Disposal Method:	Transfer Station
Tons:	0.45
Facility County:	San Bernardino

Gepaid:	CAR000130690
Contact:	MIKE DANE, MGR
Telephone:	9098251212
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1900 W VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	San Bernardino
TSD EPA ID:	ARD981057870
TSD County:	99
Waste Category:	Waste oil and mixed oil
Disposal Method:	H06
Tons:	0.22
Facility County:	San Bernardino

Gepaid:	CAL000262514

MOSS BROS FORD (Continued) **1008153008**

Contact:	MIKE DAWE, DIRECTOR P/S
Telephone:	9098251212
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1900 W VALLEY
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	San Bernardino
TSD EPA ID:	CAD981696420
TSD County:	San Bernardino
Waste Category:	Waste oil and mixed oil
Disposal Method:	Recycler
Tons:	3.12
Facility County:	San Bernardino

Gepaid:	CAL000262514
Contact:	MIKE DAWE, DIRECTOR P/S
Telephone:	9098251212
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1900 W VALLEY
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	San Bernardino
TSD EPA ID:	CAT000613927
TSD County:	San Bernardino
Waste Category:	Aqueous solution with less than 10% total organic residues
Disposal Method:	Not reported
Tons:	0.45
Facility County:	San Bernardino

Click this hyperlink while viewing on your computer to access
4 additional CA_HAZNET: record(s) in the EDR Site Report.

H35 **MOSS BROS FORD.** **San Bern. Co. Permit** **S105790353**
SW **1900 W VALLEY BLVD** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.297 mi.
1566 ft. **Site 3 of 4 in cluster H**

Relative:
Lower

Actual:
1067 ft.

San Bern. Co. Permit:

Region:	SAN BERNARDINO
Facility ID:	FA0007627
Owner:	MOSS BROS FORD INC.
Permit Number:	PT0002636
Permit Category:	GENERATOR - 51-100 EMPLOYEES
Facility Status:	ACTIVE
Expiration Date:	11/30/2008 12:00:00AM

Region:	SAN BERNARDINO
Facility ID:	FA0007627
Owner:	MOSS BROS FORD INC.
Permit Number:	PT0002646
Permit Category:	HAZMAT HANDLER 51-100 EMPLOYEES (W/GEN PRMT)
Facility Status:	ACTIVE
Expiration Date:	11/30/2008 12:00:00AM

Region:	SAN BERNARDINO
Facility ID:	FA0007627
Owner:	MOSS BROS FORD INC.

MOSS BROS FORD. (Continued) **S105790353**

Permit Number: PT0012766
Permit Category: ABOVEGROUND PETROLEUM STORAGE (AST) (SPCC)
Facility Status: ACTIVE
Expiration Date: 11/30/2008 12:00:00AM

H36 **COLTON GOLF CLUB** **HAZNET** **S103958144**
SW **1901 W VALLEY BLVD** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.297 mi.
1566 ft. **Site 4 of 4 in cluster H**

Relative:
Lower

Actual:
1067 ft.

HAZNET:

Gepaid:	CAC001380464
Contact:	BOB JAMES
Telephone:	9098771712
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1901 W VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	San Bernardino
TSD EPA ID:	CAT080022148
TSD County:	San Bernardino
Waste Category:	Off-specification, aged, or surplus organics
Disposal Method:	Transfer Station
Tons:	.0834
Facility County:	San Bernardino

Gepaid:	CAC001380464
Contact:	BOB JAMES
Telephone:	9098771712
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1901 W VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	San Bernardino
TSD EPA ID:	CAD982444481
TSD County:	San Bernardino
Waste Category:	Off-specification, aged, or surplus organics
Disposal Method:	Transfer Station
Tons:	.0834
Facility County:	San Bernardino

Gepaid:	CAC001380464
Contact:	BOB JAMES
Telephone:	9098771712
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1901 W VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	San Bernardino
TSD EPA ID:	CAD982444481
TSD County:	San Bernardino
Waste Category:	Waste oil and mixed oil
Disposal Method:	Transfer Station
Tons:	.5004
Facility County:	San Bernardino

Gepaid: CAC001380464

COLTON GOLF CLUB (Continued) **S103958144**

Contact: BOB JAMES
Telephone: 9098771712
Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: 1901 W VALLEY BLVD
Mailing City,St,Zip: COLTON, CA 923240000
Gen County: San Bernardino
TSD EPA ID: CAD982444481
TSD County: San Bernardino
Waste Category: Unspecified oil-containing waste
Disposal Method: Transfer Station
Tons: .0834
Facility County: San Bernardino

Click this hyperlink while viewing on your computer to access
-1 additional CA_HAZNET: record(s) in the EDR Site Report.

37
NNW
1/4-1/2
0.317 mi.
1674 ft.

CARPENTERS JOINT APPRENT & TRNG **San Bern. Co. Permit** **S104764690**
1750 SAN BERNARDINO AVE **N/A**
COLTON, CA 92324

Relative:
Higher

Actual:
1103 ft.

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0001789
Owner: CARPENTERS JOINT APPRENT & TRN
Permit Number: PT0007921
Permit Category: HAZMAT HANDLER 0-10 EMPLOYEES
Facility Status: INACTIVE
Expiration Date: 5/31/2007 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0001789
Owner: CARPENTERS JOINT APPRENT & TRN
Permit Number: PT0007920
Permit Category: SPECIAL GENERATOR(B)
Facility Status: INACTIVE
Expiration Date: 5/31/2004 12:00:00AM

38
NNE
1/4-1/2
0.336 mi.
1772 ft.

CHMIRS **S100280750**
N/A

CORNER OF PEPPER/SAN BERNARDINO AVE.
COLTON, CA 92324

Relative:
Lower

Actual:
1081 ft.

CHMIRS:
OES Incident Number: 9990861
OES notification: Not reported
OES Date: Not reported
OES Time: Not reported
Incident Date: 20-FEB-88
Date Completed: 20-FEB-88
Property Use: 962
Agency Id Number: 36709
Agency Incident Number: 0

S100280750

(Continued)

Time Notified:	1855
Time Completed:	2000
Surrounding Area:	400
Estimated Temperature:	55
Property Management:	C
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Involved?:	N
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	LYNETTE E. REICHERT
Report Date:	07-MAY-88
Comments:	Y
Facility Telephone:	714 387-3044
Waterway Involved:	Not reported
Waterway:	Not reported
Spill Site:	Not reported
Cleanup By:	Not reported
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	88-92
Agency:	Not reported
Incident Date:	Not reported
Admin Agency:	Not reported
Amount:	Not reported
Contained:	Not reported
Site Type:	Not reported
E Date:	03-MAY-89
Substance:	Not reported
Quantity Released:	Not reported
BBLS:	Not reported
Cups:	Not reported
CUFT:	Not reported
Gallons:	Not reported
Grams:	Not reported
Pounds:	Not reported
Liters:	Not reported
Ounces:	Not reported
Pints:	Not reported

S100280750

(Continued)

Quarts:	Not reported
Sheen:	Not reported
Tons:	Not reported
Unknown:	Not reported
Description:	Not reported
Evacuations:	Not reported
Number of Injuries:	Not reported
Number of Fatalities:	Not reported
Description:	Not reported

I39 **HUD IN TOWN PROPERTIES** HAZNET S103621760
North **1065 AGUA CALIENTE LN** N/A
1/4-1/2 **COLTON, CA 92324**
0.373 mi.
1970 ft. **Site 1 of 2 in cluster I**

Relative: HAZNET:
Higher

Gepaid:	CAC001346304
Contact:	HUD
Telephone:	0000000000
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	2086 S E ST STE 204
Mailing City,St,Zip:	SAN BERNARDINO, CA 920480000
Gen County:	San Bernardino
TSD EPA ID:	CAD028409019
TSD County:	Los Angeles
Waste Category:	Household waste
Disposal Method:	Treatment, Tank
Tons:	.0250
Facility County:	San Bernardino

Actual:
1103 ft.

---

40 **INTOWN PROPERTIES INC/HUD** HAZNET S103970179
North **1001 WHISTLE STOP DR** N/A
1/4-1/2 **COLTON, CA 92324**
0.377 mi.
1993 ft.

Relative: HAZNET:
Higher

Gepaid:	CAC001389840
Contact:	HUD
Telephone:	7149577333
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	2086 SOUTH E ST STE 204
Mailing City,St,Zip:	SAN BERNARDINO, CA 924080000
Gen County:	San Bernardino
TSD EPA ID:	CAD982444481
TSD County:	San Bernardino
Waste Category:	Household waste
Disposal Method:	Transfer Station
Tons:	.0208
Facility County:	San Bernardino

Actual:
1101 ft.

J41 **GRACE WR & CO DISTRIB SVCS** **FINDS** **1000168595**
WSW **1988 W VALLEY BLVD** **RCRA-NonGen** **CAT000612168**
1/4-1/2 **COLTON, CA 92324**
0.386 mi.
2040 ft. **Site 1 of 6 in cluster J**

Relative:
Lower

Actual:
1068 ft.

FINDS:
Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

RCRA-NonGen:

Date form received by agency:	08/18/1980
Facility name:	GRACE WR & CO DISTRIB SVCS
Facility address:	1988 W VALLEY BLVD COLTON, CA 92324
EPA ID:	CAT000612168
Mailing address:	W VALLEY BLVD COLTON, CA 92324
Contact:	ENVIRONMENTAL MANAGER
Contact address:	1988 W VALLEY BLVD COLTON, CA 92324
Contact country:	US
Contact telephone:	(803) 433-2107
Contact email:	Not reported
EPA Region:	09
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	NOT REQUIRED
Owner/operator address:	NOT REQUIRED NOT REQUIRED, ME 99999
Owner/operator country:	Not reported
Owner/operator telephone:	(415) 555-1212
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported
Owner/operator name:	W R GRACE & CO
Owner/operator address:	NOT REQUIRED NOT REQUIRED, ME 99999
Owner/operator country:	Not reported
Owner/operator telephone:	(415) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: Unknown

GRACE WR & CO DISTRIB SVCS (Continued) **1000168595**

Mixed waste (haz. and radioactive):	Unknown
Recycler of hazardous waste:	No
Transporter of hazardous waste:	Yes
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	Unknown
Furnace exemption:	Unknown
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No
Off-site waste receiver:	Commercial status unknown

Violation Status: No violations found

J42 **SAMMON'S TRUCKING** **SWEEPS UST** **S106931760**
WSW **1988 W VALLEY BLVD** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.386 mi.
2040 ft. **Site 2 of 6 in cluster J**

Relative: **Lower**

Actual: **1068 ft.**

SWEEPS UST:

Status:	A
Comp Number:	13611
Number:	9
Board Of Equalization:	Not reported
Ref Date:	03-24-92
Act Date:	03-24-92
Created Date:	09-16-88
Tank Status:	A
Owner Tank Id:	Not reported
Swrcb Tank Id:	36-000-013611-000001
Actv Date:	09-16-88
Capacity:	1
Tank Use:	UNKNOWN
Stg:	P
Content:	UNKNOWN
Number Of Tanks:	1

---

43 **BISHOPS CENTRAL STORES** **HIST UST** **U001574701**
SSE **9908 PEPPER AVE** **SWEEPS UST** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.392 mi.
2070 ft.

Relative: **Lower**

Actual: **1063 ft.**

HIST UST:

Region:	STATE
Facility ID:	00000067062
Facility Type:	Other
Other Type:	CHURCH
Total Tanks:	0003
Contact Name:	Not reported
Telephone:	7148240486
Owner Name:	CHURCH OF JESUS CHRIST OF LATT

U001574701

BISHOPS CENTRAL STORES (Continued)

Owner Address: 9908 PEPPER AVE.
Owner City,St,Zip: COLTON, CA 92324

Tank Num: 001
Container Num: 6D4
Year Installed: 1977
Tank Capacity: 00000250
Tank Used for: WASTE
Type of Fuel: 5
Tank Construction: Unkown centimeters
Leak Detection: Visual, Stock Inventor

Tank Num: 002
Container Num: 6D1
Year Installed: 1977
Tank Capacity: 00012000
Tank Used for: PRODUCT
Type of Fuel: DIESEL
Tank Construction: Not reported
Leak Detection: Visual, Stock Inventor

Tank Num: 003
Container Num: 6D2
Year Installed: 1977
Tank Capacity: 00006000
Tank Used for: PRODUCT
Type of Fuel: DIESEL
Tank Construction: Not reported
Leak Detection: Visual, Stock Inventor

SWEEPS UST:
Status: A
Comp Number: 67062
Number: 9
Board Of Equalization: 44-021460
Ref Date: 08-28-91
Act Date: 08-28-91
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 6D2
Swrcb Tank Id: 36-000-067062-000003
Actv Date: 06-28-88
Capacity: 6000
Tank Use: M.V. FUEL
Stg: P
Content: DIESEL
Number Of Tanks: 1

K44 **WORLD PROPHETIC MINISTRY** **RCRA-SQG** **1001967567**
NNE **1099 N PEPPER AVE** **FINDS** **CAR000070615**
1/4-1/2 **COLTON, CA 92324** **HAZNET**
0.394 mi.
2080 ft. **Site 1 of 2 in cluster K**

Relative:
Higher

Actual:
1094 ft.

RCRA-SQG:

Date form received by agency:	04/17/2000
Facility name:	WORLD PROPHETIC MINISTRY
Facility address:	1099 N PEPPER AVE COLTON, CA 92324
EPA ID:	CAR000070615
Contact:	LIDGE GIBBSON
Contact address:	1099 N PEPPER AVE COLTON, CA 92324
Contact country:	US
Contact telephone:	(909) 825-2767
Contact email:	Not reported
EPA Region:	09
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	WORLD PROPHETIC MINISTRY
Owner/operator address:	1099 N PEPPER AVE COLTON, CA 92324
Owner/operator country:	Not reported
Owner/operator telephone:	(909) 825-2767
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	Unknown
Mixed waste (haz. and radioactive):	Unknown
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	Unknown
Furnace exemption:	Unknown
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No
Off-site waste receiver:	Commercial status unknown

Hazardous Waste Summary:

Waste code:	D000
Waste name:	Not Defined

WORLD PROPHETIC MINISTRY (Continued) **1001967567**

Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D018
Waste name: BENZENE

Waste code: D039
Waste name: TETRACHLOROETHYLENE

Waste code: D040
Waste name: TRICHLOROETHYLENE

Violation Status: No violations found

FINDS:
Other Pertinent Environmental Activity Identified at Site

California - Hazardous Waste Tracking System - Datamart

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZNET:
Gepaid: CAR000070615
Contact: ENVIRONMENTAL MGR
Telephone: 9098252767
Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: 1099 N PEPPER AVE
Mailing City,St,Zip: COLTON, CA 923240000
Gen County: San Bernardino
TSD EPA ID: Not reported
TSD County: Orange
Waste Category: Liquids with halogenated organic compounds > 1000 mg/l
Disposal Method: Transfer Station
Tons: 0.47
Facility County: Not reported

Gepaid: CAR000070615
Contact: ENVIRONMENTAL MGR
Telephone: 9098252767
Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: 1099 N PEPPER AVE
Mailing City,St,Zip: COLTON, CA 923240000
Gen County: San Bernardino

WORLD PROPHETIC MINISTRY (Continued) **1001967567**

TSD EPA ID:	Not reported
TSD County:	Los Angeles
Waste Category:	Waste oil and mixed oil
Disposal Method:	Recycler
Tons:	0.22
Facility County:	Not reported
Gepaid:	CAR000070615
Contact:	ENVIRONMENTAL MGR
Telephone:	9098252767
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1099 N PEPPER AVE
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	San Bernardino
TSD EPA ID:	Not reported
TSD County:	Orange
Waste Category:	Liquids with halogenated organic compounds > 1000 mg/l
Disposal Method:	Transfer Station
Tons:	0.07
Facility County:	Not reported

J45 **COLTON AUTO SALES** **HAZNET** **S103958142**
WSW **1998 W. VALLEY BLVD** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.398 mi.
2104 ft. **Site 3 of 6 in cluster J**

Relative: HAZNET:
Lower

Actual: Gepaid:	CAL000194592
1068 ft. Contact:	LINDA RAWDING/OWNER
Telephone:	9098209981
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1998 W. VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	San Bernardino
TSD EPA ID:	Not reported
TSD County:	Los Angeles
Waste Category:	Waste oil and mixed oil
Disposal Method:	Recycler
Tons:	0.22
Facility County:	Not reported
Gepaid:	CAL000194592
Contact:	LINDA RAWDING
Telephone:	9098209981
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1998 W. VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	San Bernardino
TSD EPA ID:	CAD008302903
TSD County:	Los Angeles
Waste Category:	Waste oil and mixed oil
Disposal Method:	Recycler
Tons:	.1668
Facility County:	San Bernardino

COLTON AUTO SALES (Continued) **S103958142**

Gepaid:	CAL000194592
Contact:	LINDA RAWDING
Telephone:	9098209981
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1998 W. VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	San Bernardino
TSD EPA ID:	CAD008302903
TSD County:	Los Angeles
Waste Category:	Other organic solids
Disposal Method:	Transfer Station
Tons:	.2000
Facility County:	San Bernardino

Gepaid:	CAL000194592
Contact:	LINDA RAWDING
Telephone:	9098209981
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1998 W. VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	San Bernardino
TSD EPA ID:	CAD008302903
TSD County:	Los Angeles
Waste Category:	Waste oil and mixed oil
Disposal Method:	Recycler
Tons:	0.417
Facility County:	San Bernardino

Gepaid:	CAL000194592
Contact:	LINDA RAWDING
Telephone:	9098209981
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1998 W. VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	San Bernardino
TSD EPA ID:	CAD008302903
TSD County:	Los Angeles
Waste Category:	Waste oil and mixed oil
Disposal Method:	Recycler
Tons:	.5212
Facility County:	San Bernardino

Click this hyperlink while viewing on your computer to access additional CA_HAZNET: detail in the EDR Site Report.

INTOWN PROPERTIES INC (Continued) **S103622097**

Disposal Method: Transfer Station
Tons: .0291
Facility County: San Bernardino

I48 **HUD INTOWN PROPERTIES** **HAZNET** **S103968836**
North **1801 DE CARMEN DR** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.406 mi.
2144 ft. **Site 2 of 2 in cluster I**

Relative: **Higher**

Actual: **1110 ft.**

HAZNET:
Gepaid: CAC001498240
Contact: HUD
Telephone: 0000000000
Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: 2086 S E ST STE 204
Mailing City,St,Zip: SAN BERNARDINO, CA 924080000
Gen County: San Bernardino
TSD EPA ID: CAD982444481
TSD County: San Bernardino
Waste Category: Household waste
Disposal Method: Transfer Station
Tons: .0125
Facility County: San Bernardino

J49 **LARSEN, BRAD & CAROL** **San Bern. Co. Permit** **S106112121**
WSW **2006 W VALLEY BLVD** **SWEEPS UST** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.407 mi.
2148 ft. **Site 5 of 6 in cluster J**

Relative: **Lower**

Actual: **1068 ft.**

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0007517
Owner: VASQUEZ, JOSE
Permit Number: PT0012881
Permit Category: ABOVEGROUND PETROLEUM STORAGE (AST) (SPCC)
Facility Status: ACTIVE
Expiration Date: 11/30/2008 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0007517
Owner: VASQUEZ, JOSE
Permit Number: PT0012880
Permit Category: SPECIAL HANDLER
Facility Status: ACTIVE
Expiration Date: 11/30/2008 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0007517
Owner: VASQUEZ, JOSE
Permit Number: PT0012879
Permit Category: SPECIAL GENERATOR(B)
Facility Status: ACTIVE
Expiration Date: 11/30/2008 12:00:00AM

LARSEN, BRAD & CAROL (Continued) **S106112121**

SWEEPS UST:

Status:	A
Comp Number:	7907
Number:	2
Board Of Equalization:	44-020027
Ref Date:	03-24-92
Act Date:	03-24-92
Created Date:	09-15-88
Tank Status:	A
Owner Tank Id:	Not reported
Swrcb Tank Id:	36-000-007907-000001
Actv Date:	09-15-88
Capacity:	1
Tank Use:	UNKNOWN
Stg:	P
Content:	UNKNOWN
Number Of Tanks:	1

J50 **SIERRA DIESEL REPAIR** HAZNET **S103987927**
WSW **2006 WEST VALLEY** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.407 mi.
2148 ft. **Site 6 of 6 in cluster J**

Relative: **Lower**

Actual: **1068 ft.**

HAZNET:

Gepaid:	CAL000115443
Contact:	JAMES SMITH
Telephone:	9099479254
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	2006 W VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 923241831
Gen County:	San Bernardino
TSD EPA ID:	CAL922955281
TSD County:	Santa Clara
Waste Category:	Photochemicals/photoprocessing waste
Disposal Method:	Not reported
Tons:	.0583
Facility County:	San Bernardino

K51 **KRAGEN AUTO PARTS #4298** San Bern. Co. Permit **S108724333**
NNE **1100 N PEPPER AVE** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.417 mi.
2203 ft. **Site 2 of 2 in cluster K**

Relative: **Higher**

Actual: **1094 ft.**

San Bern. Co. Permit:

Region:	SAN BERNARDINO
Facility ID:	FA0011114
Owner:	CSK AUTO, INC.
Permit Number:	PT0019217
Permit Category:	SPECIAL HANDLER
Facility Status:	ACTIVE
Expiration Date:	9/30/2007 12:00:00AM

Region:	SAN BERNARDINO

KRAGEN AUTO PARTS #4298 (Continued) **S108724333**

Facility ID: FA0011114
Owner: CSK AUTO, INC.
Permit Number: PT0019218
Permit Category: SPECIAL GENERATOR(B)
Facility Status: ACTIVE
Expiration Date: 9/30/2007 12:00:00AM

L52 **HUD INTOWN PROPERTIES** **HAZNET** **S103968852**
NNW **1897 DE CARMEN DR** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.430 mi.
2272 ft. **Site 1 of 2 in cluster L**

Relative: HAZNET:
Higher
Gepaid: CAC001497344
Contact: HUD
Actual: Telephone: 0000000000
1127 ft. Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: 2086 S E ST STE 204
Mailing City,St,Zip: SAN BERNARDINO, CA 924080000
Gen County: San Bernardino
TSD EPA ID: CAD982444481
TSD County: San Bernardino
Waste Category: Household waste
Disposal Method: Transfer Station
Tons: .0625
Facility County: San Bernardino

---

53 **1X COUNTY OF SAN BERNARDINO** **HAZNET** **S104565139**
NE **1500 W SAN BERNARDINO AVE** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.431 mi.
2277 ft.

Relative: HAZNET:
Higher
Gepaid: CAC000902760
Contact: Not reported
Actual: Telephone: 0000000000
1100 ft. Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: 825 E 3RD ST
Mailing City,St,Zip: SAN BERNARDINO, CA 924150849
Gen County: San Bernardino
TSD EPA ID: CAD980883177
TSD County: Kern
Waste Category: Tank bottom waste
Disposal Method: Recycler
Tons: 1.0425
Facility County: San Bernardino

M54 **HUD INTOWN PROPERTIES** **HAZNET** **S103968661**
North **1174 EXPRESS CIR** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.431 mi.
2278 ft. **Site 1 of 3 in cluster M**

Relative: HAZNET:
Higher

Gepaid:	CAC002125832
Contact:	HUD
Actual: Telephone:	0000000000
1112 ft. Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	2086 S E T STE 204
Mailing City,St,Zip:	SAN BERNARDINO, CA 924080000
Gen County:	San Bernardino
TSD EPA ID:	CAD028409019
TSD County:	Los Angeles
Waste Category:	Household waste
Disposal Method:	Treatment, Tank
Tons:	.0025
Facility County:	San Bernardino

Gepaid:	CAC002125832
Contact:	HUD
Telephone:	0000000000
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	2086 S E T STE 204
Mailing City,St,Zip:	SAN BERNARDINO, CA 924080000
Gen County:	San Bernardino
TSD EPA ID:	CAD028409019
TSD County:	Los Angeles
Waste Category:	Household waste
Disposal Method:	Transfer Station
Tons:	.0075
Facility County:	San Bernardino

M55 **HUD INTOWN PROPERTIES** **HAZNET** **S103968666**
North **1187 EXPRESS CIR** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.441 mi.
2330 ft. **Site 2 of 3 in cluster M**

Relative: HAZNET:
Higher

Gepaid:	CAC001503536
Contact:	HUD
Actual: Telephone:	0000000000
1117 ft. Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	2086 S E ST STE 204
Mailing City,St,Zip:	SAN BERNARDINO, CA 924080000
Gen County:	San Bernardino
TSD EPA ID:	CAD982444481
TSD County:	San Bernardino
Waste Category:	Household waste
Disposal Method:	Transfer Station
Tons:	.0208
Facility County:	San Bernardino

N56 **OROWEAT FOODS CO/RIALTO** **San Bern. Co. Permit S102041385**
WSW **2036 W VALLEY BLVD** **SWEEPS UST N/A**
1/4-1/2 **COLTON, CA 92324**
0.446 mi.
2352 ft. **Site 1 of 3 in cluster N**

Relative:
Lower

Actual:
1069 ft.

San Bern. Co. Permit:

Region:	SAN BERNARDINO
Facility ID:	FA0002924
Owner:	ENTENMANN'S OROWHEAT
Permit Number:	PT0002886
Permit Category:	SPECIAL GENERATOR(B)
Facility Status:	INACTIVE
Expiration Date:	4/30/2007 12:00:00AM

Region:	SAN BERNARDINO
Facility ID:	FA0002924
Owner:	ENTENMANN'S OROWHEAT
Permit Number:	PT0002887
Permit Category:	SPECIAL HANDLER
Facility Status:	INACTIVE
Expiration Date:	4/30/2007 12:00:00AM

SWEEPS UST:

Status:	A
Comp Number:	8398
Number:	1
Board Of Equalization:	Not reported
Ref Date:	03-24-92
Act Date:	03-24-92
Created Date:	09-21-88
Tank Status:	A
Owner Tank Id:	Not reported
Swrcb Tank Id:	36-000-008398-000001
Actv Date:	09-21-88
Capacity:	1
Tank Use:	UNKNOWN
Stg:	P
Content:	UNKNOWN
Number Of Tanks:	1

L57 **HUD** **HAZNET S103638708**
NNW **1927 DE CARMEN DR** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.447 mi.
2359 ft. **Site 2 of 2 in cluster L**

Relative:
Higher

Actual:
1129 ft.

HAZNET:

Gepaid:	CAC001299888
Contact:	HUD
Telephone:	0000000000
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	INTOWN PROPERTIES
Mailing City,St,Zip:	RANCHO CUCAMONGA, CA 917300000
Gen County:	San Bernardino
TSD EPA ID:	CAD000088252
TSD County:	Los Angeles
Waste Category:	Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)

HUD (Continued) **S103638708**

Disposal Method: Transfer Station
Tons: .0041
Facility County: San Bernardino

N58 **BIMBO BAKERIES USA INC** **HAZNET** **S108743236**
WSW **2036 W VALLEY BLVD** **N/A**
1/4-1/2 **RIALTO, CA 92376**
0.448 mi.
2364 ft. **Site 2 of 3 in cluster N**

Relative: HAZNET:
Lower
Gepaid: CAL000257126
Contact: MARK ARMSTRONG/SR PROJECT ENGR
Actual: Telephone: 3237206002
1069 ft. Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: 480 S VAIL AVE
Mailing City,St,Zip: MONTEBELLO, CA 906400000
Gen County: San Bernardino
TSD EPA ID: CAT080013352
TSD County: Los Angeles
Waste Category: Unspecified organic liquid mixture
Disposal Method: Recycler
Tons: 0.16
Facility County: San Bernardino

---

59 **FOOD 4 LESS #786** **HAZNET** **S108207042**
NNE **1150 N PEPPER AVE** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.455 mi.
2400 ft.

Relative: HAZNET:
Higher
Gepaid: CAL000278830
Contact: JULIE BAKAS
Actual: Telephone: 9093701761
1101 ft. Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: 2100 WILMINGTON
Mailing City,St,Zip: COMPTON, CA 90220
Gen County: San Bernardino
TSD EPA ID: CAD008302903
TSD County: Los Angeles
Waste Category: Other organic solids
Disposal Method: Not reported
Tons: 0.03
Facility County: Not reported

Gepaid: CAL000278830
Contact: JULIE BAKAS
Telephone: 9093701761
Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: 2100 WILMINGTON
Mailing City,St,Zip: COMPTON, CA 90220
Gen County: San Bernardino

FOOD 4 LESS #786 (Continued) **S108207042**

TSD EPA ID:	CAD008302903
TSD County:	Los Angeles
Waste Category:	Other organic solids
Disposal Method:	Not reported
Tons:	0.03
Facility County:	Not reported
Gepaid:	CAL000278830
Contact:	JULIE BAKAS
Telephone:	9093701761
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	2100 WILMINGTON
Mailing City,St,Zip:	COMPTON, CA 90220
Gen County:	San Bernardino
TSD EPA ID:	CAD008302903
TSD County:	Los Angeles
Waste Category:	Other organic solids
Disposal Method:	Transfer Station
Tons:	0.04
Facility County:	San Bernardino

M60 CDL S107529298
NNE **1610 NORTH BENT RAIL CIRCLE** N/A
1/4-1/2 **COLTON, CA 92324**
0.455 mi.
2405 ft. **Site 3 of 3 in cluster M**

Relative: **Higher**

Actual: **1103 ft.**

CDL:

Facility ID:	199705022
Date:	1997-05-05 00:00:00
Lab Type:	Illegal Drug Lab (L) - location where an illegal drug lab was operated or drug lab equipment and/or materials were stored.

N61 **LANDJET MOTOR CARRIERS** San Bern. Co. Permit S102683578
WSW **2048 W VALLEY BLVD** N/A
1/4-1/2 **COLTON, CA 92324**
0.464 mi.
2450 ft. **Site 3 of 3 in cluster N**

Relative: **Lower**

Actual: **1070 ft.**

San Bern. Co. Permit:

Region:	SAN BERNARDINO
Facility ID:	FA0004376
Owner:	SACALAS, BARRY
Permit Number:	PT0009072
Permit Category:	SPECIAL HANDLER
Facility Status:	ACTIVE
Expiration Date:	7/31/2008 12:00:00AM
Region:	SAN BERNARDINO
Facility ID:	FA0004376
Owner:	SACALAS, BARRY
Permit Number:	PT0009073
Permit Category:	SPECIAL GENERATOR(B)
Facility Status:	ACTIVE
Expiration Date:	7/31/2008 12:00:00AM

O62 **HUD** **HAZNET** **S103634592**
North **1641 IRON HORSE CIR** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.491 mi.
2594 ft. **Site 1 of 2 in cluster O**

Relative: HAZNET:
Higher

Gepaid:	CAC001304672
Contact:	HUD
Actual: Telephone:	0000000000
1112 ft. Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	2086 SOUTH E ST STE 204
Mailing City,St,Zip:	SAN BERNARDINO, CA 924080000
Gen County:	San Bernardino
TSD EPA ID:	CAD000088252
TSD County:	Los Angeles
Waste Category:	Alkaline solution without metals (pH > 12.5)
Disposal Method:	Transfer Station
Tons:	.0041
Facility County:	San Bernardino

Gepaid:	CAC001304672
Contact:	HUD
Telephone:	0000000000
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	2086 SOUTH E ST STE 204
Mailing City,St,Zip:	SAN BERNARDINO, CA 924080000
Gen County:	San Bernardino
TSD EPA ID:	CAD000088252
TSD County:	Los Angeles
Waste Category:	Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method:	Transfer Station
Tons:	.0125
Facility County:	San Bernardino

O63 **ASSETT MANAGEMENT SPECIALIST** **HAZNET** **S104567368**
North **1620 IRON HORSE CIRCLE** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.493 mi.
2605 ft. **Site 2 of 2 in cluster O**

Relative: HAZNET:
Higher

Gepaid:	CAC001427424
Contact:	ERNIE STEFKOVIC
Actual: Telephone:	0000000000
1107 ft. Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1141 POMONA RD STE D
Mailing City,St,Zip:	CORONA, CA 917200000
Gen County:	San Bernardino
TSD EPA ID:	CAD982444481
TSD County:	San Bernardino
Waste Category:	Household waste
Disposal Method:	Transfer Station
Tons:	0.0675
Facility County:	San Bernardino

64 **HUD** **HAZNET** **S103637765**
North **1851 GOLDEN SPIKE DR** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.498 mi.
2629 ft.

Relative: HAZNET:
Higher

Gepaid:	CAC001299880
Contact:	HUD
Actual: Telephone:	0000000000
1130 ft. Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	INTOWN PROPERTIES
Mailing City,St,Zip:	SAN BERNARDINO, CA 924080000
Gen County:	San Bernardino
TSD EPA ID:	CAD000088252
TSD County:	Los Angeles
Waste Category:	Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method:	Transfer Station
Tons:	.0417
Facility County:	San Bernardino

P65 **COLTON JT USD/WAREHOUSE** **HAZNET** **S102038873**
ESE **1313 W VALLEY BLVD** **San Bern. Co. Permit** **N/A**
1/2-1 **COLTON, CA 92324**
0.534 mi.
2820 ft. **Site 1 of 3 in cluster P**

Relative: HAZNET:
Lower

Gepaid:	CAD982331746
Contact:	COLTON JNT UNFD SHCOOL DIST
Actual: Telephone:	9098764123
1031 ft. Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1212 VALENCIA DR
Mailing City,St,Zip:	COLTON, CA 923241731
Gen County:	San Bernardino
TSD EPA ID:	CAD982444481
TSD County:	San Bernardino
Waste Category:	Unspecified organic liquid mixture
Disposal Method:	Transfer Station
Tons:	.2085
Facility County:	San Bernardino

Gepaid:	CAD982331746
Contact:	COLTON JNT UNFD SHCOOL DIST
Telephone:	9098764123
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1212 VALENCIA DR
Mailing City,St,Zip:	COLTON, CA 923241731
Gen County:	San Bernardino
TSD EPA ID:	NVT330010000
TSD County:	99
Waste Category:	Polychlorinated biphenyls and material containing PCB's
Disposal Method:	Not reported
Tons:	7.6644
Facility County:	San Bernardino

Gepaid:	CAD982331746

COLTON JT USD/WAREHOUSE (Continued) **S102038873**

Contact: COLTON JNT UNFD SHCOOL DIST
Telephone: 9098764123
Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: 1212 VALENCIA DR
Mailing City,St,Zip: COLTON, CA 923241731
Gen County: San Bernardino
TSD EPA ID: CAD008252405
TSD County: Los Angeles
Waste Category: Unspecified solvent mixture Waste
Disposal Method: Recycler
Tons: .1334
Facility County: San Bernardino

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0005966
Owner: COLTON UNIFIED SCHOOL
Permit Number: PT0004263
Permit Category: HAZMAT HANDLER 0-10 EMPLOYEES
Facility Status: ACTIVE
Expiration Date: 5/31/2008 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0005966
Owner: COLTON UNIFIED SCHOOL
Permit Number: PT0004262
Permit Category: SPECIAL GENERATOR(B)
Facility Status: ACTIVE
Expiration Date: 5/31/2008 12:00:00AM

P66 **COLTON JOINT USD/WAREHOUSE** **HAZNET** **S108202874**
ESE **1313 W VALLEY BLVD** **N/A**
1/2-1 **COLTON, CA 92324**
0.534 mi.
2820 ft. **Site 2 of 3 in cluster P**

Relative:
Lower

Actual:
1031 ft.

HAZNET:
Gepaid: CAD982331746
Contact: E LERMA DIR OF MAINT & OPS
Telephone: 9098764160
Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: 1313 W VALLEY BLVD
Mailing City,St,Zip: COLTON, CA 92324
Gen County: San Bernardino
TSD EPA ID: CAD028409019
TSD County: Los Angeles
Waste Category: Unspecified aqueous solution
Disposal Method: Treatment, Tank
Tons: 0.02
Facility County: Not reported

Gepaid: CAD982331746
Contact: E LERMA DIR OF MAINT & OPS
Telephone: 9098764160
Facility Addr2: Not reported

COLTON JOINT USD/WAREHOUSE (Continued) **S108202874**

Mailing Name:	Not reported
Mailing Address:	1313 W VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 92324
Gen County:	San Bernardino
TSD EPA ID:	CAD028409019
TSD County:	Los Angeles
Waste Category:	Unspecified aqueous solution
Disposal Method:	Treatment, Tank
Tons:	0.02
Facility County:	Not reported

Q67 **PRICE CLUB** **SWEEPS UST** **S106930885**
WSW **2109 W VALLEY** **N/A**
1/2-1 **COLTON, CA 92324**
0.534 mi.
2818 ft. **Site 1 of 3 in cluster Q**

Relative:
Lower

Actual:
1073 ft.

SWEEPS UST:

Status:	A
Comp Number:	13847
Number:	1
Board Of Equalization:	44-020518
Ref Date:	03-24-92
Act Date:	03-24-92
Created Date:	09-23-88
Tank Status:	A
Owner Tank Id:	Not reported
Swrcb Tank Id:	36-000-013847-000001
Actv Date:	09-23-88
Capacity:	1
Tank Use:	UNKNOWN
Stg:	P
Content:	UNKNOWN
Number Of Tanks:	3

Status:	A
Comp Number:	13847
Number:	1
Board Of Equalization:	44-020518
Ref Date:	03-24-92
Act Date:	03-24-92
Created Date:	09-23-88
Tank Status:	A
Owner Tank Id:	Not reported
Swrcb Tank Id:	36-000-013847-000002
Actv Date:	09-23-88
Capacity:	1
Tank Use:	UNKNOWN
Stg:	P
Content:	UNKNOWN
Number Of Tanks:	Not reported

Status:	A
Comp Number:	13847
Number:	1
Board Of Equalization:	44-020518
Ref Date:	03-24-92
Act Date:	03-24-92

PRICE CLUB (Continued) **S106930885**

Created Date:	09-23-88
Tank Status:	A
Owner Tank Id:	Not reported
Swrcb Tank Id:	36-000-013847-000003
Actv Date:	09-23-88
Capacity:	1
Tank Use:	UNKNOWN
Stg:	P
Content:	UNKNOWN
Number Of Tanks:	Not reported

P68 **COLTON JOINT UNIFIED SCHOOL DISTRICT** **FTTS 1009512654**
ESE **1313 W VALLEY BLVD** **HIST FTTS N/A**
1/2-1 **COLTON, CA 92324**
0.535 mi.
2823 ft. **Site 3 of 3 in cluster P**

Relative:
Lower

Actual:
1031 ft.

FTTS INSP:

Inspection Number:	Not reported
Region:	09
Inspection Date:	Not reported
Inspector:	LGARCIA
Violation occurred:	Yes
Investigation Type:	Section 6 PCB State Conducted
Investigation Reason:	Neutral Scheme, State
Legislation Code:	TSCA
Facility Function:	User

HIST FTTS INSP:

Inspection Number:	1991102301231 3
Region:	09
Inspection Date:	Not reported
Inspector:	LGARCIA
Violation occurred:	Yes
Investigation Type:	Section 6 PCB State Conducted
Investigation Reason:	Neutral Scheme, State
Legislation Code:	TSCA
Facility Function:	User

Q69 **TELCO FOOD PRODUCTS** **AIRS S108433425**
WSW **2111 W VALLEY BLVD** **N/A**
1/2-1 **COLTON, CA 92324**
0.537 mi.
2838 ft. **Site 2 of 3 in cluster Q**

Relative:
Lower

Actual:
1073 ft.

EMI:

Year:	2005
Carbon Monoxide Emissions Tons/Yr:	36
Air Basin:	SC
Facility ID:	141077
Air District Name:	SC
SIC Code:	2051
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported

TELCO FOOD PRODUCTS (Continued) **S108433425**

Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	3.064
Reactive Organic Gases Tons/Yr:	2.0313324
Carbon Monoxide Emissions Tons/Yr:	1.98
NOX - Oxides of Nitrogen Tons/Yr:	1.44
SOX - Oxides of Sulphur Tons/Yr:	.0339
Particulate Matter Tons/Yr:	.664
Part. Matter 10 Micrometers & Smllr Tons/Yr:	.63704

Q70 **TELCO FOODS** **LUST** **S108723555**
WSW **2111 VALLEY BOULEVARD WEST** **N/A**
1/2-1 **COLTON, CA 92324**
0.537 mi.
2838 ft. **Site 3 of 3 in cluster Q**

Relative: **Lower**

Actual: **1073 ft.**

LUST:

Region:	STATE
Case Type:	Soil only
Cross Street:	WILDROSE AVENUE
Enf Type:	LOPF
Funding:	Not reported
How Discovered:	Tank Closure
How Stopped:	Close Tank
Leak Cause:	UNK
Leak Source:	UNK
Global Id:	T0607105014
Stop Date:	Not reported
Confirm Leak:	Not reported
Workplan:	Not reported
Prelim Assess:	Not reported
Pollution Char:	Not reported
Remed Plan:	Not reported
Remed Action:	Not reported
Monitoring:	Not reported
Close Date:	2007-07-30 00:00:00
Discover Date:	1997-04-30 00:00:00
Enforcement Dt:	Not reported
Release Date:	2006-11-21 00:00:00
Review Date:	Not reported
Enter Date:	Not reported
MTBE Date:	Not reported
GW Qualifier:	Not reported
Soil Qualifier:	=
Max MTBE GW ppb:	Not reported
Max MTBE Soil ppb:	Not reported
County:	36
Org Name:	Not reported
Reg Board:	Santa Ana Region
Status:	Case Closed
Chemical:	Gasoline
Contact Person:	Not reported
Responsible Party:	FRANK LOWRIE
RP Address:	2111 W. VALLEY BOULEVARD
Interim:	Not reported
Oversight Prgm:	LUST
MTBE Class:	*
MTBE Conc:	0
MTBE Fuel:	1

TELCO FOODS (Continued) **S108723555**

MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.
Staff: Not reported
Staff Initials: JC3
Lead Agency: Local Agency
Local Agency: 36000L
Hydr Basin #: Not reported
Beneficial: Not reported
Priority: Not reported
Cleanup Fund Id: Not reported
Work Suspended: Not reported
Local Case #: 2006010
Case Number: Not reported
Qty Leaked: Not reported
Abate Method: Not reported
Operator: Not reported
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 0
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported
Summary: Not reported

71
ENE
1/2-1
0.541 mi.
2855 ft.

987 N CYPRESS ST
COLTON, CA 92324

CDL **S107537386**
N/A

Relative:
Higher

Actual:
1088 ft.

CDL:
Facility ID: 200307097
Date: 2003-07-21 00:00:00
Lab Type: Illegal Drug Lab (L) - location where an illegal drug lab was operated or drug lab equipment and/or materials were stored.

R72
WSW
1/2-1
0.555 mi.
2931 ft.

2111 WEST VALLEY BLVD
2111 WEST VALLEY BLVD
COLTON, CA 0

Site 1 of 6 in cluster R

ERNS **2002597380**
N/A

Relative:
Lower

Actual:
1081 ft.

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

R73
WSW
1/2-1
0.555 mi.
2931 ft.

2111 W. VALLEY BLVD
COLTON, CA 92324

Site 2 of 6 in cluster R

CHMIRS **S105882965**
N/A

Relative:
Lower

Actual:
1081 ft.

CHMIRS:
OES Incident Number: 02-1449
OES notification: 3/17/200208:39:58 PM
OES Date: Not reported
OES Time: Not reported
Incident Date: Not reported

(Continued) S105882965

Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	No
Waterway:	Not reported
Spill Site:	Not reported
Cleanup By:	Contractor
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	2002
Agency:	San Bernardino FD
Incident Date:	3/17/200212:00:00 AM
Admin Agency:	San Bernardino County Health Department
Amount:	Not reported
Contained:	Yes
Site Type:	Other
E Date:	Not reported
Substance:	ammonia anhydrous
Quantity Released:	Not reported
BBLS:	0
Cups:	0
CUFT:	0
Gallons:	0.000000
Grams:	0

(Continued) **S105882965**

Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	Compressor seal burst causing the release. Food storage facility. All is contained inside the building.

R74 CHMIRS S105883679
WSW **2111 W. VALLEY BLVD.** N/A
1/2-1 **COLTON, CA 92324**
0.555 mi.
2931 ft. **Site 3 of 6 in cluster R**

Relative: CHMIRS:
Lower

OES Incident Number:	02-1581
OES notification:	3/22/200203:41:18 PM
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported

(Continued) **S105883679**

Facility Telephone:	Not reported
Waterway Involved:	No
Waterway:	Not reported
Spill Site:	Not reported
Cleanup By:	N/A
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	2002
Agency:	Telco
Incident Date:	3/17/200212:00:00 AM
Admin Agency:	San Bernardino County Health Department
Amount:	Not reported
Contained:	Yes
Site Type:	Industrial Plant
E Date:	Not reported
Substance:	Anhydrous Ammonia
Quantity Released:	Not reported
BBLS:	0
Cups:	0
CUFT:	0
Gallons:	0.000000
Grams:	0
Pounds:	500
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	HISTORICAL REPORT: Valve failed causing this release.

R75 **TELCO FOOD PRODUCTS, INC.** **San Bern. Co. Permit** **S104770949**
WSW **2111 W VALLEY BLVD** **N/A**
1/2-1 **COLTON, CA 92324**
0.555 mi.
2931 ft. **Site 4 of 6 in cluster R**

Relative:
Lower

Actual:
1081 ft.

San Bern. Co. Permit:

Region:	SAN BERNARDINO
Facility ID:	FA0006607
Owner:	TELLIARD, TIMOTHY P.
Permit Number:	PT0009722
Permit Category:	RISK MANAGEMENT PLAN - LEVEL III
Facility Status:	ACTIVE
Expiration Date:	9/30/2008 12:00:00AM

Region:	SAN BERNARDINO
Facility ID:	FA0006607
Owner:	TELLIARD, TIMOTHY P.

TELCO FOOD PRODUCTS, INC. (Continued) **S104770949**

Permit Number: PT0009738
Permit Category: CALARP FACILITY PERMIT
Facility Status: ACTIVE
Expiration Date: 9/30/2008 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0006607
Owner: TELLIARD, TIMOTHY P.
Permit Number: PT0009723
Permit Category: EPCRA FACILITY (RIGHT TO KNOW PLAN)
Facility Status: ACTIVE
Expiration Date: 9/30/2008 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0006607
Owner: TELLIARD, TIMOTHY P.
Permit Number: PT0009736
Permit Category: HAZMAT HANDLER 26-50 EMPLOYEES
Facility Status: ACTIVE
Expiration Date: 9/30/2008 12:00:00AM

R76
WSW
1/2-1
0.555 mi.
2931 ft.

Relative:
Lower

Actual:
1081 ft.

PRICE CLUB # 106 **HAZNET** **S100871248**
2111 W VALLEY BLVD **N/A**
COLTON, CA 92324

Site 5 of 6 in cluster R

HAZNET:
Gepaid: CAL000055261
Contact: Not reported
Telephone: 0000000000
Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: 10809 120TH AVE NE
Mailing City,St,Zip: KIRKLAND, WA 980330000
Gen County: San Bernardino
TSD EPA ID: CAD003963592
TSD County: Santa Clara
Waste Category: Metal sludge - Alkaline solution (pH <UN-> 12.5) with metals (antimony, arsenic, barium, beryllium, cadmium, chromium, cobalt, copper, lead, mercury, molybdenum, nickel, selenium, silver, thallium, vanadium, and zinc)
Disposal Method: Recycler
Tons: .3000
Facility County: San Bernardino

Gepaid: CAL000055261
Contact: Not reported
Telephone: 0000000000
Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: 10809 120TH AVE NE
Mailing City,St,Zip: KIRKLAND, WA 980330000
Gen County: San Bernardino
TSD EPA ID: CAD003963592
TSD County: Santa Clara
Waste Category: Metal sludge - Alkaline solution (pH <UN-> 12.5) with metals (antimony, arsenic, barium, beryllium, cadmium, chromium, cobalt,

PRICE CLUB # 106 (Continued) **S100871248**

copper, lead, mercury, molybdenum, nickel, selenium, silver, thallium, vanadium, and zinc)
Disposal Method: Recycler
Tons: .2000
Facility County: San Bernardino

Gepaid: CAL000055261
Contact: Not reported
Telephone: 0000000000
Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: 10809 120TH AVE NE
Mailing City,St,Zip: KIRKLAND, WA 980330000
Gen County: San Bernardino
TSD EPA ID: CAD003963592
TSD County: Santa Clara
Waste Category: Other inorganic solid waste
Disposal Method: Recycler
Tons: .0600
Facility County: San Bernardino

Gepaid: CAL000055261
Contact: Not reported
Telephone: 0000000000
Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: 10809 120TH AVE NE
Mailing City,St,Zip: KIRKLAND, WA 980330000
Gen County: San Bernardino
TSD EPA ID: CAD003963592
TSD County: Santa Clara
Waste Category: Metal sludge - Alkaline solution (pH <UN-> 12.5) with metals (antimony, arsenic, barium, beryllium, cadmium, chromium, cobalt, copper, lead, mercury, molybdenum, nickel, selenium, silver, thallium, vanadium, and zinc)
Disposal Method: Recycler
Tons: .2000
Facility County: San Bernardino

Gepaid: CAL000055261
Contact: Not reported
Telephone: 0000000000
Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: 10809 120TH AVE NE
Mailing City,St,Zip: KIRKLAND, WA 980330000
Gen County: San Bernardino
TSD EPA ID: CAT080013352
TSD County: Los Angeles
Waste Category: Waste oil and mixed oil
Disposal Method: Recycler
Tons: 1.6680
Facility County: San Bernardino

Click this hyperlink while viewing on your computer to access additional CA_HAZNET: detail in the EDR Site Report.

R77
WSW
1/2-1
0.555 mi.
2931 ft.

TALCO INC
2111 VALLEY BLVD
COLTON, CA 92325

Site 6 of 6 in cluster R

HAZNET **S105085433**
N/A

Relative:
Lower

Actual:
1081 ft.

HAZNET:

Gepaid:	CAC002455311
Contact:	GREGG SOME/ENG
Telephone:	5629621699
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	2111 VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 923250000
Gen County:	San Bernardino
TSD EPA ID:	CAT080013352
TSD County:	Los Angeles
Waste Category:	Waste oil and mixed oil
Disposal Method:	Recycler
Tons:	0.68
Facility County:	Not reported

Gepaid:	CAC002247257
Contact:	TELECO CORPORATION
Telephone:	8009871064
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	2111 VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	San Bernardino
TSD EPA ID:	CAT080022148
TSD County:	San Bernardino
Waste Category:	Waste oil and mixed oil
Disposal Method:	Transfer Station
Tons:	.4587
Facility County:	San Bernardino

Gepaid:	CAC002455311
Contact:	GREGG SOME/ENG
Telephone:	5629621699
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	2111 VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 923250000
Gen County:	San Bernardino
TSD EPA ID:	CAT080013352
TSD County:	Los Angeles
Waste Category:	Waste oil and mixed oil
Disposal Method:	Recycler
Tons:	2.91
Facility County:	San Bernardino

Gepaid:	CAC002455311
Contact:	GREGG SOME/ENG
Telephone:	5629621699
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	2111 VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 923250000

TALCO INC (Continued) **S105085433**

Gen County:	San Bernardino
TSD EPA ID:	Not reported
TSD County:	99
Waste Category:	Unspecified oil-containing waste
Disposal Method:	Recycler
Tons:	0.67
Facility County:	Not reported
Gepaid:	CAC002455311
Contact:	GREGG SOME/ENG
Telephone:	5629621699
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	2111 VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 923250000
Gen County:	San Bernardino
TSD EPA ID:	CAT080013352
TSD County:	San Bernardino
Waste Category:	Unspecified oil-containing waste
Disposal Method:	Recycler
Tons:	2.98
Facility County:	San Bernardino

Click this hyperlink while viewing on your computer to access
1 additional CA_HAZNET: record(s) in the EDR Site Report.

S78 **HUD** **HAZNET** **S103639363**
NW **1989 FIG TREE RD** **N/A**
1/2-1 **COLTON, CA 92324**
0.568 mi.
2998 ft. **Site 1 of 2 in cluster S**

Relative: HAZNET:
Higher

Gepaid:	CAC001299856
Contact:	HUD
Telephone:	0000000000
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	INTOWN PROPERTIES
Mailing City,St,Zip:	SAN BERNARDINO, CA 924080000
Gen County:	San Bernardino
TSD EPA ID:	CAD000088252
TSD County:	Los Angeles
Waste Category:	Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method:	Transfer Station
Tons:	.0291
Facility County:	San Bernardino

Actual:
1130 ft.

S79 **HUN/INTOWN PROP** **HAZNET** **S103639432**
NW **1994 FIG TREE RD** **N/A**
1/2-1 **COLTON, CA 92376**
0.569 mi.
3004 ft. **Site 2 of 2 in cluster S**

Relative: HAZNET:
Higher

Gepaid:	CAC001365032
Contact:	HUD/INTOWN PORP
Telephone:	9098243723
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	2086 S E ST STE 204
Mailing City,St,Zip:	SAN BERNARDINO, CA 924080000
Gen County:	San Bernardino
TSD EPA ID:	CAD028409019
TSD County:	Los Angeles
Waste Category:	Household waste
Disposal Method:	Transfer Station
Tons:	.0375
Facility County:	San Bernardino

Actual:
1130 ft.

Gepaid:	CAC001365032
Contact:	HUD/INTOWN PORP
Telephone:	9098243723
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	2086 S E ST STE 204
Mailing City,St,Zip:	SAN BERNARDINO, CA 924080000
Gen County:	San Bernardino
TSD EPA ID:	CAD028409019
TSD County:	Los Angeles
Waste Category:	Household waste
Disposal Method:	Treatment, Tank
Tons:	.0300
Facility County:	San Bernardino

T80 **TOMRA PACIFIC INC/FOOD 4 LESS #786** **SWRCY** **S107138042**
NNE **1150 N PEPPER AVE** **N/A**
1/2-1 **COLTON, CA 92324**
0.572 mi.
3020 ft. **Site 1 of 2 in cluster T**

Relative: SWRCY:
Higher

Certification Status:	O
Facility Phone Number:	Not reported
Date facility became certified:	04/29/04
Date facility began operating:	07/12/04
Date facility ceased operating:	Still operating
Whether The Facility Is Grandfathered:	Not reported
Convenience Zone Where Facilty Located:	5601
Convenience Zone Where Facilty Located 2:	0
Convenience Zone Where Facilty Located 3:	0
Convenience Zone Where Facilty Located 4:	0
Convenience Zone Where Facilty Located 5:	0
Convenience Zone Where Facilty Located 6:	0
Convenience Zone Where Facilty Located 7:	0
Aluminum Beverage Containers Redeemed:	AL
Glass Beverage Containers Redeemed:	GL
Plastic Beverage Containers Redeemed:	PL

Actual:
1122 ft.

TOMRA PACIFIC INC/FOOD 4 LESS #786 (Continued) **S107138042**

Other mat beverage containers redeemed: Not reported
Refillable Beverage Containers Redeemed: Not reported

---

81 **CDL** **S108723644**
North **1822 W ADMIRALTY ST** **N/A**
1/2-1 **COLTON, CA 92324**
0.578 mi.
3054 ft.

Relative:
Higher

Actual:
1134 ft.

CDL:
Facility ID: 200706020
Date: 2007-06-16 00:00:00
Lab Type: Illegal Drug Lab (L) - location where an illegal drug lab was operated or drug lab equipment and/or materials were stored.

T82 **FOOD 4 LESS GAS STATION** **San Bern. Co. Permit** **S106229966**
NNE **1170 N PEPPER AVE** **N/A**
1/2-1 **COLTON, CA 92324**
0.586 mi.
3095 ft. **Site 2 of 2 in cluster T**

Relative:
Higher

Actual:
1125 ft.

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0007698
Owner: RALPHS GROCERY CO
Permit Number: PT0014184
Permit Category: HAZMAT HANDLER - UST ONLY
Facility Status: ACTIVE
Expiration Date: 7/31/2008 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0007698
Owner: RALPHS GROCERY CO
Permit Number: PT0014183
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 7/31/2008 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0007698
Owner: RALPHS GROCERY CO
Permit Number: PT0014182
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 7/31/2008 12:00:00AM

83
NNE
1/2-1
0.587 mi.
3101 ft.

INTOWN PROPERTIES **HAZNET** **S103625359**
1201 CANTARA ST **N/A**
COLTON, CA 92324

Relative:
Higher

Actual:
1101 ft.

HAZNET:

Gepaid:	CAC000744872
Contact:	INTOWN PROPERTIES
Telephone:	0000000000
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	2086 SOUTH E ST STE 204
Mailing City,St,Zip:	SAN BERNARDINO, CA 924080000
Gen County:	San Bernardino
TSD EPA ID:	CAD028409019
TSD County:	Los Angeles
Waste Category:	Household waste
Disposal Method:	Treatment, Tank
Tons:	.4000
Facility County:	San Bernardino

Gepaid:	CAC000744872
Contact:	INTOWN PROPERTIES
Telephone:	0000000000
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	2086 SOUTH E ST STE 204
Mailing City,St,Zip:	SAN BERNARDINO, CA 924080000
Gen County:	San Bernardino
TSD EPA ID:	CAD028409019
TSD County:	Los Angeles
Waste Category:	Household waste
Disposal Method:	Transfer Station
Tons:	.0550
Facility County:	San Bernardino

84
NNW
1/2-1
0.639 mi.
3375 ft.

HUD **HAZNET** **S103968461**
1918 QUARTERMASTER **N/A**
COLTON, CA 92324

Relative:
Higher

Actual:
1135 ft.

HAZNET:

Gepaid:	CAC001299872
Contact:	HUD
Telephone:	0000000000
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	INTOWN PROPERTIES
Mailing City,St,Zip:	SAN BERNARDINO, CA 924080000
Gen County:	San Bernardino
TSD EPA ID:	CAD000088252
TSD County:	Los Angeles
Waste Category:	Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method:	Transfer Station
Tons:	.0125
Facility County:	San Bernardino

85
NW
1/2-1
0.642 mi.
3389 ft.

INTOWN PROPERTIES, INC/HUD
1988 CLUSTER PINE RD
COLTON, CA 92324

HAZNET **S103970904**
N/A

Relative:
Higher

Actual:
1140 ft.

HAZNET:

Gepaid:	CAC001082016
Contact:	HUD
Telephone:	0000000000
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	2086 S "E" ST, STE 204
Mailing City,St,Zip:	SAN BERNARDINO, CA 924080000
Gen County:	San Bernardino
TSD EPA ID:	CAD982444481
TSD County:	San Bernardino
Waste Category:	Household waste
Disposal Method:	Transfer Station
Tons:	.0291
Facility County:	San Bernardino

U86
ESE
1/2-1
0.650 mi.
3430 ft.

SLOVER MT HIGH SCHOOL
325 HERMOSA
COLTON, CA 92324

Site 1 of 2 in cluster U

HAZNET **S102038879**
N/A

Relative:
Lower

Actual:
1045 ft.

HAZNET:

Gepaid:	CAL000016219
Contact:	COLTON JOINT UNIFIED
Telephone:	0000000000
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1212 VALENCIA DRIVE
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	San Bernardino
TSD EPA ID:	CAD067786749
TSD County:	Los Angeles
Waste Category:	Asbestos-containing waste
Disposal Method:	Disposal, Land Fill
Tons:	21.0700
Facility County:	San Bernardino

Gepaid:	CAL000016219
Contact:	COLTON JOINT UNIFIED
Telephone:	0000000000
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1212 VALENCIA DRIVE
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	San Bernardino
TSD EPA ID:	CAD067786749
TSD County:	Los Angeles
Waste Category:	Asbestos-containing waste
Disposal Method:	Not reported
Tons:	8.4280
Facility County:	San Bernardino

U87 **SLOVER MOUNTAIN HIGH (CONT.)** **FINDS** **1008292459**
ESE **325 HERMOSA AVE.** **110021916079**
1/2-1 **COLTON, CA 92324**
0.650 mi.
3430 ft. **Site 2 of 2 in cluster U**

Relative:
Lower

Actual:
1045 ft.

FINDS:
Other Pertinent Environmental Activity Identified at Site

NCES (National Center for Education Statistics) is the primary federal entity for collecting and analyzing data related to education in the United States and other nations and the institute of education sciences.

V88 **INLAND EMPIRE EQUIP INC** **AIRS** **S106833040**
WSW **1762 S. SYCAMORE** **N/A**
1/2-1 **RIALTO, CA 92376**
0.652 mi.
3445 ft. **Site 1 of 3 in cluster V**

Relative:
Lower

Actual:
1064 ft.

EMI:

Year:	1987
Carbon Monoxide Emissions Tons/Yr:	36
Air Basin:	SC
Facility ID:	20131
Air District Name:	SC
SIC Code:	5311
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2
Reactive Organic Gases Tons/Yr:	2
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1990
Carbon Monoxide Emissions Tons/Yr:	36
Air Basin:	SC
Facility ID:	20131
Air District Name:	SC
SIC Code:	5084
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2
Reactive Organic Gases Tons/Yr:	2
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

V89 **CLARKLIFT OF CALIFORNIA INC** **FINDS** **1007738539**
WSW **1762 S SYCAMORE** **110018985598**
1/2-1 **RIALTO, CA 92376**
0.652 mi.
3445 ft. **Site 2 of 3 in cluster V**

Relative:
Lower

Actual:
1064 ft.

FINDS:
Other Pertinent Environmental Activity Identified at Site

California - Hazardous Waste Tracking System - Datamart

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

V90 **INLAND EMPIRE EQUIPT, INC** **RCRA-SQG** **1000151901**
WSW **1762 S SYCAMORE** **HAZNET** **CAD981375249**
1/2-1 **RIALTO, CA 92376** **CA FID UST**
0.652 mi. **HIST UST**
3445 ft. **Site 3 of 3 in cluster V** **San Bern. Co. Permit**
SWEEPS UST

Relative:
Lower

Actual:
1064 ft.

RCRA-SQG:

Date form received by agency:	01/29/1986
Facility name:	INLAND EMPIRE EQUIPT, INC
Facility address:	1762 S SYCAMORE RIALTO, CA 92376
EPA ID:	CAD981375249
Mailing address:	P O BOX 640 RIALTO, CA 92376
Contact:	ENVIRONMENTAL MANAGER
Contact address:	1762 S SYCAMORE RIALTO, CA 92376
Contact country:	US
Contact telephone:	(714) 877-0657
Contact email:	Not reported
EPA Region:	09
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	INLAND EMPIRE EQUIPT
Owner/operator address:	NOT REQUIRED NOT REQUIRED, ME 99999
Owner/operator country:	Not reported
Owner/operator telephone:	(415) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

INLAND EMPIRE EQUIPT, INC (Continued) **1000151901**

Owner/operator name: NOT REQUIRED
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: Unknown
Mixed waste (haz. and radioactive): Unknown
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: Unknown
Furnace exemption: Unknown
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No
Off-site waste receiver: Commercial status unknown

Violation Status: No violations found

HAZNET:
Gepaid: CAD981375249
Contact: DIANNE LOOMIS
Telephone: 9098770657
Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: PO BOX 640
Mailing City,St,Zip: RIALTO, CA 923770640
Gen County: San Bernardino
TSD EPA ID: CAT080013352
TSD County: Los Angeles
Waste Category: Aqueous solution with 10% or more total organic residues
Disposal Method: Recycler
Tons: .6254
Facility County: San Bernardino

Gepaid: CAD981375249
Contact: DIANNE LOOMIS
Telephone: 9098770657
Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: PO BOX 640
Mailing City,St,Zip: RIALTO, CA 923770640
Gen County: San Bernardino
TSD EPA ID: CAT080013352
TSD County: Los Angeles
Waste Category: Aqueous solution with less than 10% total organic residues

INLAND EMPIRE EQUIPT, INC (Continued) **1000151901**

Disposal Method: Transfer Station
Tons: .2293
Facility County: San Bernardino

Gepaid: CAD981375249
Contact: DIANNE LOOMIS
Telephone: 9098770657
Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: PO BOX 640
Mailing City,St,Zip: RIALTO, CA 923770640
Gen County: San Bernardino
TSD EPA ID: CAT080025711
TSD County: San Bernardino
Waste Category: Aqueous solution with less than 10% total organic residues
Disposal Method: Recycler
Tons: .2293
Facility County: San Bernardino

Gepaid: CAD981375249
Contact: DIANNE LOOMIS
Telephone: 9098770657
Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: PO BOX 640
Mailing City,St,Zip: RIALTO, CA 923770640
Gen County: San Bernardino
TSD EPA ID: CAT080013352
TSD County: Los Angeles
Waste Category: Waste oil and mixed oil
Disposal Method: Recycler
Tons: .9382
Facility County: San Bernardino

Gepaid: CAD981375249
Contact: DIANNE LOOMIS
Telephone: 9098770657
Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: PO BOX 640
Mailing City,St,Zip: RIALTO, CA 923770640
Gen County: San Bernardino
TSD EPA ID: CAT080025711
TSD County: San Bernardino
Waste Category: Aqueous solution with less than 10% total organic residues
Disposal Method: Recycler
Tons: .5004
Facility County: San Bernardino

Click this hyperlink while viewing on your computer to access
5 additional CA_HAZNET: record(s) in the EDR Site Report.

CA FID UST:
Facility ID: 36002637
Regulated By: UTNKA
Regulated ID: 00039009
Cortese Code: Not reported

INLAND EMPIRE EQUIPT, INC (Continued) **1000151901**

SIC Code: Not reported
Facility Phone: Not reported
Mail To: Not reported
Mailing Address: P O BOX
Mailing Address 2: Not reported
Mailing City,St,Zip: RIALTO 92376
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Active

HIST UST:
Region: STATE
Facility ID: 00000039009
Facility Type: Other
Other Type: SALES, SERVICE
Total Tanks: 0003
Contact Name: TROY MARSHALL
Telephone: 7148770657
Owner Name: INLAND EMPIRE EQUIPMENT, INC.
Owner Address: 1762 S. SYCAMORE AVE.
Owner City,St,Zip: RIALTO, CA 92376

Tank Num: 001
Container Num: G-1
Year Installed: Not reported
Tank Capacity: 00005000
Tank Used for: PRODUCT
Type of Fuel: REGULAR
Tank Construction: Not reported
Leak Detection: Stock Inventor

Tank Num: 002
Container Num: G-2
Year Installed: Not reported
Tank Capacity: 00001000
Tank Used for: Not reported
Type of Fuel: Not reported
Tank Construction: Not reported
Leak Detection: Stock Inventor

Tank Num: 003
Container Num: S-1
Year Installed: Not reported
Tank Capacity: 00000900
Tank Used for: WASTE
Type of Fuel: Not reported
Tank Construction: 4 inches
Leak Detection: None

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0003957

INLAND EMPIRE EQUIPT, INC (Continued) **1000151901**

Owner: CLARKLIFT OF CALIFORNIA, INC.
Permit Number: PT0001968
Permit Category: HAZMAT HANDLER 11-25 EMPLOYEES
Facility Status: ACTIVE
Expiration Date: 5/31/2008 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0003957
Owner: CLARKLIFT OF CALIFORNIA, INC.
Permit Number: PT0001969
Permit Category: SPECIAL GENERATOR(B)
Facility Status: ACTIVE
Expiration Date: 5/31/2008 12:00:00AM

SWEEPS UST:
Status: Not reported
Comp Number: 39009
Number: Not reported
Board Of Equalization: 44-020962
Ref Date: Not reported
Act Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 36-000-039009-000001
Actv Date: Not reported
Capacity: 5000
Tank Use: M.V. FUEL
Stg: PRODUCT
Content: REG UNLEADED
Number Of Tanks: 1

---

91 **CLUTCH MASTERS** **San Bern. Co. Permit** **S102041351**
WSW **267 E VALLEY BLVD** **N/A**
1/2-1 **RIALTO, CA 92376**
0.654 mi.
3453 ft.

Relative:
Lower

Actual:
1067 ft.

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0002237
Owner: CLUTCH MASTERS
Permit Number: PT0003833
Permit Category: SPECIAL GENERATOR(B)
Facility Status: ACTIVE
Expiration Date: 8/31/2008 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0002237
Owner: CLUTCH MASTERS
Permit Number: PT0003834
Permit Category: SPECIAL HANDLER
Facility Status: ACTIVE
Expiration Date: 8/31/2008 12:00:00AM

W92 **AT&T MOBILITY COLTON #13829** **San Bern. Co. Permit** **S106718013**
ESE **1205 1/2 W VALLEY BLVD** **N/A**
1/2-1 **COLTON, CA 92324**
0.660 mi.
3485 ft. **Site 1 of 2 in cluster W**

Relative: San Bern. Co. Permit:
Lower Region: SAN BERNARDINO
Facility ID: FA0009029
Actual: Owner: AT & T MOBILITY
1036 ft. Permit Number: PT0015897
Permit Category: HAZMAT HANDLER - UNSTAFFED REMOTE FACILITY
Facility Status: ACTIVE
Expiration Date: 8/31/2008 12:00:00AM

W93 **PARKHOUSE TIRE** **HAZNET** **S102038852**
ESE **1205 W. VALLEY BLVD.** **N/A**
1/2-1 **COLTON, CA 92324**
0.660 mi.
3485 ft. **Site 2 of 2 in cluster W**

Relative: HAZNET:
Lower Gepaid: CAL000159476
Contact: JIM PARKHOUSE
Actual: Telephone: 0000000000
1036 ft. Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: 1205 W VALLEY BLVD
Mailing City,St,Zip: COLTON, CA 923241908
Gen County: San Bernardino
TSD EPA ID: CAT080013352
TSD County: Los Angeles
Waste Category: Oil/water separation sludge
Disposal Method: Recycler
Tons: .4587
Facility County: San Bernardino

Gepaid: CAL000159476
Contact: JIM PARKHOUSE
Telephone: 0000000000
Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: 1205 W VALLEY BLVD
Mailing City,St,Zip: COLTON, CA 923241908
Gen County: San Bernardino
TSD EPA ID: CAT080013352
TSD County: Los Angeles
Waste Category: Aqueous solution with 10% or more total organic residues
Disposal Method: Recycler
Tons: .2293
Facility County: San Bernardino

Gepaid: CAL000159476
Contact: JIM PARKHOUSE
Telephone: 0000000000
Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: 1205 W VALLEY BLVD
Mailing City,St,Zip: COLTON, CA 923241908
Gen County: San Bernardino

PARKHOUSE TIRE (Continued) **S102038852**

TSD EPA ID:	CAT080025711
TSD County:	San Bernardino
Waste Category:	Aqueous solution with less than 10% total organic residues
Disposal Method:	Transfer Station
Tons:	0.2293
Facility County:	San Bernardino

---

94 **INTOWN PROPERTIES INC** **HAZNET** **S103970171**
North **1761 W WIND ST** **N/A**
1/2-1 **COLTON, CA 92324**
0.679 mi.
3587 ft.

Relative: **Higher**

Actual: **1143 ft.**

HAZNET:

Gepaid:	CAC001352528
Contact:	INTOWN PROPERTIES INC
Telephone:	9098243723
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	2086 SOUTH E ST STE 204
Mailing City,St,Zip:	SAN BERNARDINO, CA 924080000
Gen County:	San Bernardino
TSD EPA ID:	CAD000088252
TSD County:	Los Angeles
Waste Category:	Household waste
Disposal Method:	Transfer Station
Tons:	.1275
Facility County:	San Bernardino

X95 **HUD** **HAZNET** **S103629238**
NNW **1365 CHRISTOBAL LN** **N/A**
1/2-1 **COLTON, CA 92324**
0.689 mi.
3636 ft. **Site 1 of 2 in cluster X**

Relative: **Higher**

Actual: **1143 ft.**

HAZNET:

Gepaid:	CAC001299864
Contact:	HUD
Telephone:	0000000000
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	INTOWN PROPERTIES
Mailing City,St,Zip:	SAN BERNARDINO, CA 924080000
Gen County:	San Bernardino
TSD EPA ID:	CAD000088252
TSD County:	Los Angeles
Waste Category:	Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method:	Transfer Station
Tons:	.0834
Facility County:	San Bernardino

X96 **HUD INTOWN PROPERTIES** **HAZNET** **S103968736**
NNW **1365 CHRISTOBAL LN N** **N/A**
1/2-1 **COLTON, CA 92324**
0.689 mi.
3636 ft. **Site 2 of 2 in cluster X**

Relative: **Higher**

Actual: **1143 ft.**

HAZNET:

Gepaid:	CAC002123312
Contact:	HUD
Telephone:	0000000000
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	2086 S E ST STE 204
Mailing City,St,Zip:	SAN BERNARDINO, CA 924080000
Gen County:	San Bernardino
TSD EPA ID:	CAD028409019
TSD County:	Los Angeles
Waste Category:	Household waste
Disposal Method:	Treatment, Tank
Tons:	.1042
Facility County:	San Bernardino

Gepaid:	CAC002123312
Contact:	HUD
Telephone:	0000000000
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	2086 S E ST STE 204
Mailing City,St,Zip:	SAN BERNARDINO, CA 924080000
Gen County:	San Bernardino
TSD EPA ID:	CAD982444481
TSD County:	San Bernardino
Waste Category:	Household waste
Disposal Method:	Transfer Station
Tons:	.0208
Facility County:	San Bernardino

Y97 **CAL NEV PIPELINE COLTON** **San Bern. Co. Permit** **S102038736**
South **2051 W SLOVER AVE** **N/A**
1/2-1 **COLTON, CA 92326**
0.689 mi.
3639 ft. **Site 1 of 6 in cluster Y**

Relative: **Lower**

Actual: **1062 ft.**

San Bern. Co. Permit:

Region:	SAN BERNARDINO
Facility ID:	FA0001679
Owner:	CAL NEV PIPELINE COMPANY
Permit Number:	PT0002632
Permit Category:	ABOVEGROUND PETROLEUM STORAGE (AST) (SPCC)
Facility Status:	ACTIVE
Expiration Date:	7/31/2008 12:00:00AM

Region:	SAN BERNARDINO
Facility ID:	FA0001679
Owner:	CAL NEV PIPELINE COMPANY
Permit Number:	PT0002631
Permit Category:	EPCRA FACILITY (RIGHT TO KNOW PLAN)
Facility Status:	ACTIVE
Expiration Date:	7/31/2008 12:00:00AM

CAL NEV PIPELINE COLTON (Continued) **S102038736**

Region: SAN BERNARDINO
Facility ID: FA0001679
Owner: CAL NEV PIPELINE COMPANY
Permit Number: PT0002634
Permit Category: HAZMAT HANDLER 0-10 EMPLOYEES (W/GEN PRMT)
Facility Status: ACTIVE
Expiration Date: 7/31/2008 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0001679
Owner: CAL NEV PIPELINE COMPANY
Permit Number: PT0002635
Permit Category: GENERATOR - 0-10 EMPLOYEES
Facility Status: ACTIVE
Expiration Date: 7/31/2008 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0001679
Owner: CAL NEV PIPELINE COMPANY
Permit Number: PT0002633
Permit Category: CE ANNUAL FEE
Facility Status: INACTIVE
Expiration Date: 7/31/2007 12:00:00AM

Y98 **CHMIRS** **S100275088**
South **2051 W. SLOVER AVE** **N/A**
1/2-1 **SOLTON, CA 92324**
0.695 mi.
3671 ft. **Site 2 of 6 in cluster Y**

Relative: CHMIRS:
Lower

Actual:
1060 ft.

OES Incident Number: 8907724
OES notification: Not reported
OES Date: Not reported
OES Time: Not reported
Incident Date: 31-AUG-89
Date Completed: 31-AUG-89
Property Use: 800
Agency Id Number: 36709
Agency Incident Number: 892200262
Time Notified: Not reported
Time Completed: Not reported
Surrounding Area: 600
Estimated Temperature: 80
Property Management: P
Special Studies 1: Not reported
Special Studies 2: Not reported
Special Studies 3: Not reported
Special Studies 4: Not reported
Special Studies 5: Not reported
Special Studies 6: Not reported
More Than Two Substances Involved?: N
Resp Agncy Personel # Of Decontaminated: 0
Responding Agency Personel # Of Injuries: 0
Responding Agency Personel # Of Fatalities: 0
Others Number Of Decontaminated: 0
Others Number Of Injuries: 0
Others Number Of Fatalities: 0

(Continued) **S100275088**

Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	CATHERINE B. RICHARDS ENV. HEALTH SPECIALIST
Report Date:	27-OCT-89
Comments:	Not reported
Facility Telephone:	714 387-3044
Waterway Involved:	Not reported
Waterway:	Not reported
Spill Site:	Not reported
Cleanup By:	Not reported
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	88-92
Agency:	Not reported
Incident Date:	Not reported
Admin Agency:	Not reported
Amount:	Not reported
Contained:	Not reported
Site Type:	Not reported
E Date:	18-MAY-90
Substance:	Not reported
Quantity Released:	Not reported
BBLS:	Not reported
Cups:	Not reported
CUFT:	Not reported
Gallons:	Not reported
Grams:	Not reported
Pounds:	Not reported
Liters:	Not reported
Ounces:	Not reported
Pints:	Not reported
Quarts:	Not reported
Sheen:	Not reported
Tons:	Not reported
Unknown:	Not reported
Description:	Not reported
Evacuations:	Not reported
Number of Injuries:	Not reported
Number of Fatalities:	Not reported
Description:	Not reported

Map ID / Direction / Distance / Elevation	Site	Database(s)	EDR ID Number / EPA ID Number
Y99	**2051 SLOVER AVE**	**ERNS**	**92280739**
South	**2051 SLOVER AVE**		**N/A**
1/2-1	**COLTON, CA 92324**		
0.695 mi.			
3671 ft.	**Site 3 of 6 in cluster Y**		
Relative:			
Lower	Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.		
Actual:			
1060 ft.			
Y100	**2051 W. SLOVER AVENUE**	**ERNS**	**90179352**
South	**2051 W. SLOVER AVENUE**		**N/A**
1/2-1	**COLTON, CA 92324**		
0.695 mi.			
3671 ft.	**Site 4 of 6 in cluster Y**		
Relative:			
Lower	Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.		
Actual:			
1060 ft.			
Y101	**2051 SLOVER AVE**	**ERNS**	**92280900**
South	**2051 SLOVER AVE**		**N/A**
1/2-1	**COLTEN, CA 92412**		
0.696 mi.			
3673 ft.	**Site 5 of 6 in cluster Y**		
Relative:			
Lower	Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.		
Actual:			
1060 ft.			
Y102		**CHMIRS**	**S105641951**
South	**CAL NEV COLTON TERMINAL 2051 EAST SLOVER AVE**		**N/A**
1/2-1	**BLOOMINGTON, CA 92316**		
0.696 mi.			
3673 ft.	**Site 6 of 6 in cluster Y**		

Relative: **Lower**

Actual: **1060 ft.**

CHMIRS:

OES Incident Number:	006728
OES notification:	Not reported
OES Date:	2/10/1995
OES Time:	10:35:17 AM
Incident Date:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported

(Continued) **S105641951**

Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	YES
Waterway:	Not reported
Spill Site:	Not reported
Cleanup By:	on scene personnel/priv cont
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	1995
Agency:	cal nev p/l
Incident Date:	2/9/95 0900
Admin Agency:	Not reported
Amount:	2800 gal
Contained:	NO
Site Type:	Not reported
E Date:	Not reported
Substance:	diesel fuel
Quantity Released:	Not reported
BBLS:	Not reported
Cups:	Not reported
CUFT:	Not reported
Gallons:	Not reported
Grams:	Not reported
Pounds:	Not reported
Liters:	Not reported
Ounces:	Not reported
Pints:	Not reported
Quarts:	Not reported
Sheen:	Not reported
Tons:	Not reported
Unknown:	Not reported
Description:	tank 133 being put back into service found to be faulty during filling
Evacuations:	NO
Number of Injuries:	NO
Number of Fatalities:	NO
Description:	Not reported

Z103 **CHMIRS** **S106398795**
South **PEPPER / SLOVER AVE.** **N/A**
1/2-1 **COLTON, CA**
0.705 mi.
3723 ft. **Site 1 of 6 in cluster Z**

Relative: CHMIRS:
Lower

OES Incident Number:	03-3799
OES notification:	7/29/200301:28:47 PM
Actual: OES Date:	Not reported
1044 ft. OES Time:	Not reported
Incident Date:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	No
Waterway:	Not reported
Spill Site:	Not reported
Cleanup By:	Contractor
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	2003
Agency:	UPRR
Incident Date:	7/29/200312:00:00 AM
Admin Agency:	San Bernardino County Health Department
Amount:	Not reported

(Continued) **S106398795**

Contained:	Yes
Site Type:	Rail Road
E Date:	Not reported
Substance:	Paint
Quantity Released:	Not reported
BBLS:	0
Cups:	0
CUFT:	0
Gallons:	30
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	Workers discovered 6 -5 gallon containers abandoned at the rail yard..

Z104 **GATX** **AIRS S106831541**
South **PEPPER AV/SLOVER ST.** **N/A**
1/2-1 **COLTON, CA 92324**
0.705 mi.
3723 ft. **Site 2 of 6 in cluster Z**

Relative: **Lower**

Actual: **1044 ft.**

EMI:

Year:	1987
Carbon Monoxide Emissions Tons/Yr:	36
Air Basin:	SC
Facility ID:	12332
Air District Name:	SC
SIC Code:	3714
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	9
Reactive Organic Gases Tons/Yr:	9
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1990
Carbon Monoxide Emissions Tons/Yr:	36
Air Basin:	SC
Facility ID:	12332
Air District Name:	SC
SIC Code:	3714
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	7

GATX (Continued) **S106831541**

Reactive Organic Gases Tons/Yr:	6
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	1
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Z105 **GENERAL AMERICAN TRANSPORTATION CORP** **HAZNET S103679577**
South **PEPPER / SLOVER ST** **CHMIRS N/A**
1/2-1 **COLTON, CA 92324**
0.705 mi.
3723 ft. **Site 3 of 6 in cluster Z**

Relative: **Lower**

Actual: **1044 ft.**

HAZNET:

Gepaid:	CAD055698815
Contact:	GENERAL AMERICAN TRANS CORP
Telephone:	3126218456
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	20878 SLOVER AVE
Mailing City,St,Zip:	COLTON, CA 923240590
Gen County:	San Bernardino
TSD EPA ID:	AZD983481813
TSD County:	99
Waste Category:	Other organic solids
Disposal Method:	Not reported
Tons:	1.0000
Facility County:	San Bernardino

Gepaid:	CAD055698815
Contact:	GENERAL AMERICAN TRANS CORP
Telephone:	3126218456
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	20878 SLOVER AVE
Mailing City,St,Zip:	COLTON, CA 923240590
Gen County:	San Bernardino
TSD EPA ID:	AZD983481813
TSD County:	99
Waste Category:	Other organic solids
Disposal Method:	Disposal, Land Fill
Tons:	20.0000
Facility County:	San Bernardino

Gepaid:	CAD055698815
Contact:	GENERAL AMERICAN TRANS CORP
Telephone:	3126218456
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	20878 SLOVER AVE
Mailing City,St,Zip:	COLTON, CA 923240590
Gen County:	San Bernardino
TSD EPA ID:	AZC950823111
TSD County:	99
Waste Category:	Other inorganic solid waste
Disposal Method:	Not reported
Tons:	27.0000
Facility County:	San Bernardino

GENERAL AMERICAN TRANSPORTATION CORP (Continued) **S103679577**

Gepaid:	CAD055698815
Contact:	GENERAL AMERICAN TRANS CORP
Telephone:	3126218456
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	20878 SLOVER AVE
Mailing City,St,Zip:	COLTON, CA 923240590
Gen County:	San Bernardino
TSD EPA ID:	AZC950823111
TSD County:	99
Waste Category:	Not reported
Disposal Method:	Not reported
Tons:	3.0000
Facility County:	San Bernardino

Gepaid:	CAD055698815
Contact:	GENERAL AMERICAN TRANS CORP
Telephone:	3126218456
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	20878 SLOVER AVE
Mailing City,St,Zip:	COLTON, CA 923240590
Gen County:	San Bernardino
TSD EPA ID:	CAD008302903
TSD County:	Los Angeles
Waste Category:	Unspecified solvent mixture Waste
Disposal Method:	Recycler
Tons:	8.9655
Facility County:	San Bernardino

Click this hyperlink while viewing on your computer to access
115 additional CA_HAZNET: record(s) in the EDR Site Report.

CHMIRS:

OES Incident Number:	2731
OES notification:	Not reported
OES Date:	6/15/1994
OES Time:	08:25:34 PM
Incident Date:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported

GENERAL AMERICAN TRANSPORTATION CORP (Continued) **S103679577**

Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	YES
Waterway:	Not reported
Spill Site:	Not reported
Cleanup By:	DISPOSAL CONTROL SERVICES
Containment:	Not reported
What Happened:	Not reported
Type:	CHEMICAL
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	1994
Agency:	COLTON FD
Incident Date:	1206 6/15/94
Admin Agency:	Not reported
Amount:	30 GAL
Contained:	NO
Site Type:	RD
E Date:	Not reported
Substance:	ACID
Quantity Released:	Not reported
BBLS:	Not reported
Cups:	Not reported
CUFT:	Not reported
Gallons:	Not reported
Grams:	Not reported
Pounds:	Not reported
Liters:	Not reported
Ounces:	Not reported
Pints:	Not reported
Quarts:	Not reported
Sheen:	Not reported
Tons:	Not reported
Unknown:	Not reported
Description:	ILLEGAL DUMP
Evacuations:	NO
Number of Injuries:	NO
Number of Fatalities:	NO
Description:	Not reported

GATX RAIL (Continued) **S107144613**

Disposal Method:	Transfer Station
Tons:	0.5
Facility County:	San Bernardino
Gepaid:	CAD055698815
Contact:	TERRY RALSTON
Telephone:	9097775123
Facility Addr2:	Not reported
Mailing Name:	PEPPER & SLOVER STS
Mailing Address:	20878 SLOVER AVE
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	San Bernardino
TSD EPA ID:	CAD028409019
TSD County:	San Bernardino
Waste Category:	Off-specification, aged, or surplus organics
Disposal Method:	Treatment, Tank
Tons:	0.31
Facility County:	San Bernardino
Gepaid:	CAD055698815
Contact:	TERRY RALSTON
Telephone:	9097775123
Facility Addr2:	Not reported
Mailing Name:	PEPPER & SLOVER STS
Mailing Address:	20878 SLOVER AVE
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	San Bernardino
TSD EPA ID:	AZD983481813
TSD County:	San Bernardino
Waste Category:	Other organic solids
Disposal Method:	Not reported
Tons:	33.71
Facility County:	San Bernardino

Click this hyperlink while viewing on your computer to access
16 additional CA_HAZNET: record(s) in the EDR Site Report.

Z108 **GATX RAIL** **FINDS** **1000213813**
South **20878 SLOVER STREET** **RCRA-LQG** **CAD055698815**
1/2-1 **COLTON, CA 92324** **RCRA-TSDF**
0.705 mi. **CORRACTS**
3723 ft. **Site 6 of 6 in cluster Z** **CERC-NFRAP**
HIST UST

Relative:
Lower

FINDS:
Other Pertinent Environmental Activity Identified at Site

Actual:
1044 ft.

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

GATX RAIL (Continued) **1000213813**

California - Hazardous Waste Tracking System - Datamart

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and its Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

RCRA-LQG:

Date form received by agency:	02/10/2006
Facility name:	GATX RAIL
Facility address:	20878 SLOVER STREET COLTON, CA 92324
EPA ID:	CAD055698815
Mailing address:	20878 SLOVER ST. COLTON, CA 92324
Contact:	TERRY D RALSTON
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(909) 777-5123
Contact email:	TERRY.RALSTON@GATX.COM
EPA Region:	09
Land type:	Private
Classification:	TSDF
Description:	Handler is engaged in the treatment, storage or disposal of hazardous waste
TSD commencement date:	Not reported
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1

GATX RAIL (Continued) **1000213813**

kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	GATX CORPORATION
Owner/operator address:	500 WEST MONROE STREET
	CHICAGO, IL 60661
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	01/01/1948
Owner/Op end date:	Not reported
Owner/operator name:	GATX CORPORATION
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	01/01/1948
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No
Off-site waste receiver:	Commercial status unknown

Universal Waste Summary:

Waste type:	Batteries
Accumulated waste on-site:	No
Generated waste on-site:	No
Waste type:	Lamps
Accumulated waste on-site:	No
Generated waste on-site:	No
Waste type:	Pesticides
Accumulated waste on-site:	No

GATX RAIL (Continued) **1000213813**

Generated waste on-site: No

Waste type: Thermostats
Accumulated waste on-site: No
Generated waste on-site: No

Historical Generators:
Date form received by agency: 01/30/2004
Facility name: GATX RAIL
Classification: Large Quantity Generator

Date form received by agency: 02/01/2002
Facility name: GATX RAIL
Classification: Large Quantity Generator

Date form received by agency: 10/12/2000
Facility name: GATX RAIL
Classification: Large Quantity Generator

Date form received by agency: 04/05/2000
Facility name: GATX RAIL
Classification: Large Quantity Generator

Date form received by agency: 04/15/1999
Facility name: GATX RAIL
Site name: GENERAL AMERICAN TRANSPORT CO.
Classification: Large Quantity Generator

Date form received by agency: 09/01/1996
Facility name: GATX RAIL
Classification: Large Quantity Generator

Date form received by agency: 02/26/1996
Facility name: GATX RAIL
Site name: GENERAL AMERICAN TRANSPORTATION
Classification: Large Quantity Generator

Date form received by agency: 03/31/1994
Facility name: GATX RAIL
Site name: GENERAL AMERICAN TRANSPORTATION
Classification: Large Quantity Generator

Date form received by agency: 02/27/1992
Facility name: GATX RAIL
Site name: GENERAL AMERICAN TRANSPORTATIO
Classification: Large Quantity Generator

Date form received by agency: 04/12/1990
Facility name: GATX RAIL
Site name: GENERAL AMERICAN TRANSPORTATION CORP.
Classification: Large Quantity Generator

Date form received by agency: 08/18/1980
Facility name: GATX RAIL
Classification: Large Quantity Generator

Date form received by agency: 08/18/1980

GATX RAIL (Continued) **1000213813**

Facility name: GATX RAIL
Classification: Large Quantity Generator

Hazardous Waste Summary:
Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002
Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Waste code: D018
Waste name: BENZENE

Waste code: D035
Waste name: METHYL ETHYL KETONE

Biennial Reports:

Last Biennial Reporting Year: 2005

Annual Waste Handled:
Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.
Amount (Lbs): 89400

Waste code: D002
Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.
Amount (Lbs): 61580

Waste code: D018
Waste name: BENZENE
Amount (Lbs): 64080

GATX RAIL (Continued) **1000213813**

Waste code: D035
Waste name: METHYL ETHYL KETONE
Amount (Lbs): 27820

Corrective Action Summary:
Event date: 06/21/1989
Event: CA074LO

Event date: 06/21/1989
Event: RFA Completed, Assessment was a PA-Plus.

Event date: 06/21/1989
Event: CA Prioritization, Facility or area was assigned a low corrective action priority.

Event date: 06/21/1989
Event: CA029ST

Event date: 06/21/1989
Event: CA049PA

Event date: 12/15/1991
Event: RFI Imposition

Event date: 09/24/1992
Event: RFI Workplan Approved

Event date: Not reported
Event: CA048ST

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 03/29/2005
Date achieved compliance: 05/16/2005
Violation lead agency: State
Enforcement action: LETTER OF INTENT TO INITIATE ENFORCEMENT ACTION
Enforcement action date: 06/23/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 03/29/2005
Date achieved compliance: 05/16/2005
Violation lead agency: State
Enforcement action: INITIAL 3008(A) COMPLIANCE
Enforcement action date: 10/28/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State

GATX RAIL (Continued) **1000213813**

Proposed penalty amount:	14100
Final penalty amount:	Not reported
Paid penalty amount:	Not reported
Regulation violated:	Not reported
Area of violation:	Generators - General
Date violation determined:	03/29/2005
Date achieved compliance:	05/16/2005
Violation lead agency:	State
Enforcement action:	WRITTEN INFORMAL
Enforcement action date:	03/29/2005
Enf. disposition status:	Not reported
Enf. disp. status date:	Not reported
Enforcement lead agency:	State
Proposed penalty amount:	Not reported
Final penalty amount:	Not reported
Paid penalty amount:	Not reported
Regulation violated:	Not reported
Area of violation:	Generators - General
Date violation determined:	03/29/2005
Date achieved compliance:	05/16/2005
Violation lead agency:	State
Enforcement action:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date:	02/17/2006
Enf. disposition status:	Not reported
Enf. disp. status date:	Not reported
Enforcement lead agency:	State
Proposed penalty amount:	Not reported
Final penalty amount:	10000
Paid penalty amount:	Not reported
Regulation violated:	Not reported
Area of violation:	Generators - Manifest
Date violation determined:	03/29/2005
Date achieved compliance:	03/30/2005
Violation lead agency:	State
Enforcement action:	WRITTEN INFORMAL
Enforcement action date:	03/29/2005
Enf. disposition status:	Not reported
Enf. disp. status date:	Not reported
Enforcement lead agency:	State
Proposed penalty amount:	Not reported
Final penalty amount:	Not reported
Paid penalty amount:	Not reported
Regulation violated:	Not reported
Area of violation:	TSD - Contingency Plan and Emergency Procedures
Date violation determined:	08/19/2003
Date achieved compliance:	09/18/2003
Violation lead agency:	State
Enforcement action:	WRITTEN INFORMAL
Enforcement action date:	08/19/2003
Enf. disposition status:	Not reported
Enf. disp. status date:	Not reported
Enforcement lead agency:	State
Proposed penalty amount:	Not reported

GATX RAIL (Continued) **1000213813**

Final penalty amount:	Not reported
Paid penalty amount:	Not reported
Regulation violated:	Not reported
Area of violation:	TSD - General Facility Standards
Date violation determined:	08/19/2003
Date achieved compliance:	09/18/2003
Violation lead agency:	State
Enforcement action:	WRITTEN INFORMAL
Enforcement action date:	08/19/2003
Enf. disposition status:	Not reported
Enf. disp. status date:	Not reported
Enforcement lead agency:	State
Proposed penalty amount:	Not reported
Final penalty amount:	Not reported
Paid penalty amount:	Not reported
Regulation violated:	Not reported
Area of violation:	TSD - Contingency Plan and Emergency Procedures
Date violation determined:	09/04/2002
Date achieved compliance:	01/15/2003
Violation lead agency:	State
Enforcement action:	WRITTEN INFORMAL
Enforcement action date:	09/04/2002
Enf. disposition status:	Not reported
Enf. disp. status date:	Not reported
Enforcement lead agency:	State
Proposed penalty amount:	Not reported
Final penalty amount:	Not reported
Paid penalty amount:	Not reported
Regulation violated:	Not reported
Area of violation:	TSD - General Facility Standards
Date violation determined:	09/04/2002
Date achieved compliance:	01/15/2003
Violation lead agency:	State
Enforcement action:	WRITTEN INFORMAL
Enforcement action date:	09/04/2002
Enf. disposition status:	Not reported
Enf. disp. status date:	Not reported
Enforcement lead agency:	State
Proposed penalty amount:	Not reported
Final penalty amount:	Not reported
Paid penalty amount:	Not reported
Regulation violated:	Not reported
Area of violation:	TSD - Container Use and Management
Date violation determined:	11/14/2000
Date achieved compliance:	12/19/2000
Violation lead agency:	State
Enforcement action:	WRITTEN INFORMAL
Enforcement action date:	11/15/2000
Enf. disposition status:	Not reported
Enf. disp. status date:	Not reported
Enforcement lead agency:	State
Proposed penalty amount:	Not reported
Final penalty amount:	Not reported

GATX RAIL (Continued) **1000213813**

Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 11/14/2000
Date achieved compliance: 12/19/2000
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 11/15/2000
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Contingency Plan and Emergency Procedures
Date violation determined: 11/14/2000
Date achieved compliance: 12/19/2000
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 11/15/2000
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Financial Requirements
Date violation determined: 11/14/2000
Date achieved compliance: 12/19/2000
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 11/15/2000
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Financial Requirements
Date violation determined: 10/31/2000
Date achieved compliance: 12/19/2000
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 11/15/2000
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

GATX RAIL (Continued) **1000213813**

Regulation violated:	Not reported
Area of violation:	TSD - Financial Requirements
Date violation determined:	10/31/2000
Date achieved compliance:	12/19/2000
Violation lead agency:	State
Enforcement action:	Not reported
Enforcement action date:	Not reported
Enf. disposition status:	Not reported
Enf. disp. status date:	Not reported
Enforcement lead agency:	Not reported
Proposed penalty amount:	Not reported
Final penalty amount:	Not reported
Paid penalty amount:	Not reported

Regulation violated:	F - 264.30-37.C
Area of violation:	TSD - General
Date violation determined:	04/09/1996
Date achieved compliance:	04/09/1996
Violation lead agency:	State
Enforcement action:	WRITTEN INFORMAL
Enforcement action date:	04/09/1996
Enf. disposition status:	Not reported
Enf. disp. status date:	Not reported
Enforcement lead agency:	State
Proposed penalty amount:	Not reported
Final penalty amount:	Not reported
Paid penalty amount:	Not reported

Regulation violated:	FR - 264.170-177.I
Area of violation:	TSD - General
Date violation determined:	04/09/1996
Date achieved compliance:	04/09/1996
Violation lead agency:	State
Enforcement action:	WRITTEN INFORMAL
Enforcement action date:	04/09/1996
Enf. disposition status:	Not reported
Enf. disp. status date:	Not reported
Enforcement lead agency:	State
Proposed penalty amount:	Not reported
Final penalty amount:	Not reported
Paid penalty amount:	Not reported

Regulation violated:	FR - 264.110-120.G
Area of violation:	TSD - Closure/Post-Closure
Date violation determined:	04/09/1996
Date achieved compliance:	04/09/1996
Violation lead agency:	State
Enforcement action:	WRITTEN INFORMAL
Enforcement action date:	04/09/1996
Enf. disposition status:	Not reported
Enf. disp. status date:	Not reported
Enforcement lead agency:	State
Proposed penalty amount:	Not reported
Final penalty amount:	Not reported
Paid penalty amount:	Not reported

Regulation violated:	F - 264.400-406.Q

GATX RAIL (Continued) **1000213813**

Area of violation: TSD IS-Chemical, Physical, AND Treatment
Date violation determined: 04/09/1996
Date achieved compliance: 04/09/1996
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/09/1996
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 264.190-201.J
Area of violation: TSD - General
Date violation determined: 04/09/1996
Date achieved compliance: 04/09/1996
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/09/1996
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 264.190-201.J
Area of violation: TSD - General
Date violation determined: 10/07/1994
Date achieved compliance: 05/05/1995
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 10/07/1994
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 264.10-18.B
Area of violation: TSD - General
Date violation determined: 10/07/1994
Date achieved compliance: 05/05/1995
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 05/01/1995
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: 1000
Paid penalty amount: 1000

Regulation violated: FR - 264.190-201.J
Area of violation: TSD - General

GATX RAIL (Continued) **1000213813**

Date violation determined: 10/07/1994
Date achieved compliance: 05/05/1995
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 05/01/1995
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: 1000
Paid penalty amount: 1000

Regulation violated: FR - 264.10-18.B
Area of violation: TSD - General
Date violation determined: 10/07/1994
Date achieved compliance: 05/05/1995
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 10/07/1994
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 270
Area of violation: TSD - General
Date violation determined: 10/07/1994
Date achieved compliance: 05/05/1995
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 10/07/1994
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 270
Area of violation: TSD - General
Date violation determined: 10/07/1994
Date achieved compliance: 05/05/1995
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 05/01/1995
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: 1000
Paid penalty amount: 1000

Regulation violated: F - 270
Area of violation: TSD - General
Date violation determined: 02/24/1992

GATX RAIL (Continued) **1000213813**

Date achieved compliance: 03/13/1992
Violation lead agency: State
Enforcement action: INITIAL 3008(A) COMPLIANCE
Enforcement action date: 02/24/1992
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 900
Final penalty amount: 900
Paid penalty amount: Not reported

Regulation violated: F - 264.140-150.H
Area of violation: TSD - Financial Requirements
Date violation determined: 11/21/1991
Date achieved compliance: 04/07/1994
Violation lead agency: EPA
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 270
Area of violation: TSD - General
Date violation determined: 06/15/1989
Date achieved compliance: 08/08/1989
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/12/1989
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: F - 270
Area of violation: TSD - General
Date violation determined: 11/23/1987
Date achieved compliance: 10/24/1989
Violation lead agency: State
Enforcement action: INITIAL 3008(A) COMPLIANCE
Enforcement action date: 01/30/1989
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: F - 270
Area of violation: TSD - General
Date violation determined: 11/23/1987
Date achieved compliance: 10/24/1989

GATX RAIL (Continued) **1000213813**

Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 12/30/1987
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 01/18/2007
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 05/11/2006
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 03/15/2006
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 05/16/2005
Evaluation: NOT A SIGNIFICANT NON-COMPLIER
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 03/29/2005
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 05/16/2005
Evaluation lead agency: State

Evaluation date: 03/29/2005
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Manifest
Date achieved compliance: 03/30/2005
Evaluation lead agency: State

Evaluation date: 03/29/2005
Evaluation: SIGNIFICANT NON-COMPLIER
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 03/23/2005
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported

GATX RAIL (Continued) **1000213813**

Evaluation lead agency: State

Evaluation date: 08/19/2003
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General Facility Standards
Date achieved compliance: 09/18/2003
Evaluation lead agency: State

Evaluation date: 08/19/2003
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - Contingency Plan and Emergency Procedures
Date achieved compliance: 09/18/2003
Evaluation lead agency: State

Evaluation date: 08/05/2003
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 09/04/2002
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General Facility Standards
Date achieved compliance: 01/15/2003
Evaluation lead agency: State

Evaluation date: 09/04/2002
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - Contingency Plan and Emergency Procedures
Date achieved compliance: 01/15/2003
Evaluation lead agency: State

Evaluation date: 07/15/2002
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 11/14/2000
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - Financial Requirements
Date achieved compliance: 12/19/2000
Evaluation lead agency: State

Evaluation date: 11/14/2000
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - Container Use and Management
Date achieved compliance: 12/19/2000
Evaluation lead agency: State

Evaluation date: 11/14/2000
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General
Date achieved compliance: 12/19/2000
Evaluation lead agency: State

Evaluation date: 11/14/2000

GATX RAIL (Continued) **1000213813**

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - Contingency Plan and Emergency Procedures
Date achieved compliance: 12/19/2000
Evaluation lead agency: State

Evaluation date: 10/31/2000
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: TSD - Financial Requirements
Date achieved compliance: 12/19/2000
Evaluation lead agency: State

Evaluation date: 06/12/1996
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 04/03/1996
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD IS-Chemical, Physical, AND Treatment
Date achieved compliance: 04/09/1996
Evaluation lead agency: State

Evaluation date: 04/03/1996
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - Closure/Post-Closure
Date achieved compliance: 04/09/1996
Evaluation lead agency: State

Evaluation date: 04/03/1996
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General
Date achieved compliance: 04/09/1996
Evaluation lead agency: State

Evaluation date: 08/23/1994
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General
Date achieved compliance: 05/05/1995
Evaluation lead agency: State

Evaluation date: 12/10/1991
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General
Date achieved compliance: 03/13/1992
Evaluation lead agency: State

Evaluation date: 11/21/1991
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: TSD - Financial Requirements
Date achieved compliance: 04/07/1994
Evaluation lead agency: EPA Contractor/Grantee

Evaluation date: 06/15/1989
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General
Date achieved compliance: 08/08/1989

GATX RAIL (Continued) **1000213813**

Evaluation lead agency: State

Evaluation date: 06/12/1989
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 06/30/1988
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 11/23/1987
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General
Date achieved compliance: 10/24/1989
Evaluation lead agency: State

CORRACTS:

EPA ID: CAD055698815
EPA Region: 9
Area Name: ENTIRE FACILITY
Actual Date: 6/21/1989
Action: CA075LO - CA Prioritization, Facility or area was assigned a low corrective action priority
NAICS Code(s): 48821
Support Activities for Rail Transportation
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: CAD055698815
EPA Region: 9
Area Name: ENTIRE FACILITY
Actual Date: 9/24/1992
Action: CA150 - RFI Workplan Approved
NAICS Code(s): 48821
Support Activities for Rail Transportation
Original schedule date: Not reported
Schedule end date: Not reported

CERC-NFRAP:
Site ID: 0903282
Federal Facility: Not a Federal Facility
NPL Status: Not on the NPL
Non NPL Status: NFRAP

CERCLIS-NFRAP Site Contact Name(s):
Contact Name: Matt Mitguard
Contact Tel: (415) 972-3096
Contact Title: Site Assessment Manager (SAM)

Contact Name: Nuria Muniz
Contact Tel: (415) 972-3811

GATX RAIL (Continued) **1000213813**

Contact Title: Site Assessment Manager (SAM)

Site Description: Not reported

CERCLIS-NFRAP Assessment History:

Action:	DISCOVERY
Date Started:	Not reported
Date Completed:	07/12/1989
Priority Level:	Not reported
Action:	ARCHIVE SITE
Date Started:	Not reported
Date Completed:	09/21/1990
Priority Level:	Not reported
Action:	PRELIMINARY ASSESSMENT
Date Started:	Not reported
Date Completed:	09/21/1990
Priority Level:	NFRAP (No Futher Remedial Action Planned

HIST UST:

Region:	STATE
Facility ID:	00000002923
Facility Type:	Other
Other Type:	RAILCAR REPAIR SHOP
Total Tanks:	0004
Contact Name:	ROBERT C. MERCER
Telephone:	7148253043
Owner Name:	GENERAL AMERICAN TRANSPORTATIO
Owner Address:	120 SOUTH RIVERSIDE PLAZA
Owner City,St,Zip:	CHICAGO, IL 60606
Tank Num:	001
Container Num:	65-89
Year Installed:	Not reported
Tank Capacity:	00001000
Tank Used for:	PRODUCT
Type of Fuel:	DIESEL
Tank Construction:	Not reported
Leak Detection:	Visual, None
Tank Num:	002
Container Num:	65-187
Year Installed:	Not reported
Tank Capacity:	00010000
Tank Used for:	PRODUCT
Type of Fuel:	DIESEL
Tank Construction:	Not reported
Leak Detection:	Visual, None
Tank Num:	003
Container Num:	65-19
Year Installed:	Not reported
Tank Capacity:	00070684
Tank Used for:	WASTE
Type of Fuel:	WASTE OIL
Tank Construction:	10 inches

GATX RAIL (Continued) **1000213813**

Leak Detection: Visual, None

Tank Num: 004
Container Num: 65-20
Year Installed: Not reported
Tank Capacity: 00058000
Tank Used for: WASTE
Type of Fuel: Not reported
Tank Construction: 12.5 inches
Leak Detection: Visual

AA109 **10-10 TRUCK STOP** **HAZNET U003784644**
WSW **195 E VALLEY BLVD** **San Bern. Co. Permit N/A**
1/2-1 **RIALTO, CA 92376** **SWEEPS UST**
0.718 mi.
3789 ft. **Site 1 of 2 in cluster AA**

Relative:
Lower

Actual:
1065 ft.

HAZNET:
Gepaid: CAL000140570
Contact: JILL YI-MGR
Telephone: 9098771171
Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: 195 E VALLEY BLVD
Mailing City,St,Zip: RIALTO, CA 923760000
Gen County: San Bernardino
TSD EPA ID: CAT080025711
TSD County: San Bernardino
Waste Category: Waste oil and mixed oil
Disposal Method: Transfer Station
Tons: 22.88
Facility County: Not reported

Gepaid: CAL000140570
Contact: JILL YI-MGR
Telephone: 9098771171
Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: 195 E VALLEY BLVD
Mailing City,St,Zip: RIALTO, CA 923760000
Gen County: San Bernardino
TSD EPA ID: Not reported
TSD County: San Bernardino
Waste Category: Waste oil and mixed oil
Disposal Method: Not reported
Tons: 10.42
Facility County: Not reported

Gepaid: CAL000140570
Contact: JILL YI-MGR
Telephone: 9098771171
Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: 195 E VALLEY BLVD
Mailing City,St,Zip: RIALTO, CA 923760000
Gen County: San Bernardino
TSD EPA ID: Not reported
TSD County: San Bernardino

10-10 TRUCK STOP (Continued) **U003784644**

Waste Category: Waste oil and mixed oil
Disposal Method: Recycler
Tons: 9.17
Facility County: Not reported

Gepaid: CAL000140570
Contact: JILL YI-MGR
Telephone: 9098771171
Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: 195 E VALLEY BLVD
Mailing City,St,Zip: RIALTO, CA 923760000
Gen County: San Bernardino
TSD EPA ID: Not reported
TSD County: San Bernardino
Waste Category: Waste oil and mixed oil
Disposal Method: Transfer Station
Tons: 46.49
Facility County: Not reported

Gepaid: CAL000140570
Contact: JILL YI-MGR
Telephone: 9098771171
Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: 195 E VALLEY BLVD
Mailing City,St,Zip: RIALTO, CA 923760000
Gen County: San Bernardino
TSD EPA ID: Not reported
TSD County: San Bernardino
Waste Category: Waste oil and mixed oil
Disposal Method: Transfer Station
Tons: 16.68
Facility County: Not reported

Click this hyperlink while viewing on your computer to access
13 additional CA_HAZNET: record(s) in the EDR Site Report.

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0003905
Owner: I-10 TRUCK STOP
Permit Number: PT0012207
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 7/31/2008 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0003905
Owner: I-10 TRUCK STOP
Permit Number: PT0002004
Permit Category: HAZMAT HANDLER 0-10 EMPLOYEES (W/GEN PRMT)
Facility Status: ACTIVE
Expiration Date: 7/31/2008 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0003905

10-10 TRUCK STOP (Continued) **U003784644**

Owner: I-10 TRUCK STOP
Permit Number: PT0002005
Permit Category: GENERATOR - 0-10 EMPLOYEES
Facility Status: ACTIVE
Expiration Date: 7/31/2008 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0003905
Owner: I-10 TRUCK STOP
Permit Number: PT0012205
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 7/31/2008 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0003905
Owner: I-10 TRUCK STOP
Permit Number: PT0012206
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 7/31/2008 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0003905
Owner: I-10 TRUCK STOP
Permit Number: PT0012208
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 7/31/2008 12:00:00AM

SWEEPS UST:
Status: A
Comp Number: 8453
Number: 2
Board Of Equalization: Not reported
Ref Date: 06-30-94
Act Date: 06-30-94
Created Date: 06-30-94
Tank Status: A
Owner Tank Id: 1
Swrcb Tank Id: 36-000-008453-000001
Actv Date: 06-30-94
Capacity: 10000
Tank Use: OIL
Stg: W
Content: WASTE OIL
Number Of Tanks: 5

Status: A
Comp Number: 8453
Number: 2
Board Of Equalization: Not reported
Ref Date: 06-30-94
Act Date: 06-30-94
Created Date: 06-30-94
Tank Status: A
Owner Tank Id: 2

10-10 TRUCK STOP (Continued) **U003784644**

Swrcb Tank Id:	36-000-008453-000002
Actv Date:	06-30-94
Capacity:	12000
Tank Use:	M.V. FUEL
Stg:	P
Content:	DIESEL
Number Of Tanks:	Not reported
Status:	A
Comp Number:	8453
Number:	2
Board Of Equalization:	Not reported
Ref Date:	06-30-94
Act Date:	06-30-94
Created Date:	06-30-94
Tank Status:	A
Owner Tank Id:	3
Swrcb Tank Id:	36-000-008453-000003
Actv Date:	06-30-94
Capacity:	10000
Tank Use:	M.V. FUEL
Stg:	P
Content:	DIESEL
Number Of Tanks:	Not reported
Status:	A
Comp Number:	8453
Number:	2
Board Of Equalization:	Not reported
Ref Date:	06-30-94
Act Date:	06-30-94
Created Date:	06-30-94
Tank Status:	A
Owner Tank Id:	4
Swrcb Tank Id:	36-000-008453-000004
Actv Date:	06-30-94
Capacity:	10000
Tank Use:	M.V. FUEL
Stg:	P
Content:	REG UNLEADED
Number Of Tanks:	Not reported
Status:	A
Comp Number:	8453
Number:	2
Board Of Equalization:	Not reported
Ref Date:	06-30-94
Act Date:	06-30-94
Created Date:	06-30-94
Tank Status:	A
Owner Tank Id:	5
Swrcb Tank Id:	36-000-008453-000005
Actv Date:	06-30-94
Capacity:	12000
Tank Use:	M.V. FUEL
Stg:	P
Content:	DIESEL

10-10 TRUCK STOP (Continued) **U003784644**

Number Of Tanks: Not reported

AB110 **CALNEV PIPE LINE CO (NSR USE)** **AIRS** **S106827890**
SSW **1901 SLOVER AVE.** **N/A**
1/2-1 **BLOOMINGTON, CA 92324**
0.730 mi.
3856 ft. **Site 1 of 3 in cluster AB**

Relative:
Lower

Actual:
1022 ft.

EMI:

Year:	1987
Carbon Monoxide Emissions Tons/Yr:	36
Air Basin:	SC
Facility ID:	800022
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	78
Reactive Organic Gases Tons/Yr:	74
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1990
Carbon Monoxide Emissions Tons/Yr:	36
Air Basin:	SC
Facility ID:	800022
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	34
Reactive Organic Gases Tons/Yr:	31
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

AB111 **HMIRS** **94030905**
SSW **1900 SLOVER AVE** **N/A**
1/2-1 **BLOOMINGTON, CA**
0.731 mi.
3861 ft. **Site 2 of 3 in cluster AB**

Relative:
Lower

Actual:
1022 ft.

Click this hyperlink while viewing on your computer to access additional HMIRS detail in the EDR Site Report.

AB112
SSW
1/2-1
0.731 mi.
3861 ft.

1900 SLOVER AVE
BLOOMINGTON, CA

Site 3 of 3 in cluster AB

Relative: Lower

Actual: 1022 ft.

Click this hyperlink while viewing on your computer to access additional HMIRS detail in the EDR Site Report.

HMIRS **94030918**
N/A

AA113
WSW
1/2-1
0.737 mi.
3892 ft.

195 E VALLEY BLVD
195 E VALLEY BLVD
RIALTO, CA 92376

Site 2 of 2 in cluster AA

Relative: Lower

Actual: 1066 ft.

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

ERNS **91241843**
N/A

114
North
1/2-1
0.745 mi.
3931 ft.

JEHUE (WILLIAM G.) MIDDLE
1500 N. EUCALYPTUS AVE.
COLTON, CA 92324

Relative: Higher

Actual: 1152 ft.

FINDS:
Other Pertinent Environmental Activity Identified at Site

NCES (National Center for Education Statistics) is the primary federal entity for collecting and analyzing data related to education in the United States and other nations and the institute of education sciences.

FINDS **1008241942**
110021398815

115
NW
1/2-1
0.748 mi.
3952 ft.

INTOWN PROPERTIES INC/HUD
1355 WHITEOAK
COLTON, CA 92324

Relative: Higher

Actual: 1142 ft.

HAZNET:

Gepaid:	CAC001390160
Contact:	HUD
Telephone:	7149577333
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	6850 BROCKTON AVE STE 215
Mailing City,St,Zip:	RIVERSIDE, CA 925060000
Gen County:	San Bernardino
TSD EPA ID:	CAD000088252
TSD County:	Los Angeles
Waste Category:	Household waste
Disposal Method:	Transfer Station
Tons:	.2293
Facility County:	San Bernardino

HAZNET **S103970290**
N/A

AC116 **BRINE FAC,COLTON** **WMUDS/SWAT** **S103443302**
SSE **CA WDS** **N/A**
1/2-1 **COLTON CA, CA**
0.760 mi.
4015 ft. **Site 1 of 2 in cluster AC**

Relative:
Lower

Actual:
1012 ft.

WMUDS/SWAT:

Edit Date:	Not reported
Complexity:	Category C - Facilities having no waste treatment systems, such as cooling water dischargers or thosewho must comply through best management practices, facilities with passive waste treatment and disposal systems, such as septic systems with subsurface disposal, or dischargers having waste storage systems with land disposal such as dairy waste ponds.
Primary Waste:	Washwater Waste (Product washwater wastes: E.G., photo reuse wastewater, vegetable washwater)
Primary Waste Type:	Designated/Influent or Solid Wastes that pose a significant threat to water quality because of their high concentrations (E.G., BOD, Hardness, TRF, Chloride). 'Manageable' hazardous wastes (E.G., inorganic salts and heavy metals) are included in this category.
Secondary Waste:	Not reported
Secondary Waste Type:	Not reported
Base Meridian:	Not reported
NPID:	Not reported
Tonnage:	0
Regional Board ID:	Not reported
Municipal Solid Waste:	False
Superorder:	False
Open To Public:	False
Waste List:	False
Agency Type:	Private
Agency Name:	GATX RAIL CORPORATION
Agency Department:	Not reported
Agency Address:	PO BOX 590
Agency City,St,Zip:	COLTON CA 923240266
Agency Contact:	DANNY CONTRERAS
Agency Telephone:	9098253043
Land Owner Name:	Not reported
Land Owner Address:	Not reported
Land Owner City,St,Zip:	Not reported
Land Owner Contact:	Not reported
Land Owner Phone:	Not reported
Region:	8
Facility Type:	Industrial - Facility that treats and/or disposes of liquid or semisolid wastes from any servicing, producing, manufacturing or processing operation of whatever nature, including mining, gravel washing, geothermal operations, air conditioning, ship building and repairing, oil production, storage and disposal operations, water pumping.
Facility Description:	Not reported
Facility Telephone:	Not reported
SWAT Facility Name:	Not reported
Primary SIC:	3743
Secondary SIC:	Not reported
Comments:	Not reported
Last Facility Editors:	Not reported
Waste Discharge System:	True
Solid Waste Assessment Test Program:	False
Toxic Pits Cleanup Act Program:	False

BRINE FAC,COLTON (Continued) **S103443302**

Resource Conservation Recovery Act:	False
Department of Defence:	False
Solid Waste Assessment Test Program:	Not reported
Threat to Water Quality:	Minor Threat to Water Quality. A violation of a regional board order should cause a relatively minor impairment of beneficial uses compared to a major or minor threat. Not: All nurds without a TTWQ will be considered a minor threat to water quality unless coded at a higher Level. A Zero (0) may be used to code those NURDS that are found to represent no threat to water quality.
Sub Chapter 15:	True
Regional Board Project Officer:	KDP
Number of WMUDS at Facility:	1
Section Range:	Not reported
RCRA Facility:	No
Waste Discharge Requirements:	Active - Any facility with a continuous or seasonal discharge that is under Waste Discharge Requirements.
Self-Monitoring Rept. Frequency:	Bimonthly (Every two months)
Waste Discharge System ID:	8 362016002
Solid Waste Information ID:	Not reported

CA WDS:

Facility ID:	Santa Ana River 362016002
Facility Type:	Industrial - Facility that treats and/or disposes of liquid or semisolid wastes from any servicing, producing, manufacturing or processing operation of whatever nature, including mining, gravel washing, geothermal operations, air conditioning, ship building and repairing, oil production, storage and disposal operations, water pumping.
Facility Status:	Active - Any facility with a continuous or seasonal discharge that is under Waste Discharge Requirements.
NPDES Number:	Not reported
Subregion:	8
Facility Telephone:	Not reported
Facility Contact:	JAY GROVE
Agency Name:	GATX RAIL CORPORATION
Agency Address:	PO BOX 590
Agency City,St,Zip:	COLTON 923240266
Agency Contact:	DANNY CONTRERAS
Agency Telephone:	Not reported
Agency Type:	Private
SIC Code:	3743
SIC Code 2:	Not reported
Primary Waste:	Washwater Waste (Product washwater wastes: E.G., photo reuse wastewater, vegetable washwater)
Primary Waste Type:	Designated/Influent or Solid Wastes that pose a significant threat to water quality because of their high concentrations (E.G., BOD, Hardness, TRF, Chloride). 'Manageable' hazardous wastes (E.G., inorganic salts and heavy metals) are included in this category.
Secondary Waste:	Not reported
Secondary Waste Type:	Not reported
Design Flow:	0
Baseline Flow:	0
Reclamation:	No reclamation requirements associated with this facility.
POTW:	The facility is not a POTW.
Treat To Water:	Minor Threat to Water Quality. A violation of a regional board order should cause a relatively minor impairment of beneficial uses compared to a major or minor threat. Not: All nurds without a TTWQ will be

BRINE FAC,COLTON (Continued) **S103443302**

considered a minor threat to water quality unless coded at a higher Level. A Zero (0) may be used to code those NURDS that are found to represent no threat to water quality.

Complexity: Category C - Facilities having no waste treatment systems, such as cooling water dischargers or thosewho must comply through best management practices, facilities with passive waste treatment and disposal systems, such as septic systems with subsurface disposal, or dischargers having waste storage systems with land disposal such as dairy waste ponds.

AC117 **GEN AMERICAN TRANSPORTATION CO** **AIRS S104766487**
SSE **20878 SLOVER** **San Bern. Co. Permit N/A**
1/2-1 **COLTON, CA 92324**
0.769 mi.
4059 ft. **Site 2 of 2 in cluster AC**

Relative:
Lower

Actual:
1004 ft.

EMI:

Year:	1996
Carbon Monoxide Emissions Tons/Yr:	36
Air Basin:	SC
Facility ID:	12332
Air District Name:	SC
SIC Code:	3714
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	27
Reactive Organic Gases Tons/Yr:	22
Carbon Monoxide Emissions Tons/Yr:	14
NOX - Oxides of Nitrogen Tons/Yr:	5
SOX - Oxides of Sulphur Tons/Yr:	1
Particulate Matter Tons/Yr:	2
Part. Matter 10 Micrometers & Smllr Tons/Yr:	1

Year:	1997
Carbon Monoxide Emissions Tons/Yr:	36
Air Basin:	SC
Facility ID:	12332
Air District Name:	SC
SIC Code:	3714
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	25
Reactive Organic Gases Tons/Yr:	25
Carbon Monoxide Emissions Tons/Yr:	7
NOX - Oxides of Nitrogen Tons/Yr:	4
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	1
Part. Matter 10 Micrometers & Smllr Tons/Yr:	1

Year:	1998
Carbon Monoxide Emissions Tons/Yr:	36
Air Basin:	SC
Facility ID:	12332
Air District Name:	SC
SIC Code:	3714
Air District Name:	SOUTH COAST AQMD

GEN AMERICAN TRANSPORTATION CO (Continued) **S104766487**

Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	25
Reactive Organic Gases Tons/Yr:	25
Carbon Monoxide Emissions Tons/Yr:	7
NOX - Oxides of Nitrogen Tons/Yr:	4
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	1
Part. Matter 10 Micrometers & Smllr Tons/Yr:	1

Year:	1999
Carbon Monoxide Emissions Tons/Yr:	36
Air Basin:	SC
Facility ID:	12332
Air District Name:	SC
SIC Code:	3714
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	25
Reactive Organic Gases Tons/Yr:	25
Carbon Monoxide Emissions Tons/Yr:	7
NOX - Oxides of Nitrogen Tons/Yr:	4
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	1
Part. Matter 10 Micrometers & Smllr Tons/Yr:	1

Year:	2000
Carbon Monoxide Emissions Tons/Yr:	36
Air Basin:	SC
Facility ID:	12332
Air District Name:	SC
SIC Code:	3714
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	25
Reactive Organic Gases Tons/Yr:	25
Carbon Monoxide Emissions Tons/Yr:	7
NOX - Oxides of Nitrogen Tons/Yr:	4
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	1
Part. Matter 10 Micrometers & Smllr Tons/Yr:	1

Year:	2001
Carbon Monoxide Emissions Tons/Yr:	36
Air Basin:	SC
Facility ID:	12332
Air District Name:	SC
SIC Code:	3714
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	6
Reactive Organic Gases Tons/Yr:	6
Carbon Monoxide Emissions Tons/Yr:	2
NOX - Oxides of Nitrogen Tons/Yr:	1

GEN AMERICAN TRANSPORTATION CO (Continued) **S104766487**

SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	1
Part. Matter 10 Micrometers & Smllr Tons/Yr:	1
Year:	2002
Carbon Monoxide Emissions Tons/Yr:	36
Air Basin:	SC
Facility ID:	12332
Air District Name:	SC
SIC Code:	3743
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	9
Reactive Organic Gases Tons/Yr:	8
Carbon Monoxide Emissions Tons/Yr:	6
NOX - Oxides of Nitrogen Tons/Yr:	3
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	1
Part. Matter 10 Micrometers & Smllr Tons/Yr:	1
Year:	2003
Carbon Monoxide Emissions Tons/Yr:	36
Air Basin:	SC
Facility ID:	12332
Air District Name:	SC
SIC Code:	3743
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	9
Reactive Organic Gases Tons/Yr:	8
Carbon Monoxide Emissions Tons/Yr:	6
NOX - Oxides of Nitrogen Tons/Yr:	3
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	1
Part. Matter 10 Micrometers & Smllr Tons/Yr:	1
Year:	2004
Carbon Monoxide Emissions Tons/Yr:	36
Air Basin:	SC
Facility ID:	12332
Air District Name:	SC
SIC Code:	3743
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	8.578442
Reactive Organic Gases Tons/Yr:	7.94
Carbon Monoxide Emissions Tons/Yr:	5.7675
NOX - Oxides of Nitrogen Tons/Yr:	2.9874
SOX - Oxides of Sulphur Tons/Yr:	0.0331244
Particulate Matter Tons/Yr:	1.42047
Part. Matter 10 Micrometers & Smllr Tons/Yr:	1.19
Year:	2005
Carbon Monoxide Emissions Tons/Yr:	36

GEN AMERICAN TRANSPORTATION CO (Continued) **S104766487**

Air Basin:	SC
Facility ID:	12332
Air District Name:	SC
SIC Code:	3743
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	11.10066
Reactive Organic Gases Tons/Yr:	10.602243786
Carbon Monoxide Emissions Tons/Yr:	10.42735
NOX - Oxides of Nitrogen Tons/Yr:	2.84125
SOX - Oxides of Sulphur Tons/Yr:	.048475
Particulate Matter Tons/Yr:	.9573
Part. Matter 10 Micrometers & Smllr Tons/Yr:	.91681768

San Bern. Co. Permit:

Region:	SAN BERNARDINO
Facility ID:	FA0003431
Owner:	GATX RAIL CORPORATION
Permit Number:	PT0001560
Permit Category:	ABOVEGROUND PETROLEUM STORAGE (AST) (SPCC)
Facility Status:	ACTIVE
Expiration Date:	7/31/2008 12:00:00AM

Region:	SAN BERNARDINO
Facility ID:	FA0003431
Owner:	GATX RAIL CORPORATION
Permit Number:	PT0018710
Permit Category:	RISK MANAGEMENT PLAN - LEVEL III
Facility Status:	ACTIVE
Expiration Date:	7/31/2008 12:00:00AM

Region:	SAN BERNARDINO
Facility ID:	FA0003431
Owner:	GATX RAIL CORPORATION
Permit Number:	PT0012461
Permit Category:	UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status:	ACTIVE
Expiration Date:	7/31/2008 12:00:00AM

Region:	SAN BERNARDINO
Facility ID:	FA0009719
Owner:	GOODYEAR RUBBER COMPANY
Permit Number:	PT0016561
Permit Category:	LIMITED QUANTITY GENERATOR(B)
Facility Status:	ACTIVE
Expiration Date:	5/31/2008 12:00:00AM

Region:	SAN BERNARDINO
Facility ID:	FA0003431
Owner:	GATX RAIL CORPORATION
Permit Number:	PT0001566
Permit Category:	EPCRA FACILITY (RIGHT TO KNOW PLAN)
Facility Status:	ACTIVE
Expiration Date:	7/31/2008 12:00:00AM

Region: SAN BERNARDINO

GEN AMERICAN TRANSPORTATION CO (Continued) **S104766487**

Facility ID: FA0003431
Owner: GATX RAIL CORPORATION
Permit Number: PT0018708
Permit Category: RISK MANAGEMENT PLAN - LEVEL III
Facility Status: ACTIVE
Expiration Date: 7/31/2008 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0003431
Owner: GATX RAIL CORPORATION
Permit Number: PT0001553
Permit Category: RISK MANAGEMENT PLAN - LEVEL III
Facility Status: ACTIVE
Expiration Date: 7/31/2008 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0003431
Owner: GATX RAIL CORPORATION
Permit Number: PT0001556
Permit Category: HAZMAT HANDLER 51-100 EMPLOYEES (W/GEN PRMT)
Facility Status: ACTIVE
Expiration Date: 7/31/2008 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0003431
Owner: GATX RAIL CORPORATION
Permit Number: PT0001558
Permit Category: CALARP FACILITY PERMIT
Facility Status: ACTIVE
Expiration Date: 7/31/2008 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0003431
Owner: GATX RAIL CORPORATION
Permit Number: PT0018709
Permit Category: RISK MANAGEMENT PLAN - LEVEL III
Facility Status: ACTIVE
Expiration Date: 7/31/2008 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0003431
Owner: GATX RAIL CORPORATION
Permit Number: PT0012460
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 7/31/2008 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0003431
Owner: GATX RAIL CORPORATION
Permit Number: PT0001557
Permit Category: GENERATOR - 51-100 EMPLOYEES
Facility Status: ACTIVE
Expiration Date: 7/31/2008 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0003431

GEN AMERICAN TRANSPORTATION CO (Continued) **S104766487**

Owner: GATX RAIL CORPORATION
Permit Number: PT0012462
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: INACTIVE
Expiration Date: 7/31/2004 12:00:00AM

AD118 **P S TRUCK SUPPLY INC** **RCRA-SQG** **1000595840**
WSW **245 E VALLEY BLVD** **FINDS** **CAD983597956**
1/2-1 **RIALTO, CA 92376** **HAZNET**
0.795 mi.
4196 ft. **Site 1 of 5 in cluster AD**

Relative:
Lower

Actual:
1069 ft.

RCRA-SQG:
Date form received by agency: 07/26/1991
Facility name: P S TRUCK SUPPLY INC
Facility address: 245 E VALLEY BLVD
RIALTO, CA 92376
EPA ID: CAD983597956
Contact: LYLE MCKEE
Contact address: 245 E VALLEY BLVD
RIALTO, CA 92376
Contact country: US
Contact telephone: (714) 874-2000
Contact email: Not reported
EPA Region: 09
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: P S TRUCK SUPPLY INC
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: Unknown
Mixed waste (haz. and radioactive): Unknown
Recycler of hazardous waste: No

P S TRUCK SUPPLY INC (Continued) **1000595840**

Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	Unknown
Furnace exemption:	Unknown
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No
Off-site waste receiver:	Commercial status unknown

Violation Status: No violations found

FINDS:
Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZNET:

Gepaid:	CAD983597956
Contact:	LYLE MCKEE
Telephone:	0000000000
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	161 E VALLEY BLVD
Mailing City,St,Zip:	RIALTO, CA 923760000
Gen County:	San Bernardino
TSD EPA ID:	CAT080025711
TSD County:	San Bernardino
Waste Category:	Waste oil and mixed oil
Disposal Method:	Recycler
Tons:	1.3344
Facility County:	San Bernardino

Gepaid:	CAD983597956
Contact:	LYLE MCKEE
Telephone:	0000000000
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	161 E VALLEY BLVD
Mailing City,St,Zip:	RIALTO, CA 923760000
Gen County:	San Bernardino
TSD EPA ID:	CAD982444481
TSD County:	San Bernardino
Waste Category:	Other organic solids
Disposal Method:	Transfer Station
Tons:	.4000
Facility County:	San Bernardino

P S TRUCK SUPPLY INC (Continued) **1000595840**

Gepaid:	CAD983597956
Contact:	STEVE HEATER/PARTS MGR
Telephone:	9098742000
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	161 E VALLEY BLVD
Mailing City,St,Zip:	RIALTO, CA 923760000
Gen County:	San Bernardino
TSD EPA ID:	Not reported
TSD County:	San Bernardino
Waste Category:	Other organic solids
Disposal Method:	Transfer Station
Tons:	0.22
Facility County:	Not reported

Gepaid:	CAD983597956
Contact:	LYLE MCKEE
Telephone:	0000000000
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	161 E VALLEY BLVD
Mailing City,St,Zip:	RIALTO, CA 923760000
Gen County:	San Bernardino
TSD EPA ID:	CAD982444481
TSD County:	San Bernardino
Waste Category:	Oil/water separation sludge
Disposal Method:	Transfer Station
Tons:	7.5060
Facility County:	San Bernardino

Gepaid:	CAD983597956
Contact:	LYLE MCKEE
Telephone:	0000000000
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	161 E VALLEY BLVD
Mailing City,St,Zip:	RIALTO, CA 923760000
Gen County:	San Bernardino
TSD EPA ID:	CAD028409019
TSD County:	Los Angeles
Waste Category:	Hydrocarbon solvents (benzene, hexane, Stoddard, etc.)
Disposal Method:	Transfer Station
Tons:	.2585
Facility County:	San Bernardino

Click this hyperlink while viewing on your computer to access
15 additional CA_HAZNET: record(s) in the EDR Site Report.

AD119 **LUCKY FARMS** **San Bern. Co. Permit** **S108087303**
WSW **245 E VALLEY BLVD** **N/A**
1/2-1 **RIALTO, CA 92376**
0.795 mi.
4199 ft. **Site 2 of 5 in cluster AD**

Relative: San Bern. Co. Permit:
Lower
Region: SAN BERNARDINO
Facility ID: FA0010571
Actual: Owner: LUCKY FARMS INC
1069 ft. Permit Number: PT0017969
Permit Category: SPECIAL GENERATOR(B)
Facility Status: ACTIVE
Expiration Date: 9/30/2008 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0010571
Owner: LUCKY FARMS INC
Permit Number: PT0017970
Permit Category: SPECIAL HANDLER
Facility Status: ACTIVE
Expiration Date: 9/30/2008 12:00:00AM

AE120 **CALNEV PIPE LINE COMPANY** **SLIC** **S108542905**
SSW **2051 E SLOVER AVE** **N/A**
1/2-1 **BLOOMINGTON, CA**
0.807 mi.
4262 ft. **Site 1 of 3 in cluster AE**

Relative: SLIC:
Lower
Type: ITEM #27
Facility Status: I
Actual: Region: 8
1039 ft. Staff: Kamron Saremi, Tel 909-782-4303, SLIC
Description Information: JET FUEL
Date: THRU 12/19/00
Order No: 98-67-075
Npdes No: CAG998001
File Type: REG
Sequency: 01

AE121 **CALNEV PIPE LINE COMPANY COLTON TERMINAL** **FINDS** **1000314453**
SSW **2051 E SLOVER AVE** **HAZNET** **CAD007907322**
1/2-1 **COLTON, CA 92324** **RCRA-LQG**
0.807 mi. **SWEEPS UST**
4262 ft. **Site 2 of 3 in cluster AE**

Relative: FINDS:
Lower
Other Pertinent Environmental Activity Identified at Site

Actual:
1039 ft.
AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the

CALNEV PIPE LINE COMPANY COLTON TERMINAL (Continued) **1000314453**

estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

California - Hazardous Waste Tracking System - Datamart

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZNET:

Gepaid:	CAD007907322
Contact:	GATX TERMINALS CORPORTATION
Telephone:	3126216200
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	PO BOX 6346
Mailing City,St,Zip:	SAN BERNARDINO, CA 924126346
Gen County:	San Bernardino
TSD EPA ID:	CAD008302903
TSD County:	Los Angeles
Waste Category:	Other organic solids
Disposal Method:	Recycler
Tons:	.3500
Facility County:	San Bernardino

Gepaid:	CAD007907322
Contact:	GATX TERMINALS CORPORTATION
Telephone:	3126216200
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	PO BOX 6346
Mailing City,St,Zip:	SAN BERNARDINO, CA 924126346
Gen County:	San Bernardino
TSD EPA ID:	CAT080013352
TSD County:	Los Angeles
Waste Category:	Unspecified aqueous solution
Disposal Method:	Recycler
Tons:	34.1940
Facility County:	San Bernardino

Gepaid:	CAD007907322
Contact:	GATX TERMINALS CORPORTATION
Telephone:	3126216200
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	PO BOX 6346
Mailing City,St,Zip:	SAN BERNARDINO, CA 924126346
Gen County:	San Bernardino

CALNEV PIPE LINE COMPANY COLTON TERMINAL (Continued) **1000314453**

TSD EPA ID: CAD982444481
TSD County: San Bernardino
Waste Category: Other organic solids
Disposal Method: Transfer Station
Tons: 2.0000
Facility County: San Bernardino

Gepaid: CAD007907322
Contact: GATX TERMINALS CORPORTATION
Telephone: 3126216200
Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: PO BOX 6346
Mailing City,St,Zip: SAN BERNARDINO, CA 924126346
Gen County: San Bernardino
TSD EPA ID: CAT000613927
TSD County: San Bernardino
Waste Category: Aqueous solution with less than 10% total organic residues
Disposal Method: Transfer Station
Tons: .5336
Facility County: San Bernardino

Gepaid: CAD007907322
Contact: ROBERT GRANADO
Telephone: 7145604873
Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: 1100 TOWN & COUNTRY RD
Mailing City,St,Zip: ORANGE, CA 928686346
Gen County: San Bernardino
TSD EPA ID: CAD008302903
TSD County: Los Angeles
Waste Category: Unspecified solvent mixture Waste
Disposal Method: Recycler
Tons: 1.66
Facility County: Not reported

Click this hyperlink while viewing on your computer to access
45 additional CA_HAZNET: record(s) in the EDR Site Report.

RCRA-LQG:
Date form received by agency: 02/28/2006
Facility name: CALNEV PIPE LINE, LLC COLTON TERMINAL
Facility address: 2051 WEST SLOVER AVENUE
COLTON, CA 92326
EPA ID: CAD007907322
Mailing address: 1100 TOWN AND COUNTRY ROAD
ORANGE, CA 92868
Contact: ROBERT G GRANADO
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (714) 560-4873
Contact email: GRANADOR@KINDERMORGAN.COM
EPA Region: 09
Land type: Private
Classification: Large Quantity Generator

CALNEV PIPE LINE COMPANY COLTON TERMINAL (Continued) **1000314453**

Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	CALNEV PIPE LINE, LLC
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	03/30/2001
Owner/Op end date:	Not reported

Owner/operator name:	CALNEV PIPE LINE, LLC
Owner/operator address:	1100 TOWN AND COUNTRY ROAD
	ORANGE, CA 92868
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	03/30/2001
Owner/Op end date:	Not reported

Owner/operator name:	CALNEV PIPE LINE CO
Owner/operator address:	NOT REQUIRED
	NOT REQUIRED, ME 99999
Owner/operator country:	Not reported
Owner/operator telephone:	(415) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	NOT REQUIRED
Owner/operator address:	NOT REQUIRED
	NOT REQUIRED, ME 99999
Owner/operator country:	Not reported
Owner/operator telephone:	(415) 555-1212
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No

CALNEV PIPE LINE COMPANY COLTON TERMINAL (Continued) **1000314453**

Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No
Off-site waste receiver: Commercial status unknown

Universal Waste Summary:
Waste type: Batteries
Accumulated waste on-site: No
Generated waste on-site: No

Waste type: Lamps
Accumulated waste on-site: No
Generated waste on-site: No

Waste type: Pesticides
Accumulated waste on-site: No
Generated waste on-site: No

Waste type: Thermostats
Accumulated waste on-site: No
Generated waste on-site: No

Historical Generators:
Date form received by agency: 10/12/2000
Facility name: CALNEV PIPE LINE, LLC COLTON TERMINAL
Site name: CALNEV PIPE LINE COMPANY COLTON TERMINAL
Classification: Large Quantity Generator

Date form received by agency: 04/15/1999
Facility name: CALNEV PIPE LINE, LLC COLTON TERMINAL
Site name: CALNEV PIPE LINE CO, COLTON TERMINAL
Classification: Large Quantity Generator

Date form received by agency: 09/01/1996
Facility name: CALNEV PIPE LINE, LLC COLTON TERMINAL
Site name: CALNEV PIPE LINE CO
Classification: Small Quantity Generator

Date form received by agency: 03/27/1990
Facility name: CALNEV PIPE LINE, LLC COLTON TERMINAL
Site name: CALNEV PIPE LINE CO/COLTON TERMINAL
Classification: Large Quantity Generator

Date form received by agency: 07/15/1980
Facility name: CALNEV PIPE LINE, LLC COLTON TERMINAL

CALNEV PIPE LINE COMPANY COLTON TERMINAL (Continued) **1000314453**

Site name: CALNEV PIPE LINE CO
Classification: Large Quantity Generator

Hazardous Waste Summary:
Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D018
Waste name: BENZENE

Biennial Reports:

Last Biennial Reporting Year: 2005

Annual Waste Handled:
Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.
Amount (Lbs): 1163102.6

Waste code: D018
Waste name: BENZENE
Amount (Lbs): 1163102.6

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 01/17/2006
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 11/08/2005
Evaluation: NOT A SIGNIFICANT NON-COMPLIER
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

Evaluation date: 08/26/2005
Evaluation: SIGNIFICANT NON-COMPLIER
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

CALNEV PIPE LINE COMPANY COLTON TERMINAL (Continued) **1000314453**

Evaluation date: 08/26/2005
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

SWEEPS UST:
Status: A
Comp Number: 20392
Number: 9
Board Of Equalization: 44-020737
Ref Date: 08-28-91
Act Date: 08-28-91
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: CU-07
Swrcb Tank Id: 36-000-020392-000004
Actv Date: 06-28-88
Capacity: 5000
Tank Use: UNKNOWN
Stg: P
Content: Not reported
Number Of Tanks: 1

AE122 **CALNEV COLTON TERMINAL** **AST** **A100225813**
SSW **2051 E. SLOVER AVE.** **N/A**
1/2-1 **COLTON, CA 92316**
0.807 mi.
4262 ft. **Site 3 of 3 in cluster AE**

Relative: **Lower**

Actual: **1039 ft.**

AST:
Owner: CALNEV PIPE LINE CO.
Total Gallons: 38476200

AD123 **I-10 TRUCK STOP** **UST** **U004061579**
WSW **195 E VALLEY BLVD** **N/A**
1/2-1 **RIALTO, CA 92376**
0.820 mi.
4329 ft. **Site 3 of 5 in cluster AD**

Relative: **Lower**

Actual: **1068 ft.**

UST:
Local Agency: 36000
Facility ID: 86008453

AD124 **I-10 TRUCK STOP** **LUST** **S108087034**
WSW **195 VALLEY BOULEVARD EAST** **N/A**
1/2-1 **RIALTO, CA 92376**
0.820 mi.
4329 ft. **Site 4 of 5 in cluster AD**

Relative: **Lower**

Actual: **1068 ft.**

LUST:
Region: STATE
Case Type: Soil only
Cross Street: RIVERSIDE AVENUE
Enf Type: LOPF

I-10 TRUCK STOP (Continued) **S108087034**

Funding:	Not reported
How Discovered:	Tank Closure
How Stopped:	Close Tank
Leak Cause:	UNK
Leak Source:	UNK
Global Id:	T0607199509
Stop Date:	Not reported
Confirm Leak:	2006-08-22 00:00:00
Workplan:	Not reported
Prelim Assess:	Not reported
Pollution Char:	Not reported
Remed Plan:	Not reported
Remed Action:	Not reported
Monitoring:	Not reported
Close Date:	2007-06-01 00:00:00
Discover Date:	1998-12-16 00:00:00
Enforcement Dt:	Not reported
Release Date:	1998-12-30 00:00:00
Review Date:	Not reported
Enter Date:	Not reported
MTBE Date:	Not reported
GW Qualifier:	Not reported
Soil Qualifier:	=
Max MTBE GW ppb:	Not reported
Max MTBE Soil ppb:	3.3
County:	36
Org Name:	Not reported
Reg Board:	Santa Ana Region
Status:	Case Closed
Chemical:	8006619,1203
Contact Person:	Not reported
Responsible Party:	LUCIA KIM
RP Address:	7825 WINSHIP WAY
Interim:	Not reported
Oversight Prgm:	LUST
MTBE Class:	*
MTBE Conc:	1
MTBE Fuel:	0
MTBE Tested:	MTBE Detected. Site tested for MTBE and MTBE detected
Staff:	Not reported
Staff Initials:	JC3
Lead Agency:	Local Agency
Local Agency:	36000L
Hydr Basin #:	Not reported
Beneficial:	Not reported
Priority:	Not reported
Cleanup Fund Id:	Not reported
Work Suspended:	Not reported
Local Case #:	2006007
Case Number:	Not reported
Qty Leaked:	Not reported
Abate Method:	Not reported
Operator:	Not reported
Water System Name:	Not reported
Well Name:	Not reported
Distance To Lust:	0
Waste Discharge Global ID:	Not reported

I-10 TRUCK STOP (Continued) **S108087034**

Waste Disch Assigned Name: Not reported
Summary: Not reported

AD125 **CUMMINS WEST INC** **HAZNET 1000300226**
WSW **161 E VALLEY BLVD** **CA FID UST N/A**
1/2-1 **RIALTO, CA 92376** **HIST UST**
0.837 mi. **San Bern. Co. Permit**
4422 ft. **Site 5 of 5 in cluster AD** **SWEEPS UST**

Relative:
Lower

Actual:
1067 ft.

HAZNET:

Gepaid:	CAD149773418
Contact:	CUMMINS CAL PACIFIC
Telephone:	7142536000
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	3061 S. RIVERSIDE AVE.
Mailing City,St,Zip:	BLOOMINGTON, CA 923160000
Gen County:	San Bernardino
TSD EPA ID:	CAD008252405
TSD County:	Los Angeles
Waste Category:	Unspecified organic liquid mixture
Disposal Method:	Recycler
Tons:	.2293
Facility County:	San Bernardino

Gepaid:	CAD149773418
Contact:	CUMMINS CAL PACIFIC
Telephone:	7142536000
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	3061 S. RIVERSIDE AVE.
Mailing City,St,Zip:	BLOOMINGTON, CA 923160000
Gen County:	San Bernardino
TSD EPA ID:	CAD982444481
TSD County:	San Bernardino
Waste Category:	Other inorganic solid waste
Disposal Method:	Recycler
Tons:	.9250
Facility County:	San Bernardino

Gepaid:	CAD149773418
Contact:	CUMMINS CAL PACIFIC
Telephone:	7142536000
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	3061 S. RIVERSIDE AVE.
Mailing City,St,Zip:	BLOOMINGTON, CA 923160000
Gen County:	San Bernardino
TSD EPA ID:	CAD982444481
TSD County:	San Bernardino
Waste Category:	Other inorganic solid waste
Disposal Method:	Not reported
Tons:	.7500
Facility County:	San Bernardino

Gepaid:	CAD149773418
Contact:	CUMMINS CAL PACIFIC
Telephone:	7142536000

CUMMINS WEST INC (Continued) **1000300226**

Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: 3061 S. RIVERSIDE AVE.
Mailing City,St,Zip: BLOOMINGTON, CA 923160000
Gen County: San Bernardino
TSD EPA ID: Not reported
TSD County: 0
Waste Category: Waste oil and mixed oil
Disposal Method: Recycler
Tons: 3.3360
Facility County: San Bernardino

Gepaid: CAD149773418
Contact: CUMMINS CAL PACIFIC
Telephone: 7142536000
Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: 3061 S. RIVERSIDE AVE.
Mailing City,St,Zip: BLOOMINGTON, CA 923160000
Gen County: San Bernardino
TSD EPA ID: CAD008252405
TSD County: Los Angeles
Waste Category: Unspecified organic liquid mixture
Disposal Method: Recycler
Tons: .9174
Facility County: San Bernardino

Click this hyperlink while viewing on your computer to access
39 additional CA_HAZNET: record(s) in the EDR Site Report.

CA FID UST:
Facility ID: 36002536
Regulated By: UTNKA
Regulated ID: 00008519
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: Not reported
Mail To: Not reported
Mailing Address: 161 E VALLEY BLVD
Mailing Address 2: Not reported
Mailing City,St,Zip: RIALTO 92376
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Active

HIST UST:
Region: STATE
Facility ID: 00000008519
Facility Type: Other
Other Type: CUMMINS DIESEL SALES
Total Tanks: 0003
Contact Name: PHILLIP WEST

CUMMINS WEST INC (Continued) **1000300226**

Telephone: 7148770433
Owner Name: C.S.S. INVESTMENTS
Owner Address: 710 SILVER SPUR RD. SUITE #298
Owner City,St,Zip: ROLLING HILLS ESTATE, CA 90274

Tank Num: 001
Container Num: #1
Year Installed: 1979
Tank Capacity: 00000250
Tank Used for: WASTE
Type of Fuel: WASTE OIL
Tank Construction: Not reported
Leak Detection: None

Tank Num: 002
Container Num: #2
Year Installed: 1979
Tank Capacity: 00000250
Tank Used for: WASTE
Type of Fuel: WASTE OIL
Tank Construction: Not reported
Leak Detection: None

Tank Num: 003
Container Num: 3
Year Installed: 1979
Tank Capacity: 00001500
Tank Used for: WASTE
Type of Fuel: WASTE OIL
Tank Construction: Not reported
Leak Detection: None

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0005146
Owner: MCKEE, LYLE
Permit Number: PT0001406
Permit Category: GENERATOR - 0-10 EMPLOYEES
Facility Status: ACTIVE
Expiration Date: 9/30/2008 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0005146
Owner: MCKEE, LYLE
Permit Number: PT0001405
Permit Category: HAZMAT HANDLER 0-10 EMPLOYEES (W/GEN PRMT)
Facility Status: ACTIVE
Expiration Date: 9/30/2008 12:00:00AM

SWEEPS UST:
Status: A
Comp Number: 8519
Number: 9
Board Of Equalization: 44-020070
Ref Date: 07-28-92
Act Date: 07-28-92

CUMMINS WEST INC (Continued) **1000300226**

Created Date:	02-29-88
Tank Status:	A
Owner Tank Id:	#1
Swrcb Tank Id:	36-000-008519-000001
Actv Date:	08-25-88
Capacity:	250
Tank Use:	OIL
Stg:	W
Content:	WASTE OIL
Number Of Tanks:	2
Status:	A
Comp Number:	8519
Number:	9
Board Of Equalization:	44-020070
Ref Date:	07-28-92
Act Date:	07-28-92
Created Date:	02-29-88
Tank Status:	A
Owner Tank Id:	#2
Swrcb Tank Id:	36-000-008519-000002
Actv Date:	08-25-88
Capacity:	250
Tank Use:	OIL
Stg:	W
Content:	WASTE OIL
Number Of Tanks:	Not reported

126
ESE
1/2-1
0.840 mi.
4437 ft.

CIRCLE K STORE #627
990 VALLEY BLVD
COLTON, CA 92324

RCRA-SQG **1000174015**
FINDS **CAD981679590**
HIST UST

Relative:
Lower

Actual:
1019 ft.

RCRA-SQG:

Date form received by agency:	09/01/1996
Facility name:	CIRCLE K STORE #627
Facility address:	990 VALLEY BLVD COLTON, CA 92324
EPA ID:	CAD981679590
Mailing address:	5811 MANZANITA AVE CARMICHAEL, CA 95608
Contact:	Not reported
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	09
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

CIRCLE K STORE #627 (Continued) **1000174015**

Owner/operator name:	NOT REQUIRED
Owner/operator address:	NOT REQUIRED
	NOT REQUIRED, ME 99999
Owner/operator country:	Not reported
Owner/operator telephone:	(415) 555-1212
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	CIRCLE K CORP
Owner/operator address:	NOT REQUIRED
	NOT REQUIRED, ME 99999
Owner/operator country:	Not reported
Owner/operator telephone:	(415) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	Unknown
Mixed waste (haz. and radioactive):	Unknown
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	Unknown
Furnace exemption:	Unknown
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No
Off-site waste receiver:	Commercial status unknown

Historical Generators:

Date form received by agency:	10/16/1986
Facility name:	CIRCLE K STORE #627
Classification:	Large Quantity Generator

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CIRCLE K STORE #627 (Continued) **1000174015**

HIST UST:

Region:	STATE
Facility ID:	00000013599
Facility Type:	Gas Station
Other Type:	Not reported
Total Tanks:	0002
Contact Name:	KEN ZIMMERMAN
Telephone:	7148252135
Owner Name:	CIRCLE K CORPORATION
Owner Address:	4500 SOUTH 40TH STREET
Owner City,St,Zip:	PHOENIX, AZ 85040
Tank Num:	001
Container Num:	1
Year Installed:	Not reported
Tank Capacity:	00009940
Tank Used for:	PRODUCT
Type of Fuel:	REGULAR
Tank Construction:	Not reported
Leak Detection:	Stock Inventor
Tank Num:	002
Container Num:	2
Year Installed:	Not reported
Tank Capacity:	00009940
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Tank Construction:	Not reported
Leak Detection:	Stock Inventor

AF127 **SOUTHERN PACIFIC RAILYARD** **LUST S100676364**
SW **200 MARION WAY** **Cortese N/A**
1/2-1 **BLOOMINGTON, CA 92316** **Toxic Pits**
0.846 mi. **AIRS**
4469 ft. **Site 1 of 3 in cluster AF** **SWEEPS UST**

Relative:
Lower

Actual:
1043 ft.

LUST:

Region:	STATE
Case Type:	Soil only
Cross Street:	ONE SPOT
Enf Type:	Not reported
Funding:	CLOS
How Discovered:	Tank Closure
How Stopped:	Not reported
Leak Cause:	UNK
Leak Source:	UNK
Global Id:	T0607100106
Stop Date:	1988-03-22 00:00:00
Confirm Leak:	Not reported
Workplan:	Not reported
Prelim Assess:	Not reported
Pollution Char:	1988-08-24 00:00:00
Remed Plan:	Not reported
Remed Action:	Not reported
Monitoring:	Not reported
Close Date:	1991-03-28 00:00:00
Discover Date:	1988-07-20 00:00:00

SOUTHERN PACIFIC RAILYARD (Continued) **S100676364**

Enforcement Dt: Not reported
Release Date: 1988-07-21 00:00:00
Review Date: Not reported
Enter Date: 1988-08-24 00:00:00
MTBE Date: Not reported
GW Qualifier: Not reported
Soil Qualifier: Not reported
Max MTBE GW ppb: Not reported
Max MTBE Soil ppb: Not reported
County: 36
Org Name: Not reported
Reg Board: Santa Ana Region
Status: Case Closed
Chemical: Diesel
Contact Person: Not reported
Responsible Party: SOUTHERN PACIFIC TRANS/COLTON
RP Address: 200 MARION WAY, BLOOMINGTON, CA 92316
Interim: Not reported
Oversight Prgm: LUST
MTBE Class: *
MTBE Conc: 0
MTBE Fuel: 0
MTBE Tested: Not Required to be Tested.
Staff: PAH
Staff Initials: CR2
Lead Agency: Local Agency
Local Agency: 36000L
Hydr Basin #: UPPER SANTA ANA VALL
Beneficial: Not reported
Priority: Not reported
Cleanup Fund Id: Not reported
Work Suspended: Not reported
Local Case #: 87003
Case Number: 083600986T
Qty Leaked: Not reported
Abate Method: Not reported
Operator: BEESE, TOM
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 0
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported
Summary: Not reported

LUST:
Region: 8
Case Type: Soil only
Cross Street: ONE SPOT
Enf Type: CLOS
Funding: Not reported
How Discovered: Tank Closure
How Stopped: Not reported
Leak Cause: UNK
Leak Source: UNK
Global ID: T0607100106
How Stopped Date: 3/22/1988
Review Date: Not reported

SOUTHERN PACIFIC RAILYARD (Continued) **S100676364**

Workplan:	Not reported
Prelim Assess:	Not reported
Pollution Char:	8/24/1988
Remed Plan:	Not reported
Remed Action:	Not reported
Monitoring:	Not reported
Close Date:	3/28/1991
Discover Date:	7/20/1988
Enforcement Date:	Not reported
Review Date:	Not reported
Enter Date:	8/24/1988
MTBE Date:	Not reported
GW Qualifies:	Not reported
Soil Qualifies:	Not reported
Max MTBE GW:	Not reported
Max MTBE Soil:	Not reported
County:	San Bernardino
Operator:	Not reported
Regional Board:	08
Facility Status:	Case Closed
Substance:	12034
Facility Contact:	Not reported
Interim:	Not reported
Oversite Program:	LUST
Latitude:	34.0672235
Longitude:	-117.3679377
MTBE Concentration:	0
MTBE Fuel:	0
MTBE Tested:	NRQ
Staff:	PAH
Staff Initials:	CR2
Lead Agency:	Local Agency
Local Agency:	36000L
Hydr Basin #:	UPPER SANTA ANA VALL
Beneficial:	Not reported
Priority:	Not reported
Cleanup Fund Id:	Not reported
Work Suspended:	Not reported
Local Case Num:	87003
Case Number:	083600986T
Qty Leaked:	Not reported
Abate Method:	Not reported
MTBE Class:	*
Summary:	Not reported

Cortese:

Region:	CORTESE
Facility Addr2:	200 MARION WAY

Toxic Pits:

Region:	08
Task #:	88005
Owner:	SOUTHERN PACIFIC TRANS. CO.
1/2 Mi Limit:	Y
Num. of Pits:	1
Cease Discharge Due:	06/30/90

SOUTHERN PACIFIC RAILYARD (Continued) **S100676364**

Cease Discharge Complete: 04/11/89
Closure Due: 06/30/90
Closure Completed: 02/21/91
Status: CLOSED
Hydro Geological Assessment Report Due: / /
Final Hydro Geological Assessment Review Completed: / /

EMI:

Year:	1987
Carbon Monoxide Emissions Tons/Yr:	36
Air Basin:	SC
Facility ID:	1625
Air District Name:	SC
SIC Code:	4463
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

SWEEPS UST:

Status:	A
Comp Number:	5231
Number:	1
Board Of Equalization:	44-019903
Ref Date:	03-19-92
Act Date:	03-19-92
Created Date:	09-13-88
Tank Status:	A
Owner Tank Id:	Not reported
Swrcb Tank Id:	36-000-005231-000001
Actv Date:	09-13-88
Capacity:	1
Tank Use:	UNKNOWN
Stg:	P
Content:	UNKNOWN
Number Of Tanks:	1

AF128 **UNION PACIFIC RAILROAD CO** **San Bern. Co. Permit** **S104771577**
SW **200 MARION WAY** **N/A**
1/2-1 **BLOOMINGTON, CA 92316**
0.846 mi.
4469 ft. **Site 2 of 3 in cluster AF**

Relative:
Lower

Actual:
1043 ft.

San Bern. Co. Permit:

Region:	SAN BERNARDINO
Facility ID:	FA0006899
Owner:	UNION PACIFIC RAILROAD
Permit Number:	PT0001676
Permit Category:	GENERATOR - 51-100 EMPLOYEES
Facility Status:	ACTIVE
Expiration Date:	7/31/2008 12:00:00AM

UNION PACIFIC RAILROAD CO (Continued) **S104771577**

Region: SAN BERNARDINO
Facility ID: FA0006899
Owner: UNION PACIFIC RAILROAD
Permit Number: PT0001675
Permit Category: HAZMAT HANDLER 51-100 EMPLOYEES (W/GEN PRMT)
Facility Status: ACTIVE
Expiration Date: 7/31/2008 12:00:00AM

AG129 **BESTFOODS BAKING COMPANY** **HAZNET** **S103640452**
WSW **2036 W VALLEY BLVD** **San Bern. Co. Permit** **N/A**
1/2-1 **RIALTO, CA 92376**
0.849 mi.
4485 ft. **Site 1 of 16 in cluster AG**

Relative:
Lower

Actual:
1067 ft.

HAZNET:
Gepaid: CAL000037893
Contact: BESTFOODS BAKING COMPANY
Telephone: 2137206002
Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: 480 S VAIL AVE
Mailing City,St,Zip: MONTEBELLO, CA 906400000
Gen County: San Bernardino
TSD EPA ID: CAT000613893
TSD County: Los Angeles
Waste Category: Aqueous solution with less than 10% total organic residues
Disposal Method: Transfer Station
Tons: .0417
Facility County: San Bernardino

Gepaid: CAL000037893
Contact: BESTFOODS BAKING COMPANY
Telephone: 2137206002
Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: 480 S VAIL AVE
Mailing City,St,Zip: MONTEBELLO, CA 906400000
Gen County: San Bernardino
TSD EPA ID: CAT080025711
TSD County: San Bernardino
Waste Category: Waste oil and mixed oil
Disposal Method: Transfer Station
Tons: 1.6680
Facility County: San Bernardino

Gepaid: CAL000037893
Contact: BESTFOODS BAKING COMPANY
Telephone: 2137206002
Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: 480 S VAIL AVE
Mailing City,St,Zip: MONTEBELLO, CA 906400000
Gen County: San Bernardino
TSD EPA ID: CAT080025711
TSD County: San Bernardino
Waste Category: Waste oil and mixed oil
Disposal Method: Recycler
Tons: 9.1740

BESTFOODS BAKING COMPANY (Continued) **S103640452**

Facility County: San Bernardino

Gepaid: CAL000037893
Contact: MARK ARMSTRONG/SR PROJECT ENGR
Telephone: 3237206002
Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: 480 S VAIL AVE
Mailing City,St,Zip: MONTEBELLO, CA 906400000
Gen County: San Bernardino
TSD EPA ID: Not reported
TSD County: San Bernardino
Waste Category: Aqueous solution with less than 10% total organic residues
Disposal Method: Transfer Station
Tons: 0.23
Facility County: Not reported

Gepaid: CAL000037893
Contact: BESTFOODS BAKING COMPANY
Telephone: 2137206002
Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: 480 S VAIL AVE
Mailing City,St,Zip: MONTEBELLO, CA 906400000
Gen County: San Bernardino
TSD EPA ID: CAD050099696
TSD County: Los Angeles
Waste Category: Aqueous solution with less than 10% total organic residues
Disposal Method: Recycler
Tons: .2085
Facility County: San Bernardino

Click this hyperlink while viewing on your computer to access
9 additional CA_HAZNET: record(s) in the EDR Site Report.

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0001436
Owner: BIMBO BAKERIES USA, INC.
Permit Number: PT0009469
Permit Category: SPECIAL HANDLER
Facility Status: ACTIVE
Expiration Date: 12/31/2007 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0001436
Owner: BIMBO BAKERIES USA, INC.
Permit Number: PT0009470
Permit Category: SPECIAL GENERATOR(B)
Facility Status: ACTIVE
Expiration Date: 12/31/2007 12:00:00AM

130 **RIALTO MED SUPPLIES INC** **San Bern. Co. Permit** **S103820663**
West **1517 S RIVERSIDE AVE** **N/A**
1/2-1 **RIALTO, CA 92376**
0.850 mi.
4490 ft.

Relative: San Bern. Co. Permit:
Higher Region: SAN BERNARDINO
Facility ID: FA0005698
Actual: Owner: RIALTO MED SUPPLIES INC
1086 ft. Permit Number: PT0009481
Permit Category: HAZMAT HANDLER 0-10 EMPLOYEES
Facility Status: ACTIVE
Expiration Date: 9/30/2008 12:00:00AM

AF131 **VULCAN STEEL CO** **San Bern. Co. Permit** **S104772095**
SW **270 E CAMERON WAY** **N/A**
1/2-1 **RIALTO, CA 92376**
0.858 mi.
4528 ft. **Site 3 of 3 in cluster AF**

Relative: San Bern. Co. Permit:
Lower Region: SAN BERNARDINO
Facility ID: FA0007170
Actual: Owner: VULCAN STEEL CO INC
1043 ft. Permit Number: PT0004818
Permit Category: GENERATOR - 0-10 EMPLOYEES
Facility Status: ACTIVE
Expiration Date: 5/31/2008 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0007170
Owner: VULCAN STEEL CO INC
Permit Number: PT0004817
Permit Category: HAZMAT HANDLER 0-10 EMPLOYEES (W/GEN PRMT)
Facility Status: ACTIVE
Expiration Date: 5/31/2008 12:00:00AM

AG132 **JUST GAS INC** **CA FID UST** **S101590968**
WSW **102 E VALLEY BLVD** **SWEEPS UST** **N/A**
1/2-1 **RIALTO, CA 92376**
0.866 mi.
4575 ft. **Site 2 of 16 in cluster AG**

Relative: CA FID UST:
Lower Facility ID: 36000394
Regulated By: UTNKI
Actual: Regulated ID: 00051115
1065 ft. Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: Not reported
Mail To: Not reported
Mailing Address: 102 E VALLEY BLVD
Mailing Address 2: Not reported
Mailing City,St,Zip: RIALTO 92376
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported

JUST GAS INC (Continued) **S101590968**

NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Inactive

SWEEPS UST:
Status: Not reported
Comp Number: 51115
Number: Not reported
Board Of Equalization: 44-021150
Ref Date: Not reported
Act Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 36-000-051115-000001
Actv Date: Not reported
Capacity: 12000
Tank Use: M.V. FUEL
Stg: PRODUCT
Content: DIESEL
Number Of Tanks: 6

Status: Not reported
Comp Number: 51115
Number: Not reported
Board Of Equalization: 44-021150
Ref Date: Not reported
Act Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 36-000-051115-000002
Actv Date: Not reported
Capacity: 280
Tank Use: OIL
Stg: WASTE
Content: WASTE OIL
Number Of Tanks: Not reported

Status: Not reported
Comp Number: 51115
Number: Not reported
Board Of Equalization: 44-021150
Ref Date: Not reported
Act Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 36-000-051115-000003
Actv Date: Not reported
Capacity: 4000
Tank Use: M.V. FUEL
Stg: PRODUCT
Content: LEADED
Number Of Tanks: Not reported

JUST GAS INC (Continued) **S101590968**

Status:	Not reported
Comp Number:	51115
Number:	Not reported
Board Of Equalization:	44-021150
Ref Date:	Not reported
Act Date:	Not reported
Created Date:	Not reported
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	36-000-051115-000004
Actv Date:	Not reported
Capacity:	4000
Tank Use:	M.V. FUEL
Stg:	PRODUCT
Content:	LEADED
Number Of Tanks:	Not reported

Status:	Not reported
Comp Number:	51115
Number:	Not reported
Board Of Equalization:	44-021150
Ref Date:	Not reported
Act Date:	Not reported
Created Date:	Not reported
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	36-000-051115-000005
Actv Date:	Not reported
Capacity:	6000
Tank Use:	M.V. FUEL
Stg:	PRODUCT
Content:	LEADED
Number Of Tanks:	Not reported

Status:	Not reported
Comp Number:	51115
Number:	Not reported
Board Of Equalization:	44-021150
Ref Date:	Not reported
Act Date:	Not reported
Created Date:	Not reported
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	36-000-051115-000006
Actv Date:	Not reported
Capacity:	10000
Tank Use:	M.V. FUEL
Stg:	PRODUCT
Content:	REG UNLEADED
Number Of Tanks:	Not reported

AG133 **10-10 TRUCK STOP** **HIST UST** **U001575515**
WSW **195 E VALLEY RIALTO, CA .92376** **N/A**
1/2-1 **RIALTO, CA 92376**
0.867 mi.
4578 ft. **Site 3 of 16 in cluster AG**

Relative:
Lower

Actual:
1065 ft.

HIST UST:

Region:	STATE
Facility ID:	00000057683
Facility Type:	Gas Station
Other Type:	Not reported
Total Tanks:	0005
Contact Name:	Not reported
Telephone:	7148771171
Owner Name:	ROBERT W. CASTALOI
Owner Address:	195 E. VALLEY
Owner City,St,Zip:	RIALTO, CA 92376
Tank Num:	001
Container Num:	1
Year Installed:	Not reported
Tank Capacity:	00000000
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Tank Construction:	Not reported
Leak Detection:	Pressure Test
Tank Num:	002
Container Num:	2
Year Installed:	Not reported
Tank Capacity:	00000000
Tank Used for:	PRODUCT
Type of Fuel:	REGULAR
Tank Construction:	Not reported
Leak Detection:	None
Tank Num:	003
Container Num:	3
Year Installed:	Not reported
Tank Capacity:	00000000
Tank Used for:	PRODUCT
Type of Fuel:	DIESEL
Tank Construction:	Not reported
Leak Detection:	None
Tank Num:	004
Container Num:	4
Year Installed:	Not reported
Tank Capacity:	00000000
Tank Used for:	PRODUCT
Type of Fuel:	DIESEL
Tank Construction:	Not reported
Leak Detection:	None
Tank Num:	005
Container Num:	5
Year Installed:	Not reported
Tank Capacity:	00000000
Tank Used for:	PRODUCT

10-10 TRUCK STOP (Continued) **U001575515**

Type of Fuel: UNLEADED
Tank Construction: Not reported
Leak Detection: None

AG134 **CHEVRON STATION NO 96969** **RCRA-SQG** **1005904248**
WSW **101 E VALLEY BLVD** **FINDS** **CAR000118208**
1/2-1 **RIALTO, CA 92376** **HAZNET**
0.869 mi.
4587 ft. **Site 4 of 16 in cluster AG**

Relative:
Lower

Actual:
1065 ft.

RCRA-SQG:
Date form received by agency: 05/16/2002
Facility name: CHEVRON STATION NO 96969
Facility address: 101 E VALLEY BLVD
RIALTO, CA 923767721
EPA ID: CAR000118208
Mailing address: P O BOX 6004
SAN RAMON, CA 94583
Contact: KATHY NORRIS
Contact address: P O BOX 6004
SAN RAMON, CA 94583
Contact country: US
Contact telephone: (925) 842-5931
Contact email: Not reported
EPA Region: 09
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: CHEVRON PRODUCTS CO
Owner/operator address: P O BOX 6004
SAN RAMON, CA 94583
Owner/operator country: Not reported
Owner/operator telephone: (925) 842-5931
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: Unknown
Mixed waste (haz. and radioactive): Unknown
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: Unknown
Furnace exemption: Unknown
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No

CHEVRON STATION NO 96969 (Continued) **1005904248**

Used oil transfer facility: No
Used oil transporter: No
Off-site waste receiver: Commercial status unknown

Hazardous Waste Summary:
Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D018
Waste name: BENZENE

Violation Status: No violations found

FINDS:
Other Pertinent Environmental Activity Identified at Site

California - Hazardous Waste Tracking System - Datamart

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZNET:
Gepaid: CAR000118208
Contact: Kathy Norris
Telephone: 9258425931
Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: PO BOX 6004
Mailing City,St,Zip: San Ramon, CA 94583
Gen County: San Bernardino
TSD EPA ID: CAD982444481
TSD County: San Bernardino
Waste Category: Other organic solids
Disposal Method: Recycler
Tons: 0.03
Facility County: Not reported

Gepaid: CAR000118208
Contact: Kathy Norris
Telephone: 9258425931
Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: PO BOX 6004
Mailing City,St,Zip: San Ramon, CA 94583
Gen County: San Bernardino
TSD EPA ID: CAD982444481

CHEVRON STATION NO 96969 (Continued) **1005904248**

TSD County: San Bernardino
Waste Category: Other organic solids
Disposal Method: Recycler
Tons: 0.02
Facility County: San Bernardino

AG135 **CHEVRON STATION #6969** **UST** **U004061578**
WSW **101 E VALLEY BLVD** **N/A**
1/2-1 **RIALTO, CA 92376**
0.869 mi.
4587 ft. **Site 5 of 16 in cluster AG**

Relative:
Lower

UST:
Local Agency: 36000
Facility ID: 86008451

Actual:
1065 ft.

AG136 **96969** **HIST UST** **U001575517**
WSW **101 E VALLEY BLVD** **N/A**
1/2-1 **RIALTO, CA 92376**
0.869 mi.
4587 ft. **Site 6 of 16 in cluster AG**

Relative:
Lower

Actual:
1065 ft.

HIST UST:
Region: STATE
Facility ID: 00000062941
Facility Type: Gas Station
Other Type: Not reported
Total Tanks: 0004
Contact Name: COPELAND,RAYMOND L
Telephone: 7148775083
Owner Name: CHEVRON U.S.A. INC.
Owner Address: 575 MARKET
Owner City,St,Zip: SAN FRANCISCO, CA 94105

Tank Num: 001
Container Num: 1
Year Installed: 1961
Tank Capacity: 00010000
Tank Used for: PRODUCT
Type of Fuel: Not reported
Tank Construction: 0000250 unknown
Leak Detection: Stock Inventor

Tank Num: 002
Container Num: 2
Year Installed: 1961
Tank Capacity: 00008000
Tank Used for: PRODUCT
Type of Fuel: Not reported
Tank Construction: 0000250 unknown
Leak Detection: Stock Inventor

Tank Num: 003
Container Num: 3
Year Installed: 1961
Tank Capacity: 00004000

96969 (Continued) **U001575517**

Tank Used for: PRODUCT
Type of Fuel: Not reported
Tank Construction: 0000170 unknown
Leak Detection: Stock Inventor

Tank Num: 004
Container Num: 4
Year Installed: 1961
Tank Capacity: 00000550
Tank Used for: WASTE
Type of Fuel: Not reported
Tank Construction: 0000100 unknown
Leak Detection: Stock Inventor

AG137 **CHEVRON STATION #6969** **CA FID UST** **S101591821**
WSW **101 E VALLEY BLVD** **N/A**
1/2-1 **RIALTO, CA 92376**
0.869 mi.
4587 ft. **Site 7 of 16 in cluster AG**

Relative:
Lower

Actual:
1065 ft.

CA FID UST:
Facility ID: 36009223
Regulated By: UTNKA
Regulated ID: 00062941
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: Not reported
Mail To: Not reported
Mailing Address: 101 E VALLEY BLVD
Mailing Address 2: Not reported
Mailing City,St,Zip: RIALTO 92376
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Active

AG138 **RCRA-LQG** **1007200511**
WSW **101 E VALLEY BLVD.** **CAP000067413**
1/2-1 **RIALTO, CA 92376**
0.869 mi.
4587 ft. **Site 8 of 16 in cluster AG**

Relative:
Lower

Actual:
1065 ft.

RCRA-LQG:
Date form received by agency: 10/12/2000
Facility name: Not reported
Facility address: 101 E VALLEY BLVD.
RIALTO, CA 92376
EPA ID: CAP000067413
Mailing address: PO BOX 6004
SAN RAMON, CA 94583
Contact: KATHY L. NORRIS
Contact address: Not reported
Not reported

(Continued) **1007200511**

Contact country:	Not reported
Contact telephone:	(925) 842-5931
Contact email:	Not reported
EPA Region:	Not reported
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Handler Activities Summary:

U.S. importer of hazardous waste:	Unknown
Mixed waste (haz. and radioactive):	Unknown
Recycler of hazardous waste:	Unknown
Transporter of hazardous waste:	Unknown
Treater, storer or disposer of HW:	No
Underground injection activity:	Unknown
On-site burner exemption:	Unknown
Furnace exemption:	Unknown
Used oil fuel burner:	Unknown
Used oil processor:	Unknown
User oil refiner:	Unknown
Used oil fuel marketer to burner:	Unknown
Used oil Specification marketer:	Unknown
Used oil transfer facility:	Unknown
Used oil transporter:	Unknown
Off-site waste receiver:	Commercial status unknown

Violation Status: No violations found

AG139 **CHEVRON STATION #6969** **San Bern. Co. Permit** **U003938912**
WSW **101 E VALLEY BLVD** **SWEEPS UST** **N/A**
1/2-1 **RIALTO, CA 92376**
0.869 mi.
4587 ft. **Site 9 of 16 in cluster AG**

Relative:
Lower

Actual:
1065 ft.

San Bern. Co. Permit:

Region:	SAN BERNARDINO
Facility ID:	FA0001899
Owner:	CHEVRON PRODUCTS CO
Permit Number:	PT0012204
Permit Category:	UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status:	ACTIVE
Expiration Date:	7/31/2008 12:00:00AM

Region:	SAN BERNARDINO
Facility ID:	FA0001899
Owner:	CHEVRON PRODUCTS CO
Permit Number:	PT0002003
Permit Category:	HAZMAT HANDLER - UST ONLY
Facility Status:	ACTIVE
Expiration Date:	7/31/2008 12:00:00AM

Region:	SAN BERNARDINO
Facility ID:	FA0001899
Owner:	CHEVRON PRODUCTS CO
Permit Number:	PT0012203

CHEVRON STATION #6969 (Continued) **U003938912**

Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 7/31/2008 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0001899
Owner: CHEVRON PRODUCTS CO
Permit Number: PT0012202
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 7/31/2008 12:00:00AM

SWEEPS UST:
Status: A
Comp Number: 62941
Number: 9
Board Of Equalization: 44-021353
Ref Date: 07-28-92
Act Date: 07-28-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 1
Swrcb Tank Id: 36-000-062941-000001
Actv Date: 08-25-88
Capacity: 10000
Tank Use: UNKNOWN
Stg: P
Content: Not reported
Number Of Tanks: 4

Status: A
Comp Number: 62941
Number: 9
Board Of Equalization: 44-021353
Ref Date: 07-28-92
Act Date: 07-28-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 2
Swrcb Tank Id: 36-000-062941-000002
Actv Date: 08-25-88
Capacity: 8000
Tank Use: UNKNOWN
Stg: P
Content: Not reported
Number Of Tanks: Not reported

Status: A
Comp Number: 62941
Number: 9
Board Of Equalization: 44-021353
Ref Date: 07-28-92
Act Date: 07-28-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 3
Swrcb Tank Id: 36-000-062941-000003

CHEVRON STATION #6969 (Continued) **U003938912**

Actv Date:	08-25-88
Capacity:	4000
Tank Use:	UNKNOWN
Stg:	P
Content:	Not reported
Number Of Tanks:	Not reported
Status:	A
Comp Number:	62941
Number:	9
Board Of Equalization:	44-021353
Ref Date:	07-28-92
Act Date:	07-28-92
Created Date:	02-29-88
Tank Status:	A
Owner Tank Id:	4
Swrcb Tank Id:	36-000-062941-000004
Actv Date:	08-25-88
Capacity:	550
Tank Use:	UNKNOWN
Stg:	W
Content:	Not reported
Number Of Tanks:	Not reported

AG140 **CHEVRON #9-6969** **LUST** **S106784791**
WSW **101 VALLEY BLVD** **N/A**
1/2-1 **RIALTO, CA 92376**
0.883 mi.
4663 ft. **Site 10 of 16 in cluster AG**

Relative: LUST:
Lower

Region:	STATE
Case Type:	Drinking water wells have been affected
Cross Street:	RIVERSIDE
Enf Type:	F
Funding:	CLOS
How Discovered:	Tank Closure
How Stopped:	Not reported
Leak Cause:	UNK
Leak Source:	UNK
Global Id:	T0607100325
Stop Date:	1993-09-16 00:00:00
Confirm Leak:	1993-09-16 00:00:00
Workplan:	Not reported
Prelim Assess:	1993-10-05 00:00:00
Pollution Char:	Not reported
Remed Plan:	Not reported
Remed Action:	Not reported
Monitoring:	Not reported
Close Date:	2000-04-28 00:00:00
Discover Date:	1993-09-16 00:00:00
Enforcement Dt:	Not reported
Release Date:	1993-10-05 00:00:00
Review Date:	Not reported
Enter Date:	1994-06-16 00:00:00
MTBE Date:	Not reported
GW Qualifier:	Not reported
Soil Qualifier:	Not reported

Actual:
1064 ft.

CHEVRON #9-6969 (Continued) **S106784791**

Max MTBE GW ppb: Not reported
Max MTBE Soil ppb: Not reported
County: 36
Org Name: Not reported
Reg Board: Santa Ana Region
Status: Case Closed
Chemical: Gasoline
Contact Person: Not reported
Responsible Party: CHEVRON U.S.A.
RP Address: P.O. BOX 2833, LA HABRA, CA 90632-2833
Interim: Not reported
Oversight Prgm: LUST
MTBE Class: *
MTBE Conc: 0
MTBE Fuel: 1
MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.
Staff: TME
Staff Initials: CB5
Lead Agency: Local Agency
Local Agency: 36000L
Hydr Basin #: UPPER SANTA ANA VALL
Beneficial: Not reported
Priority: Not reported
Cleanup Fund Id: Not reported
Work Suspended: Not reported
Local Case #: 92045
Case Number: 083602453T
Qty Leaked: Not reported
Abate Method: Not reported
Operator: Not reported
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 0
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported
Summary: Site closed on April 28, 2000.

LUST:
Region: 8
Case Type: Drinking water wells have been affected
Cross Street: RIVERSIDE
Enf Type: CLOS
Funding: Federal
How Discovered: Tank Closure
How Stopped: Not reported
Leak Cause: UNK
Leak Source: UNK
Global ID: T0607100325
How Stopped Date: 9/16/1993
Review Date: 9/16/1993
Workplan: Not reported
Prelim Assess: 10/5/1993
Pollution Char: Not reported
Remed Plan: Not reported
Remed Action: Not reported
Monitoring: Not reported
Close Date: 4/28/2000

CHEVRON #9-6969 (Continued) **S106784791**

Discover Date:	9/16/1993
Enforcement Date:	Not reported
Review Date:	Not reported
Enter Date:	6/16/1994
MTBE Date:	Not reported
GW Qualifies:	Not reported
Soil Qualifies:	Not reported
Max MTBE GW:	Not reported
Max MTBE Soil:	Not reported
County:	San Bernardino
Operator:	Not reported
Regional Board:	08
Facility Status:	Case Closed
Substance:	8006619
Facility Contact:	Not reported
Interim:	Not reported
Oversite Program:	LUST
Latitude:	34.0703024
Longitude:	-117.3700508
MTBE Concentration:	0
MTBE Fuel:	1
MTBE Tested:	NT
Staff:	TME
Staff Initials:	CB5
Lead Agency:	Local Agency
Local Agency:	36000L
Hydr Basin #:	UPPER SANTA ANA VALL
Beneficial:	Not reported
Priority:	Not reported
Cleanup Fund Id:	Not reported
Work Suspended:	Not reported
Local Case Num:	92045
Case Number:	083602453T
Qty Leaked:	Not reported
Abate Method:	Not reported
MTBE Class:	*
Summary:	Site closed on April 28, 2000.

AG141 **RIALTO, CITY OF (TEXACO)** **LUST** **S101301260**
WSW **102 VALLEY BLVD** **Cortese** **N/A**
1/2-1 **RIALTO, CA 92376**
0.883 mi.
4663 ft. **Site 11 of 16 in cluster AG**

Relative:
Lower

Actual:
1064 ft.

LUST:

Region:	STATE
Case Type:	Soil only
Cross Street:	RIVERSIDE
Enf Type:	Not reported
Funding:	CLOS
How Discovered:	Tank Closure
How Stopped:	Not reported
Leak Cause:	UNK
Leak Source:	UNK
Global Id:	T0607100101
Stop Date:	1991-04-29 00:00:00
Confirm Leak:	1991-04-29 00:00:00
Workplan:	1992-01-28 00:00:00

RIALTO, CITY OF (TEXACO) (Continued) **S101301260**

Prelim Assess: Not reported
Pollution Char: Not reported
Remed Plan: Not reported
Remed Action: Not reported
Monitoring: Not reported
Close Date: 1992-08-25 00:00:00
Discover Date: 1991-04-29 00:00:00
Enforcement Dt: Not reported
Release Date: 1992-01-29 00:00:00
Review Date: 1992-02-18 00:00:00
Enter Date: 1992-02-11 00:00:00
MTBE Date: Not reported
GW Qualifier: Not reported
Soil Qualifier: Not reported
Max MTBE GW ppb: Not reported
Max MTBE Soil ppb: Not reported
County: 36
Org Name: Not reported
Reg Board: Santa Ana Region
Status: Case Closed
Chemical: Regular Gasoline
Contact Person: Not reported
Responsible Party: CITY OF RIALTO
RP Address: 150 S. PALM AVE RIALTO CA 92376
Interim: Not reported
Oversight Prgm: LUST
MTBE Class: *
MTBE Conc: 0
MTBE Fuel: 1
MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.
Staff: VJB
Staff Initials: DG4
Lead Agency: Local Agency
Local Agency: 36000L
Hydr Basin #: UPPER SANTA ANA VALL
Beneficial: Not reported
Priority: Not reported
Cleanup Fund Id: Not reported
Work Suspended: Not reported
Local Case #: 91033
Case Number: 083600955T
Qty Leaked: Not reported
Abate Method: Not reported
Operator: Not reported
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 0
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported
Summary: FORMER CAL TARGET ENTERPRISES SITE

LUST:
Region: 8
Case Type: Soil only
Cross Street: RIVERSIDE
Enf Type: CLOS
Funding: Not reported

RIALTO, CITY OF (TEXACO) (Continued) **S101301260**

How Discovered:	Tank Closure
How Stopped:	Not reported
Leak Cause:	UNK
Leak Source:	UNK
Global ID:	T0607100101
How Stopped Date:	4/29/1991
Review Date:	4/29/1991
Workplan:	1/28/1992
Prelim Assess:	Not reported
Pollution Char:	Not reported
Remed Plan:	Not reported
Remed Action:	Not reported
Monitoring:	Not reported
Close Date:	8/25/1992
Discover Date:	4/29/1991
Enforcement Date:	Not reported
Review Date:	2/18/1992
Enter Date:	2/11/1992
MTBE Date:	Not reported
GW Qualifies:	Not reported
Soil Qualifies:	Not reported
Max MTBE GW:	Not reported
Max MTBE Soil:	Not reported
County:	San Bernardino
Operator:	Not reported
Regional Board:	08
Facility Status:	Case Closed
Substance:	12032
Facility Contact:	Not reported
Interim:	Not reported
Oversite Program:	LUST
Latitude:	34.0705254
Longitude:	-117.3700108
MTBE Concentration:	0
MTBE Fuel:	1
MTBE Tested:	NT
Staff:	VJJ
Staff Initials:	DG4
Lead Agency:	Local Agency
Local Agency:	36000L
Hydr Basin #:	UPPER SANTA ANA VALL
Beneficial:	Not reported
Priority:	Not reported
Cleanup Fund Id:	Not reported
Work Suspended:	Not reported
Local Case Num:	91033
Case Number:	083600955T
Qty Leaked:	Not reported
Abate Method:	Not reported
MTBE Class:	*
Summary:	FORMER CAL TARGET ENTERPRISES SITE

Cortese:

Region:	CORTESE
Facility Addr2:	102 VALLEY BLVD

AG142 **ARCO #9695** **UST** **U003937821**
WSW **111 W VALLEY BLVD** **N/A**
1/2-1 **RIALTO, CA 92376**
0.890 mi.
4700 ft. **Site 12 of 16 in cluster AG**

Relative: UST:
Lower Local Agency: 36000
Facility ID: 86008454

Actual:
1063 ft.

AG143 **ARCO FACILITY NO 09695** **RCRA-SQG** **1004678016**
WSW **111 W VALLEY BLVD** **FINDS** **CAR000104000**
1/2-1 **RIALTO, CA 92376** **HAZNET**
0.890 mi.
4700 ft. **Site 13 of 16 in cluster AG**

Relative: RCRA-SQG:
Lower Date form received by agency: 07/10/2002
Facility name: ARCO FACILITY NO 09695
Actual: Facility address: 111 W VALLEY BLVD
1063 ft. RIALTO, CA 92376
EPA ID: CAR000104000
Mailing address: P O BOX 6038
ARTESIA, CA 907026038
Contact: JACK OMAN
Contact address: P O BOX 6038
ARTESIA, CA 907026038
Contact country: US
Contact telephone: (714) 690-2425
Contact email: Not reported
EPA Region: 09
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: B P W COAST PRODUCTS LLC
Owner/operator address: P O BOX 6038
ARTESIA, CA 90702
Owner/operator country: Not reported
Owner/operator telephone: (714) 690-2425
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: Unknown
Mixed waste (haz. and radioactive): Unknown
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: Unknown
Furnace exemption: Unknown
Used oil fuel burner: No

ARCO FACILITY NO 09695 (Continued) **1004678016**

Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No
Off-site waste receiver:	Commercial status unknown

Hazardous Waste Summary:

Waste code:	D000
Waste name:	Not Defined
Waste code:	D001
Waste name:	IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.
Waste code:	D018
Waste name:	BENZENE
Violation Status:	No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site

California - Hazardous Waste Tracking System - Datamart

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZNET:

Gepaid:	CAR000104000
Contact:	Jack Oman
Telephone:	7146902425
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	PO BOX 6038
Mailing City,St,Zip:	Artesia, CA 907026038
Gen County:	San Bernardino
TSD EPA ID:	Not reported
TSD County:	Los Angeles
Waste Category:	Other organic solids
Disposal Method:	Transfer Station
Tons:	0.10
Facility County:	Not reported

AG144 **ARCO #09695** **San Bern. Co. Permit** **S105698175**
WSW **111 W VALLEY BLVD** **N/A**
1/2-1 **RIALTO, CA 92376**
0.890 mi.
4700 ft. **Site 14 of 16 in cluster AG**

Relative:
Lower

Actual:
1063 ft.

San Bern. Co. Permit:

Region:	SAN BERNARDINO
Facility ID:	FA0001024
Owner:	BP WEST COAST PRODUCTS LLC
Permit Number:	PT0012210
Permit Category:	UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status:	ACTIVE
Expiration Date:	7/31/2008 12:00:00AM

Region:	SAN BERNARDINO
Facility ID:	FA0001024
Owner:	BP WEST COAST PRODUCTS LLC
Permit Number:	PT0012211
Permit Category:	UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status:	ACTIVE
Expiration Date:	7/31/2008 12:00:00AM

Region:	SAN BERNARDINO
Facility ID:	FA0001024
Owner:	BP WEST COAST PRODUCTS LLC
Permit Number:	PT0012209
Permit Category:	UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status:	ACTIVE
Expiration Date:	7/31/2008 12:00:00AM

Region:	SAN BERNARDINO
Facility ID:	FA0001024
Owner:	BP WEST COAST PRODUCTS LLC
Permit Number:	PT0002006
Permit Category:	HAZMAT HANDLER 0-10 EMPLOYEES (W/GEN PRMT)
Facility Status:	ACTIVE
Expiration Date:	7/31/2008 12:00:00AM

Region:	SAN BERNARDINO
Facility ID:	FA0001024
Owner:	BP WEST COAST PRODUCTS LLC
Permit Number:	PT0013702
Permit Category:	SPECIAL GENERATOR(B)
Facility Status:	ACTIVE
Expiration Date:	7/31/2008 12:00:00AM

Region:	SAN BERNARDINO
Facility ID:	FA0001024
Owner:	BP WEST COAST PRODUCTS LLC
Permit Number:	PT0012212
Permit Category:	UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status:	INACTIVE
Expiration Date:	7/31/2006 12:00:00AM

AG145 **ARCO STN. #323** **HAZNET U001575522**
WSW **111 W VALLEY BLVD** **HIST UST N/A**
1/2-1 **RIALTO, CA 92376**
0.890 mi.
4700 ft. **Site 15 of 16 in cluster AG**

Relative:
Lower

Actual:
1063 ft.

HAZNET:

Gepaid:	CAR000104000
Contact:	JACK OMAN WASTE SPECIALIST
Telephone:	7146703958
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	PO BOX 80249
Mailing City,St,Zip:	RCHO STA MARG, CA 926880000
Gen County:	San Bernardino
TSD EPA ID:	CAD008302903
TSD County:	Los Angeles
Waste Category:	Other organic solids
Disposal Method:	Transfer Station
Tons:	0.05
Facility County:	Not reported

Gepaid:	CAR000104000
Contact:	JACK OMAN WASTE SPECIALIST
Telephone:	7146703958
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	PO BOX 80249
Mailing City,St,Zip:	RCHO STA MARG, CA 926880000
Gen County:	San Bernardino
TSD EPA ID:	CAD008302903
TSD County:	Los Angeles
Waste Category:	Other organic solids
Disposal Method:	Transfer Station
Tons:	0.12
Facility County:	San Bernardino

Gepaid:	CAR000104000
Contact:	JACK OMAN WASTE SPECIALIST
Telephone:	7146703958
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	PO BOX 80249
Mailing City,St,Zip:	RCHO STA MARG, CA 926880000
Gen County:	San Bernardino
TSD EPA ID:	CAD008302903
TSD County:	Los Angeles
Waste Category:	Other organic solids
Disposal Method:	Transfer Station
Tons:	0.05
Facility County:	Not reported

Gepaid:	CAR000104000
Contact:	JACK OMAN WASTE SPECIALIST
Telephone:	7146703958
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	PO BOX 80249
Mailing City,St,Zip:	RCHO STA MARG, CA 926880000

ARCO STN. #323 (Continued) **U001575522**

Gen County: San Bernardino
TSD EPA ID: CAD008302903
TSD County: San Bernardino
Waste Category: Other organic solids
Disposal Method: Transfer Station
Tons: 0.09
Facility County: San Bernardino

Gepaid: CAR000104000
Contact: JACK OMAN WASTE SPECIALIST
Telephone: 7146703958
Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: PO BOX 80249
Mailing City,St,Zip: RCHO STA MARG, CA 926880000
Gen County: San Bernardino
TSD EPA ID: CAT080013352
TSD County: San Bernardino
Waste Category: Aqueous solution with less than 10% total organic residues
Disposal Method: Recycler
Tons: 0.25
Facility County: San Bernardino

Click this hyperlink while viewing on your computer to access additional CA_HAZNET: detail in the EDR Site Report.

HIST UST:
Region: STATE
Facility ID: 00000002500
Facility Type: Gas Station
Other Type: Not reported
Total Tanks: 0005
Contact Name: Not reported
Telephone: 2139239876
Owner Name: THRIFTY OIL CO.
Owner Address: 1000 LAKEWOOD BLVD.
Owner City,St,Zip: DOWNEY, CA 90240

Tank Num: 001
Container Num: 323-1
Year Installed: Not reported
Tank Capacity: 00008136
Tank Used for: PRODUCT
Type of Fuel: REGULAR
Tank Construction: 1/4 inches
Leak Detection: Stock Inventor

Tank Num: 002
Container Num: 323-2
Year Installed: 1981
Tank Capacity: 00015000
Tank Used for: PRODUCT
Type of Fuel: UNLEADED
Tank Construction: .267 inches
Leak Detection: Stock Inventor

Tank Num: 003

ARCO STN. #323 (Continued) **U001575522**

Container Num:	323-5
Year Installed:	Not reported
Tank Capacity:	00008136
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Tank Construction:	1/4 inches
Leak Detection:	Stock Inventor
Tank Num:	004
Container Num:	323-6
Year Installed:	Not reported
Tank Capacity:	00006259
Tank Used for:	PRODUCT
Type of Fuel:	REGULAR
Tank Construction:	1/4 inches
Leak Detection:	Stock Inventor
Tank Num:	005
Container Num:	323-10
Year Installed:	Not reported
Tank Capacity:	00000550
Tank Used for:	WASTE
Type of Fuel:	WASTE OIL
Tank Construction:	12 gauge
Leak Detection:	Stock Inventor

AG146 **THRIFTY OIL CO #323** **HAZNET S101591044**
WSW **111 W VALLEY** **CA FID UST N/A**
1/2-1 **RIALTO, CA 92376** **SWEEPS UST**
0.890 mi.
4700 ft. **Site 16 of 16 in cluster AG**

Relative:
Lower

Actual:
1063 ft.

HAZNET:

Gepaid:	CAL000225581
Contact:	CARLOS RODRIGUEZ
Telephone:	7146705402
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	PO BOX 6038
Mailing City,St,Zip:	ARTESIA, CA 907026038
Gen County:	San Bernardino
TSD EPA ID:	Not reported
TSD County:	Los Angeles
Waste Category:	Aqueous solution with less than 10% total organic residues
Disposal Method:	Recycler
Tons:	1.66
Facility County:	Not reported

CA FID UST:

Facility ID:	36000967
Regulated By:	UTNKA
Regulated ID:	00002500
Cortese Code:	Not reported
SIC Code:	Not reported
Facility Phone:	Not reported
Mail To:	Not reported
Mailing Address:	10000 LAKEWOOD BLVD

THRIFTY OIL CO #323 (Continued) **S101591044**

Mailing Address 2: Not reported
Mailing City,St,Zip: RIALTO 92376
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Active

SWEEPS UST:
Status: A
Comp Number: 2500
Number: 9
Board Of Equalization: 44-007386
Ref Date: 07-28-92
Act Date: 07-28-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 323-1
Swrcb Tank Id: 36-000-002500-000001
Actv Date: 08-25-88
Capacity: 8136
Tank Use: M.V. FUEL
Stg: P
Content: LEADED
Number Of Tanks: 5

Status: A
Comp Number: 2500
Number: 9
Board Of Equalization: 44-007386
Ref Date: 07-28-92
Act Date: 07-28-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 323-2
Swrcb Tank Id: 36-000-002500-000002
Actv Date: 08-25-88
Capacity: 15000
Tank Use: M.V. FUEL
Stg: P
Content: REG UNLEADED
Number Of Tanks: Not reported

Status: A
Comp Number: 2500
Number: 9
Board Of Equalization: 44-007386
Ref Date: 07-28-92
Act Date: 07-28-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 323-5
Swrcb Tank Id: 36-000-002500-000003
Actv Date: 08-25-88
Capacity: 8136

THRIFTY OIL CO #323 (Continued) **S101591044**

Tank Use: M.V. FUEL
Stg: P
Content: REG UNLEADED
Number Of Tanks: Not reported

Status: A
Comp Number: 2500
Number: 9
Board Of Equalization: 44-007386
Ref Date: 07-28-92
Act Date: 07-28-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 323-6
Swrcb Tank Id: 36-000-002500-000004
Actv Date: 08-25-88
Capacity: 6259
Tank Use: M.V. FUEL
Stg: P
Content: LEADED
Number Of Tanks: Not reported

Status: A
Comp Number: 2500
Number: 9
Board Of Equalization: 44-007386
Ref Date: 07-28-92
Act Date: 07-28-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 323-10
Swrcb Tank Id: 36-000-002500-000005
Actv Date: 08-25-88
Capacity: 550
Tank Use: OIL
Stg: W
Content: WASTE OIL
Number Of Tanks: Not reported

AH147 **DUNCAN BROS INC** **San Bern. Co. Permit** **S103368013**
SW **1966 S DATE** **N/A**
1/2-1 **RIALTO, CA 92376**
0.891 mi.
4704 ft. **Site 1 of 4 in cluster AH**

Relative:
Lower

Actual:
1037 ft.

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0002801
Owner: DUNCAN BROS INC
Permit Number: PT0004812
Permit Category: HAZMAT HANDLER 11-25 EMPLOYEES
Facility Status: ACTIVE
Expiration Date: 5/31/2008 12:00:00AM

AH148 **DUNCAN BROS INC** **FINDS 1005692322**
SW **1966 S DATE ST** **HAZNET 110006176315**
1/2-1 **BLOOMINGTON, CA 92316** **AIRS**
0.901 mi. **SWEEPS UST**
4758 ft. **Site 2 of 4 in cluster AH**

Relative: **Lower**

Actual: **1036 ft.**

FINDS:
Other Pertinent Environmental Activity Identified at Site

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

HAZNET:

Gepaid:	CAC002175257
Contact:	DUNCAN BROS INC
Telephone:	9098771904
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1966 S DATE ST
Mailing City,St,Zip:	BLOOMINGTON, CA 923160000
Gen County:	San Bernardino
TSD EPA ID:	CAD008252405
TSD County:	Los Angeles
Waste Category:	Off-specification, aged, or surplus organics
Disposal Method:	Recycler
Tons:	1.3
Facility County:	San Bernardino

Gepaid:	CAC002175257
Contact:	DUNCAN BROS INC
Telephone:	9098771904
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1966 S DATE ST
Mailing City,St,Zip:	BLOOMINGTON, CA 923160000
Gen County:	San Bernardino
TSD EPA ID:	CAD008252405
TSD County:	Los Angeles
Waste Category:	Unspecified organic liquid mixture
Disposal Method:	Not reported
Tons:	0
Facility County:	San Bernardino

EMI:

DUNCAN BROS INC (Continued) **1005692322**

Year:	1987
Carbon Monoxide Emissions Tons/Yr:	36
Air Basin:	SC
Facility ID:	50869
Air District Name:	SC
SIC Code:	3444
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	7
Reactive Organic Gases Tons/Yr:	6
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1990
Carbon Monoxide Emissions Tons/Yr:	36
Air Basin:	SC
Facility ID:	50869
Air District Name:	SC
SIC Code:	3599
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	11
Reactive Organic Gases Tons/Yr:	3
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1993
Carbon Monoxide Emissions Tons/Yr:	36
Air Basin:	SC
Facility ID:	50869
Air District Name:	SC
SIC Code:	3599
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	9
Reactive Organic Gases Tons/Yr:	5
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1995
Carbon Monoxide Emissions Tons/Yr:	36
Air Basin:	SC
Facility ID:	50869
Air District Name:	SC
SIC Code:	3599

DUNCAN BROS INC (Continued) **1005692322**

Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	9
Reactive Organic Gases Tons/Yr:	5
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1997
Carbon Monoxide Emissions Tons/Yr:	36
Air Basin:	SC
Facility ID:	50869
Air District Name:	SC
SIC Code:	3599
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	19
Reactive Organic Gases Tons/Yr:	13
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1998
Carbon Monoxide Emissions Tons/Yr:	36
Air Basin:	SC
Facility ID:	50869
Air District Name:	SC
SIC Code:	3599
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	19
Reactive Organic Gases Tons/Yr:	13
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1999
Carbon Monoxide Emissions Tons/Yr:	36
Air Basin:	SC
Facility ID:	50869
Air District Name:	SC
SIC Code:	3599
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	19
Reactive Organic Gases Tons/Yr:	13
Carbon Monoxide Emissions Tons/Yr:	0

DUNCAN BROS INC (Continued) **1005692322**

NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0
Year:	2000
Carbon Monoxide Emissions Tons/Yr:	36
Air Basin:	SC
Facility ID:	50869
Air District Name:	SC
SIC Code:	3599
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	19
Reactive Organic Gases Tons/Yr:	13
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0
Year:	2001
Carbon Monoxide Emissions Tons/Yr:	36
Air Basin:	SC
Facility ID:	50869
Air District Name:	SC
SIC Code:	3599
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	8
Reactive Organic Gases Tons/Yr:	7
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0
Year:	2002
Carbon Monoxide Emissions Tons/Yr:	36
Air Basin:	SC
Facility ID:	50869
Air District Name:	SC
SIC Code:	3599
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	5
Reactive Organic Gases Tons/Yr:	5
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0
Year:	2003

DUNCAN BROS INC (Continued) **1005692322**

Carbon Monoxide Emissions Tons/Yr:	36
Air Basin:	SC
Facility ID:	50869
Air District Name:	SC
SIC Code:	3599
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	5
Reactive Organic Gases Tons/Yr:	5
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	2004
Carbon Monoxide Emissions Tons/Yr:	36
Air Basin:	SC
Facility ID:	50869
Air District Name:	SC
SIC Code:	3599
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	5.21056
Reactive Organic Gases Tons/Yr:	5.15
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	2005
Carbon Monoxide Emissions Tons/Yr:	36
Air Basin:	SC
Facility ID:	50869
Air District Name:	SC
SIC Code:	3599
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.8003
Reactive Organic Gases Tons/Yr:	1.77851637
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

SWEEPS UST:

Status:	A
Comp Number:	54092
Number:	9
Board Of Equalization:	Not reported
Ref Date:	03-19-92
Act Date:	03-19-92

DUNCAN BROS INC (Continued) **1005692322**

Created Date:	02-29-88
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	Not reported
Actv Date:	Not reported
Capacity:	Not reported
Tank Use:	Not reported
Stg:	Not reported
Content:	Not reported
Number Of Tanks:	Not reported

AH149 **DUNCAN BROS., INC.** **HIST UST** **U001574572**
SW **1966 S DATE AVE** **San Bern. Co. Permit** **N/A**
1/2-1 **BLOOMINGTON, CA 92316**
0.901 mi.
4760 ft. **Site 3 of 4 in cluster AH**

Relative:
Lower

Actual:
1036 ft.

HIST UST:

Region:	STATE
Facility ID:	00000054092
Facility Type:	Other
Other Type:	STEEL FABRICATION
Total Tanks:	0001
Contact Name:	MICHAEL DUNCAN
Telephone:	7148771904
Owner Name:	CECIL D. OR CAROLYN L. DUNCAN
Owner Address:	1966 S. DATE ST.
Owner City,St,Zip:	BLOOMINGTON, CA 92316
Tank Num:	001
Container Num:	1
Year Installed:	Not reported
Tank Capacity:	00001000
Tank Used for:	PRODUCT
Type of Fuel:	DIESEL
Tank Construction:	10 gauge
Leak Detection:	Stock Inventor

San Bern. Co. Permit:

Region:	SAN BERNARDINO
Facility ID:	FA0005665
Owner:	GILSON, JERRY
Permit Number:	PT0000419
Permit Category:	SPECIAL GENERATOR(B)
Facility Status:	ACTIVE
Expiration Date:	4/30/2008 12:00:00AM
Region:	SAN BERNARDINO
Facility ID:	FA0005665
Owner:	GILSON, JERRY
Permit Number:	PT0000420
Permit Category:	SPECIAL HANDLER
Facility Status:	ACTIVE
Expiration Date:	4/30/2008 12:00:00AM

AI150 **THRIFTY OIL #323/ ARCO #9695** **LUST** **S103464083**
WSW **111 VALLEY BLVD** **N/A**
1/2-1 **RIALTO, CA 92376**
0.904 mi.
4774 ft. **Site 1 of 5 in cluster AI**

Relative:
Lower

Actual:
1053 ft.

LUST:

Region:	STATE
Case Type:	Soil only
Cross Street:	RIVERSIDE
Enf Type:	Not reported
Funding:	Not reported
How Discovered:	Not reported
How Stopped:	Not reported
Leak Cause:	Not reported
Leak Source:	Not reported
Global Id:	T0607100519
Stop Date:	Not reported
Confirm Leak:	Not reported
Workplan:	Not reported
Prelim Assess:	1965-01-01 00:00:00
Pollution Char:	Not reported
Remed Plan:	Not reported
Remed Action:	Not reported
Monitoring:	Not reported
Close Date:	Not reported
Discover Date:	1997-12-29 00:00:00
Enforcement Dt:	Not reported
Release Date:	1998-04-29 00:00:00
Review Date:	1998-11-06 00:00:00
Enter Date:	1998-11-06 00:00:00
MTBE Date:	Not reported
GW Qualifier:	Not reported
Soil Qualifier:	Not reported
Max MTBE GW ppb:	Not reported
Max MTBE Soil ppb:	Not reported
County:	36
Org Name:	Not reported
Reg Board:	Santa Ana Region
Status:	Preliminary site assessment underway
Chemical:	8006619, MTB
Contact Person:	Not reported
Responsible Party:	THRIFTY OIL CO.
RP Address:	13539 E. FOSTER RD., SANTA FE SPRINGS
Interim:	Not reported
Oversight Prgm:	LUST
MTBE Class:	*
MTBE Conc:	0
MTBE Fuel:	0
MTBE Tested:	MTBE Detected. Site tested for MTBE and MTBE detected
Staff:	VJB
Staff Initials:	LH6
Lead Agency:	Local Agency
Local Agency:	36000L
Hydr Basin #:	UPPER SANTA ANA VALL
Beneficial:	MUN
Priority:	A2
Cleanup Fund Id:	Not reported
Work Suspended:	Not reported

THRIFTY OIL #323/ ARCO #9695 (Continued) **S103464083**

Local Case #: 98096
Case Number: 083603296T
Qty Leaked: Not reported
Abate Method: Not reported
Operator: Not reported
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 0
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported
Summary: Not reported

LUST:
Region: 8
Case Type: Soil only
Cross Street: RIVERSIDE
Enf Type: Not reported
Funding: Not reported
How Discovered: Not reported
How Stopped: Not reported
Leak Cause: Not reported
Leak Source: Not reported
Global ID: T0607100519
How Stopped Date: Not reported
Review Date: Not reported
Workplan: Not reported
Prelim Assess: 1/1/1965
Pollution Char: Not reported
Remed Plan: Not reported
Remed Action: Not reported
Monitoring: Not reported
Close Date: Not reported
Discover Date: 12/29/1997
Enforcement Date: Not reported
Review Date: 11/6/1998
Enter Date: 11/6/1998
MTBE Date: 11/15/2001
GW Qualifies: =
Soil Qualifies: =
Max MTBE GW: 2.2
Max MTBE Soil: 10300
County: San Bernardino
Operator: Not reported
Regional Board: 08
Facility Status: Preliminary site assessment underway
Substance: 8006619, MTB
Facility Contact: Not reported
Interim: Not reported
Oversite Program: LUST
Latitude: 34.0703134
Longitude: -117.3703439
MTBE Concentration: 0
MTBE Fuel: 0
MTBE Tested: YES
Staff: VJJ
Staff Initials: LH6
Lead Agency: Local Agency

AI152 **VALLEY ANIMAL HOSPITAL** **HAZNET S102818483**
WSW **127 W VALLEY BLVD** **San Bern. Co. Permit N/A**
1/2-1 **RIALTO, CA 92376**
0.909 mi.
4802 ft. **Site 2 of 5 in cluster AI**

Relative:
Lower

Actual:
1062 ft.

HAZNET:

Gepaid:	CAL000106539
Contact:	KENNETH COX
Telephone:	9098732384
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	127 W VALLEY BLVD
Mailing City,St,Zip:	RIALTO, CA 923760000
Gen County:	San Bernardino
TSD EPA ID:	CAD983604000
TSD County:	San Bernardino
Waste Category:	Photochemicals/photoprocessing waste
Disposal Method:	Recycler
Tons:	.0625
Facility County:	San Bernardino

Gepaid:	CAL000106539
Contact:	KENNETH COX
Telephone:	9098732384
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	127 W VALLEY BLVD
Mailing City,St,Zip:	RIALTO, CA 923760000
Gen County:	San Bernardino
TSD EPA ID:	CAD983604000
TSD County:	San Bernardino
Waste Category:	Photochemicals/photoprocessing waste
Disposal Method:	Recycler
Tons:	.0834
Facility County:	San Bernardino

San Bern. Co. Permit:

Region:	SAN BERNARDINO
Facility ID:	FA0011224
Owner:	BUFFETS, INC.
Permit Number:	PT0019535
Permit Category:	BULK CO2 AT RETAIL FOOD FACILITIES
Facility Status:	ACTIVE
Expiration Date:	12/31/2007 12:00:00AM

AI153 **TEXACO SERVICE STATION** **LUST S102438785**
WSW **120 VALLEY BLVD** **Cortese N/A**
1/2-1 **RIALTO, CA 92376**
0.911 mi.
4812 ft. **Site 3 of 5 in cluster AI**

Relative:
Lower

Actual:
1062 ft.

LUST:

Region:	STATE
Case Type:	Soil only
Cross Street:	RIVERSIDE
Enf Type:	Not reported
Funding:	CLOS
How Discovered:	OM

TEXACO SERVICE STATION (Continued) **S102438785**

How Stopped:	Not reported
Leak Cause:	UNK
Leak Source:	UNK
Global Id:	T0607100424
Stop Date:	Not reported
Confirm Leak:	1990-12-11 00:00:00
Workplan:	Not reported
Prelim Assess:	Not reported
Pollution Char:	1996-09-10 00:00:00
Remed Plan:	Not reported
Remed Action:	Not reported
Monitoring:	Not reported
Close Date:	1997-03-05 00:00:00
Discover Date:	1990-12-11 00:00:00
Enforcement Dt:	Not reported
Release Date:	1996-09-04 00:00:00
Review Date:	Not reported
Enter Date:	1996-09-19 00:00:00
MTBE Date:	Not reported
GW Qualifier:	Not reported
Soil Qualifier:	Not reported
Max MTBE GW ppb:	Not reported
Max MTBE Soil ppb:	Not reported
County:	36
Org Name:	Not reported
Reg Board:	Santa Ana Region
Status:	Case Closed
Chemical:	Waste Oil
Contact Person:	Not reported
Responsible Party:	CITY OF RIALTO
RP Address:	150 S. PALM, RIALTO, CA 92376
Interim:	Not reported
Oversight Prgm:	LUST
MTBE Class:	*
MTBE Conc:	0
MTBE Fuel:	0
MTBE Tested:	Not Required to be Tested.
Staff:	RS
Staff Initials:	BM7
Lead Agency:	Local Agency
Local Agency:	36000L
Hydr Basin #:	UPPER SANTA ANA VALL
Beneficial:	Not reported
Priority:	Not reported
Cleanup Fund Id:	Not reported
Work Suspended:	Not reported
Local Case #:	96045
Case Number:	083602887T
Qty Leaked:	Not reported
Abate Method:	Excavate and Treat - remove contaminated soil and treat (includes spreading or land farming)
Operator:	Not reported
Water System Name:	Not reported
Well Name:	Not reported
Distance To Lust:	0
Waste Discharge Global ID:	Not reported
Waste Disch Assigned Name:	Not reported

TEXACO SERVICE STATION (Continued) **S102438785**

Summary: Not reported

LUST:

Region:	8
Case Type:	Soil only
Cross Street:	RIVERSIDE
Enf Type:	CLOS
Funding:	Not reported
How Discovered:	OM
How Stopped:	Not reported
Leak Cause:	UNK
Leak Source:	UNK
Global ID:	T0607100424
How Stopped Date:	Not reported
Review Date:	12/11/1990
Workplan:	Not reported
Prelim Assess:	Not reported
Pollution Char:	9/10/1996
Remed Plan:	Not reported
Remed Action:	Not reported
Monitoring:	Not reported
Close Date:	3/5/1997
Discover Date:	12/11/1990
Enforcement Date:	Not reported
Review Date:	Not reported
Enter Date:	9/19/1996
MTBE Date:	Not reported
GW Qualifies:	Not reported
Soil Qualifies:	Not reported
Max MTBE GW:	Not reported
Max MTBE Soil:	Not reported
County:	San Bernardino
Operator:	Not reported
Regional Board:	08
Facility Status:	Case Closed
Substance:	12035
Facility Contact:	Not reported
Interim:	Not reported
Oversite Program:	LUST
Latitude:	34.0705584
Longitude:	-117.3698618
MTBE Concentration:	0
MTBE Fuel:	0
MTBE Tested:	NRQ
Staff:	RS
Staff Initials:	BM7
Lead Agency:	Local Agency
Local Agency:	36000L
Hydr Basin #:	UPPER SANTA ANA VALL
Beneficial:	Not reported
Priority:	Not reported
Cleanup Fund Id:	Not reported
Work Suspended:	Not reported
Local Case Num:	96045
Case Number:	083602887T
Qty Leaked:	Not reported
Abate Method:	Excavate and Treat - remove contaminated soil and treat (includes

TEXACO SERVICE STATION (Continued) **S102438785**

spreading or land farming)
MTBE Class: *
Summary: Not reported

Cortese:
Region: CORTESE
Facility Addr2: 120 VALLEY BLVD

AJ154 **COLTON TERMINAL** **HIST UST** **U001574659**
SW **1901 SLOVER AVENUE** **N/A**
1/2-1 **COLTON, CA 92324**
0.917 mi.
4840 ft. **Site 1 of 2 in cluster AJ**

Relative:
Lower

Actual:
1043 ft.

HIST UST:
Region: STATE
Facility ID: 00000020392
Facility Type: Other
Other Type: PIPELINE TERMINAL
Total Tanks: 0005
Contact Name: HAROLD MOYE
Telephone: 7148772414
Owner Name: CALNEV PIPE LINE COMPANY
Owner Address: 412 HOSPITALITY LANE
Owner City,St,Zip: SAN BERNARDINO, CA 92408

Tank Num: 001
Container Num: CU-01
Year Installed: Not reported
Tank Capacity: 00001000
Tank Used for: PRODUCT
Type of Fuel: Not reported
Tank Construction: Not reported
Leak Detection: Visual

Tank Num: 002
Container Num: CU-02
Year Installed: Not reported
Tank Capacity: 00010000
Tank Used for: PRODUCT
Type of Fuel: REGULAR
Tank Construction: Not reported
Leak Detection: Visual

Tank Num: 003
Container Num: CU-03
Year Installed: Not reported
Tank Capacity: 00003000
Tank Used for: PRODUCT
Type of Fuel: 06
Tank Construction: Not reported
Leak Detection: Visual, Stock Inventor

Tank Num: 004
Container Num: CU-06
Year Installed: 1985
Tank Capacity: 00005000

COLTON TERMINAL (Continued) **U001574659**

Tank Used for: PRODUCT
Type of Fuel: Not reported
Tank Construction: 250 2 inches
Leak Detection: None

Tank Num: 005
Container Num: CU-07
Year Installed: 1985
Tank Capacity: 00005000
Tank Used for: PRODUCT
Type of Fuel: Not reported
Tank Construction: .250 inches
Leak Detection: None

AJ155 **SANTA FE PACIFIC PIPE LINE** **SLIC** **S101541259**
SW **2720 SLOVER** **N/A**
1/2-1 **COLTON, CA**
0.917 mi.
4841 ft. **Site 2 of 2 in cluster AJ**

Relative: **Lower**

Actual: **1043 ft.**

SLIC:
Region: STATE
Global Id: SLT8R1754101
Assigned Name: SLICSITE
Lead Agency Contact: Not reported
Lead Agency: Not reported
Lead Agency Case Number: Not reported
Responsible Party: Not reported
Recent Dtw: Not reported
Substance Released: Not reported
Facility Status: Not reported

---

156 **CIRCLE K #627** **HAZNET** **S103956583**
ESE **990 VALLEY BLVD** **SWEEPS UST** **N/A**
1/2-1 **COLTON, CA 92324**
0.924 mi.
4881 ft.

Relative: **Lower**

Actual: **1016 ft.**

HAZNET:
Gepaid: CAD981679590
Contact: TOSCO MARKETING
Telephone: 6027284180
Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: P O BOX 52085
Mailing City,St,Zip: PHOENIX, AZ 850722085
Gen County: San Bernardino
TSD EPA ID: CAD099452708
TSD County: Los Angeles
Waste Category: Tank bottom waste
Disposal Method: Recycler
Tons: .1251
Facility County: San Bernardino

Gepaid: CAD981679590
Contact: TOSCO MARKETING

CIRCLE K #627 (Continued) **S103956583**

Telephone:	6027284180
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	P O BOX 52085
Mailing City,St,Zip:	PHOENIX, AZ 850722085
Gen County:	San Bernardino
TSD EPA ID:	CAD028409019
TSD County:	Los Angeles
Waste Category:	Waste oil and mixed oil
Disposal Method:	Recycler
Tons:	1.0633
Facility County:	San Bernardino

SWEEPS UST:

Status:	A
Comp Number:	13599
Number:	9
Board Of Equalization:	44-020476
Ref Date:	07-28-92
Act Date:	07-28-92
Created Date:	02-29-88
Tank Status:	A
Owner Tank Id:	1
Swrcb Tank Id:	36-000-013599-000001
Actv Date:	07-01-85
Capacity:	9940
Tank Use:	M.V. FUEL
Stg:	P
Content:	LEADED
Number Of Tanks:	2

Status:	A
Comp Number:	13599
Number:	9
Board Of Equalization:	44-020476
Ref Date:	07-28-92
Act Date:	07-28-92
Created Date:	02-29-88
Tank Status:	A
Owner Tank Id:	2
Swrcb Tank Id:	36-000-013599-000002
Actv Date:	07-01-85
Capacity:	9940
Tank Use:	M.V. FUEL
Stg:	P
Content:	REG UNLEADED
Number Of Tanks:	Not reported

AI157 **PAUL HUBBS CONSTRUCTION CO.** **CA FID UST** **S101619402**
WSW **140 W VALLEY BLVD** **AIRS** **N/A**
1/2-1 **RIALTO, CA 92376** **SWEEPS UST**
0.932 mi.
4924 ft. **Site 4 of 5 in cluster AI**

Relative:
Lower

Actual:
1061 ft.

CA FID UST:

Facility ID:	36002127
Regulated By:	UTNKI
Regulated ID:	00035560
Cortese Code:	Not reported
SIC Code:	Not reported
Facility Phone:	Not reported
Mail To:	Not reported
Mailing Address:	140 W VALLEY BLVD
Mailing Address 2:	Not reported
Mailing City,St,Zip:	RIALTO 92376
Contact:	Not reported
Contact Phone:	Not reported
DUNs Number:	Not reported
NPDES Number:	Not reported
EPA ID:	Not reported
Comments:	Not reported
Status:	Inactive

EMI:

Year:	1990
Carbon Monoxide Emissions Tons/Yr:	36
Air Basin:	SC
Facility ID:	30510
Air District Name:	SC
SIC Code:	0
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	1
NOX - Oxides of Nitrogen Tons/Yr:	2
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

SWEEPS UST:

Status:	Not reported
Comp Number:	35560
Number:	Not reported
Board Of Equalization:	44-020912
Ref Date:	Not reported
Act Date:	Not reported
Created Date:	Not reported
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	36-000-035560-000001
Actv Date:	Not reported
Capacity:	10000
Tank Use:	M.V. FUEL
Stg:	PRODUCT

PAUL HUBBS CONSTRUCTION CO. (Continued) **S101619402**

Content: DIESEL
Number Of Tanks: 5

Status: Not reported
Comp Number: 35560
Number: Not reported
Board Of Equalization: 44-020912
Ref Date: Not reported
Act Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 36-000-035560-000002
Actv Date: Not reported
Capacity: 6000
Tank Use: M.V. FUEL
Stg: PRODUCT
Content: DIESEL
Number Of Tanks: Not reported

Status: Not reported
Comp Number: 35560
Number: Not reported
Board Of Equalization: 44-020912
Ref Date: Not reported
Act Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 36-000-035560-000003
Actv Date: Not reported
Capacity: 4000
Tank Use: M.V. FUEL
Stg: PRODUCT
Content: LEADED
Number Of Tanks: Not reported

Status: Not reported
Comp Number: 35560
Number: Not reported
Board Of Equalization: 44-020912
Ref Date: Not reported
Act Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 36-000-035560-000004
Actv Date: Not reported
Capacity: 4000
Tank Use: M.V. FUEL
Stg: PRODUCT
Content: LEADED
Number Of Tanks: Not reported

Status: Not reported
Comp Number: 35560
Number: Not reported

PAUL HUBBS CONSTRUCTION CO. (Continued) **S101619402**

Board Of Equalization:	44-020912
Ref Date:	Not reported
Act Date:	Not reported
Created Date:	Not reported
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	36-000-035560-000005
Actv Date:	Not reported
Capacity:	4000
Tank Use:	M.V. FUEL
Stg:	PRODUCT
Content:	LEADED
Number Of Tanks:	Not reported

AI158 **PAUL HUBBS CONSTRUCTION CO.** **HIST UST** **U001575550**
WSW **140 W VALLEY BLVD** **N/A**
1/2-1 **RIALTO, CA 92376**
0.932 mi.
4924 ft. **Site 5 of 5 in cluster AI**

Relative:
Lower

Actual:
1061 ft.

HIST UST:

Region:	STATE
Facility ID:	00000035560
Facility Type:	Other
Other Type:	CONSTRUCTION YARD
Total Tanks:	0004
Contact Name:	JAY HUBBS
Telephone:	7148772726
Owner Name:	PAUL J. HUBBS
Owner Address:	140 WEST VALLEY BLVD.
Owner City,St,Zip:	RIALTO, CA 92376
Tank Num:	001
Container Num:	1
Year Installed:	1964
Tank Capacity:	00010000
Tank Used for:	PRODUCT
Type of Fuel:	DIESEL
Tank Construction:	Not reported
Leak Detection:	Vapor Sniff Well
Tank Num:	002
Container Num:	2
Year Installed:	1964
Tank Capacity:	00006000
Tank Used for:	PRODUCT
Type of Fuel:	DIESEL
Tank Construction:	Not reported
Leak Detection:	Vapor Sniff Well
Tank Num:	003
Container Num:	3
Year Installed:	1964
Tank Capacity:	00004000
Tank Used for:	PRODUCT
Type of Fuel:	REGULAR
Tank Construction:	Not reported
Leak Detection:	Vapor Sniff Well

PAUL HUBBS CONSTRUCTION CO. (Continued) **U001575550**

Tank Num: 004
Container Num: 4
Year Installed: 1964
Tank Capacity: 00004000
Tank Used for: PRODUCT
Type of Fuel: REGULAR
Tank Construction: Not reported
Leak Detection: Vapor Sniff Well

159
East
1/2-1
0.951 mi.
5019 ft.

DALE JONES PHOTOGRAPHY
915 W C ST
COLTON, CA 92324

RCRA-SQG **1000197253**
FINDS **CAD982483729**
HAZNET

Relative:
Lower

Actual:
1034 ft.

RCRA-SQG:
Date form received by agency: 03/09/1990
Facility name: DALE JONES PHOTOGRAPHY
Facility address: 915 W C ST
COLTON, CA 92324
EPA ID: CAD982483729
Mailing address: 785 N LA CADENA SUITE A
COLTON, CA 92324
Contact: ENVIRONMENTAL MANAGER
Contact address: 915 W C ST
COLTON, CA 92324
Contact country: US
Contact telephone: (714) 825-6516
Contact email: Not reported
EPA Region: 09
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: DALE JONES
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

DALE JONES PHOTOGRAPHY (Continued) **1000197253**

Handler Activities Summary:

U.S. importer of hazardous waste:	Unknown
Mixed waste (haz. and radioactive):	Unknown
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	Unknown
Furnace exemption:	Unknown
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No
Off-site waste receiver:	Commercial status unknown

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZNET:

Gepaid:	CAD982483729
Contact:	Not reported
Telephone:	0000000000
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	785 N LA CADENA #A
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	San Bernardino
TSD EPA ID:	CAD108040858
TSD County:	Los Angeles
Waste Category:	Photochemicals/photoprocessing waste
Disposal Method:	Recycler
Tons:	.2501
Facility County:	San Bernardino

AK160 **COLTON TERMINAL** **HIST UST U001575531**
SW **271 E. SLOVER AVENUE** **CA WDS N/A**
1/2-1 **RIALTO, CA 92376**
0.961 mi.
5073 ft. **Site 1 of 4 in cluster AK**

Relative:
Lower

Actual:
1039 ft.

HIST UST:

Region:	STATE
Facility ID:	00000008220
Facility Type:	Other

COLTON TERMINAL (Continued) **U001575531**

Other Type: PRODUCT TERMINAL
Total Tanks: 0002
Contact Name: B.G. HAZLEWOOD
Telephone: 7148771666
Owner Name: TOSCO CORPORATION
Owner Address: 2401 COLORADO AVENUE
Owner City,St,Zip: SANTA MONICA, CA 90406

Tank Num: 001
Container Num: 201
Year Installed: 1972
Tank Capacity: 00000600
Tank Used for: WASTE
Type of Fuel: DIESEL
Tank Construction: 3/16 inches
Leak Detection: None

Tank Num: 002
Container Num: 202
Year Installed: 1972
Tank Capacity: 00000550
Tank Used for: WASTE
Type of Fuel: DIESEL
Tank Construction: 3/16 centimeters
Leak Detection: None

CA WDS:
Facility ID: Santa Ana River 36I006067
Facility Type: Industrial - Facility that treats and/or disposes of liquid or semisolid wastes from any servicing, producing, manufacturing or processing operation of whatever nature, including mining, gravel washing, geothermal operations, air conditioning, ship building and repairing, oil production, storage and disposal operations, water pumping.
Facility Status: Active - Any facility with a continuous or seasonal discharge that is under Waste Discharge Requirements.
NPDES Number: CAS000001 The 1st 2 characters designate the state. The remaining 7 are assigned by the Regional Board
Subregion: 8
Facility Telephone: Not reported
Facility Contact: HENRY JOHNSON
Agency Name: TOSCO CORPORATION
Agency Address: PO BOX 2628
Agency City,St,Zip: SANTA FE SPRINGS 90670
Agency Contact: HENRY JOHNSON
Agency Telephone: Not reported
Agency Type: Private
SIC Code: 9999
SIC Code 2: Not reported
Primary Waste: Stormwater Runoff
Primary Waste Type: Designated/Influent or Solid Wastes that pose a significant threat to water quality because of their high concentrations (E.G., BOD, Hardness, TRF, Chloride). 'Manageable' hazardous wastes (E.G., inorganic salts and heavy metals) are included in this category.
Secondary Waste: Not reported
Secondary Waste Type: Not reported
Design Flow: 0

COLTON TERMINAL (Continued) **U001575531**

Baseline Flow: 0
Reclamation: No reclamation requirements associated with this facility.
POTW: The facility is not a POTW.
Treat To Water: Minor Threat to Water Quality. A violation of a regional board order should cause a relatively minor impairment of beneficial uses compared to a major or minor threat. Not: All nurds without a TTWQ will be considered a minor threat to water quality unless coded at a higher Level. A Zero (0) may be used to code those NURDS that are found to represent no threat to water quality.
Complexity: Category C - Facilities having no waste treatment systems, such as cooling water dischargers or thosewho must comply through best management practices, facilities with passive waste treatment and disposal systems, such as septic systems with subsurface disposal, or dischargers having waste storage systems with land disposal such as dairy waste ponds.

AK161 **COLTON TERMINAL, EAST** **AST** **A100225868**
SW **271 E. SLOVER AVE.** **N/A**
1/2-1 **RIALTO, CA 92376**
0.961 mi.
5073 ft. **Site 2 of 4 in cluster AK**

Relative: **Lower**

Actual: **1039 ft.**

AST:
Owner: TOSCO REFINING COMPANY
Total Gallons: 3163600

AK162 **CONOCO PHILLIPS COLTON TERMINAL EAST** **RCRA-SQG** **1006805684**
SW **271 E SLOVER AVE** **FINDS** **CAR000131086**
1/2-1 **RIALTO, CA 92376** **HAZNET**
0.961 mi.
5073 ft. **Site 3 of 4 in cluster AK**

Relative: **Lower**

Actual: **1039 ft.**

RCRA-SQG:
Date form received by agency: 01/15/2003
Facility name: CONOCO PHILLIPS COLTON TERMINAL EAST
Facility address: 271 E SLOVER AVE
RIALTO, CA 92376
EPA ID: CAR000131086
Mailing address: S RIVERSIDE AVE
BLOOMINGTON, CA 92316
Contact: DON KNABE
Contact address: S RIVERSIDE AVE
BLOOMINGTON, CA 92316
Contact country: US
Contact telephone: (909) 877-6500
Contact email: Not reported
EPA Region: 09
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: CONOCO PHILLIPS

CONOCO PHILLIPS COLTON TERMINAL EAST (Continued) **1006805684**

Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/2003
Owner/Op end date: Not reported

Owner/operator name: CONOCO PHILLIPS
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/01/2003
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No
Off-site waste receiver: Commercial status unknown

Hazardous Waste Summary:
Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D008
Waste name: LEAD

Waste code: D018
Waste name: BENZENE

Violation Status: No violations found

FINDS:
Other Pertinent Environmental Activity Identified at Site

CONOCO PHILLIPS COLTON TERMINAL EAST (Continued) **1006805684**

California - Hazardous Waste Tracking System - Datamart

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZNET:

Gepaid:	CAR000131086
Contact:	DAN KNABE/EX: 2
Telephone:	9098776500
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	2301 S RIVERSIDE AVE
Mailing City,St,Zip:	BLOOMINGTON, CA 923160000
Gen County:	San Bernardino
TSD EPA ID:	CAD982444481
TSD County:	San Bernardino
Waste Category:	Other organic solids
Disposal Method:	Not reported
Tons:	0.09
Facility County:	Not reported

AK163 **CONOCO COLTON TERMINAL - EAST YARD** **SLIC** **S108543182**
SW **271 E. SLOVER AVE** **N/A**
1/2-1 **BLOOMINGTON, CA 92316**
0.961 mi.
5073 ft. **Site 4 of 4 in cluster AK**

Relative:
Lower

Actual:
1039 ft.

SLIC:

Region:	STATE
Global Id:	SL0607169415
Assigned Name:	SLICSITE
Lead Agency Contact:	ROSE SCOTT
Lead Agency:	SANTA ANA RWQCB (REGION 8)
Lead Agency Case Number:	Not reported
Responsible Party:	Not reported
Recent Dtw:	Not reported
Substance Released:	8006619, NOT_SELECTED
Facility Status:	**Verification Monitoring Underway**

AL164 **RIALTO RUBBISH SERVICES INC** San Bern. Co. Permit S103369213
SW **210 E CAMERON WAY** N/A
1/2-1 **RIALTO, CA 92376**
0.986 mi.
5208 ft. **Site 1 of 2 in cluster AL**

Relative: **Lower**

Actual: **1028 ft.**

San Bern. Co. Permit:

Region:	SAN BERNARDINO
Facility ID:	FA0005700
Owner:	EDCO DISPOSAL CORP
Permit Number:	PT0002092
Permit Category:	SPECIAL HANDLER
Facility Status:	ACTIVE
Expiration Date:	5/31/2008 12:00:00AM

Region:	SAN BERNARDINO
Facility ID:	FA0005700
Owner:	EDCO DISPOSAL CORP
Permit Number:	PT0002091
Permit Category:	SPECIAL GENERATOR(B)
Facility Status:	ACTIVE
Expiration Date:	5/31/2008 12:00:00AM

AL165 **RIALTO RUBBISH** HAZNET S103641202
SW **210 E CAMERON** SWEEPS UST N/A
1/2-1 **BLOOMINGTON, CA 92316**
0.986 mi.
5208 ft. **Site 2 of 2 in cluster AL**

Relative: **Lower**

Actual: **1028 ft.**

HAZNET:

Gepaid:	CAD096106711
Contact:	ED BURR/PARTNER
Telephone:	0000000000
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	6670 FEDERAL BLVD
Mailing City,St,Zip:	LEMON GROVE, CA 919451312
Gen County:	San Bernardino
TSD EPA ID:	AZC000000150
TSD County:	99
Waste Category:	Other organic solids
Disposal Method:	Not reported
Tons:	7.0958
Facility County:	San Bernardino

Gepaid:	CAD096106711
Contact:	ED BURR/PARTNER
Telephone:	0000000000
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	6670 FEDERAL BLVD
Mailing City,St,Zip:	LEMON GROVE, CA 919451312
Gen County:	San Bernardino
TSD EPA ID:	AZC000000150
TSD County:	99
Waste Category:	Other organic solids
Disposal Method:	Not reported
Tons:	4.2000
Facility County:	San Bernardino

RIALTO RUBBISH (Continued) **S103641202**

Gepaid:	CAD096106711
Contact:	ED BURR/PARTNER
Telephone:	0000000000
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	6670 FEDERAL BLVD
Mailing City,St,Zip:	LEMON GROVE, CA 919451312
Gen County:	San Bernardino
TSD EPA ID:	CAD093459485
TSD County:	Fresno
Waste Category:	Unspecified solvent mixture Waste
Disposal Method:	Transfer Station
Tons:	.0166
Facility County:	San Bernardino

SWEEPS UST:

Status:	A
Comp Number:	6636
Number:	9
Board Of Equalization:	44-019933
Ref Date:	03-19-92
Act Date:	03-19-92
Created Date:	02-29-88
Tank Status:	A
Owner Tank Id:	17
Swrcb Tank Id:	36-000-006636-000001
Actv Date:	08-25-88
Capacity:	10000
Tank Use:	M.V. FUEL
Stg:	P
Content:	DIESEL
Number Of Tanks:	2

Status:	A
Comp Number:	6636
Number:	9
Board Of Equalization:	44-019933
Ref Date:	03-19-92
Act Date:	03-19-92
Created Date:	02-29-88
Tank Status:	A
Owner Tank Id:	18
Swrcb Tank Id:	36-000-006636-000002
Actv Date:	08-25-88
Capacity:	1000
Tank Use:	M.V. FUEL
Stg:	P
Content:	REG UNLEADED
Number Of Tanks:	Not reported

166
West
> 1
1.013 mi.
5347 ft.

CLEM TRANS INC
213 VALLEY BLVD.
RIALTO, CA 92376

LUST **S105050725**
N/A

Relative:
Lower

Actual:
1060 ft.

LUST:

Region:	STATE
Case Type:	Soil only
Cross Street:	Not reported
Enf Type:	Not reported
Funding:	Not reported
How Discovered:	Tank Closure
How Stopped:	Not reported
Leak Cause:	UNK
Leak Source:	UNK
Global Id:	T0607199297
Stop Date:	2000-03-20 00:00:00
Confirm Leak:	2000-09-15 00:00:00
Workplan:	Not reported
Prelim Assess:	Not reported
Pollution Char:	2004-04-22 00:00:00
Remed Plan:	Not reported
Remed Action:	Not reported
Monitoring:	Not reported
Close Date:	2004-08-26 00:00:00
Discover Date:	2000-03-20 00:00:00
Enforcement Dt:	Not reported
Release Date:	2000-03-20 00:00:00
Review Date:	Not reported
Enter Date:	Not reported
MTBE Date:	Not reported
GW Qualifier:	Not reported
Soil Qualifier:	=
Max MTBE GW ppb:	Not reported
Max MTBE Soil ppb:	Not reported
County:	36
Org Name:	Not reported
Reg Board:	Santa Ana Region
Status:	Case Closed
Chemical:	Diesel
Contact Person:	Not reported
Responsible Party:	GM. CLEMONS-BROWN
RP Address:	Not reported
Interim:	Not reported
Oversight Prgm:	LUST
MTBE Class:	*
MTBE Conc:	0
MTBE Fuel:	0
MTBE Tested:	Not Required to be Tested.
Staff:	RS
Staff Initials:	JC3
Lead Agency:	Local Agency
Local Agency:	36000L
Hydr Basin #:	UPPER SANTA ANA VALL
Beneficial:	GWR, MUN
Priority:	Not reported
Cleanup Fund Id:	Not reported
Work Suspended:	Not reported

CLEM TRANS INC (Continued) **S105050725**

Local Case #: 2000021
Case Number: 083603808T
Qty Leaked: Not reported
Abate Method: Not reported
Operator: Not reported
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 0
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported
Summary: Haz Mat incident report filed : SAN BERNARDINO COUNTY FIRE DEPT. HAZMAT HAS ORDERED A SITE INVESTIGATION

LUST:
Region: 8
Case Type: Soil only
Cross Street: Not reported
Enf Type: Not reported
Funding: Not reported
How Discovered: Tank Closure
How Stopped: Not reported
Leak Cause: UNK
Leak Source: UNK
Global ID: T0607199297
How Stopped Date: 3/20/2000
Review Date: 9/15/2000
Workplan: Not reported
Prelim Assess: Not reported
Pollution Char: 4/22/2004
Remed Plan: Not reported
Remed Action: Not reported
Monitoring: Not reported
Close Date: 8/26/2004
Discover Date: 3/20/2000
Enforcement Date: Not reported
Review Date: Not reported
Enter Date: Not reported
MTBE Date: Not reported
GW Qualifies: Not reported
Soil Qualifies: Not reported
Max MTBE GW: Not reported
Max MTBE Soil: Not reported
County: San Bernardino
Operator: Not reported
Regional Board: 08
Facility Status: Case Closed
Substance: 12034
Facility Contact: Not reported
Interim: Not reported
Oversite Program: LUST
Latitude: 34.070363
Longitude: -117.371411
MTBE Concentration: 0
MTBE Fuel: 0
MTBE Tested: NRQ
Staff: RS
Staff Initials: JC3

CLEM TRANS INC (Continued) **S105050725**

Lead Agency:	Local Agency
Local Agency:	36000L
Hydr Basin #:	UPPER SANTA ANA VALL
Beneficial:	GWR, MUN
Priority:	Not reported
Cleanup Fund Id:	Not reported
Work Suspended:	Not reported
Local Case Num:	2000021
Case Number:	083603808T
Qty Leaked:	Not reported
Abate Method:	Not reported
MTBE Class:	*
Summary:	Haz Mat incident report filed : SAN BERNARDINO COUNTY FIRE DEPT. HAZMAT HAS ORDERED A SITE INVESTIGATION

---

167 **POMA AUTOMATED FUELING, INC.** **LUST** **S100871021**
SW **2095 RIVERSIDE AVE** **N/A**
> 1 **RIALTO, CA 92377**
1.096 mi.
5785 ft.

Relative: **Lower**

Actual: **1018 ft.**

LUST:

Region:	STATE
Case Type:	Soil only
Cross Street:	Not reported
Enf Type:	Not reported
Funding:	Not reported
How Discovered:	Not reported
How Stopped:	Not reported
Leak Cause:	Not reported
Leak Source:	Not reported
Global Id:	T0607100462
Stop Date:	Not reported
Confirm Leak:	Not reported
Workplan:	Not reported
Prelim Assess:	Not reported
Pollution Char:	Not reported
Remed Plan:	Not reported
Remed Action:	Not reported
Monitoring:	Not reported
Close Date:	1998-07-17 00:00:00
Discover Date:	1997-10-29 00:00:00
Enforcement Dt:	Not reported
Release Date:	1997-12-02 00:00:00
Review Date:	1998-08-11 00:00:00
Enter Date:	1998-02-10 00:00:00
MTBE Date:	Not reported
GW Qualifier:	Not reported
Soil Qualifier:	Not reported
Max MTBE GW ppb:	Not reported
Max MTBE Soil ppb:	Not reported
County:	36
Org Name:	Not reported
Reg Board:	Santa Ana Region
Status:	Case Closed
Chemical:	Gasoline
Contact Person:	Not reported
Responsible Party:	POMA AUTOMATED FUELING, INC.

POMA AUTOMATED FUELING, INC. (Continued) **S100871021**

RP Address: P.O. BOX 5550, RIVERSIDE, CA 92517-0550
Interim: Not reported
Oversight Prgm: LUST
MTBE Class: *
MTBE Conc: 0
MTBE Fuel: 1
MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.
Staff: CAB
Staff Initials: CB5
Lead Agency: Local Agency
Local Agency: 36000L
Hydr Basin #: UPPER SANTA ANA VALL
Beneficial: Not reported
Priority: Not reported
Cleanup Fund Id: Not reported
Work Suspended: Not reported
Local Case #: 97066
Case Number: 083603105T
Qty Leaked: Not reported
Abate Method: Not reported
Operator: Not reported
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 0
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported
Summary: Not reported

LUST:
Region: 8
Case Type: Soil only
Cross Street: Not reported
Enf Type: Not reported
Funding: Not reported
How Discovered: Not reported
How Stopped: Not reported
Leak Cause: Not reported
Leak Source: Not reported
Global ID: T0607100462
How Stopped Date: Not reported
Review Date: Not reported
Workplan: Not reported
Prelim Assess: Not reported
Pollution Char: Not reported
Remed Plan: Not reported
Remed Action: Not reported
Monitoring: Not reported
Close Date: 7/17/1998
Discover Date: 10/29/1997
Enforcement Date: Not reported
Review Date: 8/11/1998
Enter Date: 2/10/1998
MTBE Date: Not reported
GW Qualifies: Not reported
Soil Qualifies: Not reported
Max MTBE GW: Not reported
Max MTBE Soil: Not reported

POMA AUTOMATED FUELING, INC. (Continued) **S100871021**

County:	San Bernardino
Operator:	Not reported
Regional Board:	08
Facility Status:	Case Closed
Substance:	8006619
Facility Contact:	Not reported
Interim:	Not reported
Oversite Program:	LUST
Latitude:	34.1359152
Longitude:	-117.3702883
MTBE Concentration:	0
MTBE Fuel:	1
MTBE Tested:	NT
Staff:	CAB
Staff Initials:	CB5
Lead Agency:	Local Agency
Local Agency:	36000L
Hydr Basin #:	UPPER SANTA ANA VALL
Beneficial:	Not reported
Priority:	Not reported
Cleanup Fund Id:	Not reported
Work Suspended:	Not reported
Local Case Num:	97066
Case Number:	083603105T
Qty Leaked:	Not reported
Abate Method:	Not reported
MTBE Class:	*
Summary:	Not reported

AM168 **TERMINAL (EQUILON ENTERPRISES)** **LUST** **S105690146**
SW **2237 RIVERSIDE AVE** **N/A**
> 1 **RIALTO, CA 92316**
1.184 mi.
6252 ft. **Site 1 of 4 in cluster AM**

Relative:
Lower

Actual:
1008 ft.

LUST:

Region:	STATE
Case Type:	Soil only
Cross Street:	Not reported
Enf Type:	Not reported
Funding:	Not reported
How Discovered:	Tank Closure
How Stopped:	Not reported
Leak Cause:	UNK
Leak Source:	UNK
Global Id:	T0607100567
Stop Date:	Not reported
Confirm Leak:	Not reported
Workplan:	Not reported
Prelim Assess:	1999-02-22 00:00:00
Pollution Char:	Not reported
Remed Plan:	Not reported
Remed Action:	Not reported
Monitoring:	Not reported
Close Date:	Not reported
Discover Date:	1999-02-21 00:00:00
Enforcement Dt:	Not reported
Release Date:	1999-03-23 00:00:00

TERMINAL (EQUILON ENTERPRISES) (Continued) **S105690146**

Review Date: 2002-07-09 00:00:00
Enter Date: 1999-05-11 00:00:00
MTBE Date: Not reported
GW Qualifier: Not reported
Soil Qualifier: Not reported
Max MTBE GW ppb: Not reported
Max MTBE Soil ppb: Not reported
County: 36
Org Name: Not reported
Reg Board: Santa Ana Region
Status: Preliminary site assessment underway
Chemical: Gasoline
Contact Person: Not reported
Responsible Party: EQUILON ENTERPRISES LLC
RP Address: 20945 S. WILMINGTON, CARSON, CA 90720
Interim: Not reported
Oversight Prgm: LUST
MTBE Class: *
MTBE Conc: 0
MTBE Fuel: 1
MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.
Staff: RS
Staff Initials: CR2
Lead Agency: Local Agency
Local Agency: 36000L
Hydr Basin #: UPPER SANTA ANA VALL
Beneficial: Not reported
Priority: Not reported
Cleanup Fund Id: Not reported
Work Suspended: Not reported
Local Case #: 99057
Case Number: 083603436T
Qty Leaked: Not reported
Abate Method: Not reported
Operator: Not reported
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 0
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported
Summary: Not reported

LUST:
Region: 8
Case Type: Soil only
Cross Street: Not reported
Enf Type: Not reported
Funding: Not reported
How Discovered: Tank Closure
How Stopped: Not reported
Leak Cause: UNK
Leak Source: UNK
Global ID: T0607100567
How Stopped Date: Not reported
Review Date: Not reported
Workplan: Not reported
Prelim Assess: 2/22/1999

TERMINAL (EQUILON ENTERPRISES) (Continued) **S105690146**

Pollution Char:	Not reported
Remed Plan:	Not reported
Remed Action:	Not reported
Monitoring:	Not reported
Close Date:	Not reported
Discover Date:	2/21/1999
Enforcement Date:	Not reported
Review Date:	7/9/2002
Enter Date:	5/11/1999
MTBE Date:	Not reported
GW Qualifies:	Not reported
Soil Qualifies:	Not reported
Max MTBE GW:	Not reported
Max MTBE Soil:	Not reported
County:	San Bernardino
Operator:	Not reported
Regional Board:	08
Facility Status:	Preliminary site assessment underway
Substance:	8006619
Facility Contact:	Not reported
Interim:	Not reported
Oversite Program:	LUST
Latitude:	34.0606958
Longitude:	-117.3700158
MTBE Concentration:	0
MTBE Fuel:	1
MTBE Tested:	NT
Staff:	RS
Staff Initials:	CB5
Lead Agency:	Local Agency
Local Agency:	36000L
Hydr Basin #:	UPPER SANTA ANA VALL
Beneficial:	Not reported
Priority:	Not reported
Cleanup Fund Id:	Not reported
Work Suspended:	Not reported
Local Case Num:	99057
Case Number:	083603436T
Qty Leaked:	Not reported
Abate Method:	Not reported
MTBE Class:	*
Summary:	Not reported

AM169 **TERMINAL** **Cortese** **S105025776**
SW **2237 RIVERSIDE AVE** **N/A**
> 1 **RIALTO, CA 92316**
1.184 mi.
6252 ft. **Site 2 of 4 in cluster AM**

Relative:
Lower

Actual:
1008 ft.

Cortese:

Region:	CORTESE
Facility Addr2:	2237 RIVERSIDE AVE

AN170 **FORMER ARCO STATION #1569** **LUST** **S105850454**
ESE **792 VALLEY BOULEVARD WEST** **N/A**
> 1 **COLTON, CA 92324**
1.186 mi.
6262 ft. **Site 1 of 3 in cluster AN**

Relative: LUST:
Lower

Region:	STATE
Case Type:	Drinking Water Aquifer affected
Actual: Cross Street:	RANCHO AVENUE
1007 ft. Enf Type:	Not reported
Funding:	Not reported
How Discovered:	Tank Closure
How Stopped:	Close Tank
Leak Cause:	UNK
Leak Source:	UNK
Global Id:	T0607135690
Stop Date:	2001-12-20 00:00:00
Confirm Leak:	Not reported
Workplan:	Not reported
Prelim Assess:	Not reported
Pollution Char:	2002-01-10 00:00:00
Remed Plan:	Not reported
Remed Action:	Not reported
Monitoring:	Not reported
Close Date:	Not reported
Discover Date:	2001-12-20 00:00:00
Enforcement Dt:	Not reported
Release Date:	2002-01-04 00:00:00
Review Date:	Not reported
Enter Date:	Not reported
MTBE Date:	Not reported
GW Qualifier:	Not reported
Soil Qualifier:	Not reported
Max MTBE GW ppb:	Not reported
Max MTBE Soil ppb:	Not reported
County:	36
Org Name:	Not reported
Reg Board:	Santa Ana Region
Status:	Pollution Characterization
Chemical:	Gasoline
Contact Person:	Not reported
Responsible Party:	ROY THUN
RP Address:	4 CENTERPOINTE DRIVE
Interim:	Not reported
Oversight Prgm:	LUST
MTBE Class:	*
MTBE Conc:	0
MTBE Fuel:	1
MTBE Tested:	MTBE Detected. Site tested for MTBE and MTBE detected
Staff:	VJB
Staff Initials:	LH6
Lead Agency:	Local Agency
Local Agency:	36000L
Hydr Basin #:	Not reported
Beneficial:	Not reported
Priority:	Not reported
Cleanup Fund Id:	Not reported
Work Suspended:	Not reported

FORMER ARCO STATION #1569 (Continued) **S105850454**

Local Case #: 2002003
Case Number: Not reported
Qty Leaked: Not reported
Abate Method: Not reported
Operator: Not reported
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 0
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported
Summary: Not reported

LUST:
Region: 8
Case Type: Drinking Water Aquifer affected
Cross Street: RANCHO AVENUE
Enf Type: Not reported
Funding: Not reported
How Discovered: Tank Closure
How Stopped: Close Tank
Leak Cause: UNK
Leak Source: UNK
Global ID: T0607135690
How Stopped Date: 12/20/2001
Review Date: Not reported
Workplan: Not reported
Prelim Assess: Not reported
Pollution Char: 1/10/2002
Remed Plan: Not reported
Remed Action: Not reported
Monitoring: Not reported
Close Date: Not reported
Discover Date: 12/20/2001
Enforcement Date: Not reported
Review Date: Not reported
Enter Date: Not reported
MTBE Date: 11/12/2002
GW Qualifies: =
Soil Qualifies: =
Max MTBE GW: 2100
Max MTBE Soil: 62000
County: San Bernardino
Operator: Not reported
Regional Board: 08
Facility Status: Pollution Characterization
Substance: 8006619
Facility Contact: Not reported
Interim: Not reported
Oversite Program: LUST
Latitude: 0
Longitude: 0
MTBE Concentration: 0
MTBE Fuel: 1
MTBE Tested: YES
Staff: VJJ
Staff Initials: LH6
Lead Agency: Local Agency

FORMER ARCO STATION #1569 (Continued) **S105850454**

Local Agency:	36000L
Hydr Basin #:	Not reported
Beneficial:	Not reported
Priority:	Not reported
Cleanup Fund Id:	Not reported
Work Suspended:	Not reported
Local Case Num:	2002003
Case Number:	Not reported
Qty Leaked:	Not reported
Abate Method:	Not reported
MTBE Class:	*
Summary:	Not reported

AN171 **ARCO #1569** **LUST** **S103943718**
ESE **792 VALLEY BLVD** **Cortese** **N/A**
> 1 **COLTON, CA 92324**
1.191 mi.
6289 ft. **Site 2 of 3 in cluster AN**

Relative: **Lower**

Actual: **1007 ft.**

LUST:

Region:	STATE
Case Type:	Drinking Water Aquifer affected
Cross Street:	RANCHO
Enf Type:	Not reported
Funding:	Not reported
How Discovered:	OM
How Stopped:	Not reported
Leak Cause:	Other Cause
Leak Source:	Other Source
Global Id:	T0607100105
Stop Date:	1988-05-01 00:00:00
Confirm Leak:	1988-05-01 00:00:00
Workplan:	1988-05-04 00:00:00
Prelim Assess:	Not reported
Pollution Char:	Not reported
Remed Plan:	Not reported
Remed Action:	Not reported
Monitoring:	Not reported
Close Date:	1994-05-11 00:00:00
Discover Date:	1988-05-01 00:00:00
Enforcement Dt:	Not reported
Release Date:	1988-05-04 00:00:00
Review Date:	1994-12-12 00:00:00
Enter Date:	1988-08-01 00:00:00
MTBE Date:	Not reported
GW Qualifier:	Not reported
Soil Qualifier:	Not reported
Max MTBE GW ppb:	Not reported
Max MTBE Soil ppb:	Not reported
County:	36
Org Name:	Not reported
Reg Board:	Santa Ana Region
Status:	Case Closed
Chemical:	Gasoline
Contact Person:	Not reported
Responsible Party:	ARCO PETROLEUM PRODUCTS CO.
RP Address:	17315 STUDEBAKER ROAD, CERRITOS, CA 90701
Interim:	Not reported

ARCO #1569 (Continued) **S103943718**

Oversight Prgm: LUST
MTBE Class: *
MTBE Conc: 0
MTBE Fuel: 1
MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.
Staff: VJB
Staff Initials: LH6
Lead Agency: Local Agency
Local Agency: 36000L
Hydr Basin #: UPPER SANTA ANA VALL
Beneficial: Not reported
Priority: Not reported
Cleanup Fund Id: Not reported
Work Suspended: Not reported
Local Case #: 90122
Case Number: 083600976T
Qty Leaked: Not reported
Abate Method: Vapor Extraction
Operator: Not reported
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 0
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported
Summary: ANOTHER TANK REMOVAL SHOWED LEAK (08/09/91)

LUST:
Region: 8
Case Type: Drinking Water Aquifer affected
Cross Street: RANCHO
Enf Type: Not reported
Funding: Not reported
How Discovered: OM
How Stopped: Not reported
Leak Cause: Other Cause
Leak Source: Other Source
Global ID: T0607100105
How Stopped Date: 5/1/1988
Review Date: 5/1/1988
Workplan: 5/4/1988
Prelim Assess: Not reported
Pollution Char: Not reported
Remed Plan: Not reported
Remed Action: Not reported
Monitoring: Not reported
Close Date: 5/11/1994
Discover Date: 5/1/1988
Enforcement Date: Not reported
Review Date: 12/12/1994
Enter Date: 8/1/1988
MTBE Date: Not reported
GW Qualifies: Not reported
Soil Qualifies: Not reported
Max MTBE GW: Not reported
Max MTBE Soil: Not reported
County: San Bernardino
Operator: Not reported

ARCO #1569 (Continued) **S103943718**

Regional Board:	08
Facility Status:	Case Closed
Substance:	8006619
Facility Contact:	Not reported
Interim:	Not reported
Oversite Program:	LUST
Latitude:	34.0684187
Longitude:	-117.3356656
MTBE Concentration:	0
MTBE Fuel:	1
MTBE Tested:	NT
Staff:	VJJ
Staff Initials:	LH6
Lead Agency:	Local Agency
Local Agency:	36000L
Hydr Basin #:	UPPER SANTA ANA VALL
Beneficial:	Not reported
Priority:	Not reported
Cleanup Fund Id:	Not reported
Work Suspended:	Not reported
Local Case Num:	90122
Case Number:	083600976T
Qty Leaked:	Not reported
Abate Method:	Vapor Extraction
MTBE Class:	*
Summary:	ANOTHER TANK REMOVAL SHOWED LEAK (08/09/91)

Cortese:

Region:	CORTESE
Facility Addr2:	792 VALLEY BLVD

AN172 **COLTON UNIFIED SCHOOL DISTRICT** **HAZNET S104160684**
ESE **777 VALLEY BLVD** **LUST N/A**
> 1 **COLTON, CA 92324**
1.202 mi.
6349 ft. **Site 3 of 3 in cluster AN**

Relative:
Lower

Actual:
1007 ft.

HAZNET:

Gepaid:	CAD982331209
Contact:	COLTON JT UNIFIED SCHOOL DIST
Telephone:	9098764123
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1212 VALENCIA DR
Mailing City,St,Zip:	COLTON, CA 923241731
Gen County:	San Bernardino
TSD EPA ID:	CAD009007626
TSD County:	Los Angeles
Waste Category:	Asbestos-containing waste
Disposal Method:	Disposal, Land Fill
Tons:	1.6856
Facility County:	San Bernardino

Gepaid:	CAD982331209
Contact:	COLTON JT UNIFIED SCHOOL DIST
Telephone:	9098764123
Facility Addr2:	Not reported

COLTON UNIFIED SCHOOL DISTRICT (Continued) **S104160684**

Mailing Name:	Not reported
Mailing Address:	1212 VALENCIA DR
Mailing City,St,Zip:	COLTON, CA 923241731
Gen County:	San Bernardino
TSD EPA ID:	CAD067786749
TSD County:	Los Angeles
Waste Category:	Asbestos-containing waste
Disposal Method:	Disposal, Land Fill
Tons:	21.0700
Facility County:	San Bernardino

Gepaid:	CAD982331209
Contact:	COLTON JT UNIFIED SCHOOL DIST
Telephone:	9098764123
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1212 VALENCIA DR
Mailing City,St,Zip:	COLTON, CA 923241731
Gen County:	San Bernardino
TSD EPA ID:	CAD067786749
TSD County:	Los Angeles
Waste Category:	Asbestos-containing waste
Disposal Method:	Not reported
Tons:	12.6420
Facility County:	San Bernardino

Gepaid:	CAD982331209
Contact:	ADRIAN CHAVEZ DIR MNTNC & OPS
Telephone:	9098764169
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1212 VALENCIA DR
Mailing City,St,Zip:	COLTON, CA 923241731
Gen County:	San Bernardino
TSD EPA ID:	Not reported
TSD County:	Los Angeles
Waste Category:	Asbestos-containing waste
Disposal Method:	Disposal, Land Fill
Tons:	1.13
Facility County:	Not reported

Gepaid:	CAD982331209
Contact:	COLTON JT UNIFIED SCHOOL DIST
Telephone:	9098764123
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1212 VALENCIA DR
Mailing City,St,Zip:	COLTON, CA 923241731
Gen County:	San Bernardino
TSD EPA ID:	CAD044429835
TSD County:	Los Angeles
Waste Category:	Laboratory waste chemicals
Disposal Method:	Recycler
Tons:	.1534
Facility County:	San Bernardino

COLTON UNIFIED SCHOOL DISTRICT (Continued) **S104160684**

Click this hyperlink while viewing on your computer to access
10 additional CA_HAZNET: record(s) in the EDR Site Report.

LUST:

Region:	STATE
Case Type:	Soil only
Cross Street:	THIRD STREET
Enf Type:	Not reported
Funding:	CLOS
How Discovered:	Tank Closure
How Stopped:	Not reported
Leak Cause:	UNK
Leak Source:	UNK
Global Id:	T0607100346
Stop Date:	1994-08-02 00:00:00
Confirm Leak:	1994-08-12 00:00:00
Workplan:	Not reported
Prelim Assess:	1996-02-05 00:00:00
Pollution Char:	1994-11-10 00:00:00
Remed Plan:	1996-02-05 00:00:00
Remed Action:	1996-02-05 00:00:00
Monitoring:	Not reported
Close Date:	1997-07-03 00:00:00
Discover Date:	1994-08-02 00:00:00
Enforcement Dt:	Not reported
Release Date:	1994-08-12 00:00:00
Review Date:	Not reported
Enter Date:	1994-11-18 00:00:00
MTBE Date:	Not reported
GW Qualifier:	Not reported
Soil Qualifier:	=
Max MTBE GW ppb:	Not reported
Max MTBE Soil ppb:	NA
County:	36
Org Name:	Not reported
Reg Board:	Santa Ana Region
Status:	Case Closed
Chemical:	Diesel
Contact Person:	Not reported
Responsible Party:	COLTON UNIFIED SCHOOL DISTRICT
RP Address:	1212 VALENCIA DRIVE, COLTON CA 92324-1798
Interim:	Not reported
Oversight Prgm:	LUST
MTBE Class:	*
MTBE Conc:	1
MTBE Fuel:	0
MTBE Tested:	MTBE Detected. Site tested for MTBE and MTBE detected
Staff:	VJB
Staff Initials:	JC3
Lead Agency:	Local Agency
Local Agency:	36000L
Hydr Basin #:	UPPER SANTA ANA VALL
Beneficial:	Not reported
Priority:	Not reported
Cleanup Fund Id:	Not reported
Work Suspended:	Not reported
Local Case #:	94047

COLTON UNIFIED SCHOOL DISTRICT (Continued) **S104160684**

Case Number: 083602538T
Qty Leaked: Not reported
Abate Method: Not reported
Operator: Not reported
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 0
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported
Summary: BIOVENTING

LUST:
Region: 8
Case Type: Soil only
Cross Street: THIRD STREET
Enf Type: CLOS
Funding: Not reported
How Discovered: Tank Closure
How Stopped: Not reported
Leak Cause: UNK
Leak Source: UNK
Global ID: T0607100346
How Stopped Date: 8/2/1994
Review Date: 8/12/1994
Workplan: Not reported
Prelim Assess: 2/5/1996
Pollution Char: 11/10/1994
Remed Plan: 2/5/1996
Remed Action: 2/5/1996
Monitoring: Not reported
Close Date: 7/3/1997
Discover Date: 8/2/1994
Enforcement Date: Not reported
Review Date: Not reported
Enter Date: 11/18/1994
MTBE Date: Not reported
GW Qualifies: Not reported
Soil Qualifies: Not reported
Max MTBE GW: Not reported
Max MTBE Soil: Not reported
County: San Bernardino
Operator: Not reported
Regional Board: 08
Facility Status: Case Closed
Substance: 12034
Facility Contact: Not reported
Interim: Not reported
Oversite Program: LUST
Latitude: 34.0685467
Longitude: -117.3348186
MTBE Concentration: 1
MTBE Fuel: 0
MTBE Tested: YES
Staff: VJJ
Staff Initials: JC3
Lead Agency: Local Agency
Local Agency: 36000L

COLTON UNIFIED SCHOOL DISTRICT (Continued) **S104160684**

Hydr Basin #:	UPPER SANTA ANA VALL
Beneficial:	Not reported
Priority:	Not reported
Cleanup Fund Id:	Not reported
Work Suspended:	Not reported
Local Case Num:	94047
Case Number:	083602538T
Qty Leaked:	Not reported
Abate Method:	Not reported
MTBE Class:	*
Summary:	BIOVENTING

AM173 **FILTER RECYCLING SERVICES INC** **PADS 1000473043**
SW **180 W MONTE AVE** **FINDS CAD982444481**
> 1 **RIALTO, CA 92316** **HAZNET**
1.222 mi. **RCRA-LQG**
6450 ft. **Site 3 of 4 in cluster AM** **CORRACTS**
San Bern. Co. Permit
Relative: **CA WDS**
Lower

Actual: FINDS:
1008 ft. Other Pertinent Environmental Activity Identified at Site

California - Hazardous Waste Tracking System - Datamart

NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

UORS (California - Used Oil Recycling System). California Integrated Waste Management Board (CIWMB) helps communities establish and promote convenient collection opportunities for used oil and used oil filters.

HAZNET:

Gepaid:	CAD982444481
Contact:	JON L BENNETT JR
Telephone:	8006984377
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	PO BOX 449
Mailing City,St,Zip:	COLTON, CA 923240449
Gen County:	San Bernardino
TSD EPA ID:	AZD983481813
TSD County:	99
Waste Category:	Not reported
Disposal Method:	Not reported
Tons:	96.9220

FILTER RECYCLING SERVICES INC (Continued) **1000473043**

Facility County: San Bernardino

Gepaid: CAD982444481
Contact: JON L BENNETT JR
Telephone: 8006984377
Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: PO BOX 449
Mailing City,St,Zip: COLTON, CA 923240449
Gen County: San Bernardino
TSD EPA ID: AZD983481813
TSD County: 99
Waste Category: Other organic solids
Disposal Method: Recycler
Tons: 67.4240
Facility County: San Bernardino

Gepaid: CAD982444481
Contact: JON L BENNETT JR
Telephone: 8006984377
Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: PO BOX 449
Mailing City,St,Zip: COLTON, CA 923240449
Gen County: San Bernardino
TSD EPA ID: AZD983481813
TSD County: 99
Waste Category: Other organic solids
Disposal Method: Recycler
Tons: 3750.4600
Facility County: San Bernardino

Gepaid: CAD982444481
Contact: JON L BENNETT JR
Telephone: 8006984377
Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: PO BOX 449
Mailing City,St,Zip: COLTON, CA 923240449
Gen County: San Bernardino
TSD EPA ID: AZD983481813
TSD County: 99
Waste Category: Other organic solids
Disposal Method: Transfer Station
Tons: 16.8560
Facility County: San Bernardino

Gepaid: CAD982444481
Contact: JON L BENNETT JR
Telephone: 8006984377
Facility Addr2: Not reported
Mailing Name: Not reported
Mailing Address: PO BOX 449
Mailing City,St,Zip: COLTON, CA 923240449
Gen County: San Bernardino
TSD EPA ID: AZD983481813
TSD County: 99

FILTER RECYCLING SERVICES INC (Continued) **1000473043**

Waste Category: Not reported
Disposal Method: Recycler
Tons: .0000
Facility County: San Bernardino

Click this hyperlink while viewing on your computer to access
963 additional CA_HAZNET: record(s) in the EDR Site Report.

RCRA-LQG:
Date form received by agency: 02/08/2006
Facility name: FILTER RECYCLING SERVICES, INC.
Facility address: 180 W. MONTE AVE.
BLOOMINGTON, CA 92316
EPA ID: CAD982444481
Mailing address: PO BOX 449
COLTON, CA 92316
Contact: WADE RIDDERING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (909) 873-4141
Contact email: WADE_RIDDERING@FILTERRECYCLING.COM
EPA Region: 09
Land type: Private
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:
Owner/operator name: JON L. BENNETT, JR.
Owner/operator address: PO BOX 449
COLTON, CA 92324
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 06/12/1990
Owner/Op end date: Not reported

Owner/operator name: FILTER RECYCLING SERVICES, INC.
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator

FILTER RECYCLING SERVICES INC (Continued) **1000473043**

Owner/Op start date: 06/12/1990
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: Yes
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: Yes
Transporter of hazardous waste: Yes
Treater, storer or disposer of HW: Yes
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: Yes
Used oil transporter: Yes
Off-site waste receiver: Commercial status unknown

Universal Waste Summary:
Waste type: Batteries
Accumulated waste on-site: Yes
Generated waste on-site: Yes

Waste type: Lamps
Accumulated waste on-site: Yes
Generated waste on-site: Yes

Waste type: Pesticides
Accumulated waste on-site: Yes
Generated waste on-site: No

Waste type: Thermostats
Accumulated waste on-site: Yes
Generated waste on-site: Yes

Historical Generators:
Date form received by agency: 02/23/2004
Facility name: FILTER RECYCLING SERVICES, INC.
Classification: Large Quantity Generator

Date form received by agency: 03/22/2002
Facility name: FILTER RECYCLING SERVICES, INC.
Classification: Large Quantity Generator

Date form received by agency: 10/12/2000
Facility name: FILTER RECYCLING SERVICES, INC.
Classification: Large Quantity Generator

Date form received by agency: 09/30/1999
Facility name: FILTER RECYCLING SERVICES, INC.
Site name: FILTER RECYCLING SERVICES INC
Classification: Large Quantity Generator

FILTER RECYCLING SERVICES INC (Continued) **1000473043**

Date form received by agency: 06/06/1999
Facility name: FILTER RECYCLING SERVICES, INC.
Classification: Large Quantity Generator

Date form received by agency: 09/01/1996
Facility name: FILTER RECYCLING SERVICES, INC.
Site name: FILTER RECYCLING SERVICES INC
Classification: Small Quantity Generator

Date form received by agency: 03/20/1996
Facility name: FILTER RECYCLING SERVICES, INC.
Classification: Large Quantity Generator

Hazardous Waste Summary:
Waste code: 122
Waste name: 122

Waste code: 123
Waste name: 123

Waste code: 133
Waste name: 133

Waste code: 134
Waste name: 134

Waste code: 135
Waste name: 135

Waste code: 141
Waste name: 141

Waste code: 172
Waste name: 172

Waste code: 181
Waste name: 181

Waste code: 212
Waste name: 212

Waste code: 213
Waste name: 213

Waste code: 214
Waste name: 214

Waste code: 221
Waste name: 221

Waste code: 222
Waste name: 222

Waste code: 223
Waste name: 223

Waste code: 241

FILTER RECYCLING SERVICES INC (Continued) **1000473043**

Waste name: 241

Waste code: 281
Waste name: 281

Waste code: 291
Waste name: 291

Waste code: 311
Waste name: 311

Waste code: 331
Waste name: 331

Waste code: 343
Waste name: 343

Waste code: 352
Waste name: 352

Waste code: 451
Waste name: 451

Waste code: 461
Waste name: 461

Waste code: 491
Waste name: 491

Waste code: 512
Waste name: 512

Waste code: 513
Waste name: 513

Waste code: 561
Waste name: 561

Waste code: 611
Waste name: 611

Waste code: 612
Waste name: 612

Waste code: 741
Waste name: 741

Waste code: 791
Waste name: 791

Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT

FILTER RECYCLING SERVICES INC (Continued) **1000473043**

WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002
Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Waste code: D007
Waste name: CHROMIUM

Waste code: D008
Waste name: LEAD

Waste code: D039
Waste name: TETRACHLOROETHYLENE

Waste code: F001
Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLOROETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE, AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste code: F003
Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste code: F005
Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Biennial Reports:

Last Biennial Reporting Year: 2005

Annual Waste Handled:
Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF

FILTER RECYCLING SERVICES INC (Continued) **1000473043**

LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Amount (Lbs): 137110.4

Waste code: D002
Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.
Amount (Lbs): 6450.3

Waste code: D007
Waste name: CHROMIUM
Amount (Lbs): 800

Waste code: D008
Waste name: LEAD
Amount (Lbs): 400

Waste code: D039
Waste name: TETRACHLOROETHYLENE
Amount (Lbs): 5016.2

Waste code: F001
Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLOROETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE, AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Amount (Lbs): 231

Waste code: F003
Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Amount (Lbs): 6145.2

Waste code: F005
Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE,

FILTER RECYCLING SERVICES INC (Continued) **1000473043**

2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Amount (Lbs): 5750.2

Corrective Action Summary:

Event date: 01/01/1990
Event: CA029ST

Event date: 12/20/1991
Event: CA074LO

Event date: 12/20/1991
Event: CA Prioritization, Facility or area was assigned a low corrective action priority.

Event date: 12/20/1991
Event: CA049PA

Facility Has Received Notices of Violations:

Regulation violated: Not reported
Area of violation: TSD - General Facility Standards
Date violation determined: 06/22/2005
Date achieved compliance: 06/23/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/23/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Permits - Application
Date violation determined: 06/23/2004
Date achieved compliance: 07/23/2004
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/23/2004
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Container Use and Management
Date violation determined: 06/23/2004
Date achieved compliance: 07/23/2004
Violation lead agency: State

FILTER RECYCLING SERVICES INC (Continued) **1000473043**

Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/23/2004
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Container Use and Management
Date violation determined: 06/23/2004
Date achieved compliance: 07/01/2004
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/23/2004
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 06/30/2003
Date achieved compliance: 07/03/2003
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: 06/30/2003
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Pre-transport
Date violation determined: 06/30/2003
Date achieved compliance: 07/03/2003
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: 06/30/2003
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 06/30/2003
Date achieved compliance: 07/03/2003
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL

FILTER RECYCLING SERVICES INC (Continued) **1000473043**

Enforcement action date: 07/03/2003
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Pre-transport
Date violation determined: 06/30/2003
Date achieved compliance: 07/03/2003
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/03/2003
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Financial Requirements
Date violation determined: 05/21/2002
Date achieved compliance: 09/23/2003
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 05/21/2002
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Financial Requirements
Date violation determined: 11/15/2001
Date achieved compliance: 01/22/2002
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 11/21/2001
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 11/15/2001
Date achieved compliance: 01/22/2002
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: 11/15/2001

FILTER RECYCLING SERVICES INC (Continued) **1000473043**

Enf. disposition status:	Not reported
Enf. disp. status date:	Not reported
Enforcement lead agency:	State
Proposed penalty amount:	Not reported
Final penalty amount:	Not reported
Paid penalty amount:	Not reported
Regulation violated:	Not reported
Area of violation:	TSD - General Facility Standards
Date violation determined:	11/15/2001
Date achieved compliance:	01/22/2002
Violation lead agency:	State
Enforcement action:	WRITTEN INFORMAL
Enforcement action date:	11/21/2001
Enf. disposition status:	Not reported
Enf. disp. status date:	Not reported
Enforcement lead agency:	State
Proposed penalty amount:	Not reported
Final penalty amount:	Not reported
Paid penalty amount:	Not reported
Regulation violated:	Not reported
Area of violation:	TSD - General
Date violation determined:	11/15/2001
Date achieved compliance:	01/22/2002
Violation lead agency:	State
Enforcement action:	WRITTEN INFORMAL
Enforcement action date:	11/21/2001
Enf. disposition status:	Not reported
Enf. disp. status date:	Not reported
Enforcement lead agency:	State
Proposed penalty amount:	Not reported
Final penalty amount:	Not reported
Paid penalty amount:	Not reported
Regulation violated:	Not reported
Area of violation:	TSD - Container Use and Management
Date violation determined:	11/15/2001
Date achieved compliance:	01/22/2002
Violation lead agency:	State
Enforcement action:	WRITTEN INFORMAL
Enforcement action date:	11/21/2001
Enf. disposition status:	Not reported
Enf. disp. status date:	Not reported
Enforcement lead agency:	State
Proposed penalty amount:	Not reported
Final penalty amount:	Not reported
Paid penalty amount:	Not reported
Regulation violated:	Not reported
Area of violation:	TSD - Financial Requirements
Date violation determined:	11/15/2001
Date achieved compliance:	01/22/2002
Violation lead agency:	State
Enforcement action:	WRITTEN INFORMAL
Enforcement action date:	07/17/2001
Enf. disposition status:	Not reported

FILTER RECYCLING SERVICES INC (Continued) **1000473043**

Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 12/18/2000
Date achieved compliance: 02/09/2001
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 12/19/2000
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 06/21/1999
Date achieved compliance: 11/11/1999
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: 06/21/1999
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 06/21/1999
Date achieved compliance: 11/11/1999
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/22/1999
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: F - 263
Area of violation: Transporters - General
Date violation determined: 05/27/1998
Date achieved compliance: 06/19/1998
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 05/27/1998
Enf. disposition status: Not reported
Enf. disp. status date: Not reported

FILTER RECYCLING SERVICES INC (Continued) **1000473043**

Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: F - 270
Area of violation: TSD - General
Date violation determined: 01/23/1998
Date achieved compliance: 02/23/1998
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 01/23/1998
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: F - 264.50-56.D
Area of violation: TSD - General
Date violation determined: 04/24/1997
Date achieved compliance: 05/24/1997
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/24/1997
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: F - 264.30-37.C
Area of violation: TSD - General
Date violation determined: 04/24/1997
Date achieved compliance: 05/24/1997
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/24/1997
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: F - 270
Area of violation: TSD - General
Date violation determined: 04/24/1997
Date achieved compliance: 05/24/1997
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/24/1997
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State

FILTER RECYCLING SERVICES INC (Continued) **1000473043**

Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: F - 262.40-43.D
Area of violation: Generators - General
Date violation determined: 04/24/1997
Date achieved compliance: 05/24/1997
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/24/1997
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: F - 264.70-77.E
Area of violation: TSD - General
Date violation determined: 04/24/1997
Date achieved compliance: 05/24/1997
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/24/1997
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: F - 264.170-177.I
Area of violation: TSD - General
Date violation determined: 04/24/1997
Date achieved compliance: 05/24/1997
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/24/1997
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 270
Area of violation: TSD - General
Date violation determined: 06/26/1995
Date achieved compliance: 09/07/1995
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/26/1995
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported

FILTER RECYCLING SERVICES INC (Continued) **1000473043**

Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 264.140-150.H
Area of violation: TSD - Financial Requirements
Date violation determined: 06/26/1995
Date achieved compliance: 09/01/1995
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/26/1995
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 06/28/2006
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 06/12/2006
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 06/22/2005
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General Facility Standards
Date achieved compliance: 06/23/2005
Evaluation lead agency: State

Evaluation date: 06/03/2005
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 07/06/2004
Evaluation: NOT A SIGNIFICANT NON-COMPLIER
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 06/23/2004
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Permits - Application
Date achieved compliance: 07/23/2004
Evaluation lead agency: State

Evaluation date: 06/23/2004
Evaluation: SIGNIFICANT NON-COMPLIER
Area of violation: Not reported

FILTER RECYCLING SERVICES INC (Continued) **1000473043**

Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 06/23/2004
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - Container Use and Management
Date achieved compliance: 07/01/2004
Evaluation lead agency: State

Evaluation date: 06/23/2004
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - Container Use and Management
Date achieved compliance: 07/23/2004
Evaluation lead agency: State

Evaluation date: 04/29/2004
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 09/19/2003
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 06/30/2003
Evaluation: FOLLOW-UP INSPECTION
Area of violation: Generators - Pre-transport
Date achieved compliance: 07/03/2003
Evaluation lead agency: State

Evaluation date: 06/30/2003
Evaluation: FOLLOW-UP INSPECTION
Area of violation: TSD - General
Date achieved compliance: 07/03/2003
Evaluation lead agency: State

Evaluation date: 05/21/2002
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: TSD - Financial Requirements
Date achieved compliance: 09/23/2003
Evaluation lead agency: State

Evaluation date: 11/15/2001
Evaluation: FOLLOW-UP INSPECTION
Area of violation: TSD - General Facility Standards
Date achieved compliance: 01/22/2002
Evaluation lead agency: State

Evaluation date: 11/15/2001
Evaluation: FOLLOW-UP INSPECTION
Area of violation: TSD - Container Use and Management
Date achieved compliance: 01/22/2002
Evaluation lead agency: State

FILTER RECYCLING SERVICES INC (Continued) **1000473043**

Evaluation date: 11/15/2001
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: TSD - Financial Requirements
Date achieved compliance: 01/22/2002
Evaluation lead agency: State

Evaluation date: 11/15/2001
Evaluation: FOLLOW-UP INSPECTION
Area of violation: TSD - General
Date achieved compliance: 01/22/2002
Evaluation lead agency: State

Evaluation date: 11/15/2001
Evaluation: FOLLOW-UP INSPECTION
Area of violation: TSD - Financial Requirements
Date achieved compliance: 01/22/2002
Evaluation lead agency: State

Evaluation date: 12/18/2000
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General
Date achieved compliance: 02/09/2001
Evaluation lead agency: State

Evaluation date: 12/15/2000
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 06/21/1999
Evaluation: FOLLOW-UP INSPECTION
Area of violation: TSD - General
Date achieved compliance: 11/11/1999
Evaluation lead agency: State

Evaluation date: 05/20/1999
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

Evaluation date: 05/27/1998
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Transporters - General
Date achieved compliance: 06/19/1998
Evaluation lead agency: State

Evaluation date: 01/22/1998
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General
Date achieved compliance: 02/23/1998
Evaluation lead agency: State

Evaluation date: 04/23/1997
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General

FILTER RECYCLING SERVICES INC (Continued) **1000473043**

Date achieved compliance: 05/24/1997
Evaluation lead agency: State

Evaluation date: 04/23/1997
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 05/24/1997
Evaluation lead agency: State

Evaluation date: 01/19/1996
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 06/26/1995
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - Financial Requirements
Date achieved compliance: 09/01/1995
Evaluation lead agency: State

Evaluation date: 06/26/1995
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General
Date achieved compliance: 09/07/1995
Evaluation lead agency: State

Evaluation date: 11/29/1990
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

CORRACTS:

EPA ID: CAD982444481
EPA Region: 9
Area Name: ENTIRE FACILITY
Actual Date: 12/20/1991
Action: CA075LO - CA Prioritization, Facility or area was assigned a low corrective action priority
NAICS Code(s): 562112 562111
Hazardous Waste Collection
Solid Waste Collection
Original schedule date: Not reported
Schedule end date: Not reported

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0003215
Owner: FILTER RECYCLING SVCS INC
Permit Number: PT0018851
Permit Category: APPLIANCE RECYCLER
Facility Status: ACTIVE
Expiration Date: 7/31/2006 12:00:00AM

Region: SAN BERNARDINO

FILTER RECYCLING SERVICES INC (Continued) **1000473043**

Facility ID: FA0003215
Owner: FILTER RECYCLING SVCS INC
Permit Number: PT0005816
Permit Category: ABOVEGROUND PETROLEUM STORAGE (AST) (SPCC)
Facility Status: ACTIVE
Expiration Date: 7/31/2008 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0003215
Owner: FILTER RECYCLING SVCS INC
Permit Number: PT0005814
Permit Category: SPECIAL HANDLER
Facility Status: ACTIVE
Expiration Date: 7/31/2008 12:00:00AM

Region: SAN BERNARDINO
Facility ID: FA0003215
Owner: FILTER RECYCLING SVCS INC
Permit Number: PT0005815
Permit Category: SPECIAL GENERATOR(B)
Facility Status: ACTIVE
Expiration Date: 7/31/2008 12:00:00AM

CA WDS:
Facility ID: Santa Ana River 36I012307
Facility Type: Industrial - Facility that treats and/or disposes of liquid or semisolid wastes from any servicing, producing, manufacturing or processing operation of whatever nature, including mining, gravel washing, geothermal operations, air conditioning, ship building and repairing, oil production, storage and disposal operations, water pumping.
Facility Status: Active - Any facility with a continuous or seasonal discharge that is under Waste Discharge Requirements.
NPDES Number: CAS000001 The 1st 2 characters designate the state. The remaining 7 are assigned by the Regional Board
Subregion: 8
Facility Telephone: 9094212012
Facility Contact: WADE RIDDERING
Agency Name: FILTER RECYCLING SERVICE
Agency Address: 2230 RIVERSIDE AVE.
Agency City,St,Zip: RIALTO 92317
Agency Contact: JOHN BENNETT JR.
Agency Telephone: 9094211630
Agency Type: Private
SIC Code: 0
SIC Code 2: Not reported
Primary Waste: Not reported
Primary Waste Type: Not reported
Secondary Waste: Not reported
Secondary Waste Type: Not reported
Design Flow: 0
Baseline Flow: 0
Reclamation: Not reported
POTW: Not reported
Treat To Water: Minor Threat to Water Quality. A violation of a regional board order should cause a relatively minor impairment of beneficial uses compared to a major or minor threat. Not: All nurds without a TTWQ will be

FILTER RECYCLING SERVICES INC (Continued) **1000473043**

considered a minor threat to water quality unless coded at a higher Level. A Zero (0) may be used to code those NURDS that are found to represent no threat to water quality.

Complexity: Category C - Facilities having no waste treatment systems, such as cooling water dischargers or thosewho must comply through best management practices, facilities with passive waste treatment and disposal systems, such as septic systems with subsurface disposal, or dischargers having waste storage systems with land disposal such as dairy waste ponds.

AM174 **FILTER RECYCLING SERVICES, INC.** **SWF/LF** **S106800136**
SW **180 WEST MONTE AVENUE** **N/A**
> 1 **BLOOMINGTON, CA**
1.222 mi.
6450 ft. **Site 4 of 4 in cluster AM**

Relative: **Lower**

Actual: **1008 ft.**

SWF/LF:

Region:	STATE
Facility ID:	36-AA-0424
Lat/Long:	34.06216 / -117.37245
Owner Name:	Filter Recycling Services, Inc.
Owner Telephone:	9098734141
Owner Address:	Not reported
Owner Address2:	2230 South Riverside Avenue
Owner City,St,Zip:	Rialto, CA 92316
Operator:	Filter Recycling Services, Inc.
Operator Phone:	9094241630
Operator Address:	Jon L. Bennett Jr.
Operator Address2:	P.O. Box 449
Operator City,St,Zip:	Colton, CA 92324-0449
Operator's Status:	Active
Permit Date:	10/6/2004
Permit Status:	Not reported
Permitted Acreage:	$1.00
Activity:	Contaminated Soil Operation, Xfer
Regulation Status:	Notification
Landuse Name:	Not reported
GIS Source:	Map
Category:	Transfer/Processing
Unit Number:	01
Inspection Frequency:	Quarterly
Accepted Waste:	Contaminated soil
Closure Date:	Not reported
Closure Type:	Not reported
Disposal Acreage:	Not reported
Swisnumber:	36-AA-0424
Issue & Observations:	Colton, CA 92324-0449
Program Type:	Not reported
Permitted Throughput with Units:	25
Actual Throughput with Units:	Tons/day
Permitted Capacity with Units:	2410
Remaining Capacity:	Not reported
Remaining Capacity with Units:	Tons/year

AO175 **CHEVRON COLTON TERMINAL** SLIC S108724691
SW **2297 RIVERSIDE AVE S** N/A
> 1 **BLOOMINGTON, CA**
1.242 mi.
6556 ft. **Site 1 of 4 in cluster AO**

Relative: SLIC:
Lower

Actual:
1001 ft.

Region:	STATE
Global Id:	SL0607119456
Assigned Name:	SLICSITE
Lead Agency Contact:	ROSE SCOTT
Lead Agency:	SANTA ANA RWQCB (REGION 8)
Lead Agency Case Number:	Not reported
Responsible Party:	Not reported
Recent Dtw:	Not reported
Substance Released:	12034, 8006619
Facility Status:	**Feasibility Study for Remedial Action Plan**

AO176 **GW CLEANUP-COLTON TERMINA** Cortese S105022790
SW **2301 RIVERSIDE** N/A
> 1 **BLOOMINGTON, CA 92316**
1.244 mi.
6566 ft. **Site 2 of 4 in cluster AO**

Relative: Cortese:
Lower

Actual:
1001 ft.

Region:	CORTESE
Facility Addr2:	Not reported

AO177 **INLAND COMPOSTING AND ORGANIC RECYCLING** SWF/LF S103340414
SW **2300 SOUTH RIVERSIDE AVENUE** N/A
> 1 **BLOOMINGTON, CA**
1.246 mi.
6577 ft. **Site 3 of 4 in cluster AO**

Relative: SWF/LF:
Lower

Actual:
1001 ft.

Region:	STATE
Facility ID:	36-AA-0384
Lat/Long:	34.06194 / -117.37028
Owner Name:	Agua Mansa River Farms LLP
Owner Telephone:	Not reported
Owner Address:	Not reported
Owner Address2:	1951 West Key Road
Owner City,St,Zip:	Colton, CA 92324
Operator:	Inland Composting Organic Recyc, Inc.
Operator Phone:	Not reported
Operator Address:	Not reported
Operator Address2:	1951 West Key Road
Operator City,St,Zip:	Colton, CA 92324
Operator's Status:	Planned
Permit Date:	1/30/2002
Permit Status:	Not reported
Permitted Acreage:	$0.00
Activity:	Composting Facility (Mixed)
Regulation Status:	Proposed
Landuse Name:	Industrial
GIS Source:	Map
Category:	Composting
Unit Number:	01

INLAND COMPOSTING AND ORGANIC RECYCLING (Continued) **S103340414**

Inspection Frequency:	None
Accepted Waste:	Not reported
Closure Date:	Not reported
Closure Type:	Not reported
Disposal Acreage:	Not reported
Swisnumber:	36-AA-0384
Issue & Observations:	Colton, CA 92324
Program Type:	Not reported
Permitted Throughput with Units:	Not reported
Actual Throughput with Units:	Tons/day
Permitted Capacity with Units:	Not reported
Remaining Capacity:	Not reported
Remaining Capacity with Units:	Tons/year

AO178 **MOBIL FAC. #04-086 /COLTON TER** **LUST** **S102433686**
SW **2305 RIVERSIDE AVE** **N/A**
> 1 **BLOOMINGTON, CA 92316**
1.248 mi.
6588 ft. **Site 4 of 4 in cluster AO**

Relative:
Lower

Actual:
1001 ft.

LUST:

Region:	STATE
Case Type:	Drinking Water Aquifer affected
Cross Street:	Not reported
Enf Type:	Not reported
Funding:	SI
How Discovered:	Not reported
How Stopped:	Not reported
Leak Cause:	Not reported
Leak Source:	Not reported
Global Id:	T0607100402
Stop Date:	Not reported
Confirm Leak:	Not reported
Workplan:	1993-03-01 00:00:00
Prelim Assess:	Not reported
Pollution Char:	1995-12-01 00:00:00
Remed Plan:	1996-07-15 00:00:00
Remed Action:	2006-10-13 00:00:00
Monitoring:	Not reported
Close Date:	Not reported
Discover Date:	Not reported
Enforcement Dt:	Not reported
Release Date:	1993-04-12 00:00:00
Review Date:	1999-10-12 00:00:00
Enter Date:	1995-12-20 00:00:00
MTBE Date:	1998-02-25 00:00:00
GW Qualifier:	=
Soil Qualifier:	Not reported
Max MTBE GW ppb:	10000
Max MTBE Soil ppb:	Not reported
County:	36
Org Name:	Not reported
Reg Board:	Santa Ana Region
Status:	Remedial action (cleanup) Underway
Chemical:	Gasoline
Contact Person:	Not reported
Responsible Party:	MOBIL OIL CORP
RP Address:	3700 W. 190TH ST., TPT-2

MOBIL FAC. #04-086 /COLTON TER (Continued) **S102433686**

Interim: Not reported
Oversight Prgm: LUST
MTBE Class: B
MTBE Conc: 1
MTBE Fuel: 1
MTBE Tested: MTBE Detected. Site tested for MTBE and MTBE detected
Staff: RS
Staff Initials: CR2
Lead Agency: Regional Board
Local Agency: 36000L
Hydr Basin #: UPPER SANTA ANA VALL
Beneficial: Not reported
Priority: Not reported
Cleanup Fund Id: Not reported
Work Suspended: Not reported
Local Case #: Not reported
Case Number: 083602777T
Qty Leaked: Not reported
Abate Method: Remove Free Product - remove floating product from water table
Operator: Not reported
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 0
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported
Summary: SUBMITTED NUMEROUS LETTERS TO CONDUCT INTERIM REMEDIATION. WORKING W/SWPPP TO OBTAIN ACCESS FOR VES, HIGH BTEX AND MTBE LEVELS IN GW.

LUST:
Region: 8
Case Type: Drinking Water Aquifer affected
Cross Street: Not reported
Enf Type: VER
Funding: Not reported
How Discovered: Not reported
How Stopped: Not reported
Leak Cause: Not reported
Leak Source: Not reported
Global ID: T0607100402
How Stopped Date: Not reported
Review Date: Not reported
Workplan: 3/1/1993
Prelim Assess: Not reported
Pollution Char: 12/1/1995
Remed Plan: 7/15/1996
Remed Action: 6/1/2000
Monitoring: Not reported
Close Date: Not reported
Discover Date: Not reported
Enforcement Date: Not reported
Review Date: 10/12/1999
Enter Date: 12/20/1995
MTBE Date: 2/25/1998
GW Qualifies: =
Soil Qualifies: Not reported
Max MTBE GW: 10000
Max MTBE Soil: Not reported

MOBIL FAC. #04-086 /COLTON TER (Continued) **S102433686**

County:	San Bernardino
Operator:	Not reported
Regional Board:	08
Facility Status:	Remedial action (cleanup) Underway
Substance:	8006619
Facility Contact:	Not reported
Interim:	Not reported
Oversite Program:	LUST
Latitude:	34.0594498
Longitude:	-117.3700118
MTBE Concentration:	1
MTBE Fuel:	1
MTBE Tested:	YES
Staff:	RS
Staff Initials:	CR2
Lead Agency:	Regional Board
Local Agency:	36000L
Hydr Basin #:	UPPER SANTA ANA VALL
Beneficial:	Not reported
Priority:	Not reported
Cleanup Fund Id:	Not reported
Work Suspended:	Not reported
Local Case Num:	Not reported
Case Number:	083602777T
Qty Leaked:	Not reported
Abate Method:	Remove Free Product - remove floating product from water table
MTBE Class:	B
Summary:	SUBMITTED NUMEROUS LETTERS TO CONDUCT INTERIM REMEDIATION. WORKING W/SWPPP TO OBTAIN ACCESS FOR VES, HIGH BTEX AND MTBE LEVELS IN GW.

179
West
> 1
1.612 mi.
8513 ft.

CACTUS MIDDLE SCHOOL
VALLEY BOULEVARD/CACTUS AVENUE
RIALTO, CA 92316

SCH S105628851
ENVIROSTOR N/A

Relative:
Lower

Actual:
0 ft.

SCH:

Facility ID:	36010034
Site Type:	School Investigation
Site Type Detail:	School
Acres:	17
National Priorities List:	NO
Cleanup Oversight Agencies:	DTSC
Lead Agency:	NONE SPECIFIED
Lead Agency Description:	Not reported
Project Manager:	Not reported
Supervisor:	Javier Hinojosa
Division Branch:	School Evaluation - Glendale / Sacramento
Site Code:	404329-11
Assembly:	62
Senate:	32
Special Program Status:	Not reported
Status:	No Further Action
Status Date:	2002-08-29 00:00:00
Restricted Use:	NO
Funding:	School District
Latitude:	34.070785
Longitude:	-117.382273

CACTUS MIDDLE SCHOOL (Continued) **S105628851**

Alias Name:	404329-11
	COLTON JOINT UNIFIED SCHOOL DISTRICT
	COLTON JOINT USD-PRPSD MID SCL VLLEY BLV
	CACTUS MIDDLE SCHOOL
	36010034
Alias Type:	Project Code (Site Code)
	Alternate Name
	Envirostor ID Number
	Alternate Name
	Alternate Name
APN:	NONE SPECIFIED
APN Description:	Not reported
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Preliminary Endangerment Assessment Report
Completed Date:	2005-03-16 00:00:00
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Preliminary Endangerment Assessment Workplan
Completed Date:	2004-08-04 00:00:00
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Cost Recovery Closeout Memo
Completed Date:	2005-06-07 00:00:00
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Environmental Oversight Agreement
Completed Date:	2002-08-29 00:00:00
Confirmed:	NONE SPECIFIED
Confirmed Description:	Not reported
Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Media Affected:	NONE SPECIFIED
Media Affected Desc:	Not reported
Management Required:	NONE SPECIFIED
Management Required Desc:	Not reported
Potential:	NONE SPECIFIED,31000
Potenital Description:	Not reported
Potenital Description:	No Contaminants found
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported
PastUse:	AGRICULTURAL - ROW CROPS

ENVIROSTOR:

Site Type:	School Investigation
Site Type Detailed:	School
Acres:	17
NPL:	NO
Regulatory Agencies:	DTSC
Lead Agency:	NONE SPECIFIED
Program Manager:	Not reported

CACTUS MIDDLE SCHOOL (Continued) **S105628851**

Supervisor:	Javier Hinojosa
Division Branch:	School Evaluation - Glendale / Sacramento
Facility ID:	36010034
Site Code:	404329-11
Assembly:	62
Senate:	32
Special Program:	Not reported
Status:	No Further Action
Status Date:	2002-08-29 00:00:00
Restricted Use:	NO
Funding:	School District
Latitude:	34.070785
Longitude:	-117.382273
Alias Name:	404329-11
	COLTON JOINT UNIFIED SCHOOL DISTRICT
	COLTON JOINT USD-PRPSD MID SCL VLLEY BLV
	CACTUS MIDDLE SCHOOL
	36010034
Alias Type:	Project Code (Site Code)
	Alternate Name
	Envirostor ID Number
	Alternate Name
	Alternate Name
APN:	NONE SPECIFIED
APN Description:	Not reported
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Preliminary Endangerment Assessment Report
Completed Date:	2005-03-16 00:00:00
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Preliminary Endangerment Assessment Workplan
Completed Date:	2004-08-04 00:00:00
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Cost Recovery Closeout Memo
Completed Date:	2005-06-07 00:00:00
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Environmental Oversight Agreement
Completed Date:	2002-08-29 00:00:00
Confirmed:	NONE SPECIFIED
Confirmed Description:	Not reported
Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Media Affected:	NONE SPECIFIED
Media Affected Desc:	Not reported
Management Required:	NONE SPECIFIED
Management Required Desc:	Not reported
Potential:	NONE SPECIFIED,31000
Potenital Description:	Not reported
Potenital Description:	No Contaminants found
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported

CACTUS MIDDLE SCHOOL (Continued) **S105628851**

Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported
PastUse: AGRICULTURAL - ROW CROPS

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
BLOOMINGTON	93468248	COLTON YARD 19100 SLOVER AVE	COLTON YARD 19100 SLOVER AVE	92324	ERNS
BLOOMINGTON	S103950569	ARCO PRODUCTS CO.	I-10 FREEWAY @ RIVERSIDE AVE	92316	HAZNET
BLOOMINGTON	S106911230	DANNY & J'S AUTO CARE	18111 VALLEY BLVD UNIT A	92316	San Bern. Co. Permit
COLTON	S108743987	CALTRANS DIST 8/CONSTR/EA08-OC1804	RTE 215 KM 4.35-8.05 FROM WASH	92324	HAZNET
COLTON	S108221121	SOUTHERN CALIFORNIA GAS CO COLTON	NE CORNER OF 6TH ST / FOGG ST	92324	HAZNET
COLTON	S107532013		265 W G ST (CROSS-LACADENA)	92324	CDL
COLTON	S106911419	J&S FORKLIFT SERVICES, INC	300 W OLIVE ST UNIT C / D	92324	San Bern. Co. Permit
COLTON	S108419374	IMAGO	300 W OLIVE ST UNIT D	92324	San Bern. Co. Permit
COLTON	S108540947	J & S FORKLIFT SERVICES INC	300 W OLIVE ST UNIT C	92324	DRYCLEANERS
COLTON	1010344275	PUREENERGY (ALLIANCE COLTON)	559 PEPPER AVE (DREWS FACILITY	92324	FINDS
COLTON	S107140182	COLTON GARDEN APTS	2190 RANCHO AVE	92324	HAZNET
COLTON	S108724313	JOAQUIN'S WELDING	2901 S RIVERSIDE AVE UNIT K-1	92324	San Bern. Co. Permit
COLTON	S108724314	JUARITOS CITRUS DISTRIBUTION	2901 S RIVERSIDE AVE UNIT M	92324	San Bern. Co. Permit
COLTON	S108724315	FREDDY'S IRONWORKS	2901 S RIVERSIDE AVE UNIT W	92324	San Bern. Co. Permit
COLTON	S108724316	JAT TRUCKING INC	2901 S RIVERSIDE AVE UNIT P-1	92324	San Bern. Co. Permit
COLTON	S108724317	SOUTHSIDE METAL	2901 S RIVERSIDE AVE UNIT G	92324	San Bern. Co. Permit
COLTON	S108724329	ALLIED STORAGE CONTAINERS	2901 S RIVERSIDE AVE LOT A	92324	San Bern. Co. Permit
COLTON	S108724330	A & SONS TOWING	2901 S RIVERSIDE AVE LOT E	92324	San Bern. Co. Permit
COLTON	S106486949	ARCO TANK FARM	2395 RIVERSIDE AVENUE S		SLIC
RIALTO	S106448555	CIRCLE K # 5249	105 PEPPER AVE	92410	LUST
RIALTO	S104570678	HUD INTOWN PROPERTIES	940 PINE ST N	92376	HAZNET
RIALTO	S103962676	ELIZABETH GILES DDS INC	350 RIVERSIDE AVE	92376	HAZNET
RIALTO	S107537157		935 SAGE ST	92376	CDL
RIALTO	S108087010	ECOLOGY AUTO WRECKING	221 SANTA ANA AVENUE EAST	92376	LUST
RIALTO	S106910715	BISCOMERICA	561 SLOVER AVE	92376	San Bern. Co. Permit
RIALTO	S101591616	ENTENMANN'S OROWEAT	20213 VALLEY BLVD	92376	CA FID UST, SWEEPS UST
RIALTO	S106837882	R & H FIBERGLASS	20159 VALLEY BL	92376	AIRS
RIALTO	S106911280	RESIDENCE	515 W VALLEY BLVD	92376	San Bern. Co. Permit
RIALTO	S106922226	10-10 TRUCK STOP	195 E VALLEY RIALTO CA 92376	92376	SWEEPS UST
RIALTO	S108202595	CLARENCE E BAILEY	515 W VALLEY BLVD	92376	HAZNET
RIALTO	S108748767	INTEGRITY TIRE	476 W VALLEY BLVD	92376	HAZNET
RIALTO	S103636678	HUD	178 WALNUT AVE STE E	92376	HAZNET
SAN BERNARDINO	S101308124	CALTRANS PANARAMA PT.MAINT.ST.	HWY 18, MILEPOST 15.84	92410	LUST
SAN BERNARDINO	S103629593	MELCHOR BRICEOCENO	139 ACACIA AVE	92376	HAZNET
SAN BERNARDINO	1003878981	SECCOMBE LAKE STATE REC AREA	7TH ST BETW SERRIA & WATERMAN	92410	CERC-NFRAP
SAN BERNARDINO	S106910939	JOHN M POWELL O.D.	222 N G ST STE 1	92410	San Bern. Co. Permit
SAN BERNARDINO	S105628833	JONES ELEMENTARY SCHOOL	SEVENTH STREET/F STREET	92410	SCH, ENVIROSTOR
SAN BERNARDINO	S104751426	INLAND BEVERAGE COMPANY	223 G ST	92410	LUST, Cortese

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

FEDERAL RECORDS

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 10/02/2007
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 12/28/2007
Number of Days to Update: 25

Source: EPA
Telephone: N/A
Last EDR Contact: 01/28/2008
Next Scheduled EDR Contact: 04/28/2008
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 3
Telephone 215-814-5418

EPA Region 4
Telephone 404-562-8033

EPA Region 5
Telephone 312-886-6686

EPA Region 10
Telephone 206-553-8665

EPA Region 6
Telephone: 214-655-6659

EPA Region 7
Telephone: 913-551-7247

EPA Region 8
Telephone: 303-312-6774

EPA Region 9
Telephone: 415-947-4246

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 10/02/2007
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 12/28/2007
Number of Days to Update: 25

Source: EPA
Telephone: N/A
Last EDR Contact: 01/28/2008
Next Scheduled EDR Contact: 04/28/2008
Data Release Frequency: Quarterly

DELISTED NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 10/02/2007
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 12/28/2007
Number of Days to Update: 25

Source: EPA
Telephone: N/A
Last EDR Contact: 01/28/2008
Next Scheduled EDR Contact: 04/28/2008
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 02/19/2008
Next Scheduled EDR Contact: 05/19/2008
Data Release Frequency: No Update Planned

CERCLIS: Comprehensive Environmental Response, Compensation, and Liability Information System

CERCLIS contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). CERCLIS contains sites which are either proposed to or on the National Priorities List (NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 01/09/2008
Date Data Arrived at EDR: 02/05/2008
Date Made Active in Reports: 02/20/2008
Number of Days to Update: 15

Source: EPA
Telephone: 703-412-9810
Last EDR Contact: 02/05/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: Quarterly

CERCLIS-NFRAP: CERCLIS No Further Remedial Action Planned

Archived sites are sites that have been removed and archived from the inventory of CERCLIS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

Date of Government Version: 12/03/2007
Date Data Arrived at EDR: 12/06/2007
Date Made Active in Reports: 02/20/2008
Number of Days to Update: 76

Source: EPA
Telephone: 703-412-9810
Last EDR Contact: 12/06/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: Quarterly

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 12/09/2007
Date Data Arrived at EDR: 01/07/2008
Date Made Active in Reports: 02/20/2008
Number of Days to Update: 44

Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 02/15/2008
Next Scheduled EDR Contact: 05/19/2008
Data Release Frequency: Varies

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 12/12/2007
Date Data Arrived at EDR: 12/18/2007
Date Made Active in Reports: 02/20/2008
Number of Days to Update: 64

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 03/03/2008
Next Scheduled EDR Contact: 06/02/2008
Data Release Frequency: Quarterly

RCRA-TSDF: RCRA - Transporters, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 09/11/2007
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 12/28/2007
Number of Days to Update: 25

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 03/06/2008
Next Scheduled EDR Contact: 05/19/2008
Data Release Frequency: Quarterly

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 09/11/2007
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 12/28/2007
Number of Days to Update: 25

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 03/06/2008
Next Scheduled EDR Contact: 05/19/2008
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 09/11/2007
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 12/28/2007
Number of Days to Update: 25

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 03/06/2008
Next Scheduled EDR Contact: 05/19/2008
Data Release Frequency: Quarterly

RCRA-CESQG: RCRA - Conditionally Exempt Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 09/11/2007
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 12/28/2007
Number of Days to Update: 25

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 03/06/2008
Next Scheduled EDR Contact: 05/19/2008
Data Release Frequency: Varies

RCRA-NonGen: RCRA - Non Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 09/11/2007
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 12/28/2007
Number of Days to Update: 25

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 03/06/2008
Next Scheduled EDR Contact: 05/19/2008
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 07/16/2007
Date Data Arrived at EDR: 08/03/2007
Date Made Active in Reports: 10/11/2007
Number of Days to Update: 69

Source: Environmental Protection Agency
Telephone: 703-603-8905
Last EDR Contact: 01/02/2008
Next Scheduled EDR Contact: 03/31/2008
Data Release Frequency: Varies

US INST CONTROL: Sites with Institutional Controls

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 07/16/2007
Date Data Arrived at EDR: 08/03/2007
Date Made Active in Reports: 10/11/2007
Number of Days to Update: 69

Source: Environmental Protection Agency
Telephone: 703-603-8905
Last EDR Contact: 01/02/2008
Next Scheduled EDR Contact: 03/31/2008
Data Release Frequency: Varies

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 12/31/2006
Date Data Arrived at EDR: 01/24/2007
Date Made Active in Reports: 03/12/2007
Number of Days to Update: 47

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 01/23/2008
Next Scheduled EDR Contact: 04/21/2008
Data Release Frequency: Annually

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 10/01/2007
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 12/28/2007
Number of Days to Update: 25

Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 01/17/2008
Next Scheduled EDR Contact: 04/14/2008
Data Release Frequency: Annually

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 11/14/2007
Date Data Arrived at EDR: 11/29/2007
Date Made Active in Reports: 02/20/2008
Number of Days to Update: 83

Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 02/27/2008
Next Scheduled EDR Contact: 05/26/2008
Data Release Frequency: Varies

CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 09/01/2007
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 12/28/2007
Number of Days to Update: 25

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 12/28/2007
Next Scheduled EDR Contact: 03/24/2008
Data Release Frequency: Quarterly

US BROWNFIELDS: A Listing of Brownfields Sites

Included in the listing are brownfields properties addresses by Cooperative Agreement Recipients and brownfields properties addressed by Targeted Brownfields Assessments. Targeted Brownfields Assessments-EPA's Targeted Brownfields Assessments (TBA) program is designed to help states, tribes, and municipalities--especially those without EPA Brownfields Assessment Demonstration Pilots--minimize the uncertainties of contamination often associated with brownfields. Under the TBA program, EPA provides funding and/or technical assistance for environmental assessments at brownfields sites throughout the country. Targeted Brownfields Assessments supplement and work with other efforts under EPA's Brownfields Initiative to promote cleanup and redevelopment of brownfields. Cooperative Agreement Recipients-States, political subdivisions, territories, and Indian tribes become Brownfields Cleanup Revolving Loan Fund (BCRLF) cooperative agreement recipients when they enter into BCRLF cooperative agreements with the U.S. EPA. EPA selects BCRLF cooperative agreement recipients based on a proposal and application process. BCRLF cooperative agreement recipients must use EPA funds provided through BCRLF cooperative agreement for specified brownfields-related cleanup activities.

Date of Government Version: 01/03/2008
Date Data Arrived at EDR: 01/17/2008
Date Made Active in Reports: 02/20/2008
Number of Days to Update: 34

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 01/17/2008
Next Scheduled EDR Contact: 03/10/2008
Data Release Frequency: Semi-Annually

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 11/10/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 62

Source: USGS
Telephone: 703-692-8801
Last EDR Contact: 02/08/2008
Next Scheduled EDR Contact: 05/05/2008
Data Release Frequency: Semi-Annually

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 12/31/2006
Date Data Arrived at EDR: 08/31/2007
Date Made Active in Reports: 10/11/2007
Number of Days to Update: 41

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 01/02/2008
Next Scheduled EDR Contact: 03/31/2008
Data Release Frequency: Varies

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 12/09/2005
Date Data Arrived at EDR: 12/11/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 31

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 03/10/2008
Next Scheduled EDR Contact: 06/09/2008
Data Release Frequency: Varies

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 09/01/2007
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 12/28/2007
Number of Days to Update: 25

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 01/21/2008
Next Scheduled EDR Contact: 04/21/2008
Data Release Frequency: Varies

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 01/14/2008
Date Data Arrived at EDR: 01/22/2008
Date Made Active in Reports: 01/30/2008
Number of Days to Update: 8

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 01/02/2008
Next Scheduled EDR Contact: 03/31/2008
Data Release Frequency: Annually

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 07/13/2007
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: Varies

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 12/28/2007
Date Data Arrived at EDR: 12/28/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 27

Source: EPA, Region 9
Telephone: 415-972-3336
Last EDR Contact: 12/26/2007
Next Scheduled EDR Contact: 03/24/2008
Data Release Frequency: Varies

MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 11/20/2007
Date Data Arrived at EDR: 01/03/2008
Date Made Active in Reports: 02/20/2008
Number of Days to Update: 48

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 01/03/2008
Next Scheduled EDR Contact: 03/24/2008
Data Release Frequency: Semi-Annually

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 04/27/2007
Date Made Active in Reports: 07/05/2007
Number of Days to Update: 69

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 02/29/2008
Next Scheduled EDR Contact: 06/16/2008
Data Release Frequency: Annually

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2002
Date Data Arrived at EDR: 04/14/2006
Date Made Active in Reports: 05/30/2006
Number of Days to Update: 46

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 01/28/2008
Next Scheduled EDR Contact: 04/14/2008
Data Release Frequency: Every 4 Years

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 01/15/2008
Date Data Arrived at EDR: 01/22/2008
Date Made Active in Reports: 01/30/2008
Number of Days to Update: 8

Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: Quarterly

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 01/15/2008
Date Data Arrived at EDR: 01/22/2008
Date Made Active in Reports: 01/30/2008
Number of Days to Update: 8

Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing

A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing

A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 03/13/2007
Date Made Active in Reports: 04/27/2007
Number of Days to Update: 45

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 01/28/2008
Next Scheduled EDR Contact: 04/14/2008
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 07/27/2007
Date Data Arrived at EDR: 08/13/2007
Date Made Active in Reports: 10/11/2007
Number of Days to Update: 59

Source: Environmental Protection Agency
Telephone: 202-564-5088
Last EDR Contact: 01/15/2008
Next Scheduled EDR Contact: 04/14/2008
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 04/12/2007
Date Data Arrived at EDR: 06/08/2007
Date Made Active in Reports: 08/29/2007
Number of Days to Update: 82

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 02/07/2008
Next Scheduled EDR Contact: 05/05/2008
Data Release Frequency: Annually

MLTS: Material Licensing Tracking System

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 10/04/2007
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 12/28/2007
Number of Days to Update: 25

Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
Last EDR Contact: 01/02/2008
Next Scheduled EDR Contact: 03/31/2008
Data Release Frequency: Quarterly

RADINFO: Radiation Information Database

The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 10/30/2007
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 01/31/2008
Next Scheduled EDR Contact: 04/28/2008
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 01/04/2008
Date Data Arrived at EDR: 01/10/2008
Date Made Active in Reports: 02/20/2008
Number of Days to Update: 41

Source: EPA
Telephone: (415) 947-8000
Last EDR Contact: 01/02/2008
Next Scheduled EDR Contact: 03/31/2008
Data Release Frequency: Quarterly

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 03/03/2008
Next Scheduled EDR Contact: 06/02/2008
Data Release Frequency: No Update Planned

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 03/06/2007
Date Made Active in Reports: 04/13/2007
Number of Days to Update: 38

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 12/13/2007
Next Scheduled EDR Contact: 03/10/2008
Data Release Frequency: Biennially

STATE AND LOCAL RECORDS

HIST CAL-SITES: Calsites Database

The Calsites database contains potential or confirmed hazardous substance release properties. In 1996, California EPA reevaluated and significantly reduced the number of sites in the Calsites database. No longer updated by the state agency. It has been replaced by ENVIROSTOR.

Date of Government Version: 08/08/2005
Date Data Arrived at EDR: 08/03/2006
Date Made Active in Reports: 08/24/2006
Number of Days to Update: 21

Source: Department of Toxic Substance Control
Telephone: 916-323-3400
Last EDR Contact: 02/25/2008
Next Scheduled EDR Contact: 05/26/2008
Data Release Frequency: No Update Planned

CA BOND EXP. PLAN: Bond Expenditure Plan

Department of Health Services developed a site-specific expenditure plan as the basis for an appropriation of Hazardous Substance Cleanup Bond Act funds. It is not updated.

Date of Government Version: 01/01/1989
Date Data Arrived at EDR: 07/27/1994
Date Made Active in Reports: 08/02/1994
Number of Days to Update: 6

Source: Department of Health Services
Telephone: 916-255-2118
Last EDR Contact: 05/31/1994
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SCH: School Property Evaluation Program
This category contains proposed and existing school sites that are being evaluated by DTSC for possible hazardous materials contamination. In some cases, these properties may be listed in the CalSites category depending on the level of threat to public health and safety or the environment they pose.

Date of Government Version: 11/27/2007
Date Data Arrived at EDR: 11/28/2007
Date Made Active in Reports: 02/14/2008
Number of Days to Update: 78

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 02/27/2008
Next Scheduled EDR Contact: 02/25/2008
Data Release Frequency: Quarterly

TOXIC PITS: Toxic Pits Cleanup Act Sites
Toxic PITS Cleanup Act Sites. TOXIC PITS identifies sites suspected of containing hazardous substances where cleanup has not yet been completed.

Date of Government Version: 07/01/1995
Date Data Arrived at EDR: 08/30/1995
Date Made Active in Reports: 09/26/1995
Number of Days to Update: 27

Source: State Water Resources Control Board
Telephone: 916-227-4364
Last EDR Contact: 02/11/2008
Next Scheduled EDR Contact: 04/28/2008
Data Release Frequency: No Update Planned

SWF/LF (SWIS): Solid Waste Information System
Active, Closed and Inactive Landfills. SWF/LF records typically contain an inve ntory of solid waste disposal facilities or landfills. These may be active or i nactive facilities or open dumps that failed to meet RCRA Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 12/12/2007
Date Data Arrived at EDR: 12/13/2007
Date Made Active in Reports: 02/14/2008
Number of Days to Update: 63

Source: Integrated Waste Management Board
Telephone: 916-341-6320
Last EDR Contact: 12/13/2007
Next Scheduled EDR Contact: 03/10/2008
Data Release Frequency: Quarterly

WMUDS/SWAT: Waste Management Unit Database
Waste Management Unit Database System. WMUDS is used by the State Water Resources Control Board staff and the Regional Water Quality Control Boards for program tracking and inventory of waste management units. WMUDS is composed of the following databases: Facility Information, Scheduled Inspections Information, Waste Management Unit Information, SWAT Program Information, SWAT Report Summary Information, SWAT Report Summary Data, Chapter 15 (formerly Subchapter 15) Information, Chapter 15 Monitoring Parameters, TPCA Program Information, RCRA Program Information, Closure Information, and Interested Parties Information.

Date of Government Version: 04/01/2000
Date Data Arrived at EDR: 04/10/2000
Date Made Active in Reports: 05/10/2000
Number of Days to Update: 30

Source: State Water Resources Control Board
Telephone: 916-227-4448
Last EDR Contact: 03/03/2008
Next Scheduled EDR Contact: 06/02/2008
Data Release Frequency: Quarterly

CA WDS: Waste Discharge System
Sites which have been issued waste discharge requirements.

Date of Government Version: 06/19/2007
Date Data Arrived at EDR: 06/20/2007
Date Made Active in Reports: 06/29/2007
Number of Days to Update: 9

Source: State Water Resources Control Board
Telephone: 916-341-5227
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: Quarterly

CORTESE: "Cortese" Hazardous Waste & Substances Sites List
The sites for the list are designated by the State Water Resource Control Board (LUST), the Integrated Waste Board (SWF/LS), and the Department of Toxic Substances Control (Cal-Sites). This listing is no longer updated by the state agency.

Date of Government Version: 04/01/2001
Date Data Arrived at EDR: 05/29/2001
Date Made Active in Reports: 07/26/2001
Number of Days to Update: 58

Source: CAL EPA/Office of Emergency Information
Telephone: 916-323-3400
Last EDR Contact: 01/21/2008
Next Scheduled EDR Contact: 04/21/2008
Data Release Frequency: No Update Planned

SWRCY: Recycler Database
A listing of recycling facilities in California.

Date of Government Version: 01/07/2008
Date Data Arrived at EDR: 01/09/2008
Date Made Active in Reports: 02/14/2008
Number of Days to Update: 36

Source: Department of Conservation
Telephone: 916-323-3836
Last EDR Contact: 01/09/2008
Next Scheduled EDR Contact: 04/07/2008
Data Release Frequency: Quarterly

LUST REG 9: Leaking Underground Storage Tank Report
Orange, Riverside, San Diego counties. For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 03/01/2001
Date Data Arrived at EDR: 04/23/2001
Date Made Active in Reports: 05/21/2001
Number of Days to Update: 28

Source: California Regional Water Quality Control Board San Diego Region (9)
Telephone: 858-637-5595
Last EDR Contact: 01/15/2008
Next Scheduled EDR Contact: 04/14/2008
Data Release Frequency: No Update Planned

LUST REG 8: Leaking Underground Storage Tanks
California Regional Water Quality Control Board Santa Ana Region (8). For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 02/14/2005
Date Data Arrived at EDR: 02/15/2005
Date Made Active in Reports: 03/28/2005
Number of Days to Update: 41

Source: California Regional Water Quality Control Board Santa Ana Region (8)
Telephone: 909-782-4496
Last EDR Contact: 02/05/2008
Next Scheduled EDR Contact: 05/05/2008
Data Release Frequency: Varies

LUST REG 6V: Leaking Underground Storage Tank Case Listing
Leaking Underground Storage Tank locations. Inyo, Kern, Los Angeles, Mono, San Bernardino counties.

Date of Government Version: 06/07/2005
Date Data Arrived at EDR: 06/07/2005
Date Made Active in Reports: 06/29/2005
Number of Days to Update: 22

Source: California Regional Water Quality Control Board Victorville Branch Office (6)
Telephone: 760-241-7365
Last EDR Contact: 01/02/2008
Next Scheduled EDR Contact: 03/31/2008
Data Release Frequency: No Update Planned

LUST REG 6L: Leaking Underground Storage Tank Case Listing
For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 09/09/2003
Date Data Arrived at EDR: 09/10/2003
Date Made Active in Reports: 10/07/2003
Number of Days to Update: 27

Source: California Regional Water Quality Control Board Lahontan Region (6)
Telephone: 530-542-5572
Last EDR Contact: 03/03/2008
Next Scheduled EDR Contact: 06/02/2008
Data Release Frequency: No Update Planned

LUST REG 5: Leaking Underground Storage Tank Database
Leaking Underground Storage Tank locations. Alameda, Alpine, Amador, Butte, Colusa, Contra Costa, Calveras, El Dorado, Fresno, Glenn, Kern, Kings, Lake, Lassen, Madera, Mariposa, Merced, Modoc, Napa, Nevada, Placer, Plumas, Sacramento, San Joaquin, Shasta, Solano, Stanislaus, Sutter, Tehama, Tulare, Tuolumne, Yolo, Yuba counties.

Date of Government Version: 01/01/2008
Date Data Arrived at EDR: 01/23/2008
Date Made Active in Reports: 02/14/2008
Number of Days to Update: 22

Source: California Regional Water Quality Control Board Central Valley Region (5)
Telephone: 916-464-4834
Last EDR Contact: 01/23/2008
Next Scheduled EDR Contact: 03/31/2008
Data Release Frequency: Quarterly

LUST REG 4: Underground Storage Tank Leak List
Los Angeles, Ventura counties. For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 09/07/2004
Date Data Arrived at EDR: 09/07/2004
Date Made Active in Reports: 10/12/2004
Number of Days to Update: 35

Source: California Regional Water Quality Control Board Los Angeles Region (4)
Telephone: 213-576-6710
Last EDR Contact: 12/26/2007
Next Scheduled EDR Contact: 03/24/2008
Data Release Frequency: No Update Planned

LUST REG 3: Leaking Underground Storage Tank Database
Leaking Underground Storage Tank locations. Monterey, San Benito, San Luis Obispo, Santa Barbara, Santa Cruz counties.

Date of Government Version: 05/19/2003
Date Data Arrived at EDR: 05/19/2003
Date Made Active in Reports: 06/02/2003
Number of Days to Update: 14

Source: California Regional Water Quality Control Board Central Coast Region (3)
Telephone: 805-542-4786
Last EDR Contact: 02/11/2008
Next Scheduled EDR Contact: 05/12/2008
Data Release Frequency: No Update Planned

LUST REG 2: Fuel Leak List
Leaking Underground Storage Tank locations. Alameda, Contra Costa, Marin, Napa, San Francisco, San Mateo, Santa Clara, Solano, Sonoma counties.

Date of Government Version: 09/30/2004
Date Data Arrived at EDR: 10/20/2004
Date Made Active in Reports: 11/19/2004
Number of Days to Update: 30

Source: California Regional Water Quality Control Board San Francisco Bay Region (2)
Telephone: 510-622-2433
Last EDR Contact: 01/07/2008
Next Scheduled EDR Contact: 04/07/2008
Data Release Frequency: Quarterly

LUST REG 1: Active Toxic Site Investigation
Del Norte, Humboldt, Lake, Mendocino, Modoc, Siskiyou, Sonoma, Trinity counties. For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 02/01/2001
Date Data Arrived at EDR: 02/28/2001
Date Made Active in Reports: 03/29/2001
Number of Days to Update: 29

Source: California Regional Water Quality Control Board North Coast (1)
Telephone: 707-570-3769
Last EDR Contact: 02/19/2008
Next Scheduled EDR Contact: 05/19/2008
Data Release Frequency: No Update Planned

LUST: Geotracker's Leaking Underground Fuel Tank Report
Leaking Underground Storage Tank Incident Reports. LUST records contain an inventory of reported leaking underground storage tank incidents. Not all states maintain these records, and the information stored varies by state. For more information on a particular leaking underground storage tank sites, please contact the appropriate regulatory agency.

Date of Government Version: 01/07/2008
Date Data Arrived at EDR: 01/09/2008
Date Made Active in Reports: 02/14/2008
Number of Days to Update: 36

Source: State Water Resources Control Board
Telephone: see region list
Last EDR Contact: 01/09/2008
Next Scheduled EDR Contact: 04/07/2008
Data Release Frequency: Quarterly

LUST REG 7: Leaking Underground Storage Tank Case Listing
Leaking Underground Storage Tank locations. Imperial, Riverside, San Diego, Santa Barbara counties.

Date of Government Version: 02/26/2004
Date Data Arrived at EDR: 02/26/2004
Date Made Active in Reports: 03/24/2004
Number of Days to Update: 27

Source: California Regional Water Quality Control Board Colorado River Basin Region (7)
Telephone: 760-776-8943
Last EDR Contact: 02/19/2008
Next Scheduled EDR Contact: 05/19/2008
Data Release Frequency: No Update Planned

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

CA FID UST: Facility Inventory Database
The Facility Inventory Database (FID) contains a historical listing of active and inactive underground storage tank locations from the State Water Resource Control Board. Refer to local/county source for current data.

Date of Government Version: 10/31/1994
Date Data Arrived at EDR: 09/05/1995
Date Made Active in Reports: 09/29/1995
Number of Days to Update: 24

Source: California Environmental Protection Agency
Telephone: 916-341-5851
Last EDR Contact: 12/28/1998
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SLIC: Statewide SLIC Cases
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 01/07/2008
Date Data Arrived at EDR: 01/09/2008
Date Made Active in Reports: 02/14/2008
Number of Days to Update: 36

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 01/09/2008
Next Scheduled EDR Contact: 04/07/2008
Data Release Frequency: Varies

SLIC REG 1: Active Toxic Site Investigations
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 04/03/2003
Date Data Arrived at EDR: 04/07/2003
Date Made Active in Reports: 04/25/2003
Number of Days to Update: 18

Source: California Regional Water Quality Control Board, North Coast Region (1)
Telephone: 707-576-2220
Last EDR Contact: 02/19/2008
Next Scheduled EDR Contact: 05/19/2008
Data Release Frequency: No Update Planned

SLIC REG 2: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 09/30/2004
Date Data Arrived at EDR: 10/20/2004
Date Made Active in Reports: 11/19/2004
Number of Days to Update: 30

Source: Regional Water Quality Control Board San Francisco Bay Region (2)
Telephone: 510-286-0457
Last EDR Contact: 01/07/2008
Next Scheduled EDR Contact: 04/07/2008
Data Release Frequency: Quarterly

SLIC REG 3: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 05/18/2006
Date Data Arrived at EDR: 05/18/2006
Date Made Active in Reports: 06/15/2006
Number of Days to Update: 28

Source: California Regional Water Quality Control Board Central Coast Region (3)
Telephone: 805-549-3147
Last EDR Contact: 02/11/2008
Next Scheduled EDR Contact: 05/12/2008
Data Release Frequency: Semi-Annually

SLIC REG 4: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 11/17/2004
Date Data Arrived at EDR: 11/18/2004
Date Made Active in Reports: 01/04/2005
Number of Days to Update: 47

Source: Region Water Quality Control Board Los Angeles Region (4)
Telephone: 213-576-6600
Last EDR Contact: 01/21/2008
Next Scheduled EDR Contact: 04/21/2008
Data Release Frequency: Varies

SLIC REG 5: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 04/01/2005
Date Data Arrived at EDR: 04/05/2005
Date Made Active in Reports: 04/21/2005
Number of Days to Update: 16

Source: Regional Water Quality Control Board Central Valley Region (5)
Telephone: 916-464-3291
Last EDR Contact: 01/02/2008
Next Scheduled EDR Contact: 03/31/2008
Data Release Frequency: Semi-Annually

SLIC REG 6V: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 05/24/2005
Date Data Arrived at EDR: 05/25/2005
Date Made Active in Reports: 06/16/2005
Number of Days to Update: 22

Source: Regional Water Quality Control Board, Victorville Branch
Telephone: 619-241-6583
Last EDR Contact: 01/02/2008
Next Scheduled EDR Contact: 03/31/2008
Data Release Frequency: Semi-Annually

SLIC REG 6L: SLIC Sites
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 09/07/2004
Date Data Arrived at EDR: 09/07/2004
Date Made Active in Reports: 10/12/2004
Number of Days to Update: 35

Source: California Regional Water Quality Control Board, Lahontan Region
Telephone: 530-542-5574
Last EDR Contact: 03/03/2008
Next Scheduled EDR Contact: 06/02/2008
Data Release Frequency: No Update Planned

SLIC REG 7: SLIC List
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 11/24/2004
Date Data Arrived at EDR: 11/29/2004
Date Made Active in Reports: 01/04/2005
Number of Days to Update: 36

Source: California Regional Quality Control Board, Colorado River Basin Region
Telephone: 760-346-7491
Last EDR Contact: 03/03/2008
Next Scheduled EDR Contact: 05/19/2008
Data Release Frequency: No Update Planned

SLIC REG 8: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 10/02/2007
Date Data Arrived at EDR: 10/03/2007
Date Made Active in Reports: 11/07/2007
Number of Days to Update: 35

Source: California Region Water Quality Control Board Santa Ana Region (8)
Telephone: 951-782-3298
Last EDR Contact: 01/02/2008
Next Scheduled EDR Contact: 03/31/2008
Data Release Frequency: Semi-Annually

SLIC REG 9: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 09/10/2007
Date Data Arrived at EDR: 09/11/2007
Date Made Active in Reports: 09/28/2007
Number of Days to Update: 17

Source: California Regional Water Quality Control Board San Diego Region (9)
Telephone: 858-467-2980
Last EDR Contact: 02/25/2008
Next Scheduled EDR Contact: 05/26/2008
Data Release Frequency: Annually

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

UST: Active UST Facilities
Active UST facilities gathered from the local regulatory agencies

Date of Government Version: 01/07/2008
Date Data Arrived at EDR: 01/09/2008
Date Made Active in Reports: 02/08/2008
Number of Days to Update: 30

Source: SWRCB
Telephone: 916-480-1028
Last EDR Contact: 01/09/2008
Next Scheduled EDR Contact: 04/07/2008
Data Release Frequency: Semi-Annually

UST MENDOCINO: Mendocino County UST Database
A listing of underground storage tank locations in Mendocino County.

Date of Government Version: 12/26/2007
Date Data Arrived at EDR: 12/28/2007
Date Made Active in Reports: 02/08/2008
Number of Days to Update: 42

Source: Department of Public Health
Telephone: 707-463-4466
Last EDR Contact: 12/26/2007
Next Scheduled EDR Contact: 03/24/2008
Data Release Frequency: Varies

HIST UST: Hazardous Substance Storage Container Database
The Hazardous Substance Storage Container Database is a historical listing of UST sites. Refer to local/county source for current data.

Date of Government Version: 10/15/1990
Date Data Arrived at EDR: 01/25/1991
Date Made Active in Reports: 02/12/1991
Number of Days to Update: 18

Source: State Water Resources Control Board
Telephone: 916-341-5851
Last EDR Contact: 07/26/2001
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

LIENS: Environmental Liens Listing
A listing of property locations with environmental liens for California where DTSC is a lien holder.

Date of Government Version: 11/06/2007
Date Data Arrived at EDR: 11/09/2007
Date Made Active in Reports: 02/14/2008
Number of Days to Update: 97

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 02/05/2008
Next Scheduled EDR Contact: 05/05/2008
Data Release Frequency: Varies

AST: Aboveground Petroleum Storage Tank Facilities
Registered Aboveground Storage Tanks.

Date of Government Version: 11/01/2007
Date Data Arrived at EDR: 11/27/2007
Date Made Active in Reports: 02/14/2008
Number of Days to Update: 79

Source: State Water Resources Control Board
Telephone: 916-341-5712
Last EDR Contact: 01/28/2008
Next Scheduled EDR Contact: 04/28/2008
Data Release Frequency: Quarterly

SWEEPS UST: SWEEPS UST Listing
Statewide Environmental Evaluation and Planning System. This underground storage tank listing was updated and maintained by a company contacted by the SWRCB in the early 1990's. The listing is no longer updated or maintained. The local agency is the contact for more information on a site on the SWEEPS list.

Date of Government Version: 06/01/1994
Date Data Arrived at EDR: 07/07/2005
Date Made Active in Reports: 08/11/2005
Number of Days to Update: 35

Source: State Water Resources Control Board
Telephone: N/A
Last EDR Contact: 06/03/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

CHMIRS: California Hazardous Material Incident Report System
California Hazardous Material Incident Reporting System. CHMIRS contains information on reported hazardous material incidents (accidental releases or spills).

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 02/23/2007
Date Made Active in Reports: 04/06/2007
Number of Days to Update: 42

Source: Office of Emergency Services
Telephone: 916-845-8400
Last EDR Contact: 02/19/2008
Next Scheduled EDR Contact: 05/19/2008
Data Release Frequency: Varies

NOTIFY 65: Proposition 65 Records

Proposition 65 Notification Records. NOTIFY 65 contains facility notifications about any release which could impact drinking water and thereby expose the public to a potential health risk.

Date of Government Version: 10/21/1993
Date Data Arrived at EDR: 11/01/1993
Date Made Active in Reports: 11/19/1993
Number of Days to Update: 18

Source: State Water Resources Control Board
Telephone: 916-445-3846
Last EDR Contact: 01/15/2008
Next Scheduled EDR Contact: 04/14/2008
Data Release Frequency: No Update Planned

DEED: Deed Restriction Listing

Site Mitigation and Brownfields Reuse Program Facility Sites with Deed Restrictions & Hazardous Waste Management Program Facility Sites with Deed / Land Use Restriction. The DTSC Site Mitigation and Brownfields Reuse Program (SMBRP) list includes sites cleaned up under the program's oversight and generally does not include current or former hazardous waste facilities that required a hazardous waste facility permit. The list represents deed restrictions that are active. Some sites have multiple deed restrictions. The DTSC Hazardous Waste Management Program (HWMP) has developed a list of current or former hazardous waste facilities that have a recorded land use restriction at the local county recorder's office. The land use restrictions on this list were required by the DTSC HWMP as a result of the presence of hazardous substances that remain on site after the facility (or part of the facility) has been closed or cleaned up. The types of land use restriction include deed notice, deed restriction, or a land use restriction that binds current and future owners.

Date of Government Version: 01/03/2008
Date Data Arrived at EDR: 01/04/2008
Date Made Active in Reports: 02/14/2008
Number of Days to Update: 41

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 01/04/2008
Next Scheduled EDR Contact: 03/31/2008
Data Release Frequency: Semi-Annually

VCP: Voluntary Cleanup Program Properties

Contains low threat level properties with either confirmed or unconfirmed releases and the project proponents have request that DTSC oversee investigation and/or cleanup activities and have agreed to provide coverage for DTSC's costs.

Date of Government Version: 11/27/2007
Date Data Arrived at EDR: 11/28/2007
Date Made Active in Reports: 02/14/2008
Number of Days to Update: 78

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 02/27/2008
Next Scheduled EDR Contact: 05/26/2008
Data Release Frequency: Quarterly

DRYCLEANERS: Cleaner Facilities

A list of drycleaner related facilities that have EPA ID numbers. These are facilities with certain SIC codes: power laundries, family and commercial; garment pressing and cleaner's agents; linen supply; coin-operated laundries and cleaning; drycleaning plants, except rugs; carpet and upholster cleaning; industrial launderers; laundry and garment services.

Date of Government Version: 07/31/2007
Date Data Arrived at EDR: 07/31/2007
Date Made Active in Reports: 08/09/2007
Number of Days to Update: 9

Source: Department of Toxic Substance Control
Telephone: 916-327-4498
Last EDR Contact: 01/02/2008
Next Scheduled EDR Contact: 03/31/2008
Data Release Frequency: Annually

WIP: Well Investigation Program Case List

Well Investigation Program case in the San Gabriel and San Fernando Valley area.

Date of Government Version: 10/25/2007
Date Data Arrived at EDR: 01/23/2008
Date Made Active in Reports: 02/14/2008
Number of Days to Update: 22

Source: Los Angeles Water Quality Control Board
Telephone: 213-576-6726
Last EDR Contact: 01/23/2008
Next Scheduled EDR Contact: 04/21/2008
Data Release Frequency: Varies

CDL: Clandestine Drug Labs

A listing of drug lab locations. Listing of a location in this database does not indicate that any illegal drug lab materials were or were not present there, and does not constitute a determination that the location either requires or does not require additional cleanup work.

Date of Government Version: 09/30/2007
Date Data Arrived at EDR: 10/15/2007
Date Made Active in Reports: 11/07/2007
Number of Days to Update: 23

Source: Department of Toxic Substances Control
Telephone: 916-255-6504
Last EDR Contact: 02/19/2008
Next Scheduled EDR Contact: 04/21/2008
Data Release Frequency: Varies

RESPONSE: State Response Sites

Identifies confirmed release sites where DTSC is involved in remediation, either in a lead or oversight capacity. These confirmed release sites are generally high-priority and high potential risk.

Date of Government Version: 11/27/2007
Date Data Arrived at EDR: 11/28/2007
Date Made Active in Reports: 02/14/2008
Number of Days to Update: 78

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 02/27/2008
Next Scheduled EDR Contact: 05/26/2008
Data Release Frequency: Quarterly

HAZNET: Facility and Manifest Data

Facility and Manifest Data. The data is extracted from the copies of hazardous waste manifests received each year by the DTSC. The annual volume of manifests is typically 700,000 - 1,000,000 annually, representing approximately 350,000 - 500,000 shipments. Data are from the manifests submitted without correction, and therefore many contain some invalid values for data elements such as generator ID, TSD ID, waste category, and disposal method.

Date of Government Version: 12/31/2006
Date Data Arrived at EDR: 10/04/2007
Date Made Active in Reports: 11/07/2007
Number of Days to Update: 34

Source: California Environmental Protection Agency
Telephone: 916-255-1136
Last EDR Contact: 02/08/2008
Next Scheduled EDR Contact: 05/05/2008
Data Release Frequency: Annually

EMI: Emissions Inventory Data

Toxics and criteria pollutant emissions data collected by the ARB and local air pollution agencies.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 04/17/2007
Date Made Active in Reports: 05/10/2007
Number of Days to Update: 23

Source: California Air Resources Board
Telephone: 916-322-2990
Last EDR Contact: 01/18/2008
Next Scheduled EDR Contact: 04/14/2008
Data Release Frequency: Varies

ENVIROSTOR: EnviroStor Database

The Department of Toxic Substances Control's (DTSC's) Site Mitigation and Brownfields Reuse Program's (SMBRP's) EnviroStor database identifes sites that have known contamination or sites for which there may be reasons to investigate further. The database includes the following site types: Federal Superfund sites (National Priorities List (NPL)); State Response, including Military Facilities and State Superfund; Voluntary Cleanup; and School sites. EnviroStor provides similar information to the information that was available in CalSites, and provides additional site information, including, but not limited to, identification of formerly-contaminated properties that have been released for reuse, properties where environmental deed restrictions have been recorded to prevent inappropriate land uses, and risk characterization information that is used to assess potential impacts to public health and the environment at contaminated sites.

Date of Government Version: 11/27/2007
Date Data Arrived at EDR: 11/28/2007
Date Made Active in Reports: 02/14/2008
Number of Days to Update: 78

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 02/27/2008
Next Scheduled EDR Contact: 05/26/2008
Data Release Frequency: Quarterly

HAULERS: Registered Waste Tire Haulers Listing
A listing of registered waste tire haulers.

Date of Government Version: 09/17/2007
Date Data Arrived at EDR: 09/18/2007
Date Made Active in Reports: 09/28/2007
Number of Days to Update: 10

Source: Integrated Waste Management Board
Telephone: 916-341-6422
Last EDR Contact: 03/10/2008
Next Scheduled EDR Contact: 06/09/2008
Data Release Frequency: Varies

TRIBAL RECORDS

INDIAN RESERV: Indian Reservations
This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 12/08/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 34

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 02/08/2008
Next Scheduled EDR Contact: 05/05/2008
Data Release Frequency: Semi-Annually

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands
Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 02/25/2008
Next Scheduled EDR Contact: 05/26/2008
Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 06/01/2007
Date Data Arrived at EDR: 06/14/2007
Date Made Active in Reports: 07/05/2007
Number of Days to Update: 21

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 02/15/2008
Next Scheduled EDR Contact: 05/19/2008
Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 12/03/2007
Date Data Arrived at EDR: 12/06/2007
Date Made Active in Reports: 12/28/2007
Number of Days to Update: 22

Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 02/15/2008
Next Scheduled EDR Contact: 05/19/2008
Data Release Frequency: Quarterly

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 12/01/2006
Date Data Arrived at EDR: 12/01/2006
Date Made Active in Reports: 01/29/2007
Number of Days to Update: 59

Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 02/15/2008
Next Scheduled EDR Contact: 05/19/2008
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 12/12/2007
Date Data Arrived at EDR: 12/12/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 43

Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 02/15/2008
Next Scheduled EDR Contact: 05/19/2008
Data Release Frequency: Varies

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 11/30/2007
Date Data Arrived at EDR: 11/30/2007
Date Made Active in Reports: 12/28/2007
Number of Days to Update: 28

Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 02/15/2008
Next Scheduled EDR Contact: 05/19/2008
Data Release Frequency: Quarterly

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 11/27/2007
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 02/15/2008
Next Scheduled EDR Contact: 05/19/2008
Data Release Frequency: Quarterly

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 09/05/2007
Date Data Arrived at EDR: 10/02/2007
Date Made Active in Reports: 10/11/2007
Number of Days to Update: 9

Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 02/15/2008
Next Scheduled EDR Contact: 05/19/2008
Data Release Frequency: Semi-Annually

INDIAN UST R1: Underground Storage Tanks on Indian Land
A listing of underground storage tank locations on Indian Land.

Date of Government Version: 12/01/2006
Date Data Arrived at EDR: 12/01/2006
Date Made Active in Reports: 01/29/2007
Number of Days to Update: 59

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 02/15/2008
Next Scheduled EDR Contact: 05/19/2008
Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land
No description is available for this data

Date of Government Version: 12/12/2007
Date Data Arrived at EDR: 12/12/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 43

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 02/15/2008
Next Scheduled EDR Contact: 05/19/2008
Data Release Frequency: Semi-Annually

INDIAN UST R7: Underground Storage Tanks on Indian Land
No description is available for this data

Date of Government Version: 06/01/2007
Date Data Arrived at EDR: 06/14/2007
Date Made Active in Reports: 07/05/2007
Number of Days to Update: 21

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 02/15/2008
Next Scheduled EDR Contact: 05/19/2008
Data Release Frequency: Varies

INDIAN UST R9: Underground Storage Tanks on Indian Land
No description is available for this data

Date of Government Version: 11/30/2007
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 02/15/2008
Next Scheduled EDR Contact: 05/19/2008
Data Release Frequency: Quarterly

INDIAN UST R4: Underground Storage Tanks on Indian Land
No description is available for this data

Date of Government Version: 09/05/2007
Date Data Arrived at EDR: 10/02/2007
Date Made Active in Reports: 10/11/2007
Number of Days to Update: 9

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 02/15/2008
Next Scheduled EDR Contact: 05/19/2008
Data Release Frequency: Semi-Annually

INDIAN UST R5: Underground Storage Tanks on Indian Land
No description is available for this data

Date of Government Version: 12/21/2007
Date Data Arrived at EDR: 12/21/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 34

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 02/15/2008
Next Scheduled EDR Contact: 05/19/2008
Data Release Frequency: Varies

INDIAN UST R10: Underground Storage Tanks on Indian Land
No description is available for this data

Date of Government Version: 11/27/2007
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 02/15/2008
Next Scheduled EDR Contact: 05/19/2008
Data Release Frequency: Quarterly

INDIAN UST R8: Underground Storage Tanks on Indian Land
No description is available for this data

Date of Government Version: 12/03/2007
Date Data Arrived at EDR: 12/06/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 49

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 02/15/2008
Next Scheduled EDR Contact: 05/19/2008
Data Release Frequency: Quarterly

EDR PROPRIETARY RECORDS

Manufactured Gas Plants: EDR Proprietary Manufactured Gas Plants
The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

EDR Historical Auto Stations: EDR Proprietary Historic Gas Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Historical Cleaners: EDR Proprietary Historic Dry Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

COUNTY RECORDS

ALAMEDA COUNTY:

Contaminated Sites

A listing of contaminated sites overseen by the Toxic Release Program (oil and groundwater contamination from chemical releases and spills) and the Leaking Underground Storage Tank Program (soil and ground water contamination from leaking petroleum USTs).

Date of Government Version: 01/28/2008
Date Data Arrived at EDR: 01/29/2008
Date Made Active in Reports: 02/14/2008
Number of Days to Update: 16

Source: Alameda County Environmental Health Services
Telephone: 510-567-6700
Last EDR Contact: 01/21/2008
Next Scheduled EDR Contact: 04/21/2008
Data Release Frequency: Semi-Annually

Underground Tanks

Underground storage tank sites located in Alameda county.

Date of Government Version: 01/28/2008
Date Data Arrived at EDR: 01/29/2008
Date Made Active in Reports: 02/08/2008
Number of Days to Update: 10

Source: Alameda County Environmental Health Services
Telephone: 510-567-6700
Last EDR Contact: 01/21/2008
Next Scheduled EDR Contact: 04/21/2008
Data Release Frequency: Semi-Annually

CONTRA COSTA COUNTY:

Site List

List includes sites from the underground tank, hazardous waste generator and business plan/2185 programs.

Date of Government Version: 12/04/2007
Date Data Arrived at EDR: 12/06/2007
Date Made Active in Reports: 02/14/2008
Number of Days to Update: 70

Source: Contra Costa Health Services Department
Telephone: 925-646-2286
Last EDR Contact: 02/25/2008
Next Scheduled EDR Contact: 05/26/2008
Data Release Frequency: Semi-Annually

FRESNO COUNTY:

CUPA Resources List

Certified Unified Program Agency. CUPA's are responsible for implementing a unified hazardous materials and hazardous waste management regulatory program. The agency provides oversight of businesses that deal with hazardous materials, operate underground storage tanks or aboveground storage tanks.

Date of Government Version: 01/16/2008
Date Data Arrived at EDR: 01/17/2008
Date Made Active in Reports: 02/14/2008
Number of Days to Update: 28

Source: Dept. of Community Health
Telephone: 559-445-3271
Last EDR Contact: 01/17/2008
Next Scheduled EDR Contact: 02/04/2008
Data Release Frequency: Semi-Annually

KERN COUNTY:

Underground Storage Tank Sites & Tank Listing

Kern County Sites and Tanks Listing.

Date of Government Version: 12/17/2007
Date Data Arrived at EDR: 12/18/2007
Date Made Active in Reports: 02/08/2008
Number of Days to Update: 52

Source: Kern County Environment Health Services Department
Telephone: 661-862-8700
Last EDR Contact: 03/03/2008
Next Scheduled EDR Contact: 06/02/2008
Data Release Frequency: Quarterly

LOS ANGELES COUNTY:

San Gabriel Valley Areas of Concern

San Gabriel Valley areas where VOC contamination is at or above the MCL as designated by region 9 EPA office.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 07/07/1999
Date Made Active in Reports: N/A
Number of Days to Update: 0

Source: EPA Region 9
Telephone: 415-972-3178
Last EDR Contact: 02/19/2008
Next Scheduled EDR Contact: 04/14/2008
Data Release Frequency: No Update Planned

HMS: Street Number List

Industrial Waste and Underground Storage Tank Sites.

Date of Government Version: 11/29/2007
Date Data Arrived at EDR: 01/22/2008
Date Made Active in Reports: 02/14/2008
Number of Days to Update: 23

Source: Department of Public Works
Telephone: 626-458-3517
Last EDR Contact: 02/11/2008
Next Scheduled EDR Contact: 05/12/2008
Data Release Frequency: Semi-Annually

List of Solid Waste Facilities

Solid Waste Facilities in Los Angeles County.

Date of Government Version: 11/13/2007
Date Data Arrived at EDR: 11/20/2007
Date Made Active in Reports: 02/14/2008
Number of Days to Update: 86

Source: La County Department of Public Works
Telephone: 818-458-5185
Last EDR Contact: 02/14/2008
Next Scheduled EDR Contact: 05/12/2008
Data Release Frequency: Varies

City of Los Angeles Landfills

Landfills owned and maintained by the City of Los Angeles.

Date of Government Version: 03/01/2007
Date Data Arrived at EDR: 03/27/2007
Date Made Active in Reports: 04/27/2007
Number of Days to Update: 31

Source: Engineering & Construction Division
Telephone: 213-473-7869
Last EDR Contact: 12/10/2007
Next Scheduled EDR Contact: 03/10/2008
Data Release Frequency: Varies

Site Mitigation List
Industrial sites that have had some sort of spill or complaint.

Date of Government Version: 05/30/2007
Date Data Arrived at EDR: 07/11/2007
Date Made Active in Reports: 08/09/2007
Number of Days to Update: 29

Source: Community Health Services
Telephone: 323-890-7806
Last EDR Contact: 02/11/2008
Next Scheduled EDR Contact: 05/12/2008
Data Release Frequency: Annually

City of El Segundo Underground Storage Tank
Underground storage tank sites located in El Segundo city.

Date of Government Version: 11/13/2007
Date Data Arrived at EDR: 11/20/2007
Date Made Active in Reports: 02/08/2008
Number of Days to Update: 80

Source: City of El Segundo Fire Department
Telephone: 310-524-2236
Last EDR Contact: 02/11/2008
Next Scheduled EDR Contact: 05/12/2008
Data Release Frequency: Semi-Annually

City of Long Beach Underground Storage Tank
Underground storage tank sites located in the city of Long Beach.

Date of Government Version: 03/28/2003
Date Data Arrived at EDR: 10/23/2003
Date Made Active in Reports: 11/26/2003
Number of Days to Update: 34

Source: City of Long Beach Fire Department
Telephone: 562-570-2563
Last EDR Contact: 02/19/2008
Next Scheduled EDR Contact: 05/19/2008
Data Release Frequency: Annually

City of Torrance Underground Storage Tank
Underground storage tank sites located in the city of Torrance.

Date of Government Version: 12/13/2007
Date Data Arrived at EDR: 12/14/2007
Date Made Active in Reports: 02/08/2008
Number of Days to Update: 56

Source: City of Torrance Fire Department
Telephone: 310-618-2973
Last EDR Contact: 02/25/2008
Next Scheduled EDR Contact: 05/12/2008
Data Release Frequency: Semi-Annually

MARIN COUNTY:

Underground Storage Tank Sites
Currently permitted USTs in Marin County.

Date of Government Version: 11/29/2007
Date Data Arrived at EDR: 12/19/2007
Date Made Active in Reports: 02/08/2008
Number of Days to Update: 51

Source: Public Works Department Waste Management
Telephone: 415-499-6647
Last EDR Contact: 01/28/2008
Next Scheduled EDR Contact: 04/28/2008
Data Release Frequency: Semi-Annually

NAPA COUNTY:

Sites With Reported Contamination
A listing of leaking underground storage tank sites located in Napa county.

Date of Government Version: 01/15/2008
Date Data Arrived at EDR: 01/16/2008
Date Made Active in Reports: 02/14/2008
Number of Days to Update: 29

Source: Napa County Department of Environmental Management
Telephone: 707-253-4269
Last EDR Contact: 01/07/2008
Next Scheduled EDR Contact: 03/24/2008
Data Release Frequency: Semi-Annually

Closed and Operating Underground Storage Tank Sites
Underground storage tank sites located in Napa county.

Date of Government Version: 01/15/2008
Date Data Arrived at EDR: 01/16/2008
Date Made Active in Reports: 02/08/2008
Number of Days to Update: 23

Source: Napa County Department of Environmental Management
Telephone: 707-253-4269
Last EDR Contact: 01/07/2008
Next Scheduled EDR Contact: 03/24/2008
Data Release Frequency: Annually

ORANGE COUNTY:

List of Industrial Site Cleanups
Petroleum and non-petroleum spills.

Date of Government Version: 12/03/2007
Date Data Arrived at EDR: 12/19/2007
Date Made Active in Reports: 02/14/2008
Number of Days to Update: 57

Source: Health Care Agency
Telephone: 714-834-3446
Last EDR Contact: 03/06/2008
Next Scheduled EDR Contact: 06/02/2008
Data Release Frequency: Annually

List of Underground Storage Tank Cleanups
Orange County Underground Storage Tank Cleanups (LUST).

Date of Government Version: 12/03/2007
Date Data Arrived at EDR: 12/21/2007
Date Made Active in Reports: 02/14/2008
Number of Days to Update: 55

Source: Health Care Agency
Telephone: 714-834-3446
Last EDR Contact: 03/06/2008
Next Scheduled EDR Contact: 06/02/2008
Data Release Frequency: Quarterly

List of Underground Storage Tank Facilities
Orange County Underground Storage Tank Facilities (UST).

Date of Government Version: 12/03/2007
Date Data Arrived at EDR: 12/19/2007
Date Made Active in Reports: 02/08/2008
Number of Days to Update: 51

Source: Health Care Agency
Telephone: 714-834-3446
Last EDR Contact: 03/06/2008
Next Scheduled EDR Contact: 06/02/2008
Data Release Frequency: Quarterly

PLACER COUNTY:

Master List of Facilities
List includes aboveground tanks, underground tanks and cleanup sites.

Date of Government Version: 07/23/2007
Date Data Arrived at EDR: 07/23/2007
Date Made Active in Reports: 08/09/2007
Number of Days to Update: 17

Source: Placer County Health and Human Services
Telephone: 530-889-7312
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: Semi-Annually

RIVERSIDE COUNTY:

Listing of Underground Tank Cleanup Sites
Riverside County Underground Storage Tank Cleanup Sites (LUST).

Date of Government Version: 08/06/2007
Date Data Arrived at EDR: 08/07/2007
Date Made Active in Reports: 09/26/2007
Number of Days to Update: 50

Source: Department of Public Health
Telephone: 951-358-5055
Last EDR Contact: 01/15/2008
Next Scheduled EDR Contact: 04/14/2008
Data Release Frequency: Quarterly

Underground Storage Tank Tank List
Underground storage tank sites located in Riverside county.

Date of Government Version: 08/06/2007
Date Data Arrived at EDR: 08/07/2007
Date Made Active in Reports: 09/24/2007
Number of Days to Update: 48

Source: Health Services Agency
Telephone: 951-358-5055
Last EDR Contact: 01/15/2008
Next Scheduled EDR Contact: 04/14/2008
Data Release Frequency: Quarterly

SACRAMENTO COUNTY:

Contaminated Sites
List of sites where unauthorized releases of potentially hazardous materials have occurred.

Date of Government Version: 10/29/2007
Date Data Arrived at EDR: 10/30/2007
Date Made Active in Reports: 11/07/2007
Number of Days to Update: 8

Source: Sacramento County Environmental Management
Telephone: 916-875-8406
Last EDR Contact: 02/27/2008
Next Scheduled EDR Contact: 04/28/2008
Data Release Frequency: Quarterly

ML - Regulatory Compliance Master List
Any business that has hazardous materials on site - hazardous material storage sites, underground storage tanks, waste generators.

Date of Government Version: 10/29/2007
Date Data Arrived at EDR: 10/30/2007
Date Made Active in Reports: 11/07/2007
Number of Days to Update: 8

Source: Sacramento County Environmental Management
Telephone: 916-875-8406
Last EDR Contact: 02/27/2008
Next Scheduled EDR Contact: 04/28/2008
Data Release Frequency: Quarterly

SAN BERNARDINO COUNTY:

Hazardous Material Permits
This listing includes underground storage tanks, medical waste handlers/generators, hazardous materials handlers, hazardous waste generators, and waste oil generators/handlers.

Date of Government Version: 12/28/2007
Date Data Arrived at EDR: 12/28/2007
Date Made Active in Reports: 02/14/2008
Number of Days to Update: 48

Source: San Bernardino County Fire Department Hazardous Materials Division
Telephone: 909-387-3041
Last EDR Contact: 03/03/2008
Next Scheduled EDR Contact: 12/03/2007
Data Release Frequency: Quarterly

SAN DIEGO COUNTY:

Hazardous Materials Management Division Database
The database includes: HE58 - This report contains the business name, site address, business phone number, establishment 'H' permit number, type of permit, and the business status. HE17 - In addition to providing the same information provided in the HE58 listing, HE17 provides inspection dates, violations received by the establishment, hazardous waste generated, the quantity, method of storage, treatment/disposal of waste and the hauler, and information on underground storage tanks. Unauthorized Release List - Includes a summary of environmental contamination cases in San Diego County (underground tank cases, non-tank cases, groundwater contamination, and soil contamination are included.)

Date of Government Version: 05/16/2005
Date Data Arrived at EDR: 05/18/2005
Date Made Active in Reports: 06/16/2005
Number of Days to Update: 29

Source: Hazardous Materials Management Division
Telephone: 619-338-2268
Last EDR Contact: 01/04/2008
Next Scheduled EDR Contact: 03/31/2008
Data Release Frequency: Quarterly

Solid Waste Facilities
San Diego County Solid Waste Facilities.

Date of Government Version: 08/01/2007
Date Data Arrived at EDR: 02/05/2008
Date Made Active in Reports: 02/14/2008
Number of Days to Update: 9

Source: Department of Health Services
Telephone: 619-338-2209
Last EDR Contact: 02/19/2008
Next Scheduled EDR Contact: 05/19/2008
Data Release Frequency: Varies

Environmental Case Listing
The listing contains all underground tank release cases and projects pertaining to properties contaminated with hazardous substances that are actively under review by the Site Assessment and Mitigation Program.

Date of Government Version: 08/22/2007
Date Data Arrived at EDR: 10/03/2007
Date Made Active in Reports: 11/07/2007
Number of Days to Update: 35

Source: San Diego County Department of Environmental Health
Telephone: 619-338-2371
Last EDR Contact: 01/04/2008
Next Scheduled EDR Contact: 03/31/2008
Data Release Frequency: Varies

SAN FRANCISCO COUNTY:

Local Oversite Facilities
A listing of leaking underground storage tank sites located in San Francisco county.

Date of Government Version: 12/18/2007
Date Data Arrived at EDR: 12/19/2007
Date Made Active in Reports: 02/14/2008
Number of Days to Update: 57

Source: Department Of Public Health San Francisco County
Telephone: 415-252-3920
Last EDR Contact: 03/03/2008
Next Scheduled EDR Contact: 06/02/2008
Data Release Frequency: Quarterly

Underground Storage Tank Information
Underground storage tank sites located in San Francisco county.

Date of Government Version: 12/18/2007
Date Data Arrived at EDR: 12/19/2007
Date Made Active in Reports: 02/08/2008
Number of Days to Update: 51

Source: Department of Public Health
Telephone: 415-252-3920
Last EDR Contact: 03/03/2008
Next Scheduled EDR Contact: 06/02/2008
Data Release Frequency: Quarterly

SAN JOAQUIN COUNTY:

San Joaquin Co. UST
A listing of underground storage tank locations in San Joaquin county.

Date of Government Version: 10/18/2007
Date Data Arrived at EDR: 11/19/2007
Date Made Active in Reports: 02/08/2008
Number of Days to Update: 81

Source: Environmental Health Department
Telephone: N/A
Last EDR Contact: 01/15/2008
Next Scheduled EDR Contact: 04/14/2008
Data Release Frequency: Semi-Annually

SAN MATEO COUNTY:

Business Inventory
List includes Hazardous Materials Business Plan, hazardous waste generators, and underground storage tanks.

Date of Government Version: 01/31/2008
Date Data Arrived at EDR: 02/01/2008
Date Made Active in Reports: 02/14/2008
Number of Days to Update: 13

Source: San Mateo County Environmental Health Services Division
Telephone: 650-363-1921
Last EDR Contact: 10/09/2007
Next Scheduled EDR Contact: 01/07/2008
Data Release Frequency: Annually

Fuel Leak List
A listing of leaking underground storage tank sites located in San Mateo county.

Date of Government Version: 01/09/2008
Date Data Arrived at EDR: 01/11/2008
Date Made Active in Reports: 02/14/2008
Number of Days to Update: 34

Source: San Mateo County Environmental Health Services Division
Telephone: 650-363-1921
Last EDR Contact: 01/07/2008
Next Scheduled EDR Contact: 04/07/2008
Data Release Frequency: Semi-Annually

SANTA CLARA COUNTY:

HIST LUST - Fuel Leak Site Activity Report
A listing of open and closed leaking underground storage tanks. This listing is no longer updated by the county. Leaking underground storage tanks are now handled by the Department of Environmental Health.

Date of Government Version: 03/29/2005
Date Data Arrived at EDR: 03/30/2005
Date Made Active in Reports: 04/21/2005
Number of Days to Update: 22

Source: Santa Clara Valley Water District
Telephone: 408-265-2600
Last EDR Contact: 12/26/2007
Next Scheduled EDR Contact: 03/24/2008
Data Release Frequency: No Update Planned

LOP Listing
A listing of leaking underground storage tanks located in Santa Clara county.

Date of Government Version: 02/01/2008
Date Data Arrived at EDR: 02/05/2008
Date Made Active in Reports: 02/14/2008
Number of Days to Update: 9

Source: Department of Environmental Health
Telephone: 408-918-3417
Last EDR Contact: 01/15/2008
Next Scheduled EDR Contact: 03/24/2008
Data Release Frequency: Varies

Hazardous Material Facilities
Hazardous material facilities, including underground storage tank sites.

Date of Government Version: 12/17/2007
Date Data Arrived at EDR: 12/19/2007
Date Made Active in Reports: 02/14/2008
Number of Days to Update: 57

Source: City of San Jose Fire Department
Telephone: 408-277-4659
Last EDR Contact: 03/03/2008
Next Scheduled EDR Contact: 06/02/2008
Data Release Frequency: Annually

SOLANO COUNTY:

Leaking Underground Storage Tanks
A listing of leaking underground storage tank sites located in Solano county.

Date of Government Version: 09/24/2007
Date Data Arrived at EDR: 10/23/2007
Date Made Active in Reports: 11/07/2007
Number of Days to Update: 15

Source: Solano County Department of Environmental Management
Telephone: 707-784-6770
Last EDR Contact: 01/07/2008
Next Scheduled EDR Contact: 03/24/2008
Data Release Frequency: Quarterly

Underground Storage Tanks
Underground storage tank sites located in Solano county.

Date of Government Version: 01/07/2008
Date Data Arrived at EDR: 01/30/2008
Date Made Active in Reports: 02/08/2008
Number of Days to Update: 9

Source: Solano County Department of Environmental Management
Telephone: 707-784-6770
Last EDR Contact: 01/07/2008
Next Scheduled EDR Contact: 03/24/2008
Data Release Frequency: Quarterly

SONOMA COUNTY:

Leaking Underground Storage Tank Sites
A listing of leaking underground storage tank sites located in Sonoma county.

Date of Government Version: 01/22/2008
Date Data Arrived at EDR: 01/22/2008
Date Made Active in Reports: 02/14/2008
Number of Days to Update: 23

Source: Department of Health Services
Telephone: 707-565-6565
Last EDR Contact: 01/21/2008
Next Scheduled EDR Contact: 04/21/2008
Data Release Frequency: Quarterly

SUTTER COUNTY:

Underground Storage Tanks
Underground storage tank sites located in Sutter county.

Date of Government Version: 05/04/2007
Date Data Arrived at EDR: 05/04/2007
Date Made Active in Reports: 05/24/2007
Number of Days to Update: 20

Source: Sutter County Department of Agriculture
Telephone: 530-822-7500
Last EDR Contact: 01/02/2008
Next Scheduled EDR Contact: 03/31/2008
Data Release Frequency: Semi-Annually

VENTURA COUNTY:

Business Plan, Hazardous Waste Producers, and Operating Underground Tanks
The BWT list indicates by site address whether the Environmental Health Division has Business Plan (B), Waste Producer (W), and/or Underground Tank (T) information.

Date of Government Version: 11/26/2007
Date Data Arrived at EDR: 01/07/2008
Date Made Active in Reports: 02/14/2008
Number of Days to Update: 38

Source: Ventura County Environmental Health Division
Telephone: 805-654-2813
Last EDR Contact: 12/13/2007
Next Scheduled EDR Contact: 03/10/2008
Data Release Frequency: Quarterly

Inventory of Illegal Abandoned and Inactive Sites
Ventura County Inventory of Closed, Illegal Abandoned, and Inactive Sites.

Date of Government Version: 08/01/2007
Date Data Arrived at EDR: 08/29/2007
Date Made Active in Reports: 09/26/2007
Number of Days to Update: 28

Source: Environmental Health Division
Telephone: 805-654-2813
Last EDR Contact: 02/19/2008
Next Scheduled EDR Contact: 05/19/2008
Data Release Frequency: Annually

Listing of Underground Tank Cleanup Sites
Ventura County Underground Storage Tank Cleanup Sites (LUST).

Date of Government Version: 11/26/2007
Date Data Arrived at EDR: 01/07/2008
Date Made Active in Reports: 02/14/2008
Number of Days to Update: 38

Source: Environmental Health Division
Telephone: 805-654-2813
Last EDR Contact: 12/13/2007
Next Scheduled EDR Contact: 03/10/2008
Data Release Frequency: Quarterly

Underground Tank Closed Sites List
Ventura County Operating Underground Storage Tank Sites (UST)/Underground Tank Closed Sites List.

Date of Government Version: 12/26/2007
Date Data Arrived at EDR: 01/09/2008
Date Made Active in Reports: 02/08/2008
Number of Days to Update: 30

Source: Environmental Health Division
Telephone: 805-654-2813
Last EDR Contact: 01/09/2008
Next Scheduled EDR Contact: 04/07/2008
Data Release Frequency: Quarterly

YOLO COUNTY:

Underground Storage Tank Comprehensive Facility Report
Underground storage tank sites located in Yolo county.

Date of Government Version: 10/16/2007
Date Data Arrived at EDR: 11/05/2007
Date Made Active in Reports: 02/08/2008
Number of Days to Update: 95

Source: Yolo County Department of Health
Telephone: 530-666-8646
Last EDR Contact: 01/28/2008
Next Scheduled EDR Contact: 04/14/2008
Data Release Frequency: Annually

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data
Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 06/15/2007
Date Made Active in Reports: 08/20/2007
Number of Days to Update: 66

Source: Department of Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 12/13/2007
Next Scheduled EDR Contact: 03/10/2008
Data Release Frequency: Annually

NJ MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 09/30/2007
Date Data Arrived at EDR: 12/04/2007
Date Made Active in Reports: 12/31/2007
Number of Days to Update: 27

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 01/03/2008
Next Scheduled EDR Contact: 03/31/2008
Data Release Frequency: Annually

NY MANIFEST: Facility and Manifest Data
Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 11/26/2007
Date Data Arrived at EDR: 11/29/2007
Date Made Active in Reports: 02/05/2008
Number of Days to Update: 68

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 02/28/2008
Next Scheduled EDR Contact: 05/26/2008
Data Release Frequency: Annually

PA MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2006
Date Data Arrived at EDR: 12/21/2007
Date Made Active in Reports: 01/10/2008
Number of Days to Update: 20

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 03/10/2008
Next Scheduled EDR Contact: 06/09/2008
Data Release Frequency: Annually

RI MANIFEST: Manifest information
Hazardous waste manifest information

Date of Government Version: 10/01/2007
Date Data Arrived at EDR: 11/09/2007
Date Made Active in Reports: 01/15/2008
Number of Days to Update: 67

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2006
Date Data Arrived at EDR: 04/27/2007
Date Made Active in Reports: 06/08/2007
Number of Days to Update: 42

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 01/07/2008
Next Scheduled EDR Contact: 04/07/2008
Data Release Frequency: Annually

Oil/Gas Pipelines: This data was obtained by EDR from the USGS in 1994. It is referred to by USGS as GeoData Digital Line Graphs from 1:100,000-Scale Maps. It was extracted from the transportation category including some oil, but primarily gas pipelines.

Electric Power Transmission Line Data
Source: PennWell Corporation
Telephone: (800) 823-6277
This map includes information copyrighted by PennWell Corporation. This information is provided on a best effort basis and PennWell Corporation does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of PennWell.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Licensed Facilities
Source: Department of Social Services
Telephone: 916-657-4041

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 1999 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002 and 2005 from the U.S. Fish and Wildlife Service.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Scanned Digital USGS 7.5' Topographic Map (DRG)

Source: United States Geologic Survey

A digital raster graphic (DRG) is a scanned image of a U.S. Geological Survey topographic map. The map images are made by scanning published paper maps on high-resolution scanners. The raster image is georeferenced and fit to the Universal Transverse Mercator (UTM) projection.

STREET AND ADDRESS INFORMATION

© 2008 Tele Atlas North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

COLTON SUPER BLOCK
SAN BERNARDINO AVENUE/NORTH PEPPER AVENUE
COLTON, CA 92324

TARGET PROPERTY COORDINATES

Latitude (North):	34.07330 - 34° 4' 23.9"
Longitude (West):	117.35543 - 117° 21' 19.6"
Universal Tranverse Mercator:	Zone 11
UTM X (Meters):	467204.2
UTM Y (Meters):	3770145.8
Elevation:	1083 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	34117-A3 SAN BERNARDINO SOUTH, CA
Most Recent Revision:	1980
West Map:	34117-A4 FONTANA, CA
Most Recent Revision:	1980

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principle investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).

TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General SE

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Target Property County	FEMA Flood Electronic Data
SAN BERNARDINO, CA	YES - refer to the Overview Map and Detail Map

Flood Plain Panel at Target Property:	06071C8678F
Additional Panels in search area:	06071C8679F 06071C8686F 06071C8687F

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
NOT AVAILABLE	Not Available

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius:	1.25 miles
Location Relative to TP:	1 - 2 Miles NE
Site Name:	Crane Co
Site EPA ID Number:	CAD066135690
Groundwater Flow Direction:	Southeast
Measured Depth to Water:	130 feet.
Hydraulic Connection:	A hydraulic connection exists between the aquifers underlying the site.
Sole Source Aquifer:	No information about a sole source aquifer is available
Data Quality:	Information based on site-specific subsurface investigations is documented in the CERCLIS investigation report(s)

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW

* ©1996 Site-specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
18	1/2 - 1 Mile WSW	SE

For additional site information, refer to Physical Setting Source Map Findings.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT

Era:	Cenozoic
System:	Quaternary
Series:	Quaternary
Code:	Q *(decoded above as Era, System & Series)*

GEOLOGIC AGE IDENTIFICATION

Category: Stratifed Sequence

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

SSURGO SOIL MAP - 02165111.2r



★ Target Property
SSURGO Soil
Water

0 1/16 1/8 1/4 Miles

N

SITE NAME:	Colton Super Block	CLIENT:	Petra Geotechnical Inc
ADDRESS:	San Bernardino Avenue/North Pepper Avenue Colton CA 92324	CONTACT:	Callie Cullum
LAT/LONG:	34.0733 / 117.3554	INQUIRY #:	02165111.2r
		DATE:	March 12, 2008 7:55 am

Copyright © 2008 EDR, Inc. © 2007 Tele Atlas Rel. 07/2006.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. The following information is based on Soil Conservation Service SSURGO data.

Soil Map ID: 1

Soil Component Name: DELHI

Soil Surface Texture: fine sand

Hydrologic Group: Class A - High infiltration rates. Soils are deep, well drained to excessively drained sands and gravels.

Soil Drainage Class: Somewhat excessive. Soils have high hydraulic conductivity and low water holding capacity. Depth to water table is more than 6 feet.

Hydric Status: Soil does not meet the requirements for a hydric soil.

Corrosion Potential - Uncoated Steel: MODERATE

Depth to Bedrock Min: > 0 inches

Depth to Bedrock Max: > 0 inches

Soil Layer Information

	Boundary			Classification			
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil	Permeability Rate (in/hr)	Soil Reaction (pH)
1	0 inches	18 inches	fine sand	Granular materials (35 pct. or less passing No. 200), Silty, or Clayey Gravel and Sand.	COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 20.00 Min: 6.00	Max: 7.30 Min: 5.60
2	18 inches	60 inches	sand	Granular materials (35 pct. or less passing No. 200), Fine Sand.	COARSE-GRAINED SOILS, Sands, Clean Sands, Poorly graded sand. COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 20.00 Min: 6.00	Max: 7.80 Min: 6.10

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 1 mile
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
A2	USGS3135346	1/4 - 1/2 Mile East
B4	USGS3135316	1/4 - 1/2 Mile ESE
C6	USGS3135243	1/2 - 1 Mile NE
C7	USGS3135254	1/2 - 1 Mile NE
9	USGS3135490	1/2 - 1 Mile WSW
E12	USGS3135605	1/2 - 1 Mile SSE
E13	USGS3135604	1/2 - 1 Mile SSE
E15	USGS3135599	1/2 - 1 Mile SSE
E16	USGS3290384	1/2 - 1 Mile SSE
E17	USGS3222275	1/2 - 1 Mile SSE
20	USGS3135590	1/2 - 1 Mile SSE

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No PWS System Found		

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
A1	CADW10000006584	1/4 - 1/2 Mile East
B3	CADW10000006570	1/4 - 1/2 Mile ESE
C5	CADW10000006626	1/2 - 1 Mile NE
C8	3139	1/2 - 1 Mile NE
D10	1005	1/2 - 1 Mile WSW
D11	1006	1/2 - 1 Mile WSW
14	969	1/2 - 1 Mile SE
19	995	1/2 - 1 Mile NW

OTHER STATE DATABASE INFORMATION

STATE OIL/GAS WELL INFORMATION

DISTANCE FROM TP (Miles)	DISTANCE FROM TP (Miles)
1/2 - 1 Mile NE	

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

STATE OIL/GAS WELL INFORMATION

DISTANCE FROM TP (Miles)	DISTANCE FROM TP (Miles)
	1/2 - 1 Mile South

PHYSICAL SETTING SOURCE MAP - 02165111.2r

- County Boundary
- Major Roads
- Contour Lines
- Earthquake Fault Lines
- Airports
- Earthquake epicenter, Richter 5 or greater
- Water Wells
- Public Water Supply Wells
- Cluster of Multiple Icons

- Groundwater Flow Direction
- (GI) Indeterminate Groundwater Flow at Location
- (GV) Groundwater Flow Varies at Location
- (HD) Closest Hydrogeological Data
- Oil, gas or related wells

SITE NAME: Colton Super Block ADDRESS: San Bernardino Avenue/North Pepper Avenue Colton CA 92324 LAT/LONG: 34.0733 / 117.3554	CLIENT: Petra Geotechnical Inc CONTACT: Callie Cullum INQUIRY #: 02165111.2r DATE: March 12, 2008 7:55 am

Copyright © 2008 EDR, Inc. © 2007 Tele Atlas Rel. 07/2005.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

	Database	EDR ID Number
A1 **East** **1/4 - 1/2 Mile** **Lower**	**CA WELLS**	**CADW10000006584**

Longn:	-117.3489
Latn:	34.0731
Stwellno:	01S05W24H002S
Districtco:	3
Wellusecod:	P
Countycode:	36
Gwcode:	800203
Site id:	CADW10000006584

A2
East
1/4 - 1/2 Mile
Lower

FED USGS **USGS3135346**

Agency cd:	USGS	Site no:	340423117205301
Site name:	001S005W24H002S		
Latitude:	340423		
Longitude:	1172053	Dec lat:	34.07306804
Dec lon:	-117.34893368	Coor meth:	M
Coor accr:	F	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	06
State:	06	County:	071
Country:	US	Land net:	Not Reported
Location map:	SAN BERNARDINO SOUTH	Map scale:	24000
Altitude:	1050		
Altitude method:	Interpolated from topographic map		
Altitude accuracy:	20		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Santa Ana. California. Area = 1680 sq.mi.		
Topographic:	Hillside (slope)		
Site type:	Ground-water other than Spring	Date construction:	19970422
Date inventoried:	19980715	Mean greenwich time offset:	PST
Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	700	Hole depth:	712
Source of depth data:	driller		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1997-06-19	Ground water data end date:	2004-10-21
Ground water data count:	16		

Ground-water levels, Number of Measurements: 16

Date	Feet below Surface	Feet to Sealevel
2004-10-21	190.78	
2003-10-21	184.06	
2002-10-29	181.02	
2001-10-24	178.85	
2000-10-25	175.55	
1999-10-19	173.66	
1999-04-13		
Note: The site was being pumped.		
1998-10-20	172.38	
1997-06-19	175	
2004-04-20	187.88	
2003-04-22	181.40	
2002-04-10	178.70	
2001-04-17	176.70	
2000-04-18	173.60	
1999-04-14	170.59	
1998-07-15	172.4	

B3
ESE
1/4 - 1/2 Mile
Lower

CA WELLS **CADW10000006570**

Longn:	-117.3484
Latn:	34.0711
Stwellno:	01S04W19E001S
Districtco:	3
Wellusecod:	Z
Countycode:	36
Gwcode:	800203
Site id:	CADW10000006570

B4
ESE
1/4 - 1/2 Mile
Lower

FED USGS **USGS3135316**

Agency cd:	USGS	Site no:	340416117205101
Site name:	001S004W19E001S		
Latitude:	340416		
Longitude:	1172051	Dec lat:	34.07112367
Dec lon:	-117.34837809	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	06
State:	06	County:	071
Country:	US	Land net:	S19T01SR04WS
Location map:	SAN BERNARDINO SOUTH	Map scale:	24000
Altitude:	1038.90		
Altitude method:	Level or other surveying method		
Altitude accuracy:	.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Santa Ana. California. Area = 1680 sq.mi.		
Topographic:	Undulating		
Site type:	Ground-water other than Spring	Date construction:	19640227
Date inventoried:	Not Reported	Mean greenwich time offset:	PST
Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	222	Hole depth:	251
Source of depth data:	Not Reported		
Project number:	9479300236		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Peak flow data count: 0
Water quality data end date:0000-00-00
Ground water data begin date: 1964-03-02
Ground water data count: 91

Water quality data begin date: 0000-00-00
Water quality data count: 0
Ground water data end date: 1998-04-07

Ground-water levels, Number of Measurements: 91

Date	Feet below Surface	Feet to Sealevel
1998-04-07		
Note: The well was destroyed (no water level is recorded).		
1997-10-29	162.83	
1996-10-09	158.51	
1995-10-23	155.10	
1994-10-24	157.07	
1993-10-18	159.25	
1992-10-27	164.15	
1991-11-27	163.15	
1990-11-28	161.07	
1989-11-27	156.52	
1988-11-28	151.55	
1988-04-12	150.91	
1987-06-18	150.31	
Note: Other conditions existed that would affect the measured water level.		
1987-05-01	149.62	
1986-11-20	149.40	
Note: Other conditions existed that would affect the measured water level.		
1986-09-15	149.58	
1986-05-15	148.38	
1985-09-18	149.58	
Note: Other conditions existed that would affect the measured water level.		
1985-05-10	149.85	
1984-04-11	149.85	
1983-07-27	152.74	
1981-11-20	155.67	
1981-09-16	156.32	
1981-08-13	156.77	
1981-06-11	157.68	
1981-04-16	157.87	
1981-02-20	158.90	
1980-12-19	159.95	
1980-11-21	160.59	
1980-09-18	161.47	
1980-07-23	165.27	
1980-06-12	163.92	
1980-04-16	168.32	
1980-02-13	158.43	
1979-12-12	166.22	
1979-07-12	167.32	
1979-06-14	168.12	
1979-03-15	169.82	
1979-01-18	170.37	
1978-11-16	172.07	
1978-07-14	184.73	
1977-12-15	182.89	
1977-10-11	181.54	
1977-08-26	179.19	
1970-03-30	173.34	
1969-04-28	187.94	
1997-04-15	158.63	
1996-04-25	153.60	
1995-04-19	154.84	
1994-04-19	156.72	
1993-04-14	161.81	
1992-06-17	162.35	
1991-06-24	158.87	
1990-06-28	156.87	
1989-09-21	155.71	
1988-06-29	151.82	
1986-06-20	148.61	
1984-09-21	150.21	
1983-11-30	151.67	
1982-09-15	155.21	
1981-10-22	155.87	
1981-08-19	158.05	
1981-07-22	156.92	
1981-05-15	157.74	
1981-03-12	158.04	
1981-01-15	159.38	
1980-12-04	161.28	
1980-10-22	160.98	
1980-08-14	162.79	
1980-06-13	163.57	
1980-05-16	166.20	
1980-03-14	166.57	
1980-01-18	165.87	
1979-09-14	167.49	
1979-07-06	167.49	
1979-05-17	172.42	
1979-02-20	169.97	
1978-12-15	171.67	
1978-08-11	173.88	
1978-01-14	182.53	
1977-11-15	182.40	
1977-09-21	180.13	
1977-07-07	179.37	
1969-11-20	175.84	
1969-01-02	193.94	

Ground-water levels, continued.

Date	Feet below Surface	Feet to Sealevel
1968-05-25	190.44	
1964-04-09	189.43	
1964-03-04	189.79	
1967-11-30	192.14	
1964-03-16	189.60	
1964-03-02	189.82	

C5
NE
1/2 - 1 Mile
Higher

CA WELLS **CADW10000006626**

Longn:	-117.3482
Latn:	34.0788
Stwellno:	01S05W34R001S
Districtco:	3
Wellusecod:	Z
Countycode:	36
Gwcode:	800203
Site id:	CADW10000006626

C6
NE
1/2 - 1 Mile
Higher

FED USGS **USGS3135243**

Agency cd:	USGS	Site no:	340441117205001
Site name:	001S004W18N001S		
Latitude:	340441		
Longitude:	1172050	Dec lat:	34.07806787
Dec lon:	-117.34810035	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	06
State:	06	County:	071
Country:	US	Land net:	Not Reported
Location map:	Not Reported	Map scale:	Not Reported
Altitude:	1085.00		
Altitude method:	Interpolated from topographic map		
Altitude accuracy:	10		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Santa Ana. California. Area = 1680 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19430101
Date inventoried:	Not Reported	Mean greenwich time offset:	PST
Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	600	Hole depth:	4015
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

	Database	EDR ID Number
C7 **NE** **1/2 - 1 Mile** **Higher**	**FED USGS**	**USGS3135254**

Agency cd:	USGS	Site no:	340444117205401
Site name:	001S005W34R001S		
Latitude:	340443.57		
Longitude:	1172053.64	Dec lat:	34.07876944
Dec lon:	-117.34823333	Coor meth:	G
Coor accr:	5	Latlong datum:	NAD83
Dec latlong datum:	NAD83	District:	06
State:	06	County:	071
Country:	US	Land net:	Not Reported
Location map:	SAN BERNARDINO SOUTH	Map scale:	24000
Altitude:	1090		
Altitude method:	Interpolated from topographic map		
Altitude accuracy:	10		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Not Reported		
Topographic:	Flat surface		
Site type:	Ground-water other than Spring	Date construction:	1994
Date inventoried:	20000411	Mean greenwich time offset:	PST
Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Unconfined single aquifer		
Aquifer:	CENOZOIC ERATHEM		
Well depth:	644	Hole depth:	706
Source of depth data:	other reported		
Project number:	470652422		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	2000-04-18
Water quality data end date:	2000-04-18	Water quality data count:	1
Ground water data begin date:	2000-05-00	Ground water data end date:	2004-05-04
Ground water data count:	2		

Ground-water levels, Number of Measurements: 2

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
2004-05-04	197		2000-05	197	

	Database	EDR ID Number
C8 **NE** **1/2 - 1 Mile** **Higher**	**CA WELLS**	**3139**

Water System Information:

Prime Station Code:	036/014-002	User ID:	TAN
FRDS Number:	3610014021	County:	San Beernardino
District Number:	13	Station Type:	WELL/AMBNT
Water Type:	Well/Groundwater	Well Status:	Active Raw
Source Lat/Long:	340444.0 1172050.0	Precision:	1,000 Feet (10 Seconds)
Source Name:	WELL 24		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

System Number: 3610014
System Name: CITY OF COLTON
Organization That Operates System:
650 N LA CADENA DR
COLTON, CA 92324
Pop Served: 42103 Connections: 8604
Area Served: CITY OF COLTON

Sample Collected:	01/10/2002 00:00:00	Findings:	.76 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	01/10/2002 00:00:00	Findings:	25 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	01/23/2002 00:00:00	Findings:	4.3 UG/L
Chemical:	PERCHLORATE		
Sample Collected:	02/11/2002 00:00:00	Findings:	4.5 UG/L
Chemical:	PERCHLORATE		
Sample Collected:	03/19/2002 00:00:00	Findings:	4.4 UG/L
Chemical:	PERCHLORATE		
Sample Collected:	05/08/2002 00:00:00	Findings:	5.2 UG/L
Chemical:	PERCHLORATE		
Sample Collected:	06/20/2002 00:00:00	Findings:	2 UG/L
Chemical:	CHROMIUM, HEXAVALENT		
Sample Collected:	06/20/2002 00:00:00	Findings:	3.8 UG/L
Chemical:	VANADIUM		
Sample Collected:	06/20/2002 00:00:00	Findings:	4.2 UG/L
Chemical:	PERCHLORATE		
Sample Collected:	08/19/2003 00:00:00	Findings:	420 US
Chemical:	SPECIFIC CONDUCTANCE		
Sample Collected:	08/19/2003 00:00:00	Findings:	7.3
Chemical:	PH, LABORATORY		
Sample Collected:	08/19/2003 00:00:00	Findings:	160 MG/L
Chemical:	ALKALINITY (TOTAL) AS CACO3		
Sample Collected:	08/19/2003 00:00:00	Findings:	190 MG/L
Chemical:	BICARBONATE ALKALINITY		
Sample Collected:	08/19/2003 00:00:00	Findings:	190 MG/L
Chemical:	HARDNESS (TOTAL) AS CACO3		
Sample Collected:	08/19/2003 00:00:00	Findings:	65 MG/L
Chemical:	CALCIUM		
Sample Collected:	08/19/2003 00:00:00	Findings:	7.1 MG/L
Chemical:	MAGNESIUM		
Sample Collected:	08/19/2003 00:00:00	Findings:	15 MG/L
Chemical:	SODIUM		
Sample Collected:	08/19/2003 00:00:00	Findings:	2.4 MG/L
Chemical:	POTASSIUM		
Sample Collected:	08/19/2003 00:00:00	Findings:	9.8 MG/L
Chemical:	CHLORIDE		
Sample Collected:	08/19/2003 00:00:00	Findings:	.23 MG/L
Chemical:	FLUORIDE (F) (NATURAL-SOURCE)		
Sample Collected:	08/19/2003 00:00:00	Findings:	280 MG/L
Chemical:	TOTAL DISSOLVED SOLIDS		
Sample Collected:	08/19/2003 00:00:00	Findings:	25 MG/L
Chemical:	NITRATE (AS NO3)		

Sample Collected:	08/23/2003 00:00:00	Findings:	.97 PCI/L
Chemical:	GROSS ALPHA COUNTING ERROR		
Sample Collected:	10/06/2003 00:00:00	Findings:	4.2 UG/L
Chemical:	PERCHLORATE		
Sample Collected:	10/08/2003 00:00:00	Findings:	26 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	10/10/2003 00:00:00	Findings:	18.9 C
Chemical:	SOURCE TEMPERATURE C		
Sample Collected:	10/10/2003 00:00:00	Findings:	7.4
Chemical:	PH, LABORATORY		
Sample Collected:	10/10/2003 00:00:00	Findings:	.35 MG/L
Chemical:	FLUORIDE (F) (NATURAL-SOURCE)		
Sample Collected:	10/10/2003 00:00:00	Findings:	3.6 UG/L
Chemical:	VANADIUM		
Sample Collected:	10/10/2003 00:00:00	Findings:	.59
Chemical:	LANGELIER INDEX @ 60 C		
Sample Collected:	10/10/2003 00:00:00	Findings:	- .14
Chemical:	LANGELIER INDEX AT SOURCE TEMP.		
Sample Collected:	10/10/2003 00:00:00	Findings:	27 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	10/10/2003 00:00:00	Findings:	.1 NTU
Chemical:	TURBIDITY, LABORATORY		
Sample Collected:	10/10/2003 00:00:00	Findings:	11.82
Chemical:	AGGRSSIVE INDEX (CORROSIVITY)		
Sample Collected:	10/10/2003 00:00:00	Findings:	6100 UG/L
Chemical:	NITRATE + NITRITE (AS N)		
Sample Collected:	10/28/2003 00:00:00	Findings:	.9 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	12/04/2003 00:00:00	Findings:	.97 PCI/L
Chemical:	GROSS ALPHA COUNTING ERROR		
Sample Collected:	01/14/2004 00:00:00	Findings:	1.4 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	03/02/2004 00:00:00	Findings:	.97 PCI/L
Chemical:	GROSS ALPHA COUNTING ERROR		
Sample Collected:	06/01/2004 00:00:00	Findings:	.97 PCI/L
Chemical:	GROSS ALPHA COUNTING ERROR		
Sample Collected:	08/02/2004 00:00:00	Findings:	1.2 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	08/04/2004 00:00:00	Findings:	410 US
Chemical:	SPECIFIC CONDUCTANCE		
Sample Collected:	08/04/2004 00:00:00	Findings:	7.8
Chemical:	PH, LABORATORY		
Sample Collected:	08/04/2004 00:00:00	Findings:	160 MG/L
Chemical:	ALKALINITY (TOTAL) AS CACO3		
Sample Collected:	08/04/2004 00:00:00	Findings:	190 MG/L
Chemical:	BICARBONATE ALKALINITY		
Sample Collected:	08/04/2004 00:00:00	Findings:	190 MG/L
Chemical:	HARDNESS (TOTAL) AS CACO3		
Sample Collected:	08/04/2004 00:00:00	Findings:	64 MG/L
Chemical:	CALCIUM		

Sample Collected:	08/04/2004 00:00:00	Findings:	7 MG/L
Chemical:	MAGNESIUM		
Sample Collected:	08/04/2004 00:00:00	Findings:	15 MG/L
Chemical:	SODIUM		
Sample Collected:	08/04/2004 00:00:00	Findings:	2.5 MG/L
Chemical:	POTASSIUM		
Sample Collected:	08/04/2004 00:00:00	Findings:	12 MG/L
Chemical:	CHLORIDE		
Sample Collected:	08/04/2004 00:00:00	Findings:	.3 MG/L
Chemical:	FLUORIDE (F) (NATURAL-SOURCE)		
Sample Collected:	08/04/2004 00:00:00	Findings:	270 MG/L
Chemical:	TOTAL DISSOLVED SOLIDS		
Sample Collected:	08/04/2004 00:00:00	Findings:	24 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	09/27/2004 00:00:00	Findings:	1.1 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	12/01/2004 00:00:00	Findings:	.84 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	01/20/2005 00:00:00	Findings:	1.5 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	01/20/2005 00:00:00	Findings:	.549 PCI/L
Chemical:	RADIUM 228 COUNTING ERROR		
Sample Collected:	04/04/2005 00:00:00	Findings:	.388 PCI/L
Chemical:	RADIUM 228 COUNTING ERROR		
Sample Collected:	04/05/2005 00:00:00	Findings:	1 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	04/05/2005 00:00:00	Findings:	21 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	07/13/2005 00:00:00	Findings:	.54 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	07/14/2005 00:00:00	Findings:	23 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	08/03/2005 00:00:00	Findings:	20 C
Chemical:	SOURCE TEMPERATURE C		
Sample Collected:	08/03/2005 00:00:00	Findings:	400 US
Chemical:	SPECIFIC CONDUCTANCE		
Sample Collected:	08/03/2005 00:00:00	Findings:	7.7
Chemical:	PH, LABORATORY		
Sample Collected:	08/03/2005 00:00:00	Findings:	180 MG/L
Chemical:	ALKALINITY (TOTAL) AS CACO3		
Sample Collected:	08/03/2005 00:00:00	Findings:	220 MG/L
Chemical:	BICARBONATE ALKALINITY		
Sample Collected:	08/03/2005 00:00:00	Findings:	190 MG/L
Chemical:	HARDNESS (TOTAL) AS CACO3		
Sample Collected:	08/03/2005 00:00:00	Findings:	62 MG/L
Chemical:	CALCIUM		
Sample Collected:	08/03/2005 00:00:00	Findings:	6.9 MG/L
Chemical:	MAGNESIUM		
Sample Collected:	08/03/2005 00:00:00	Findings:	15 MG/L
Chemical:	SODIUM		

Sample Collected:	08/03/2005 00:00:00	Findings:	2.1 MG/L
Chemical:	POTASSIUM		
Sample Collected:	08/03/2005 00:00:00	Findings:	8.5 MG/L
Chemical:	CHLORIDE		
Sample Collected:	08/03/2005 00:00:00	Findings:	.25 MG/L
Chemical:	FLUORIDE (F) (NATURAL-SOURCE)		
Sample Collected:	08/03/2005 00:00:00	Findings:	8.6 UG/L
Chemical:	LEAD		
Sample Collected:	08/03/2005 00:00:00	Findings:	6.2 UG/L
Chemical:	VANADIUM		
Sample Collected:	08/03/2005 00:00:00	Findings:	250 MG/L
Chemical:	TOTAL DISSOLVED SOLIDS		
Sample Collected:	08/03/2005 00:00:00	Findings:	.93
Chemical:	LANGELIER INDEX @ 60 C		
Sample Collected:	08/03/2005 00:00:00	Findings:	.23
Chemical:	LANGELIER INDEX AT SOURCE TEMP.		
Sample Collected:	08/03/2005 00:00:00	Findings:	23 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	08/03/2005 00:00:00	Findings:	.1 NTU
Chemical:	TURBIDITY, LABORATORY		
Sample Collected:	08/03/2005 00:00:00	Findings:	12.16
Chemical:	AGGRSSIVE INDEX (CORROSIVITY)		
Sample Collected:	08/03/2005 00:00:00	Findings:	5200 UG/L
Chemical:	NITRATE + NITRITE (AS N)		
Sample Collected:	10/04/2005 00:00:00	Findings:	24 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	01/03/2006 00:00:00	Findings:	25 MG/L
Chemical:	NITRATE (AS NO3)		

9
WSW
1/2 - 1 Mile
Lower

FED USGS **USGS3135490**

Agency cd:	USGS	Site no:	340411117215301
Site name:	001S005W24M001S		
Latitude:	340411		
Longitude:	1172153	Dec lat:	34.0697347
Dec lon:	-117.3656009	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	06
State:	06	County:	071
Country:	US	Land net:	Not Reported
Location map:	SAN BERNARDINO SOUTH	Map scale:	24000
Altitude:	Not Reported		
Altitude method:	Not Reported		
Altitude accuracy:	Not Reported		
Altitude datum:	Not Reported		
Hydrologic:	Santa Ana. California. Area = 1680 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	PST

Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	342	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	9479335800		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

D10
WSW
1/2 - 1 Mile
Lower

CA WELLS **1005**

Water System Information:

Prime Station Code:	01S/05W-23Q01 S	User ID:	TAN
FRDS Number:	3610004023	County:	San Beernardino
District Number:	13	Station Type:	WELL/AMBNT/MUN/INTAKE/SUPPLY
Water Type:	Well/Groundwater	Well Status:	Active Raw
Source Lat/Long:	340400.0 1172200.0	Precision:	Undefined
Source Name:	WELL 29		
System Number:	3610004		
System Name:	WEST SAN BERNARDINO CWD		
Organization That Operates System:			
	PO BOX 920		
	RIALTO, CA 92376-0920		
Pop Served:	41454	Connections:	15052
Area Served:	RIALTO-BLOOMINGTON		

D11
WSW
1/2 - 1 Mile
Lower

CA WELLS **1006**

Water System Information:

Prime Station Code:	01S/05W-24M01 S	User ID:	TAN
FRDS Number:	3610004013	County:	San Beernardino
District Number:	13	Station Type:	WELL/AMBNT/MUN/INTAKE/SUPPLY
Water Type:	Well/Groundwater	Well Status:	Destroyed
Source Lat/Long:	340400.0 1172200.0	Precision:	Undefined
Source Name:	WELL 18 - DESTROYED		
System Number:	3610004		
System Name:	WEST SAN BERNARDINO CWD		
Organization That Operates System:			
	PO BOX 920		
	RIALTO, CA 92376-0920		
Pop Served:	41454	Connections:	15052
Area Served:	RIALTO-BLOOMINGTON		

Map ID
Direction
Distance
Elevation

	Database	EDR ID Number
E12 **SSE** **1/2 - 1 Mile** **Lower**	**FED USGS**	**USGS3135605**

Agency cd:	USGS	Site no:	340344117205102
Site name:	001S004W30D007S		
Latitude:	340344		
Longitude:	1172051	Dec lat:	34.06223509
Dec lon:	-117.34837803	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	06
State:	06	County:	071
Country:	US	Land net:	Not Reported
Location map:	Not Reported	Map scale:	Not Reported
Altitude:	1000.00		
Altitude method:	Interpolated from topographic map		
Altitude accuracy:	10		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Santa Ana. California. Area = 1680 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19550101
Date inventoried:	Not Reported	Mean greenwich time offset:	PST
Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	189	Hole depth:	232
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

	Database	EDR ID Number
E13 **SSE** **1/2 - 1 Mile** **Lower**	**FED USGS**	**USGS3135604**

Agency cd:	USGS	Site no:	340344117205101
Site name:	001S004W30D006S		
Latitude:	340344		
Longitude:	1172051	Dec lat:	34.06223509
Dec lon:	-117.34837803	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	06
State:	06	County:	071
Country:	US	Land net:	Not Reported
Location map:	Not Reported	Map scale:	Not Reported

Altitude:	995.00		
Altitude method:	Interpolated from topographic map		
Altitude accuracy:	10		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Santa Ana. California. Area = 1680 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19470101
Date inventoried:	Not Reported	Mean greenwich time offset:	PST
Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	215	Hole depth:	300
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1964-10-02
Water quality data end date:	1964-10-02	Water quality data count:	1
Ground water data begin date:	0000-00-00	Ground water data end date:	0000-00-00
Ground water data count:	0		

Ground-water levels, Number of Measurements: 0

14
SE
1/2 - 1 Mile
Lower

CA WELLS **969**

Water System Information:

Prime Station Code:	01S/04W-30D06 S	User ID:	36C
FRDS Number:	3600793001	County:	San Beernardino
District Number:	66	Station Type:	WELL/AMBNT/MUN/INTAKE
Water Type:	Well/Groundwater	Well Status:	Active Raw
Source Lat/Long:	340345.0 1172045.0	Precision:	100 Feet (one Second)
Source Name:	WELL 05		
System Number:	3600793		
System Name:	CA PORTLAND CEMENT		
Organization That Operates System:			
	2025 E FINANCIAL WAY		
	GLENDORA, CA 91740		
Pop Served:	25	Connections:	1
Area Served:	Not Reported		

E15
SSE
1/2 - 1 Mile
Lower

FED USGS **USGS3135599**

Agency cd:	USGS	Site no:	340343117204701
Site name:	001S004W30D004S		
Latitude:	340343		
Longitude:	1172047	Dec lat:	34.06195733
Dec lon:	-117.34726688	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	06
State:	06	County:	071
Country:	US	Land net:	Not Reported
Location map:	Not Reported	Map scale:	Not Reported
Altitude:	988.00		
Altitude method:	Interpolated from topographic map		
Altitude accuracy:	10		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Santa Ana. California. Area = 1680 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19450101
Date inventoried:	Not Reported	Mean greenwich time offset:	PST
Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	215	Hole depth:	300
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

E16
SSE
1/2 - 1 Mile
Lower

FED USGS **USGS3290384**

Agency cd:	USGS	Site no:	340341117205001
Site name:	001S004W30D002S		
Latitude:	340341		
Longitude:	1172050	Dec lat:	34.06140179
Dec lon:	-117.34810023	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	06
State:	06	County:	071
Country:	US	Land net:	Not Reported
Location map:	Not Reported	Map scale:	Not Reported
Altitude:	985.00		
Altitude method:	Interpolated from topographic map		
Altitude accuracy:	10		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Santa Ana. California. Area = 1680 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	PST

Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	150	Hole depth:	150
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

E17
SSE
1/2 - 1 Mile
Lower

FED USGS **USGS3222275**

Agency cd:	USGS	Site no:	340341117204801
Site name:	001S004W30D003S		
Latitude:	340341		
Longitude:	1172048	Dec lat:	34.06140179
Dec lon:	-117.34754466	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	06
State:	06	County:	071
Country:	US	Land net:	Not Reported
Location map:	Not Reported	Map scale:	Not Reported
Altitude:	987.00		
Altitude method:	Interpolated from topographic map		
Altitude accuracy:	10		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Santa Ana. California. Area = 1680 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19370101
Date inventoried:	Not Reported	Mean greenwich time offset:	PST
Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	396	Hole depth:	396
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID Direction Distance Elevation			Database	EDR ID Number
18 **WSW** **1/2 - 1 Mile** **Lower**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	083303059T SE Not Reported Not Reported 30 ft 05/21/1999	**AQUIFLOW**	**51030**

19
NW
1/2 - 1 Mile
Higher

CA WELLS **995**

Water System Information:

Prime Station Code:	01S/05W-12N01 S	User ID:	TAN
FRDS Number:	3610004012	County:	San Beernardino
District Number:	13	Station Type:	WELL/AMBNT/MUN/INTAKE/SUPPLY
Water Type:	Well/Groundwater	Well Status:	Active Raw
Source Lat/Long:	340500.0 1172200.0	Precision:	Undefined
Source Name:	WELL 17		
System Number:	3610004		
System Name:	WEST SAN BERNARDINO CWD		
Organization That Operates System:			
	PO BOX 920		
	RIALTO, CA 92376-0920		
Pop Served:	41454	Connections:	15052
Area Served:	RIALTO-BLOOMINGTON		
Sample Collected:	05/08/2002 00:00:00	Findings:	22.2 C
Chemical:	SOURCE TEMPERATURE C		
Sample Collected:	05/08/2002 00:00:00	Findings:	400 US
Chemical:	SPECIFIC CONDUCTANCE		
Sample Collected:	05/08/2002 00:00:00	Findings:	7.4
Chemical:	PH, LABORATORY		
Sample Collected:	05/08/2002 00:00:00	Findings:	150 MG/L
Chemical:	ALKALINITY (TOTAL) AS CACO3		
Sample Collected:	05/08/2002 00:00:00	Findings:	180 MG/L
Chemical:	BICARBONATE ALKALINITY		
Sample Collected:	05/08/2002 00:00:00	Findings:	180 MG/L
Chemical:	HARDNESS (TOTAL) AS CACO3		
Sample Collected:	05/08/2002 00:00:00	Findings:	66 MG/L
Chemical:	CALCIUM		
Sample Collected:	05/08/2002 00:00:00	Findings:	3.3 MG/L
Chemical:	MAGNESIUM		
Sample Collected:	05/08/2002 00:00:00	Findings:	15 MG/L
Chemical:	SODIUM		
Sample Collected:	05/08/2002 00:00:00	Findings:	1.9 MG/L
Chemical:	POTASSIUM		
Sample Collected:	05/08/2002 00:00:00	Findings:	8.4 MG/L
Chemical:	CHLORIDE		
Sample Collected:	05/08/2002 00:00:00	Findings:	.25 MG/L
Chemical:	FLUORIDE (F) (NATURAL-SOURCE)		

Sample Collected:	05/08/2002 00:00:00	Findings:	2.2 UG/L
Chemical:	ARSENIC		
Sample Collected:	05/08/2002 00:00:00	Findings:	2 UG/L
Chemical:	CHROMIUM, HEXAVALENT		
Sample Collected:	05/08/2002 00:00:00	Findings:	4.9 UG/L
Chemical:	VANADIUM		
Sample Collected:	05/08/2002 00:00:00	Findings:	.7 PCI/L
Chemical:	GROSS ALPHA COUNTING ERROR		
Sample Collected:	05/08/2002 00:00:00	Findings:	230 MG/L
Chemical:	TOTAL DISSOLVED SOLIDS		
Sample Collected:	05/08/2002 00:00:00	Findings:	.57
Chemical:	LANGELIER INDEX @ 60 C		
Sample Collected:	05/08/2002 00:00:00	Findings:	- .09
Chemical:	LANGELIER INDEX AT SOURCE TEMP.		
Sample Collected:	05/08/2002 00:00:00	Findings:	23 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	05/08/2002 00:00:00	Findings:	.4 NTU
Chemical:	TURBIDITY, LABORATORY		
Sample Collected:	05/08/2002 00:00:00	Findings:	6 PCI/L
Chemical:	RADON 222 COUNTING ERROR		
Sample Collected:	05/08/2002 00:00:00	Findings:	200 PCI/L
Chemical:	RADON 222		
Sample Collected:	05/08/2002 00:00:00	Findings:	11.8
Chemical:	AGGRSSIVE INDEX (CORROSIVITY)		
Sample Collected:	05/08/2002 00:00:00	Findings:	5200 UG/L
Chemical:	NITRATE + NITRITE (AS N)		
Sample Collected:	05/08/2002 00:00:00	Findings:	6.5 MG/L
Chemical:	TOTAL ORGANIC CARBON (TOC)		
Sample Collected:	07/01/2002 00:00:00	Findings:	24 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	07/01/2002 00:00:00	Findings:	24 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	07/01/2002 00:00:00	Findings:	23 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	07/01/2002 00:00:00	Findings:	23 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	07/01/2002 00:00:00	Findings:	23 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	07/01/2002 00:00:00	Findings:	22 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	07/01/2002 00:00:00	Findings:	23 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	07/01/2002 00:00:00	Findings:	22 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	07/01/2002 00:00:00	Findings:	23 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	07/01/2002 00:00:00	Findings:	22 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	01/05/2004 00:00:00	Findings:	2.2 UG/L
Chemical:	TETRACHLOROETHYLENE		

Sample Collected:	01/05/2004 00:00:00	Findings:	27 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	01/05/2004 00:00:00	Findings:	.57 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	01/05/2004 00:00:00	Findings:	22 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	01/05/2004 00:00:00	Findings:	.55 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	01/05/2004 00:00:00	Findings:	22 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	01/05/2004 00:00:00	Findings:	.55 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	01/05/2004 00:00:00	Findings:	2 MG/L
Chemical:	TOTAL ORGANIC CARBON (TOC)		
Sample Collected:	01/05/2004 00:00:00	Findings:	.57 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	01/05/2004 00:00:00	Findings:	22 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	01/07/2004 00:00:00	Findings:	.55 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	01/07/2004 00:00:00	Findings:	22 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	01/07/2004 00:00:00	Findings:	.92 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	01/07/2004 00:00:00	Findings:	28 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	01/07/2004 00:00:00	Findings:	.58 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	01/07/2004 00:00:00	Findings:	22 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	01/07/2004 00:00:00	Findings:	.59 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	01/07/2004 00:00:00	Findings:	22 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	01/07/2004 00:00:00	Findings:	22 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	01/07/2004 00:00:00	Findings:	.54 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	01/28/2004 00:00:00	Findings:	.71 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	01/28/2004 00:00:00	Findings:	25 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	01/28/2004 00:00:00	Findings:	22 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	01/28/2004 00:00:00	Findings:	.51 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	01/28/2004 00:00:00	Findings:	22 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	01/28/2004 00:00:00	Findings:	22 MG/L
Chemical:	NITRATE (AS NO3)		

Sample Collected:	01/28/2004 00:00:00	Findings:	.62 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	01/28/2004 00:00:00	Findings:	.62 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	01/28/2004 00:00:00	Findings:	.61 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	01/28/2004 00:00:00	Findings:	22 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	01/28/2004 00:00:00	Findings:	.72 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	01/28/2004 00:00:00	Findings:	.68 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	01/28/2004 00:00:00	Findings:	22 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	02/10/2004 00:00:00	Findings:	1.3 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	02/10/2004 00:00:00	Findings:	33 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	02/10/2004 00:00:00	Findings:	.74 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	02/10/2004 00:00:00	Findings:	22 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	02/10/2004 00:00:00	Findings:	.89 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	02/10/2004 00:00:00	Findings:	22 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	02/10/2004 00:00:00	Findings:	.81 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	02/10/2004 00:00:00	Findings:	.82 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	02/10/2004 00:00:00	Findings:	22 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	02/10/2004 00:00:00	Findings:	.85 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	02/10/2004 00:00:00	Findings:	.87 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	02/10/2004 00:00:00	Findings:	.85 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	02/10/2004 00:00:00	Findings:	22 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	02/10/2004 00:00:00	Findings:	1.1 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	02/10/2004 00:00:00	Findings:	1 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	02/10/2004 00:00:00	Findings:	22 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	02/19/2004 00:00:00	Findings:	.94 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	02/19/2004 00:00:00	Findings:	22 MG/L
Chemical:	NITRATE (AS NO3)		

Sample Collected:	02/19/2004 00:00:00	Findings:	.92 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	02/19/2004 00:00:00	Findings:	22 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	02/19/2004 00:00:00	Findings:	.96 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	02/19/2004 00:00:00	Findings:	22 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	02/19/2004 00:00:00	Findings:	.93 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	02/19/2004 00:00:00	Findings:	.9 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	02/19/2004 00:00:00	Findings:	22 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	02/19/2004 00:00:00	Findings:	.93 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	02/19/2004 00:00:00	Findings:	.91 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	02/19/2004 00:00:00	Findings:	.89 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	02/19/2004 00:00:00	Findings:	22 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	02/19/2004 00:00:00	Findings:	.94 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	02/19/2004 00:00:00	Findings:	.95 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	02/19/2004 00:00:00	Findings:	22 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	03/12/2004 00:00:00	Findings:	.72 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	03/12/2004 00:00:00	Findings:	24 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	03/12/2004 00:00:00	Findings:	.61 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	03/12/2004 00:00:00	Findings:	22 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	03/12/2004 00:00:00	Findings:	.65 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	03/12/2004 00:00:00	Findings:	22 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	03/12/2004 00:00:00	Findings:	.65 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	03/12/2004 00:00:00	Findings:	.67 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	03/12/2004 00:00:00	Findings:	22 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	03/12/2004 00:00:00	Findings:	.63 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	03/12/2004 00:00:00	Findings:	.62 UG/L
Chemical:	TETRACHLOROETHYLENE		

Sample Collected:	03/12/2004 00:00:00	Findings:	.69 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	03/12/2004 00:00:00	Findings:	22 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	03/12/2004 00:00:00	Findings:	.89 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	03/12/2004 00:00:00	Findings:	.9 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	03/12/2004 00:00:00	Findings:	22 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	03/19/2004 00:00:00	Findings:	1.2 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	03/19/2004 00:00:00	Findings:	26 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	03/19/2004 00:00:00	Findings:	.79 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	03/19/2004 00:00:00	Findings:	22 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	03/19/2004 00:00:00	Findings:	.83 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	03/19/2004 00:00:00	Findings:	22 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	03/19/2004 00:00:00	Findings:	.79 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	03/19/2004 00:00:00	Findings:	.8 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	03/19/2004 00:00:00	Findings:	22 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	03/19/2004 00:00:00	Findings:	.9 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	03/19/2004 00:00:00	Findings:	.75 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	03/19/2004 00:00:00	Findings:	22 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	03/19/2004 00:00:00	Findings:	.91 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	03/19/2004 00:00:00	Findings:	1.1 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	03/19/2004 00:00:00	Findings:	22 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	03/30/2005 00:00:00	Findings:	25 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	06/16/2005 00:00:00	Findings:	3.68 PCI/L
Chemical:	GROSS ALPHA		
Sample Collected:	06/16/2005 00:00:00	Findings:	1.32 PCI/L
Chemical:	GROSS ALPHA COUNTING ERROR		
Sample Collected:	06/16/2005 00:00:00	Findings:	1.6 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	06/16/2005 00:00:00	Findings:	460 US
Chemical:	SPECIFIC CONDUCTANCE		

Sample Collected:	06/16/2005 00:00:00	Findings:	7.81
Chemical:	PH, LABORATORY		
Sample Collected:	06/16/2005 00:00:00	Findings:	180 MG/L
Chemical:	ALKALINITY (TOTAL) AS CACO3		
Sample Collected:	06/16/2005 00:00:00	Findings:	180 MG/L
Chemical:	BICARBONATE ALKALINITY		
Sample Collected:	06/16/2005 00:00:00	Findings:	5800 UG/L
Chemical:	NITRATE NITROGEN (NO3-N)		
Sample Collected:	06/16/2005 00:00:00	Findings:	190 MG/L
Chemical:	HARDNESS (TOTAL) AS CACO3		
Sample Collected:	06/16/2005 00:00:00	Findings:	64 MG/L
Chemical:	CALCIUM		
Sample Collected:	06/16/2005 00:00:00	Findings:	6.7 MG/L
Chemical:	MAGNESIUM		
Sample Collected:	06/16/2005 00:00:00	Findings:	13 MG/L
Chemical:	SODIUM		
Sample Collected:	06/16/2005 00:00:00	Findings:	8.6 MG/L
Chemical:	CHLORIDE		
Sample Collected:	06/16/2005 00:00:00	Findings:	.28 MG/L
Chemical:	FLUORIDE (F) (NATURAL-SOURCE)		
Sample Collected:	06/16/2005 00:00:00	Findings:	1800 UG/L
Chemical:	IRON		
Sample Collected:	06/16/2005 00:00:00	Findings:	290 MG/L
Chemical:	TOTAL DISSOLVED SOLIDS		
Sample Collected:	06/16/2005 00:00:00	Findings:	.45
Chemical:	LANGELIER INDEX @ 60 C		
Sample Collected:	06/16/2005 00:00:00	Findings:	26 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	06/16/2005 00:00:00	Findings:	12
Chemical:	AGGRSSIVE INDEX (CORROSIVITY)		
Sample Collected:	07/21/2005 00:00:00	Findings:	1.8 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	09/20/2005 00:00:00	Findings:	37 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	09/20/2005 00:00:00	Findings:	26 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	12/09/2005 00:00:00	Findings:	12.2 PCI/L
Chemical:	GROSS ALPHA		
Sample Collected:	12/09/2005 00:00:00	Findings:	2.61 PCI/L
Chemical:	GROSS ALPHA COUNTING ERROR		
Sample Collected:	12/09/2005 00:00:00	Findings:	26 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	06/29/2006 00:00:00	Findings:	2.12 PCI/L
Chemical:	RADIUM 228		
Sample Collected:	06/29/2006 00:00:00	Findings:	.577 PCI/L
Chemical:	RADIUM 228 COUNTING ERROR		
Sample Collected:	06/29/2006 00:00:00	Findings:	.69 NTU
Chemical:	TURBIDITY, LABORATORY		
Sample Collected:	06/29/2006 00:00:00	Findings:	430 US
Chemical:	SPECIFIC CONDUCTANCE		

Sample Collected:	06/29/2006 00:00:00	Findings:	7.88
Chemical:	PH, LABORATORY		
Sample Collected:	06/29/2006 00:00:00	Findings:	4.7 PCI/L
Chemical:	URANIUM (PCI/L)		
Sample Collected:	06/29/2006 00:00:00	Findings:	240 MG/L
Chemical:	TOTAL DISSOLVED SOLIDS		
Sample Collected:	06/29/2006 00:00:00	Findings:	25 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	06/29/2006 00:00:00	Findings:	6.72 PCI/L
Chemical:	GROSS ALPHA		
Sample Collected:	06/29/2006 00:00:00	Findings:	.944 PCI/L
Chemical:	GROSS ALPHA COUNTING ERROR		
Sample Collected:	07/13/2006 00:00:00	Findings:	2 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	07/18/2006 00:00:00	Findings:	2.1 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	07/26/2006 00:00:00	Findings:	1.9 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	08/02/2006 00:00:00	Findings:	1.9 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	08/10/2006 00:00:00	Findings:	2.1 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	08/22/2006 00:00:00	Findings:	3.2 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	08/28/2006 00:00:00	Findings:	3.3 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	09/07/2006 00:00:00	Findings:	3.1 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	09/19/2006 00:00:00	Findings:	.29 PCI/L
Chemical:	RADIUM 228 COUNTING ERROR		
Sample Collected:	09/19/2006 00:00:00	Findings:	27 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	09/25/2006 00:00:00	Findings:	2.8 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	10/10/2006 00:00:00	Findings:	2.9 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	10/10/2006 00:00:00	Findings:	2.8 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	10/20/2006 00:00:00	Findings:	2.2 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	10/20/2006 00:00:00	Findings:	29 MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	11/03/2006 00:00:00	Findings:	1.6 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	11/03/2006 00:00:00	Findings:	22 MG/L
Chemical:	NITRATE (AS NO3)		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

Database	EDR ID Number
FED USGS	**USGS3135590**

20
SSE
1/2 - 1 Mile
Lower

Agency cd:	USGS	Site no:	340340117204301
Site name:	001S004W30D001S		
Latitude:	340340		
Longitude:	1172043	Dec lat:	34.06112403
Dec lon:	-117.34615572	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	06
State:	06	County:	071
Country:	US	Land net:	Not Reported
Location map:	Not Reported	Map scale:	Not Reported
Altitude:	977.00		
Altitude method:	Interpolated from topographic map		
Altitude accuracy:	10		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Santa Ana. California. Area = 1680 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	PST
Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	80.0	Hole depth:	80.0
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Direction
Distance | Database | EDR ID Number

NE
1/2 - 1 Mile | **OIL_GAS** | **CAOG30000037242**

Apinumber:	07100048	Operator:	R. A. Dean & Associates
Lease:	Higgs	Well no:	1
Field:	SAN BERNARDINO COUNTY	Caoilgas m2 area:	Not Reported
Map:	W1-7	Status cod:	006
Source:	hud		
Latitude:	34.07913		
Longitude:	-117.34406		
Td:	0		
Sec:	18		
Twn:	1S	Rge:	4W
Bm:	SB		
X coord1:	0		
Y coord1:	0		
Zone:	Not Reported	Spuddate:	12/12/1968 00:00:00
Abanddate:	12/30/1899 00:00:00	Comments:	P
District:	1	Mapinfo id:	249
Site id:	CAOG30000037242		

South
1/2 - 1 Mile | **OIL_GAS** | **CAOG30000035554**

Apinumber:	07100042	Operator:	Colton Terrace Oil Co.
Lease:	Not Reported	Well no:	1
Field:	SAN BERNARDINO COUNTY	Caoilgas m2 area:	Not Reported
Map:	W1-4	Status cod:	006
Source:	hud		
Latitude:	34.060025		
Longitude:	-117.356807		
Td:	1799		
Sec:	25		
Twn:	1S	Rge:	5W
Bm:	SB		
X coord1:	0		
Y coord1:	0		
Zone:	Not Reported	Spuddate:	12/12/1968 00:00:00
Abanddate:	12/30/1899 00:00:00	Comments:	Not Reported
District:	1	Mapinfo id:	28314
Site id:	CAOG30000035554		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

State Database: CA Radon

Radon Test Results

Zip	Total Sites	> 4 Pci/L	Pct. > 4 Pci/L
92324	7	0	0.00

Federal EPA Radon Zone for SAN BERNARDINO County: 2

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for Zip Code: 92324

Number of sites tested: 1

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area - 1st Floor	0.000 pCi/L	100%	0%	0%
Living Area - 2nd Floor	Not Reported	Not Reported	Not Reported	Not Reported
Basement	Not Reported	Not Reported	Not Reported	Not Reported

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Scanned Digital USGS 7.5' Topographic Map (DRG)
Source: United States Geologic Survey
A digital raster graphic (DRG) is a scanned image of a U.S. Geological Survey topographic map. The map images are made by scanning published paper maps on high-resolution scanners. The raster image is georeferenced and fit to the Universal Transverse Mercator (UTM) projection.

HYDROLOGIC INFORMATION

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 1999 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002 and 2005 from the U.S. Fish and Wildlife Service.

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Services
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Services (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Services, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

Water Well Database
Source: Department of Water Resources
Telephone: 916-651-9648

California Drinking Water Quality Database
Source: Department of Health Services
Telephone: 916-324-2319
The database includes all drinking water compliance and special studies monitoring for the state of California since 1984. It consists of over 3,200,000 individual analyses along with well and water system information.

OTHER STATE DATABASE INFORMATION

California Oil and Gas Well Locations
Source: Department of Conservation
Telephone: 916-323-1779

RADON

State Database: CA Radon
Source: Department of Health Services
Telephone: 916-324-2208
Radon Database for California

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

California Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary fault lines, prepared in 1975 by the United State Geological Survey. Additional information (also from 1975) regarding activity at specific fault lines comes from California's Preliminary Fault Activity Map prepared by the California Division of Mines and Geology.

STREET AND ADDRESS INFORMATION

© 2008 Tele Atlas North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

1849 W VALLEY BLVD
COLTON, CA

Inquiry Number:
May 19, 2008

EDR Site Report™

EDR® Environmental Data Resources Inc

440 Wheelers Farms Road
Milford, CT 06461
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

The EDR-Site Report™ is a comprehensive presentation of government filings on a facility identified in a search of over 4 million government records from more than 600 federal, state and local environmental databases. The report is divided into three sections:

Section 1: Facility Summary ..... **Page 3**

Summary of facility filings including a review of the following areas: waste management, waste disposal, multi-media issues, and Superfund liability.

Section 2: Facility Detail Reports ..... **Page 4**

All available detailed information from databases where sites are identified.

Section 3: Databases Searched and Update Information. ..... **Page 6**

Name, source, update dates, contact phone number and description of each of the databases searched for this report.

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This report contains information obtained from a variety of public and other sources reasonably available to Environmental Data Resources , Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANYSUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES.ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.**Purchaser accepts this report "AS IS". Any analyses, estimates, ratings, or risk codes provided in this report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assesment performed by an environmental professional can produce information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2008 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

SECTION 1: FACILITY SUMMARY

FACILITY AREA	FACILITY 1 1849 W VALLEY BLVD COLTON, CA EDR ID #94030500
WASTE MANAGEMENT Facility generates hazardous waste (RCRA)	NO
Facility treats, stores, or disposes of hazardous waste on-site (RCRA/TSDF)	NO
Facility has received Notices of Violations (RCRA/VIOL)	NO
Facility has been subject to RCRA administrative actions (RAATS)	NO
Facility has been subject to corrective actions (CORRACTS)	NO
Facility handles PCBs (PADS)	NO
Facility uses radioactive materials (MLTS)	NO
Facility manages registered aboveground storage tanks (AST)	NO
Facility manages registered underground storage tanks (UST)	NO
Facility has reported leaking underground storage tank incidents (LUST)	NO
Facility has reported emergency releases to the soil (ERNS)	NO
Facility has reported hazardous material incidents to DOT (HMIRS)	**YES - p4**
WASTE DISPOSAL Facility is a Superfund Site (NPL)	NO
Facility has a known or suspect abandoned, inactive or uncontrolled hazardous waste site (CERCLIS)	NO
Facility has a reported Superfund Lien on it (LIENS)	NO
Facility is listed as a state hazardous waste site (SHWS)	NO
Facility has disposed of solid waste on-site (SWF/LF)	NO
MULTIMEDIA Facility uses toxic chemicals and has notified EPA under SARA Title III, Section 313 (TRIS)	NO
Facility produces pesticides and has notified EPA under Section 7 of FIFRA (SSTS)	NO
Facility manufactures or imports toxic chemicals on the TSCA list (TSCA)	NO
Facility has inspections under FIFRA, TSCA or EPCRA (FTTS)	NO
Facility is listed in EPA's index system (FINDS)	NO
Facility is listed in a county/local unique database (LOCAL)	NO
POTENTIAL SUPERFUND LIABILITY Facility has a list of potentially responsible parties PRP	NO
TOTAL (YES)	1

SECTION 2: FACILITY DETAIL REPORTS

WASTE MANAGEMENT

Facility has reported hazardous material incidents to DOT

DATABASE: Hazardous Materials Information Reporting System (HMIRS)

1849 W VALLEY BLVD
COLTON, CA
EDR ID #94030500

HMIRS:

Report #:	94030500
Site location:	1849 W VALLEY BLVD COLTON, CA
Place of origin:	11251 JERSEY BLVD RANCHO CUCAMONGA, CA 91730
Destination:	M & H VALVE CO 605 WEST 23RD ANNISTON, AL 36201
Carrier ID:	19759
Carrier reporting #:	MC29910
Carrier:	ABF FREIGHT SYSTEM INC
Carrier address:	P O BOX 48 FORT SMITH, AR 72902
Shipper ID:	58356
Shipper name:	SOCCO PLASTIC COATING CO
Shipper address:	11251 JERSEY BLVD RANCHO CUCAMONGA, CA 91730
Shipping paper number:	PRO 165358288
Consignee ID:	31320
Consignee name:	M & H VALVE CO
Consignee addess:	605 WEST 23RD ANNISTON, AL 36201
General cause:	010
Transportation mode:	004
Date:	02161994
Commodity name:	1,1,1-TRICHLOROETHANE
Trade name:	Not reported
Amount:	1.0000000 GAL
Result:	Spillage
Hazard Class:	61
ID Number:	UN2831
Hazardous:	True
R.Q. met:	False
Misc. info:	130 100
Vehicle Type:	Van truck/trailer
Trans. phase:	263
Land use:	272
Community:	281
Accident/Derailment:	False
Estimated speed:	F
Highway type:	Not reported
number of lanes:	Not reported
Number evacuated:	000000
Major injuries:	000
Minor injuries:	000
Fatalities:	00
Product loss:	00000010
Carrier damage:	00000000
Pvt/Pub damage:	00000000
Cleanup cost:	00000020
Other damage:	00000000
Reported damage:	00000030
Incident damage:	00000000

Inner and Outer Container Information:

Container type:	CAN MTL
Container capacity:	1.00000000 GAL
Number failed:	00001
Number in shipment:	00000
Container gauge:	30
Manufacture's ID:	16222
Manuf. name:	NOT REPORTED BY CARRIER UNKNOWN, XX
Tank serial #:	Not reported
Label:	Not reported
Registration #:	Not reported
Inspection date:	Not reported
Exemption #:	Not reported

SECTION 2: FACILITY DETAIL REPORTS

...Continued...

Contributing cause:	Improper loading
Contributing Object:	No object
Contributing failure:	OTHER
Affected side:	Top
Other contributing cause:	Closure
Capacity container code:	Not reported
Number failed code:	Not reported
Shipment code number:	Not reported
Container type:	BOX FBR
Container capacity:	3.00000000 GAL
Number failed:	00001
Number in shipment:	00000
Container gauge:	10
Manufacture's ID:	16222
Manuf. name:	NOT REPORTED BY CARRIER UNKNOWN, XX
Tank serial #:	Not reported
Label:	Not reported
Registration #:	Not reported
Inspection date:	Not reported
Exemption #:	Not reported
Contributing cause:	Improper loading
Contributing Object:	No object
Contributing failure:	OTHER
Affected side:	Top
Other contributing cause:	Closure
Capacity container code:	Not reported
Number failed code:	Not reported
Shipment code number:	Not reported

Remarks:

CARTON WAS IMPROPERLY LOADED WITH ORIENTATION ARROWS POINTING SIDEWAYS. CARTON WAS IMPROPERLY LOADED WITH ORIENTATION ARROWS POINTING SIDEWAYS. THE LID ON ONE SIDE GALLON PAIL WAS LOOSE AND ALLOWED THE CONTENTS TO LEAK THE LID ON ONE SIDE GALLON PAIL WAS LOOSE AND ALLOWED THE CONTENTS TO LEAK OUT. CARTON WAS RECOOPED IN RECOVERY DRUM WITH CLEAN UP MATERIAL AND OUT. CARTON WAS RECOOPED IN RECOVERY DRUM WITH CLEAN UP MATERIAL AND RETURNED TO SHIPPER.
RETURNED TO SHIPPER.

1849 WEST VALLEY BLVD
COLTON, CA

Inquiry Number:
May 19, 2008

EDR Site Report™

EDR® Environmental Data Resources Inc

440 Wheelers Farms Road
Milford, CT 06461
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

The EDR-Site Report™ is a comprehensive presentation of government filings on a facility identified in a search of over 4 million government records from more than 600 federal, state and local environmental databases. The report is divided into three sections:

Section 1: Facility Summary ..... **Page 3**

Summary of facility filings including a review of the following areas: waste management, waste disposal, multi-media issues, and Superfund liability.

Section 2: Facility Detail Reports ..... **Page 4**

All available detailed information from databases where sites are identified.

Section 3: Databases Searched and Update Information. ..... **Page 6**

Name, source, update dates, contact phone number and description of each of the databases searched for this report.

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This report contains information obtained from a variety of public and other sources reasonably available to Environmental Data Resources , Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANYSUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES.ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.**Purchaser accepts this report "AS IS". Any analyses, estimates, ratings, or risk codes provided in this report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assesment performed by an environmental professional can produce information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2008 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

SECTION 1: FACILITY SUMMARY

FACILITY AREA	FACILITY 1 1849 WEST VALLEY BLVD COLTON, CA EDR ID #95060019
WASTE MANAGEMENT Facility generates hazardous waste (RCRA)	NO
Facility treats, stores, or disposes of hazardous waste on-site (RCRA/TSDF)	NO
Facility has received Notices of Violations (RCRA/VIOL)	NO
Facility has been subject to RCRA administrative actions (RAATS)	NO
Facility has been subject to corrective actions (CORRACTS)	NO
Facility handles PCBs (PADS)	NO
Facility uses radioactive materials (MLTS)	NO
Facility manages registered aboveground storage tanks (AST)	NO
Facility manages registered underground storage tanks (UST)	NO
Facility has reported leaking underground storage tank incidents (LUST)	NO
Facility has reported emergency releases to the soil (ERNS)	NO
Facility has reported hazardous material incidents to DOT (HMIRS)	**YES - p4**
WASTE DISPOSAL Facility is a Superfund Site (NPL)	NO
Facility has a known or suspect abandoned, inactive or uncontrolled hazardous waste site (CERCLIS)	NO
Facility has a reported Superfund Lien on it (LIENS)	NO
Facility is listed as a state hazardous waste site (SHWS)	NO
Facility has disposed of solid waste on-site (SWF/LF)	NO
MULTIMEDIA Facility uses toxic chemicals and has notified EPA under SARA Title III, Section 313 (TRIS)	NO
Facility produces pesticides and has notified EPA under Section 7 of FIFRA (SSTS)	NO
Facility manufactures or imports toxic chemicals on the TSCA list (TSCA)	NO
Facility has inspections under FIFRA, TSCA or EPCRA (FTTS)	NO
Facility is listed in EPA's index system (FINDS)	NO
Facility is listed in a county/local unique database (LOCAL)	NO
POTENTIAL SUPERFUND LIABILITY Facility has a list of potentially responsible parties PRP	NO
TOTAL (YES)	1

SECTION 2: FACILITY DETAIL REPORTS

WASTE MANAGEMENT

Facility has reported hazardous material incidents to DOT

DATABASE: Hazardous Materials Information Reporting System (HMIRS)

1849 WEST VALLEY BLVD
COLTON, CA
EDR ID #95060019

HMIRS:

Report #:	95060019
Site location:	1849 WEST VALLEY BLVD COLTON, CA
Place of origin:	100 1/2 WALDRON DR DURANT, OK 74701
Destination:	CARPENTER CO 7809 LINCOLN AVE RIVERSIDE, CA 92504
Carrier ID:	19759
Carrier reporting #:	MC29910
Carrier:	ABF FREIGHT SYSTEM INC
Carrier address:	PO BOX 10048 FORT SMITH, AR 729170048
Shipper ID:	30573
Shipper name:	DYSON OIL CO
Shipper address:	100 1/2 WALDRON DR DURANT, OK 74701
Shipping paper number:	PRO 164051410
Consignee ID:	11646
Consignee name:	CARPENTER CO
Consignee addess:	7809 LINCOLN AVE RIVERSIDE, CA 92504
General cause:	010
Transportation mode:	004
Date:	05/22/1995
Commodity name:	ISOBUTANOL
Trade name:	Not reported
Amount:	.50000000 GAL
Result:	Spillage
Hazard Class:	30
ID Number:	UN1212
Hazardous:	True
R.Q. met:	False
Misc. info:	100 100
Vehicle Type:	Van truck/trailer
Trans. phase:	263
Land use:	271
Community:	281
Accident/Derailment:	False
Estimated speed:	F
Highway type:	Not reported
number of lanes:	Not reported
Number evacuated:	000000
Major injuries:	000
Minor injuries:	000
Fatalities:	00
Product loss:	00000005
Carrier damage:	00000000
Pvt/Pub damage:	00000000
Cleanup cost:	00000000
Other damage:	00000000
Reported damage:	00000005
Incident damage:	00000000

Inner and Outer Container Information:

Container type:	PAIL PLS
Container capacity:	5.00000000 GAL
Number failed:	00001
Number in shipment:	00000
Container gauge:	40
Manufacture's ID:	16222
Manuf. name:	NOT REPORTED BY CARRIER UNKNOWN, XX
Tank serial #:	Not reported
Label:	RED
Registration #:	Not reported
Inspection date:	Not reported
Exemption #:	Not reported

Contributing cause:	Dropped
Contributing Object:	Roadway
Contributing failure:	Cracked
Affected side:	Bottom
Other contributing cause:	Package material
Capacity container code:	Not reported
Number failed code:	Not reported
Shipment code number:	Not reported

1849 W VALLEY BLVD
COLTON, CA

Inquiry Number:
May 19, 2008

EDR Site Report™

EDR® Environmental Data Resources Inc

440 Wheelers Farms Road
Milford, CT 06461
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

The EDR-Site Report™ is a comprehensive presentation of government filings on a facility identified in a search of over 4 million government records from more than 600 federal, state and local environmental databases. The report is divided into three sections:

Section 1: Facility Summary . . . . . **Page 3**

Summary of facility filings including a review of the following areas: waste management, waste disposal, multi-media issues, and Superfund liability.

Section 2: Facility Detail Reports . . . . . **Page 4**

All available detailed information from databases where sites are identified.

Section 3: Databases Searched and Update Information. . . . . . **Page 6**

Name, source, update dates, contact phone number and description of each of the databases searched for this report.

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This report contains information obtained from a variety of public and other sources reasonably available to Environmental Data Resources , Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANYSUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES.ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.**Purchaser accepts this report "AS IS". Any analyses, estimates, ratings, or risk codes provided in this report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assesment performed by an environmental professional can produce information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2008 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

SECTION 1: FACILITY SUMMARY

FACILITY AREA	FACILITY 1 1849 W VALLEY BLVD COLTON, CA EDR ID #95101485
WASTE MANAGEMENT Facility generates hazardous waste (RCRA)	NO
Facility treats, stores, or disposes of hazardous waste on-site (RCRA/TSDF)	NO
Facility has received Notices of Violations (RCRA/VIOL)	NO
Facility has been subject to RCRA administrative actions (RAATS)	NO
Facility has been subject to corrective actions (CORRACTS)	NO
Facility handles PCBs (PADS)	NO
Facility uses radioactive materials (MLTS)	NO
Facility manages registered aboveground storage tanks (AST)	NO
Facility manages registered underground storage tanks (UST)	NO
Facility has reported leaking underground storage tank incidents (LUST)	NO
Facility has reported emergency releases to the soil (ERNS)	NO
Facility has reported hazardous material incidents to DOT (HMIRS)	**YES - p4**
WASTE DISPOSAL Facility is a Superfund Site (NPL)	NO
Facility has a known or suspect abandoned, inactive or uncontrolled hazardous waste site (CERCLIS)	NO
Facility has a reported Superfund Lien on it (LIENS)	NO
Facility is listed as a state hazardous waste site (SHWS)	NO
Facility has disposed of solid waste on-site (SWF/LF)	NO
MULTIMEDIA Facility uses toxic chemicals and has notified EPA under SARA Title III, Section 313 (TRIS)	NO
Facility produces pesticides and has notified EPA under Section 7 of FIFRA (SSTS)	NO
Facility manufactures or imports toxic chemicals on the TSCA list (TSCA)	NO
Facility has inspections under FIFRA, TSCA or EPCRA (FTTS)	NO
Facility is listed in EPA's index system (FINDS)	NO
Facility is listed in a county/local unique database (LOCAL)	NO
POTENTIAL SUPERFUND LIABILITY Facility has a list of potentially responsible parties PRP	NO
TOTAL (YES)	1

SECTION 2: FACILITY DETAIL REPORTS

WASTE MANAGEMENT

Facility has reported hazardous material incidents to DOT

DATABASE: Hazardous Materials Information Reporting System (HMIRS)

1849 W VALLEY BLVD
COLTON, CA
EDR ID #95101485

HMIRS:

Report #:	95101485
Site location:	1849 W VALLEY BLVD COLTON, CA
Place of origin:	3535 LATONIA AVE FORT WRIGHT, KY 41015
Destination:	REV CHEM PLASTICS 2720 S WILLOW AVE 8 RIALTO, CA 92376
Carrier ID:	19759
Carrier reporting #:	MC29910
Carrier:	ABF FREIGHT SYSTEM INC
Carrier address:	PO BOX 10048 FORT SMITH, AR 729710048
Shipper ID:	61182
Shipper name:	SILMAR INTERPLASTIC CORP
Shipper address:	3535 LATONIA AVE FORT WRIGHT, KY 41015
Shipping paper number:	PRO 067823935
Consignee ID:	21405
Consignee name:	REV CHEM PLASTICS
Consignee addess:	2720 S WILLOW AVE 8 RIALTO, CA 92376
General cause:	010
Transportation mode:	004
Date:	10/09/1995
Commodity name:	RESIN SOLUTION
Trade name:	STYRENE MONOMER
Amount:	5.0000000 GAL
Result:	Spillage
Hazard Class:	30
ID Number:	UN1866
Hazardous:	False
R.Q. met:	False
Misc. info:	100 100
Vehicle Type:	Van truck/trailer
Trans. phase:	263
Land use:	272
Community:	281
Accident/Derailment:	False
Estimated speed:	F
Highway type:	Not reported
number of lanes:	Not reported
Number evacuated:	000000
Major injuries:	000
Minor injuries:	000
Fatalities:	00
Product loss:	00000025
Carrier damage:	00000000
Pvt/Pub damage:	00000000
Cleanup cost:	00000100
Other damage:	00000000
Reported damage:	00000125
Incident damage:	00000000

Inner and Outer Container Information:

Container type:	DRUM MTL
Container capacity:	55.0000000 GAL
Number failed:	00001
Number in shipment:	00001
Container gauge:	00
Manufacture's ID:	16222
Manuf. name:	NOT REPORTED BY CARRIER UNKNOWN, XX
Tank serial #:	Not reported
Label:	RED
Registration #:	Not reported
Inspection date:	Not reported
Exemption #:	Not reported

SECTION 2: FACILITY DETAIL REPORTS

...Continued...

Contributing cause:	Struck/rammed
Contributing Object:	Forklift
Contributing failure:	Punctured
Affected side:	Bottom
Other contributing cause:	Package material
Capacity container code:	Not reported
Number failed code:	Not reported
Shipment code number:	Not reported

MOSS BROS FORD
1900 W VALLEY BLVD
COLTON, CA 92324

Inquiry Number:
May 19, 2008

EDR Site Report™

EDR® Environmental Data Resources Inc

440 Wheelers Farms Road
Milford, CT 06461
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

The EDR-Site Report™ is a comprehensive presentation of government filings on a facility identified in a search of over 4 million government records from more than 600 federal, state and local environmental databases. The report is divided into three sections:

Section 1: Facility Summary ..... **Page 3**

Summary of facility filings including a review of the following areas: waste management, waste disposal, multi-media issues, and Superfund liability.

Section 2: Facility Detail Reports ..... **Page 4**

All available detailed information from databases where sites are identified.

Section 3: Databases Searched and Update Information. ..... **Page 7**

Name, source, update dates, contact phone number and description of each of the databases searched for this report.

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This report contains information obtained from a variety of public and other sources reasonably available to Environmental Data Resources , Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANYSUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES.ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.**Purchaser accepts this report "AS IS". Any analyses, estimates, ratings, or risk codes provided in this report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assesment performed by an environmental professional can produce information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2008 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

SECTION 1: FACILITY SUMMARY

FACILITY AREA	FACILITY 1 MOSS BROS FORD 1900 W VALLEY BLVD COLTON, CA 92324 EDR ID #1008153008 EPA #110018973388
WASTE MANAGEMENT Facility generates hazardous waste (RCRA)	NO
Facility treats, stores, or disposes of hazardous waste on-site (RCRA/TSDF)	NO
Facility has received Notices of Violations (RCRA/VIOL)	NO
Facility has been subject to RCRA administrative actions (RAATS)	NO
Facility has been subject to corrective actions (CORRACTS)	NO
Facility handles PCBs (PADS)	NO
Facility uses radioactive materials (MLTS)	NO
Facility manages registered aboveground storage tanks (AST)	NO
Facility manages registered underground storage tanks (UST)	NO
Facility has reported leaking underground storage tank incidents (LUST)	NO
Facility has reported emergency releases to the soil (ERNS)	NO
Facility has reported hazardous material incidents to DOT (HMIRS)	NO
WASTE DISPOSAL Facility is a Superfund Site (NPL)	NO
Facility has a known or suspect abandoned, inactive or uncontrolled hazardous waste site (CERCLIS)	NO
Facility has a reported Superfund Lien on it (LIENS)	NO
Facility is listed as a state hazardous waste site (SHWS)	NO
Facility has disposed of solid waste on-site (SWF/LF)	NO
MULTIMEDIA Facility uses toxic chemicals and has notified EPA under SARA Title III, Section 313 (TRIS)	NO
Facility produces pesticides and has notified EPA under Section 7 of FIFRA (SSTS)	NO
Facility manufactures or imports toxic chemicals on the TSCA list (TSCA)	NO
Facility has inspections under FIFRA, TSCA or EPCRA (FTTS)	NO
Facility is listed in EPA's index system (FINDS)	**YES - p4**
Facility is listed in a county/local unique database (LOCAL)	**YES - p5**
POTENTIAL SUPERFUND LIABILITY Facility has a list of potentially responsible parties PRP	NO
TOTAL (YES)	2

SECTION 2: FACILITY DETAIL REPORTS

MULTIMEDIA

Facility is listed in EPA's index system

DATABASE: Facility Index System (FINDS)

MOSS BROS FORD
1900 W VALLEY BLVD
COLTON, CA 92324
EDR ID #1008153008

This site is listed in the Federal FINDS database. The FINDS database may contain references to records from government databases included elsewhere in the report.
Please note: the FINDS database may also contain references to out of date records formerly associated with the site.

Registry ID:	110018973388
Facility Name:	MOSS BROTHERS FORD
Facility Address:	1900 W VALLEY BLVD COLTON, CA 923240000
Facility County:	SAN BERNARDINO
EPA Region:	09
Fed. Gov. Facility:	Not reported
Indian Tribal Land:	No

EPA Records Indicate Facility Is Listed In
California - Hazardous Waste Tracking System - Datamart

UORS (California - Used Oil Recycling System). California Integrated Waste Management Board (CIWMB) helps communities establish and promote convenient collection opportunities for used oil and used oil filters.

Prg. Sys. ID:	CAR000130690
Supplemental Interest:	HAZARDOU WASTE PROGRAM
Facility SIC Codes:	Not reported
Facility NAICS Codes:	Not reported

Prg. Sys. ID:	36-C-07557
Supplemental Interest:	USED OIL PROGRAM
Facility SIC Codes:	Not reported
Facility NAICS Codes:	Not reported

Alternative name: MOSS BROTHERS FORD

MULTIMEDIA

Facility is listed in a county/local unique database

DATABASE: State/County (LOCAL)

MOSS BROS FORD
1900 W VALLEY BLVD
COLTON, CA 92324
EDR ID #1008153008

HAZNET:

Gepaid:	CAL000262514
Contact:	MIKE DAWE, DIRECTOR P/S
Telephone:	9098251212
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1900 W VALLEY
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	San Bernardino
TSD EPA ID:	CAD028409019
TSD County:	Los Angeles
Waste Category:	Unspecified solvent mixture Waste
Disposal Method:	Transfer Station
Tons:	0.45
Facility County:	Not reported

Gepaid:	CAL000262514
Contact:	MIKE DAWE, MGR
Telephone:	9098251212
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1900 W VALLEY
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	San Bernardino
TSD EPA ID:	CAD028409019
TSD County:	Los Angeles
Waste Category:	Unspecified solvent mixture Waste
Disposal Method:	Transfer Station
Tons:	0.45
Facility County:	San Bernardino

Gepaid:	CAR000130690
Contact:	MIKE DANE, MGR
Telephone:	9098251212
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1900 W VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	San Bernardino
TSD EPA ID:	ARD981057870
TSD County:	99
Waste Category:	Waste oil and mixed oil
Disposal Method:	H06
Tons:	0.22
Facility County:	San Bernardino

Gepaid:	CAL000262514
Contact:	MIKE DAWE, DIRECTOR P/S
Telephone:	9098251212
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1900 W VALLEY
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	San Bernardino
TSD EPA ID:	CAD981696420
TSD County:	San Bernardino
Waste Category:	Waste oil and mixed oil
Disposal Method:	Recycler
Tons:	3.12
Facility County:	San Bernardino

Gepaid:	CAL000262514
Contact:	MIKE DAWE, DIRECTOR P/S
Telephone:	9098251212
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1900 W VALLEY
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	San Bernardino
TSD EPA ID:	CAT000613927

SECTION 2: FACILITY DETAIL REPORTS

...Continued...

TSD County:	San Bernardino
Waste Category:	Aqueous solution with less than 10% total organic residues
Disposal Method:	Not reported
Tons:	0.45
Facility County:	San Bernardino

Gepaid:	CAL000262514
Contact:	MIKE DAWE, DIRECTOR P/S
Telephone:	9098251212
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1900 W VALLEY
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	San Bernardino
TSD EPA ID:	CAD028409019
TSD County:	San Bernardino
Waste Category:	Unspecified solvent mixture Waste
Disposal Method:	Treatment, Tank
Tons:	0.2
Facility County:	San Bernardino

Gepaid:	CAL000262514
Contact:	MIKE DAWE, DIRECTOR P/S
Telephone:	9098251212
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1900 W VALLEY
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	San Bernardino
TSD EPA ID:	CAD981696420
TSD County:	San Bernardino
Waste Category:	Aqueous solution with less than 10% total organic residues
Disposal Method:	Recycler
Tons:	0.83
Facility County:	San Bernardino

Gepaid:	CAL000262514
Contact:	MIKE DAWE, DIRECTOR P/S
Telephone:	9098251212
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1900 W VALLEY
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	San Bernardino
TSD EPA ID:	CAT000613927
TSD County:	San Bernardino
Waste Category:	Aqueous solution with less than 10% total organic residues
Disposal Method:	Transfer Station
Tons:	3.05
Facility County:	San Bernardino

Gepaid:	CAL000262514
Contact:	MIKE DAWE, DIRECTOR P/S
Telephone:	9098251212
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1900 W VALLEY
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	San Bernardino
TSD EPA ID:	CAD028409019
TSD County:	Los Angeles
Waste Category:	Unspecified solvent mixture Waste
Disposal Method:	Transfer Station
Tons:	0.45
Facility County:	Not reported

2051 SLOVER AVE
2051 SLOVER AVE
COLTON, CA 92324

Inquiry Number:
May 20, 2008

EDR Site Report™



EDR® Environmental Data Resources Inc

440 Wheelers Farms Road
Milford, CT 06461
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

The EDR-Site Report™ is a comprehensive presentation of government filings on a facility identified in a search of over 4 million government records from more than 600 federal, state and local environmental databases. The report is divided into three sections:

Section 1: Facility Summary ..... **Page 3**

Summary of facility filings including a review of the following areas: waste management, waste disposal, multi-media issues, and Superfund liability.

Section 2: Facility Detail Reports ..... **Page 4**

All available detailed information from databases where sites are identified.

Section 3: Databases Searched and Update Information. ..... **Page 5**

Name, source, update dates, contact phone number and description of each of the databases searched for this report.

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This report contains information obtained from a variety of public and other sources reasonably available to Environmental Data Resources , Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANYSUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES.ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.**Purchaser accepts this report "AS IS". Any analyses, estimates, ratings, or risk codes provided in this report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assesment performed by an environmental professional can produce information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2008 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

SECTION 1: FACILITY SUMMARY

FACILITY AREA	FACILITY 1 **2051 SLOVER AVE** 2051 SLOVER AVE COLTON, CA 92324 EDR ID #92280739
WASTE MANAGEMENT Facility generates hazardous waste (RCRA)	NO
Facility treats, stores, or disposes of hazardous waste on-site (RCRA/TSDF)	NO
Facility has received Notices of Violations (RCRA/VIOL)	NO
Facility has been subject to RCRA administrative actions (RAATS)	NO
Facility has been subject to corrective actions (CORRACTS)	NO
Facility handles PCBs (PADS)	NO
Facility uses radioactive materials (MLTS)	NO
Facility manages registered aboveground storage tanks (AST)	NO
Facility manages registered underground storage tanks (UST)	NO
Facility has reported leaking underground storage tank incidents (LUST)	NO
Facility has reported emergency releases to the soil (ERNS)	**YES - p4**
Facility has reported hazardous material incidents to DOT (HMIRS)	NO
WASTE DISPOSAL Facility is a Superfund Site (NPL)	NO
Facility has a known or suspect abandoned, inactive or uncontrolled hazardous waste site (CERCLIS)	NO
Facility has a reported Superfund Lien on it (LIENS)	NO
Facility is listed as a state hazardous waste site (SHWS)	NO
Facility has disposed of solid waste on-site (SWF/LF)	NO
MULTIMEDIA Facility uses toxic chemicals and has notified EPA under SARA Title III, Section 313 (TRIS)	NO
Facility produces pesticides and has notified EPA under Section 7 of FIFRA (SSTS)	NO
Facility manufactures or imports toxic chemicals on the TSCA list (TSCA)	NO
Facility has inspections under FIFRA, TSCA or EPCRA (FTTS)	NO
Facility is listed in EPA's index system (FINDS)	NO
Facility is listed in a county/local unique database (LOCAL)	NO
POTENTIAL SUPERFUND LIABILITY Facility has a list of potentially responsible parties PRP	NO
TOTAL (YES)	1

SECTION 2: FACILITY DETAIL REPORTS

WASTE MANAGEMENT

Facility has reported emergency releases to the soil

DATABASE: Emergency Response Notification System (ERNS)

2051 SLOVER AVE
2051 SLOVER AVE
COLTON, CA 92324
EDR ID #92280739

ERNS:

Site ID:	92280739
Site location:	2051 SLOVER AVE COLTON, CA 92324-
County:	SAN BERNARDINO
Report number:	Not reported
EPA region:	09
Spill date:	08/19/1992
Spill time:	09:30
Medium affected:	Land
Damage:	False
Damage $ amount:	0.00
Number of injured:	0
Number of fatalities:	0
Notes:	Not reported
Discharger:	CAL NEV PIPELINE CO
Discharger address:	PO BOX 6346 SAN BERNARDINO, CA 92412-
Discharger county:	SAN BERNARDINO
C.G. Unit:	Not reported
EPA notified:	True
Initial report:	True
Updated report:	True
Spill cause:	Not reported
Spilled material:	DIESEL
Spill total qty:	100.00 BBL
In water:	0.00 UNK
DOT #:	UN1270
CAS:	6833430
Quantity (lbs):	29400.00
Description:	OVERFILLED
Action:	FREE PRODUCT CLEANED UP. REMOVING CONTAMINATED SOIL.
Comments:	CALLER WAS CONCERNED ABOUT ENDANGERED FISH IN CREEK

2051 W. SLOVER AVENUE
2051 W. SLOVER AVENUE
COLTON, CA 92324

Inquiry Number:
May 20, 2008

EDR Site Report™



EDR® Environmental Data Resources Inc

440 Wheelers Farms Road
Milford, CT 06461
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

The EDR-Site Report™ is a comprehensive presentation of government filings on a facility identified in a search of over 4 million government records from more than 600 federal, state and local environmental databases. The report is divided into three sections:

Section 1: Facility Summary ..... **Page 3**

Summary of facility filings including a review of the following areas: waste management, waste disposal, multi-media issues, and Superfund liability.

Section 2: Facility Detail Reports ..... **Page 4**

All available detailed information from databases where sites are identified.

Section 3: Databases Searched and Update Information ..... **Page 5**

Name, source, update dates, contact phone number and description of each of the databases searched for this report.

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This report contains information obtained from a variety of public and other sources reasonably available to Environmental Data Resources , Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANYSUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES.ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.**Purchaser accepts this report "AS IS". Any analyses, estimates, ratings, or risk codes provided in this report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assesment performed by an environmental professional can produce information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2008 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

SECTION 1: FACILITY SUMMARY

AREA	FACILITY FACILITY 1 **2051 W. SLOVER AVENUE** 2051 W. SLOVER AVENUE COLTON, CA 92324 EDR ID #90179352
WASTE MANAGEMENT Facility generates hazardous waste (RCRA)	NO
Facility treats, stores, or disposes of hazardous waste on-site (RCRA/TSDF)	NO
Facility has received Notices of Violations (RCRA/VIOL)	NO
Facility has been subject to RCRA administrative actions (RAATS)	NO
Facility has been subject to corrective actions (CORRACTS)	NO
Facility handles PCBs (PADS)	NO
Facility uses radioactive materials (MLTS)	NO
Facility manages registered aboveground storage tanks (AST)	NO
Facility manages registered underground storage tanks (UST)	NO
Facility has reported leaking underground storage tank incidents (LUST)	NO
Facility has reported emergency releases to the soil (ERNS)	**YES - p4**
Facility has reported hazardous material incidents to DOT (HMIRS)	NO
WASTE DISPOSAL Facility is a Superfund Site (NPL)	NO
Facility has a known or suspect abandoned, inactive or uncontrolled hazardous waste site (CERCLIS)	NO
Facility has a reported Superfund Lien on it (LIENS)	NO
Facility is listed as a state hazardous waste site (SHWS)	NO
Facility has disposed of solid waste on-site (SWF/LF)	NO
MULTIMEDIA Facility uses toxic chemicals and has notified EPA under SARA Title III, Section 313 (TRIS)	NO
Facility produces pesticides and has notified EPA under Section 7 of FIFRA (SSTS)	NO
Facility manufactures or imports toxic chemicals on the TSCA list (TSCA)	NO
Facility has inspections under FIFRA, TSCA or EPCRA (FTTS)	NO
Facility is listed in EPA's index system (FINDS)	NO
Facility is listed in a county/local unique database (LOCAL)	NO
POTENTIAL SUPERFUND LIABILITY Facility has a list of potentially responsible parties PRP	NO
TOTAL (YES)	1

SECTION 2: FACILITY DETAIL REPORTS

WASTE MANAGEMENT

Facility has reported emergency releases to the soil

DATABASE: Emergency Response Notification System (ERNS)

2051 W. SLOVER AVENUE
2051 W. SLOVER AVENUE
COLTON, CA 92324
EDR ID #90179352

ERNS:

Site ID:	90179352
Site location:	2051 W. SLOVER AVENUE COLTON, CA 92324-
County:	SAN BERNARDINO
Report number:	Not reported
EPA region:	09
Spill date:	08/27/1990
Spill time:	10:30
Medium affected:	Land
Damage:	False
Damage $ amount:	0.00
Number of injured:	0
Number of fatalities:	0
Notes:	NONE
Discharger:	SANTA FE PACIFIC PIPELINE
Discharger address:	888 S. FIGUEROA LOS ANGELES, CA 90017-
Discharger county:	LOS ANGELES
C.G. Unit:	Not reported
EPA notified:	True
Initial report:	True
Updated report:	True
Spill cause:	Equipment Failure
Spilled material:	#2 DIESEL
Spill total qty:	0.00 OTH
In water:	0.00
DOT #:	UN1270
CAS:	Not reported
Quantity (lbs):	0.00
Description:	QUANTITY=UNKNOWN SMALL AMOUNT PINHOLE LEAK IN 2" LINE ON CAL NEW PROPERTY, DISCOVERED DURING EXCAVAT ION.
Action:	CLEANUP BY RP.
Comments:	Not reported

2051 SLOVER AVE
2051 SLOVER AVE
COLTEN, CA 92412

Inquiry Number:
May 20, 2008

EDR Site Report™



EDR® Environmental Data Resources Inc

440 Wheelers Farms Road
Milford, CT 06461
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

The EDR-Site Report™ is a comprehensive presentation of government filings on a facility identified in a search of over 4 million government records from more than 600 federal, state and local environmental databases. The report is divided into three sections:

Section 1: Facility Summary ..... **Page 3**

Summary of facility filings including a review of the following areas: waste management, waste disposal, multi-media issues, and Superfund liability.

Section 2: Facility Detail Reports ..... **Page 4**

All available detailed information from databases where sites are identified.

Section 3: Databases Searched and Update Information ..... **Page 5**

Name, source, update dates, contact phone number and description of each of the databases searched for this report.

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This report contains information obtained from a variety of public and other sources reasonably available to Environmental Data Resources , Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANYSUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES.ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.**Purchaser accepts this report "AS IS". Any analyses, estimates, ratings, or risk codes provided in this report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assesment performed by an environmental professional can produce information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2008 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

SECTION 1: FACILITY SUMMARY

FACILITY AREA	FACILITY 1 **2051 SLOVER AVE** 2051 SLOVER AVE COLTEN, CA 92412 EDR ID #92280900
WASTE MANAGEMENT Facility generates hazardous waste (RCRA)	NO
Facility treats, stores, or disposes of hazardous waste on-site (RCRA/TSDF)	NO
Facility has received Notices of Violations (RCRA/VIOL)	NO
Facility has been subject to RCRA administrative actions (RAATS)	NO
Facility has been subject to corrective actions (CORRACTS)	NO
Facility handles PCBs (PADS)	NO
Facility uses radioactive materials (MLTS)	NO
Facility manages registered aboveground storage tanks (AST)	NO
Facility manages registered underground storage tanks (UST)	NO
Facility has reported leaking underground storage tank incidents (LUST)	NO
Facility has reported emergency releases to the soil (ERNS)	**YES - p4**
Facility has reported hazardous material incidents to DOT (HMIRS)	NO
WASTE DISPOSAL Facility is a Superfund Site (NPL)	NO
Facility has a known or suspect abandoned, inactive or uncontrolled hazardous waste site (CERCLIS)	NO
Facility has a reported Superfund Lien on it (LIENS)	NO
Facility is listed as a state hazardous waste site (SHWS)	NO
Facility has disposed of solid waste on-site (SWF/LF)	NO
MULTIMEDIA Facility uses toxic chemicals and has notified EPA under SARA Title III, Section 313 (TRIS)	NO
Facility produces pesticides and has notified EPA under Section 7 of FIFRA (SSTS)	NO
Facility manufactures or imports toxic chemicals on the TSCA list (TSCA)	NO
Facility has inspections under FIFRA, TSCA or EPCRA (FTTS)	NO
Facility is listed in EPA's index system (FINDS)	NO
Facility is listed in a county/local unique database (LOCAL)	NO
POTENTIAL SUPERFUND LIABILITY Facility has a list of potentially responsible parties PRP	NO
TOTAL (YES)	1

SECTION 2: FACILITY DETAIL REPORTS

WASTE MANAGEMENT

Facility has reported emergency releases to the soil

DATABASE: Emergency Response Notification System (ERNS)

2051 SLOVER AVE
2051 SLOVER AVE
COLTEN, CA 92412
EDR ID #92280900

ERNS:

Site ID:	92280900
Site location:	2051 SLOVER AVE COLTEN, CA 92412
County:	SAN BERNARDINO
Report number:	132626
EPA region:	09
Spill date:	08/19/1992
Spill time:	09:30
Medium affected:	Land
Damage:	False
Damage $ amount:	0.00
Number of injured:	0
Number of fatalities:	0
Notes:	Not reported
Discharger:	CALNEV PIPELINE CO
Discharger address:	POB 6346 SAN BERNARDINO, CA 92412
Discharger county:	SAN BERNARDINO
C.G. Unit:	Not reported
EPA notified:	True
Initial report:	False
Updated report:	True
Spill cause:	Unknown
Spilled material:	OIL: DIESEL
Spill total qty:	100.00 BBL
In water:	0.00 UNK
DOT #:	UN1270
CAS:	6833430
Quantity (lbs):	29400.00
Description:	STORAGE TANK/OVERFILL DUE TO UNKNOWN CAUSE
Action:	VAC TRUCKS AND PUMPS HAVE COLLECTED ALL FREE PRODUCT, REMOVING CONTAMINATED SOIL
Comments:	Not reported

BACK TO SEARCH | GEOTRACKER HOME

Site Search Results

84 records found Page 1 of 3

SITE NAME	ADDRESS	CITY	COUNTY	SITE TYPE	STATUS		
)INT AUTO SERVICE	1221 E WASHINGTON ST	COLTON	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
ABC COMPANY	T 2S, R 4W, SEC 2-Q	COLTON	SAN BERNARDINO	WELL	N/A	VIEW PWS WELLS	
AM PM MINI MARKET #6144	1240 E WASHINGTON ST	COLTON	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
AMERICAN TIRE REPAIR	330 W CITRUS ST	COLTON	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
ARCO #1569	792 VALLEY BLVD	COLTON	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
ARCO #1569 (FORMER)	792 VALLEY BOULEVARD WEST	COLTON	SAN BERNARDINO	LUFT	**OPEN**	REPORT	SHOW ON MAP
ARCO #6144	22895 WASHINGTON ST	COLTON	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
ARCO #6144	1240 WASHINGTON STREET	COLTON	SAN BERNARDINO	LUFT	CLOSED	REPORT	
ARCO PETROLEUM PROD #1569	792 W VALLEY BLVD	COLTON	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
ARCO TANK FARM	2395 RIVERSIDE AVENUE S	COLTON	SAN BERNARDINO	SLIC	**OPEN**	REPORT	SHOW ON MAP
ARISTECH	291 ADAMS ST	COLTON	SAN BERNARDINO	LUFT	**OPEN**	REPORT	SHOW ON MAP
ARROWHEAD DRINKING WATER CO.	130 FOGG ST	COLTON	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
ARROWHEAD MEDICAL CTR (SAN BDNO MED CTR)	400 N. PEPPER AVE	COLTON	SAN BERNARDINO	WELL	N/A	VIEW PWS WELLS	
ARROWHEAD MTN SPRING WATR	130 FOGG ST	COLTON	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
\CON TRUCK STOP	2300 E STEEL RD	COLTON	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
BISHOP'S CENTRAL STORES	791 N PEPPER AVE	COLTON	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
BOB HUBBARD HORSE TRANSPR	3730 S RIVERSIDE AVE	COLTON	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
BRIGGS PLUMBING WARE INC	330 CITRUS ST	COLTON	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
BRINE FAC,COLTON	20870 SLOVER	COLTON	SAN BERNARDINO	LANDFILL	**OPEN**	REPORT	
CAL PORTLAND CEMENT	695 S RANCHO AVE	COLTON	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
CAL-MAT COMPANY	695 RANCHO AVE	COLTON	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
CALIF PORTLAND CEMENT	PO BOX 947	COLTON	SAN BERNARDINO	WELL	N/A	VIEW PWS WELLS	
CALWAL GYPSUM SUPPLY	125 9TH ST	COLTON	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
CANALE FOODS	1810 RIVERSIDE AVENUE	COLTON	SAN BERNARDINO	WELL	N/A	VIEW PWS WELLS	
CENTREPOINTE CAR WASH	1140 S MOUNT VERNON AVE	COLTON	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
CERAMIC-ENAMAL MFG FACILITY	330 CITRUS	COLTON	SAN BERNARDINO	LANDFILL	CLOSED	REPORT	SHOW ON MAP
CI-COLTON PUB WRKS/AUTO	160 S 10TH ST	COLTON	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
CITY OF COLTON	160 S. 10TH STREET	COLTON	SAN BERNARDINO	WELL	N/A	VIEW PWS WELLS	
CO-ARROWHEAD G.MED.CTR	400 N PEPPER AVE	COLTON	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
LTON UNIFIED SCHOOL DISTRICT	777 VALLEY BLVD	COLTON	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP

Jump to page: 1 2 3

Next 30

BACK TO SEARCH | GEOTRACKER HOME

Site Search Results

84 records found

SITE NAME	ADDRESS	CITY	COUNTY	SITE TYPE	STATUS		
COMPOSTING-INLAND COMPOSTING &	2300 RIVERSIDE	COLTON	SAN BERNARDINO	LANDFILL	CLOSED	REPORT	
COUNTRY CLUB TOW & STORAGE	1203 RANCHO AVE	COLTON	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
CUTTING EDGE SUPPLY	234 O ST	COLTON	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
DOMECQ RESERVOIR	1011 ELLEN ST	COLTON	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
FAND S GAS	1101 RANCHO RD	COLTON	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
FIVE POINT AUTO SERVICE	1221 WASHINGTON ST	COLTON	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
FORMER E-Z SERVE FACILIT Y #100779	847 VALLEY BLVD	COLTON	SAN BERNARDINO	LUFT	**OPEN**	REPORT	SHOW ON MAP
G & G	424 MILL ST	COLTON	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
GATX RAIL CORPORATION	20878 SLOVER ST	COLTON	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
GEN AMERICAN TRANS CORP	20878 SLOVER AVE	COLTON	SAN BERNARDINO	WELL	N/A	VIEW PWS WELLS	
GREENWASTE - INLAND EMPIRE COM	1951 KEY STREET	COLTON	SAN BERNARDINO	LANDFILL	CLOSED	REPORT	SHOW ON MAP
GRIFFIN WHEEL	1280 JEFFERSON LANE	COLTON	RIVERSIDE	SLIC	**OPEN**	REPORT	SHOW ON MAP
HONDA RIDER EDUCATION CTR	1301 VIA VENITO	COLTON	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
IOWA SHELL	2718 S IOWA AVE	COLTON	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
JON-LIN INC.	1620 8TH ST	COLTON	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
KEY MUTUAL WATER CO.	20378 KEY ST	COLTON	SAN BERNARDINO	WELL	N/A	VIEW PWS WEL	
LA CADENA EXPRESS	420 N LA CADENA DR	COLTON	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
LANDFILL,COLTON	1280 JEFFERSON LANE	COLTON	SAN BERNARDINO	LANDFILL	**OPEN**	REPORT	SHOW ON MAP
LANDFILL,COLTON	850 TROPICA RANCHO ROAD	COLTON	SAN BERNARDINO	LANDFILL	**OPEN**	REPORT	SHOW ON MAP
LANDFILL,COOLEY RANCH-INACTIVE	WASHINGTON	COLTON	SAN BERNARDINO	LANDFILL	**OPEN**	REPORT	SHOW ON MAP
MOBIL #18-HTQ	130 VALLEY BLVD	COLTON	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
MOBIL S S #18-HTQ	130 W VALLEY BLVD	COLTON	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
MONTECITO MORTUARY	24145 BARTON RD	COLTON	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
MORTON INTERNATIONAL	1231 LINCOLN AVE	COLTON	SAN BERNARDINO	LUFT	**OPEN**	REPORT	SHOW ON MAP
MT VERNON/VALLEY AM/PM	202 N MOUNT VERNON AVE	COLTON	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
OLIVE DELL RANCH	26520 KEISSEL RD	COLTON	SAN BERNARDINO	WELL	N/A	VIEW PWS WELLS	
ORANGE SHELL - COLTON	1600 W VALLEY BLVD	COLTON	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
RANCHO READY MIX	1150 RANCHO AVE	COLTON	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
RECHE CANYON MOBILE ESTATES	2751 RECHE CANYON	COLTON	SAN BERNARDINO	WELL	N/A	VIEW PWS WELLS	
RECHE CANYON MWC	22125 BARTON ROAD, SUITE 600	COLTON	RIVERSIDE	WELL	N/A	VIEW PWS WEL	

Prev 30 Jump to page: 1 2 3 Next 30

BACK TO SEARCH | GEOTRACKER HOME

Site Search Results

84 records found Page 3 of 3

SITE NAME	ADDRESS	CITY	COUNTY	SITE TYPE	STATUS		
ERSIDE CONSTRUCTION CO.	2951 RIVERSIDE AVE	COLTON	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
RIVERSIDE HIGHLAND WATER CO	1450 WASHINGTON ST	COLTON	SAN BERNARDINO	WELL	N/A	VIEW PWS WELLS	
RIVERSIDE HIGHLAND WATER CO.	1450 WASHINGTON ST	COLTON	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
RIVERSIDE HIGHLAND WATER COMPANY	1450 E. WASHINGTON STREET	COLTON	SAN BERNARDINO	WELL	N/A	VIEW PWS WELLS	
S P EAST COLTON YARD	MOUNT VERNON	COLTON	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
SANDY'S MINI MART	1511 N MOUNT VERNON AVE	COLTON	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
SANTA FE PACIFIC PIPE LINE	2720 SLOVER	COLTON	SAN BERNARDINO	SLIC	**OPEN**	REPORT	SHOW ON MAP
SC-COLTON USD/TRANS	777 W VALLEY BLVD	COLTON	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
SHADID WATER SYSTEM	3013 SHADID DR.	COLTON	SAN BERNARDINO	WELL	N/A	VIEW PWS WELLS	
SHELL SERVICE STATION	1600 VALLEY BOULEVARD WEST	COLTON	SAN BERNARDINO	LUFT	CLOSED	REPORT	
SHELL STATION	2718 IOWA AVENUE	COLTON	SAN BERNARDINO	LUFT	**OPEN**	REPORT	
SONNY'S ENGINEERING	450 FOGG ST	COLTON	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
STATER BROS. WAREHOUSE	21700 BARTON RD	COLTON	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
STATER BROTHERS TRIBUTION	21700 BARTON RD	COLTON	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
TELCO FOODS	2111 VALLEY BOULEVARD WEST	COLTON	SAN BERNARDINO	LUFT	CLOSED	REPORT	
TERMINAL STATIONS, INC.	2300/23659 STEEL RD	COLTON	SAN BERNARDINO	LUFT	**OPEN**	REPORT	SHOW ON MAP
TERRACE WATER CO	1095-1/2 STEVENSON STREET	COLTON	SAN BERNARDINO	WELL	N/A	VIEW PWS WELLS	
TOM PREWITT CHEVRON #3537	1241 E WASHINGTON ST	COLTON	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
UNION PACIFIC RAILROAD COMPANY	EAST COLTON "M" YARD	COLTON	SAN BERNARDINO	SLIC	**OPEN**	REPORT	
UNOCAL TANK FARM	2301 RIVERSIDE AVENUE S	COLTON	SAN BERNARDINO	SLIC	**OPEN**	REPORT	SHOW ON MAP
VALLEY COLTON TRUCK STOP	791 E VALLEY BLVD	COLTON	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
WMB TRANSPORTATION	20414 KEY ST	COLTON	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
WMB TRANSPORTATION	2001 W KEY ST	COLTON	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
WMB TRANSPORTATION	2001 W KEY ST	COLTON	SAN BERNARDINO	WELL	N/A	VIEW PWS WELLS	

Prev 30 Jump to page: 1 2 3

BACK TO SEARCH | GEOTRACKER HOME

Site Search Results

27 records found Page 1 of 1

SITE NAME	ADDRESS	CITY	COUNTY	SITE TYPE	STATUS		
ARCO AM/PM	11510 CEDAR AVENUE	BLOOMINGTON	SAN BERNARDINO	LUFT	**OPEN**	REPORT	SHOW ON
ARCO AM/PM # 5997	18762 VALLEY BLVD	BLOOMINGTON	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
BLOOMGTN TEXACO/HOSSEIN A	18509 VALLEY BLVD	BLOOMINGTON	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
BRINE FAC,BLOOMINGTON	18298 SLOVER	BLOOMINGTON	SAN BERNARDINO	LANDFILL	**OPEN**	REPORT	
BRINE FAC,GENE BELK BLOOMINGTON-CLOSED	10380 ALDER	BLOOMINGTON	SAN BERNARDINO	LANDFILL	**OPEN**	REPORT	SHOW ON MAP
CEDAR AND SANTA ANA STATION	10898 CEDAR AVE	BLOOMINGTON	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
CHASTAIN PROPERTY	2591 S. RIVERSIDE AVE.	BLOOMINGTON	SAN BERNARDINO	SLIC	**OPEN**	REPORT	SHOW ON MAP
CHEVRON #9-8646	18745 VALLEY BLVD	BLOOMINGTON	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
CHEVRON COLTON TERMINAL	2297 RIVERSIDE AVE S	BLOOMINGTON	SAN BERNARDINO	SLIC	**OPEN**	REPORT	
CHEVRON STATION #8646	18745 VALLEY BLVD	BLOOMINGTON	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
CONOCO COLTON TERMINAL - EAST YARD	271 E. SLOVER AVE	BLOOMINGTON	SAN BERNARDINO	SLIC	CLOSED	REPORT	SHOW ON MAP
EQUILON ENT LLC	2307 S RIVERSIDE AVE	BLOOMINGTON	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
EQUILON ENT., L.L.C.	2237 S RIVERSIDE AVE	BLOOMINGTON	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
FEDEX GROUND	330 RESOURCE DR	BLOOMINGTON	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
GREENWASTE,CALIF. BIOMASS-BLOOMINGTON (CLOSED)	10397 ALDER	BLOOMINGTON	SAN BERNARDINO	LANDFILL	CLOSED	REPORT	SHOW ON
HERMAN WEISSKER, INC	2820 INDUSTRIAL DR	BLOOMINGTON	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHO ON MAP
LANDFILL,CRESTMORE-CLOSED	JURUPA	BLOOMINGTON	SAN BERNARDINO	LANDFILL	**OPEN**	REPORT	SHOW ON MAP
LIFEBOAT MOBIL	18689 VALLEY BLVD	BLOOMINGTON	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
MARYGOLD MWC	9715 ALDER AVENUE	BLOOMINGTON	SAN BERNARDINO	WELL	N/A	VIEW PWS WELLS	
MCI TELECOMM INC-BLMGTN	18850 ORANGE ST	BLOOMINGTON	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
MERIT OIL COMPANY	10065 ALDER	BLOOMINGTON	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
MOBIL FAC. #04-086 /COLTON TER	2305 RIVERSIDE AVE	BLOOMINGTON	SAN BERNARDINO	LUFT	**OPEN**	REPORT	SHOW ON MAP
S B C F D CENTRAL VALLEY #76	10174 MAGNOLIA ST	BLOOMINGTON	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
SEVEN-11 STORE #16755	10492 CEDAR AVE	BLOOMINGTON	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
SOUTHERN PACIFIC RAILYARD	200 MARION WAY	BLOOMINGTON	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
ST-CAL TRANS SLOVER STA	451 W SLOVER AVE	BLOOMINGTON	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
UNION PACIFIC RAILROAD-NILAND	19100 SLOVER AVENUE	BLOOMINGTON	SAN BERNARDINO	SLIC	**OPEN**	REPORT	

BACK TO SEARCH | GEOTRACKER HOME

Site Search Results

109 records found Page 1 of 4

SITE NAME	ADDRESS	CITY	COUNTY	SITE TYPE	STATUS		
ERICAN PROMOTIONAL EVENTS, INC.	3196 NORTH LOCUST	RIALTO	SAN BERNARDINO	SLIC	**OPEN**	REPORT	SHOW ON MAP
ARCO # 6365	2898 RIALTO AVENUE	RIALTO	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
ARCO #5305	484 RIVERSIDE AVE	RIALTO	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
ARCO #9551	280 E FOOTHILL BLVD	RIALTO	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
ARCO #9695	111 W VALLEY BLVD	RIALTO	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
ARCO - RIVERSIDE SERVICE	1877 RIVERSIDE AVE	RIALTO	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
ARCO 5305	484 RIVERSIDE AVE. SOUTH	RIALTO	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
ARCO COLTON TERMINAL	2395 RIVERSIDE AVE	RIALTO	SAN BERNARDINO	LUFT	**OPEN**	REPORT	SHOW ON MAP
ARCO COLTON TERMINAL (PUMPBACK STATION)	2395 RIVERSIDE AVENUE SOUTH	RIALTO	SAN BERNARDINO	LUFT	**OPEN**	REPORT	SHOW ON MAP
ARCO PETROLEUM PROD-COLTN	239S S RIVERSIDE AVE	RIALTO	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
ART SCHOLL AVIATION, INC	1700 MIRO WAY	RIALTO	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
BENETO INC	2329 S LILAC	RIALTO	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
BF GOODRICH	160 ACRES LOCUST AVE	RIALTO	SAN BERNARDINO	SLIC	**OPEN**	REPORT	
CALNEV	SLOVER AVE	RIALTO	SAN BERNARDINO	SLIC	**OPEN**	REPORT	
IEX USA CONST MATERIALS	3221 N RIVERSIDE AVE	RIALTO	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
CHEVRON #9-5626	115 BASELINE RD	RIALTO	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
CHEVRON #9-6969	101 VALLEY BLVD	RIALTO	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
CHEVRON STATION #6969	101 E VALLEY BLVD	RIALTO	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
CI-RIALTO WASTEWATER PLNT	501 E SANTA ANA AVE	RIALTO	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
CIRCLE K # 5249	105 PEPPER AVE	RIALTO	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
CIRCLE K #1979	688 W BASE LINE RD	RIALTO	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
CIRCLE K #5252	518 W FOOTHILL BLVD	RIALTO	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
CIRCLE K #5252/TOSCO	518 FOOTHILL BLVD	RIALTO	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
CIRCLE K #5253	920 W BLOOMINGTON AVE	RIALTO	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
CITY OF RIALTO	150 SOUTH PALM AVENUE	RIALTO	SAN BERNARDINO	WELL	N/A	VIEW PWS WELLS	
CLEM TRANS INC	213 VALLEY BLVD.	RIALTO	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
CO-RIALTO SHERIFF'S OFC	1776 MIRO WAY	RIALTO	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
COLTON TERMINAL	2359 SOUTH RIVERSIDE AVE	RIALTO	SAN BERNARDINO	SLIC	**OPEN**	REPORT	SHOW ON MAP
NOCO OIL	296 BASELINE RD	RIALTO	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
NTRACTORS CARGO COMPANY	2170 STONEHURST ROAD	RIALTO	SAN BERNARDINO	SLIC	**OPEN**	REPORT	

Jump to page: 1 2 3 4

Next 30

BACK TO SEARCH | GEOTRACKER HOME

Site Search Results

109 records found

SITE NAME	ADDRESS	CITY	COUNTY	SITE TYPE	STATUS		
CYPHER, CHARLES	265S S RIVERSIDE AVE	RIALTO	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON M
DENOVA ENVIRONMENTAL INC.	2610 NORTH ALDER	RIALTO	SAN BERNARDINO	SLIC	**OPEN**	REPORT	
DI-WEST SAN BDNO CWD	855 W BASE LINE RD	RIALTO	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
E & M AIRCRAFT	1480 LINDEN AVENUE N	RIALTO	SAN BERNARDINO	SLIC	**OPEN**	REPORT	SHOW ON MAP
ECOLOGY AUTO WRECKING	221 SANTA ANA AVENUE EAST	RIALTO	SAN BERNARDINO	LUFT	**OPEN**	REPORT	
ECOLOGY AUTO WRECKING	221 E SANTA ANA	RIALTO	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
EMPIRE OIL	2756 S RIVERSIDE AVE	RIALTO	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
ENSIGN-BICKFORD COMPANY	3196 LOCUST AVE	RIALTO	SAN BERNARDINO	SLIC	**OPEN**	REPORT	
ETI EXPLOSIVES TECHNOLOGIES INTERNATIONAL INC.	2900 TAMARIND AVE	RIALTO	SAN BERNARDINO	SLIC	**OPEN**	REPORT	
FEDERAL EXPRESS CORP	280 W VALLEY BLVD	RIALTO	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
FORMER UNION 76 STATION	120 BASELINE RD.WEST	RIALTO	SAN BERNARDINO	LUFT	CLOSED	REPORT	
GENCORP (AEROJET)	2170 STONEHURST ROAD	RIALTO	SAN BERNARDINO	SLIC	**OPEN**	REPORT	
GENERAL DYNAMICS	2610 NORTH ALDER	RIALTO	SAN BERNARDINO	SLIC	**OPEN**	REPORT	
I-10 TRUCK STOP	195 VALLEY BOULEVARD EAST	RIALTO	SAN BERNARDINO	LUFT	CLOSED	REPORT	
I-10 TRUCK STOP	195 E VALLEY BLVD	RIALTO	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
INLAND EMPIRE CAR WASH	445 FOOTHILL BOULEVARD WEST	RIALTO	SAN BERNARDINO	LUFT	CLOSED	REPORT	
INLAND EMPIRE CAR WASH	445 W FOOTHILL BLVD	RIALTO	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
INTER AM-PM MINI MART	2898 W RIALTO AVE	RIALTO	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
KEN THOMPSON, INC.	2250 LOWELL STREET	RIALTO	SAN BERNARDINO	SLIC	**OPEN**	REPORT	
KINDER/MORGAN	230S S RIVERSIDE AVE	RIALTO	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
KINDER/MORGAN.	2297 S RIVERSIDE AVE	RIALTO	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
LANDFILL,AGUA MANSA-INERT	588 EAST AGUA MANSA ROAD	RIALTO	SAN BERNARDINO	LANDFILL	**OPEN**	REPORT	SHOW ON MAP
LANDFILL,MID-VALLEY		RIALTO	SAN BERNARDINO	LANDFILL	**OPEN**	REPORT	
LANDFILL,RIALTO	SANTA ANA	RIALTO	SAN BERNARDINO	LANDFILL	**OPEN**	REPORT	
LOCKHEED/GCR	BUNKERS	RIALTO	SAN BERNARDINO	SLIC	**OPEN**	REPORT	
LYTLE SPRINGS WC	3546 N RIVERSIDE AVENUE	RIALTO	SAN BERNARDINO	WELL	N/A	VIEW PWS WELLS	
MERIT OIL	1020 BLOOMINGTON AVE	RIALTO	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
MID-VALLEY SANITARY LANDFILL NORTHEAST EXPANSION AREA	2170 STONEHURST ROAD, W	RIALTO	SAN BERNARDINO	SLIC	**OPEN**	REPORT	
MING CHUNG WONG	3196 NORTH LOCUST AVENUE	RIALTO	SAN BERNARDINO	SLIC	**OPEN**	REPORT	
MOBIL #18-E3B	116 BASELINE RD	RIALTO	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON M

Prev 30 Jump to page: 1 2 3 4 Next

BACK TO SEARCH | GEOTRACKER HOME

Site Search Results

109 records found Page 3 of 4

SITE NAME	ADDRESS	CITY	COUNTY	SITE TYPE	STATUS		
T'L CONVENIENCE STORE, INC.(AKA CIRCLE K STORE NO. 5249)	105 PEPPER ST	RIALTO	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
OLD DOMINION FREIGHT LINE	2209 S WILLOW AVE	RIALTO	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
OWL ROCK PRODUCTS	3221 RIVERSIDE AVE	RIALTO	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
PACIFIC BELL	495 S RIVERSIDE AVE	RIALTO	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
PENHALL COMPANY	2190 RIVERSIDE AVE	RIALTO	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
POMA AUTOMATED FUELING, INC.	2095 RIVERSIDE AVE	RIALTO	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
PYRO SPECTACULARS BY SOUZA (MCLAUGHLIN PIT SITE)	2250 WEST LOWELL STREET	RIALTO	SAN BERNARDINO	SLIC	**OPEN**	REPORT	
PYRO SPECTACULARS, INC. (ASTRO PYROTECHNICS)	2298 STONEHURST DRIVE, W	RIALTO	SAN BERNARDINO	SLIC	**OPEN**	REPORT	SHOW ON MAP
RAYTHEON COMPANY	2824 LOCUST AVENUE	RIALTO	SAN BERNARDINO	SLIC	**OPEN**	REPORT	
RIALTO CAR WASH	660 FOOTHILL BLVD	RIALTO	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
RIALTO MOBIL CTR #18-EE2	104 W FOOTHILL BLVD	RIALTO	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
RIALTO TEXACO SVC	110 E FOOTHILL BLVD	RIALTO	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
RIALTO UNIFIED SCHOOL DISTRICT	625 RIALTO AVE	RIALTO	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
RIALTO, CITY OF (TEXACO)	102 VALLEY BLVD	RIALTO	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
LTO, CITY OF/ METROLINK	290 PALM AVE	RIALTO	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
RIALTO-CITY	150 SOUTH PALM AVENUE	RIALTO	SAN BERNARDINO	WELL	N/A	VIEW PWS WELLS	
RIB ROOF	2745 LOCUST AVE	RIALTO	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
RICHARD ENGLE	2824 N. LOCUST	RIALTO	SAN BERNARDINO	SLIC	**OPEN**	REPORT	
RIVERSIDE SERVICE	1877 N RIVERSIDE AVE	RIALTO	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
RIALTO AMM STGE PT (J09CA057200)		RIALTO	SAN BERNARDINO	DOD	**OPEN**	REPORT	
RIALTO AMM STGE PT (J09CA057200)		RIALTO	SAN BERNARDINO	LUFT	**OPEN**	REPORT	
SCE-RIALTO GARAGE	300 N PEPPER AVE	RIALTO	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
SFPP, L.P.	2359 S RIVERSIDE AVE	RIALTO	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
SMITH FOOD & DRUG/FORMER SHELL	115 BASELINE RD	RIALTO	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
STANDON COMPANY INC	2830 S RIVERSIDE AVE	RIALTO	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
SURU'S SHELL	684 FOOTHILL BLVD	RIALTO	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
T-21 WEST SAN BERDO WATER	LINDEN AVE	RIALTO	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
TERMINAL (EQUILON ENTERPRISES)	2237 RIVERSIDE AVE	RIALTO	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
XACO SERVICE STATION	110 FOOTHILL BLVD	RIALTO	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
TEXACO SERVICE STATION	120 VALLEY BLVD	RIALTO	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP

Prev 30 Jump to page: 1 2 3 4 Next 30

BACK TO SEARCH | GEOTRACKER HOME

Site Search Results

109 records found Page 4 of 4

SITE NAME	ADDRESS	CITY	COUNTY	SITE TYPE	STATUS		
THE MARQUARDT COMPANY	NORTH ALDER AVENUE	RIALTO	SAN BERNARDINO	SLIC	**OPEN**	REPORT	
THOMAS O. PETERS	2298 W. STONEHURST DR.	RIALTO	SAN BERNARDINO	SLIC	**OPEN**	REPORT	
THRIFTY OIL #323/ ARCO #9695	111 VALLEY BLVD	RIALTO	SAN BERNARDINO	LUFT	**OPEN**	REPORT	SHOW ON MAP
THRIFTY OIL #77 / ARCO #9551	280 FOOTHILL BLVD	RIALTO	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
TOSCO COLTON TERMINAL	2301 S RIVERSIDE AVE	RIALTO	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
TOSCO SS # 30697-4638	120 W BASE LINE RD	RIALTO	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
TOSCO SS# 30419-1995	101 W FOOTHILL BLVD	RIALTO	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
TOSCO/ UNOCAL #1995	101 FOOTHILL BLVD	RIALTO	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
TOYS R US	1110 W MERRILL AVE	RIALTO	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
U S SPRINT/RIALTO SWH STA	282 S SYCAMORE AVE	RIALTO	SAN BERNARDINO	UST	N/A	REPORT	SHOW ON MAP
VAN DYK OIL COMPANY	2756 RIVERSIDE AVE	RIALTO	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
W.A. MURPHY, INC.	2824 NORTH LOCUST AVENUE	RIALTO	SAN BERNARDINO	SLIC	**OPEN**	REPORT	
WEST COAST LOADING COMPANY	160 ACRES	RIALTO	SAN BERNARDINO	SLIC	**OPEN**	REPORT	
WEST SAN BERNARDINO COUNTY WATER DISTRICT	855 BASELINE WEST	RIALTO	SAN BERNARDINO	LUFT	CLOSED	REPORT	
WEST SAN BERNARDINO CWD	P. O. BOX 920	RIALTO	SAN BERNARDINO	WELL	N/A	VIEW PWS WELLS	
WESTERN HELICOPTER, INC	1670 MIRO WAY W	RIALTO	SAN BERNARDINO	SLIC	**OPEN**	REPORT	SHOW ON MAP
WHITTAKER CORPORATION	2298 W. STONEHURST DR.	RIALTO	SAN BERNARDINO	SLIC	**OPEN**	REPORT	
YOUNG'S MARKET	260 WILLOW AVE	RIALTO	SAN BERNARDINO	LUFT	CLOSED	REPORT	SHOW ON MAP
ZAMBELLI FIREWORKS MANUFACTURING COMPANY	2170 WEST STONEHURST AVE	RIALTO	SAN BERNARDINO	SLIC	**OPEN**	REPORT	

Prev 30 Jump to page: 1 2 3 4

ORANGE SHELL - COLTON

1600 W VALLEY BLVD
COLTON, CA
92324-1807

Facility ID : 86008825
Local Agency: SAN BERNARDINO COUNTY

NO WELLS NEARBY THIS UST SITE

REGULATORY HISTORY

SHELL SERVICE STATION (COLTON)
1600 VALLEY BOULEVARD WEST
COLTON , CA 92373
CASE STATUS: CLOSED
RETURN TO REPORT MAIN MENU

LOCAL AGENCY (LEAD AGENCY) - CASE #: 2003014
SAN BERNARDINO COUNTY LOP - **(LH6)**

REGIONAL BOARD
SANTA ANA RWQCB (REGION 8) - **(CAB)**
CONTACT: CARL BERNHARDT - (951) 782-4130
CUF REIMBURSEMENT AMOUNT: $0
RB RECORD FILE #:

REGULATORY HISTORY

BEGIN DATE	STATUS
11/15/2002	* Site Assessment
3/20/2003	Case Open
3/20/2003	* Leak Reported
6/6/2003	* Site Assessment
7/31/2003	Remediation
7/27/2005	Case Closed

Geotracker Home | Site/Facility Finder | Case Finder | MTBE/Case Reports

COUNTY FIRE DEPARTMENT

COUNTY OF SAN BERNARDINO
ECONOMIC DEVELOPMENT/
PUBLIC SERVICES GROUP

OFFICE OF THE FIRE MARSHAL
HAZARDOUS MATERIALS DIVISION
620 South "E" Street • San Bernardino, CA 92415-0153
(909) 386-8401 • Fax (909) 386-8460

PETER R. HILLS
Fire Chief
County Fire Warden

REMEDIAL ACTION COMPLETION CERTIFICATION

JUL 2 7 2005

DEBORAH PRYOR
SHELL OIL PRODUCTS U.S.
20945 S. WILMINGTON AVE., #S-E
CARSON, CA 90810-1039

SITE #2003014

SUBJECT: UNDERGROUND STORAGE TANK (UST) CASE CLOSURE FOR ORANGE SHELL, 1600 W. VALLEY BLVD., COLTON, CA UNAUTHORIZED RELEASE REPORT DATED 3/20/03

This letter confirms the completion of site investigation and corrective action for the underground storage tank(s) located at the above-described location. Thank you for your cooperation throughout this investigation. Your willingness and promptness in responding to our inquiries concerning the former underground storage tank(s) are greatly appreciated.

Based on information in the above-referenced file and with the provision that the information provided to this agency was accurate and representative of site conditions, this agency finds that the site investigation and corrective action carried out at your underground storage tank(s) site is in compliance with requirements of subdivisions (a) and (b) of Section 25299.37 of the Health and Safety Code and with corrective action regulations adopted pursuant to Section 25299.77 of the Health and Safety Code and that no further action related to the petroleum release(s) at the site is required.

This notice is issued pursuant to subdivision (h) of Section 25299.37 of the Health and Safety Code. Please contact Lisa Holst of our office at (909) 386-8419 if you have any questions regarding this matter.

Sincerely,

Peter Brierty

PETER S. BRIERTY, FIRE MARSHAL
HAZARDOUS MATERIALS DIVISION

cc: Carl Bernhardt, Santa Ana Regional Water Quality Control Board
Nancy Comacho, State Water Resources Control Board
Zakaria Haggag, Orange Shell Station

CASE CLOSURE SUMMARY
Leaking Underground Storage Tank Program

FILE

I. Agency Information Date: MAR 2 9 2005

Agency Name	Address
San Bernardino County Fire Department Hazardous Materials Division	620 South "E" Street
City/State/Zip San Bernardino, CA 92415-0153	Phone (909) 386-8419
Responsible Staff Person Lisa Holst LH	Title Environmental Health Specialist II

II. Case Information

Site Facility Name
Orange Shell Station

Site Facility Address
1600 West Valley Boulevard, Colton, CA

RB LUSTIS Case No.	Local Case No.	LOP Case No.
Not available	2003014	2003014
URF Filing Date 3/20/03	SWEEPS No. NA	

Responsible Parties	Address	Phone Numbers
Shell Oil Products U.S. Attention: Deborah Pryor	20945 S. Wilmington Ave., #S-E Carson, CA 90810-1039	(323) 291-9595
Orange Shell Station Attention: Zakaria Haggag	1600 West Valley Boulvard Colton, CA 92324	(909) 824-6372

Tank No.	Size in Gallons	Contents	Closed in Place/ Removed?	Date
1		(UST's were not removed - upgrade modification only)		
2				
3				
4				

III. Release and Site Characterization Information

Cause and type of release:
Unknown

Site characterization complete? ☒Yes ☐No	Date approved by oversight agency: 1/18/05	
Monitoring wells installed? ☐Yes ☒No	Number:	Proper screened interval? ☐Yes ☐No
Highest groundwater depth below ground surface: Approximately 150 feet bgs.	Lowest depth: Approximately 200 feet bgs.	Flow direction: Expected flow is to the southwest

Most sensitive current use: Municipal supply

Are drinking water wells affected? ☐Yes ☒No	Aquifer Name: Riverside-North

CASE CLOSURE SUMMARY
Leaking Underground Storage Tank Program

III. Release and Site Characterization Information (continued)

Is surface water affected? ☐Yes ☒No	Nearest/affected surface water name:

Off-site beneficial use impacts (addresses/locations):
None

Report(s) on file? ☒Yes ☐No	Where is report filed? San Bernardino County Fire Dept Hazardous Materials Division

Treatment and Disposal of Affected Material

Material	Amount (Include Units)	Action (Treatment or Disposal w/Destination)	Date
Tank			
Piping			
Free Product			
Soil	95 tons	TPS, Adelanto	8/22/03
Ground Water			
Barrels			

Maximum Documented Contaminant Concentrations ------ Before and After Cleanup

Contaminant	Soil (ppm)		Water (ppm)		Contaminant	Soil (ppm)		Water (ppm)	
	Before	After	Before	After		Before	After	Before	After
TPH (Gas)	3.0				Xylene	0.02			
TPH (Diesel)					Ethylbenzene	ND			
Benzene	ND				Oil & Grease				
Toluene	ND				Heavy Metals				
Other (TBA)	2.9				MTBE	5.0			

Comments (Depth of Remediation, etc.):
In March 2003 a phase II environmental site assessment identified petroleum contaminated soil in the area of the UST's and dispenser islands (data shown in the "Before" column). In July 2003 the analytical results of soil samples collected from beneath the dispenser islands during UST system upgrade activity reported 110 ug/kg TBA at sample DI-d4. Impacted soil was removed from beneath the northeast dispenser island to approximately 5 feet bgs. The analytical results of one confirmation sample reported non-detectable concentrations. The installation (see section VII)

IV. Closure

Does completed corrective action protect existing beneficial uses per the Regional Board Basin Plan? ☒Yes ☐No

Does completed corrective action protect potential beneficial uses per the Regional Board Basin Plan? ☒Yes ☐No

Does corrective action protect public health for current land use? ☒Yes ☐No

CASE CLOSURE SUMMARY
Leaking Underground Storage Tank Program

Orange Shell Station, 1600 W. Valley Blvd., Colton, CA LOP Site # 2003014 SBCFD FAX (909) 386-8460

Site Management requirements: None

Should corrective action be reviewed if land use changes? ☐Yes ☒No

Monitoring wells decommissioned: ☐Yes ☐No (4 SVE wells will be abandoned prior to case closure) | Number Decommissioned: | Number retained:

List enforcement actions taken: Notice of Requirement to Reimburse

List enforcement actions rescinded: NONE

V. Local Agency Representative Data

Name: Peter S. Brierty Title: Fire Marshal

Signature: Peter S Brierty

VI. RWQCB Notification

Date Submitted to RB: RB Response: Concurs w/ Closure

RWQCB Staff Name: Ken Williams, C.E.G. Title: Senior Engineering Geologist Date: 4/1/05

Kenneth R. Williams Chief, UST Section

VII. Additional Comments, Data, etc.

of 9 soil borings and 4 SVE wells sufficiently defined the vertical and horizontal extent of contamination. Initial 8 hour SVE testing removed 0.4 lbs of MTBE and 0.5 lbs of TPH-g. Four weeks of extended SVE testing removed only 0.16 lbs of MTBE and 0.57 lbs of TPH-g. Vapor sample results at the end of the test were low to non-detect. Extended SVE testing demonstrates that minimal extractable mass is present in the vadose zone. The Department recommends case closure for the following reasons: 1) The vertical and lateral extent of contamination is sufficiently defined. 2) Groundwater was not encountered at the deepest depth drilled (136') and is expected to occur between 150 feet to 200 feet bgs. 3) A minimum of 60 feet of clean soil is present between deepest identified contamination (90' bgs) and groundwater. 4) The nearest supply wells are reported to be approximately 1500 feet northeast (upgradient) and 2000 feet south (downgradient) of the site. 5) The residual mass of petroleum hydrocarbons in the soil does not pose a threat to human health, the environment, or to groundwater resources.

This document and the related CASE CLOSURE LETTER shall be retained by the lead agency as part of the official site file.

COUNTY FIRE DEPARTMENT

COUNTY OF SAN BERNARDINO
PUBLIC AND SUPPORT
SERVICES GROUP

OFFICE OF THE FIRE MARSHAL
HAZARDOUS MATERIALS DIVISION
620 South "E" Street • San Bernardino, CA 92415-0153
(909) 386-8401 • Fax (909) 386-8460

PAT A. DENNEN
Fire Chief
County Fire Warden

REMEDIAL ACTION COMPLETION CERTIFICATION

JUL 3 0 2007

TELCO FOOD PRODUCTS **SITE #2006010**
2111 W. VALLEY BOULEVARD
COLTON, CA 92324

ATTENTION: FRANK LOWRIE

SUBJECT: UNDERGROUND STORAGE TANK (UST) CASE CLOSURE FOR TELCO FOOD PRODUCTS, 2111 W. VALLEY BLVD., COLTON UNAUTHORIZED RELEASE REPORT DATED: 11/21/06

This letter confirms the completion of site investigation and corrective action for the underground storage tank(s) formerly located at the above-described location. Thank you for your cooperation throughout this investigation. Your willingness and promptness in responding to our inquiries concerning the former underground storage tank(s) are greatly appreciated.

Based on information in the above-referenced file and with the provision that the information provided to this agency was accurate and representative of site conditions, this agency finds that the site investigation and corrective action carried out at your underground storage tank(s) site is in compliance with requirements of subdivisions (a) and (b) of Section 25296.10 of the Health and Safety Code and with corrective action regulations adopted pursuant to Section 25299.3 of the Health and Safety Code and that no further action related to the petroleum release(s) at the site is required..

This notice is issued pursuant to subdivision (h) of Section 25296.10 of the Health and Safety Code. Please contact Jackson Crutsinger of our office at (909) 386-8419 if you have any questions regarding this matter.

Sincerely,

Peter Brierty

PETER S. BRIERTY, FIRE MARSHAL
HAZARDOUS MATERIALS DIVISION

cc: Ken Williams C.E.G, Santa Ana Regional Water Quality Control Board
Nancy Camacho, State Water Resources Control Board

MARK H. UFFER
County Administrative Officer
NORMAN A. KANOLD
Assistant County Administrator
Public and Support
Services Group

Board of Supervisors
BILL POSTMUS . . . . . First District
PAUL BIANE . . . . . Second District
JOSIE GONZALES . . . . . Fifth District
DENNIS HANSBERGER . . . . . Third District
GARY C. OVITT . . . . . Fourth District

CASE CLOSURE SUMMARY
Leaking Underground Storage Tank Program

file

I. Agency Information Date: MAR 2 0 2007

Agency Name	Address
San Bernardino County Fire Department Hazardous Materials Division	385 N. Arrowhead Avenue, 2nd Floor
City/State/Zip San Bernardino, CA 92415-0153	Phone (909) 387-3041
Responsible Staff Person Jackson Crutsinger	Title Hazardous Materials Specialist III

II. Case Information

Site Facility Name
Telco Foods

Site Facility Address
2111 W. Valley Boulevard, Colton, CA 92324

RB LUSTIS Case No.	Local Case No. 2006010	LOP Case No. 2006010
URF Filing Date 11/21/06	SWEEPS No. 36-000-013847-0000001,2,3	

Responsible Parties	Address	Phone Numbers
Telco Food Products Attn: Frank Lowrie	2111 W. Valley Boulevard Colton, CA 92324	(909) 825-7343

Tank No.	Size in Gallons	Contents	Closed in Place/ Removed?	Date
1	20,000	gasoline	removed	4/30/97
2	20,000	gasoline	removed	4/30/97
3	20,000	gasoline	removed	4/30/97
4				

III. Release and Site Characterization Information

Cause and type of release:
unknown

Site characterization complete? ☒Yes ☐No	Date approved by oversight agency: 12/29/06		
Monitoring wells installed? ☐Yes ☒No	Number: NA	Proper screened interval? ☐Yes ☐No	
Highest groundwater depth below ground surface: 175 ft	Lowest depth: 200 ft	Flow direction: NA	
Most sensitive current use: domestic			
Are drinking water wells affected? ☐Yes ☒No	Aquifer Name: Colton - Rialto subarea		

CASE CLOSURE SUMMARY
Leaking Underground Storage Tank Program

III. Release and Site Characterization Information (continued)

Is surface water affected? ☐Yes ☒No	Nearest/affected surface water name: NA
Off-site beneficial use impacts (addresses/locations): none	
Report(s) on file? ☐Yes ☐No	Where is report filed? San Bernardino County Fire Dept Hazardous Materials Division

Treatment and Disposal of Affected Material

Material	Amount (Include Units)	Action (Treatment or Disposal w/Desination)	Date
Tank	3	to be recertified for re-use	4/30/97
Piping			
Free Product			
Soil			
Ground Water			
Barrels			

Maximum Documented Contaminant Concentrations ——— Before and After Cleanup

Contaminant	Soil (ppm)		Water (ppm)		Contaminant	Soil (ppm)		Water (ppm)	
	Before	After	Before	After		Before	After	Before	After
TPH (Gas)	5	12			Xylene	ND	ND		
TPH (Diesel)	-				Ethylbenzene	ND	ND		
Benzene	ND	ND			Oil & Grease				
Toluene	ND	ND			Heavy Metals	ND	ND		
Other					MTBE	1.5	ND		

Comments (Depth of Remediation, etc.):
The highest "Before" concentrations of MTBE were found at the north end of Tank 1 at 17 ft. depth. A site investigation consisted of 3 borings to a maximum depth of 72 ft. The USTs were removed in 1997, but because the sample results were not received by the County, no closure letter was ever issued. The results of the current, 2006 site investigation were all NDs except for 12 ppm TRPH at 17 ft. depth, the location where MTBE was indicated in the tank removal samples. No remediation was done at this site.

IV. Closure

Does completed corrective action protect existing beneficial uses per the Regional Board Basin Plan? ☒Yes ☐No

Does completed corrective action protect potential beneficial uses per the Regional Board Basin Plan? ☒Yes ☐No

Does corrective action protect public health for current land use? ☒Yes ☐No

CASE CLOSURE SUMMARY
Leaking Underground Storage Tank Program

Telco Food Products, 2111 W. Valley Blvd., Colton LOP# 2006010 FAX (909) 386-8460

Site Management requirements: none

Should corrective action be reviewed if land use changes? ☐Yes ☒No

Monitoring wells decommissioned: ☐Yes ☒No	Number Decommissioned: NA	Number retained: NA

List enforcement actions taken: Notice of Requirement to Reimburse

List enforcement actions rescinded: NONE

V. Local Agency Representative Data

Name: Peter S. Brierty Title: Division Chief

Signature: Peter Brierty Date: 3/15/07

VI. RWQCB Notification

Date Submitted to RB: RB Response: Concurs w/ Closure

RWQCB Staff Name: Ken Williams Title: Senior Geologist Date: 3/26/07

Signature: Kenneth R. Williams Chief, UST Section

VII. Additional Comments, Data, etc.

Justification for closure:

well defined contaminant plume,

highly localized contaminant,

very low residual concentrations,

groundwater depth of approximately 200 ft. with large ND buffer.

This document and the related CASE CLOSURE LETTER shall be retained by the lead agency as part of the official site file.

BISHOP'S CENTRAL STORES

791 N PEPPER AVE
COLTON, CA
92324-1800

Facility ID : 87013607
Local Agency: SAN BERNARDINO COUNTY

NO WELLS NEARBY THIS UST SITE

CO-ARROWHEAD REG.MED.CTR

400 N PEPPER AVE
COLTON, CA
92324-1801

Facility ID : 98046597
Local Agency: SAN BERNARDINO COUNTY

NO WELLS NEARBY THIS UST SITE

Wells Owned By W0603601135

ARROWHEAD MEDICAL CTR (SAN BDNO MED CTR) (COLTON)
400 N. PEPPER AVE
COLTON , CA 92324

State Well No.	Well Common Name		
3601135-001	MAIN WELL	Show on Map	Report
PWS MAIN FAC	3601135	Show on Map	Report

Geotracker Home | Site/Facility Finder | Case Finder | MTBE/Case Reports

Well Report

ARROWHEAD MEDICAL CTR (SAN BDNO MED CTR) (COLTON)
MAIN WELL
State Well Number: 3601135-001

Well Details | Geographic Information | DHS Water Quality Data | PWS Detailed Information

Local Name
MAIN WELL (3601135-001)

Source Origin
G

Status
AU

Treatment Method
Unknown

Treatment Phase
Unknown

1 LUFT Site(s) Estimated to be Nearby this Well

- **List These LUFT Sites**

Geotracker Home | Site/Facility Finder | Case Finder | MTBE/Case Reports

Public Water System Information

ARROWHEAD MEDICAL CTR (SAN BDNO MED CTR) (COLTON)
MAIN WELL
State Well Number: 3601135-001

Well Details | Geographic Information | DHS Water Quality Data | PWS Detailed Information

Public Water System
ARROWHEAD MEDICAL CTR (SAN BDNO MED CTR)

Water System Address:
400 N. PEPPER AVE
COLTON, CA 92324

PWS Class:

Ownership/Regulation

Ownership:

Regulating Entity:

Service Area:

Date Entered System:

System Status:

Deactivation Date:

Last Revised:

Connection Information

Number of Service Connections:
1

Population Served:
500

- List all wells for this Public Water System

Geotracker Home | Site/Facility Finder | Case Finder | MTBE/Case Reports

Luft Sites Estimated to be Nearby

ARROWHEAD MEDICAL CTR (SAN BDNO MED CTR) (COLTON)
MAIN WELL
State Well Number: 3601135-001

Well Details | Geographic Information | DHS Water Quality Data | PWS Detailed Information

Facility Name	Feet
RANCHO READY MIX	n/a

Geotracker Home | Site/Facility Finder | Case Finder | MTBE/Case Reports

REPORT

RANCHO READY MIX (COLTON)
1150 RANCHO AVE
COLTON , CA 92324
CASE STATUS: CLOSED
SHOW THIS SITE ON MAP
RETURN TO REPORT MAIN MENU

LOCAL AGENCY (LEAD AGENCY) - CASE #: 99128
SAN BERNARDINO COUNTY LOP - **(CR2)**

REGIONAL BOARD - CASE #: 083603585T
SANTA ANA RWQCB (REGION 8) - **(VJB)**
CONTACT: VALERIE JAHN-BULL - (951) 782-4130
CUF REIMBURSEMENT AMOUNT: $25,044
RB RECORD FILE #:

CHOOSE A REPORT TO VIEW

SITE INFO:

- REGULATORY HISTORY
- LOCATIONAL INFORMATION
- ANALYTICAL DATA
- ELECTRONIC ANALYTICAL DATA
- DEPTH TO WATER INFORMATION
- RISK MANAGEMENT
- LAND USE CONTROLS

LEAK INFO:

- DETAILED RELEASE INFORMATION
- REMEDIATION ON SITE

ADDITIONAL INFO:

- 0 FIELD POINTS FOR THIS SITE
- 2 PUBLIC WATER WELL(S) ESTIMATED TO BE NEARBY THIS SITE

ELECTRONIC SUBMITTALS:

- ANALYTICAL DATA (NONE AVAILABLE)
- LOCATION DATA (NONE AVAILABLE)
- ELEVATION DATA (NONE AVAILABLE)
- DEPTH TO WATER DATA (NONE AVAILABLE)
- GEO MAP DATA (NONE AVAILABLE)
- GEO REPORT / SITE DOCUMENTS (NONE AVAILABLE)
- GEO BORE DATA (NONE AVAILABLE)

CUF REIMBURSEMENT AMOUNT:
$25,044

Geotracker Home | Site/Facility Finder | Case Finder | MTBE/Case Reports

GeoTracker

Help

ZoomIn 2X ZoomOut 2X Pan Identify LUFT Sites

Layers

Show All sites within Any of public wells.

Click on the map to perform the selected action.

- LUFT Sites
- Permitted UST Sites
- SLIC Sites
- Landfill Sites
- DoD Sites
- Public Wells
- Highways
- Major Roads
- Minor Roads
- USGS Quads
- Surface Water
- Vulnerability
- GAMA Sites
- Watersheds
- GW Basins



Map Size: 1X

Redraw

Street:

City: Zip: Go

GeoTracker Home | Contact GeoTracker Help Desk | Road Maps by GDT

Well and LUFT site positions are approximate. Locational accuracy will improve as state agencies and responsible parties obtain and report new information.

REGULATORY HISTORY

SOUTHERN PACIFIC RAILYARD (BLOOMINGTON)
200 MARION WAY
BLOOMINGTON , CA 92316
CASE STATUS: CLOSED
SHOW THIS SITE ON MAP
RETURN TO REPORT MAIN MENU

LOCAL AGENCY (LEAD AGENCY) - CASE #: 87003
SAN BERNARDINO COUNTY LOP - **(CR2)**

REGIONAL BOARD - CASE #: 083600986T
SANTA ANA RWQCB (REGION 8) - **(PAH)**
CONTACT: PATRICIA HANNON - (951) 782-4130
CUF REIMBURSEMENT AMOUNT: $0
RB RECORD FILE #:

REGULATORY HISTORY

BEGIN DATE	STATUS
3/22/1988	* Leak Stopped
7/20/1988	* Leak Discovery
7/21/1988	* Leak Reported
8/24/1988	* Site Assessment
8/24/1988	* System Entry
3/28/1991	Case Closed

Geotracker Home | Site/Facility Finder | Case Finder | MTBE/Case Reports

Risk Management

SOUTHERN PACIFIC RAILYARD (BLOOMINGTON)
200 MARION WAY
BLOOMINGTON , CA 92316
CASE STATUS: CLOSED
SHOW THIS SITE ON MAP
RETURN TO REPORT MAIN MENU

LOCAL AGENCY (LEAD AGENCY) - CASE #: 87003
SAN BERNARDINO COUNTY LOP - **(CR2)**
REGIONAL BOARD - CASE #: 083600986T
SANTA ANA RWQCB (REGION 8) - **(PAH)**
CONTACT: PATRICIA HANNON - (951) 782-4130
CUF REIMBURSEMENT AMOUNT: $0
RB RECORD FILE #:

CASE TYPE
SOIL IMPACTED

BENEFICIAL USE

BASIN (CALCULATED)
UPPER SANTA ANA VALLEY (8-2)

VULNERABILITY BASIS

MTBE THREAT CLASSIFICATION

MTBE THREAT DESCRIPTION

MTBE CLEANUP CLASSIFICATION

MTBE CLEANUP DESCRIPTION

 # DRINKING WELLS IMPACTED

IMPACTED DRINKING SOURCE DESCRIPTION

NEAREST SURFACE WATER BODY (CALCULATED)
NOT YET CALCULATED

DISTANCE TO SURFACE WATER (CALCULATED)
NOT YET CALCULATED

ECOLOGICAL RISK DESCRIPTION

RB RECORD FILE #

PLUME/CONTAMINANT DESCRIPTION

SOIL DESCRIPTION

PRIORITY

CASE DESCRIPTION

Geotracker Home | Site/Facility Finder | Case Finder | MTBE/Case Reports

Detailed Release Information

SOUTHERN PACIFIC RAILYARD (BLOOMINGTON)
200 MARION WAY
BLOOMINGTON , CA 92316
CASE STATUS: CLOSED
SHOW THIS SITE ON MAP
RETURN TO REPORT MAIN MENU

LOCAL AGENCY (LEAD AGENCY) - CASE #: 87003
SAN BERNARDINO COUNTY LOP - **(CR2)**
REGIONAL BOARD - CASE #: 083600986T
SANTA ANA RWQCB (REGION 8) - **(PAH)**
CONTACT: PATRICIA HANNON - (951) 782-4130
CUF REIMBURSEMENT AMOUNT: $0
RB RECORD FILE #:

CASE TYPE:
Soil impacted

ENFORCEMENT TYPE:

FUNDING:

HOW LEAK WAS DISCOVERED:
Tank Closure

METHOD USED TO STOP DISCHARGE:

INTERIM:

CAUSE OF LEAK:
Unknown

SOURCE OF LEAK:
Unknown

SUBSTANCES RELEASED:

Discharge Begin Date	Substance	Quantity
UNKNOWN	Diesel fuel oil and additives	

Geotracker Home | Site/Facility Finder | Case Finder | MTBE/Case Reports

Remediation On Site

SOUTHERN PACIFIC RAILYARD (BLOOMINGTON)
200 MARION WAY
BLOOMINGTON , CA 92316
CASE STATUS: CLOSED
SHOW THIS SITE ON MAP
RETURN TO REPORT MAIN MENU

LOCAL AGENCY (LEAD AGENCY) - CASE #: 87003
SAN BERNARDINO COUNTY LOP - **(CR2)**
REGIONAL BOARD - CASE #: 083600986T
SANTA ANA RWQCB (REGION 8) - **(PAH)**
CONTACT: PATRICIA HANNON - (951) 782-4130
CUF REIMBURSEMENT AMOUNT: $0
RB RECORD FILE #:

Start Date	Method	Phase
No Records Found!		

Geotracker Home | Site/Facility Finder | Case Finder | MTBE/Case Reports

GeoTracker Help

ZoomIn 2X ZoomOut 2X Pan Identify LUFT Sites

Layers

Show All sites within Any of public wells.

- [x] LUFT Sites
- [ ] Permitted UST Sites
- [x] SLIC Sites
- [ ] Landfill Sites
- [ ] DoD Sites
- [ ] Public Wells
- [x] Highways
- [x] Major Roads
- [x] Minor Roads
- [ ] USGS Quads
- [ ] Surface Water
- [ ] Vulnerability
- [ ] GAMA Sites
- [ ] Watersheds
- [ ] GW Basins

Identify Results: T0607100325-CHEVRON #9-6969



Map Size: 1X

Redraw

Street:

City: Zip: Go

GeoTracker Home | Contact GeoTracker Help Desk | Road Maps by GDT

Well and LUFT site positions are approximate. Locational accuracy will improve as state agencies and responsible parties obtain and report new information.

REGULATORY HISTORY

CHEVRON #9-6969 (RIALTO)
101 VALLEY BLVD
RIALTO , CA 92376
CASE STATUS: CLOSED
SHOW THIS SITE ON MAP
RETURN TO REPORT MAIN MENU

LOCAL AGENCY (LEAD AGENCY) - CASE #: 92045
SAN BERNARDINO COUNTY LOP - **(CB5)**

REGIONAL BOARD - CASE #: 083602453T
SANTA ANA RWQCB (REGION 8) - **(TME)**
CONTACT: TOM E. MBEKE-EKANEM - (951) 782-4130
CUF REIMBURSEMENT AMOUNT: $0
RB RECORD FILE #:

REGULATORY HISTORY

BEGIN DATE	STATUS
9/21/1992	* Leak Reported
9/16/1993	Case Open
9/16/1993	* Leak Discovery
9/16/1993	* Leak Stopped
10/5/1993	* Site Assessment
6/16/1994	* System Entry
4/28/2000	Case Closed

Geotracker Home | Site/Facility Finder | Case Finder | MTBE/Case Reports

GeoTracker Help

ZoomIn 2X ZoomOut 2X Pan Identify LUFT Sites

Layers

Show All sites within Any of public wells.

Identify Results: T0607100101-RIALTO, CITY OF (TEXACO)

- [x] LUFT Sites
- [ ] Permitted UST Sites
- [ ] SLIC Sites
- [ ] Landfill Sites
- [ ] DoD Sites
- [ ] Public Wells
- [x] Highways
- [x] Major Roads
- [x] Minor Roads
- [ ] USGS Quads
- [ ] Surface Water
- [ ] Vulnerability
- [ ] GAMA Sites
- [ ] Watersheds
- [ ] GW Basins



Map Size: 1X

Redraw

Street:

City: Zip: Go

GeoTracker Home | Contact GeoTracker Help Desk | Road Maps by GDT

Well and LUFT site positions are approximate. Locational accuracy will improve as state agencies and responsible parties obtain and report new information.

Remediation On Site

RIALTO, CITY OF (TEXACO) (RIALTO)
102 VALLEY BLVD
RIALTO , CA 92376
CASE STATUS: CLOSED
SHOW THIS SITE ON MAP
RETURN TO REPORT MAIN MENU

LOCAL AGENCY (LEAD AGENCY) - CASE #: 91033
SAN BERNARDINO COUNTY LOP - **(DG4)**
REGIONAL BOARD - CASE #: 083600955T
SANTA ANA RWQCB (REGION 8) - **(VJB)**
CONTACT: VALERIE JAHN-BULL - (951) 782-4130
CUF REIMBURSEMENT AMOUNT: $0
RB RECORD FILE #:

Start Date	Method	Phase
No Records Found!		

Geotracker Home | Site/Facility Finder | Case Finder | MTBE/Case Reports

Detailed Release Information

RIALTO, CITY OF
(TEXACO) (RIALTO)
102 VALLEY BLVD
RIALTO , CA 92376
CASE STATUS: CLOSED
SHOW THIS SITE ON MAP
RETURN TO REPORT MAIN MENU

LOCAL AGENCY (LEAD AGENCY) - CASE #: 91033
SAN BERNARDINO COUNTY LOP - **(DG4)**

REGIONAL BOARD - CASE #: 083600955T
SANTA ANA RWQCB (REGION 8) - **(VJB)**
CONTACT: VALERIE JAHN-BULL - (951) 782-4130
CUF REIMBURSEMENT AMOUNT: $0
RB RECORD FILE #:

CASE TYPE:
Soil impacted

ENFORCEMENT TYPE:

FUNDING:

HOW LEAK WAS DISCOVERED:
Tank Closure

METHOD USED TO STOP DISCHARGE:

INTERIM:

CAUSE OF LEAK:
Unknown

SOURCE OF LEAK:
Unknown

SUBSTANCES RELEASED:

Discharge Begin Date	Substance	Quantity
UNKNOWN	Regular gasoline	

Geotracker Home | Site/Facility Finder | Case Finder | MTBE/Case Reports

REGULATORY HISTORY

RIALTO, CITY OF
(TEXACO) (RIALTO)
102 VALLEY BLVD
RIALTO , CA 92376
CASE STATUS: CLOSED
SHOW THIS SITE ON MAP
RETURN TO REPORT MAIN MENU

LOCAL AGENCY (LEAD AGENCY) - CASE #: 91033
SAN BERNARDINO COUNTY LOP - **(DG4)**

REGIONAL BOARD - CASE #: 083600955T
SANTA ANA RWQCB (REGION 8) - **(VJB)**
CONTACT: VALERIE JAHN-BULL - (951) 782-4130
CUF REIMBURSEMENT AMOUNT: $0
RB RECORD FILE #:

REGULATORY HISTORY

BEGIN DATE	STATUS
4/29/1991	Case Open
4/29/1991	* Leak Discovery
4/29/1991	* Leak Stopped
5/23/1991	* Leak Reported
1/28/1992	* Site Assessment
2/11/1992	* System Entry
2/18/1992	* Regulatory Review
8/25/1992	Case Closed

Geotracker Home | Site/Facility Finder | Case Finder | MTBE/Case Reports

Remediation On Site

THRIFTY OIL #323/ ARCO #9695 (RIALTO)
111 VALLEY BLVD
RIALTO , CA 92376
CASE STATUS: OPEN
SHOW THIS SITE ON MAP
RETURN TO REPORT MAIN MENU

LOCAL AGENCY (LEAD AGENCY) - CASE #: 98096
SAN BERNARDINO COUNTY LOP - **(LH6)**
REGIONAL BOARD - CASE #: 083603296T
SANTA ANA RWQCB (REGION 8) - **(VJB)**
CONTACT: VALERIE JAHN-BULL - (951) 782-4130
CUF REIMBURSEMENT AMOUNT: $398,509
RB RECORD FILE #:

Start Date	Method	Phase
No Records Found!		

Geotracker Home | Site/Facility Finder | Case Finder | MTBE/Case Reports

REGULATORY HISTORY

THRIFTY OIL #323/ ARCO #9695 (RIALTO)
111 VALLEY BLVD
RIALTO , CA 92376
CASE STATUS: OPEN
SHOW THIS SITE ON MAP
RETURN TO REPORT MAIN MENU

LOCAL AGENCY (LEAD AGENCY) - CASE #: 98096
SAN BERNARDINO COUNTY LOP - **(LH6)**

REGIONAL BOARD - CASE #: 083603296T
SANTA ANA RWQCB (REGION 8) - **(VJB)**
CONTACT: VALERIE JAHN-BULL - (951) 782-4130
CUF REIMBURSEMENT AMOUNT: $398,509
RB RECORD FILE #:

REGULATORY HISTORY

BEGIN DATE	STATUS
UNKNOWN	* Site Assessment
2/18/1998	* Leak Discovery
11/6/1998	* System Entry
11/6/1998	* Regulatory Review
11/30/1998	* Leak Reported

Geotracker Home | Site/Facility Finder | Case Finder | MTBE/Case Reports

Detailed Release Information

THRIFTY OIL #323/ ARCO #9695 (RIALTO)
111 VALLEY BLVD
RIALTO , CA 92376
CASE STATUS: OPEN
SHOW THIS SITE ON MAP
RETURN TO REPORT MAIN MENU

LOCAL AGENCY (LEAD AGENCY) - CASE #: 98096
SAN BERNARDINO COUNTY LOP - **(LH6)**
REGIONAL BOARD - CASE #: 083603296T
SANTA ANA RWQCB (REGION 8) - **(VJB)**
CONTACT: VALERIE JAHN-BULL - (951) 782-4130
CUF REIMBURSEMENT AMOUNT: $398,509
RB RECORD FILE #:

CASE TYPE:
Soil impacted

ENFORCEMENT TYPE:

FUNDING:

HOW LEAK WAS DISCOVERED:

METHOD USED TO STOP DISCHARGE:

INTERIM:

CAUSE OF LEAK:

SOURCE OF LEAK:

SUBSTANCES RELEASED:

Discharge Begin Date	Substance	Quantity
UNKNOWN	METHYL-TERT-BUTYL-ETHER (MTBE), Gasoline - Automotive	

Geotracker Home | Site/Facility Finder | Case Finder | MTBE/Case Reports

REGULATORY HISTORY

TEXACO SERVICE STATION (RIALTO)
120 VALLEY BLVD
RIALTO , CA 92376
CASE STATUS: CLOSED
SHOW THIS SITE ON MAP
RETURN TO REPORT MAIN MENU

LOCAL AGENCY (LEAD AGENCY) - CASE #: 96045
SAN BERNARDINO COUNTY LOP - **(BM7)**

REGIONAL BOARD - CASE #: 083602887T
SANTA ANA RWQCB (REGION 8) - **(RS)**
CONTACT: ROSE SCOTT - (951) 782-4130
CUF REIMBURSEMENT AMOUNT: $0
RB RECORD FILE #:

REGULATORY HISTORY

BEGIN DATE	STATUS
12/11/1990	Case Open
12/11/1990	* Leak Discovery
9/4/1996	* Leak Reported
9/10/1996	* Site Assessment
9/19/1996	* System Entry
3/5/1997	Case Closed

Geotracker Home | Site/Facility Finder | Case Finder | MTBE/Case Reports

REGULATORY HISTORY

CALNEV (RIALTO)
SLOVER AVE
RIALTO , CA
CASE STATUS: OPEN
RETURN TO REPORT MAIN MENU

REGIONAL BOARD (LEAD AGENCY)
SANTA ANA RWQCB (REGION 8) - **(RS)**
CONTACT: ROSE SCOTT - (951) 782-4130

LOCAL AGENCY
SAN BERNARDINO COUNTY LOP - **(CB5)**
RB RECORD FILE #:

REGULATORY HISTORY

BEGIN DATE	STATUS
1/1/2001	Case Open
1/1/2001	RP

Geotracker Home | Site/Facility Finder | Case Finder | MTBE/Case Reports

Third Quarter 2007 Groundwater Monitoring Report Calnev Colton Terminal

2051 East Slover Avenue Bloomington, California

Prepared for

Kinder Morgan Energy Partners, L.P.

1100 Town & Country Road
Orange, California 92868

October 19, 2007



CH2MHILL

3 Hutton Center Drive, Suite 200
Santa Ana, California 92707

Contents

Section			Page
1.0	**Introduction**		**1-1**
	1.1	Objectives	1-1
	1.2	Groundwater Monitoring Activities	1-1
2.0	**Background**		**2-1**
	2.1	Physical Setting	2-1
	2.2	Climate	2-1
	2.3	Local Hydrogeology	2-1
	2.4	Monitoring Well Network	2-2
3.0	**Groundwater Monitoring Results**		**3-1**
	3.1	Groundwater Flow Conditions	3-1
		3.1.1 Perching Silt Unit	3-1
		3.1.2 Regional Water Table Aquifer	3-1
	3.2	Groundwater Quality	3-1
		3.2.1 Distribution of LNAPL	3-2
		3.2.2 Analytical Results	3-2
		3.2.3 Field and Laboratory Quality Assurance/Quality Control (QA/QC) Results	3-3
4.0	**Summary of Ongoing Activities**		**4-1**
5.0	**Planned Activities**		**5-1**
6.0	**References**		**6-1**

Appendixes

A TRC Field Data Sheets
B Laboratory Analytical Reports (CD ROM)

Tables

2-1 Total Precipitation
2-2 Well Construction Summary
3-1 Water Levels and Apparent LNAPL Thickness
3-2 Summary of Analytical Results

Figures

1-1 Site Vicinity Map
3-1 Groundwater Elevations Perching Silt Unit, Third Quarter 2007
3-2 Groundwater Elevations Regional Water Table Aquifer, Third Quarter 2007
3-3 LNAPL Distribution Perching Silt Unit, Third Quarter 2007
3-4 Benzene Distribution Perching Silt Unit, Third Quarter 2007
3-5 MTBE Distribution Perching Silt Unit, Third Quarter 2007
3-6 TBA Distribution Perching Silt Unit, Third Quarter 2007
3-7 Benzene Distribution Regional Water Table Aquifer, Third Quarter 2007
3-8 MTBE Distribution Regional Water Table Aquifer, Third Quarter 2007
3-9 TBA Distribution Regional Water Table Aquifer, Third Quarter 2007

1.0 Introduction

This report presents the results of groundwater monitoring and sampling activities conducted during the Third Quarter 2007 for the Calnev Pipeline Company, L.L.C. (Calnev) Colton Terminal (the Terminal). Calnev is an operating partner of Kinder Morgan Energy Partners, L.P. (KMEP). The Terminal is located at 2051 East Slover Avenue in Bloomington, California (Figure 1-1). This quarterly monitoring report was prepared in response to a directive issued by the California Regional Water Quality Control Board (RWQCB), Santa Ana Region.

The Terminal is operated by Calnev, an operating partner of KMEP, and serves as a terminal for the storage and distribution of gasoline, diesel, and jet fuel. The Terminal includes fuel storage tanks, several small buildings, and numerous buried and aboveground pipelines and other utilities. The Terminal is bounded on the south by Slover Avenue, on the west by Sycamore Avenue, and on the north and east by undeveloped property. The Colton Fuel Terminal is located southwest of the Calnev facility.

1.1 Objectives

The objectives of the groundwater monitoring program are to characterize the groundwater flow conditions and the lateral and vertical extent of light nonaqueous phase liquid (LNAPL) and dissolved-phase hydrocarbons in groundwater at the Terminal.

1.2 Groundwater Monitoring Activities

Groundwater monitoring at the Terminal includes quarterly sampling, gauging of groundwater levels, and measurement of LNAPL accumulations in onsite and offsite monitoring wells. TRC, Inc. performed groundwater monitoring activities on behalf of KMEP.

Groundwater samples collected from the monitoring wells were submitted to Alpha Analytical, Inc., of Sparks, Nevada, for the following analyses:

- Total petroleum hydrocarbons quantified as gasoline (TPH-g) and total petroleum hydrocarbons quantified as diesel (TPH-d) using U.S. Environmental Protection Agency (EPA) Method 8015 modified.
- Ethanol and methanol using EPA Method 8015 modified.
- Volatile organic compounds (VOCs) including methyl tertiary butyl ether (MTBE) and other fuel oxygenates using EPA Method 8260B-Full-Scan.

2.0 Background

This section presents background information for the Terminal, including descriptions of the physical setting, climate, local hydrogeology, and monitoring well network.

2.1 Physical Setting

The Terminal is located within the Riverside Basin in the eastern portion of the Upper Santa Ana River Valley (Figure 1-1). Approximate elevations in the area range from 1,037 to 1,045 feet above mean sea level (msl), with the topography sloping to the southeast. The Santa Ana River is located approximately 1 mile southeast of the Terminal. The partially lined Rialto Flood Control Channel traverses the Colton Fuel Terminal southwest of the Calnev Terminal.

2.2 Climate

The total annual precipitation in the vicinity of the Terminal averaged approximately 16.30 inches for the period of record between 1905 and 2005 based on data from the precipitation stations located closest to the Terminal (i.e., the San Bernardino Medical and San Bernardino County Yard [SCY] stations). The monthly precipitation since 2000 is summarized in Table 2-1. As these data show, the extreme precipitation events occurred during the winter of 2004/2005, and the total annual precipitation during 2005 (34.99 inches) was more than twice the long-term average (16.30 inches). In addition, 15.98 inches of rain was recorded during February 2006 at the SCY station (Table 2-1).

The above-average groundwater recharge associated with these anomalously high precipitation events appears to have caused groundwater levels to rise in the vicinity of the Terminal during the First and Second Quarters of 2006, reversing a trend of decreasing water levels prior to 2005. Recent conditions are substantially dryer. Only 2.66 inches of precipitation was recorded between July 2006 and September 2007; consequently, groundwater levels have started to decrease at the Terminal (refer to Section 3.1, Groundwater Flow Conditions).

2.3 Local Hydrogeology

The sediments beneath the Terminal consist predominantly of fluvial deposits of fine- to coarse-grained unconsolidated sand and gravel with interbedded, discontinuous silt and clay layers that separate permeable aquifer materials. These permeable units create zones of perched water and localized confined groundwater conditions.

Four hydrostratigraphic units have been defined beneath the site. These units are listed below in reverse stratigraphic order:

- Perched groundwater zone referred to as the "perching silt unit"
- Regional water table aquifer
- Intermediate horizon
- Principal production aquifer

Groundwater production in the area is from the principal production aquifer, which is separated from the perching silt unit and the regional water table aquifer by the low-permeability intermediate horizon.

2.4 Monitoring Well Network

The monitoring well network for the terminal consists of 27 wells. Six of the wells are equipped for LNAPL recovery. The remaining wells are gauged and sampled on a quarterly basis. Table 2-2 summarizes the construction details of the Terminal wells.

3.0 Groundwater Monitoring Results

This section presents the results of the groundwater monitoring activities performed during the Third Quarter 2007.

3.1 Groundwater Flow Conditions

Groundwater flow conditions in the perching silt unit and regional water table aquifer are discussed below. The groundwater level information for the Terminal is summarized in Table 3-1. Groundwater elevation contour maps for the perching silt unit and the regional water table aquifer are presented in Figures 3-1 and 3-2, respectively. Hydrographs for select monitoring wells are included on these figures. TRC field data sheets for water level gauging are provided in Appendix A.

3.1.1 Perching Silt Unit

Groundwater flow conditions in the perching silt unit are generally consistent with those observed during the Second Quarter 2007. Groundwater elevations in the perching silt unit ranged from 939.36 feet msl in EB-2 (located within the central portion of the Terminal) to 896.86 feet msl in well EMW-10 (located southwest of the Terminal). The groundwater flow gradient varies slightly in magnitude. Groundwater flow in the northeastern portion of the site has a gradient of 0.0035 foot per foot (ft/ft); groundwater flow in the southwestern portion of the site has a gradient of 0.0085 ft/ft. The groundwater elevations in the perching silt unit wells have increased by an average of 0.29 foot since last quarter (Figure 3-1; Table 3-1).

3.1.2 Regional Water Table Aquifer

The groundwater flow conditions in the regional water table aquifer are generally consistent with those observed during the Second Quarter 2007. Groundwater elevations in the regional water table aquifer ranged from 850.61 feet msl in well EMW-8 (located in the southeast corner of the Terminal) to 847.45 feet msl in EMW-16 (located southwest of the Terminal). The groundwater flow direction is to the southwest with an average hydraulic gradient of 0.0033 ft/ft. Groundwater elevations in the regional water table aquifer wells increased by an average of 0.63 foot since last quarter (Figure 3-2; Table 3-1).

3.2 Groundwater Quality

The distribution of LNAPL and the dissolved-phase concentrations of benzene, MTBE, and tertiary butyl alcohol (TBA) are discussed below. TRC groundwater sampling data sheets are included in Appendix A.

3.2.1 Distribution of LNAPL

The distribution of LNAPL observed during the Third Quarter 2007 in the perching silt unit wells is shown in Figure 3-3. LNAPL was measured in eight wells (EB-1, EB-2, EMW-5, EMW-7, EMW-13, EMW-14, EMW-15, and MW-1). LNAPL thicknesses ranged from 0.09 foot in MW-1 to 1.51 feet in newly installed EMW-7. Only a trace of LNAPL was observed in EB-2.

Compared to the Second Quarter 2007, the measured LNAPL thickness during the Third Quarter 2007 decreased in five wells (EMW-5, EMW-13, EMW-14, EMW-15, and MW-1) and increased in three wells (EB-1, EB-2, and EMW-7).

Depth to LNAPL measurements were not collected in wells EMW-1, EMW-2, EB-3, and EB-4 because these wells are equipped with product-recovery pumps and do not have sufficient annular space for an interface probe. LNAPL does, however, accumulate in these wells.

3.2.2 Analytical Results

Current and historical analytical results are summarized in Table 3-2. The laboratory analytical reports for the Third Quarter 2007 are included in Appendix B (on CD ROM).

3.2.2.1 Perching Silt Unit

Figures 3-4, 3-5, and 3-6 show the distribution of benzene, MTBE, and TBA, respectively, in the perching silt unit. In general, the distributions of these constituents are consistent with the results from previous quarterly monitoring events.

Benzene was detected in three monitoring wells this quarter: EMW-4, EMW-6, and EWM-10 (Figure 3-4). The maximum benzene concentration during the Third Quarter 2007 was reported in EMW-10 (2,700 micrograms per liter [µg/L]). Compared to the Second Quarter 2007, benzene concentrations for the Third Quarter 2007 have increased in one well (EMW-4) and decreased in three wells (EMW-6, EMW-10, and LF-2). One well had the highest reported benzene concentration to date: EMW-4 at 1,300 µg/L. Benzene concentrations were not reported in four wells (LF-1, LF-2, LF-3, and EMW-3) this quarter.

MTBE was detected in four monitoring wells this quarter: EMW-4, EMW-10, LF-2, and LF-3 (Figure 3-5). The maximum MTBE concentration during the Third Quarter 2007 was reported in EMW-10 (32,000 µg/L). Compared to the Second Quarter 2007, MTBE concentrations for the Third Quarter 2007 have increased in two wells (LF-3 and EMW-4) and decreased in two wells (EMW-10 and LF-2). One well had the highest MTBE concentration reported to date (EMW-4 at 8,500 µg/L); one well had the second lowest concentration reported to date (LF-2 at 4.6 µg/L). MTBE concentrations were not reported in three wells (LF-1, EMW-3, and EMW-6) this quarter.

TBA was reported only in EMW-6 at 12 µg/L this quarter (Figure 3-6). This is the first time TBA has been reported in EMW-6 since December 2005 (16 µg/L).

3.2.2.2 Regional Water Table Aquifer

Figures 3-7, 3-8, and 3-9 show the distributions of benzene, MTBE, and TBA, respectively, in the regional water table aquifer. In general, the distributions of these constituents are similar to those of previous quarterly monitoring events.

Benzene was detected only in one monitoring well this quarter: MW-3R (Figure 3-7). Benzene concentrations were reported at 1,100 µg/L. Compared to the Second Quarter 2007, benzene concentrations for the Third Quarter 2007 have decreased in four wells (EMW-8, EMW-9, MW-3R, and MW-8); benzene was not detected above reporting limits in these wells.

MTBE was detected in only two wells this quarter: MW-3R at a concentration of 120 µg/L and EMW-11 at a concentration of 0.55 µg/L (Figure 3-8). MTBE was not detected above reporting limits in four wells (EMW-8, EMW-9, EMW-16, and MW-8) this quarter.

TBA was not detected above the reporting limits in any of the regional water table aquifer wells sampled this quarter (Figure 3-9; Table 3-2).

3.2.3 Field and Laboratory Quality Assurance/Quality Control (QA/QC) Results

Data precision for the Third Quarter 2007 sampling event was evaluated by analyzing two field duplicate samples, two equipment blanks, and two trip blanks. The duplicate samples were collected from wells EMW-8 and MW-3R and analyzed for all target analytes. The relative percent difference (RPD) of the primary and duplicate samples from EMW-8 and MW-3R was acceptable. The trip blanks were analyzed for VOCs, and the equipment blanks were analyzed for all target analytes. The sample results for the blank samples were below the laboratory reporting limits for the target compounds. The data precision, based on the duplicate, trip blank, and field blank, is acceptable.

Data accuracy was evaluated by examining the method blanks, matrix spike/matrix spike duplicate (MS/MSD) percent recoveries and RPDs, laboratory control sample (LCS) percent recoveries, and surrogate percent recoveries. Method blanks were analyzed at the appropriate frequency and were within laboratory detection limits. The surrogate recovery was within acceptance limits for the LCS and MS/MSD. MS/MSD and LCS percent recoveries were analyzed at the appropriate frequency, correctly reported, and within QC limits. Surrogate percent recoveries for benzene, toluene, ethylbenzene, and xylenes (BTEX); MTBE; and VOCs were within laboratory-established control limits. The overall accuracy of the MS/MSD percent recoveries, RPD values, LCS percent recoveries, and surrogate recoveries was acceptable. Some reporting limits were increased due to sample foaming and high concentration of target analytes.

4.0 Summary of Ongoing Activities

KMEP operates an LNAPL recovery system that recovers LNAPL from four wells screened in the perching silt unit (EB-3, EB-4, EMW-1, and EMW-2) using automated skimmer pumps. The system has been active since March 2002. The recovered LNAPL is temporarily stored onsite and later transported to an offsite recycling facility. In the First Quarter 2004, KMEP began recovering LNAPL from wells that have LNAPL accumulation and are not equipped with skimmer pumps. LNAPL is recovered from EMW-14, MW-1, and EMW-5 by manual bailing, and from EMW-13 and EB-1 using a portable, solar-powered free-product recovery collection system. The portable free-product recovery systems in EWM-13 and EB-1 were temporarily removed in February 2007 to accommodate construction in this area. The portable recovery systems will be reinstalled in November 2007. Through September 31, 2007, a total of approximately 22,993 gallons of LNAPL have been recovered from the perching silt unit by automatic and manual methods.

On November 20, 2006, CH2M HILL submitted the *Site Characterization Work Plan* (CH2M HILL, 2006b), which describes the proposed data collection effort to support feasibility studies and remedial design activities. The proposed scope of work includes exploratory drilling in the perching silt unit, the installation of groundwater monitoring wells in the regional water table aquifer, and LNAPL baildown testing and aquifer testing in the perching silt unit. Fieldwork commenced in late January 2007 and was completed in March 2007. KMEP intends to submit a Site Characterization Report to present the findings of this investigation in October 2007.

5.0 Planned Activities

KMEP proposed additional site assessment activities and an evaluation of the existing LNAPL recovery system in the *Additional Site Assessment and Remediation Evaluation Work Plan*, which was prepared by CH2M HILL and submitted to the RWQCB in October 2004 (CH2M HILL, 2004). The proposed work included installation of two new onsite perching silt unit wells, EMW-13 and EMW-14; installation of three additional offsite monitoring wells; and an assessment of LNAPL recovery rates in all wells containing LNAPL.

In May 2005, CH2M HILL submitted the *Remediation Well Installation and Evaluation Report* (CH2M HILL, 2005b), which documents the installation of EMW-13 and EMW-14 and the results of the LNAPL recovery assessment. As described in this report, the proposed offsite monitoring wells will be installed after the U.S. Fish and Wildlife Service grants access to these locations. KMEP is evaluating the logistics of installing automatic LNAPL recovery pumps in EMW-13 and EMW-14. A mobile, solar-powered LNAPL recovery system is presently operating at well EMW-13.

6.0 References

CH2M HILL. 2004. *Additional Site Assessment and Remediation Evaluation Work Plan.* October 20.

_____. 2005a. *Monitoring Well Destruction and Replacement Work Plan, Calnev Colton Fuels Terminal, Bloomington, California.* December 2.

_____. 2005b. *Remediation Well Installation and Evaluation Report, Kinder Morgan Energy Partners, L.P. Calnev Terminal, Bloomington, California.* May 1.

_____. 2006a. *Monitoring Well Destruction and Replacement Well Installation Report, Kinder Morgan Energy Partners, L.P., Calnev Terminal, Bloomington, California.* May 23.

_____. 2006b. *Site Characterization Work Plan, Calnev Pipeline Company, L.P. Colton Terminal.* November.

Figures

Figure 1-1
Site Vicinity Map
Calnev Colton Terminal
Bloomington, California

Source: U.S.G.S. Maps, San Bernardino South, Edited 1980

CH2MHILL

E032003003SCO343176.KM.70.10 CalnevVicinity.ai 4/06





Legend:

- EMW-6 903.94 — Perching Silt Unit Monitoring Well with Groundwater Elevation in Feet Relative to Mean Sea Level (ft msl)
- LNAPL System Recovery Well
- Groundwater Elevation Contour (ft msl) (Dashed Where Inferred)
- Groundwater Flow Direction

Notes: 1. Contour Interval = 1 Foot
2. NG - Not Gauged
*3. * - Water Level Calculated Due to LNAPL in Well.*
4. NU - Not Used

Figure 3-1
Groundwater Elevations
Perching Silt Unit
Third Quarter 2007

Calnev Colton Fuels Terminal



Legend:

EMW-8 847.52 — Regional Water Table Aquifer Monitoring Well with Groundwater Elevation in Feet Relative to Mean Sea Level (ft msl)

Groundwater Elevation Contour (ft msl) (Dashed Where Inferred)

Groundwater Flow Direction

Notes: 1. Contour Interval = 1 Foot
2. NU - Not Used

Figure 3-2
Groundwater Elevations
Regional Water Table Aquifer
Third Quarter 2007

Calnev Colton Fuels Terminal



250 125 0 250 Feet

Legend:

- EMW-6 0.00 — Perching Silt Unit Monitoring Well Showing LNAPL Thickness in Feet
- LNAPL System Recovery Well
- Approximate LNAPL Extent

Notes: 1. NG - Not Gauged
2. Trace - A thin layer of LNAPL was observed when screening with a bailer, however, no measurable thickness of LNAPL was detected.
3. Sheen - Groundwater in monitoring well had a sheen but no measurable thickness of LNAPL.

Figure 3-3
LNAPL Distribution
Perching Silt Unit
Third Quarter 2007

Calnev Colton Fuels Terminal



Legend:

EMW-6 6.8 — Perching Silt Unit Monitoring Well with Benzene Concentration in Micrograms per Liter (ug/L)

LNAPL System Recovery Well

Benzene Isoconcentration Contour (ug/L) (Dashed Where Inferred)

Notes: 1. FP - Free Product
2. NS - Not Sampled

250 125 0 250 Feet

Figure 3-4
Benzene Distribution
Perching Silt Unit
Third Quarter 2007

Calnev Colton Fuels Terminal

SCO \\SALTFRCJKINGERM1\GIS\PROTECT\CALNEV\GDB\MAPFILES\3RDQTR07\CALNEV_PERCHBENZ_3RDQTR07.MXD 10/2/2007 14:42:56



250 125 0 250 Feet

Legend:

EMW-6 <0.5 — Perching Silt Unit Monitoring Well with MTBE Concentration in Micrograms per Liter (ug/L)

LNAPL System Recovery Well

MTBE Isoconcentration Contour (ug/L) (Dashed Where Inferred)

Notes: 1. FP - Free Product
2. NS - Not Sampled

Figure 3-5
MTBE Distribution
Perching Silt Unit
Third Quarter 2007

Calnev Colton Fuels Terminal





Legend:

EMW-6 12 — Perching Silt Unit Monitoring Well with TBA Concentration in Micrograms per Liter (ug/L)

LNAPL System Recovery Well

TBA Isoconcentration Contour (ug/L) (Dashed Where Inferred)

Notes: 1. FP - Free Product
2. NS - Not Sampled

Figure 3-6
TBA Distribution
Perching Silt Unit
Third Quarter 2007

Calnev Colton Fuels Terminal



Legend:

MW-8
<0.5
Regional Water Table Aquifer Monitoring Well with Benzene Concentration in Micrograms per Liter (ug/L)

Benzene Isoconcentration Contour (ug/L) (Dashed Where Inferred)

250 125 0 250 Feet

Figure 3-7
Benzene Distribution
Regional Water Table Aquifer
Third Quarter 2007

Calnev Colton Fuels Terminal



250 125 0 250 Feet

Legend:

MW-9
<0.5
Regional Water Table Aquifer Monitoring Well with MTBE Concentration in Micrograms per Liter (ug/L)

MTBE Isoconcentration Contour (ug/L) (Dashed Where Inferred)

Figure 3-8
MTBE Distribution
Regional Water Table Aquifer
Third Quarter 2007

Calnev Colton Fuels Terminal



Legend:

MW-8
<10
Regional Water Table Aquifer Monitoring Well with TBA Concentration in Micrograms per Liter (ug/L)

250 125 0 250 Feet

Figure 3-9
TBA Distribution
Regional Water Table Aquifer
Third Quarter 2007

Calnev Colton Fuels Terminal

Detailed Release Information

COLTON TERMINAL (RIALTO)
2359 SOUTH RIVERSIDE AVE
RIALTO , CA
CASE STATUS: OPEN
SHOW THIS SITE ON MAP
RETURN TO REPORT MAIN MENU

REGIONAL BOARD (LEAD AGENCY) -
CASE #: SL208023857
SANTA ANA RWQCB (REGION 8) - **(RS)**
CONTACT: ROSE SCOTT - (951) 782-4130
RB RECORD FILE #:

CASE TYPE:
Drinking Water Aquifer

ENFORCEMENT TYPE:

FUNDING:
Cost Recovery Funds

HOW LEAK WAS DISCOVERED:

METHOD USED TO STOP DISCHARGE:

INTERIM:

CAUSE OF LEAK:

SOURCE OF LEAK:

SUBSTANCES RELEASED:

Discharge Begin Date	Substance	Quantity
UNKNOWN	Petroleum - Automotive gasolines, Petroleum - Diesel fuels, Petroleum - Jet Fuel / Aviation	268000

Geotracker Home | Site/Facility Finder | Case Finder | MTBE/Case Reports

Fourth Quarter 2007 Groundwater Monitoring Report SFPP Colton Terminal 2359 South Riverside Avenue Bloomington, California

Prepared for

Kinder Morgan Energy Partners, L.P.

1100 Town & Country Road
Orange, California 92868

January 20, 2008



CH2MHILL

3 Hutton Centre Drive, Suite 200
Santa Ana, California 92707

Contents

Section		Page
1.0	**Introduction**	**1-1**
	1.1 Objectives	1-1
	1.2 Groundwater Monitoring Activities	1-1
2.0	**Background**	**2-1**
	2.1 Physical Setting	2-1
	2.2 Climate	2-1
	2.3 Local Hydrogeology	2-1
	2.4 Monitoring Well Network	2-2
3.0	**Groundwater Monitoring Results**	**3-1**
	3.1 Groundwater Flow Conditions	3-1
	3.1.1 Perching Silt Unit	3-1
	3.1.2 Regional Water Table Aquifer	3-1
	3.2 Groundwater Quality	3-1
	3.2.1 Distribution of LNAPL	3-1
	3.2.2 Analytical Results	3-2
	3.3 Field and Laboratory Quality Assurance/Quality Control (QA/QC) Results	3-3
4.0	**Summary of Ongoing Remedial Activities**	**4-1**
5.0	**Planned Activities**	**5-1**
	5.1 TFE System Expansion	5-1
	5.2 Offsite Characterization	5-1
6.0	**References**	**6-1**

Appendixes

A TRC Field Data Sheets

B Laboratory Analytical Reports (CD-ROM)

Tables

2-1 Total Precipitation

2-2 Well Construction Summary

3-1 Water Levels and Apparent LNAPL Thickness

3-2 Summary of Analytical Results

Figures

1-1 Site Vicinity Map
3-1 Groundwater Elevations Perching Silt Unit, Fourth Quarter 2007
3-2 Groundwater Elevations Regional Water Table Aquifer, Fourth Quarter 2007
3-3 LNAPL Distribution Perching Silt Unit, Fourth Quarter 2007
3-4 Benzene Distribution Perching Silt Unit, Fourth Quarter 2007
3-5 MTBE Distribution Perching Silt Unit, Fourth Quarter 2007
3-6 TBA Distribution Perching Silt Unit, Fourth Quarter 2007
3-7 Benzene Distribution Regional Water Table Aquifer, Fourth Quarter 2007
3-8 MTBE Distribution Regional Water Table Aquifer, Fourth Quarter 2007
3-9 TBA Distribution Regional Water Table Aquifer, Fourth Quarter 2007

1.0 Introduction

This report presents the results of the quarterly groundwater monitoring activities conducted during the Fourth Quarter 2007 at the Colton Fuel Terminal (the Terminal). The Terminal is located at 2359 South Riverside Avenue in Bloomington, California (Figure 1-1). Quarterly monitoring activities were conducted in response to Cleanup and Abatement Order No. 88-114, dated October 14, 1988, issued by the California Regional Water Quality Control Board (RWQCB), Santa Ana Region. This report also presents sampling results for Sentinel Wells DPPA-1 and DIHZ-1, and West Valley Water District (WVWD) Production Wells 40 and 41.

The Terminal is operated by SFPP, an operating partner of Kinder Morgan Energy Partners, L.P. (KMEP), as a bulk petroleum storage and distribution Terminal. The Terminal was constructed in the 1950s and has been subsequently expanded numerous times. Currently, it occupies 82 acres and consists of 32 refined petroleum product tanks and fuel-loading racks where transport tanker trucks are filled.

The Terminal is divided into individual petroleum company storage and transfer subterminals, which include SFPP, ARCO Petroleum Products Company (ARCO; a division of British Petroleum [BP]), ConocoPhillips, and Shell Oil Products USA (SOPUS). ARCO, SOPUS, and ConocoPhillips perform quarterly groundwater monitoring independent of KMEP. Their monitoring results are included in this report to provide a more complete picture of groundwater conditions at the Terminal.

1.1 Objectives

The objectives of the groundwater monitoring program are to characterize groundwater flow conditions and the lateral and vertical extent of light nonaqueous phase liquid (LNAPL) and dissolved-phase hydrocarbons in groundwater at the Terminal.

1.2 Groundwater Monitoring Activities

Groundwater monitoring at the Terminal includes quarterly sampling, gauging of groundwater levels, and measurement of LNAPL accumulations in onsite and offsite monitoring wells. TRC, Inc., performed field data collection and sampling on behalf of KMEP.

Groundwater samples collected from the monitoring wells were submitted to Alpha Analytical, Inc., of Sparks, Nevada, for the following analyses:

- Total petroleum hydrocarbons quantified as gasoline (TPH-g) and total petroleum hydrocarbons quantified as diesel (TPH-d) using U.S. Environmental Protection Agency (EPA) Method 8015 modified.
- Ethanol and methanol using EPA Method 8015 modified.

- Volatile organic compounds (VOCs) including methyl tertiary butyl ether (MTBE) and other fuel oxygenates using EPA Method 8260B-Full-Scan.

In addition, Sentinel Wells DPPA-1 and DIHZ-1 are sampled twice monthly, and Production Wells 40 and 41 are sampled monthly. Groundwater samples from these wells are analyzed for MTBE using EPA Method 8260B.

2.0 Background

This section presents background information for the Terminal, including descriptions of the physical setting, climate, and local hydrogeology.

2.1 Physical Setting

The Terminal is located within the Riverside Basin in the eastern portion of the Upper Santa Ana River Valley (Figure 1-1). Approximate elevations in the area range from 875 to 1,025 feet above mean sea level (msl), with the topography sloping to the southeast. The Santa Ana River is located approximately 1 mile southeast of the Terminal, and the partially lined Rialto Flood Control Channel traverses through the northeast portion of the Terminal.

2.2 Climate

The total annual precipitation in the vicinity of the Terminal averaged approximately 16.30 inches for the period of record between 1905 and 2005 based on data from the precipitation stations located closest to the Terminal (i.e., the San Bernardino Medical and San Bernardino County Yard [SCY] stations). The monthly precipitation since 2000 is summarized in Table 2-1. As these data show, the extreme precipitation events occurred during the winter of 2004/2005, and the total annual precipitation during 2005 (34.99 inches) was nearly twice the long-term average (16.30 inches). In addition, 15.98 inches of rain was recorded during February 2006 at the SCY station (Table 2-1).

The above-average groundwater recharge associated with these anomalously high precipitation events appears to have caused groundwater levels to rise in the vicinity of the Terminal during the First and Second Quarters of 2006, reversing a trend of decreasing water levels prior to 2005. Recent conditions are substantially dryer. Only 4.59 inches of precipitation was recorded between July 2006 and December 2007; consequently, groundwater levels have started to decrease at the Terminal (refer to Section 3.1, Groundwater Flow Conditions).

2.3 Local Hydrogeology

The sediments beneath the Terminal consist predominantly of fine- to coarse-grained, unconsolidated sand and gravel with occasional layers of silt and clay, which separate permeable aquifer materials and create zones of perched water and localized confined groundwater conditions. Four hydrostratigraphic units have been defined beneath the Terminal; these units are listed below in reverse stratigraphic order:

- Perched groundwater zone, referred to as the "perching silt unit"
- Regional water table aquifer
- Intermediate horizon
- Principal production aquifer

The perching silt unit occurs at approximately 90 feet below ground surface (bgs) at the Terminal, is 5 to 20 feet thick, and dips to the south. An additional 20 to 30 feet of unsaturated sediment occurs between the perching silt unit and the regional water table aquifer. The regional water table aquifer is approximately 150 feet thick and is separated from the principal production aquifer by fine-grained sediments of the intermediate horizon. The groundwater flow direction is toward the southwest in the perched zone, regional water table aquifer, and the principal production aquifer. For further information regarding the subsurface conditions in the vicinity of the Terminal, refer to the *Site Characterization Report for the Colton Fuels Terminal* (CH2M HILL, 2003).

2.4 Monitoring Well Network

The monitoring well network for the Terminal consists of 138 wells, including wells located on the various leases at the Terminal and offsite wells. There are six operational total fluids extraction (TFE) wells and six other wells equipped for TFE located onsite; there is a single groundwater extraction well located offsite. In addition, there are 17 soil vapor extraction (SVE) wells at the Terminal. Table 2-2 summarizes the construction details of the Terminal wells.

3.0 Groundwater Monitoring Results

This section presents the results of the groundwater monitoring activities performed during the Fourth Quarter 2007.

3.1 Groundwater Flow Conditions

Groundwater flow conditions in the perching silt unit and regional water table aquifer are discussed below. The groundwater level information for the Terminal is summarized in Table 3-1. Groundwater elevation contour maps for the perching silt unit and the regional water table aquifer are presented in Figures 3-1 and 3-2, respectively; hydrographs for select monitoring wells are included in these figures. The TRC field data sheets for water level gauging are provided in Appendix A.

3.1.1 Perching Silt Unit

The Fourth Quarter 2007 groundwater elevations in the perching silt unit range from 895.14 feet msl at PVX-5 (located in the northeastern portion of the Terminal) to 883.17 feet msl at LFMW-13 (located along the west-central portion of the Terminal). Groundwater elevations in the perching silt unit have decreased 0.25 foot compared to the Third Quarter 2007 (Figure 3-1). The groundwater flow direction is toward the southwest with a gradient that varies from approximately 0.004 foot per foot (ft/ft) in the northeastern portion of the terminal to 0.005 ft/ft south of the terminal.

3.1.2 Regional Water Table Aquifer

The Fourth Quarter 2007 groundwater elevations in the regional water table aquifer range from 846.54 feet msl at LFDW-1 (located in the northeast portion of the Terminal) to 835.63 feet msl at DW-29 (located southwest of the Terminal, west of Riverside Avenue). Groundwater elevations in the regional water table aquifer have decreased by an average of 0.59 foot since the Third Quarter 2007. The groundwater flow direction in the regional water table aquifer beneath the Terminal varies from southwest to south-southwest with a gradient of approximately 0.0018 ft/ft in the northeastern portion of the terminal to 0.0022 ft/ft south-southwest of the terminal.

3.2 Groundwater Quality

The distribution of LNAPL and concentrations of dissolved-phase benzene, MTBE, and tertiary butyl alcohol (TBA) are discussed below. The groundwater sampling data sheets are included in Appendix A.

3.2.1 Distribution of LNAPL

LNAPL was observed in four perched zone wells (PVX-2, PVX-3, PVX-4, and LFMW-12) located in the east-central portion of the facility as shown in Figure 3-3. Generally, the

distribution of LNAPL in the perching silt unit is consistent with previous monitoring events. Traces of LNAPL were observed in seven perched zone wells (PVX-1, PVX-11, PVX-12, LFDW-1, LFMW-5, LFMW-10, and LFMW-11). LNAPL was not observed in any of the regional water table aquifer wells this quarter (Table 3-1).

3.2.2 Analytical Results

During the Fourth Quarter 2007 groundwater sampling event, 42 groundwater samples from the perching silt unit and 52 groundwater samples from the regional water table aquifer were collected and submitted for laboratory analysis. Analytical results are summarized in Table 3-2. The laboratory analytical reports are included in Appendix B (on CD ROM).

3.2.2.1 Perching Silt Unit

Figures 3-4, 3-5, and 3-6 show the distribution of benzene, MTBE, and TBA, respectively, in the perching silt unit. The highest concentrations of benzene, MTBE, and TBA were detected in the east-central and central portions of the Terminal.

Benzene

Benzene was detected in 19 monitoring wells this quarter (Figure 3-4). Concentrations ranged from 0.49 J micrograms per liter (µg/L) in TWB-6 to 2,000 µg/L in PVX-14. Compared to the Third Quarter 2007, benzene concentrations for the Fourth Quarter 2007 have increased in 11 wells and decreased in 4 wells. The highest concentrations of benzene were reported in wells located in the south-central portion of the facility. Benzene concentrations were reported at or near the laboratory detection limit in wells located downgradient in the southwest portion of the site, east of Riverside Avenue and north of Santa Ana Avenue. Benzene concentrations were not reported in 25 wells this quarter.

MTBE

MTBE was detected in 41 monitoring wells this quarter (Figure 3-5). Concentrations ranged from 0.7 µg/L in TWMW-2A to 10,000 µg/L in PVX-5. Compared to the Third Quarter 2007, MTBE concentrations for the Fourth Quarter 2007 have increased in 23 wells and decreased in 13 wells. The highest concentrations of MTBE were reported in wells located in the central-northeast and central portions of the facility. MTBE concentrations were reported at low to moderate levels in wells located downgradient in the southwest portion of the site. MTBE concentrations were reported at or near the laboratory detection limit in wells located along Riverside Avenue. MTBE was not detected above reporting limits in six wells this quarter.

TBA

TBA was detected in 27 monitoring wells this quarter (Figure 3-6). Concentrations ranged from 12 µg/L in AMW-5 and MobilSB-02 to 17,000 µg/L in PVX-14. Compared to the Third Quarter 2007, TBA concentrations for the Fourth Quarter 2007 have increased in 19 wells and decreased in 4 wells. The highest concentrations of TBA were reported in wells located in the east-central and northeast portions of the facility. TBA concentrations were reported at low to moderate levels in wells located downgradient in the southwest portion of the site. TBA concentrations were reported at the laboratory detection limit in wells located along Riverside Avenue. TBA was not detected above reporting limits in 19 wells this quarter.

3.2.2.2 Regional Water Table Aquifer

Figures 3-7, 3-8, and 3-9 show the distribution of benzene, MTBE, and TBA, respectively, in the regional water table aquifer. The overall distribution of these constituents is generally consistent with that of the previous quarterly monitoring event, which suggests an overall decrease in dissolved-phase concentrations offsite south of the Terminal.

Benzene

Benzene was detected in six monitoring wells this quarter (Figure 3-7). Concentrations ranged from 0.51 µg/L in ASW-3 to 870 µg/L in TFE-A. Compared to the Third Quarter 2007, benzene concentrations for the Fourth Quarter 2007 have increased in two wells and decreased in seven wells. The highest concentrations of benzene were reported in wells located in the eastern and south-central portions of the facility. Benzene concentrations were reported at low levels in wells located downgradient in the southwest portion of the site. Benzene concentrations were reported at the laboratory detection limit in wells located offsite along Riverside Avenue. Benzene was not detected above reporting limits in 47 wells this quarter.

MTBE

MTBE was detected in 27 monitoring wells this quarter (Figure 3-8). Concentrations ranged from 0.54 µg/L in DDW-27 to 13,000 µg/L in DW-47. Compared to the Third Quarter 2007, MTBE concentrations for the Fourth Quarter 2007 have increased in 14 wells and decreased in 12 wells. The highest concentrations of MTBE were reported in wells located in the southwestern portion of the facility. MTBE concentrations were reported at low to moderate levels in most wells located offsite to the west and south. However, MTBE was reported at elevated concentrations in ADW-1 located west of the facility along Riverside Avenue. Additionally, this quarter MTBE concentrations were reported in DW-20 at 65 µg/L; however, based on historical data for this well, these concentrations appear to be anomalous. MTBE was not detected above reporting limits in 25 wells this quarter.

TBA

TBA was detected in 11 monitoring wells this quarter (Figure 3-9). Concentrations ranged from 12 µg/L in ASW-2 to 1,500 µg/L in LFDW-1. Compared to the Third Quarter 2007, TBA concentrations for the Fourth Quarter 2007 have increased in six wells and decreased in six wells. The highest concentrations of TBA were reported in wells located in the east-central and central portions of the facility. TBA concentrations were reported at low to moderate levels in wells located downgradient in the southwest portion of the site. TBA concentrations were reported at or near the laboratory detection limit in most wells located offside along Riverside Avenue. TBA was not detected above reporting limits in 41 wells this quarter.

3.3 Field and Laboratory Quality Assurance/Quality Control (QA/QC) Results

For the Fourth Quarter 2007 sampling event, 13 field duplicate samples, 13 equipment blanks, and 19 trip blanks were collected and analyzed to help assess data reliability. A summary of analytical results for these samples is presented below.

- The duplicate samples were analyzed for all target analytes. The relative percent differences (RPDs) for duplicate samples in MobilMW-02 for MTBE it was 57 percent, in MobilSB-02 for TBA it was 114 percent, in PVX-14 for ethylbenzene it was -48 percent, in PVX-8 for MTBE it was -171 percent. For all other samples, the RPDs were within acceptable limits for all target analytes.
- Results for the trip blanks were below the laboratory reporting limits.
- The equipment blanks were analyzed for all target analytes. Analytical results for the equipment blank samples were below the laboratory reporting limits for target compounds.

Laboratory data quality was evaluated by examining the method blanks, matrix spike/matrix spike duplicate (MS/MSD) percent recoveries and RPDs, laboratory control sample (LCS) percent recoveries, and surrogate percent recoveries. Method blanks were analyzed at the appropriate frequency and were below laboratory detection limits for all analytes of interest. MS/MSD and LCS percent recoveries were analyzed at the appropriate frequency, and correctly reported.

The MS/MSD recovery for MTBE was high on November 8, 2007, but the method control sample was acceptable. The MS/MSD recovery for total petroleum hydrocarbons-extractable (TPH-E) (diesel range organics [DRO]) on November 19, 2007, was above acceptance limits due to heavy-end hydrocarbons (C10-C40). The MS was below the acceptable limit and the MSD was above the acceptable limit for TPH-E (DRO) on November 20, 2007, likely due to non-homogeneity of the sample. The MS/MSD RPD for TPH-E (DRO) on November 20, 2007, and November 26, 2007, exceeded the control limit, but the recovery met acceptance criteria. The MS/MSD RPD for MTBE on December 6, 2007, exceeded the control limit, but the recovery met acceptance criteria. The LCS was within an acceptable limit. The Continuing Calibration Verification recovery for the surrogate Tetracosane was not within established control limits on December 10, 2007. All other surrogate percent recoveries were within laboratory-established control limits. In general, the overall precision and accuracy of the laboratory data are acceptable.

4.0 Summary of Ongoing Remedial Activities

A brief summary of ongoing remedial activities at the Terminal for the Fourth Quarter 2007 is provided below. In October 2007, KMEP staff began operating the remedial systems at the Terminal, and CH2M HILL now prepares and submits the Monthly System Status Reports for both fluid extraction systems. The Soil Vapor Extraction (SVE) System Quarterly Status Report is submitted on a quarterly basis under separate cover.

- **SVE System**: KMEP operates an onsite SVE system to remediate the vadose zone beneath the southwest portion of the site. The SVE system consists of 17 operating SVE wells (16 wells in the perching silt unit and 1 well in the regional water table aquifer) and a thermal oxidizer for offgas treatment. The system has been inoperable since the Fourth Quarter 2006 due to equipment failure. KMEP is currently working to decommission the existing SVE blower and thermal oxidizer and install rental equipment for offgas treatment.

- **Total Fluids Extraction (TFE) System**: KMEP operates the TFE system to contain offsite migration of dissolved-phase contaminants and LNAPL in the regional water table aquifer. The system has been in operation since June 2002. The current TFE system consists of four extraction wells (TFE-A, TFE-B, TFE-C, and TFE-D) and a granular activated carbon (GAC) treatment system. Between October and December 2007, approximately 2.5 million gallons of groundwater was treated and discharged to the Rialto Flood Control Channel under National Pollutant Discharge Elimination System (NPDES) Permit No. CAG 918001. During the Fourth Quarter 2007, the average combined extraction rate for the system was approximately 19 gallons per minute (gpm).

- **LNAPL Recovery:** KMEP has recovered LNAPL from the perching silt unit onsite using two portable skimmer units. The skimmer units were most recently installed in wells PVX-2 and PVX-4, where LNAPL accumulations were thicker. The LNAPL yield from PVX-2 and PVX-4, however, is now negligible. The apparent LNAPL thickness in wells at the Terminal has decreased as water levels have risen in the perching silt unit. Because there are no wells at the Terminal with accumulations of recoverable LNAPL at this time, KMEP has temporarily discontinued LNAPL recovery efforts.

- **Interim Treatment System (ITS):** KMEP operates an offsite groundwater extraction system downgradient of the Terminal. Groundwater is extracted from a single extraction well (EX-1), treated, and then discharged to the sanitary sewer. The system has been in operation since 2002. Due to odor complaints by site occupants, the HiPOx™ treatment unit that was previously used to treat the discharge was replaced with a GAC treatment system, which is now online.

5.0 Planned Activities

This section presents a summary of planned remedial and site characterization activities to be completed by KMEP.

5.1 TFE System Expansion

Planning and design activities to expand the TFE treatment system are ongoing. Because of the planned expansion of the Terminal, the treatment system will need to be relocated west of its current position. A new concrete pad will need to be constructed, and the piping and electrical conduit for the extraction wells will need to be rerouted to the new location of the treatment system. CH2M HILL has completed the civil and electrical design for the new treatment facility, and the City of Rialto has approved the civil design for the new equipment pad. KMEP intends to start construction of the new treatment facility during March 2007.

5.2 Offsite Characterization

CH2M HILL previously proposed to install an additional offsite monitoring well in the regional water table aquifer southwest of the Terminal. The objective of this additional work is to better delineate the lateral extent of MTBE and other dissolved-phase hydrocarbons cross-gradient and downgradient of well ADW-1, where elevated MTBE concentrations have been detected. In December 2007, CH2M HILL corresponded with the City of Rialto Department of Public Works regarding an encroachment permit for the installation of this offsite well (DW-49). In January 2008, CH2M HILL was informed on the telephone that the request to install a monitoring well along Santa Ana Avenue would be denied. Currently, CH2M HILL is evaluating other potential well locations. Details regarding these negotiations with the City of Rialto have been documented in a letter and will be submitted to the RWQCB under separate cover.

6.0 References

CH2M HILL. 2003. *Site Characterization Report for Colton Fuels Terminal.* August.

_____. 2005a. *Additional Total Fluids Extraction System Work Pan, SFPP Terminal.* January 17.

_____. 2005b. *Well Construction Report for Additional Total Fluids Extraction System Expansion, SFPP Colton Fuels Terminal in Bloomington, California.* July 7.

_____. 2005c. *Well Installation Report for Additional Total Fluids Extraction System Expansion, SFPP Colton Fuels Terminal in Bloomington, California.* December 12.

_____. 2006. *Work Plan for Installation of Regional Water Table Aquifer Monitoring Wells DW-48 and DW-49, SFPP Colton Terminal.* June 9.

_____. 2007. *Well Construction Report for Additional Regional Water Table Aquifer Monitoring Well DW-48, SFPP Colton Terminal in Bloomington, California.* May 30.

Figures



Figure 1-1
Site Vicinity Map
Colton Fuels Terminal

Source: USGS 7-1/2 Minute Quadrangle Maps, Fontana, California, 1980 and South San Bernardino, 1980.

CH2MHILL

EJMStbdSCO315205.KM.50 CFvicinity ai 1/05



250 125 0 250 Feet

Legend:

AMW-12 891.49 — Perching Silt Unit Monitoring Well with Groundwater Elevation in Feet Relative to Mean Sea Level (ft msl)

Groundwater Elevation Contour (ft msl) (Dashed Where Inferred)

Groundwater Flow Direction

Notes: 1. Contour Interval = 1 Foot
2. NG - Not Gauged
3. NU - Not Used for Contouring
*4. * - Water Level Calculated Due to LNAPL in Well*

Figure 3-1
Groundwater Elevations
Perching Silt Unit
Fourth Quarter 2007

Colton Fuels Terminal

File Path: \\gallpro\kinderm\340127ColtonCalnev\2007\MapFiles\4thQtr07\Colton\Fig01_Colton_PerchedGWElev_4thQtr07.mxd, Date: January 16, 2008 11:03:32 AM



800 300 0 600 Feet

Legend:

- DW-25 842.54 — Regional Water Table Aquifer Monitoring Well with Groundwater Elevation in Feet Relative to Mean Sea Level (ft msl)
- Production Well
- Sentinel Well
- Groundwater Elevation Contour (ft msl) (Dashed Where Inferred)
- Groundwater Flow Direction

Notes: 1. Contour Interval = 1 Foot
2. NG - Not Gauged
3. NU - Not Used for contouring

Figure 3-2
Groundwater Elevations
Regional Water Table Aquifer
Fourth Quarter 2007

Colton Fuels Terminal

File Path: \\gal\proj\kinderm\340127ColtonCalnev\2007\MapFiles\4thQtr07\Colton\Fig02_Colton_Reg05GWElev_4thQtr07.mxd, Date: January 16, 2008 11:07:11 AM



250 125 0 250 Feet

Legend:

LFMW-9
0.00
Perching Silt Unit Monitoring Well with LNAPL Thickness in Feet

Approximate Extent of LNAPL

Note: 1. NG - Not Gauged
2. Sheen - Groundwater in Monitoring well had a sheen but no measurable thickness of LNAPL
3. Trace - A thin layer of LNAPL was observed when screening with a bailer; however, no measurable thickness of LNAPL was detected

Figure 3-3
LNAPL Distribution
Perching Silt Unit
Fourth Quarter 2007
Colton Fuels Terminal

File Path: \\gailfprd\kinderm\340127ColtonCalnev\2007\MapFiles\4thQtr07\Colton\Fig03_Colton_PrchdNAPL_4thQtr07.mxd, Date: January 16, 2008 11:59:40 AM



Legend:

LFMW-3 Dry — Perching Silt Unit Monitoring Well

Benzene Concentration in Micrograms per Liter (ug/L)

Benzene Isoconcentration Contour (ug/L) (Dashed Where Inferred)

250 125 0 250 Feet

Notes: 1. FP - Free Product
2. NS - Not Sampled
3. Benzene distribution in vicinity of ARCO Terminal inferred from Third Quarter 2006 distribution.

Figure 3-4
Benzene Distribution
Perching Silt Unit
Fourth Quarter 2007

Colton Fuels Terminal

File Path: \\gait\proj\kinderm\340127ColtonCalnev\2007\MapFiles\4thQtr07\Colton\Fig05_Colton_PerchedBenzElev_4thQtr07.mxd, Date: January 16, 2008 11:31:43 AM



Legend:

LFMW-3 Dry — Perching Silt Unit Monitoring Well

MTBE Concentration in Micrograms per Liter (ug/L)

MTBE Isoconcentration Contour (ug/L) (Dashed Where Inferred)

Notes: 1. FP - Free Product
2. NS - Not sampled
3. NG - Not Gauged
4. MTBE distribution in vicinity of ARCO Terminal inferred from Third Quarter 2006 distribution.

250 125 0 250 Feet

Figure 3-5
MTBE Distribution
Perching Silt Unit
Fourth Quarter 2007

Colton Fuels Terminal

File Path: \\galltproj\kinderm\340127ColtonCalnav\2007\MapFiles\4thQtr07\Colton\Fig06_Colton_PerchedMTBE_4thQtr07.mxd, Date: January 10, 2008 12:15:54 PM



Legend:

LFMW-3 Dry — Perching Silt Unit Monitoring Well
TBA Concentration in Micrograms per Liter (ug/L)

TBA Isoconcentration Contour (ug/L) (Dashed Where Inferred)

250 125 0 250 Feet

Notes: 1. FP - Free Product
2. NS - Not Sampled
3. TBA distribution in vicinity of ARCO Terminal inferred from Third Quarter 2006 distribution.

Figure 3-6
TBA Distribution
Perching Silt Unit
Fourth Quarter 2007

Colton Fuels Terminal

File Path: \\gal\proj\kinderm\340127ColtonCalnev\2007\MapFiles\4thQtr07\Colton\Fig07_Colton_PerchTBA_4thQtr07.mxd, Date: January 15, 2008 12:24:35 PM


Riverside Ave
Industrial Dr
Willow Ave
Sierra Ave
Juniper Ave
LPDW-1
LPDW-2
LPDW-3
LPDW-4
LPDW-5
ADW-1
ADW-2
ADW-3
DW-1
DW-2
DW-3
DW-4
DW-5
DW-6
DW-7
DW-8
DW-9
DW-10
DW-11
DW-12
DW-13
DW-14
DW-15
DW-16
DW-17
DW-18
DW-19
DW-20
DW-21
DW-22
DW-23
DW-24
DW-25
DW-26
DW-27
DW-28
DW-29
DW-30
DW-31
DW-32
DW-33
DW-34
DW-35
DW-36
DW-37
DW-38
DW-39
DW-40



Legend:

- EXDW-1 <0.5 — Regional Water Table Aquifer Monitoring Well; MTBE Concentration in Micrograms per Liter (ug/L)
- Production Well
- Sentinel Well
- MTBE Isoconcentration Contour (ug/L) (Dashed Where Inferred)

Notes: 1. DDW and AS/SVE Wells Not Used in Contouring
2. FP - Free Product
3. NS - Not Sampled

Figure 3-8
MTBE Distribution
Regional Water Table Aquifer
Fourth Quarter 2007

Colton Fuels Terminal

File Path: \\gatlproj\kinderm\340127ColtonCalnev\2007\MapFiles\4thQtr07\Colton\Fig09_Colton_RegMTBE_4thQtr07.mxd, Date: January 15, 2008 12:15:59 PM


Riverside Ave
Willow Ave
Industrial Dr
Sierra Ave
Cedar Ave
Juniper Ave
LFDW-1
LFDW-2
LFDW-3
LFDW-4
LFDW-5
LFDW-6
LFDW-7
LFDW-8
LFDW-9
LFDW-10
LFDW-11
LFDW-12
LFDW-13
LFDW-14
LFDW-15
LFDW-16
LFDW-17
LFDW-18
LFDW-19
LFDW-20
LFDW-21
LFDW-22
LFDW-23
LFDW-24
LFDW-25
LFDW-26
LFDW-27
LFDW-28
LFDW-29
LFDW-30
LFDW-31
LFDW-32
LFDW-33
LFDW-34
LFDW-35
LFDW-36
LFDW-37
LFDW-38
LFDW-39
LFDW-40

GATX RAIL CORPORATION

20878 SLOVER ST
COLTON, CA
92324-7300

Facility ID : 85004255
Local Agency: SAN BERNARDINO COUNTY

Wells Nearby

Water System Name	Water System ID	Well Name	Common Well Name	Dist To LUFT
GEN AMERICAN TRANS CORP	3601089	3601089-001	WELL	n/a

Well Report

GEN AMERICAN TRANS CORP (COLTON)
WELL
State Well Number: 3601089-001

Well Details | Geographic Information | DHS Water Quality Data | PWS Detailed Information

Local Name
WELL (3601089-001)

Source Origin
G

Status
AU

Treatment Method
Unknown

Treatment Phase
Unknown

0 LUFT Site(s) Estimated to be Nearby this Well

- **List These LUFT Sites**

Geotracker Home | Site/Facility Finder | Case Finder | MTBE/Case Reports

REGULATORY HISTORY

CONOCO COLTON TERMINAL - EAST YARD (BLOOMINGTON)
271 E. SLOVER AVE
BLOOMINGTON , CA 92316
CASE STATUS: OPEN
SHOW THIS SITE ON MAP
RETURN TO REPORT MAIN MENU

REGIONAL BOARD (LEAD AGENCY)
SANTA ANA RWQCB (REGION 8) - **(RS)**
CONTACT: ROSE SCOTT - (951) 782-4130

LOCAL AGENCY
SAN BERNARDINO COUNTY LOP - **(JC3)**
RB RECORD FILE #:

REGULATORY HISTORY

BEGIN DATE	STATUS
5/3/2002	Case Open
5/3/2002	RP
5/5/2002	Verification Monitoring Underway

Geotracker Home | Site/Facility Finder | Case Finder | MTBE/Case Reports

Land Use Controls

CONOCO COLTON TERMINAL - EAST YARD (BLOOMINGTON)
271 E. SLOVER AVE
BLOOMINGTON , CA 92316
CASE STATUS: OPEN
SHOW THIS SITE ON MAP
RETURN TO REPORT MAIN MENU

REGIONAL BOARD (LEAD AGENCY)
SANTA ANA RWQCB (REGION 8) - **(RS)**
CONTACT: ROSE SCOTT - (951) 782-4130

LOCAL AGENCY
SAN BERNARDINO COUNTY LOP - **(JC3)**
RB RECORD FILE #:

FUTURE LAND USE REPORTED AT CLOSURE
INDUSTRIAL

CURRENT LAND USE
INDUSTRIAL

SITE MANAGEMENT REQUIREMENTS
NO ACTION

SITE MANAGEMENT DESCRIPTION
FULL EVALUATION REQUIRED AFTER ABOVEGROUND TANKS ARE REMOVED.

BROWNFIELD (ABANDONED PROPERTY NOT REDEVELOPED DUE TO CONTAMINATION AND LIABILITY COST CONCERNS)
NO

Geotracker Home | Site/Facility Finder | Case Finder | MTBE/Case Reports

Detailed Release Information

CONOCO COLTON TERMINAL - EAST YARD (BLOOMINGTON)
271 E. SLOVER AVE
BLOOMINGTON , CA 92316
CASE STATUS: OPEN
SHOW THIS SITE ON MAP
RETURN TO REPORT MAIN MENU

REGIONAL BOARD (LEAD AGENCY)
SANTA ANA RWQCB (REGION 8) - **(RS)**
CONTACT: ROSE SCOTT - (951) 782-4130

LOCAL AGENCY
SAN BERNARDINO COUNTY LOP - **(JC3)**
RB RECORD FILE #:

CASE TYPE:
Drinking Water Aquifer

ENFORCEMENT TYPE:

FUNDING:
Cost Recovery Funds

HOW LEAK WAS DISCOVERED:
* Other Means

METHOD USED TO STOP DISCHARGE:

INTERIM:

CAUSE OF LEAK:

SOURCE OF LEAK:

SUBSTANCES RELEASED:

Discharge Begin Date	Substance	Quantity
9/6/1974	* Gasoline - Automotive	82000
UNKNOWN	NOT_SELECTED	

Geotracker Home | Site/Facility Finder | Case Finder | MTBE/Case Reports

Remediation On Site

CONOCO COLTON TERMINAL - EAST YARD (BLOOMINGTON)
271 E. SLOVER AVE
BLOOMINGTON , CA 92316
CASE STATUS: OPEN
SHOW THIS SITE ON MAP
RETURN TO REPORT MAIN MENU

REGIONAL BOARD (LEAD AGENCY)
SANTA ANA RWQCB (REGION 8) - **(RS)**
CONTACT: ROSE SCOTT - (951) 782-4130

LOCAL AGENCY
SAN BERNARDINO COUNTY LOP - **(JC3)**
RB RECORD FILE #:

Start Date	Method	Phase
9/6/1974	Remove free product	LNAPL

Geotracker Home | Site/Facility Finder | Case Finder | MTBE/Case Reports

APPENDIX C

NON-DATABASE SEARCH RESULTS

PETRA

Abandoned & Little-Known Airfields:

California: Western San Bernardino County

© 2002, © 2006 by Paul Freeman. Revised 11/4/06.

(Original) Apple Valley Airport (revised 3/5/06) - Fontana Airport / Fontana Gilfillan Airport (revised 5/16/04) - Morrow Field (revised 4/21/06)

San Bernardino Airport (1st location) / Shandin Hills Airport / Cooks Airport **(added 11/4/06)** - San Bernardino Airport (2nd location) **(revised 11/4/06)**

Tri-City Airport (revised 4/21/06)

(Original) Apple Valley Airport, Apple Valley, CA

34.53 North / 117.22 West (Northeast of Los Angeles, CA)

A circa 1956-58 photo (courtesy of Paul Bern) of Grant Kirby (Sky King) and Gloria Winters (Penny)

Evelyn (Pinky) Brier, still lives in a house on the site of the former airport,

built after the airport property was sold to developers.

"The building is large enough to house many of the things from the airport,

including a plane & Jeep used to transport people to & from their airplanes."

The airport site is located northeast of the intersection of Interstate 10 & South Western Avenue.

Morrow Field (RTO), Rialto, CA

34.08 North / 117.36 West (East of Los Angeles, CA)



An undated vintage photo of Howard Morrow Sr. & Bill Morrow in front of the prototype Morrow Trainer.

Photo is courtesy of Howard Morrow Jr., via Dan MacPherson.

Entrepreneur Howard Morrow opened Morrow Aircraft in Van Nuys in 1940.

He designed the Morrow Trainer, an all-wood monoplane trainer intended for military use,

and produced a single prototype in 1941.

Morrow Field was reportedly built in 1942,

after the military purchased Morrow's original airfield facilities (later to become Norton AAF).

The Morrow company was unsuccessful in obtaining any military orders for their aircraft,

but did produce drop tanks & other aircraft components during WW2.

The sole prototype of the Morrow Trainer went into storage.

Morrow Field may have gone through a period of inactivity after WW2,

as it does not appear on the 1945 San Diego Sectional Aeronautical Chart (courtesy of John Voss).



The earliest depiction of Morrow Field which has been located

was a November 1946 aerial view (courtesy of Bob Anderson).

It depicted the field as having a single northeast/southwest runway,

with a ramp & a single hangar on the south side of the field.



The 1954 USGS topo map (courtesy of Scott O'Donnell)

depicted Morrow Field as having a single 3,200' northeast/southwest runway,

and a taxiway leading to a single hangar along the south side of the field.

The 1955 San Diego Sectional Chart (courtesy of John Voss)

described Morrow as having a 3,200' paved runway.

Bob Cannon recalled, "My uncle lived adjacent to Morrow Field,

in fact some of the land may have been originally his. I used to fly in to visit them."

The runway at Morrow Field was also used for drag racing.

According to Paul Baechler, "Colton Raceway at Morrow Field (the dragstrip) was active in the 1950s & 60s,

according to racing websites.

Apparently the airport was closed during races & the runway used."



A 1961 aerial view of Morrow Field (courtesy of Bob Anderson)

showed the field in largely the same configuration as it had appeared in the 1946 photo.

Morrow Field was listed among active airports in the 1962 AOPA Airport Directory,

with a single asphalt 3,360' Runway 9/27,

and the operator listed as Howard Morrow.

According to the San Bernardino County Sun, at an unknown date Howard Morrow Sr. built a golf course adjacent to the airfield,

a social club with a swimming pool, and even a short-lived shallow lake on which water skiers were pulled with a cable.

Morrow sold the airport in 1968.



Morrow Field, as depicted in the 1968 Flight Guide (courtesy of Chris Kennedy).

A De Havilland DHC-6 Twin Otter, operated by Cable Commuter Airlines. Undated.

Cable Commuter Airlines began operations in 1968,

and operated passenger airline service into Morrow Field.

They eventually operated twelve De Havilland Twin Otters on routes from Los Angeles

to a number of small airports in the area (including Tri-City Airport & Brackett Field).

Sometime later the airline was bought out by a larger company, which soon went out of business.



Morrow Airport, as depicted on the September 1971 USAF Tactical Pilotage Chart (courtesy of Chris Kennedy).

Phil Du Bois recalled, "I visited the 'Colton' Airport in 1971 several times,

as my instructor took me there for landing practice because it was a 'tight' airport.

That is there were telephone poles at either end.

It was obvious then that the airport was on it's way out.

I do not remember the airport existing after 1972."

However, "Colton Airpark: Morrow Field" was listed in the 1977 Pilot's Guide to CA Airports (according to Chris Kennedy),

and was described as having a single 2,985' paved Runway 5/23.



Morrow Field evidently was closed at some point between 1977-80,

as it was labeled as "Municipal Airport (Abandoned)" on the 1980 USGS topo map.

It depicted the airfield as having a ramp extending south from the midpoint of the runway,

with several small buildings (hangars?) on either side of the ramp.

A Price Club was later built on the site, but that location was closed in the mid-1990s.

According to the San Bernardino County Sun,

the former Price Club building is being used by a food processing company.



Aerial photo of the site of the former airport, circa 2000.

Wildrose Avenue has been built through the middle of the former airport.

The golf course built by airport founder Howard Morrow Sr. still exists on the southeast portion of the former airport property,

now known as Sam Snead Golf Course.

The diagonal orientation of the former runway is still apparent in the above 2000 aerial photo of the airfield site.

The airport site is located northeast of the intersection of South Riverside Avenue & West Valley Boulevard.

Home

5/21/08

Sam Fuller - SB Valley Muni WD



Site S of RC fault trends SE/NW - barrier

Santa Ana River → to SE, High cause water to flow away fm river
Low → opposite

Chino Basin → Huge demand, pump, draw water towards (to W)
when Not → opposite

GW flow all diff directions due to above influences.

Welcome to California

DEPARTMENT OF WATER RESOURCES
PLANNING AND LOCAL ASSISTANCE

DWR

Groundwater Level Data, 01S04W19E001S

Your selection returned a total of **91** records. Wells in the Department of Water Resources monitoring identified by a State Well Number, which is based on the Public Land Grid System. The table heading contain several codes and abbreviations. Press the ***New Search*** or ***Nearby Search*** buttons or at the page to begin a new data retrieval. Data for this well can also be downloaded in MS Excel or text deli



Division of Planning and Local Assistance Department of Water Resources

901 P Street
Sacramento, CA 95814

Mailing Address:
Post Office Box 942836
Sacramento, CA 94236-0001

Groundwater Level Readings

Meas. Date	R.P. Elev.	G.S. Elev.	RPWS	WSE	GSWS	QM Code	NM Cc
03-02-1964	1038.9	1038.9	189.8	849.1	189.8		
03-04-1964	1038.9	1038.9	189.8	849.1	189.8		
03-16-1964	1038.9	1038.9	189.6	849.3	189.6		
04-09-1964	1038.9	1038.9	189.4	849.5	189.4		
11-30-1967	1038.9	1038.9	192.1	846.8	192.1		
05-25-1968	1038.9	1038.9	190.4	848.5	190.4		
01-02-1969	1038.9	1038.9	193.9	845.0	193.9		

04-28-1969	1038.9	1038.9	187.9	851.0	187.9		
11-20-1969	1038.9	1038.9	175.8	863.1	175.8		
03-30-1970	1038.9	1038.9	173.3	865.6	173.3		
07-07-1977	1038.9	1038.9	179.4	859.5	179.4		
08-26-1977	1038.9	1038.9	179.2	859.7	179.2		
09-21-1977	1038.9	1038.9	180.1	858.8	180.1		
10-11-1977	1038.9	1038.9	181.5	857.4	181.5		
11-15-1977	1038.9	1038.9	182.4	856.5	182.4		
12-15-1977	1038.9	1038.9	182.9	856.0	182.9		
01-14-1978	1038.9	1038.9	182.5	856.4	182.5		
07-14-1978	1038.9	1038.9	184.7	854.2	184.7		
08-11-1978	1038.9	1038.9	173.9	865.0	173.9		
11-16-1978	1038.9	1038.9	172.1	866.8	172.1		
12-15-1978	1038.9	1038.9	171.7	867.2	171.7		
01-18-1979	1038.9	1038.9	170.4	868.5	170.4		
02-20-1979	1038.9	1038.9	170.0	868.9	170.0		
03-15-1979	1038.9	1038.9	169.8	869.1	169.8		
05-17-1979	1038.9	1038.9	172.4	866.5	172.4		
06-14-1979	1038.9	1038.9	168.1	870.8	168.1		
07-06-1979	1038.9	1038.9	167.5	871.4	167.5		
07-12-1979	1038.9	1038.9	167.3	871.6	167.3		
09-14-1979	1038.9	1038.9	167.5	871.4	167.5		
12-12-1979	1038.9	1038.9	166.2	872.7	166.2		
01-18-1980	1038.9	1038.9	165.9	873.0	165.9		
02-13-1980	1038.9	1038.9	158.4	880.5	158.4		
03-14-1980	1038.9	1038.9	166.6	872.3	166.6		
04-16-1980	1038.9	1038.9	168.3	870.6	168.3		
05-16-1980	1038.9	1038.9	166.2	872.7	166.2		
06-12-1980	1038.9	1038.9	163.9	875.0	163.9		
06-13-1980	1038.9	1038.9	163.6	875.3	163.6		
07-23-1980	1038.9	1038.9	165.3	873.6	165.3		
08-14-1980	1038.9	1038.9	162.8	876.1	162.8		
09-18-1980	1038.9	1038.9	161.5	877.4	161.5		
10-22-1980	1038.9	1038.9	161.0	877.9	161.0		
11-21-1980	1038.9	1038.9	160.6	878.3	160.6		
12-04-1980	1038.9	1038.9	161.3	877.6	161.3		
12-19-1980	1038.9	1038.9	160.0	879.0	160.0		
01-15-1981	1038.9	1038.9	159.4	879.5	159.4		
02-20-1981	1038.9	1038.9	158.9	880.0	158.9		
03-12-1981	1038.9	1038.9	158.0	880.9	158.0		
04-16-1981	1038.9	1038.9	157.9	881.0	157.9		
05-15-1981	1038.9	1038.9	157.7	881.2	157.7		
06-11-1981	1038.9	1038.9	157.7	881.2	157.7		
07-22-1981	1038.9	1038.9	156.9	882.0	156.9		
08-13-1981	1038.9	1038.9	156.8	882.1	156.8		
08-19-1981	1038.9	1038.9	158.1	880.9	158.1		
09-16-1981	1038.9	1038.9	156.3	882.6	156.3		
10-22-1981	1038.9	1038.9	155.9	883.0	155.9		
11-20-1981	1038.9	1038.9	155.7	883.2	155.7		
09-15-1982	1038.9	1038.9	155.2	883.7	155.2		
07-27-1983	1038.9	1038.9	152.7	886.2	152.7		

11-30-1983	1038.9	1038.9	151.7	887.2	151.7		
04-11-1984	1038.9	1038.9	149.9	889.1	149.9		
09-21-1984	1038.9	1038.9	150.2	888.7	150.2		
05-10-1985	1038.9	1038.9	149.9	889.1	149.9		
09-18-1985	1038.9	1038.9	149.6	889.3	149.6	6	
05-15-1986	1038.9	1038.9	148.4	890.5	148.4		
06-20-1986	1038.9	1038.9	148.6	890.3	148.6		
09-15-1986	1038.9	1038.9	149.6	889.3	149.6		
11-20-1986	1038.9	1038.9	149.4	889.5	149.4	6	
05-01-1987	1038.9	1038.9	149.6	889.3	149.6		
06-18-1987	1038.9	1038.9	150.3	888.6	150.3	6	
04-12-1988	1038.9	1038.9	150.9	888.0	150.9		
06-29-1988	1038.9	1038.9	151.8	887.1	151.8		
11-28-1988	1038.9	1038.9	151.6	887.4	151.6		
09-21-1989	1038.9	1038.9	155.7	883.2	155.7		
11-27-1989	1038.9	1038.9	156.5	882.4	156.5		
06-28-1990	1038.9	1038.9	156.9	882.0	156.9		
11-28-1990	1038.9	1038.9	161.1	877.8	161.1		
06-24-1991	1038.9	1038.9	158.9	880.0	158.9		
11-27-1991	1038.9	1038.9	163.2	875.8	163.2		
06-17-1992	1038.9	1038.9	162.4	876.6	162.4		
10-27-1992	1038.9	1038.9	164.2	874.8	164.2		
04-14-1993	1038.9	1038.9	161.8	877.1	161.8		
10-18-1993	1038.9	1038.9	159.3	879.7	159.3		
04-19-1994	1038.9	1038.9	156.7	882.2	156.7		
10-24-1994	1038.9	1038.9	157.1	881.8	157.1		
04-19-1995	1038.9	1038.9	154.8	884.1	154.8		
10-23-1995	1038.9	1038.9	155.1	883.8	155.1		
04-25-1996	1038.9	1038.9	153.6	885.3	153.6		
10-09-1996	1038.9	1038.9	158.5	880.4	158.5		
04-15-1997	1038.9	1038.9	158.6	880.3	158.6		
10-29-1997	1038.9	1038.9	162.8	876.1	162.8		
04-07-1998	1038.9	1038.9					6

Well Coordinates

Projection	Datum	Easting	Northing	Units
UTM	NAD27	467774	3770098	metres
LL	NAD27	117.3484	34.0711	decimal degrees

Well Use: Undetermined

For more information contact:
Department of Water Resources, Southern District
Groundwater Section
770 Fairmont Avenue
Glendale, CA 91203

Phone: 818-500-1645, ext. 233
Fax: 818-543-4604

New Search

Search for wells within 0.5 mile radius. Nearby Search

Back to Top of Page

Conditions of Use | Privacy Policy | Comments or Suggestions
© 2008 State of California.

Welcome to California

DWR Home
DPLA Home
Water Data Library Home
Water Quality Data
Groundwater Data
Surface Water Data
Climatology Data
Contacts

DEPARTMENT OF WATER RESOURCES
PLANNING AND LOCAL ASSISTANCE

DWR

Groundwater Level Data, 01S05W24H002S

Your selection returned a total of **7** records. Wells in the Department of Water Resources monitoring r identified by a State Well Number, which is based on the Public Land Grid System. The table heading contain several codes and abbreviations. Press the ***New Search*** or ***Nearby Search*** buttons or at the page to begin a new data retrieval. Data for this well can also be downloaded in MS Excel or text delir

Division of Planning and Local Assistance Department of Water Resources

901 P Street
Sacramento, CA 95814

Mailing Address:
Post Office Box 942836
Sacramento, CA 94236-0001



Groundwater Level Readings

Meas. Date	R.P. Elev.	G.S. Elev.	RPWS	WSE	GSWS	QM Code	NM Cc
06-19-1997	1050.0	1050.0	175.0	875.0	175.0		
07-15-1998	1050.0	1050.0	172.4	877.6	172.4		
10-20-1998	1050.0	1050.0	172.4	877.6	172.4		
04-13-1999	1050.0	1050.0					1
04-14-1999	1050.0	1050.0	170.6	879.4	170.6		
10-19-1999	1050.0	1050.0	173.7	876.3	173.7		
04-18-2000	1050.0	1050.0	173.6	876.4	173.6		

Well Coordinates (NOTE: coordinates for this well have been generalized for homeland security r				
Projection	Datum	Easting	Northing	Units
UTM	NAD27	467600	3770400	metres
LL	NAD27	117.347	34.074	decimal degrees

Well Use: Public Supply

For more information contact:
Department of Water Resources, Southern District
Groundwater Section
770 Fairmont Avenue
Glendale, CA 91203

Phone: 818-500-1645, ext. 233
Fax: 818-543-4604

New Search

Search for wells within 0.5 mile radius. Nearby Search

Back to Top of Page

Conditions of Use | Privacy Policy | Comments or Suggestions
© 2008 State of California.

Upper Santa Ana Valley Groundwater Basin, Riverside-Arlington Subbasin

- Groundwater Basin Number: 8-2.03
- County: San Bernardino, Riverside
- Surface Area: 58,600 acres (92 square miles)

Basin Boundaries and Hydrology

The Riverside-Arlington Subbasin underlies part of the Santa Ana River Valley in northwest Riverside County and southwest San Bernardino County. This subbasin is bound by impermeable rocks of Box Springs Mountains on the southeast, Arlington Mountain on the south, La Sierra Heights and Mount Rubidoux on the northwest, and the Jurupa Mountains on the north. The northeast boundary is formed by the Rialto-Colton fault, and a portion of the northern boundary is a groundwater divide beneath the city of Bloomington. The Santa Ana River flows over the northern portion of the subbasin. Annual average precipitation is about 10 to 14 inches.

Hydrogeologic Information

Water Bearing Formations

Groundwater in the subbasin is found chiefly in alluvial deposits. Quaternary age alluvial deposits in the subbasin consist of sand, gravel, silt, and clay deposited by the Santa Ana River and its tributaries. Near the City of Riverside, the upper 50 feet of deposits are principally clay; however, deposits near the City of Arlington have considerable sand and little clay. At the northern end of the subbasin, coarser gravels with cobbles 4 to 6 inches in diameter are common. Based on data from wells, a minimum specific yield of 15 percent was assigned to unweathered gravels at the extreme northern end of the subbasin. The specific yield increases sharply to 18 percent near the Santa Ana River, then increases gradually to a maximum of 20 percent near the City of Arlington (DPW 1934).



Restrictive Structures

The Rialto-Colton fault to the northeast separates the Riverside-Arlington Subbasin from Rialto-Colton Subbasin. The fault is a barrier to groundwater flow along of its length, especially in its northern reaches (Wildermuth 2000).

A groundwater divide in the alluvium separates the Riverside portion from the Arlington portion of the subbasin (DPW 1934).

Recharge Areas

The Riverside-Arlington Subbasin is replenished by infiltration from Santa Ana River flow, underflow past the Rialto-Colton fault, intermittent underflow from the Chino Subbasin, return irrigation flow, and deep percolation of precipitation (DPW 1934; Wildermuth 2000).

Groundwater Level Trends

Groundwater moves northwest near Arlington, then flows southwest to Arlington Gap, through which it flows into the Temescal Subbasin (DPW

1934). In the northeastern part of the subbasin, groundwater levels near the Santa Ana River fluctuated about 20 feet during 1985 through 2001 and declined about 10 feet during 1995 through 2000. In the central part of the subbasin near Riverside, groundwater levels were fairly steady during 1965 through 1985, fluctuating about 4 feet.

Groundwater Budget (Type A)

Municipal water pumping from the Riverside portion of the subbasin was about 10,100 af during the 2000-2001 fiscal year (Riverside Public Utilities Department 2002).

Groundwater Storage

Groundwater Storage Capacity. The total storage capacity is estimated to be 243,000 af (DPW 1934). The Riverside portion of the subbasin is estimated to have a storage capacity of about 207,000 af and the Arlington portion, a storage capacity of 36,000 af (DPW 1934).
Groundwater in Storage. No information is available.

Groundwater Quality

Characterization. Water within the Riverside-Arlington Subbasin is dominately calcium-sodium bicarbonate. Water sampled from 46 public supply wells has an average TDS content of 463 mg/L with a range of 210 to 889 mg/L. TDS content ranges from 320 to 756 mg/L (Wildermuth 2000).
Impairments. No information is available.

Water Quality in Public Supply Wells

Constituent Group[1]	Number of wells sampled[2]	Number of wells with a concentration above an MCL[3]
Inorganics – Primary	48	2
Radiological	48	11
Nitrates	51	21
Pesticides	50	19
VOCs and SVOCs	50	8
Inorganics – Secondary	38	3

[1] A description of each member in the constituent groups and a generalized discussion of the relevance of these groups are included in *California's Groundwater – Bulletin 118* by DWR (2003).
[2] Represents distinct number of wells sampled as required under DHS Title 22 program from 1994 through 2000.
[3] Each well reported with a concentration above an MCL was confirmed with a second detection above an MCL. This information is intended as an indicator of the types of activities that cause contamination in a given basin. It represents the water quality at the sample location. It does not indicate the water quality delivered to the consumer. More detailed drinking water quality information can be obtained from the local water purveyor and its annual Consumer Confidence Report.

Well Characteristics

	Well yields (gal/min)	
Municipal/Irrigation	Range:	Range:
	Total depths (ft)	
Domestic	Range:	
Municipal/Irrigation	Range:	

Active Monitoring Data

Agency	Parameter	Number of wells /measurement frequency
USGS	Groundwater levels	11
USGS	Miscellaneous water quality	3
Department of Health Services and cooperators	Title 22 water quality	43

Basin Management

Groundwater management:	City of Riverside manages a portion of the basin under an AB3030 plan.
Water agencies	
Public	Riverside Public Utilities Department
Private	

References Cited

California Department of Public Works, Division of Water Resources (DPW). 1934. *South Coastal Basin Investigation: Geology and Ground Water Storage Capacity of Valley Fill.* Bulletin No. 45. 279 p.

Riverside Public Utilities Department. 2002. *City of Riverside Water Utility Report.* http://www.ci.riverside.ca.us/utilities/water-.PDF. 2 July 2002.

Wildermuth Environmental, Inc. (Wildermuth). 2000. *TIN/TDS Study - Phase 2A of the Santa Ana Watershed; Final Technical Memorandum.* San Clemente, California, July 2000.

Additional References

California Department of Public Works, Division of Water Resources (DPW). 1933. *South Coastal Basin Investigation: Quality of Irrigation Waters.* Bulletin No. 40. 95 p.

_____. 1933. *South Coastal Basin Investigation: Detailed Analyses Showing Quality of Irrigation Waters.* Bulletin No. 40-A. 131 p.

Errata

Substantive changes made to the basin description will be noted here.

Upper Santa Ana Valley Groundwater Basin, Rialto-Colton Subbasin

- Groundwater Basin Number: 8-2.04
- County: Riverside, San Bernardino
- Surface Area: 30,100 acres (47 square miles)

Basin Boundaries and Hydrology

The Rialto-Colton Subbasin underlies a portion of the upper Santa Ana Valley in southwestern San Bernardino County and northwestern Riverside County. This subbasin is bounded by the San Gabriel Mountains on the north, the San Jacinto fault on the east, the Box Spring Mountains on the south, and the Rialto-Colton fault on the west. Lytle Creek drains this part of the valley southeastward to its confluence with the Santa Ana River in the southern part of the subbasin.

Hydrogeologic Information

Water Bearing Formations

Groundwater in the Rialto-Colton Subbasin can be found in alluvial deposits. Specific yield ranges from about 6 percent northwest of Rialto to about 16 percent near Colton (DWR 1934). Groundwater within the subbasin is primarily unconfined to semi-confined (Wildermuth 2000).

Alluvial Deposits.
Water-bearing alluvium consists of gravel, sand, silt, and clay. Holocene age alluvial deposits are found beneath the current courses of Lytle and Cajon Creeks along the eastern part of the subbasin, and the Santa Ana River, which crosses the southern part of the subbasin. These Holocene deposits are typically less compacted and weathered than older deposits and have higher permeability (DWR 1970). Alluvial deposits of Pliocene and Pleistocene age are composed of somewhat compacted and weathered deposits of gravel, sand, silt, and clay in discontinuous lenticular bodies. The coarsest material occurs near the mouth of Lytle Creek and the material becomes finer toward the southeast where the coarsest gravels contain few cobbles. Sorting increases southeastward and deposits of highest permeability are well sorted sands found near the Santa Ana River (DWR 1934; DWR 1970).

Restrictive Structures

The San Jacinto fault, its extension barrier "E", and the Rialto-Colton fault are northwest trending barriers to groundwater movement in this subbasin (DWR 1934; DWR 1970; Wildermuth 2000). The San Jacinto fault displaces water levels about 50 feet in older deposits, but is not a barrier in the youngest materials, particularly beneath the Santa Ana River (DWR 1970). Barrier "E" (Dutcher and Garrett 1963) lies south of the San Jacinto fault and displaces groundwater elevations by about 25 to 50 feet (Wildermuth 2000). The Rialto-Colton fault is a barrier to groundwater flow along much of its length, especially in its northern reaches where groundwater elevations can reach near 400 feet higher within the Rialto-Colton Subbasin than in the Chino Subbasin to the west (Wildermuth 2000). Barrier "J" (Dutcher and Garrett 1963) is a northeast-trending, southward

step in groundwater elevation of about 100 feet in the northern part of the subbasin that may be a barrier to groundwater movement southward (Dutcher and Garrett 1963; Wildermuth 2000) or may be a groundwater cascade (DWR 1970).

Recharge Areas

The principal recharge areas are Lytle Creek in the northwestern part of the subbasin, Reche Canyon in the southeastern part, and the Santa Ana River in the south-central part. Lesser amounts of recharge are provided by percolation of precipitation to the valley floor, underflow, and irrigation and septic returns (DWR 1970; Wildermuth 2000). Underflow occurs from fractured basement rock (DWR 1970; Wildermuth 1970) and through the San Jacinto fault in younger Santa Ana River deposits at the south end of the subbasin (Dutcher and Garrett 1958) and in the northern reaches of the San Jacinto fault system (Wildermuth 2000).

Groundwater Level Trends

Groundwater moves toward the Santa Ana River from Lytle Wash in the northwest, and from Reche Canyon in the southeast (DPW 1934; DWR 1970; Wildermuth 2000). In the northern part of the subbasin, hydrographs show quick rises of water levels during high precipitation years and slower decline towards a baseline level over several years. Years of high precipitation may raise groundwater levels 40 or more feet and the range of water levels through the 1990s for a well is typically about 50 feet. In the southern part of the subbasin, near the Santa Ana River, groundwater levels have been relatively stable through the 1990s, fluctuating between 5 and 10 feet of elevation.

Groundwater Storage

Groundwater Storage Capacity. A total storage capacity of about 210,000 af of groundwater is estimated for this subbasin (DPW 1934). About 120,000 af is estimated for the Rialto portion of the subbasin and about 93,000 af is estimated for the Colton portion (DPW 1934). The total storage capacity has also been estimated at 2,517,000 af (DWR 1986).

Groundwater in Storage. An estimated 1,521,000 af of groundwater was in storage in 1984 (DWR 1986).

Groundwater Budget (Type A)

Extractions for the southern portion of the subbasin were 11,295 af for calendar year 1999 (WSBW 2001).

Groundwater Quality

Characterization. Water sampled from 41public supply wells show an average TDS content of 264 mg/L with a range of 163 to 634 mg/L. Groundwater in this subbasin has a TDS content ranging from 201 to 291 mg/L (DWR 1986) and average of 230 mg/L (Wildermuth 2000).

Impairments. No information is available.

Water Quality in Public Supply Wells

Constituent Group[1]	Number of wells sampled[2]	Number of wells with a concentration above an MCL[3]
Inorganics – Primary	38	0
Radiological	40	0
Nitrates	38	2
Pesticides	40	0
VOCs and SVOCs	40	3
Inorganics – Secondary	38	3

[1] A description of each member in the constituent groups and a generalized discussion of the relevance of these groups are included in *California's Groundwater – Bulletin 118* by DWR (2003).
[2] Represents distinct number of wells sampled as required under DHS Title 22 program from 1994 through 2000.
[3] Each well reported with a concentration above an MCL was confirmed with a second detection above an MCL. This information is intended as an indicator of the types of activities that cause contamination in a given basin. It represents the water quality at the sample location. It does not indicate the water quality delivered to the consumer. More detailed drinking water quality information can be obtained from the local water purveyor and its annual Consumer Confidence Report.

Well Characteristics

	Well yields (gal/min)	
Municipal/Irrigation	Range: to 5,000 gal/min	Average: 545 gal/min
	Total depths (ft)	
Domestic	Range:	Average:
Municipal/Irrigation	Range:	Average:

Active Monitoring Data

Agency	Parameter	Number of wells /measurement frequency
US Geological Survey	Groundwater levels	50
US Geological Survey	Miscellaneous water quality	5
Department of Health Services and cooperators	Title 22 water quality	41

Basin Management

Groundwater management:	The southern portion of the subbasin is managed as part of the adjudicated San Bernardino, Colton, and Riverside basins judgement by the Western-San Bernardino Watermaster.
Water agencies	
Public	Western-San Bernardino Watermaster, Western Municipal Water District, San Bernardino Valley Municipal Water District.
Private	

References Cited

California Department of Public Works, Division of Water Resources (DPW). 1934. *South Coastal Basin Investigation: Geology and Ground Water Storage Capacity of Valley Fill.* Bulletin No. 45. 279 p.

California Department of Water Resources (DWR). 1970. *Meeting Water Demands in the Chino-Riverside Area.* Bulletin 104-3, Appendix A: Water Supply. 108 p.

_____. 1986. *San Bernardino-San Gorgonio: Water Resources Management Investigation.* 83 p.

Dutcher, L. C., and Garrett, A. A. 1958. *Geologic and Hydrologic Features of the San Bernardino Area, California, with Special Reference to Underflow Across the San Jacinto Fault.* U. S. Geological Survey Open-File Report.

_____. 1963. *Geologic and Hydrologic Features of the San Bernardino Area, California.* U. S. Geological Survey Water-Supply Paper 1419.

Wildermuth Environmental, Inc. (Wildermuth). 2000. *TIN/TDS Study - Phase 2A of the Santa Ana Watershed; Final Technical Memorandum.* San Clemente, California, July 2000.

Additional References

June, Laurane. 2000. City of Colton, Oral Communication, December 2000.

Tincher, Robert M. 2000. *Change in Groundwater Storage for the San Bernardino Basin* Area – *Calendar Years 1934 to 1998.* San Bernardino Valley Municipal Water District.

Errata

Substantive changes made to the basin description will be noted here.


Angeles National Forest
184-08
395
15
Hesperia
Angeles National Forest
San Bernardino National Forest
San Bernardino National Forest
San Bernardino National Forest
Uplard
Rancho Cucamonga
San Bernardino
Rialto
Pomona
Ontario International
Fontana
149-08
124-08
Diamond
Chino
Redlands
Chino Hills
122-07
San Bernardino National Forest
San Bernardino National Forest
Riverside
Fullerton
Yorba Linda
San Bernardino National Forest
San Bernardino National Forest
Corona
Moreno Valley
Orange
© 2008 Tele Atlas
Image © 2008 DigitalGlobe
© 2008 Europa Technologies
Google


6-43
7-19
7-15
7-18.02
6-42
7-18.01
7-17
7-48
8-9
7-49
8-8
8-7
-23
8-2.02
8-2.04
8-2.06
7-20
4-13
8-2.01
8-2.07
8-2.03
8-2.08
7-21.02
1.04
8-2.09
7-21.04


117°30'
117°20'
117°10'
117°
34°10'
34°
San Gabriel Mountains
Cajon Pass
San Bernardino Mountains
San Andreas fault zone
Cucamonga fault zone
San Bernardino Basin
RIALTO
FONTANA
Rialto-Colton fault
San Jacinto fault zone
SAN BERNARDINO
COLTON
Jurupa Hills
Crafton Hills
Banning fault
CA
15
10
30
0
5
10
15 KM

Upper Santa Ana Valley Groundwater Basin, Bunker Hill Subbasin

- Groundwater Basin Number: 8-2.06
- County: San Bernardino
- Surface Area: 89,600 acres (120 square miles)

Basin Boundaries and Hydrology

The Bunker Hill Subbasin consists of the alluvial materials that underlie the San Bernardino Valley. This subbasin is bounded by contact with consolidated rocks of the San Gabriel Mountains, San Bernardino Mountains, and Crafton Hills, and by several faults. The southern boundary is the Banning fault, the east boundary is the Redlands fault, the San Andreas fault is roughly the northern boundary, the Glen Helen fault abuts the northwest boundary, and the southwest boundary is the San Jacinto fault. The Santa Ana River, Mill Creek, and Lytle Creek are the main tributary streams in the subbasin (SBVWCD 2000). The range in annual precipitation is 13 to 31 inches.

Hydrogeologic Information

Water Bearing Formations

The water-bearing material in the subbasin consists of Holocene and Pleistocene age alluvial deposits of sand, gravel, and boulders interspersed with deposits of silt and clay. The water-bearing material has been divided into upper and lower aquifers (Hardt and Hutchinson 1980). In the central part of the subbasin, a poorly permeable clay layer separates the aquifers, creating confined conditions in the lower aquifer under about 25 square miles of the valley. Maximum thickness of the upper aquifer is approximately 350 feet, and maximum thickness of the lower aquifer is approximately 650 feet. Groundwater generally converges toward the Santa Ana River in the southwestern part of the subbasin and discharges over the San Jacinto fault at Colton Narrows (USGS 1989). Wells yield up to 5,000 gpm and average about 1,245 gpm. Specific yield of these deposits ranges from 7 – 21 percent and average 13 percent (WE 2000).

Restrictive Structures

The San Andreas fault zone impedes movement of ground water, producing springs and a groundwater level change that marks the fault trace along the northern boundary of the subbasin. The San Jacinto fault forms a strong barrier to groundwater that raises the water table nearly to the surface below the course of the Santa Ana river. The combination of alluvial material with a high water table in a seismically active area creates a hazard for liquifaction. The Redlands and Banning faults also impede ground water movement along the borders of the subbasin (DWR 1986).

Recharge Areas

Recharge to the Bunker Hill Subbasin historically has resulted from infiltration of runoff from the San Gabriel and San Bernardino Mountains. The Santa Ana River, Mill Creek, and Lytle Creek contribute more than 60

percent of the total recharge to the ground-water system (USGS 1989). Lesser contributors include Cajon Creek, San Timoteo Creek, and most of the creeks flowing southward out of the San Bernardino Mountains. The subbasin is also replenished by deep percolation of water from precipitation and resulting runoff, percolation from delivered water, and water spread in streambeds and spreading grounds.

Groundwater Level Trends

In general the far eastern and northwestern portions of the Bunker Hill Subbasin show the largest decreases while the rest of the subbasin shows mostly stable or increasing ground water elevations. Average changes in ground water level elevations between Fall 1998 and Fall 1999 ranged up to an increase of about three feet (SBVWCD 2000).

Groundwater Storage

Groundwater Storage Capacity. Total groundwater storage of the subbasin is 5,976,000 (DWR 1986).

Groundwater in Storage. As of 1998, the total amount of water in storage in the Bunker Hill Subbasin was 5,890,300 (SBVWCD 2000).

Groundwater Budget (Type A)

Pumping data indicate 164,319 af of urban extraction and 23,977 af for water year 1998 (SBVWCD 2000). Natural recharge for 1998 is reported at 23,861 af (SBVWCD 2000) and artificial recharge is reported at 15,835 af (Crowly 2000). DWR (1986) determined an average subsurface inflow to be about 22,500 af.

Groundwater Quality

Characterization. Groundwater within the subbasin is predominately calcium-bicarbonate (USGS 1989) with a TDS range of 150 mg/l to 550 mg/l (DWR 1986). Department of Health Services data for 204 public supply wells show an average TDS content of 324 mg/l, with a range of 155 – 1,140 mg/l. Reported EC measurements range from 95 µmhos – 2,920 µmhos and average 523 µmhos (Vitt 2000).

Impairments. The Bunker Hill Subbasin contains several contamination plumes. The Redlands plume, located between Judson Street and Mountain Avenue in Redlands, is primarily composed of TCE, with lower levels of PCE and DBCP, and contaminates approximately 150,000 acre-ft of groundwater. The Norton Air Force Base plume consists of TCE and PCE. This plume stretches 2 ½ miles long, and contaminates 100,000 acre-ft of groundwater. The Newark and Muscoy plumes are spread around the east and west sides of the Shandon Hills in northern San Bernardino. These plumes consist of TCE and PCE, and are designated Superfund sites. The Santa Fe plume is primarily of petroleum based contaminates. (SBVWCD 2000).

Water Quality in Public Supply Wells

Constituent Group[1]	Number of wells sampled[2]	Number of wells with a concentration above an MCL[3]
Inorganics – Primary	212	13
Radiological	207	34
Nitrates	214	34
Pesticides	211	20
VOCs and SVOCs	211	32
Inorganics – Secondary	212	25

[1] A description of each member in the constituent groups and a generalized discussion of the relevance of these groups are included in *California's Groundwater – Bulletin 118* by DWR (2003).
[2] Represents distinct number of wells sampled as required under DHS Title 22 program from 1994 through 2000.
[3] Each well reported with a concentration above an MCL was confirmed with a second detection above an MCL. This information is intended as an indicator of the types of activities that cause contamination in a given basin. It represents the water quality at the sample location. It does not indicate the water quality delivered to the consumer. More detailed drinking water quality information can be obtained from the local water purveyor and its annual Consumer Confidence Report.

Well Characteristics

	Well yields (gal/min)	
Municipal/Irrigation	Range: to 5,000 gal/min	Average: 1,245 gal/min
	Total depths (ft)	
Domestic	Range:	Average:
Municipal/Irrigation	Range:	Average:

Active Monitoring Data

Agency	Parameter	Number of wells /measurement frequency
City of Colton	Water Levels	14/Annually (SBVWCD 2000)
East Valley Water District	Water Levels	42/Annually (SBVWCD 2000)
Loma Linda University	Water Levels	1/Annually (SBVWCD 2000)
City of Loma Linda	Water Levels	5/Annually (SBVWCD 2000)
Meeks & Daley Water Co.	Water Levels	4/Annually (SBVWCD 2000)
City of Redlands	Water Levels	46/Annually (SBVWCD 2000)
City of Rialto	Water Levels	10/Annually (SBVWCD 2000)
Riverside Highland Water Co	Water Levels	14/Annually (SBVWCD 2000)
City of Riverside	Water Levels	62/Annually (SBVWCD 2000)

San Bernardino Valley Water District	Water Levels	8/Annually (SBVWCD 2000)
City of San Bernardino	Water Levels	58/Annually (SBVWCD 2000)
USGS/SBVMWD	Water Levels	106/Annually (SBVWCD 2000)
West San Bernardino Co. Water District	Water Levels	27/Annually (SBVWCD 2000)
Western Municipal	Water Levels	1/Annually (SBVWCD 2000)
USGS	Water Levels	74
Department of Health Services and cooperators	Title 22 water quality	204
USGS	Water Quality	29
SBVWCD	Water Quality	140/monthly, quarterly

Basin Management

Groundwater management:	Groundwater management in the Bunker Hill Basin is performed by the San Bernardino Valley Water Conservation District, and is based primarily on the maintenance of groundwater levels in the pressure zone. Inflows and outflows are monitored and adjusted so as not to allow water levels to rise to the ground surface in downtown San Bernardino, where the pressure zone exists.(Crowly 2000)
Water agencies	
Public	City of Colton, East Valley Water District, City of Loma Linda, City of Redlands, City of Rialto, City of Riverside, San Bernardino Valley Municipal Water District, City of San Bernardino, West San Bernardino County Water District.
Private	Arroyo Mutual Water Co., Baseline Gardens Mutual Water Co., Bear Valley Mutual Water Co., Bryn Mawr Mutual Water Co., Cardiff Farms Mutual Water Co., Eastwood Farms Community Water, Kansas Street Mutual Water Co., King Street Mutual Water Co., Devore Water Co., Crafton Water Co., J.J. Ramirez Stowe Water Co., Mentone Acres Mutual Water Co., Montecito Mutual Water Co., Muscoy Mutual Water Co., Pioneer Mutual Water Co., City Creek Water Co., Fariview Water Co., Tennessee Mutual Water Co., Victory Farms Mutual Water Co., Fontana Union Water Co., Lugo Water Co., Mascart Water Co., Meeks & Daley Water Co., New England Water Co., Pharaoh-Powell Water Co., Riverside Highland Water Co., San Bernardino Avenue Water Co., Tennessee Water Co., Terrace Water Co. (SBVWCD 2000)

References Cited

California Department of Water Resources (DWR). 1970. *Meeting Water Demands in the Bunker Hill-San Timoteo Area.* Bulletin No. 104-5.

_____ 1986. *San Bernardino-San Gorgonio Water Resources Management Investigation.*

Crowley, Thomas. 2000. San Bernardino Valley Water Conservation District, Oral Communication with B.C Moniz, September 2000.

San Bernardino Valley Water Conservation District (SBVWCD). 2000. *Engineering Investigation of the Bunker Hill Basin 1999-2000.*

United States Geological Survey (USGS). 1989. *Appraisal of Ground- Water Quality in the Bunker Hill Basin of San Bernardino Valley, California.* Water-Resources Investigations Report 88-4203.

Vitt, Peter. 2000. Santa Ana Water Project Authority. Written Communication, September 2000.

Wildermuth Environmental, Inc. (Wildermuth). 2000. *TIN/TDS Study - Phase 2A of the Santa Ana Watershed; Final Technical Memorandum.* San Clemente, California, July 2000.

Additional References

Durbin, Timothy. J. and Charles O. Morgan. 1978. *Well-Response Model of the Confined Area, Bunker Hill Ground-Water Basin, San Bernardino County, California.* United States Geological Survey. Water-Resources Investigations Report 77-129. 39 p.

California Department of Water Resources (DWR). 1959. *Santa Ana River Investigation* Bulletin No. 15. 194 p.

____. 1960. *Upper Santa Ana River Drainage Area Land and Water Use Survey, 1957.* Bulletin No. 71. 51 p.

____. 1966. *Upper Santa Ana River Drainage Area Land and Water Use Survey, 1964.* Bulletin No. 71-64. 76 p.

Eccles, Lawrence A. 1979. *Ground-Water Quality in the Upper Santa Ana River Basin, Southern California.* United States Geological Survey. Water-Resources Investigations Report 79-113. 51 p.

Lofgren, Ben E. 1971. *Estimated Subsidence in the Chino-Riverside and Bunker hill-Yucaipa Areas in Southern California for a Postulated Water-Level Lowering, 1965-2015.* United States Geological Survey. Open-File Report. 19p.

Schaefer, Donald H. and James W. Warner. 1975. *Artificial Recharge in the Upper Santa Ana River Area, San Bernardino County, California.* United States Geological Survey. Water-Resources Investigations Report 15-75. 27 p.

Errata

Substantive changes made to the basin description will be noted here.



APPROXIMATE SCALE IN FEET

500 0 500

NATIONAL FLOOD INSURANCE PROGRAM

FIRM

FLOOD INSURANCE RATE MAP

SAN BERNARDINO COUNTY, CALIFORNIA AND INCORPORATED AREAS

PANEL 8678 OF 9400

(SEE MAP INDEX FOR PANELS NOT PRINTED)

CONTAINS:

COMMUNITY	NUMBER	PANEL	SUFFIX
COLTON, CITY OF	060273	8678	F
RIALTO, CITY OF	060280	8678	F
SAN BERNARDINO COUNTY, UNINCORPORATED AREAS	060270	8678	F
SAN BERNARDINO, CITY OF	060281	8678	F

MAP NUMBER
06071C8678 F

EFFECTIVE DATE:
MARCH 18, 1996

Federal Emergency Management Agency

This is an official copy of a portion of the above referenced flood map. It was extracted using F-MIT On-Line. This map does not reflect changes or amendments which may have been made subsequent to the date on the title block. For the latest product information about National Flood Insurance Program flood maps check the FEMA Flood Map Store at www.msc.fema.gov



NOTE: WELLS WITH DIRECTIONAL SURVEYS ON FILE WITH THE DIVISION OF OIL AND GAS ARE INDICATED WITH A SHORT LINE UNDER THE WELL SYMBOL.

CURRENT WELL STATUS SHOULD BE CONFIRMED AT THE APPROPRIATE DIVISION OF OIL AND GAS DISTRICT OFFICE

LEGEND

- DRILLING
- DRILLING-IDLE
- 78-6789 PLUGGED AND ABANDONED-DRY HOLE (Showing year drilled and total depth)
- COMPLETED-OIL
- IDLE-OIL
- PLUGGED AND ABANDONED-OIL
- COMPLETED-GAS
- IDLE-GAS
- PLUGGED AND ABANDONED-GAS
- GAS-OPEN TO OIL ZONE
- COMPLETED WATER SOURCE
- COMPLETED WATER DISPOSAL
- COMPLETED WATER FLOOD
- COMPLETED STEAM FLOOD
- FIELD BOUNDARY
- FIELD MAP BOUNDARY
- PRODUCTIVE LIMITS
- BURIED IDLE
- OBSERVATION

REGIONAL WILDCAT MAP

SHOWING WELLS NOT ON
DIVISION of OIL and GAS FIELD MAPS

STATE OF CALIFORNIA
DEPARTMENT OF CONSERVATION
DIVISION OF OIL, GAS, AND GEOTHERMAL RESOURCES

SCALE IN FEET
0 4000 8000 12000

JANUARY 22, 2000

DIVISION OF OIL, GAS, AND GEOTHE
801 K STREET, MS 20, SACRAM. NTO, CAL

W 1-4 ORANGE, RIVERSIDE, SAN BERNARDINO COUNT


6
5
4
3
2
1
7
FONTANA
8
9
10
11
12
18
17
16
15
14
13
T1S R5W
19
20
21
22
23
24
BLOOMINGTON
Colton Terrace Oil Co
1 24-1799
30
29
28
27
26
25
John W. Brashears
"Dana"
1 54-3290
31
32
33
34
35
36
6
5
4
3
2
1
7
8
9
10
11
12

REGIONAL
WILDCAT MAP

SHOWING WELLS NOT ON
DIVISION OF OIL & GAS FIELD MAPS
STATE OF CALIFORNIA
DEPARTMENT OF CONSERVATION
DIVISION OF OIL, GAS, AND GEOTHERMAL RESOURCES



MARCH 4, 2000

LEGEND

- DRILLING
- DRILLING - IDLE
- 67-2613 PLUGGED AND ABANDONED - DRY HOLE (showing year drilled and total depth)
- PRODUCING - OIL
- IDLE - OIL
- PLUGGED AND ABANDONED - OIL
- PRODUCING - GAS
- IDLE - GAS
- PLUGGED AND ABANDONED - GAS
- WATER SOURCE
- $_{G}$ GAS INJECTION
- $_{S}$ STEAM FLOOD
- WATER DISPOSAL
- BURIED IDLE
- OBSERVATION

BOUNDARY OF FIELD MAP COVERAGE
FIELD BOUNDARY

100,000-foot grid based on California coordinate system, zone 6

NOTE: WELLS WITH DIRECTIONAL SURVEYS ON FILE WITH THE DIVISION OF OIL AND GAS ARE INDICATED WITH A SHORT LINE UNDER THE WELL SYMBOL.

CURRENT WELL STATUS SHOULD BE CONFIRMED AT THE APPROPRIATE DIVISION OF OIL AND GAS DISTRICT OFFICE

DIVISION OF OIL, GAS, AND GEOTHERMAL RESOURCES
801 K STREET, MS 20, SACRAMENTO, CALIFORNIA 95814

W1-7


SAN BERNARDINO
Board of Water Commissioner City of S.B. "Mill B.D."
City of San Bernardino "Meeks & Daly"
City of San Bernardino "TG"
San Bernardino & Colton Oil Co.
R.A. Dean & Associates "Higgs"
COLTON
LOMA LINDA
City of Loma Linda "L.L."
REDLANDS
YUCAIPA
Floyd Amundson 26-213
Kennedy Land Co "Sarah Elizabeth" 90-3334
Midway Oil Syn 26-5368
The Cheney Oil Lease Syn 27-1950
Alberta Oil Co 33-3180
Perri Oil Co "Reid" 56-3711
53-1332
54-513
S V Smith "Haskell"
Beaumont Exploration Co "John Drew" 53-2215
Riverside County Oil Co 21-2162
BEAUMONT
BANNING
Morana Oil Co 23-1700
L E Smith 25-350
L W Rippeto 21-1263
Nuevo Oil Co 28-2225
San Gorgonio River
San Jacinto River
San Jacinto Res
PERRIS
SAN JACINTO
Wonder Oil Co "Strok" 42-2800
Hemet Pet Corp 31-3625
HEMET
Ella Chisholm Dorn 50-216
Pioneer Oil Syn
66
91
10
60
395
79
74
W1-4

APPENDIX D

EDR HISTORICAL REPORTS

PETRA

The EDR Aerial Photo Decade Package

Colton Super Block
San Bernardino Avenue/North Pepper
Colton, CA 92324

Inquiry Number: 2165111.5

March 14, 2008

EDR® Environmental Data Resources Inc

The Standard in Environmental Risk Information

440 Wheelers Farms Road
Milford, Connecticut 06461

Nationwide Customer Service

Telephone: 1-800-352-0050
Fax: 1-800-231-6802
Internet: www.edrnet.com

EDR Aerial Photo Decade Package

Environmental Data Resources, Inc. (EDR) Aerial Photo Decade Package is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDRs professional researchers provide digitally reproduced historical aerial photographs, and when available, provide one photo per decade.

When delivered electronically by EDR, the aerial photo images included with this report are for ONE TIME USE ONLY. Further reproduction of these aerial photo images is prohibited without permission from EDR. For more information contact your EDR Account Executive.

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report AS IS. Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2008 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

Date EDR Searched Historical Sources:

Aerial Photography March 14, 2008

Target Property:

San Bernardino Avenue/North Pepper Avenue
Colton, CA 92324

Year	*Scale*	*Details*	*Source*
1930	Aerial Photograph. Scale: 1"=800'	Flight Year: 1930	Fairchild
1938	Aerial Photograph. Scale: 1"=800'	Flight Year: 1938	Laval
1953	Aerial Photograph. Scale: 1"=800'	Flight Year: 1953	Southwestern
1966	Aerial Photograph. Scale: 1"=800'	Flight Year: 1966	Universe
1978	Aerial Photograph. Scale: 1"=800'	Flight Year: 1978	Teledyne
1989	Aerial Photograph. Scale: 1"=800'	Flight Year: 1989	USGS
1995	Aerial Photograph. Scale: 1"=800'	Flight Year: 1995	USGS
2002	Aerial Photograph. Scale: 1"=800'	Flight Year: 2002	USGS


INQUIRY #: 2165111.5
YEAR: 1930
= 800'
N

INQUIRY #: 2165111.5
YEAR: 1938
= 800'
N

INQUIRY #: 2165111.5
YEAR: 1953
= 800'
N



INQUIRY #: 2165111.5

YEAR: 1966

= 800'

N

INQUIRY #: 2165111.5

YEAR: 1978

= 800'

N



INQUIRY #: 2165111.5

YEAR: 1989

= 800'

N



INQUIRY #: 2165111.5

YEAR: 1995

= 800'

N



INQUIRY #: 2165111.5

YEAR: 2002

= 800'

N

EDR Historical Topographic Map Report

Colton Super Block
San Bernardino Avenue/North Pepper Avenue

Colton, CA 92324

Inquiry Number: 2165111.4

March 12, 2008

EDR® Environmental Data Resources Inc

The Standard in Environmental Risk Information

440 Wheelers Farms Rd
Milford, Connecticut 06461

Nationwide Customer Service

Telephone: 1-800-352-0050
Fax: 1-800-231-6802
Internet: www.edrnet.com

EDR Historical Topographic Map Report

Environmental Data Resources, Inc.s (EDR) Historical Topographic Map Report is designed to assist professionals in evaluating potential liability on a target property resulting from past activities. EDRs Historical Topographic Map Report includes a search of a collection of public and private color historical topographic maps, dating back to the early 1900s.

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report AS IS. Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2008 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

Historical Topographic Map



N	TARGET QUAD NAME: SAN BERNARDINO MAP YEAR: 1901 SERIES: 15 SCALE: 1:62500	SITE NAME: Colton Super Block ADDRESS: San Bernardino Avenue/North Pepper Avenue Colton, CA 92324 LAT/LONG: 34.0733 / 117.35	CLIENT: Petra Geotechnical Inc CONTACT: Callie Cullum INQUIRY#: 2165111.4 RESEARCH DATE: 03/12/2008

Historical Topographic Map



N	TARGET QUAD NAME: SOUTHERN CA SHEET 1 MAP YEAR: 1901 SERIES: 60 SCALE: 1:250000	SITE NAME: Colton Super Block ADDRESS: San Bernardino Avenue/North Pepper Avenue Colton, CA 92324 LAT/LONG: 34.0733 / 117.35	CLIENT: Petra Geotechnical Inc CONTACT: Callie Cullum INQUIRY#: 2165111.4 RESEARCH DATE: 03/12/2008

Historical Topographic Map



N	TARGET QUAD NAME: SAN BERNARDINO MAP YEAR: 1954 SERIES: 15 SCALE: 1:62500	SITE NAME: Colton Super Block ADDRESS: San Bernardino Avenue/North Pepper Avenue Colton, CA 92324 LAT/LONG: 34.0733 / 117.35	CLIENT: Petra Geotechnical Inc CONTACT: Callie Cullum INQUIRY#: 2165111.4 RESEARCH DATE: 03/12/2008

Historical Topographic Map



N	TARGET QUAD NAME: SAN BERNARDINO SOUTH MAP YEAR: 1954 SERIES: 7.5 SCALE: 1:24000	SITE NAME: Colton Super Block ADDRESS: San Bernardino Avenue/North Pepper Avenue Colton, CA 92324 LAT/LONG: 34.0733 / 117.35	CLIENT: Petra Geotechnical Inc CONTACT: Callie Cullum INQUIRY#: 2165111.4 RESEARCH DATE: 03/12/2008

Historical Topographic Map



N	TARGET QUAD NAME: SAN BERNARDINO SOUTH MAP YEAR: 1967 SERIES: 7.5 SCALE: 1:24000	SITE NAME: Colton Super Block ADDRESS: San Bernardino Avenue/North Pepper Avenue Colton, CA 92324 LAT/LONG: 34.0733 / 117.35	CLIENT: Petra Geotechnical Inc CONTACT: Callie Cullum INQUIRY#: 2165111.4 RESEARCH DATE: 03/12/2008

Historical Topographic Map



N	TARGET QUAD NAME: SAN BERNARDINO SOUTH MAP YEAR: 1973 PHOTOREVISED FROM:1967 SERIES: 7.5 SCALE: 1:24000	SITE NAME: Colton Super Block ADDRESS: San Bernardino Avenue/North Pepper Avenue Colton, CA 92324 LAT/LONG: 34.0733 / 117.35	CLIENT: Petra Geotechnical Inc CONTACT: Callie Cullum INQUIRY#: 2165111.4 RESEARCH DATE: 03/12/2008

Historical Topographic Map



N	TARGET QUAD NAME: SAN BERNARDINO SOUTH MAP YEAR: 1980 PHOTOREVISED FROM:1967 SERIES: 7.5 SCALE: 1:24000	SITE NAME: Colton Super Block ADDRESS: San Bernardino Avenue/North Pepper Avenue Colton, CA 92324 LAT/LONG: 34.0733 / 117.35	CLIENT: Petra Geotechnical Inc CONTACT: Callie Cullum INQUIRY#: 2165111.4 RESEARCH DATE: 03/12/2008

Historical Topographic Map



N	ADJOINING QUAD NAME: FONTANA MAP YEAR: 1967 SERIES: 7.5 SCALE: 1:24000	SITE NAME: Colton Super Block ADDRESS: San Bernardino Avenue/North Pepper Avenue Colton, CA 92324 LAT/LONG: 34.0733 / 117.35		CLIENT: Petra Geotechnical Inc CONTACT: Callie Cullum INQUIRY#: 2165111.4 RESEARCH DATE: 03/12/2008	

Historical Topographic Map



N	ADJOINING QUAD	SITE NAME:	Colton Super Block	CLIENT:	Petra Geotechnical Inc
	NAME: FONTANA	ADDRESS:	San Bernardino Avenue/North Pepper Avenue	CONTACT:	Callie Cullum
	MAP YEAR: 1973		Colton, CA 92324	INQUIRY#:	2165111.4
	PHOTOREVISED FROM:1967	LAT/LONG:	34.0733 / 117.35	RESEARCH DATE:	03/12/2008
	SERIES: 7.5				
	SCALE: 1:24000				

Historical Topographic Map



N	ADJOINING QUAD NAME: FONTANA MAP YEAR: 1980 PHOTOREVISED FROM:1967 SERIES: 7.5 SCALE: 1:24000	SITE NAME: Colton Super Block ADDRESS: San Bernardino Avenue/North Pepper Avenue Colton, CA 92324 LAT/LONG: 34.0733 / 117.35	CLIENT: Petra Geotechnical Inc CONTACT: Callie Cullum INQUIRY#: 2165111.4 RESEARCH DATE: 03/12/2008

Certified Sanborn® Map Report

Sanborn® Library search results
Certification # 7FC4-4B07-BE48

Colton Super Block
San Bernardino Avenue/North Pepper Avenue
Colton, CA 92324

Inquiry Number 2165111.3s

March 11, 2008

The Standard in Environmental Risk Information

440 Wheelers Farms Rd
Milford, Connecticut 06461

Nationwide Customer Service

Telephone: 1-800-352-0050
Fax: 1-800-231-6802
Internet: www.edrnet.com

Certified Sanborn® Map Report

3/11/08

Site Name:
Colton Super Block
San Bernardino Avenue/North
Colton, CA 92324

EDR Inquiry # 2165111.3s

Client Name:
Petra Geotechnical Inc
3185-A Airway Avenue
Costa Mesa, CA 92626

Contact: Callie Cullum

EDR® Environmental Data Resources Inc

The complete Sanborn Library collection has been searched by EDR, and fire insurance maps covering the target property location provided by Petra Geotechnical Inc were identified for the years listed below. The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by Sanborn Library LLC, the copyright holder for the collection.

Certified Sanborn Results:

Site Name: Colton Super Block
Address: San Bernardino Avenue/North Pepper Avenue
City, State, Zip: Colton, CA 92324
Cross Street:
P.O. # 149-08
Project: Colton Super BI
Certification # 7FC4-4B07-BE48

Sanborn® Library search results
Certification # 7FC4-4B07-BE48

UNMAPPED PROPERTY

This report certifies that the complete holdings of the Sanborn Library, LLC collection have been searched based on client supplied target property information, and fire insurance maps covering the target property were not found.

The Sanborn Library includes more than 1.2 million Sanborn fire insurance maps, which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ☑ Library of Congress
- ☑ University Publications of America
- ☑ EDR Private Collection

Total Maps: 0

Limited Permission To Make Copies

Petra Geotechnical Inc (the client) is permitted to make up to THREE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2008 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

The EDR-City Directory
Abstract

Colton Super Block
San Bernardino Avenue/North Pepper Avenue
Colton, CA 92324
Inquiry Number: 2165111.6

Latitude = 34.0733
Longitude = 117.35

Friday, March 28, 2008

EDR® Environmental Data Resources Inc

The Standard in Environmental Risk Information

440 Wheelers Farms Road
Milford, Connecticut 06461

Nationwide Customer Service

Telephone: 1-800-352-0050
Fax: 1-800-231-6802
Internet: www.edrnet.com

EDR City Directory Abstract

Environmental Data Resources, Inc.'s (EDR) City Directory Abstract is a screening report designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Abstract includes a search and abstract of available city directory data. For each address, the directory lists the name of the corresponding occupant at five year intervals.

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction orforecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2008 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

SUMMARY

- ***City Directories:***

Business directories including city, cross reference and telephone directories were reviewed, if available, at approximately five year intervals for the years spanning 1922 through 2003. (These years are not necessarily inclusive.) A summary of the information obtained is provided in the text of this report.

This report compiles information by geocoding the subject properties (that is, plotting the latitude and longitude for such subject properties and obtaining data concerning properties within 1980 Feet of the subject properties). There is no warranty or guarantee that geocoding will report or list all properties within the specified radius of the subject properties and any such warranty or guarantee is expressly disclaimed. Accordingly, some properties within the aforementioned radius and the information concerning those properties may not be referenced in this report.

Date EDR Searched Historical Sources: March 28, 2008

Target Property:
San Bernardino Avenue/North Pepper Avenue
Colton, CA 92324

Year	Uses	Source
1922	Address Not Listed in Research Source	Los Angeles Directory Co Publisher
1923	Address Not Listed in Research Source	Los Angeles Directory Company
1926	Address Not Listed in Research Source	Los Angeles Directory Company
1930	Address Not Listed in Research Source	San Bernardino Directory Co.
1931	Address Not Listed in Research Source	Los Angeles Directory Co.
1934	Address Not Listed in Research Source	Los Angeles Directory Co.
1936	Address Not Listed in Research Source	San Bernardino Directory Co.
1938	Address Not Listed in Research Source	Los Angeles Directory Co.
1940	Address Not Listed in Research Source	Los Angeles Directroy Co Publisher
1941	Address Not Listed in Research Source	Associated Telephone Company Limited
1942	Address Not Listed in Research Source	San Bernardino Directory Co.
1945	Address Not Listed in Research Source	Southern California Telephone Company
1946	Address Not Listed in Research Source	Los Angeles Directory Company Publishers
1949	Address Not Listed in Research Source	San Bernardino Directory Co. Publishers
1950	Address Not Listed in Research Source	The Pacific Telephone and Telegraph Co
1951	Address Not Listed in Research Source	Los Angeles Directory Company Publishers

Year	Uses	Source
1955	Address Not Listed in Research Source	The Pacific Telephone and Telegraph Co
1956	Address Not Listed in Research Source	General Telephone Company Publishers
1960	Address Not Listed in Research Source	Luskey Brothers & Co Publishers
1961	Address Not Listed in Research Source	Luskey Brothers& Co Publishers
1964	Address Not Listed in Research Source	Luskey Brothers & Co
1965	Address Not Listed in Research Source	GTE
1970	Address Not Listed in Research Source	General Telephone Company of California
1975	Address Not Listed in Research Source	General Telephone Company of California
1980	Address Not Listed in Research Source	GTE General Telephone Company of California
1981	Address Not Listed in Research Source	General Telephone Company of California
1985	Address Not Listed in Research Source	GTE
1990	Address Not Listed in Research Source	GTE California Incorporated
1991	Address Not Listed in Research Source	GTE California Incorporated
1995	Address Not Listed in Research Source	GTE Directories
1996	Address Not Listed in Research Source	GTE
2002	Address Not Listed in Research Source	SBC PACIFIC BELL
2003	Address Not Listed in Research Source	Haines & Co Publishers

Adjoining Properties

SURROUNDING

Multiple Addresses
Colton, CA 92324

Year	Uses	Source

Year	Uses	Source
1922	Address Not Listed in Research Source	Los Angeles Directory Co Publisher
1923	Address Not Listed in Research Source	Los Angeles Directory Company
1926	Address Not Listed in Research Source	Los Angeles Directory Company
1930	Address Not Listed in Research Source	San Bernardino Directory Co.
1931	Address Not Listed in Research Source	Los Angeles Directory Co.
1934	Address Not Listed in Research Source	Los Angeles Directory Co.
1936	Address Not Listed in Research Source	San Bernardino Directory Co.
1938	Address Not Listed in Research Source	Los Angeles Directory Co.
1940	Address Not Listed in Research Source	Los Angeles Directroy Co Publisher
1941	****VALLEY BLVD****	Associated Telephone Company Limited
	BEESON EDGAR L R (1408)	
	HONEY BUN INN (1503)	
	PEACHS RANCHO MKT (1648)	
	KOHN PHIL G R (1674)	
1942	Address Not Listed in Research Source	San Bernardino Directory Co.
1945	****E VALLEY BLVD****	Southern California Telephone Company
	SARGENT JOE R (1568)	
	****HERMOSA AVE****	Southern California Telephone Company
	KNOPSNYDER I M MRTURY (404)	
	RES (404)	
	****VALLEY BLVD****	Southern California Telephone Company
	ROEMER WALTER C R (1732)	
	****W VALLEY BLVD****	Southern California Telephone Company
	SWDN I SNOWDENS LOCKER SERV (1475)	
	ELKIN WM (1740)	
	****VALLEY BLVD****	Southern California Telephone Company
	TOMPKIS SARA B (1542)	
1946	****HERMOSA AVE****	Los Angeles Directory Company Publishers
	FAULKNER IRIS M R (636)	
	FAULKNER VINCENT S ETHEL RANCHER H (636)	

Year	Uses	Source
1949	Address Not Listed in Research Source	San Bernardino Directory Co. Publishers
1950	**N CYPRESS WAY**	The Pacific Telephone and Telegraph Co
	NASH EMMA R (952)	
	W VALLEY BLVD	The Pacific Telephone and Telegraph Co
	BLEDSOE LUTHER A R (1245)	
	FINDLING L A R (1310)	
	SNOWDEN H I SNOWDENS LOCKER SERV (1475)	
	SNOWDENS LOCKER SERV (1475)	
	KERR ARTHUR W R (1626)	
	RYLANDER C A R (1701)	
	OLMSTEAD CLARENCE R (1720)	
	W VALLEY	The Pacific Telephone and Telegraph Co
	FOOTE LOUIS R (1243)	
	RAWLS R R R (1244)	
	BEARD WALLACE F R (1250)	
	LOBESKI JARECKI ISABELLE MRS R (1348)	
	LUCKY SPOT CAFE (1420)	
	DINOFF MIKE R (1440)	
	CADOTTE IRA E R (1476)	
	HONEY BUN INN (1503)	
	SHANKS E W R (1541)	
	FERNAUDEZ MARIO R (1576)	
	MERRILLL KENNETH R (1693)	
	DICKS TAVERN (1727)	
	ODA JAS R (1733)	
	VALLEY BLVD	The Pacific Telephone and Telegraph Co
	TOMPKINS SARA B R (1542)	
1951	**HERMOSA AVE**	Los Angeles Directory Company Publishers
	LANNON C H (249)	
	HILANSEN W F (434)	
	E C ST	Los Angeles Directory Company Publishers
	VESTAL WM LY (1135)	
	FORESTER R D (1137)	
	ROBERTS ROBT LY (1141)	
	HAYNE M E LY (1151)	
	SAN BERNARDINO AVE	Los Angeles Directory Company Publishers
	SMITH FPW (1601)	
1955	Address Not Listed in Research Source	The Pacific Telephone and Telegraph Co
1956	Address Not Listed in Research Source	General Telephone Company Publishers

Year	Uses	Source
1960	Address Not Listed in Research Source	Luskey Brothers & Co Publishers
1961	**REXFORD**	Luskey Brothers& Co Publishers
	RH JONES (250)	
	OE PARSONS (258)	
	HH DEAN (264)	
	VACANT (270)	
	VACANT (280)	
	VACANT (288)	
1964	Address Not Listed in Research Source	Luskey Brothers & Co
1965	Address Not Listed in Research Source	GTE
1970	**N MERIDIAN ST**	General Telephone Company of California
	MR TEES GOLF COURSE (243)	
	ALEXANDER DON (504)	
	ROBINSON ANNE J (570)	
	PRATER ARTHUR L (655)	
	MINDLE BERTHA (676)	
	SMITH DEWEY B (704)	
	KING R D (732)	
	JOHNSTON M (740)	
	MORA FEMANDO (748)	
	REYES AGUSTIN (764)	
	SANTOYO ANGELA (844)	
	SANTOYO TRINIDAD MI (844)	
	KOHNER BRUNO (861)	
	SOELLER EDGAR A (883)	
	COOK JOS W (1108)	
	PARMENTER GEO (1147)	
	W MAGNOLIA DR	General Telephone Company of California
	LOPEZ GLORIA (1335)	
	GUTIERREZ TIOFILA F (1336)	
	SIMPSON ALVIN (1341)	
	MERIDIAN WAY	General Telephone Company of California
	TOHILL G O (694)	
	WESTERSON W E (1134)	
	N PEPPER DR	General Telephone Company of California
	SPIKES EDNA (727)	
	TAYLOR EMERY G (867)	

Year	Uses	Source
1975	**S VALLEY BLVD**	General Telephone Company of California
	FRYREAR FRANK D JR (1722)	
	W C	General Telephone Company of California
	SIGAFOOS STUART (1145)	
	TAYLOR IDA (1155)	
	GRIMES KENNETH REV (1165)	
	VOSBURG LAVERNE M (1175)	
	LAWRENCE LESLIE E (1227)	
	MUDD JOHN (1255)	
	ODD FELLOW REBEKAH TEMPLE (1275)	
	W VALLEY BLVD	General Telephone Company of California
	PEPPER & VALLEY MOBIL SERVICE (1601)	
	W VALLEY	General Telephone Company of California
	MAINTENANCE OPERATIONS & WAREHOUSE (1313)	
	COLTON JOINT UNIFIED SCHOOL DISTRICT DISTRICT ADMINISTRATIVE (1313)	
	COLTON PIANO CO ORGAN DIV (1405)	
	COLTON PIANO CO (1405)	
	BOBS PEPPER & VALLEY SHELL (1600)	
	ELLIS TOYOTA (1700)	
	ELLIS TOYOTA RECREATIONAL VEHICLES (1700)	
	HERMOSA CT	General Telephone Company of California
	HARRING ALBERT G (625)	
	SAN BERNARDINO AVE	General Telephone Company of California
	DYKE WM E JR (1407)	
	MORRELL CHAS T (1417)	
	OTTA MARY (1441)	
	WILHELM FRANK J (1457)	
	ERLEWINE NANCY A (1475)	
	WIENCEK STEPHEN (1479)	
	SKAAR ALBERT K (1500)	
	MALONE JACK E (1504)	
	GREEN PAUL H (1507)	
	WHITESIDE BILL (1521)	
	BUSINESS (1528)	
	MARRAMBA A J DC (1528)	
	ALLEN JAS O DR (1528)	
	AUERBACH JEROME DC (1528)	
	CORNFORTH JAS O (1532)	
1980	**W C ST**	GTE General Telephone Company of California
	O ONTARIO CEMETRY ASSN (1240)	
1981	**ACACIA DR**	General Telephone Company of California

Year	Uses	Source
1981	(continued)	
	WEST ROBT P (852)	
1985	**W C ST**	GTE
	ONTARIO CEMETRY ASSN (1240)	
1990	**HERMOSA AVE**	GTE California Incorporated
	MAUTNER ROBT JOEL (545)	
	MAUST WILLARD J (545)	
	SAN BERNARDINO AVE	GTE California Incorporated
	GLICKAUF L H (1407)	
	ALDOUS GINA (1455)	
	DAY A (1457)	
	DAWSONS ACTION CARPET & UPHOLSTERY CLEANING LA VRN (1457)	
	DAWSON TOM (1457)	
	GERSON L H (1507)	
	CHAVARRIA C (1519)	
	CHAVARRIA B (1519)	
	ALLEN JAS D DR (1528)	
	BUSINESS (1528)	
	ALLEN CHIROPRACTIC CORP (1528)	
	MCDONALD LINN S (1528)	
1991	**N C ST**	GTE California Incorporated
	EVANS MILDRED D (1139)	
	GRINDER SHOP (1807)	
	N MERIDIAN ST	GTE California Incorporated
	DALY JAS (243)	
	W C	GTE California Incorporated
	LEON MIKE & BARBARA (1165)	
	ODD FELLOW REBEKAH TEMPLE (1275)	
	W SAN BERNARDINO AVE	GTE California Incorporated
	FREEMAN BOB (1450)	
	CORTEZ JOSE REV (1471)	
	W VALLEY BLVD	GTE California Incorporated
	MAINTENANCE OPERATIONS & WAREHOUSE (1313)	
	COLTON JOINT UNIFIED SCHOOL DISTRICT (1313)	
	MOVIELAND FRONTIER TOWN GENL MGR (1317)	
	FRONTIER TOWN WEDDING CHAPEL (1317)	
	MOVIELAND FRONTIER TOWN GENERAL STORE (1349)	
	ROOKIES BASEBALL CARDS THE (1357)	
	MADELINES ULDE TYME CONFECTIONS (1365)	
	TETON TRADING POST AND LEATHER EMPORIUM (1367)	
	ULTIMATE FITNESS 2001 (1369)	

Year	Uses	Source
1991 (continued)		
	UIRICH LAWRENCE & LENORA (1369)	
	COLTON PIANO CO ORGAN DIV (1405)	
	COLTON PIANO CO (1405)	
	HAGGAG SHELL (1600)	
	BAKERS BURGERS (1620)	
	JACOBSEN TRAILER INC (1630)	
	B & G AUTO SALES (1630)	
	IF NO ANSWER CALL (1630)	
	****W VALLEY ST****	GTE California Incorporated
	HORSE CONNECTION THE (1317)	
	NICKELODEON PIZZA PASTA & PLEASIN FOOD (1351)	
	AMERICAN WEST (1373)	
	MAVERICK MARINE (1595)	
	INLAND EMPIRE TOYOTA (1700)	
	TOYOTA SALES & SERVICE (1700)	
	****HERMOSA AVE****	GTE California Incorporated
	PARKHOUSE TIRE INC (295)	
	SLOVER MOUNTAIN CONTINUATION (325)	
	COLTON HIGH (325)	
	HARRING ALBERT G (625)	
1995	Address Not Listed in Research Source	GTE Directories
1996	Address Not Listed in Research Source	GTE
2002	****W C ST****	SBC PACIFIC BELL
	YOUNG CLOREA (1225)	
	SIMPKINS ANNETTE (1227)	
	LEWIS MARCELLA (1227)	
	JONES LINDA (1245)	
	JONES LINDA M (1245)	
	GAMBRO HEALTH CARE OF C (1275)	
	****W SAN BERNARDINO AVE****	SBC PACIFIC BELL
	CORTEZ JOSE REV (1471)	
	****BEL CANTO CT****	SBC PACIFIC BELL
	ROSS JAMIE D (1063)	
	****HERMOSA AVE****	SBC PACIFIC BELL
	ACACIARV (295)	
	****VALLEY BLVD W****	SBC PACIFIC BELL
	PIANO CITY (1405)	
	CALIFORNIA AUTO SPECIALIST (1595)	
	HAGGAG SHELL (1600)	

Year	Uses	Source
2002 (continued)		
	BAKERS BURGERS (1620)	
	B&GAUTO SALES (1630)	
	****VALLEY BLVD****	SBC PACIFIC BELL
	SPAS PLUS (1295)	
	****PEPPER AVE****	SBC PACIFIC BELL
	TEXAS WESLEYAN UNIVERSITY (400)	
	SAN BERNARDINO COUNTY OF (400)	
	MCNEILUS TRUCK (401)	
	MANUFACTURING INC (401)	
	CHURCH OF JESUS CHRIST OF (791)	
	LATTER DAY SAINTS (791)	
	LATTER DAY SAINTS (791)	
	CHURCH OF JESUS CHRIST OF (791)	
	LOS FAMILYSVC (791)	
2003	****W C ST****	Haines & Co Publishers
	ALANIS ROBED (1145)	
	XXXX (1155)	
	BOOHERSTEVEN (1165)	
	DE ROSAS MANUEL MRS (1175)	
	DEROSAS MANUEL (1175)	
	RAMOS MANUEL (1175)	
	X HERMOSA AV N (1175)	
	YOUNG CREA (1225)	
	CHAPMAN RALPH (1225)	
	XXXX (1227)	
	JONES LINDA M (1245)	
	JONES LINDA (1245)	
	JAQUEZJORGE (1265)	
	DIALYSIS CENTER OF (1275)	
	COLTON GAMBRO HEALTH (1275)	
	CARE OF COLTON (1275)	
	****W SAN BERNARDINO AVE****	Haines & Co Publishers
	CORTEZJOSE REV (1471)	
	X PEPPER AV N (1500)	
	X CANTARA N (1500)	
	XXXX (1500)	
	WEALTH CODE (1595)	
	****W VALLEY BLVD****	Haines & Co Publishers
	XXXX (1295)	
	XXXX (1311)	
	OPRTNS&WRHS (1313)	
	COLTONSC (1313)	

Year	Uses	Source
2003	(continued)	
	XXXX (1317)	
	XXXX (1349)	
	XXXX (1353)	
	X MERIDIAN (1355)	
	XXXX (1355)	
	SCHAFERALBERTA (1405)	
	XXXX (1500)	
	MORRISON DONALD (1595)	
	CA AUTO UPHOL (1595)	
	SPECIALIST (1595)	
	CALIFORNIA AUTO (1595)	
	X PEPPER AV N (1600)	
	HAGGAG (1600)	
	BAKERS BURGERS (1620)	
	X REXFORD N (1630)	
	B&G AUTO SALES (1630)	
	****HERMOSA AVE****	Haines & Co Publishers
	VALENCIA COMMONS (203)	
	TOUSSAINT ML (203)	
	VILLAREALBRENDA (203)	
	VILLANUEVA KAREEN (203)	
	WATTS WINNIFRED (203)	
	VANTREESE CHARLES D (203)	
	YOUNG LOMRNE A (203)	
	COFFEEN CHARLES S (205)	
	TATUM PEARL (211)	
	TATUM FRANK (211)	
	STUFFLEBEAN RUBY (211)	
	RICKHOFF JAMES G (212)	
	STUFFLEBEAN EDWARD E (212)	
	SJOHOLM ANNA (212)	
	GUNN AV (214)	
	CRAWFORD UNA (214)	
	JESKE GILBERT SR (214)	
	COX JAMES (214)	
	GONZALEZ GUILLERMO (214)	
	HAMMOND MARY T (214)	
	MERCIERW (214)	
	LEWIS CLARK (214)	
	MCAULEYG (214)	
	HINTHORNE MAVIS (214)	
	GONZALEZ VERLA (214)	
	MURRAY MILDRED (217)	

Year	Uses	Source
2003 (continued)		
	PENN MARY (217)	
	PARENT LOUIS (217)	
	PACE HELEN (217)	
	MOOREFIELDEMME U B (217)	
	RICEJERALD D (217)	
	REV MORGAN GRACE (217)	
	YOUNG ROSANN A (236)	
	ACACIA R V (295)	
	COLTON SC HI SLOVER (325)	
	ODEANDA GENARO (345)	
	HARRING WILLIAM (625)	
	OGODWIN LUCKY (635)	
	WEALTH CODE (645)	
	JONES LINDA (645)	
	****MERIDIAN RD****	Haines & Co Publishers
	WEALTH CODE (727)	
	****MERIDIAN****	Haines & Co Publishers
	XXXX (901)	
	X VISCONTI DR (908)	
	X OLIVE W (908)	
	X SAN BERNARDINO (908)	
	X CYPRESS DR W (908)	
	XXXX (908)	
	****REXFORD****	Haines & Co Publishers
	LIM SRUN (220)	
	AUZENNE HI HON (250)	
	MARCHANT SUN (299)	
	PAIGEARHUR (310)	
	TRANSPORT (310)	
	DUMP TRUCK PARTS (310)	
	COMPONENTS (310)	
	BARRETTJOHN (313)	
	REPUBIUCTOOL 909 370 05 S (313)	
	BASCOM MARI (319)	
	ORIGINAL BODY SHOP (319)	
	AMCAL AUTOMOTIVE (320)	
	BRAVO LOUIS (320)	
	****SERENATA****	Haines & Co Publishers
	X BEL CANTO CT (1410)	
	CAHILLSEAN (1410)	
	JAUREGUI GILBERT (1420)	
	HINOJOSACECILIA (1430)	

Year	Uses	Source
2003 (continued)		
	X CANTARA N (1440)	
	LACK RICHARD (1440)	
	****VALLEY BLVD****	Haines & Co Publishers
	B XXXX (1459)	
	OLVERA MARIA ISABEL (1556)	
	IPHAM AN (1556)	
	****N PEPPER AVE****	Haines & Co Publishers
	CTR SANBDOCO (400)	
	REGIONAL MEDICAL (400)	
	ARROWHEAD 9 W (400)	
	ARROWHEAD RGNL (400)	
	MCNEILUS (401)	
	TRUCK&MANUFACTUR (401)	

APPENDIX E

RESUMES

PETRA

CALLIE L. CULLUM
Project Geologist

EDUCATION
Bachelor of Science, 1989, Geology
California State University,
Bakersfield

REGISTRATION
Environmental Assessor, California,
REA 7511

CERTIFICATION
OSHA Hazwoper 40-Hour Health and Safety

OSHA 8-Hour Site Supervisor

OSHA AHERA Asbestos Awareness

PROFESSIONAL SUMMARY

Ms. Cullum is a Project Geologist presenting over 15 years of experience in environmental consulting. She has extensive experience on hazardous waste management projects including remedial investigations and feasibility studies, technical management of field operations encompassing geologic interpretation, sampling protocol, as well as groundwater monitoring well design and installation. Ms. Cullum has also conducted numerous Phase I Environmental Site Assessments for both vacant and commercial properties.

PROFESSIONAL RESPONSIBILITIES

As a Project Geologist for Petra Geotechnical, Inc. Ms. Cullum:

- Conducts Phase I environmental site assessments.
- Conducts Phase II soil and groundwater investigations.
- Directs soil and groundwater remediation projects.

PROJECT EXPERIENCE

Phase I Environmental Site Assessments
Ms. Cullum has conducted numerous Phase I Environmental Site Assessments throughout southern California. These properties have included planned transportation facilities, industrial areas; light to moderate manufacturing facilities; trucking facilities; agricultural sites; dairy farms; residential areas; planned residential housing developments; and both developed land and previously undeveloped land ranging from 1/3-acre in urban areas to approximately 400-acres in rural areas. Ms. Cullum has completed comprehensive Phase I Environmental Site Assessments for the Romona Overpass project in the City of Monrovia and for a two city-block area in West Covina for the proposed site for a new Foothill Transit Bus terminal.

Site Investigation

Ms. Cullum has conducted soil and groundwater investigations for manufacturing production plants, dairies, active and inactive service stations, military bases, amusement parks, sewage treatment facilities, dry cleaners, landfills, and residential sites. Additionally, Ms. Cullum has provided consulting services for site investigations related to the MTBE plume in the Charnock Basin, as well as several military sites in California and Arizona, in compliance with Navy CLEAN and RAC protocol. Her responsibilities also included interfacing with regulatory agency representatives to obtain regulatory closure of sites.

Remediation

Ms. Cullum has provided remediation services of sites containing hazardous materials for amusement parks; manufacturing facilities; agricultural sites; active and inactive service stations; and residential sites. Her remediation experience includes soil vapor extraction, pump and treatment of groundwater, dual phase extraction, installation of oxygenated material into the subsurface, and soil removal.

MR. BRIAN VILLALOBOS
Environmental Division Manager
Senior Associate Geologist

EDUCATION

Bachelor of Science, 1980,
Geology, California State University
Los Angeles

REGISTRATIONS

Geologist, California, RG 4153

Engineering Geologist, California,
CEG 1298

Certified Hydrogeologist
CHg 794

CERTIFICATIONS

OSHA Hazwoper 40-Hour Health and Safety

OSHA 8-Hour Site Supervisor

PROFESSIONAL SUMMARY

Mr. Villalobos has over 15 years of professional experience in environmental geology and hydrogeology throughout southern California. His expertise encompasses methane investigations, environmental hydrogeology, hydrogeologic investigations, engineering geology, landfill studies, and geologic-seismic evaluations. Mr. Villalobos' comprehensive environmental experience includes assessments of soil and groundwater degradation at numerous petroleum service stations, underground fuel storage facilities, former petroleum refineries, chemical plants, Solid Waste Assessments Testing (SWAT) for multiple landfill sites. In addition, he has performed extensive studies in subsurface conditions in relation to regulatory specifications, and participated as an expert witness in several litigation cases.

PROFESSIONAL RESPONSIBILITIES

As a Senior Associate Geologist for Petra Geotechnical, Inc. Mr. Villalobos:

- Conducts soil and groundwater and methane investigations.
- Conducts Phase I environmental site assessments & Phase II site characterizations.
- Directs soil and groundwater remediation projects.
- Pursues new projects and interfaces with existing clients.

PROJECT EXPERIENCE

Educational Facilities

- Stone Ranch Elementary School, Poway Unified School District, Poway California
- Brea Olinda High School, Brea Olinda Unified School District, Brea, California
- Rosecrans School K-8, Paramount Unified School District, Paramount, California
- Colony High School, Chaffey Joint Union High School
- Heroes Elementary School, Santa Ana Unified School District, Santa Ana, California
- Otsuka Elementary School, Santa Ana Unified School District, Santa Ana California
- Smith Elementary School, Lawndale Elementary School District, Lawndale, California

Methane Investigations

- Sycamore Ranch Development, William Lyon Homes
- 4S - Ranch Development, William Lyon Homes
- Cloverdale IV Development, KB Homes

- The Reserve Development, The Stratham Group
- Tracts 29148 and 29533, John Laing Homes
- Tract 29115, Centex Homes
- Stone Ranch Elementary School, Poway Unified School District
- Brea Olinda High School, Brea Olinda Unified School District
- Proposed Rosecrans School, Paramount Unified School District
- Colony High School, Chaffey Joint Union High School District
- Tract 28880, William Lyon Homes
- Tracts 29248, 30905, 30904, 30576, The Stratham Group
- Tract 29694, Bill Van Leeuwen
- Tract 30785 and Seven Contiguous Parcels, C.L. William Group for Hillcrest Development

Environmental Geology and Hydrogeology

- Brand Landfill, City of Glendale
- Stough Park Landfill, City of Glendale
- Palos Verdes Landfill, Los Angeles County Sanitation District
- Calabasas Landfill, Los Angeles County Sanitation District
- Mission Canyon Landfill, Los Angeles County Sanitation District
- Scholl Canyon Landfill, Los Angeles County Sanitation District
- Puente Hills Landfill, Los Angeles County Sanitation District

Hydrogeologic and Geologic Investigations

- Hyatt Hotel, Santa Barbara
- Additional Water Supply, Fern Valley Water District
- Additional Water Supply, Big Bear Water District
- Mecca Power Plant, Morongo Indian Reservation

Landfill Siting Studies

- Niland Hazardous Waste Site
- Campo Indian Reservation Landfill

Soil Permeability

- Evaluation of Site Permeability, Los Angeles County Sanitation District, Calabasas Landfill
- Evaluation of Liner Permeability for Ponds I.T. Corporation Imperial Valley Class I Landfill
- Evaluation of Soil Infiltration Rates for Leach Lines, Santa Monica Mountains
- Evaluation of Soil Infiltration Rates for Leach Lines, Ortega Highway Area
- Assessment of Subsurface Permeability, Proposed Class II Landfill, Campo Indian Reservation

Coltons Hub City Centre
Eucalyptus Avenue/Valley Boulevard
Colton, CA 92324

Inquiry Number: 3639401.1s
June 17, 2013

The EDR Radius Map™ Report with GeoCheck®

EDR® Environmental Data Resources Inc

440 Wheelers Farms Road
Milford, CT 06461
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	8
Orphan Summary	1884
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting SSURGO Soil Map	A-5
Physical Setting Source Map	A-8
Physical Setting Source Map Findings	A-10
Physical Setting Source Records Searched	A-27

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2013 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-05) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

EUCALYPTUS AVENUE/VALLEY BOULEVARD
COLTON, CA 92324

COORDINATES

Latitude (North):	34.0724000 - 34° 4' 20.64''
Longitude (West):	117.3571000 - 117° 21' 25.56''
Universal Tranverse Mercator:	Zone 11
UTM X (Meters):	467049.8
UTM Y (Meters):	3770046.5
Elevation:	1081 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	34117-A3 SAN BERNARDINO SOUTH, CA
Most Recent Revision:	1980

AERIAL PHOTOGRAPHY IN THIS REPORT

Photo Year:	2012
Source:	USDA

TARGET PROPERTY SEARCH RESULTS

The target property was not listed in any of the databases searched by EDR.

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL---------- National Priority List

EXECUTIVE SUMMARY

Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

Federal Delisted NPL site list

Delisted NPL ---------- National Priority List Deletions

Federal CERCLIS list

CERCLIS ---------- Comprehensive Environmental Response, Compensation, and Liability Information System
FEDERAL FACILITY ---------- Federal Facility Site Information listing

Federal RCRA generators list

RCRA-CESQG ---------- RCRA - Conditionally Exempt Small Quantity Generator

Federal institutional controls / engineering controls registries

US ENG CONTROLS ---------- Engineering Controls Sites List
US INST CONTROL ---------- Sites with Institutional Controls
LUCIS ---------- Land Use Control Information System

State- and tribal - equivalent NPL

RESPONSE ---------- State Response Sites

State and tribal leaking storage tank lists

INDIAN LUST ---------- Leaking Underground Storage Tanks on Indian Land

State and tribal registered storage tank lists

INDIAN UST ---------- Underground Storage Tanks on Indian Land
FEMA UST ---------- Underground Storage Tank Listing

State and tribal voluntary cleanup sites

VCP ---------- Voluntary Cleanup Program Properties
INDIAN VCP ---------- Voluntary Cleanup Priority Listing

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS ---------- A Listing of Brownfields Sites

Local Lists of Landfill / Solid Waste Disposal Sites

ODI ---------- Open Dump Inventory
DEBRIS REGION 9 ---------- Torres Martinez Reservation Illegal Dump Site Locations
HAULERS ---------- Registered Waste Tire Haulers Listing
INDIAN ODI ---------- Report on the Status of Open Dumps on Indian Lands

Local Lists of Hazardous waste / Contaminated Sites

HIST Cal-Sites ---------- Historical Calsites Database

SCH School Property Evaluation Program
US HIST CDL National Clandestine Laboratory Register

Local Land Records

LIENS 2 CERCLA Lien Information
LIENS Environmental Liens Listing
DEED Deed Restriction Listing

Records of Emergency Release Reports

MCS Military Cleanup Sites Listing
SPILLS 90 SPILLS 90 data from FirstSearch

Other Ascertainable Records

DOT OPS Incident and Accident Data
DOD Department of Defense Sites
FUDS Formerly Used Defense Sites
CONSENT Superfund (CERCLA) Consent Decrees
ROD Records Of Decision
UMTRA Uranium Mill Tailings Sites
US MINES Mines Master Index File
TRIS Toxic Chemical Release Inventory System
TSCA Toxic Substances Control Act
SSTS Section 7 Tracking Systems
PADS PCB Activity Database System
MLTS Material Licensing Tracking System
RADINFO Radiation Information Database
RAATS RCRA Administrative Action Tracking System
CA BOND EXP. PLAN Bond Expenditure Plan
CUPA Listings CUPA Resources List
Notify 65 Proposition 65 Records
DRYCLEANERS Cleaner Facilities
WIP Well Investigation Program Case List
ENF Enforcement Action Listing
INDIAN RESERV Indian Reservations
SCRD DRYCLEANERS State Coalition for Remediation of Drycleaners Listing
COAL ASH DOE Steam-Electric Plant Operation Data
COAL ASH EPA Coal Combustion Residues Surface Impoundments List
Financial Assurance Financial Assurance Information Listing
LEAD SMELTERS Lead Smelter Sites
PRP Potentially Responsible Parties
EPA WATCH LIST EPA WATCH LIST
US FIN ASSUR Financial Assurance Information
PCB TRANSFORMER PCB Transformer Registration Database
PROC Certified Processors Database

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

EXECUTIVE SUMMARY

STANDARD ENVIRONMENTAL RECORDS

Federal CERCLIS NFRAP site List

CERC-NFRAP: Archived sites are sites that have been removed and archived from the inventory of CERCLIS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

A review of the CERC-NFRAP list, as provided by EDR, and dated 02/05/2013 has revealed that there are 2 CERC-NFRAP sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
GATX RAIL	*20878 SLOVER AVENUE*	*SSE 1/4 - 1/2 (0.417 mi.)*	*AO323*	*437*
CALIFORNIA PORTLAND CEMENT CO	*695 SOUTH RANCHO AVE.*	*SE 1/2 - 1 (0.970 mi.)*	*BK488*	*1853*

Federal RCRA CORRACTS facilities list

CORRACTS: CORRACTS is a list of handlers with RCRA Corrective Action Activity. This report shows which nationally-defined corrective action core events have occurred for every handler that has had corrective action activity.

A review of the CORRACTS list, as provided by EDR, and dated 02/12/2013 has revealed that there are 2 CORRACTS sites within approximately 1.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
GATX RAIL	*20878 SLOVER AVENUE*	*SSE 1/4 - 1/2 (0.417 mi.)*	*AO323*	*437*
FILTERRECYCLING SERVICES, INC.	*180 MONTE AVENUE*	*SW 1/2 - 1 (0.609 mi.)*	*AX416*	*1689*

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

A review of the RCRA-TSDF list, as provided by EDR, and dated 02/12/2013 has revealed that there is 1 RCRA-TSDF site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
GATX RAIL	*20878 SLOVER AVENUE*	*SSE 1/4 - 1/2 (0.417 mi.)*	*AO323*	*437*

EXECUTIVE SUMMARY

Federal RCRA generators list

RCRA-LQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, and dated 02/12/2013 has revealed that there are 13 RCRA-LQG sites within approximately 0.75 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
WAL-MART #1862	1610 SOUTH RIVERSIDE AV	W 1/8 - 1/4 (0.134 mi.)	S166	265
STEEL UNLIMITED INC	***452 W VALLEY BLVD***	***W 1/2 - 1 (0.566 mi.)***	***AY400***	***1673***

Lower Elevation	Address	Direction / Distance	Map ID	Page
CHEVRON NO 96969	101 E VALLEY BLVD.	W 0 - 1/8 (0.119 mi.)	M151	249
CALNEV PIPE LINE COMPANY COLTO	***2051 E SLOVER AVE***	***SSW 1/4 - 1/2 (0.401 mi.)***	***AI277***	***372***
CONOCO PHILLIPS COLTON TERMINA	***271 E SLOVER AVE***	***SW 1/4 - 1/2 (0.406 mi.)***	***AF308***	***414***
GATX RAIL	***20878 SLOVER AVENUE***	***SSE 1/4 - 1/2 (0.417 mi.)***	***AO323***	***437***
FILTERRECYCLING SERVICES, INC.	***180 MONTE AVENUE***	***SW 1/2 - 1 (0.609 mi.)***	***AX416***	***1689***
TOSCO COLTON TERMINAL	2301 S. RIVERSIDE AVE	SW 1/2 - 1 (0.633 mi.)	AX432	1751
PHILLIPS 66 PIPELINE LLC	***2301 S RIVERSIDE AVE***	***SW 1/2 - 1 (0.633 mi.)***	***AX434***	***1752***
EQUILON ETERPISES LLC/COLTON T	2307 S. RIVERSIDE AVE	SW 1/2 - 1 (0.670 mi.)	BC447	1777
EQUILON ENTERPRISES,SHELL OIL	***2307 RIVERSIDE AVE***	***SW 1/2 - 1 (0.670 mi.)***	***BC452***	***1785***
FONTANA POLISHING AND PLATING	130 W MINDANAO ST	SW 1/2 - 1 (0.686 mi.)	BE459	1801
SFPP, L.P. - COLTON SOUTH	2359 S. RIVERSIDE AVE	SW 1/2 - 1 (0.738 mi.)	BC478	1824

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 02/12/2013 has revealed that there are 23 RCRA-SQG sites within approximately 0.75 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
WORLD PROPHETIC MINISTRY	***1099 N PEPPER AVE***	***NNE 0 - 1/8 (0.061 mi.)***	***I115***	***214***
WALMART NO 1862	1610 S RIVERSIDE AVE	W 1/8 - 1/4 (0.134 mi.)	S165	260
WILLIAM G JEHUE MIDDLE SCHOOL	1500 N EUCALYPTUS	N 1/4 - 1/2 (0.433 mi.)	AS348	1616
RIALTO UNIFIED SCHOOL DISTRICT	***266 W RANDALL***	***NW 1/2 - 1 (0.684 mi.)***	***458***	***1799***

Lower Elevation	Address	Direction / Distance	Map ID	Page
UNIVERSAL MACK SALES SERVICE	***220 N REX FORD***	***0 - 1/8 (0.000 mi.)***	***F34***	***63***
SHELL SERVICE STATION	***1600 W VALLEY***	***0 - 1/8 (0.000 mi.)***	***K74***	***137***
B AND G AUTO SALES	***1630 W VALLEY BLVD***	***0 - 1/8 (0.000 mi.)***	***K76***	***142***
INLAND EMPIRE TOYOTA	***1700 VALLEY RD***	***0 - 1/8 (0.000 mi.)***	***F79***	***146***
INLAND EMPIRE EQUIPT, INC	***1762 S SYCAMORE***	***0 - 1/8 (0.001 mi.)***	***A85***	***155***
ARROWHEAD REGIONAL MEDICAL CEN	400 N PEPPER AVE	ESE 0 - 1/8 (0.013 mi.)	K104	188
P S TRUCK SUPPLY INC	***245 E VALLEY BLVD***	***W 0 - 1/8 (0.045 mi.)***	***A113***	***212***
CHEVRON STATION NO 96969	***101 E VALLEY BLVD***	***W 0 - 1/8 (0.119 mi.)***	***M149***	***245***

Lower Elevation	Address	Direction / Distance	Map ID	Page
ARCO FACILITY NO 09695	***111 W VALLEY BLVD***	***W 1/8 - 1/4 (0.144 mi.)***	***M183***	***282***
CIRCLE K STORE #627	***990 VALLEY BLVD***	***ESE 1/8 - 1/4 (0.168 mi.)***	***T195***	***291***
DALE JONES PHOTOGRAPHY	***915 W C ST***	***E 1/4 - 1/2 (0.316 mi.)***	***AD237***	***337***
WHITING DOOR MFG CORP	***311 W VALLEY BLVD***	***W 1/4 - 1/2 (0.391 mi.)***	***AH266***	***357***
WHITING DOOR MFG CORP	***311 W VALLEY BLVD***	***W 1/4 - 1/2 (0.391 mi.)***	***AH267***	***360***
TOSCO CORPORATION, COLTON TERM	***271 EAST SLOVER AVE***	***SW 1/4 - 1/2 (0.407 mi.)***	***AF313***	***426***
EQUILON RIALTO TERMINAL	***2237 S. RIVERSIDE AVE.***	***SW 1/2 - 1 (0.562 mi.)***	***AX392***	***1665***
CHEVRON USA INC COLTON SUPPLY	***2297 S. RIVERSIDE AVE.***	***SW 1/2 - 1 (0.605 mi.)***	***AX413***	***1684***
MOBIL OIL CORP COLTON TERM	***2305 S RIVERSIDE AVE***	***SW 1/2 - 1 (0.660 mi.)***	***AX443***	***1767***
NORTON BATTERY MFG CO	***2175 S WILLOW AVE***	***SW 1/2 - 1 (0.701 mi.)***	***BH465***	***1808***
COLTON TRUCK RACK	2359 SOUTH RIVERSIDE AV	SW 1/2 - 1 (0.738 mi.)	BC475	1815

Federal ERNS list

ERNS: The Emergency Response Notification System records and stores information on reported releases of oil and hazardous substances. The source of this database is the U.S. EPA.

A review of the ERNS list, as provided by EDR, and dated 12/31/2012 has revealed that there are 24 ERNS sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
Not reported	2111 WEST VALLEY BLVD	0 - 1/8 (0.000 mi.)	C35	64
Not reported	2111 WEST VALLEY BLVD	0 - 1/8 (0.000 mi.)	C60	127
Not reported	195 E VALLEY BLVD	W 0 - 1/8 (0.069 mi.)	A119	218
Not reported	2151 WEST SLOVER AVENUE	SW 1/4 - 1/2 (0.400 mi.)	AF269	367
Not reported	2051 EAST SLOVER AVENUE	SSW 1/4 - 1/2 (0.401 mi.)	AI270	367
Not reported	2051 E. SLOVER AVE	SSW 1/4 - 1/2 (0.401 mi.)	AI271	367
Not reported	2051 E. SLOVER AVE.	SSW 1/4 - 1/2 (0.401 mi.)	AI272	367
Not reported	2051 EAST SLOVER AVE CO	SSW 1/4 - 1/2 (0.401 mi.)	AI273	367
Not reported	2051 E. SLOVER AVE.	SSW 1/4 - 1/2 (0.401 mi.)	AI274	367
Not reported	2051 E. SLOVER	SSW 1/4 - 1/2 (0.401 mi.)	AI275	368
Not reported	2051 E. SLOVER AVE.	SSW 1/4 - 1/2 (0.401 mi.)	AI278	385
Not reported	2051 E. SLOVER AVE.	SSW 1/4 - 1/2 (0.401 mi.)	AI280	386
Not reported	2051 E. SLOVER AVE.	SSW 1/4 - 1/2 (0.401 mi.)	AI283	391
Not reported	2051 E. SLOVER AVE.	SSW 1/4 - 1/2 (0.401 mi.)	AI284	391
Not reported	2051 E. SLOVER AVE.	SSW 1/4 - 1/2 (0.401 mi.)	AI285	391
Not reported	2051 E. SLOVER	SSW 1/4 - 1/2 (0.401 mi.)	AI295	404
Not reported	2051 EAST SLOVER	SSW 1/4 - 1/2 (0.401 mi.)	AI297	406
Not reported	2051 SLOVER AVE	SSW 1/4 - 1/2 (0.401 mi.)	AI299	407
Not reported	2051 W. SLOVER AVENUE	SSW 1/4 - 1/2 (0.401 mi.)	AI300	407
Not reported	2051 EAST SLOVER	SSW 1/4 - 1/2 (0.401 mi.)	AI302	409
Not reported	2051 W. SLOVER AVE.	SSW 1/4 - 1/2 (0.402 mi.)	AI304	413
Not reported	1900 SLOVER AVE.	SSW 1/4 - 1/2 (0.408 mi.)	AL316	432
Not reported	2051 SLOVER AVE	S 1/4 - 1/2 (0.415 mi.)	AN322	436
Not reported	20878 SLOVER AVE	SSE 1/4 - 1/2 (0.418 mi.)	AO333	1600

State- and tribal - equivalent CERCLIS

ENVIROSTOR: The Department of Toxic Substances Control's (DTSC's) Site Mitigation and Brownfields Reuse Program's (SMBRP's) EnviroStor database identifes sites that have known contamination or sites for which there may be reasons to investigate further. The database includes the following site types: Federal Superfund sites (National Priorities List (NPL)); State Response, including Military Facilities and State Superfund; Voluntary Cleanup; and School sites. EnviroStor provides similar information to the information that was available in CalSites, and provides additional site information, including, but not limited to, identification of formerly-contaminated properties that have been released for reuse, properties where environmental deed restrictions have been recorded to prevent inappropriate land uses, and risk characterization information that is used to assess potential impacts to public health and the environment at contaminated sites.

A review of the ENVIROSTOR list, as provided by EDR, and dated 03/13/2013 has revealed that there are 10 ENVIROSTOR sites within approximately 1.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
WDLJ SOUTH PROPERTY Status: Active	***1485 SOUTH WILLOW STREE***	***W 1/2 - 1/2 (0.401 mi.)***	***AG292***	***399***
CACTUS MIDDLE SCHOOL Status: No Further Action	***VALLEY BOULEVARD/CACTUS***	***W 1/2 - 1 (0.875 mi.)***	***481***	***1831***

Lower Elevation	Address	Direction / Distance	Map ID	Page
GENERAL AMERICAN TRANSPORTATIO Status: Refer: RCRA	***PEPPER ST & CLOVER AVE***	***SSE 1/4 - 1/2 (0.429 mi.)***	***AQ338***	***1604***
GATX RAIL Status: Active	***PEPPER & SLOVER ST***	***SSE 1/4 - 1/2 (0.429 mi.)***	***AQ341***	***1609***
FILTERRECYCLING SERVICES, INC. Status: Inactive - Needs Evaluation	***180 MONTE AVENUE***	***SW 1/2 - 1 (0.609 mi.)***	***AX416***	***1689***
SFPP, L.P. Status: Inactive - Needs Evaluation	***2359 S RIVERSIDE AVE***	***SW 1/2 - 1 (0.738 mi.)***	***BC476***	***1816***
UNION PACIFIC RAILROAD CO Status: No Further Action	***19100 SLOVER AVE***	***WSW 1 - 2 (1.226 mi.)***	***495***	***1864***
CRANE COMPANY Status: Refer: RWQCB	330 WEST CITRUS STREET	ENE 1 - 2 (1.289 mi.)	496	1874
EDISON/COLTON 2 (10TH ST) MGP Status: Certified / Operation & Maintenance	***EAST OF 10TH STREET, SO***	***ESE 1 - 2 (1.334 mi.)***	***BM497***	***1875***
SOLVEX INC Status: No Further Action	***1475 MILLER DR***	***ENE 1 - 2 (1.495 mi.)***	***500***	***1882***

State and tribal landfill and/or solid waste disposal site lists

SWF/LF: The Solid Waste Facilities/Landfill Sites records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. The data come from the Integrated Waste Management Board's Solid Waste Information System (SWIS) database.

A review of the SWF/LF list, as provided by EDR, and dated 02/18/2013 has revealed that there are 4

SWF/LF sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
FILTER RECYCLING SERVICES, INC	180 WEST MONTE AVENUE	SW 1/2 - 1 (0.613 mi.)	AX417	1728
HOLLIDAY INERTWASTE SITE	249 EAST SANTA ANA AVEN	SSW 1/2 - 1 (0.902 mi.)	BI483	1835
RIALTO SEWER PLANT	***501 E SANTA ANA***	***SSW 1/2 - 1 (0.904 mi.)***	***BJ485***	***1838***
ECOLOGY AUTO WRECKING	***221 SANTA ANA AVENUE EA***	***SSW 1/2 - 1 (0.907 mi.)***	***BI486***	***1840***

State and tribal leaking storage tank lists

LUST: The Leaking Underground Storage Tank Incident Reports contain an inventory of reported leaking underground storage tank incidents. The data come from the State Water Resources Control Board Leaking Underground Storage Tank Information System.

A review of the LUST list, as provided by EDR, and dated 03/18/2013 has revealed that there are 31 LUST sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
DOMECQ RESERVOIR	***1011***	***NE 1/2 - 1 (0.991 mi.)***	***BL493***	***1862***
DOMECQ RESERVOIR	1011 W ELLEN ST	NE 1/2 - 1 (0.991 mi.)	BL494	1863
Status: Completed - Case Closed				

Lower Elevation	Address	Direction / Distance	Map ID	Page
TELCO FOODS	2111 VALLEY BOULEVARD W	0 - 1/8 (0.000 mi.)	C43	70
Status: Completed - Case Closed				
SHELL SERVICE STATION	1600 VALLEY BOULEVARD W	0 - 1/8 (0.000 mi.)	K71	131
Status: Completed - Case Closed				
I-10 TRUCK STOP	195 VALLEY BOULEVARD EA	W 0 - 1/8 (0.069 mi.)	A124	221
Status: Completed - Case Closed				
RIALTO, CITY OF (TEXACO)	102 E VALLEY BLVD	W 0 - 1/8 (0.118 mi.)	M143	237
Status: Completed - Case Closed				
96969	***101 E VALLEY BLVD***	***W 0 - 1/8 (0.119 mi.)***	***M147***	***241***
Status: Completed - Case Closed				
CHEVRON #9-6969	101 VALLEY BLVD	WSW 1/8 - 1/4 (0.133 mi.)	M159	254
RIALTO, CITY OF (TEXACO)	***102 VALLEY***	***WSW 1/8 - 1/4 (0.133 mi.)***	***M160***	***256***
THRIFTY OIL CO #323	***111 W VALLEY***	***W 1/8 - 1/4 (0.144 mi.)***	***M181***	***278***
Status: Completed - Case Closed				
TEXACO SERVICE STATION	***120 VALLEY***	***W 1/8 - 1/4 (0.155 mi.)***	***M191***	***287***
THRIFTY OIL #323/ ARCO #9695	111 VALLEY BLVD	W 1/8 - 1/4 (0.161 mi.)	M192	288
TEXACO SERVICE STATION	120 W VALLEY BLVD	W 1/8 - 1/4 (0.170 mi.)	M196	293
Status: Completed - Case Closed				
SOUTHERN PACIFIC TRAN/CLT	***200 MARION WAY***	***SW 1/8 - 1/4 (0.233 mi.)***	***V207***	***300***
Status: Completed - Case Closed				
CLEM TRANS INC	213 VALLEY BLVD.	W 1/4 - 1/2 (0.270 mi.)	Y213	307
CLEM-TRANS, INC.	***213 W VALLEY BLVD***	***W 1/4 - 1/2 (0.270 mi.)***	***Y215***	***309***
Status: Completed - Case Closed				
CONOCO PHILLIPS CO. - COLTON T	***271 E. SLOVER AVE.***	***SW 1/4 - 1/2 (0.407 mi.)***	***AF311***	***423***
Status: Completed - Case Closed				
POMA AUTOMATED FUELING	***2095 S RIVERSIDE AVE***	***SW 1/4 - 1/2 (0.466 mi.)***	***AM368***	***1631***
Status: Completed - Case Closed				

Lower Elevation	Address	Direction / Distance	Map ID	Page
ARCO #1569 (FORMER) Status: Open - Remediation	792 VALLEY BOULEVARD WE	ESE 1/2 - 1 (0.520 mi.)	AR378	1641
BALTAZAR CERVANTES Status: Completed - Case Closed	***792 W VALLEY BLVD***	***ESE 1/2 - 1 (0.520 mi.)***	***AR381***	***1647***
ARCO #1569	***792 VALLEY***	***ESE 1/2 - 1 (0.527 mi.)***	***AR383***	***1651***
COLTON UNIFIED SCHOOL DISTRICT	777 VALLEY BLVD	ESE 1/2 - 1 (0.536 mi.)	AR387	1654
COLTON HIGH SCHOOL Status: Completed - Case Closed	***777 W VALLEY BLVD***	***ESE 1/2 - 1 (0.559 mi.)***	***AW390***	***1657***
TEXACO USA-COLTON TERMINAL Status: Completed - Case Closed	***2237 S RIVERSIDE AVE***	***SW 1/2 - 1 (0.562 mi.)***	***AX391***	***1660***
AMERICAN FUEL Status: Completed - Case Closed	***1101 N RANCHO AVE***	***ENE 1/2 - 1 (0.590 mi.)***	***BA405***	***1677***
TERMINAL (EQUILON ENTERPRISES)	2237 RIVERSIDE AVE	SW 1/2 - 1 (0.594 mi.)	AX408	1680
MOBIL FAC. #04-086 /COLTON TER	2305 RIVERSIDE AVE	SW 1/2 - 1 (0.660 mi.)	AX444	1769
MOBIL FAC. #04-086 /COLTON TER Status: Open - Remediation	***2305 S RIVERSIDE AVE***	***SW 1/2 - 1 (0.660 mi.)***	***AX445***	***1770***
ECOLOGY AUTO WRECKING Status: Open - Site Assessment	***221 SANTA ANA AVENUE EA***	***SSW 1/2 - 1 (0.907 mi.)***	***BI486***	***1840***
CA PORTLAND CEMENT CO Status: Completed - Case Closed	***695 S RANCHO AVE***	***SE 1/2 - 1 (0.970 mi.)***	***BK487***	***1844***
Not reported	***695 SOUTH RANCHO AVE***	***SE 1/2 - 1 (0.970 mi.)***	***BK489***	***1855***

SLIC: SLIC Region comes from the California Regional Water Quality Control Board.

A review of the SLIC list, as provided by EDR, and dated 03/18/2013 has revealed that there are 6 SLIC sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
HALSEY MACHINERY Facility Status: Open - Site Assessment	***1485 S WILLOW***	***W 1/4 - 1/2 (0.401 mi.)***	***AG291***	***396***

Lower Elevation	Address	Direction / Distance	Map ID	Page
KMPP TANK FARM Facility Status: Open - Site Assessment	2720 SLOVER	SW 1/4 - 1/2 (0.394 mi.)	AF268	366
UNOCAL TANK FARM - CONOCO WEST Facility Status: Open - Assessment & Interim Remedial Action	2301 RIVERSIDE AVENUE S	SW 1/2 - 1 (0.635 mi.)	BC435	1762
CHEVRON COLTON TERMINAL Facility Status: Open - Assessment & Interim Remedial Action	2297 RIVERSIDE AVE S	SW 1/2 - 1 (0.660 mi.)	AX440	1765
SHELL OIL PROD US COLTON TERMI Facility Status: Open - Site Assessment	***2307 S RIVERSIDE AVE***	***SW 1/2 - 1 (0.670 mi.)***	***BC450***	***1784***
COLTON TERMINAL Facility Status: Open - Remediation	***2359 RIVERSIDE AVE***	***SW 1/2 - 1 (0.738 mi.)***	***BC477***	***1820***

EXECUTIVE SUMMARY

State and tribal registered storage tank lists

UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the State Water Resources Control Board's Hazardous Substance Storage Container Database.

A review of the UST list, as provided by EDR, and dated 03/18/2013 has revealed that there are 17 UST sites within approximately 0.75 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
BISHOP'S CENTRAL STORES	***791 N PEPPER AVE***	***0 - 1/8 (0.000 mi.)***	***E50***	***77***
ORANGE SHELL - COLTON	1600 W VALLEY BLVD	0 - 1/8 (0.000 mi.)	K65	128
CO-ARROWHEAD REG.MED.CTR	***400 N PEPPER AVE***	***ESE 0 - 1/8 (0.013 mi.)***	***K103***	***187***
I-10 TRUCK STOP	195 E VALLEY BLVD	W 0 - 1/8 (0.069 mi.)	A123	221
CHEVRON STATION #6969	101 E VALLEY BLVD	W 0 - 1/8 (0.119 mi.)	M152	250
ARCO #9695	111 W VALLEY BLVD	W 1/8 - 1/4 (0.144 mi.)	M182	281
FEDERAL EXPRESS CORP	***280 W VALLEY BLVD***	***W 1/4 - 1/2 (0.350 mi.)***	***Y255***	***350***
GATX RAIL CORPORATION	20878 SLOVER ST	SSE 1/4 - 1/2 (0.417 mi.)	AO326	462
ARCO PETROLEUM PROD #1569	792 W VALLEY BLVD	ESE 1/2 - 1 (0.520 mi.)	AR380	1647
SC-COLTON USD/TRANS	777 W VALLEY BLVD	ESE 1/2 - 1 (0.559 mi.)	AW388	1655
EQUILON ENT., L.L.C.	2237 S RIVERSIDE AVE	SW 1/2 - 1 (0.562 mi.)	AX394	1669
KINDER/MORGAN	230S S RIVERSIDE AVE	SW 1/2 - 1 (0.593 mi.)	AX407	1679
TOSCO COLTON TERMINAL	2301 S RIVERSIDE AVE	SW 1/2 - 1 (0.618 mi.)	AX419	1729
KINDER/MORGAN.	2297 S RIVERSIDE AVE	SW 1/2 - 1 (0.660 mi.)	AX442	1767
EQUILON ENT LLC	2307 S RIVERSIDE AVE	SW 1/2 - 1 (0.670 mi.)	BC449	1784
OLD DOMINION FREIGHT LINE	2209 S WILLOW AVE	SW 1/2 - 1 (0.732 mi.)	BH471	1813
SFPP, L.P.	***2359 S RIVERSIDE AVE***	***SW 1/2 - 1 (0.738 mi.)***	***BC476***	***1816***

AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the State Water Resources Control Board's Hazardous Substance Storage Container Database.

A review of the AST list, as provided by EDR, and dated 08/01/2009 has revealed that there are 9 AST sites within approximately 0.75 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
WAL-MART STORE #1862	1610 S. RIVERSIDE AVE	W 1/8 - 1/4 (0.134 mi.)	S168	268

Lower Elevation	Address	Direction / Distance	Map ID	Page
MOSS BROS FORD	1900 W. VALLEY BLVD	0 - 1/8 (0.000 mi.)	B4	12
BISHOP'S CENTRAL STORES	791 N. PEPPER AVE	0 - 1/8 (0.000 mi.)	E6	13
VALLEY TRUCK FILTERS & PARTS	2006 W. VALLEY BLVD	0 - 1/8 (0.000 mi.)	D30	61
TELCO FOOD PRODUCTS, INC.	2111 W VALLEY	0 - 1/8 (0.000 mi.)	C51	79
GATX RAIL CORPORATION	***20878 SLOVER AVE***	***SSE 1/4 - 1/2 (0.417 mi.)***	***AO325***	***456***
CONOCO PHILLIPS COLTON TERMINA	2301 S. RIVERSIDE AVE.	SW 1/2 - 1 (0.633 mi.)	AX433	1752
SHELL OIL PRODUCTS - COLTON TE	2307 S. RIVERSIDE AVE.	SW 1/2 - 1 (0.670 mi.)	BC451	1785
SFPP, L.P.	2359 S. RIVERSIDE AVE.	SW 1/2 - 1 (0.738 mi.)	BC474	1814

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Landfill / Solid Waste Disposal Sites

WMUDS/SWAT: The Waste Management Unit Database System is used for program tracking and inventory of waste management units. The source is the State Water Resources Control Board.

A review of the WMUDS/SWAT list, as provided by EDR, and dated 04/01/2000 has revealed that there are 4 WMUDS/SWAT sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
BRINE FACCOLTON	***20870 SLOVER AVE***	***SSE 1/4 - 1/2 (0.421 mi.)***	***AO335***	***1600***
HOLLIDAY SANITARY LANDFILL	SANTA ANA AVE	SSW 1/2 - 1 (0.900 mi.)	BI482	1834
LANDFILLRIALTO	***SANTA ANA AVE***	***SSW 1/2 - 1 (0.902 mi.)***	***BJ484***	***1836***
Not reported	***695 SOUTH RANCHO AVE***	***SE 1/2 - 1 (0.970 mi.)***	***BK490***	***1857***

SWRCY: A listing of recycling facilities in California.

A review of the SWRCY list, as provided by EDR, and dated 03/18/2013 has revealed that there are 4 SWRCY sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
FOOD 4 LESS #786	***1150 N PEPPER AVE***	***NNE 1/8 - 1/4 (0.126 mi.)***	***Q154***	***250***
RIALTO RECYCLING CENTER 2	515 S RIVERSIDE AVE	NNW 1/2 - 1 (0.973 mi.)	492	1861

Lower Elevation	Address	Direction / Distance	Map ID	Page
PONCE RECYCLING	875 N RANCHO AVE	E 1/2 - 1 (0.532 mi.)	AV386	1653
AMKO RECYCLING LLC	***340 W VALLEY BLVD***	***ESE 1/2 - 1 (0.970 mi.)***	***491***	***1860***

Local Lists of Hazardous waste / Contaminated Sites

US CDL: A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

A review of the US CDL list, as provided by EDR, and dated 03/04/2013 has revealed that there is 1 US CDL site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
1822 ADMIRALTY STREET	1822 ADMIRALTY STREET	N 1/4 - 1/2 (0.272 mi.)	AA218	311

EXECUTIVE SUMMARY

Toxic Pits: The Toxic Pits Cleanup Act Sites database identifies sites suspected of containing hazardous substances where cleanup has not yet been completed. The data come from the State Water Resources Control Board.

A review of the Toxic Pits list, as provided by EDR, and dated 07/01/1995 has revealed that there is 1 Toxic Pits site within approximately 1.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
SOUTHERN PACIFIC TRAN/CLT Closure Date: 02/21/91	***200 MARION WAY***	***SW 1/8 - 1/4 (0.233 mi.)***	***V207***	***300***

CDL: A listing of drug lab locations. Listing of a location in this database does not indicate that any illegal drug lab materials were or were not present there, and does not constitute a determination that the location either requires or does not require additional cleanup work.

A review of the CDL list, as provided by EDR, and dated 12/31/2012 has revealed that there are 21 CDL sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
Not reported	987 N CYPRESS ST	ENE 0 - 1/8 (0.064 mi.)	116	217
Not reported	1610 NORTH BENT RAIL CI	NNE 1/8 - 1/4 (0.139 mi.)	O175	273
Not reported	1822 W ADMIRALTY ST	N 1/4 - 1/2 (0.272 mi.)	AA217	311
Not reported	1155 S RIVERSIDE AVE, #	NW 1/4 - 1/2 (0.311 mi.)	AC233	335
Not reported	935 S SAGE ST	NNW 1/4 - 1/2 (0.431 mi.)	344	1615
Not reported	211 E MONTROSE ST	NW 1/4 - 1/2 (0.451 mi.)	AU364	1630

Lower Elevation	Address	Direction / Distance	Map ID	Page
Not reported	145 E VALLEY BLVD, #215	W 0 - 1/8 (0.097 mi.)	M134	230
Not reported	1087 WEST VALLEY BLVD #	ESE 1/8 - 1/4 (0.149 mi.)	T187	285
Not reported	393 CYPRESS	E 1/8 - 1/4 (0.151 mi.)	U188	285
Not reported	981 W C ST, APT 9	E 1/8 - 1/4 (0.195 mi.)	203	299
Not reported	941 W. F STREET	E 1/4 - 1/2 (0.262 mi.)	X210	305
Not reported	220 W VALLEY BLVD, UNIT	W 1/4 - 1/2 (0.279 mi.)	Y227	330
Not reported	926 F ST	E 1/4 - 1/2 (0.287 mi.)	X230	333
Not reported	639 GRAND AVE	E 1/4 - 1/2 (0.341 mi.)	AD245	345
Not reported	2071 SOUTH DATE	SW 1/4 - 1/2 (0.384 mi.)	262	355
Not reported	258 E SLOVER AVE	SW 1/4 - 1/2 (0.408 mi.)	AF319	434
Not reported	1095 STEVENSON AVE	ENE 1/4 - 1/2 (0.421 mi.)	AP336	1603
Not reported	1601 SLOVER AVE	SSE 1/4 - 1/2 (0.430 mi.)	AQ342	1614
Not reported	1073 STEVENSON	ENE 1/4 - 1/2 (0.432 mi.)	AP346	1616
Not reported	1072 STEVENSON ST	ENE 1/4 - 1/2 (0.434 mi.)	AP350	1619
Not reported	1057 STEVENSON ST	ENE 1/4 - 1/2 (0.442 mi.)	AP358	1625

Local Lists of Registered Storage Tanks

CA FID UST: The Facility Inventory Database contains active and inactive underground storage tank locations. The source is the State Water Resource Control Board.

A review of the CA FID UST list, as provided by EDR, and dated 10/31/1994 has revealed that there are 14 CA FID UST sites within approximately 0.75 miles of the target property.

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
HALSEY MACHINERY	***1485 S WILLOW***	***W 1/4 - 1/2 (0.401 mi.)***	***AG291***	***396***

Lower Elevation	Address	Direction / Distance	Map ID	Page
INLAND EMPIRE EQUIPT, INC	***1762 S SYCAMORE***	***0 - 1/8 (0.001 mi.)***	***A85***	***155***
10-10 TRUCK STOP	195 E VALLEY RIALTO CA	W 0 - 1/8 (0.069 mi.)	A122	221
CUMMINS WEST INC	***161 E VALLEY BLVD***	***W 0 - 1/8 (0.089 mi.)***	***M131***	***226***
JUST GAS INC	***102 E VALLEY BLVD***	***W 0 - 1/8 (0.118 mi.)***	***M142***	***234***
CHEVRON STATION #6969	101 E VALLEY BLVD	W 0 - 1/8 (0.119 mi.)	M146	240
THRIFTY OIL CO #323	***111 W VALLEY***	***W 1/8 - 1/4 (0.144 mi.)***	***M181***	***278***
PAUL HUBBS CONSTRUCTION CO.	***140 W VALLEY BLVD***	***W 1/8 - 1/4 (0.188 mi.)***	***M200***	***296***
CLEMONS, G.	***213 W VALLEY BLVD***	***W 1/4 - 1/2 (0.270 mi.)***	***Y214***	***308***
FEDERAL EXPRESS CORP	280 W VALLEY BLVD	W 1/4 - 1/2 (0.350 mi.)	Y254	350
ABILITY HEAVY MOVERS INC	***285 W VALLEY BLVD***	***W 1/4 - 1/2 (0.354 mi.)***	***Y258***	***352***
R THOMPSON TRUCKING	***1743 S WILLOW***	***W 1/4 - 1/2 (0.375 mi.)***	***Y260***	***353***
FAT EQUIP RENTAL INC	***350 W VALLEY BLVD***	***W 1/4 - 1/2 (0.439 mi.)***	***AH357***	***1622***
POMA DISTRIBUTING CO., INC.	***2095 S RIVERSIDE AVE***	***SW 1/4 - 1/2 (0.469 mi.)***	***AM370***	***1634***

HIST UST: Historical UST Registered Database.

A review of the HIST UST list, as provided by EDR, and dated 10/15/1990 has revealed that there are 28 HIST UST sites within approximately 0.75 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
DOOR COMPANY OF SAN BERNARDINO	***1591 S LILAC AVE***	***W 1/2 - 1 (0.626 mi.)***	***BB424***	***1731***
DON BONANNO-CITRUS CO.	***585 W VALLEY BLVD***	***W 1/2 - 1 (0.699 mi.)***	***BG464***	***1807***

Lower Elevation	Address	Direction / Distance	Map ID	Page
WESTERN EXTERMINATOR COMPANY	1998 W VALLEY BLVD	0 - 1/8 (0.000 mi.)	D5	12
ZAKARIA HAGGAG	1600 W VALLEY BLVD	0 - 1/8 (0.000 mi.)	K66	128
INLAND EMPIRE TOYOTA	***1700 VALLEY RD***	***0 - 1/8 (0.000 mi.)***	***F79***	***146***
INLAND EMPIRE EQUIPT, INC	***1762 S SYCAMORE***	***0 - 1/8 (0.001 mi.)***	***A85***	***155***
10-10 TRUCK STOP	195 E VALLEY RIALTO, CA	W 0 - 1/8 (0.069 mi.)	A120	218
CUMMINS WEST INC	***161 E VALLEY BLVD***	***W 0 - 1/8 (0.089 mi.)***	***M131***	***226***
SOUTHERN CALIF. BISHOPS CENTRA	***9908 PEPPER AVE***	***SE 0 - 1/8 (0.113 mi.)***	***P141***	***233***
96969	***101 E VALLEY BLVD***	***W 0 - 1/8 (0.119 mi.)***	***M147***	***241***
ARCO STN. #323	111 W VALLEY BLVD	W 1/8 - 1/4 (0.144 mi.)	M178	275
CIRCLE K STORE #627	***990 VALLEY BLVD***	***ESE 1/8 - 1/4 (0.168 mi.)***	***T195***	***291***
PAUL HUBBS CONSTRUCTION CO.	140 W VALLEY BLVD	W 1/8 - 1/4 (0.188 mi.)	M199	295
CLEM-TRANS, INC.	***213 W VALLEY BLVD***	***W 1/4 - 1/2 (0.270 mi.)***	***Y215***	***309***
DUNCAN BROS., INC.	1966 S DATE AVE	SW 1/4 - 1/2 (0.276 mi.)	W224	328
RIALTO RUBBISH	210 CAMERON WAY	SW 1/4 - 1/2 (0.287 mi.)	W232	335
PETROLANE	***1975 S RIVERSIDE AVE***	***WSW 1/4 - 1/2 (0.346 mi.)***	***AB248***	***347***
STORMRIALTO	***271 E. SLOVER AVENUE***	***SW 1/4 - 1/2 (0.406 mi.)***	***AF309***	***421***
COLTON TERMINAL	1901 SLOVER AVENUE	SSW 1/4 - 1/2 (0.408 mi.)	AL317	433
GATX	***PEPPER AVE/SLOVER ST***	***SSE 1/4 - 1/2 (0.417 mi.)***	***AO331***	***910***
BALTAZAR CERVANTES	***792 W VALLEY BLVD***	***ESE 1/2 - 1 (0.520 mi.)***	***AR381***	***1647***
COLTON HIGH SCHOOL (BUS GARAGE	***777 W VALLEY BLVD***	***ESE 1/2 - 1 (0.559 mi.)***	***AW389***	***1655***
COLTON SALES TERMINAL	2237 S. RIVERSIDE AVE.	SW 1/2 - 1 (0.562 mi.)	AX393	1668
PENHALL INTERNATIONAL	***2190 S RIVERSIDE AVE***	***SW 1/2 - 1 (0.563 mi.)***	***AX397***	***1670***
WEST COLTON YD.	2078 S WILLOW AVE	WSW 1/2 - 1 (0.602 mi.)	AZ412	1682
CHEVRON USA INC COLTON SUPPLY	***2297 S. RIVERSIDE AVE.***	***SW 1/2 - 1 (0.605 mi.)***	***AX413***	***1684***
UNOCAL CORP	***2301 S RIVERSIDE AVE***	***SW 1/2 - 1 (0.633 mi.)***	***AX430***	***1740***

EXECUTIVE SUMMARY

Lower Elevation	Address	Direction / Distance	Map ID	Page
COLTON TERMINAL	***2359 RIVERSIDE AVE***	***SW 1/2 - 1 (0.738 mi.)***	***BC477***	***1820***

SWEEPS UST: Statewide Environmental Evaluation and Planning System. This underground storage tank listing was updated and maintained by a company contacted by the SWRCB in the early 1990's. The listing is no longer updated or maintained. The local agency is the contact for more information on a site on the SWEEPS list.

A review of the SWEEPS UST list, as provided by EDR, and dated 06/01/1994 has revealed that there are 44 SWEEPS UST sites within approximately 0.75 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
HALSEY MACHINERY	***1485 S WILLOW***	***W 1/4 - 1/2 (0.401 mi.)***	***AG291***	***396***
DOOR COMPANY OF SAN BERNARDINO	***1591 S LILAC AVE***	***W 1/2 - 1 (0.626 mi.)***	***BB424***	***1731***
DON BONANNO-CITRUS CO.	***585 W VALLEY BLVD***	***W 1/2 - 1 (0.699 mi.)***	***BG464***	***1807***

Lower Elevation	Address	Direction / Distance	Map ID	Page
I-10 TRUCK STOP	***195 E VALLEY BLVD***	***0 - 1/8 (0.000 mi.)***	***A1***	***8***
SAMMON'S TRUCKING	1988 W VALLEY BLVD	0 - 1/8 (0.000 mi.)	D14	49
OROWEAT FOODS CO/RIALTO	2036 W VALLEY BLVD	0 - 1/8 (0.000 mi.)	C27	59
PRICE CLUB	2109 W VALLEY	0 - 1/8 (0.000 mi.)	C29	60
BISHOP'S CENTRAL STORES	***791 N PEPPER AVE***	***0 - 1/8 (0.000 mi.)***	***E50***	***77***
VALLEY TRUCK FILTERS & PARTS	***2006 W VALLEY BLVD***	***0 - 1/8 (0.000 mi.)***	***D56***	***82***
SHELL SERVICE STATION	***1600 W VALLEY***	***0 - 1/8 (0.000 mi.)***	***K74***	***137***
INLAND EMPIRE TOYOTA	***1700 VALLEY RD***	***0 - 1/8 (0.000 mi.)***	***F79***	***146***
NEW WEST CONSOLIDATED, INC.	***1700 W VALLEY BLVD***	***0 - 1/8 (0.000 mi.)***	***F82***	***153***
INLAND EMPIRE EQUIPT, INC	***1762 S SYCAMORE***	***0 - 1/8 (0.001 mi.)***	***A85***	***155***
10-10 TRUCK STOP	195 E VALLEY RIALTO CA	W 0 - 1/8 (0.069 mi.)	A121	219
CUMMINS WEST INC	***161 E VALLEY BLVD***	***W 0 - 1/8 (0.089 mi.)***	***M131***	***226***
SOUTHERN CALIF. BISHOPS CENTRA	***9908 PEPPER AVE***	***SE 0 - 1/8 (0.113 mi.)***	***P141***	***233***
JUST GAS INC	***102 E VALLEY BLVD***	***W 0 - 1/8 (0.118 mi.)***	***M142***	***234***
CHEVRON STATION #6969	101 E VALLEY BLVD	W 0 - 1/8 (0.119 mi.)	M148	243
THRIFTY OIL CO #323	***111 W VALLEY***	***W 1/8 - 1/4 (0.144 mi.)***	***M181***	***278***
PAUL HUBBS CONSTRUCTION CO.	***140 W VALLEY BLVD***	***W 1/8 - 1/4 (0.188 mi.)***	***M200***	***296***
SOUTHERN PACIFIC TRAN/CLT	***200 MARION WAY***	***SW 1/8 - 1/4 (0.233 mi.)***	***V207***	***300***
CIRCLE K #627	990 VALLEY BLVD	ESE 1/4 - 1/2 (0.251 mi.)	T208	304
CLEMONS, G.	***213 W VALLEY BLVD***	***W 1/4 - 1/2 (0.270 mi.)***	***Y214***	***308***
DUNCAN BROS INC	***1966 S DATE ST***	***SW 1/4 - 1/2 (0.276 mi.)***	***W221***	***313***
RIALTO RUBBISH	210 E CAMERON	SW 1/4 - 1/2 (0.339 mi.)	W244	344
FEDERAL EXPRESS CORP	***280 W VALLEY BLVD***	***W 1/4 - 1/2 (0.350 mi.)***	***Y255***	***350***
ABILITY HEAVY MOVERS INC	***285 W VALLEY BLVD***	***W 1/4 - 1/2 (0.354 mi.)***	***Y258***	***352***
R THOMPSON TRUCKING	***1743 S WILLOW***	***W 1/4 - 1/2 (0.375 mi.)***	***Y260***	***353***
CALNEV PIPE LINE COMPANY COLTO	***2051 E SLOVER AVE***	***SSW 1/4 - 1/2 (0.401 mi.)***	***AI277***	***372***
GENERAL AMERICAN TRANSPORTATIO	***PEPPER ST & CLOVER AVE***	***SSE 1/4 - 1/2 (0.429 mi.)***	***AQ338***	***1604***
FAT EQUIP RENTAL INC	***350 W VALLEY BLVD***	***W 1/4 - 1/2 (0.439 mi.)***	***AH357***	***1622***
POMA DISTRIBUTING CO., INC.	***2095 S RIVERSIDE AVE***	***SW 1/4 - 1/2 (0.469 mi.)***	***AM370***	***1634***
BALTAZAR CERVANTES	***792 W VALLEY BLVD***	***ESE 1/2 - 1 (0.520 mi.)***	***AR381***	***1647***
STOROS, WALTER	801 N RANCHO	E 1/2 - 1 (0.527 mi.)	AT382	1650
COLTON HIGH SCHOOL (BUS GARAGE	***777 W VALLEY BLVD***	***ESE 1/2 - 1 (0.559 mi.)***	***AW389***	***1655***
TEXACO USA-COLTON TERMINAL	***2237 S RIVERSIDE AVE***	***SW 1/2 - 1 (0.562 mi.)***	***AX391***	***1660***
PENHALL INTERNATIONAL	***2190 S RIVERSIDE AVE***	***SW 1/2 - 1 (0.563 mi.)***	***AX397***	***1670***
CHEVRON USA INC COLTON SUPPLY	***2297 S. RIVERSIDE AVE.***	***SW 1/2 - 1 (0.605 mi.)***	***AX413***	***1684***
EL TORO SPICES	1730 S LILAC	W 1/2 - 1 (0.627 mi.)	AY425	1731
MORENO VALLEY SEPTIC SVC	1770 S LILAC	W 1/2 - 1 (0.632 mi.)	AY428	1739

Lower Elevation	Address	Direction / Distance	Map ID	Page
UNOCAL CORP	***2301 S RIVERSIDE AVE***	***SW 1/2 - 1 (0.633 mi.)***	***AX430***	***1740***
MOBIL FAC. #04-086 /COLTON TER	***2305 S RIVERSIDE AVE***	***SW 1/2 - 1 (0.660 mi.)***	***AX445***	***1770***
SHELL OIL CO	***2307 RIVERSIDE AVE***	***SW 1/2 - 1 (0.670 mi.)***	***BC448***	***1778***
SFPP, L.P.	***2359 S RIVERSIDE AVE***	***SW 1/2 - 1 (0.738 mi.)***	***BC476***	***1816***

Records of Emergency Release Reports

HMIRS: The Hazardous Materials Incident Report System contains hazardous material spill incidents reported to the Department of Transportation. The source of this database is the U.S. EPA.

A review of the HMIRS list, as provided by EDR, and dated 12/31/2012 has revealed that there are 10 HMIRS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
Not reported	1849 W VALLEY BLVD	0 - 1/8 (0.000 mi.)	B39	66
Not reported	1849 W VALLEY BLVD	0 - 1/8 (0.000 mi.)	B42	69
Not reported	1849 WEST VALLEY BLVD	0 - 1/8 (0.000 mi.)	B52	79

Lower Elevation	Address	Direction / Distance	Map ID	Page
Not reported	280 WEST VALLEY BLVD	W 1/4 - 1/2 (0.350 mi.)	Y250	349
Not reported	280 W. VALLEY BLVD	W 1/4 - 1/2 (0.350 mi.)	Y251	349
280 W VALLEY BLVD	280 W VALLEY BLVD	W 1/4 - 1/2 (0.350 mi.)	Y252	349
280 W. VALLEY BLVD	280 W. VALLEY BLVD	W 1/4 - 1/2 (0.350 mi.)	Y253	349
Not reported	280 W VALLEY BLVD	W 1/4 - 1/2 (0.350 mi.)	Y257	352
Not reported	1900 SLOVER AVE	SSW 1/4 - 1/2 (0.408 mi.)	AL315	432
Not reported	1900 SLOVER AVE	SSW 1/4 - 1/2 (0.408 mi.)	AL318	434

CHMIRS: The California Hazardous Material Incident Report System contains information on reported hazardous material incidents, i.e., accidental releases or spills. The source is the California Office of Emergency Services.

A review of the CHMIRS list, as provided by EDR, and dated 12/06/2012 has revealed that there are 25 CHMIRS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
Not reported Date Completed: 20-FEB-88	CORNER OF PEPPER/SAN BE	0 - 1/8 (0.000 mi.)	I53	79
Not reported Date Completed: 08-AUG-90	1521 S. RIVERSIDE	W 1/8 - 1/4 (0.136 mi.)	S172	271
Not reported Date Completed: 16-FEB-88	1200 BLK N RIVERSIDE	WNW 1/4 - 1/2 (0.332 mi.)	242	343

Lower Elevation	Address	Direction / Distance	Map ID	Page
Not reported	2111 W. VALLEY BLVD	0 - 1/8 (0.000 mi.)	C10	45
Not reported	2111 W. VALLEY BLVD.	0 - 1/8 (0.000 mi.)	C20	53
Not reported	2111 WEST VALLEY BLVD.	0 - 1/8 (0.000 mi.)	C46	74
Not reported	1599 VALLEY BLVD	0 - 1/8 (0.000 mi.)	K72	134
Not reported	400 N. PEPPER AVE	ESE 0 - 1/8 (0.013 mi.)	K109	208

Lower Elevation	Address	Direction / Distance	Map ID	Page
Not reported	9900 PEPPER ST	SE 0 - 1/8 (0.106 mi.)	P139	231
Not reported	220 W. VALLEY BLVD	W 1/4 - 1/2 (0.279 mi.)	Y228	330
Date Completed: 28-JUN-89				
Not reported	1800 SOUTH RIVERSIDE AV	WSW 1/4 - 1/2 (0.280 mi.)	AB229	332
Not reported	2000 SOUTH SYCAMORE AVE	SW 1/4 - 1/2 (0.317 mi.)	V238	339
Not reported	2051 SLOWER AVENUE	SW 1/4 - 1/2 (0.390 mi.)	AF264	355
Date Completed: 27-AUG-90				
Not reported	2051 EAST SLOVER AVE	SSW 1/4 - 1/2 (0.401 mi.)	AI276	368
Not reported	2051 EAST SLOVER	SSW 1/4 - 1/2 (0.401 mi.)	AI281	386
Not reported	CAL NEV COLTON TERMINAL	SSW 1/4 - 1/2 (0.401 mi.)	AI287	393
Not reported	2051 E SLOVER AVE.	SSW 1/4 - 1/2 (0.401 mi.)	AI294	403
Not reported	2051 W. SLOVER AVE.	SSW 1/4 - 1/2 (0.401 mi.)	AI296	404
Not reported	2051 W. SLOVER AVE	SSW 1/4 - 1/2 (0.401 mi.)	AI298	406
Date Completed: 31-AUG-89				
Not reported	2051 EAST SLOBER AVE	SSW 1/4 - 1/2 (0.401 mi.)	AI301	408
Not reported	1800 SLOVER AVE	S 1/4 - 1/2 (0.413 mi.)	AN321	435
Not reported	20878 SLOVER	SSE 1/4 - 1/2 (0.417 mi.)	AO328	681
Not reported	PEPPER & SLOVER ST	SSE 1/4 - 1/2 (0.429 mi.)	AQ340	1607
Not reported	PEPPER & SLOVER AVE.	SSE 1/4 - 1/2 (0.430 mi.)	AQ343	1614
Not reported	379 W. VALLEY BLVD.	W 1/4 - 1/2 (0.478 mi.)	AH372	1636

LDS: The Land Disposal program regulates of waste discharge to land for treatment, storage and disposal in waste management units.

A review of the LDS list, as provided by EDR, and dated 03/18/2013 has revealed that there is 1 LDS site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
BRINE FAC,COLTON	20870 SLOVER	SSE 1/4 - 1/2 (0.420 mi.)	AO334	1600

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 02/12/2013 has revealed that there are 7 RCRA NonGen / NLR sites within approximately 0.75 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
MOSS BROS FORD	***1900 W VALLEY BLVD***	***0 - 1/8 (0.000 mi.)***	***B41***	***67***
GRACE WR & CO DISTRIB SVCS	***1988 W VALLEY BLVD***	***0 - 1/8 (0.000 mi.)***	***D54***	***81***
GOLDEN L OIL CO	***850 WEST C ST***	***E 1/4 - 1/2 (0.443 mi.)***	***AT359***	***1625***
PRESTIGE STATIONS INC NO 0781	***792 W VALLEY BLVD***	***ESE 1/2 - 1 (0.520 mi.)***	***AR379***	***1646***
INTEGRATED WASTE MGMT	***2230 S RIVERSIDE AVE***	***SW 1/2 - 1 (0.606 mi.)***	***AX415***	***1687***
ENVIRONMENTAL LOGISTICS INC	***140 W MONTE AVE***	***SW 1/2 - 1 (0.628 mi.)***	***AX426***	***1732***
STATE OF CALIF RIALTO SHOP	***170 W MINDANAO ST***	***SW 1/2 - 1 (0.672 mi.)***	***BC454***	***1795***

FTTS: FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act) over the previous five years. To maintain currency, EDR contacts the Agency on a quarterly basis.

A review of the FTTS list, as provided by EDR, and dated 04/09/2009 has revealed that there are 2 FTTS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
WAL-MART #2401	***1600 S MOUNTAIN***	***W 1/8 - 1/4 (0.134 mi.)***	***S163***	***258***
Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
COLTON JOINT UNIFIED SCHOOL DI	***1313 W VALLEY BLVD***	***0 - 1/8 (0.000 mi.)***	***J81***	***152***

HIST FTTS: A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

A review of the HIST FTTS list, as provided by EDR, and dated 10/19/2006 has revealed that there are 2 HIST FTTS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
WAL-MART #2401	***1600 S MOUNTAIN***	***W 1/8 - 1/4 (0.134 mi.)***	***S163***	***258***
Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
COLTON JOINT UNIFIED SCHOOL DI	***1313 W VALLEY BLVD***	***0 - 1/8 (0.000 mi.)***	***J81***	***152***

ICIS: The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

A review of the ICIS list, as provided by EDR, and dated 07/20/2011 has revealed that there is 1 ICIS site within approximately 0.5 miles of the target property.

Lower Elevation	Address		Direction / Distance	Map ID	Page
ALLIANCE COLTON - DREWS SUBSTA	559 PEPPER AVE	COLTO	ESE 0 - 1/8 (0.002 mi.)	K95	174

FINDS: The Facility Index System contains both facility information and "pointers" to other sources of information that contain more detail. These include: RCRIS; Permit Compliance System (PCS); Aerometric Information Retrieval System (AIRS); FATES (FIFRA [Federal Insecticide Fungicide Rodenticide Act] and TSCA Enforcement System, FTTS [FIFRA/TSCA Tracking System]; CERCLIS; DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes); Federal Underground Injection Control (FURS); Federal Reporting Data System (FRDS); Surface Impoundments (SIA); TSCA Chemicals in Commerce Information System (CICS); PADS; RCRA-J (medical waste transporters/disposers); TRIS; and TSCA. The source of this database is the U.S. EPA/NTIS.

A review of the FINDS list, as provided by EDR, and dated 10/23/2011 has revealed that there are 36

EXECUTIVE SUMMARY

FINDS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
WORLD PROPHETIC MINISTRY	***1099 N PEPPER AVE***	***NNE 0 - 1/8 (0.061 mi.)***	***I115***	***214***
KRAGEN AUTO PARTS	1100 N. PEPPER AVENUE	NNE 0 - 1/8 (0.088 mi.)	I129	225
WALMART NO 1862	1610 S RIVERSIDE AVE	W 1/8 - 1/4 (0.134 mi.)	S162	257
WAL-MART #2401	***1600 S MOUNTAIN***	***W 1/8 - 1/4 (0.134 mi.)***	***S163***	***258***
WAL-MART #1862	1610 SOUTH RIVERSIDE AV	W 1/8 - 1/4 (0.134 mi.)	S169	268
WILLIAM G. JEHUE MIDDLE	1500 NORTH EUCALYPTUS A	N 1/4 - 1/2 (0.433 mi.)	AS347	1616

Lower Elevation	Address	Direction / Distance	Map ID	Page
MOSS BROTHERS FORD	***1900 W VALLEY BLVD***	***0 - 1/8 (0.000 mi.)***	***B13***	***48***
TELCO FOOD PRODUCTS	2111 WEST VALLEY BLVD.	0 - 1/8 (0.000 mi.)	C26	59
UNIVERSAL MACK SALES SERVICE	***220 N REX FORD***	***0 - 1/8 (0.000 mi.)***	***F34***	***63***
GRACE WR & CO DISTRIB SVCS	***1988 W VALLEY BLVD***	***0 - 1/8 (0.000 mi.)***	***D54***	***81***
SLOVER MOUNTAIN HIGH (CONTINUA	325 HERMOSA ST	0 - 1/8 (0.000 mi.)	G58	124
SHELL SERVICE STATION	***1600 W VALLEY***	***0 - 1/8 (0.000 mi.)***	***K74***	***137***
B AND G AUTO SALES	***1630 W VALLEY BLVD***	***0 - 1/8 (0.000 mi.)***	***K76***	***142***
INLAND EMPIRE TOYOTA	***1700 VALLEY RD***	***0 - 1/8 (0.000 mi.)***	***F79***	***146***
CLARKLIFT OF CALIFORNIA INC	1762 S SYCAMORE	0 - 1/8 (0.001 mi.)	A86	158
PUREENERGY OPERATING SERVICES	***559 PEPPER AVE***	***ESE 0 - 1/8 (0.002 mi.)***	***K92***	***164***
ALLIANCE COLTON - DREWS SUBSTA	559 PEPPER AVE	ESE 0 - 1/8 (0.002 mi.)	K96	175
PURENERGY OPERATING SERVICES,	559 PEPPER AVE	ESE 0 - 1/8 (0.002 mi.)	K97	175
MCNEILUS TRUCK & MANUFACTURING	401 N. PEPPER AVE.	ESE 0 - 1/8 (0.003 mi.)	K98	176
ARROWHEAD REGIONAL MEDICAL CEN	***400 W PEPPER ST***	***ESE 0 - 1/8 (0.013 mi.)***	***K105***	***190***
P S TRUCK SUPPLY INC	***245 E VALLEY BLVD***	***W 0 - 1/8 (0.045 mi.)***	***A113***	***212***
CHEVRON STATION NO 96969	***101 E VALLEY BLVD***	***W 0 - 1/8 (0.119 mi.)***	***M149***	***245***
ARCO FACILITY NO 09695	***111 W VALLEY BLVD***	***W 1/8 - 1/4 (0.144 mi.)***	***M183***	***282***
CIRCLE K STORE #627	***990 VALLEY BLVD***	***ESE 1/8 - 1/4 (0.168 mi.)***	***T195***	***291***
DUNCAN BROS INC	***1966 S DATE ST***	***SW 1/4 - 1/2 (0.276 mi.)***	***W221***	***313***
DALE JONES PHOTOGRAPHY	***915 W C ST***	***E 1/4 - 1/2 (0.316 mi.)***	***AD237***	***337***
WHITING DOOR MANUFACTURING COR	311 VALLEY BL	W 1/4 - 1/2 (0.391 mi.)	AH265	357
WHITING DOOR MFG CORP	***311 W VALLEY BLVD***	***W 1/4 - 1/2 (0.391 mi.)***	***AH266***	***357***
CALNEV PIPE LINE COMPANY COLTO	***2051 E SLOVER AVE***	***SSW 1/4 - 1/2 (0.401 mi.)***	***AI277***	***372***
KINDER MORGAN COLTON TERMINAL	2051 E SLOVER AVENUE	SSW 1/4 - 1/2 (0.401 mi.)	AI279	385
CONOCOPHILLIPS COLTON TERMINAL	2050 SLOVER AVENUE	SSW 1/4 - 1/2 (0.402 mi.)	AI306	413
CONOCO PHILLIPS COLTON TERMINA	***271 E SLOVER AVE***	***SW 1/4 - 1/2 (0.406 mi.)***	***AF308***	***414***
GATX CORPORATION	20878 SLOVER	SSE 1/4 - 1/2 (0.417 mi.)	AO330	909
GATX	***PEPPER AVE/SLOVER ST***	***SSE 1/4 - 1/2 (0.417 mi.)***	***AO331***	***910***
DOUGLAS TRUCKING	350 W VALLEY BLVD	W 1/4 - 1/2 (0.439 mi.)	AH354	1621
GOLDEN L OIL CO	***850 WEST C ST***	***E 1/4 - 1/2 (0.443 mi.)***	***AT359***	***1625***

RMP: When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

A review of the RMP list, as provided by EDR, and dated 05/08/2012 has revealed that there are 6 RMP

sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CSM BAKERY PRODUCTS	2111 WEST VALLEY BLVD.	0 - 1/8 (0.000 mi.)	C7	13
TELCO FOOD PRODUCTS, INC.	2111 WEST VALLEY BLVD.	0 - 1/8 (0.000 mi.)	C57	83
ARRHOWHEAD REGIONAL MEDICAL CE	400 NORTH PEPPER	ESE 0 - 1/8 (0.013 mi.)	K102	181
GATX - COLTON, CA TANK CAR FAC	20878 SLOVER AVENUE	SSE 1/4 - 1/2 (0.417 mi.)	AO327	462
GATX RAIL - COLTON, CA TANK CA	20878 SLOVER AVENUE	SSE 1/4 - 1/2 (0.417 mi.)	AO329	683
GATC - COLTON, CA TANK CAR FAC	20878 SLOVER AVENUE	SSE 1/4 - 1/2 (0.417 mi.)	AO332	921

UIC: A listing of underground control injection wells.

A review of the UIC list, as provided by EDR, and dated 03/05/2013 has revealed that there is 1 UIC site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
R. A. DEAN & ASSOC.		ENE 1/8 - 1/4 (0.227 mi.)	206	300

NPDES: A listing of NPDES permits, including stormwater.

A review of the NPDES list, as provided by EDR, and dated 05/20/2013 has revealed that there are 12 NPDES sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
1062 S RIVERSIDE AVE	1062 S RIVERSIDE AVE	NW 1/4 - 1/2 (0.378 mi.)	AC261	354

Lower Elevation	Address	Direction / Distance	Map ID	Page
BEST BRAND CORP	***2111 W VALLEY BLVD***	***0 - 1/8 (0.000 mi.)***	***C59***	***124***
COLTON MEDICAL BUILDING	1405 W VALLEY BLVD	0 - 1/8 (0.000 mi.)	J64	128
UNITED RENTALS BRANCH 513	1690 VALLEY BLVD	0 - 1/8 (0.000 mi.)	F68	130
DREWS ENERGY FACILITY	***559 S PEPPER AVE***	***ESE 0 - 1/8 (0.002 mi.)***	***K93***	***171***
MCNEILUS TRUCK & MFG INC	***401 N PEPPER AVE***	***ESE 0 - 1/8 (0.003 mi.)***	***K100***	***178***
COLTON OFFICE PLAZA	105 CYPRESS AVE	ESE 1/8 - 1/4 (0.147 mi.)	T184	283
WHITING DOOR MANUFACTURING COR	113 WEST VALLEY BLVD	W 1/8 - 1/4 (0.147 mi.)	M185	284
VULCAN STEEL COMPANY	2038 S SYCAMORE AVE	SW 1/4 - 1/2 (0.348 mi.)	AF249	348
FED EX	***280 W VALLEY BLVD***	***W 1/4 - 1/2 (0.350 mi.)***	***Y256***	***351***
CONOCO PHILLIPS CO. - COLTON T	***271 E. SLOVER AVE.***	***SW 1/4 - 1/2 (0.407 mi.)***	***AF311***	***423***
A & M AUTO REPAIR	***2075 S RIVERSIDE AVE***	***SW 1/4 - 1/2 (0.412 mi.)***	***AM320***	***434***

Cortese: The sites for the list are designated by the State Water Resource Control Board (LUST), the Integrated Waste Board (SWF/LS), and the Department of Toxic Substances Control (Cal-Sites).

A review of the Cortese list, as provided by EDR, and dated 04/01/2013 has revealed that there is 1 Cortese site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
GW CLEANUP-COLTON TERMINA	***2301 RIVERSIDE***	***SW 1/2 - 1 (0.633 mi.)***	***AX431***	***1745***

EXECUTIVE SUMMARY

HIST CORTESE: The sites for the list are designated by the State Water Resource Control Board [LUST], the Integrated Waste Board [SWF/LS], and the Department of Toxic Substances Control [CALSITES]. This listing is no longer updated by the state agency.

A review of the HIST CORTESE list, as provided by EDR, and dated 04/01/2001 has revealed that there are 3 HIST CORTESE sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
RIALTO, CITY OF (TEXACO)	***102 VALLEY***	***WSW 1/8 - 1/4 (0.133 mi.)***	***M160***	***256***
TEXACO SERVICE STATION	***120 VALLEY***	***W 1/8 - 1/4 (0.155 mi.)***	***M191***	***287***
SOUTHERN PACIFIC TRAN/CLT	***200 MARION WAY***	***SW 1/8 - 1/4 (0.233 mi.)***	***V207***	***300***

San Bern. Co. Permit: San Bernardino County Fire Department Hazardous Materials Division.

A review of the San Bern. Co. Permit list, as provided by EDR, and dated 03/04/2013 has revealed that there are 81 San Bern. Co. Permit sites within approximately 0.75 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
AMCAL AUTOMOTIVE	320 REXFORD ST	0 - 1/8 (0.000 mi.)	F16	50
5-STAR AUTO BODY	319 REXFORD ST	0 - 1/8 (0.000 mi.)	F24	57
REPUBLIC MACHINE & FABRICATION	313 REXFORD ST	0 - 1/8 (0.000 mi.)	F36	64
CARPENTERS JOINT APPRENT & TRN	1750 SAN BERNARDINO AVE	N 0 - 1/8 (0.002 mi.)	L90	162
O'REILLY AUTO PARTS #3681	1100 N PEPPER AVE	NNE 0 - 1/8 (0.088 mi.)	I127	224
FOOD 4 LESS #786	***1150 N PEPPER AVE***	***NNE 1/8 - 1/4 (0.126 mi.)***	***Q154***	***250***
WAL-MART #1862	1610 S RIVERSIDE AVE	W 1/8 - 1/4 (0.134 mi.)	S161	257
CRESTVIEW CONVALESCENT HOSPITA	1471 S RIVERSIDE AVE	W 1/8 - 1/4 (0.136 mi.)	S173	272
RIALTO MED SUPPLIES INC	1517 S RIVERSIDE AVE	W 1/8 - 1/4 (0.136 mi.)	S174	272
FOOD 4 LESS GAS STATION	1170 N PEPPER AVE	NNE 1/8 - 1/4 (0.141 mi.)	Q176	273
HALSEY MACHINERY	***1485 S WILLOW***	***W 1/4 - 1/2 (0.401 mi.)***	***AG291***	***396***
WEST VALLEY WATER DIST WELL #4	295 W SAN BERNARDINO AV	WNW 1/4 - 1/2 (0.487 mi.)	374	1638
PRECISION TURBOCHARGER CO.	450 W VALLEY BLVD	W 1/2 - 1 (0.563 mi.)	AY398	1671
DISCOUNT TIRE CENTER	484 W VALLEY BLVD	W 1/2 - 1 (0.597 mi.)	AY410	1681
RESIDENCE	515 W VALLEY BLVD	W 1/2 - 1 (0.620 mi.)	AY420	1729
AGENCY AUTOMOTIVE, INC.	***1611 S LILAC AVE***	***W 1/2 - 1 (0.625 mi.)***	***BB422***	***1730***
PACIFIC ORNAMENTAL IRON	1625 S LILAC AVE	W 1/2 - 1 (0.626 mi.)	BB423	1730
FRITO-LAY SALES, LP	635 W VALLEY BLVD	W 1/2 - 1 (0.738 mi.)	BG473	1814
WEST VALLEY WATER DIST ZONE 2-	691 S EUCALYPTUS	N 1/2 - 1 (0.744 mi.)	479	1828

Lower Elevation	Address	Direction / Distance	Map ID	Page
I-10 TRUCK STOP	***195 E VALLEY BLVD***	***0 - 1/8 (0.000 mi.)***	***A1***	***8***
MOSS BROTHERS FORD	***1900 W VALLEY BLVD***	***0 - 1/8 (0.000 mi.)***	***B13***	***48***
ENTENMANN'S OROWHEAT	2036 W VALLEY BLVD	0 - 1/8 (0.000 mi.)	C15	50
COLTON GOLF COURSE	1901 VALLEY BLVD	0 - 1/8 (0.000 mi.)	B17	51
LANDJET MOTOR CARRIERS	2048 W VALLEY BLVD	0 - 1/8 (0.000 mi.)	C48	76
BISHOP'S CENTRAL STORES	***791 N PEPPER AVE***	***0 - 1/8 (0.000 mi.)***	***E50***	***77***
VALLEY TRUCK FILTERS & PARTS	***2006 W VALLEY BLVD***	***0 - 1/8 (0.000 mi.)***	***D56***	***82***
BEST BRAND CORP	***2111 W VALLEY BLVD***	***0 - 1/8 (0.000 mi.)***	***C59***	***124***
AT&T MOBILITY COLTON #13829	1205 1/2 W VALLEY BLVD	0 - 1/8 (0.000 mi.)	G61	127
ACACIA RV PERFORMANCE CENTER	295 N HERMOSA	0 - 1/8 (0.000 mi.)	G67	129
SHELL SERVICE STATION	***1600 W VALLEY***	***0 - 1/8 (0.000 mi.)***	***K74***	***137***
COLTON JOINT USD WAREHOUSE	1313 W VALLEY BLVD	0 - 1/8 (0.000 mi.)	J75	141
B AND G AUTO SALES	***1630 W VALLEY BLVD***	***0 - 1/8 (0.000 mi.)***	***K76***	***142***
BAKER'S DRIVE THRU #117	1620 W VALLEY BLVD	0 - 1/8 (0.000 mi.)	K77	145
INLAND EMPIRE TOYOTA	***1700 VALLEY RD***	***0 - 1/8 (0.000 mi.)***	***F79***	***146***
WEST VALLEY WATER DIST WELL #1	1783 S SYCAMORE AVE	0 - 1/8 (0.000 mi.)	84	155

EXECUTIVE SUMMARY

Lower Elevation	Address	Direction / Distance	Map ID	Page
INLAND EMPIRE EQUIPT, INC	***1762 S SYCAMORE***	***0 - 1/8 (0.001 mi.)***	***A85***	***155***
DREWS ENERGY FACILITY	***559 S PEPPER AVE***	***ESE 0 - 1/8 (0.002 mi.)***	***K93***	***171***
MCNEILUS TRUCK & MFG INC	***401 N PEPPER AVE***	***ESE 0 - 1/8 (0.003 mi.)***	***K100***	***178***
ARROWHEAD REGIONAL MED CTR	***400 N PEPPER AVE***	***ESE 0 - 1/8 (0.013 mi.)***	***K106***	***203***
CLUTCH MASTERS	267 E VALLEY BLVD	WSW 0 - 1/8 (0.034 mi.)	A110	210
LUCKY FARMS	245 E VALLEY BLVD	W 0 - 1/8 (0.045 mi.)	A112	212
CUMMINS WEST INC	***161 E VALLEY BLVD***	***W 0 - 1/8 (0.089 mi.)***	***M131***	***226***
96969	***101 E VALLEY BLVD***	***W 0 - 1/8 (0.119 mi.)***	***M147***	***241***
THRIFTY OIL CO #323	***111 W VALLEY***	***W 1/8 - 1/4 (0.144 mi.)***	***M181***	***278***
HOMETOWN BUFFET #753	127 W VALLEY BLVD	W 1/8 - 1/4 (0.164 mi.)	M193	290
DUNCAN BROS INC	1966 S DATE	SW 1/4 - 1/2 (0.258 mi.)	W209	304
VULCAN STEEL CO	270 E CAMERON WAY	SW 1/4 - 1/2 (0.264 mi.)	V211	305
CLEM-TRANS, INC.	***213 W VALLEY BLVD***	***W 1/4 - 1/2 (0.270 mi.)***	***Y215***	***309***
DUNCAN BROS INC	***1966 S DATE ST***	***SW 1/4 - 1/2 (0.276 mi.)***	***W221***	***313***
RIALTO RUBBISH SERVICES INC	210 E CAMERON WAY	SW 1/4 - 1/2 (0.338 mi.)	W243	344
FED EX	***280 W VALLEY BLVD***	***W 1/4 - 1/2 (0.350 mi.)***	***Y256***	***351***
VERIZON WIRELESS (SITE:RIALTO)	1531 S WILLOW AVE	W 1/4 - 1/2 (0.387 mi.)	AG263	355
WHITING DOOR MFG CORP	***311 W VALLEY BLVD***	***W 1/4 - 1/2 (0.391 mi.)***	***AH267***	***360***
CAL NEV PIPELINE COLTON	2051 E SLOVER AVE	SSW 1/4 - 1/2 (0.401 mi.)	AI282	390
TOSCO CORPORATION, COLTON TERM	***271 EAST SLOVER AVE***	***SW 1/4 - 1/2 (0.407 mi.)***	***AF313***	***426***
A & M AUTO REPAIR	***2075 S RIVERSIDE AVE***	***SW 1/4 - 1/2 (0.412 mi.)***	***AM320***	***434***
GATX RAIL CORPORATION	***20878 SLOVER AVE***	***SSE 1/4 - 1/2 (0.417 mi.)***	***AO325***	***456***
DEL TACO #200	834 W VALLEY BLVD	ESE 1/4 - 1/2 (0.432 mi.)	AR345	1615
KODIAK DIESEL REPAIR INC	350 W VALLEY BLVD	W 1/4 - 1/2 (0.439 mi.)	AH351	1619
POMA AUTOMATED FUELING	***2095 S RIVERSIDE AVE***	***SW 1/4 - 1/2 (0.466 mi.)***	***AM368***	***1631***
NEANDERTHAL CYCLE SALVAGE	2192 S RIVERSIDE AVE	SW 1/4 - 1/2 (0.484 mi.)	AM373	1638
CARDLOCK FUEL SYSTEMS, INC. #1	2125 S RIVERSIDE AVE	SW 1/4 - 1/2 (0.491 mi.)	AM376	1640
CIRCLE K GAS STATION	2128 S RIVERSIDE AVE	SW 1/2 - 1 (0.502 mi.)	AM377	1640
DOLLAR GENERAL #13460	869 N RANCHO AVE	E 1/2 - 1 (0.532 mi.)	AV385	1653
COLTON HIGH SCHOOL	***777 W VALLEY BLVD***	***ESE 1/2 - 1 (0.559 mi.)***	***AW390***	***1657***
TEXACO USA-COLTON TERMINAL	***2237 S RIVERSIDE AVE***	***SW 1/2 - 1 (0.562 mi.)***	***AX391***	***1660***
BOILERMAKERS LOCAL #92	2260 RIVERSIDE AVE	SW 1/2 - 1 (0.570 mi.)	AX401	1676
BEALL TRAILERS OF SOCAL	225 W SLOVER AVE	SW 1/2 - 1 (0.572 mi.)	AZ403	1677
AMERICAN FUEL	***1101 N RANCHO AVE***	***ENE 1/2 - 1 (0.590 mi.)***	***BA405***	***1677***
FILTERRECYCLING SERVICES, INC.	***180 MONTE AVENUE***	***SW 1/2 - 1 (0.609 mi.)***	***AX416***	***1689***
UNOCAL CORP	***2301 S RIVERSIDE AVE***	***SW 1/2 - 1 (0.633 mi.)***	***AX430***	***1740***
COLTON PIPE TRADES TRAINING CE	225 S RANCHO AVE	ESE 1/2 - 1 (0.641 mi.)	BD438	1764
KINDER MORGAN	2297 S RIVERSIDE AVE	SW 1/2 - 1 (0.660 mi.)	AX441	1766
SHELL OIL PRODUCTS-COLTON TERM	2307 S RIVERSIDE AVE	SW 1/2 - 1 (0.670 mi.)	BC453	1794
BUREAU OF AUTOMOTIVE REPAIRS	170 W MINDANAO ST	SW 1/2 - 1 (0.672 mi.)	BC455	1798
FOA BLOCKBUSTER FIREWORKS	169 W MINDANAO ST	SW 1/2 - 1 (0.673 mi.)	BC456	1798
FONTANA POLISHING & PLATING	130 W MINDANAO ST	SW 1/2 - 1 (0.687 mi.)	BE461	1805
C & R MANUFACTURING, INC.	***275 S RANCHO AVE***	***ESE 1/2 - 1 (0.710 mi.)***	***BD467***	***1811***
OLD DOMINION FREIGHT LINES	***2180 S WILLOW AVE***	***SW 1/2 - 1 (0.714 mi.)***	***BH469***	***1812***
SFPP, L.P.	***2359 S RIVERSIDE AVE***	***SW 1/2 - 1 (0.738 mi.)***	***BC476***	***1816***
TRANS	***451 N 3RD ST***	***E 1/2 - 1 (0.744 mi.)***	***480***	***1828***

HAZNET: The data is extracted from the copies of hazardous waste manifests received each year by the DTSC. The annual volume of manifests is typically 700,000-1,000,000 annually, representing approximately 350,000-500,000 shipments. Data from non-California manifests & continuation sheets are not included at the present time. Data are from the manifests submitted without correction, and therefore many contain some invalid values for data elements such as generator ID, TSD ID, waste category, & disposal method. The source is the Department of Toxic Substance Control is the agency

A review of the HAZNET list, as provided by EDR, and dated 12/31/2011 has revealed that there are 99

EXECUTIVE SUMMARY

HAZNET sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
5 STAR AUTO BODY & PAINT SHOP	319 REXFORD ST	0 - 1/8 (0.000 mi.)	F22	55
REPUBLIC MACHINE & FABRICATION	313 REXFORD ST	0 - 1/8 (0.000 mi.)	F23	56
1X COUNTY OF SAN BERNARDINO	1500 W SAN BERNARDINO A	0 - 1/8 (0.000 mi.)	H47	75
WORLD PROPHETIC MINISTRY	***1099 N PEPPER AVE***	***NNE 0 - 1/8 (0.061 mi.)***	***I115***	***214***
INTOWN PROPERTIES INC/HUD	1001 WHISTLE STOP DR	NNE 0 - 1/8 (0.065 mi.)	I117	217
HUD IN TOWN PROPERTIES	1065 AGUA CALIENTE LN	NNE 0 - 1/8 (0.067 mi.)	L118	217
SCHNEIDER NATIONAL CORP	1100 N PEPPER AVE	NNE 0 - 1/8 (0.088 mi.)	I128	225
INTOWN PROPERTIES INC	1081 TRUJILLO LN	N 0 - 1/8 (0.088 mi.)	L130	225
HUD INTOWN PROPERTIES	1801 DE CARMEN DR	N 0 - 1/8 (0.101 mi.)	O135	230
HUD	1927 DE CARMEN DR	N 0 - 1/8 (0.102 mi.)	N136	230
HUD INTOWN PROPERTIES	1897 DE CARMEN DR	N 0 - 1/8 (0.102 mi.)	N137	231
HUD INTOWN PROPERTIES	1174 EXPRESS CIR	NNE 0 - 1/8 (0.123 mi.)	O153	250
FOOD 4 LESS #786	1150 N PEPPER AVE	NNE 1/8 - 1/4 (0.126 mi.)	Q155	251
HUD	1989 FIG TREE RD	NNW 1/8 - 1/4 (0.127 mi.)	R156	253
HUN/INTOWN PROP	1994 FIG TREE RD	NNW 1/8 - 1/4 (0.129 mi.)	R157	253
HUD INTOWN PROPERTIES	1187 EXPRESS CIR	NNE 1/8 - 1/4 (0.132 mi.)	O158	254
WALMART #1862	1610 S RIVERSIDE AVE	W 1/8 - 1/4 (0.134 mi.)	S164	259
WAL-MART STORE #1862	1610 SOUTH RIVERSIDE AV	W 1/8 - 1/4 (0.134 mi.)	S167	267
WAL-MART STORE #1862	1610 S RIVERSIDE AVE	W 1/8 - 1/4 (0.134 mi.)	S170	268
WAL-MART	1610 S RIVERSIDE AVE	W 1/8 - 1/4 (0.134 mi.)	S171	270
FOOD 4 LESS #786 FUEL CENTER	1170 N PEPPER AVE	NNE 1/8 - 1/4 (0.141 mi.)	Q177	274
HUD	1641 IRON HORSE CIR	NNE 1/8 - 1/4 (0.178 mi.)	Q197	294
ASSETT MANAGEMENT SPECIALIST	1620 IRON HORSE CIRCLE	NNE 1/8 - 1/4 (0.180 mi.)	Q198	294
HUD	1851 GOLDEN SPIKE DR	N 1/8 - 1/4 (0.188 mi.)	O201	298
INTOWN PROPERTIES	1201 CANTARA ST	NE 1/8 - 1/4 (0.195 mi.)	202	298
RIALTO VALUE CENTER	1505 SOUTH RIVERSIDE AV	WNW 1/8 - 1/4 (0.196 mi.)	204	299
INTOWN PROPERTIES, INC/HUD	1988 CLUSTER PINE RD	NNW 1/8 - 1/4 (0.223 mi.)	R205	300
MILES PRESERVATION LLC	2070 BUTTONWOOD ST	NNW 1/4 - 1/2 (0.270 mi.)	Z216	311
US RE-ESTATE SERVICES INC	1800 ADMIRALTY ST	N 1/4 - 1/2 (0.272 mi.)	AA219	312
SANTIAGO PARKSIDE ESTATE INC	1155 S RIVERSIDE AVE	NW 1/4 - 1/2 (0.311 mi.)	AC234	335
INTOWN PROPERTIES INC/HUD	1355 WHITEOAK	NNW 1/4 - 1/2 (0.315 mi.)	Z235	337
HUD	1918 QUARTERMASTER	N 1/4 - 1/2 (0.315 mi.)	236	337
HUD	1401 CHERRYTREE RD	NW 1/4 - 1/2 (0.320 mi.)	Z239	341
HUD	1365 CHRISTOBAL LN	NNW 1/4 - 1/2 (0.326 mi.)	AE240	342
HUD INTOWN PROPERTIES	1365 CHRISTOBAL LN N	NNW 1/4 - 1/2 (0.326 mi.)	AE241	342
FIRST PRIORITY PROPERTIES PRES	1398 N TOPSAIL AVE	NNE 1/4 - 1/2 (0.344 mi.)	246	345
CITY OF RIALTO REDEVELOPMENT A	1485 S WILLOW AVE	W 1/4 - 1/2 (0.401 mi.)	AG288	394
SOCAL STRUCTURAL STEEL FABRICA	1485 S WILLOW AVE	W 1/4 - 1/2 (0.401 mi.)	AG289	395
HALSEY MACHINE & MFR COMPANY	1485 S WILLOW AVE	W 1/4 - 1/2 (0.401 mi.)	AG290	396
HALSEY MACHINE & MFR COMPANY	1485 SOUTH WILLOW AVENU	W 1/4 - 1/2 (0.401 mi.)	AG293	401
WILLIAM G JEHUE MIDDLE SCHOOL	1500 N EUCALYPTUS AVE	N 1/4 - 1/2 (0.433 mi.)	AS349	1618
MICHAEL FERGUSON	211 EAST MONTROSE STREE	NW 1/4 - 1/2 (0.451 mi.)	AU363	1629

Lower Elevation	Address	Direction / Distance	Map ID	Page
PRICE CLUB # 106	2111 W VALLEY BLVD	0 - 1/8 (0.000 mi.)	C3	11
VALLEY TRUCK FILTERS	2006 VALLEY BLVD	0 - 1/8 (0.000 mi.)	D8	44
CENTRAL TRANSPORT	1849 W VALLEY BLVD	0 - 1/8 (0.000 mi.)	B11	47
TELCO FOOD PRODUCTS INC	2111 W VALLEY BLVD	0 - 1/8 (0.000 mi.)	C18	51
CSM BAKERY PRODUCTS NA INC	2111 W VALLEY BLVD	0 - 1/8 (0.000 mi.)	C19	53
TELECO	2111 VALLEY BLVD	0 - 1/8 (0.000 mi.)	C21	55
MOSS BROS FORD	1900 W VALLEY BLVD	0 - 1/8 (0.000 mi.)	B25	57
DELSOL AUTO SALES	1998 W VALLEY BLVD	0 - 1/8 (0.000 mi.)	D28	59
COLTON GOLF CLUB	1901 W VALLEY BLVD	0 - 1/8 (0.000 mi.)	B33	62
FIRST COMMERCIAL BANK USA	1759 W VALLEY BLVD	0 - 1/8 (0.000 mi.)	F37	65

EXECUTIVE SUMMARY

Lower Elevation	Address	Direction / Distance	Map ID	Page
SLOVER MT HIGH SCHOOL	325 HERMOSA	0 - 1/8 (0.000 mi.)	G38	65
MOSS BROS FORD	***1900 W VALLEY BLVD***	***0 - 1/8 (0.000 mi.)***	***B41***	***67***
CC WESTERN/CENTRAL TRANSPORT I	1849 W VALLEY BLVD	0 - 1/8 (0.000 mi.)	B44	71
COLTON AUTO SALES	1998 W. VALLEY BLVD	0 - 1/8 (0.000 mi.)	D45	72
PEGGIE MERRIMAN	2040 VALLEY BLVD	0 - 1/8 (0.000 mi.)	C55	82
CALIFORNIA AUTO SPECIALITIES	1595 W VALLEY BLVD	0 - 1/8 (0.000 mi.)	K69	130
DON MORRISON	1595 W. VALLEY BLVD	0 - 1/8 (0.000 mi.)	K70	131
COLTON JOINT USD/WAREHOUSE	1313 W VALLEY BLVD	0 - 1/8 (0.000 mi.)	J73	135
SHELL SERVICE STATION	***1600 W VALLEY***	***0 - 1/8 (0.000 mi.)***	***K74***	***137***
B AND G AUTO SALES	***1630 W VALLEY BLVD***	***0 - 1/8 (0.000 mi.)***	***K76***	***142***
BUDGET TRUCK RENTAL	1700 W VALLEY BLVD	0 - 1/8 (0.000 mi.)	F78	145
PARKHOUSE TIRE	1205 W. VALLEY BLVD.	0 - 1/8 (0.000 mi.)	G80	151
CALIFORNIA AUTO SPECIALIST	1700 W VALLEY RD	0 - 1/8 (0.000 mi.)	F83	153
SELECT EQUIPMENT SALES INC DBA	1762 S SYCAMORE AVE	0 - 1/8 (0.001 mi.)	A87	159
CLARKLIFT OF CALIFORNIA	1762 S SYCAMORE	0 - 1/8 (0.001 mi.)	A89	161
MCNEILUS TRK & MFG	401 N PEPPER PO BOX 158	ESE 0 - 1/8 (0.003 mi.)	K99	176
ARROWHEAD REGIONAL MED CTR	400 N PEPPER AVE	ESE 0 - 1/8 (0.013 mi.)	K108	207
P & S TRUCK SUPPLY INC	245 E VALLEY BLVD	W 0 - 1/8 (0.045 mi.)	A111	210
LUCKY FARMS INC	245 E VALLEY BLVD	W 0 - 1/8 (0.045 mi.)	A114	214
I-10 TRUCK STOP	195 E VALLEY BLVD	W 0 - 1/8 (0.071 mi.)	A125	222
CUMMINS CAL PACIFIC	161 EAST VALLEY BLVD	W 0 - 1/8 (0.089 mi.)	M132	228
CHEVRON STATION #96969	101 EAST VALLEY BLVD	W 0 - 1/8 (0.119 mi.)	M144	238
CHEVRON 96969	101 EAST VALLEY BLVD	W 0 - 1/8 (0.119 mi.)	M145	239
CHEVRON STATION NO 96969	***101 E VALLEY BLVD***	***W 0 - 1/8 (0.119 mi.)***	***M149***	***245***
BP WEST COAST PRODUCTS LLC 969	111 W VALLEY BLVD	W 1/8 - 1/4 (0.144 mi.)	M180	276
KENNETH MICHAEL GARCIA	1087 W VALLEY BLVD RM 1	ESE 1/8 - 1/4 (0.149 mi.)	T186	284
EVA JEAN HORRIDGE	393 CYPRESS	E 1/8 - 1/4 (0.151 mi.)	U189	286
INTOWN PROPERTIES INC/HUD	515 CYPRESS AVE	E 1/8 - 1/4 (0.155 mi.)	U190	287
VALLEY ANIMAL HOSPITAL	127 W VALLEY BLVD	W 1/8 - 1/4 (0.164 mi.)	M194	290
VSC INC DBA VULCAN STEEL COMPA	270 CAMERON WAY	SW 1/4 - 1/2 (0.266 mi.)	V212	305
1X DUNCAN BROS INC	1966 SOUTH DATE STREET	SW 1/4 - 1/2 (0.276 mi.)	W222	326
DUNCAN BROS INC	1966 S DATE ST	SW 1/4 - 1/2 (0.276 mi.)	W223	327
REMCO MACHINING & FABRICATION,	1966 S DATE ST	SW 1/4 - 1/2 (0.276 mi.)	W225	328
DENISE BOURNS	926 F STREET	E 1/4 - 1/2 (0.287 mi.)	X231	334
DALE JONES PHOTOGRAPHY	***915 W C ST***	***E 1/4 - 1/2 (0.316 mi.)***	***AD237***	***337***
AMERIGAS PROPANE LP	1975 S RIVERSIDE AVE	WSW 1/4 - 1/2 (0.346 mi.)	AB247	346
WHITING DOOR MFG CORP	***311 W VALLEY BLVD***	***W 1/4 - 1/2 (0.391 mi.)***	***AH266***	***357***
WHITING DOOR MFG CORP	***311 W VALLEY BLVD***	***W 1/4 - 1/2 (0.391 mi.)***	***AH267***	***360***
CITY OF COLTON	20878 SLOVER ST	SSE 1/4 - 1/2 (0.417 mi.)	AO324	455
GATX RAIL	PEPPER & SLOVER ST	SSE 1/4 - 1/2 (0.429 mi.)	AQ339	1606
KODIAK DIESEL REPAIR INC	350 W VALLEY BLVD	W 1/4 - 1/2 (0.439 mi.)	AH352	1620
DOUGLAS TRUCKING	350 W VALLEY BLVD	W 1/4 - 1/2 (0.439 mi.)	AH355	1621
CALICO TRANSPORT INC	350 W VALLEY BLVD	W 1/4 - 1/2 (0.439 mi.)	AH356	1621
EM AUTO BODY REPAIR	2075 S RIVERSIDE AVE	SW 1/4 - 1/2 (0.447 mi.)	AM360	1626
RFS RIO SERVICES	1036 STEVENSON ST	ENE 1/4 - 1/2 (0.456 mi.)	AP366	1630
POMA AUTOMATED FUELING INC	2095 S RIVERSIDE AVE	SW 1/4 - 1/2 (0.466 mi.)	AM369	1633
CARDLOCK FUELS SYSTEM INC	2125 S RIVERSIDE AVE	SW 1/4 - 1/2 (0.491 mi.)	AM375	1638

EMI: Toxics and criteria pollutant emissions data collected by the ARB and local air pollution agencies

A review of the EMI list, as provided by EDR, and dated 12/31/2008 has revealed that there are 24 EMI sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
WDLJ SOUTH PROPERTY	***1485 SOUTH WILLOW STREE***	***W 1/4 - 1/2 (0.401 mi.)***	***AG292***	***399***

Lower Elevation	Address	Direction / Distance	Map ID	Page
PETER'S AUTOBODY SHOP, P. PROH	1864 VALLEY BLVD.	0 - 1/8 (0.000 mi.)	B2	10
TELCO FOOD PRODUCTS	2111 W VALLEY BLVD	0 - 1/8 (0.000 mi.)	C49	76
INLAND EMPIRE EQUIP INC	1762 S. SYCAMORE	0 - 1/8 (0.001 mi.)	A88	160
ALLIANCE COLTON, LLC	559 PEPPER AVE	ESE 0 - 1/8 (0.002 mi.)	K91	163
PURENERGY OPERATING SERVICES,	559 PEPPER AVE	ESE 0 - 1/8 (0.002 mi.)	K94	173
MCNEILUS TRUCK & MFG INC	***401 N PEPPER AVE***	***ESE 0 - 1/8 (0.003 mi.)***	***K100***	***178***
ARROWHEAD REGIONAL MED CTR	***400 N PEPPER AVE***	***ESE 0 - 1/8 (0.013 mi.)***	***K106***	***203***
PAUL HUBBS CONSTRUCTION CO.	***140 W VALLEY BLVD***	***W 1/8 - 1/4 (0.188 mi.)***	***M200***	***296***
SOUTHERN PACIFIC TRAN/CLT	***200 MARION WAY***	***SW 1/8 - 1/4 (0.233 mi.)***	***V207***	***300***
DUNCAN BROS INC	***1966 S DATE ST***	***SW 1/4 - 1/2 (0.276 mi.)***	***W221***	***313***
SOUTHWESTERN BANDAG INC	933 W. VALLEY BLVD.	ESE 1/4 - 1/2 (0.277 mi.)	226	330
PETROLANE	***1975 S RIVERSIDE AVE***	***WSW 1/4 - 1/2 (0.346 mi.)***	***AB248***	***347***
WHITING DOOR MFG CORP	***311 W VALLEY BLVD***	***W 1/4 - 1/2 (0.391 mi.)***	***AH267***	***360***
CALNEV PIPE LINE, LLC	2051 E SLOVER AVE	SSW 1/4 - 1/2 (0.401 mi.)	AI286	391
CALNEV PIPE LINE CO	2051 W SLOVER AVE	SSW 1/4 - 1/2 (0.402 mi.)	AI303	409
CALNEV PIPE LINE CO (NSR USE)	1901 SLOVER AVE.	SSW 1/4 - 1/2 (0.407 mi.)	AL310	422
CONOCO PHILLIPS CO. - COLTON T	***271 E. SLOVER AVE.***	***SW 1/4 - 1/2 (0.407 mi.)***	***AF311***	***423***
LION OIL, DIV TOSCO CORP TS-91	271 E. SLOVER	SW 1/4 - 1/2 (0.407 mi.)	AF312	425
TOSCO CORPORATION, COLTON TERM	***271 EAST SLOVER AVE***	***SW 1/4 - 1/2 (0.407 mi.)***	***AF313***	***426***
TOSCO CORP	271 EAST SLOVER AV	SW 1/4 - 1/2 (0.407 mi.)	AF314	431
GATX RAIL CORPORATION	***20878 SLOVER AVE***	***SSE 1/4 - 1/2 (0.417 mi.)***	***AO325***	***456***
GATX	PEPPER AV/SLOVER ST.	SSE 1/4 - 1/2 (0.429 mi.)	AQ337	1603
SIERRA MFG	2075 S RIVERSIDE AV	SW 1/4 - 1/2 (0.447 mi.)	AM362	1628

MWMP: The Medical Waste Management Program (MWMP) ensures the proper handling and disposal of medical waste by permitting and inspecting medical waste Offsite Treatment Facilities (PDF) and Transfer Stations (PDF) throughout the state. MWMP also oversees all Medical Waste Transporters.

A review of the MWMP list, as provided by EDR, and dated 03/06/2013 has revealed that there are 2 MWMP sites within approximately 0.75 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
ARROWHEAD REGIONAL MEDICAL CEN	400 NORTH PEPPER AVE.	ESE 0 - 1/8 (0.013 mi.)	K107	207
ENVIRONMENTAL LOGISTICS INC	***140 W MONTE AVE***	***SW 1/2 - 1 (0.628 mi.)***	***AX426***	***1732***

HWT: A listing of hazardous waste transporters. In California, unless specifically exempted, it is unlawful for any person to transport hazardous wastes unless the person holds a valid registration issued by DTSC. A hazardous waste transporter registration is valid for one year and is assigned a unique registration number.

A review of the HWT list, as provided by EDR, and dated 04/15/2013 has revealed that there are 2 HWT

sites within approximately 0.75 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
FILTER RECYCLING SERVICES, INC	180 WEST MONTE AVENUE	SW 1/2 - 1 (0.613 mi.)	AX418	1728
ENVIRONMENTAL LOGISTICS INC	***140 W MONTE AVE***	***SW 1/2 - 1 (0.628 mi.)***	***AX426***	***1732***

HWP: Detailed information on permitted hazardous waste facilities and corrective action ("cleanups") tracked in EnviroStor.

A review of the HWP list, as provided by EDR, and dated 02/25/2013 has revealed that there are 2 HWP sites within approximately 1.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
GATX RAIL	***PEPPER & SLOVER ST***	***SSE 1/4 - 1/2 (0.429 mi.)***	***AQ341***	***1609***
FILTERRECYCLING SERVICES, INC.	***180 MONTE AVENUE***	***SW 1/2 - 1 (0.609 mi.)***	***AX416***	***1689***

2020 COR ACTION: The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

A review of the 2020 COR ACTION list, as provided by EDR, and dated 11/11/2011 has revealed that there is 1 2020 COR ACTION site within approximately 0.75 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
GATX	***PEPPER AVE/SLOVER ST***	***SSE 1/4 - 1/2 (0.417 mi.)***	***AO331***	***910***

US AIRS: The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

A review of the US AIRS list, as provided by EDR, and dated 01/23/2013 has revealed that there are 6 US AIRS sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
PUREENERGY OPERATING SERVICES	***559 PEPPER AVE***	***ESE 0 - 1/8 (0.002 mi.)***	***K92***	***164***
ARROWHEAD REGIONAL MEDICAL CEN	***400 W PEPPER ST***	***ESE 0 - 1/8 (0.013 mi.)***	***K105***	***190***
DUNCAN BROS INC	***1966 S DATE ST***	***SW 1/4 - 1/2 (0.276 mi.)***	***W221***	***313***
CALNEV PIPE LINE COMPANY COLTO	***2051 E SLOVER AVE***	***SSW 1/4 - 1/2 (0.401 mi.)***	***AI277***	***372***
CONOCO PHILLIPS COLTON TERMINA	***271 E SLOVER AVE***	***SW 1/4 - 1/2 (0.406 mi.)***	***AF308***	***414***
GATX	***PEPPER AVE/SLOVER ST***	***SSE 1/4 - 1/2 (0.417 mi.)***	***AO331***	***910***

WDS: California Water Resources Control Board - Waste Discharge System.

A review of the WDS list, as provided by EDR, and dated 06/19/2007 has revealed that there are 6 WDS sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
DREWS ENERGY FACILITY	***559 S PEPPER AVE***	***ESE 0 - 1/8 (0.002 mi.)***	***K93***	***171***
MCNEILUS TRUCK & MFG INC	***401 N PEPPER AVE***	***ESE 0 - 1/8 (0.003 mi.)***	***K100***	***178***
CO-ARROWHEAD REG.MED.CTR	***400 N PEPPER AVE***	***ESE 0 - 1/8 (0.013 mi.)***	***K103***	***187***
FEDERAL EXPRESS CORP	***280 W VALLEY BLVD***	***W 1/4 - 1/2 (0.350 mi.)***	***Y255***	***350***
STORMRIALTO	***271 E. SLOVER AVENUE***	***SW 1/4 - 1/2 (0.406 mi.)***	***AF309***	***421***
BRINE FACCOLTON	***20870 SLOVER AVE***	***SSE 1/4 - 1/2 (0.421 mi.)***	***AO335***	***1600***

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

A review of the EDR MGP list, as provided by EDR, has revealed that there are 2 EDR MGP sites within approximately 1.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
EDISON/COLTON 2 (10TH ST) MGP	EAST OF 10TH STREET, SO	ESE 1 - 2 (1.389 mi.)	BM498	1881
SO CAL GAS/COLTON	NEC OF 6TH STREET AND F	SE 1 - 2 (1.419 mi.)	499	1881

EDR US Hist Auto Stat: EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR US Hist Auto Stat list, as provided by EDR, has revealed that there are 41 EDR US Hist Auto Stat sites within approximately 0.75 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
Not reported	319 REXFORD ST	0 - 1/8 (0.000 mi.)	F9	45
Not reported	310 REXFORD ST	0 - 1/8 (0.000 mi.)	F12	48
Not reported	320 REXFORD ST	0 - 1/8 (0.000 mi.)	F40	66
Not reported	1086 BAUTISTA LN	N 0 - 1/8 (0.093 mi.)	N133	230
Not reported	1748 W ADMIRALTY ST	NNE 1/4 - 1/2 (0.272 mi.)	AA220	313

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
Not reported	959 S RIVERSIDE AVE	NW 1/4 - 1/2 (0.453 mi.)	AK365	1630
Not reported	450 W VALLEY BLVD	W 1/2 - 1 (0.563 mi.)	AY399	1672
Not reported	456 W VALLEY BLVD	W 1/2 - 1 (0.570 mi.)	AY402	1676
Not reported	3121 W SANTOLINAS ST	N 1/2 - 1 (0.588 mi.)	404	1677
Not reported	476 W VALLEY BLVD	W 1/2 - 1 (0.594 mi.)	AY409	1681
Not reported	484 W VALLEY BLVD	W 1/2 - 1 (0.597 mi.)	AY411	1682
Not reported	1611 S LILAC AVE	W 1/2 - 1 (0.625 mi.)	BB421	1729
Not reported	412 W SAN BERNARDINO AV	WNW 1/2 - 1 (0.640 mi.)	437	1764
Not reported	416 W GRANADA ST	WNW 1/2 - 1 (0.659 mi.)	439	1764

Lower Elevation	Address	Direction / Distance	Map ID	Page
Not reported	1998 W VALLEY BLVD	0 - 1/8 (0.000 mi.)	D31	61
Not reported	2006 W VALLEY BLVD	0 - 1/8 (0.000 mi.)	D32	61
Not reported	235 HERMOSA AVE	0 - 1/8 (0.000 mi.)	G62	127
Not reported	1205 W VALLEY BLVD	0 - 1/8 (0.000 mi.)	G63	127
Not reported	128 E VALLEY BLVD	W 0 - 1/8 (0.105 mi.)	M138	231
Not reported	101 E VALLEY BLVD	W 0 - 1/8 (0.119 mi.)	M150	248
Not reported	111 W VALLEY BLVD	W 1/8 - 1/4 (0.144 mi.)	M179	276
Not reported	1743 S WILLOW AVE	W 1/4 - 1/2 (0.375 mi.)	Y259	353
Not reported	862 W G ST	E 1/4 - 1/2 (0.402 mi.)	AJ305	413
Not reported	350 W VALLEY BLVD	W 1/4 - 1/2 (0.439 mi.)	AH353	1620
Not reported	2075 S RIVERSIDE AVE	SW 1/4 - 1/2 (0.447 mi.)	AM361	1627
Not reported	363 W VALLEY BLVD	W 1/4 - 1/2 (0.459 mi.)	AH367	1631
Not reported	2237 S RIVERSIDE AVE	SW 1/2 - 1 (0.562 mi.)	AX395	1669
Not reported	2190 S RIVERSIDE AVE	SW 1/2 - 1 (0.563 mi.)	AX396	1669
Not reported	1101 N RANCHO AVE	ENE 1/2 - 1 (0.590 mi.)	BA406	1679
Not reported	2297 S RIVERSIDE AVE	SW 1/2 - 1 (0.605 mi.)	AX414	1686
Not reported	1750 S LILAC AVE	W 1/2 - 1 (0.629 mi.)	AY427	1738
Not reported	1770 S LILAC AVE	W 1/2 - 1 (0.632 mi.)	AY429	1740
RUSSELL L C GAS	690 W I ST	ESE 1/2 - 1 (0.637 mi.)	AW436	1764
Not reported	2305 S RIVERSIDE AVE	SW 1/2 - 1 (0.660 mi.)	AX446	1776
Not reported	149 W MINDANAO ST	SW 1/2 - 1 (0.681 mi.)	BE457	1799
Not reported	130 W MINDANAO ST	SW 1/2 - 1 (0.686 mi.)	BE460	1805
TUTTLE JOHN	632 W I ST	ESE 1/2 - 1 (0.687 mi.)	BF463	1807
Not reported	1101 LYNDON DR	ENE 1/2 - 1 (0.706 mi.)	466	1811
SOUTHERN GASOLINE STATIONS	606 W I ST	ESE 1/2 - 1 (0.710 mi.)	BF468	1812
GILBERT & JENKINS GAS STA	588 W I ST	ESE 1/2 - 1 (0.729 mi.)	BF470	1813
Not reported	582 W VALLEY BLVD	ESE 1/2 - 1 (0.735 mi.)	BF472	1814

EDR US Hist Cleaners: EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR US Hist Cleaners list, as provided by EDR, has revealed that there are 7 EDR US Hist Cleaners sites within approximately 0.75 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
Not reported	2069 SAN BERNARDINO AV	NW 0 - 1/8 (0.004 mi.)	101	181

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
Not reported	1062 BEL CANTO CT	NE 0 - 1/8 (0.072 mi.)	H126	224
Not reported	1130 N PEPPER AVE	NNE 0 - 1/8 (0.110 mi.)	Q140	233
Not reported	1025 S RIVERSIDE AVE	NW 1/4 - 1/2 (0.404 mi.)	AK307	413

Lower Elevation	Address	Direction / Distance	Map ID	Page
DEALS RUG CLNRS	825 W H ST	E 1/4 - 1/2 (0.470 mi.)	AJ371	1636
Not reported	859 N RANCHO AVE	E 1/2 - 1 (0.531 mi.)	AT384	1652
Not reported	632 W VALLEY BLVD	ESE 1/2 - 1 (0.687 mi.)	BF462	1806

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 43 records.

Site Name	Database(s)
COLTON CROSSING GRADE SEPARATION	NPDES
I 10 RIVERSIDE AVE LANDSCAPE PROJE	NPDES
	CDL
	CDL
	CDL
CALTRANS PANARAMA PT.MAINT.ST.	LUST
UNION PACIFIC RAILROAD	HAZNET
TYSON FRESH MEATS INC	HAZNET
BIMBO BAKERIES USA INC	HAZNET
BESTFOODS BAKING COMPANY	HAZNET
PICK YOUR PART	HAZNET
LAURENCE MCGUIRE	HAZNET
PALOMERA'S AUTO BODY SHOP	HAZNET
JG COLLISION CENTER	HAZNET
CHAROLETTE GUYAUX	HAZNET
E YEARA TRUCKING	HAZNET
CALTRANS DIST 8/CONSTR EA 08-45760	HAZNET
HUD INTOWN PROPERTIES	HAZNET
HENRY RAY CARTER	HAZNET
COLTON BISHOP STORE HOUSE	HAZNET
J.B. HUNT TRANSPORT SERVICES INC	HAZNET
CALTRANS DIST 8	HAZNET
CALTRANS	HAZNET
SHELL	HAZNET
B & D SPECIALTY	HAZNET
COLTON VALLEY DENTAL	HAZNET
CIRCLE K STORES INC.#627	HAZNET
INTOWN PROPERTIES, INC/HUD	HAZNET
EDCO DISPOSAL	HAZNET
1X RIALTO UNIFIED SCHOOL DISTRICT(	HAZNET
RIALTO USD/FRISBIE MIDDLE SCHOOL	HAZNET
ROADWAY EXPRESS	HAZNET
THE WALTON CONSTRUCTION	HAZNET
CONOCO PHILLIPS COLTON TERMINAL-EA	HAZNET
CONOCO PHILLIPS COLTON TERMINAL EA	HAZNET
BISCOMERICA CORP	HAZNET
UNOCAL SERVICE STATION #5961	HAZNET
CIRCLE K STORES INC STATION #5700	HAZNET
IMPORT & DOMESTIC CONVERT	PERMITS SAN BERNARDINO
MARCO AUTO REPAIR	PERMITS SAN BERNARDINO
REDLANDS PROPERTY/ORANGE GROVE	PERMITS SAN BERNARDINO
FOREST RIVER, INC-PLANT #19	PERMITS SAN BERNARDINO
ELITE ROAD SERVICE & TIRE, INC.	HAULERS

OVERVIEW MAP - 3639401.1s



This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: Coltons Hub City Centre	CLIENT: The Altum Group
ADDRESS: Eucalyptus Avenue/Valley Boulevard Colton CA 92324	CONTACT: Cheri Flores INQUIRY #: 3639401.1s
LAT/LONG: 34.0724 / 117.3571	DATE: June 17, 2013 5:56 pm

Copyright © 2013 EDR, Inc. © 2010 Tele Atlas Rel. 07/2009.

DETAIL MAP - 3639401.1s



Target Property

Sites at elevations higher than or equal to the target property

Sites at elevations lower than the target property

Manufactured Gas Plants

Sensitive Receptors

National Priority List Sites

Dept. Defense Sites

0 1/8 1/4 1/2 Miles

Indian Reservations BIA

Power transmission lines

Oil & Gas pipelines from USGS

100-year flood zone

500-year flood zone

Areas of Concern

N

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: Coltons Hub City Centre	CLIENT: The Altum Group
ADDRESS: Eucalyptus Avenue/Valley Boulevard Colton CA 92324	CONTACT: Cheri Flores
LAT/LONG: 34.0724 / 117.3571	INQUIRY #: 3639401.1s DATE: June 17, 2013 5:58 pm

Copyright © 2013 EDR, Inc. © 2010 Tele Atlas Rel. 07/2009.

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Federal NPL site list								
NPL	1.500		0	0	0	0	0	0
Proposed NPL	1.500		0	0	0	0	0	0
NPL LIENS	0.500		0	0	0	NR	NR	0
Federal Delisted NPL site list								
Delisted NPL	1.500		0	0	0	0	0	0
Federal CERCLIS list								
CERCLIS	1.000		0	0	0	0	NR	0
FEDERAL FACILITY	1.000		0	0	0	0	NR	0
Federal CERCLIS NFRAP site List								
CERC-NFRAP	1.000		0	0	1	1	NR	2
Federal RCRA CORRACTS facilities list								
CORRACTS	1.500		0	0	1	1	0	2
Federal RCRA non-CORRACTS TSD facilities list								
RCRA-TSDF	1.000		0	0	1	0	NR	1
Federal RCRA generators list								
RCRA-LQG	0.750		1	1	3	8	NR	13
RCRA-SQG	0.750		9	3	5	6	NR	23
RCRA-CESQG	0.750		0	0	0	0	NR	0
Federal institutional controls / engineering controls registries								
US ENG CONTROLS	1.000		0	0	0	0	NR	0
US INST CONTROL	1.000		0	0	0	0	NR	0
LUCIS	1.000		0	0	0	0	NR	0
Federal ERNS list								
ERNS	0.500		3	0	21	NR	NR	24
State- and tribal - equivalent NPL								
RESPONSE	1.500		0	0	0	0	0	0
State- and tribal - equivalent CERCLIS								
ENVIROSTOR	1.500		0	0	3	3	4	10
State and tribal landfill and/or solid waste disposal site lists								
SWF/LF	1.000		0	0	0	4	NR	4
State and tribal leaking storage tank lists								
LUST	1.000		5	7	4	15	NR	31

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
SLIC	1.000		0	0	2	4	NR	6
INDIAN LUST	1.000		0	0	0	0	NR	0
State and tribal registered storage tank lists								
UST	0.750		5	1	2	9	NR	17
AST	0.750		4	1	1	3	NR	9
INDIAN UST	0.750		0	0	0	0	NR	0
FEMA UST	0.750		0	0	0	0	NR	0
State and tribal voluntary cleanup sites								
VCP	1.000		0	0	0	0	NR	0
INDIAN VCP	1.000		0	0	0	0	NR	0
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	1.000		0	0	0	0	NR	0
Local Lists of Landfill / Solid Waste Disposal Sites								
ODI	1.000		0	0	0	0	NR	0
DEBRIS REGION 9	1.000		0	0	0	0	NR	0
WMUDS/SWAT	1.000		0	0	1	3	NR	4
SWRCY	1.000		0	1	0	3	NR	4
HAULERS	0.500		0	0	0	NR	NR	0
INDIAN ODI	1.000		0	0	0	0	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US CDL	0.500		0	0	1	NR	NR	1
HIST Cal-Sites	1.500		0	0	0	0	0	0
SCH	0.750		0	0	0	0	NR	0
Toxic Pits	1.500		0	1	0	0	0	1
CDL	0.500		2	4	15	NR	NR	21
US HIST CDL	0.500		0	0	0	NR	NR	0
Local Lists of Registered Storage Tanks								
CA FID UST	0.750		5	2	7	0	NR	14
HIST UST	0.750		8	3	7	10	NR	28
SWEEPS UST	0.750		15	3	12	14	NR	44
Local Land Records								
LIENS 2	0.500		0	0	0	NR	NR	0
LIENS	0.500		0	0	0	NR	NR	0
DEED	1.000		0	0	0	0	NR	0
Records of Emergency Release Reports								
HMIRS	0.500		3	0	7	NR	NR	10
CHMIRS	0.500		7	1	17	NR	NR	25
LDS	0.500		0	0	1	NR	NR	1

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
MCS	0.500		0	0	0	NR	NR	0
SPILLS 90	0.500		0	0	0	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.750		2	0	1	4	NR	7
DOT OPS	0.500		0	0	0	NR	NR	0
DOD	1.500		0	0	0	0	0	0
FUDS	1.500		0	0	0	0	0	0
CONSENT	1.500		0	0	0	0	0	0
ROD	1.500		0	0	0	0	0	0
UMTRA	1.000		0	0	0	0	NR	0
US MINES	0.750		0	0	0	0	NR	0
TRIS	0.500		0	0	0	NR	NR	0
TSCA	0.500		0	0	0	NR	NR	0
FTTS	0.500		1	1	0	NR	NR	2
HIST FTTS	0.500		1	1	0	NR	NR	2
SSTS	0.500		0	0	0	NR	NR	0
ICIS	0.500		1	0	0	NR	NR	1
PADS	0.500		0	0	0	NR	NR	0
MLTS	0.500		0	0	0	NR	NR	0
RADINFO	0.500		0	0	0	NR	NR	0
FINDS	0.500		18	5	13	NR	NR	36
RAATS	0.500		0	0	0	NR	NR	0
RMP	0.500		3	0	3	NR	NR	6
CA BOND EXP. PLAN	1.500		0	0	0	0	0	0
UIC	0.500		0	1	0	NR	NR	1
NPDES	0.500		5	2	5	NR	NR	12
Cortese	1.000		0	0	0	1	NR	1
HIST CORTESE	0.500		0	3	0	NR	NR	3
CUPA Listings	0.750		0	0	0	0	NR	0
Notify 65	1.500		0	0	0	0	0	0
DRYCLEANERS	0.750		0	0	0	0	NR	0
WIP	0.750		0	0	0	0	NR	0
ENF	0.500		0	0	0	NR	NR	0
San Bern. Co. Permit	0.750		29	7	19	26	NR	81
HAZNET	0.500		46	20	33	NR	NR	99
EMI	0.500		7	2	15	NR	NR	24
INDIAN RESERV	1.500		0	0	0	0	0	0
SCRD DRYCLEANERS	1.000		0	0	0	0	NR	0
MWMP	0.750		1	0	0	1	NR	2
COAL ASH DOE	0.500		0	0	0	NR	NR	0
COAL ASH EPA	1.000		0	0	0	0	NR	0
HWT	0.750		0	0	0	2	NR	2
HWP	1.500		0	0	1	1	0	2
Financial Assurance	0.500		0	0	0	NR	NR	0
LEAD SMELTERS	0.500		0	0	0	NR	NR	0
2020 COR ACTION	0.750		0	0	1	0	NR	1
US AIRS	0.500		2	0	4	NR	NR	6
PRP	0.500		0	0	0	NR	NR	0
WDS	0.500		3	0	3	NR	NR	6
EPA WATCH LIST	0.500		0	0	0	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
US FIN ASSUR	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	0.500		0	0	0	NR	NR	0
PROC	1.000		0	0	0	0	NR	0
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	1.500		0	0	0	0	2	2
EDR US Hist Auto Stat	0.750		10	1	7	23	NR	41
EDR US Hist Cleaners	0.750		3	0	2	2	NR	7

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

A1 **I-10 TRUCK STOP** **SWEEPS UST** **U003784644**
195 E VALLEY BLVD **San Bern. Co. Permit** **N/A**
< 1/8 **RIALTO, CA 92376**
1 ft.

Site 1 of 18 in cluster A

Relative:
Lower

Actual:
1065 ft.

SWEEPS UST:

Status:	Active
Comp Number:	8453
Number:	2
Board Of Equalization:	Not reported
Referral Date:	06-30-94
Action Date:	06-30-94
Created Date:	06-30-94
Tank Status:	A
Owner Tank Id:	1
Swrcb Tank Id:	36-000-008453-000001
Actv Date:	06-30-94
Capacity:	10000
Tank Use:	OIL
Stg:	W
Content:	WASTE OIL
Number Of Tanks:	5

Status:	Active
Comp Number:	8453
Number:	2
Board Of Equalization:	Not reported
Referral Date:	06-30-94
Action Date:	06-30-94
Created Date:	06-30-94
Tank Status:	A
Owner Tank Id:	2
Swrcb Tank Id:	36-000-008453-000002
Actv Date:	06-30-94
Capacity:	12000
Tank Use:	M.V. FUEL
Stg:	P
Content:	DIESEL
Number Of Tanks:	Not reported

Status:	Active
Comp Number:	8453
Number:	2
Board Of Equalization:	Not reported
Referral Date:	06-30-94
Action Date:	06-30-94
Created Date:	06-30-94
Tank Status:	A
Owner Tank Id:	3
Swrcb Tank Id:	36-000-008453-000003
Actv Date:	06-30-94
Capacity:	10000
Tank Use:	M.V. FUEL
Stg:	P
Content:	DIESEL
Number Of Tanks:	Not reported

Status: Active

I-10 TRUCK STOP (Continued) **U003784644**

Comp Number: 8453
Number: 2
Board Of Equalization: Not reported
Referral Date: 06-30-94
Action Date: 06-30-94
Created Date: 06-30-94
Tank Status: A
Owner Tank Id: 4
Swrcb Tank Id: 36-000-008453-000004
Actv Date: 06-30-94
Capacity: 10000
Tank Use: M.V. FUEL
Stg: P
Content: REG UNLEADED
Number Of Tanks: Not reported

Status: Active
Comp Number: 8453
Number: 2
Board Of Equalization: Not reported
Referral Date: 06-30-94
Action Date: 06-30-94
Created Date: 06-30-94
Tank Status: A
Owner Tank Id: 5
Swrcb Tank Id: 36-000-008453-000005
Actv Date: 06-30-94
Capacity: 12000
Tank Use: M.V. FUEL
Stg: P
Content: DIESEL
Number Of Tanks: Not reported

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0003905
Owner: M & M TRUCK STOP INC
Permit Number: PT0012205
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0003905
Owner: M & M TRUCK STOP INC
Permit Number: PT0012206
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0003905
Owner: M & M TRUCK STOP INC
Permit Number: PT0012207
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 10/31/2013

I-10 TRUCK STOP (Continued) **U003784644**

Region: SAN BERNARDINO
Facility ID: FA0003905
Owner: M & M TRUCK STOP INC
Permit Number: PT0012208
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0003905
Owner: M & M TRUCK STOP INC
Permit Number: PT0002004
Permit Category: HAZMAT HANDLER 0-10 EMPLOYEES
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0003905
Owner: M & M TRUCK STOP INC
Permit Number: PT0002005
Permit Category: SPECIAL GENERATOR
Facility Status: ACTIVE
Expiration Date: 10/31/2013

B2 **PETER'S AUTOBODY SHOP, P. PROH** **EMI** **S106837375**
1864 VALLEY BLVD. **N/A**
< 1/8 **BLOOMINGTON, CA 92316**
1 ft.

Site 1 of 12 in cluster B

Relative: Lower

Actual: 1069 ft.

EMI:

Year:	1990
County Code:	36
Air Basin:	SC
Facility ID:	73548
Air District Name:	SC
SIC Code:	7532
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

C3 **PRICE CLUB # 106** **HAZNET** **S113042989**
2111 W VALLEY BLVD **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 1 of 21 in cluster C

Relative:
Lower

Actual:
1073 ft.

HAZNET:

Year:	1996
Gepaid:	CAL000055261
Contact:	Not reported
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	10809 120TH AVE NE
Mailing City,St,Zip:	KIRKLAND, WA 980330000
Gen County:	Not reported
TSD EPA ID:	CAD003963592
TSD County:	Not reported
Waste Category:	Other inorganic solid waste
Disposal Method:	Recycler
Tons:	.0600
Facility County:	San Bernardino

Year:	1996
Gepaid:	CAL000055261
Contact:	Not reported
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	10809 120TH AVE NE
Mailing City,St,Zip:	KIRKLAND, WA 980330000
Gen County:	Not reported
TSD EPA ID:	CAD003963592
TSD County:	Not reported
Waste Category:	Metal sludge (Alkaline solution (pH >= 12.5) with metals)
Disposal Method:	Recycler
Tons:	.2000
Facility County:	San Bernardino

Year:	1996
Gepaid:	CAL000055261
Contact:	Not reported
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	10809 120TH AVE NE
Mailing City,St,Zip:	KIRKLAND, WA 980330000
Gen County:	Not reported
TSD EPA ID:	CAT080013352
TSD County:	Not reported
Waste Category:	Waste oil and mixed oil
Disposal Method:	Recycler
Tons:	1.6680
Facility County:	San Bernardino

Year:	1994
Gepaid:	CAL000055261
Contact:	Not reported
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	10809 120TH AVE NE
Mailing City,St,Zip:	KIRKLAND, WA 980330000

PRICE CLUB # 106 (Continued) **S113042989**

Gen County: Not reported
TSD EPA ID: CAD003963592
TSD County: Not reported
Waste Category: Metal sludge (Alkaline solution (pH >= 12.5) with metals)
Disposal Method: Recycler
Tons: .2000
Facility County: San Bernardino

Year: 1993
Gepaid: CAL000055261
Contact: Not reported
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 10809 120TH AVE NE
Mailing City,St,Zip: KIRKLAND, WA 980330000
Gen County: Not reported
TSD EPA ID: CAD003963592
TSD County: Not reported
Waste Category: Metal sludge (Alkaline solution (pH >= 12.5) with metals)
Disposal Method: Recycler
Tons: 0.29999999999
Facility County: San Bernardino

Click this hyperlink while viewing on your computer to access additional CA_HAZNET: detail in the EDR Site Report.

B4 **MOSS BROS FORD** **AST** **A100345905**
1900 W. VALLEY BLVD **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 2 of 12 in cluster B

Relative: AST:
Lower Owner: MOSS BROS FORD INC
Total Gallons: 2,700
Actual: Certified Unified Program Agencies: San Bernardino
1067 ft.

D5 **WESTERN EXTERMINATOR COMPANY** **HIST UST** **1000403056**
1998 W VALLEY BLVD **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 1 of 10 in cluster D

Relative: HIST UST:
Lower Region: STATE
Facility ID: 00000002286
Actual: Facility Type: Other
1068 ft. Other Type: EXTERMINATOR
Total Tanks: 0001
Contact Name: Not reported
Telephone: 7148773244
Owner Name: WESTERN EXTERMINATOR COMPANY
Owner Address: 1732 KAISER AV
Owner City,St,Zip: IRVINE, CA 91720

Tank Num: 001

WESTERN EXTERMINATOR COMPANY (Continued) **1000403056**

Container Num: 1
Year Installed: 1968
Tank Capacity: 00010000
Tank Used for: PRODUCT
Type of Fuel: UNLEADED
Tank Construction: Not reported
Leak Detection: Visual, Pressure Test

E6 **BISHOP'S CENTRAL STORES** **AST** **A100345547**
791 N. PEPPER AVE **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 1 of 2 in cluster E

Relative: AST:
Lower Owner: CHURCH OF JESUS CHRIST OF LATTER DAY SAINTS
Total Gallons: 125,261
Actual: Certified Unified Program Agencies: San Bernardino
1078 ft.

C7 **CSM BAKERY PRODUCTS** **RMP** **1014206743**
2111 WEST VALLEY BLVD. **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 2 of 21 in cluster C

Relative: Risk Management Plan (RMP) Facility Details:
Lower Facility ID: 1000018876
LEPC city: Region VI LEPC
Actual: Facility decimal latitude: 34.071944
1073 ft. Facility decimal longitude: -117.364722
Is facility in county box: T
LatLong method: I4
LatLong description: CE
Home page web address: www.csmglobal.com
Facility telephone: Not reported
Facility email: Not reported
Facility DUNS #: 9648304
Parent's name: CSM
Partner's name: Not reported
Parent's DUNS #: 0
Partner's DUNS #: 0
Operator's name: Raj Srinivas
Operator's telephone: 9098257343
Operator's address: 2111 West Valley Blvd.
Operators City,St,Zip: Colton, CA 92324
RMP implementation contact: Raj Srinivas
RMP contact title: Plant Manager
Emergency contact: Wayne Musselman
Emergency contact title: Maintenance Manager
Emergency contact telephone: 9098257343
24 hour emergency telephone: 9092656991
Emergency contact ext/pin #: 157
Number of full time employees: 550
EPA ID: Not reported
Facility ID provided by CEPPO: 100000164412
Is facility covered by OSHA PSM: T

CSM BAKERY PRODUCTS (Continued) **1014206743**

Is facility covered by EPCRA 302: T
Is fac. covered by CAA Title V 112(2): F
Clean air op. permit/State ID: Not reported
Last safety insp. dat: 5/16/2010
Inspected by: Cosco Fire
Is it OSHA approved with star/merit ranking: False
Will RMP involve predictive filing: False
Submission type: Resubmission
RMP description: Not reported
Facility has no accident hist. recs: False
Foreign owner's address: Not reported
Foreign owner's zip: Not reported
Foreign owner's country: Not reported
Claim # of employees as CBI: False
Date RMP accepted by EPA: 1/4/2011
Date of error Report: Not reported
Date RMP received: 1/4/2011
Does RMP contain graphics files: False
Does RMP contain attachments: False
Was certification letter received: True
RMP submission method: RMP*eSubmit
Does RMP contain CBI substantiation: False
Does RMP contain electronic waiver: False
Date RMP postmarked: 1/4/2011
Is RMP complete: True
Date of de-registration: Not reported
Date de-registration is effective: Not reported
Aniversary date: 1/4/2016
Does RMP contain CBI data: False
Does RMP contain unsanitized CBI version: False
RMP version #: 1.0
FRS latitude: 34.07051
FRS longitude: -117.36537
FRS Description: PLANT ENTRANCE (GENERAL)
FRS Method: ADDRESS MATCHING-HOUSE NUMBER

Accident History Details:
Accident History ID: 1000014897
X: 1000018876
Accident Date: 8/26/2008
Accident Time: 1611
NAICS code: 31181
Accident release duration: 00849
Chemical released: Ammonia (anhydrous)
Flammable chemical name: Not reported
Quantity of chemical released in pounds: 1413
Percent weight of chemical released: 100
Release Event: Gas
Release Source: Pressure relief valves on the Evaporative Condenser
Wind speed: Not reported
Wind speed units: Not reported
Wind direction: Not reported
Temperature: Not reported
Stability class: Not reported
Precipitation was present: False
Weather was unknown: True
Num. of on-site workers killed: 0

CSM BAKERY PRODUCTS (Continued) **1014206743**

Num. of responders killed:	0
Num. of public deaths:	0
Num. of on-site workers injured:	0
Num. of responders injured:	0
Num. of public injured:	0
Property damage in dollars:	10473
Num. of on-site deaths:	0
Num. of hospitalizations:	0
Num. of other medical treatments:	0
Num. of evacuated:	550
Num. of sheltered in place:	0
Off-site property damage in dollars:	0
Environmental damage:	Not reported
Initiating event:	a
Contributing factor:	Equipment failure, Process design failure
Were offsite responders notified:	Notified and Responded
Changes Made:	Improved equipment, Revised maintenance
Record contains CBI data:	False

Process Details:

Process ID:	1000023025
NA & Industry Classification Sys.code(s):	31181
NAICS code description:	Bread and Bakery Product Manufacturing
Optional facility description:	Bakery Manufacturer
Program level:	3
Record contains CBI data:	False

Process chemical(s):

Chemical name:	Ammonia (anhydrous)
Process chemical qty in 100s lbs:	19000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported

CSM BAKERY PRODUCTS (Continued) **1014206743**

Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported

CSM BAKERY PRODUCTS (Continued) **1014206743**

Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	c
Analytical basic:	EPA’s General Guidance on Risk Management Programs for Chemical Accident Prevention
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	3
Stability class:	D
Topography:	a
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Emergency Procedures
Percent weight of chemical:	Not reported
Physical state:	c
Analytical basic:	EPA’s RMP Guidance for Ammonia Refrigeration Reference Tables or Equations
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	3
Stability class:	D
Topography:	a
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported

CSM BAKERY PRODUCTS (Continued) **1014206743**

Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported

CSM BAKERY PRODUCTS (Continued) **1014206743**

Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Process ID: 1000023026
NA & Industry Classification Sys.code(s): 31181
NAICS code description: Bread and Bakery Product Manufacturing
Optional facility description: Bakery Manufacturer
Program level: 3
Record contains CBI data: False

Process chemical(s):
Chemical name: Ammonia (anhydrous)
Process chemical qty in 100s lbs: 22000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported

CSM BAKERY PRODUCTS (Continued) **1014206743**

Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported

CSM BAKERY PRODUCTS (Continued) **1014206743**

Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:

CSM BAKERY PRODUCTS (Continued) **1014206743**

Percent weight of chemical: Not reported
Physical state: c
Analytical basic: EPA's General Guidance on Risk Management Programs for Chemical Accident Prevention
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: 10
Release rate in pounds per second: Not reported
Wind speed in meters/second: 1.5
Stability class: F
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Enclosures

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported

CSM BAKERY PRODUCTS (Continued) **1014206743**

Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported

Emergency Response Details:

ER plan:	Not reported
ER plan most recent review date:	Not reported
ER plan most recent employee training date:	Not reported
Local agency coordinating ER plan:	San Bernardino County Fire Dept.
Telephone of the coordinating local agency:	9093874631
Federal regulation:	True
OSHA 1910 120:	False
SPCC:	False
RCRA:	False
OPA 90:	False
EPCRA:	True
Other Regulations:	Not reported

Risk Management Plan (RMP) Facility Details:

Facility ID:	1000024181
LEPC city:	Region VI LEPC
Facility decimal latitude:	34.071944
Facility decimal longitude:	-117.364722
Is facility in county box:	T
LatLong method:	I4
LatLong description:	CE
Home page web address:	www.csmglobal.com
Facility telephone:	Not reported
Facility email:	Not reported
Facility DUNS #:	9648304

CSM BAKERY PRODUCTS (Continued) **1014206743**

Parent's name:	CSM
Partner's name:	Not reported
Parent's DUNS #:	0
Partner's DUNS #:	0
Operator's name:	CSM Bakery Products
Operator's telephone:	9098257343
Operator's address:	2111 West Valley Blvd.
Operators City,St,Zip:	Colton, CA 92324
RMP implementation contact:	Wayne Musselman
RMP contact title:	Maintenance Manager
Emergency contact:	Wayne Musselman
Emergency contact title:	Maintenance Manager
Emergency contact telephone:	9098257343
24 hour emergency telephone:	9099539119
Emergency contact ext/pin #:	Not reported
Number of full time employees:	550
EPA ID:	Not reported
Facility ID provided by CEPPO:	100000164412
Is facility covered by OSHA PSM:	T
Is facility covered by EPCRA 302:	T
Is fac. covered by CAA Title V 112(2):	F
Clean air op. permit/State ID:	Not reported
Last safety insp. dat:	6/30/2011
Inspected by:	San Bernardino County Fire Department
Is it OSHA approved with star/merit ranking:	False
Will RMP involve predictive filing:	False
Submission type:	Resubmission
RMP description:	Not reported
Facility has no accident hist. recs:	False
Foreign owner's address:	Not reported
Foreign owner's zip:	Not reported
Foreign owner's country:	Not reported
Claim # of employees as CBI:	False
Date RMP accepted by EPA:	11/11/2011
Date of error Report:	Not reported
Date RMP received:	11/11/2011
Does RMP contain graphics files:	False
Does RMP contain attachments:	False
Was certification letter received:	True
RMP submission method:	RMP*eSubmit
Does RMP contain CBI substantiation:	False
Does RMP contain electronic waiver:	False
Date RMP postmarked:	11/11/2011
Is RMP complete:	True
Date of de-registration:	Not reported
Date de-registration is effective:	Not reported
Aniversary date:	11/11/2016
Does RMP contain CBI data:	False
Does RMP contain unsanitized CBI version:	False
RMP version #:	1.0
FRS latitude:	34.07051
FRS longitude:	-117.36537
FRS Description:	PLANT ENTRANCE (GENERAL)
FRS Method:	ADDRESS MATCHING-HOUSE NUMBER

Accident History Details:

Accident History ID:	1000019797

CSM BAKERY PRODUCTS (Continued) **1014206743**

X: 1000024181
Accident Date: 8/26/2008
Accident Time: 1611
NAICS code: 31181
Accident release duration: 00849
Chemical released: Ammonia (anhydrous)
Flammable chemical name: Not reported
Quantity of chemical released in pounds: 1413
Percent weight of chemical released: 100
Release Event: Gas
Release Source: Pressure relief valves on the Evaporative Condenser
Wind speed: Not reported
Wind speed units: Not reported
Wind direction: Not reported
Temperature: Not reported
Stability class: Not reported
Precipitation was present: False
Weather was unknown: True
Num. of on-site workers killed: 0
Num. of responders killed: 0
Num. of public deaths: 0
Num. of on-site workers injured: 0
Num. of responders injured: 0
Num. of public injured: 0
Property damage in dollars: 10473
Num. of on-site deaths: 0
Num. of hospitalizations: 0
Num. of other medical treatments: 0
Num. of evacuated: 550
Num. of sheltered in place: 0
Off-site property damage in dollars: 0
Environmental damage: Not reported
Initiating event: a
Contributing factor: Equipment failure, Process design failure
Were offsite responders notified: Notified and Responded
Changes Made: Improved equipment, Revised maintenance
Record contains CBI data: False

Process Details:
Process ID: 1000029589
NA & Industry Classification Sys.code(s): 31181
NAICS code description: Bread and Bakery Product Manufacturing
Optional facility description: Bakery Manufacturer
Program level: 3
Record contains CBI data: False

Process chemical(s):
Chemical name: Ammonia (anhydrous)
Process chemical qty in 100s lbs: 19000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported

CSM BAKERY PRODUCTS (Continued) **1014206743**

Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported

CSM BAKERY PRODUCTS (Continued) **1014206743**

Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	c
Analytical basic:	EPA’s General Guidance on Risk Management Programs for Chemical Accident Prevention
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	3
Stability class:	D
Topography:	a
Distance to endpoint in miles:	Not reported
Residential population:	Not reported

CSM BAKERY PRODUCTS (Continued) **1014206743**

Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Emergency shutdown, Emergency Procedures
Percent weight of chemical:	Not reported
Physical state:	c
Analytical basic:	EPA's RMP Guidance for Ammonia Refrigeration Reference Tables or Equations
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	3
Stability class:	D
Topography:	a
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Emergency shutdown, Emergency Procedures

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported

Process Flammables Alt. Releases:

Endpoint used:	Not reported
LFL value:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Flammables Worst Case:

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported

CSM BAKERY PRODUCTS (Continued) **1014206743**

Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Process ID:	1000029590
NA & Industry Classification Sys.code(s):	31181
NAICS code description:	Bread and Bakery Product Manufacturing
Optional facility description:	Bakery Manufacturer
Program level:	3
Record contains CBI data:	False

CSM BAKERY PRODUCTS (Continued) **1014206743**

Process chemical(s):
- Chemical name: Ammonia (anhydrous)
- Process chemical qty in 100s lbs: 23000
- Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Toxics Worst Case:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported

CSM BAKERY PRODUCTS (Continued) **1014206743**

Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

CSM BAKERY PRODUCTS (Continued) **1014206743**

Process Toxic Alt. Releases:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Toxics Worst Case:
- Percent weight of chemical: Not reported
- Physical state: c
- Analytical basic: EPA's General Guidance on Risk Management Programs for Chemical Accident Prevention
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: 10
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: 1.5
- Stability class: F
- Topography: a
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Enclosures

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported
- Most recent PHA date: Not reported

CSM BAKERY PRODUCTS (Continued) **1014206743**

Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported

Emergency Response Details:

ER plan:	Not reported
ER plan most recent review date:	Not reported
ER plan most recent employee training date:	Not reported
Local agency coordinating ER plan:	San Bernardino County Fire Dept.
Telephone of the coordinating local agency:	9093874631
Federal regulation:	True
OSHA 1910 120:	False

CSM BAKERY PRODUCTS (Continued) **1014206743**

SPCC:	False
RCRA:	False
OPA 90:	False
EPCRA:	True
Other Regulations:	Not reported

Risk Management Plan (RMP) Facility Details:

Facility ID:	53379
LEPC city:	Region VI LEPC
Facility decimal latitude:	34.071944
Facility decimal longitude:	-117.364722
Is facility in county box:	T
LatLong method:	I4
LatLong description:	CE
Home page web address:	www.csmglobal.com
Facility telephone:	Not reported
Facility email:	Not reported
Facility DUNS #:	9648304
Parent's name:	CSM
Partner's name:	Not reported
Parent's DUNS #:	0
Partner's DUNS #:	0
Operator's name:	Scott Buchele
Operator's telephone:	9098257343
Operator's address:	2111 West Valley Blvd.
Operators City,St,Zip:	Colton, CA 92324
RMP implementation contact:	Scott Buchele
RMP contact title:	Director of Operations
Emergency contact:	Wayne Musselman
Emergency contact title:	Maintenance Manager
Emergency contact telephone:	9098257343
24 hour emergency telephone:	9092656991
Emergency contact ext/pin #:	111
Number of full time employees:	550
EPA ID:	Not reported
Facility ID provided by CEPPO:	100000164412
Is facility covered by OSHA PSM:	T
Is facility covered by EPCRA 302:	T
Is fac. covered by CAA Title V 112(2):	F
Clean air op. permit/State ID:	Not reported
Last safety insp. dat:	5/6/2007
Inspected by:	City Fire Department
Is it OSHA approved with star/merit ranking:	False
Will RMP involve predictive filing:	False
Submission type:	Correction
RMP description:	2006 Update 12/06
Facility has no accident hist. recs:	False
Foreign owner's address:	Not reported
Foreign owner's zip:	Not reported
Foreign owner's country:	Not reported
Claim # of employees as CBI:	False
Date RMP accepted by EPA:	8/27/2010
Date of error Report:	Not reported
Date RMP received:	1/13/2009
Does RMP contain graphics files:	False
Does RMP contain attachments:	False
Was certification letter received:	True

CSM BAKERY PRODUCTS (Continued) **1014206743**

RMP submission method: RMP*Submit
Does RMP contain CBI substantiation: False
Does RMP contain electronic waiver: False
Date RMP postmarked: 1/12/2009
Is RMP complete: True
Date of de-registration: Not reported
Date de-registration is effective: Not reported
Aniversary date: 6/20/2012
Does RMP contain CBI data: False
Does RMP contain unsanitized CBI version: False
RMP version #: 3.8
FRS latitude: 34.07051
FRS longitude: -117.36537
FRS Description: PLANT ENTRANCE (GENERAL)
FRS Method: ADDRESS MATCHING-HOUSE NUMBER

Accident History Details:
Accident History ID: 8636
X: 53379
Accident Date: 3/17/2002
Accident Time: 1817
NAICS code: 31181
Accident release duration: 00643
Chemical released: Ammonia (anhydrous)
Flammable chemical name: Not reported
Quantity of chemical released in pounds: 1000
Percent weight of chemical released: 100
Release Event: Gas, Spill
Release Source: Storage Vessel, Valve
Wind speed: Not reported
Wind speed units: c
Wind direction: Not reported
Temperature: Not reported
Stability class: Not reported
Precipitation was present: False
Weather was unknown: True
Num. of on-site workers killed: 0
Num. of responders killed: 0
Num. of public deaths: 0
Num. of on-site workers injured: 0
Num. of responders injured: 0
Num. of public injured: 0
Property damage in dollars: 0
Num. of on-site deaths: 0
Num. of hospitalizations: 0
Num. of other medical treatments: 0
Num. of evacuated: 0
Num. of sheltered in place: 0
Off-site property damage in dollars: 0
Environmental damage: Not reported
Initiating event: a
Contributing factor: Equipment failure, Human error, Process design failure, Unsuitable equipment
Were offsite responders notified: Notified and Responded
Changes Made: Improved equipment, Revised maintenance
Record contains CBI data: False

CSM BAKERY PRODUCTS (Continued) **1014206743**

Process Details:
Process ID: 77827
NA & Industry Classification Sys.code(s): 31181
NAICS code description: Bread and Bakery Product Manufacturing
Optional facility description: Bakery Manufacturer
Program level: 3
Record contains CBI data: False

Process chemical(s):
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: c
Analytical basic: EPA's General Guidance on Risk Management Programs for Chemical Accident Prevention
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Emergency Procedures
Percent weight of chemical: Not reported
Physical state: c
Analytical basic: EPA's RMP Guidance for Ammonia Refrigeration Reference Tables or Equations
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported

CSM BAKERY PRODUCTS (Continued) **1014206743**

Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported

CSM BAKERY PRODUCTS (Continued) **1014206743**

Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Ammonia (anhydrous)
Process chemical qty in 100s lbs:	19000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported

CSM BAKERY PRODUCTS (Continued) **1014206743**

Process Flammables Alt. Releases:

Endpoint used:	Not reported
LFL value:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Flammables Worst Case:

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported

CSM BAKERY PRODUCTS (Continued) **1014206743**

Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Process ID: 77828
NA & Industry Classification Sys.code(s): 31181
NAICS code description: Bread and Bakery Product Manufacturing
Optional facility description: Bakery Manufacturer
Program level: 3
Record contains CBI data: False

Process chemical(s):
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: c
Analytical basic: EPA’s General Guidance on Risk Management Programs for Chemical Accident Prevention
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: 10
Release rate in pounds per second: Not reported
Wind speed in meters/second: 1.5
Stability class: F
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

CSM BAKERY PRODUCTS (Continued) **1014206743**

Environmental receptors: Not reported
Passive mitigation: Enclosures

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported

CSM BAKERY PRODUCTS (Continued) **1014206743**

Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Ammonia (anhydrous)
Process chemical qty in 100s lbs: 22000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported

CSM BAKERY PRODUCTS (Continued) **1014206743**

Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported

CSM BAKERY PRODUCTS (Continued) **1014206743**

Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported

Emergency Response Details:

ER plan:	Not reported
ER plan most recent review date:	Not reported
ER plan most recent employee training date:	Not reported
Local agency coordinating ER plan:	San Bernardino County Fire Dept.
Telephone of the coordinating local agency:	9093874631
Federal regulation:	True
OSHA 1910 120:	False
SPCC:	False
RCRA:	False
OPA 90:	False
EPCRA:	True
Other Regulations:	Not reported

D8 **VALLEY TRUCK FILTERS** **HAZNET** **S113115311**
2006 VALLEY BLVD **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 2 of 10 in cluster D

Relative: Lower

Actual: 1068 ft.

HAZNET:

Year:	2009
Gepaid:	CAL000232017
Contact:	JOSE VASQUEZ/OWNER
Telephone:	9095620525
Mailing Name:	Not reported
Mailing Address:	2006 VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	Not reported
TSD EPA ID:	AZR000501510
TSD County:	Not reported
Waste Category:	Organic solids with halogens
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.2
Facility County:	San Bernardino

F9 **EDR US Hist Auto Stat** **1015420476**
319 REXFORD ST **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 1 of 15 in cluster F

Relative: EDR Historical Auto Stations:
Higher
Name: ORIGINAL BODY SHOP
Year: 2002
Actual: Address: 319 REXFORD ST
1084 ft.

Name: ORIGINAL BODY SHOP
Year: 2004
Address: 319 REXFORD ST

Name: 5 STAR AUTO BODY & PAINT SHOP INC
Year: 2008
Address: 319 REXFORD ST

Name: 5 STAR AUTO BODY & PAINT SHOP
Year: 2010
Address: 319 REXFORD ST

Name: 5 STAR AUTO BODY & PAINT SHOP INC
Year: 2011
Address: 319 REXFORD ST

Name: 5 STAR AUTO BODY & PAINT SHOP INC
Year: 2012
Address: 319 REXFORD ST

C10 **CHMIRS** **S105882965**
2111 W. VALLEY BLVD **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 3 of 21 in cluster C

Relative: CHMIRS:
Lower
OES Incident Number: 02-1449
OES notification: 03/17/2002
Actual: OES Date: Not reported
1073 ft. OES Time: Not reported
Incident Date: Not reported
Date Completed: Not reported
Property Use: Not reported
Agency Id Number: Not reported
Agency Incident Number: Not reported
Time Notified: Not reported
Time Completed: Not reported
Surrounding Area: Not reported
Estimated Temperature: Not reported
Property Management: Not reported
Special Studies 1: Not reported
Special Studies 2: Not reported
Special Studies 3: Not reported
Special Studies 4: Not reported
Special Studies 5: Not reported
Special Studies 6: Not reported
More Than Two Substances Involved?: Not reported
Resp Agncy Personel # Of Decontaminated: Not reported

(Continued) **S105882965**

Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	No
Waterway:	Not reported
Spill Site:	Not reported
Cleanup By:	Contractor
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	2002
Agency:	San Bernardino FD
Incident Date:	3/17/200212:00:00 AM
Admin Agency:	San Bernardino County Health Department
Amount:	Not reported
Contained:	Yes
Site Type:	Other
E Date:	Not reported
Substance:	ammonia anhydrous
Quantity Released:	Not reported
BBLS:	0
Cups:	0
CUFT:	0
Gallons:	0.000000
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	Compressor seal burst causing the release. Food storage facility. All is contained inside the building.

B11 **CENTRAL TRANSPORT** **HAZNET** **S112926019**
1849 W VALLEY BLVD **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 3 of 12 in cluster B

Relative:
Lower

Actual:
1070 ft.

HAZNET:

Year:	2004
Gepaid:	CAC002558607
Contact:	CHRIS TRANBERG
Telephone:	9098747040
Mailing Name:	Not reported
Mailing Address:	1849 W VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 92324
Gen County:	Not reported
TSD EPA ID:	CAD008364432
TSD County:	Not reported
Waste Category:	Unspecified organic liquid mixture
Disposal Method:	Treatment, Tank
Tons:	0.02
Facility County:	San Bernardino

Year:	2004
Gepaid:	CAC002558607
Contact:	CHRIS TRANBERG
Telephone:	9098747040
Mailing Name:	Not reported
Mailing Address:	1849 W VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 92324
Gen County:	Not reported
TSD EPA ID:	CAD008364432
TSD County:	Not reported
Waste Category:	Liquids with pH <= 2
Disposal Method:	Transfer Station
Tons:	0.05
Facility County:	San Bernardino

Year:	2004
Gepaid:	CAC002558607
Contact:	CHRIS TRANBERG
Telephone:	9098747040
Mailing Name:	Not reported
Mailing Address:	1849 W VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 92324
Gen County:	Not reported
TSD EPA ID:	CAD008364432
TSD County:	Not reported
Waste Category:	Unspecified organic liquid mixture
Disposal Method:	Transfer Station
Tons:	0.14
Facility County:	San Bernardino

Year:	2002
Gepaid:	CAC002558607
Contact:	CHRIS TRANBERG
Telephone:	9098747040
Mailing Name:	Not reported
Mailing Address:	1849 W VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 92324

CENTRAL TRANSPORT (Continued) **S112926019**

Gen County: Not reported
TSD EPA ID: AZD980892731
TSD County: Not reported
Waste Category: Unspecified organic liquid mixture
Disposal Method: Recycler
Tons: 0.2
Facility County: San Bernardino

F12 **EDR US Hist Auto Stat** **1015412250**
310 REXFORD ST **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 2 of 15 in cluster F

Relative: Higher

Actual: 1084 ft.

EDR Historical Auto Stations:

Name: JIMMY MCVAY MOBILE SERVICE
Year: 2005
Address: 310 REXFORD ST

Name: JIMMY MCVAY MOBILE SERVICE
Year: 2006
Address: 310 REXFORD ST

Name: JIMMY MCVAY MOBILE SERVICE
Year: 2012
Address: 310 REXFORD ST

B13 **MOSS BROTHERS FORD** **FINDS** **1008153008**
1900 W VALLEY BLVD **San Bern. Co. Permit** **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 4 of 12 in cluster B

Relative: Lower

Actual: 1067 ft.

FINDS:

Registry ID: 110018973388

Environmental Interest/Information System

California Hazardous Waste Tracking System - Datamart (HWTS-DATAMART) provides California with information on hazardous waste shipments for generators, transporters, and treatment, storage, and disposal facilities.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

UORS (California - Used Oil Recycling System). California Integrated Waste Management Board (CIWMB) helps communities establish and promote convenient collection opportunities for used oil and used oil filters.

MOSS BROTHERS FORD (Continued) **1008153008**

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0007627
Owner: MOSS BROS FORD INC.
Permit Number: PT0002646
Permit Category: HAZMAT HANDLER 51-100 EMPLOYEES (W/GEN PRMT)
Facility Status: INACTIVE
Expiration Date: 11/30/2009

Region: SAN BERNARDINO
Facility ID: FA0007627
Owner: MOSS BROS FORD INC.
Permit Number: PT0002636
Permit Category: HAZARDOUS WASTE GENERATOR - 51-100 EMPLOYEES
Facility Status: INACTIVE
Expiration Date: 11/30/2009

Region: SAN BERNARDINO
Facility ID: FA0007627
Owner: MOSS BROS FORD INC.
Permit Number: PT0012766
Permit Category: ABOVEGROUND PETROLEUM STORAGE (AST) (SPCC)
Facility Status: INACTIVE
Expiration Date: 11/30/2008

D14 **SAMMON'S TRUCKING** **SWEEPS UST** **S106931760**
1988 W VALLEY BLVD **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 3 of 10 in cluster D

Relative:
Lower

Actual:
1068 ft.

SWEEPS UST:
Status: Active
Comp Number: 13611
Number: 9
Board Of Equalization: Not reported
Referral Date: 03-24-92
Action Date: 03-24-92
Created Date: 09-16-88
Tank Status: A
Owner Tank Id: Not reported
Swrcb Tank Id: 36-000-013611-000001
Actv Date: 09-16-88
Capacity: 1
Tank Use: UNKNOWN
Stg: P
Content: UNKNOWN
Number Of Tanks: 1

C15 **ENTENMANN'S OROWHEAT** **San Bern. Co. Permit** **S103640452**
2036 W VALLEY BLVD **N/A**
< 1/8 **COLTON, CA 92376**
1 ft.

Site 4 of 21 in cluster C

Relative: **Lower**

Actual: **1069 ft.**

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0002924
Owner: ENTENMANN'S OROWHEAT
Permit Number: PT0002886
Permit Category: SPECIAL GENERATOR
Facility Status: INACTIVE
Expiration Date: 04/30/2007

Region: SAN BERNARDINO
Facility ID: FA0002924
Owner: ENTENMANN'S OROWHEAT
Permit Number: PT0002887
Permit Category: SPECIAL HANDLER
Facility Status: INACTIVE
Expiration Date: 04/30/2007

Region: SAN BERNARDINO
Facility ID: FA0001436
Owner: BIMBO BAKERIES USA, INC.
Permit Number: PT0009470
Permit Category: SPECIAL GENERATOR
Facility Status: ACTIVE
Expiration Date: 12/31/2013

Region: SAN BERNARDINO
Facility ID: FA0001436
Owner: BIMBO BAKERIES USA, INC.
Permit Number: PT0009469
Permit Category: SPECIAL HANDLER
Facility Status: ACTIVE
Expiration Date: 12/31/2013

F16 **AMCAL AUTOMOTIVE** **San Bern. Co. Permit** **S110326650**
320 REXFORD ST **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 3 of 15 in cluster F

Relative: **Higher**

Actual: **1084 ft.**

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0013097
Owner: BRAVO, LOUIS
Permit Number: PT0023023
Permit Category: SPECIAL GENERATOR
Facility Status: ACTIVE
Expiration Date: 04/30/2013

Region: SAN BERNARDINO
Facility ID: FA0013097
Owner: BRAVO, LOUIS
Permit Number: PT0023022
Permit Category: SPECIAL HANDLER
Facility Status: ACTIVE

AMCAL AUTOMOTIVE (Continued) **S110326650**

Expiration Date: 04/30/2013

B17 **COLTON GOLF COURSE** **San Bern. Co. Permit** **S104765431**
1901 VALLEY BLVD **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 5 of 12 in cluster B

Relative: Lower

Actual: 1067 ft.

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0002433
Owner: H & H INVESTMENTS CO, INC.
Permit Number: PT0008798
Permit Category: HAZMAT HANDLER 11-25 EMPLOYEES
Facility Status: ACTIVE
Expiration Date: 04/30/2013

Region: SAN BERNARDINO
Facility ID: FA0002433
Owner: H & H INVESTMENTS CO, INC.
Permit Number: PT0008799
Permit Category: SPECIAL GENERATOR
Facility Status: ACTIVE
Expiration Date: 04/30/2013

C18 **TELCO FOOD PRODUCTS INC** **HAZNET** **S113147034**
2111 W VALLEY BLVD **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 5 of 21 in cluster C

Relative: Lower

Actual: 1073 ft.

HAZNET:
Year: 2011
Gepaid: CAL000318228
Contact: MICHAEL HENDRICK
Telephone: 9098257343
Mailing Name: Not reported
Mailing Address: 2111 W VALLEY BLVD
Mailing City,St,Zip: COLTON, CA 923241814
Gen County: Not reported
TSD EPA ID: CAT080013352
TSD County: Not reported
Waste Category: Off-specification, aged or surplus organics
Disposal Method: Fuel Blending Prior To Energy Recovery At Another Site
Tons: 0.099
Facility County: San Bernardino

Year: 2011
Gepaid: CAL000318228
Contact: MICHAEL HENDRICK
Telephone: 9098257343
Mailing Name: Not reported
Mailing Address: 2111 W VALLEY BLVD
Mailing City,St,Zip: COLTON, CA 923241814
Gen County: Not reported
TSD EPA ID: CAD028409019

TELCO FOOD PRODUCTS INC (Continued) **S113147034**

TSD County: Not reported
Waste Category: Other organic solids
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.086
Facility County: San Bernardino

Year: 2011
Gepaid: CAL000318228
Contact: MICHAEL HENDRICK
Telephone: 9098257343
Mailing Name: Not reported
Mailing Address: 2111 W VALLEY BLVD
Mailing City,St,Zip: COLTON, CA 923241814
Gen County: Not reported
TSD EPA ID: CAT080013352
TSD County: Not reported
Waste Category: Waste oil and mixed oil
Disposal Method: Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons: 3.344
Facility County: San Bernardino

Year: 2010
Gepaid: CAL000318228
Contact: MICHAEL HENDRICK
Telephone: 9098257343
Mailing Name: Not reported
Mailing Address: 2111 W VALLEY BLVD
Mailing City,St,Zip: COLTON, CA 923241814
Gen County: Not reported
TSD EPA ID: CAD097030993
TSD County: Not reported
Waste Category: Waste oil and mixed oil
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.209
Facility County: San Bernardino

Year: 2010
Gepaid: CAL000318228
Contact: MICHAEL HENDRICK
Telephone: 9098257343
Mailing Name: Not reported
Mailing Address: 2111 W VALLEY BLVD
Mailing City,St,Zip: COLTON, CA 923241814
Gen County: Not reported
TSD EPA ID: CAT080013352
TSD County: Not reported
Waste Category: Waste oil and mixed oil
Disposal Method: Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons: 3.705
Facility County: San Bernardino

TELCO FOOD PRODUCTS INC (Continued) **S113147034**

Click this hyperlink while viewing on your computer to access
9 additional CA_HAZNET: record(s) in the EDR Site Report.

C19 **CSM BAKERY PRODUCTS NA INC** **HAZNET** **S113161138**
2111 W VALLEY BLVD **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 6 of 21 in cluster C

Relative: HAZNET:
Lower

Year:	2011
Gepaid:	CAL000360821
Actual: Contact:	WAYNE MUSSELMAN
1073 ft. Telephone:	9092656991
Mailing Name:	Not reported
Mailing Address:	2111 W VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 923241814
Gen County:	Not reported
TSD EPA ID:	CAD028409019
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.125
Facility County:	San Bernardino

C20 **CHMIRS** **S105883679**
2111 W. VALLEY BLVD. **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 7 of 21 in cluster C

Relative: CHMIRS:
Lower

OES Incident Number:	02-1581
OES notification:	03/22/2002
Actual: OES Date:	Not reported
1073 ft. OES Time:	Not reported
Incident Date:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported

(Continued) **S105883679**

Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	No
Waterway:	Not reported
Spill Site:	Not reported
Cleanup By:	N/A
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	2002
Agency:	Telco
Incident Date:	3/17/200212:00:00 AM
Admin Agency:	San Bernardino County Health Department
Amount:	Not reported
Contained:	Yes
Site Type:	Industrial Plant
E Date:	Not reported
Substance:	Anhydrous Ammonia
Quantity Released:	Not reported
BBLS:	0
Cups:	0
CUFT:	0
Gallons:	0.000000
Grams:	0
Pounds:	500
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	HISTORICAL REPORT: Valve failed causing this release.

C21 **TELECO** **HAZNET** **S112906964**
2111 VALLEY BLVD **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 8 of 21 in cluster C

Relative: HAZNET:
Lower

Year:	2000
Gepaid:	CAC002247257
Actual: Contact:	GREG PIERCE-MGR
1073 ft. Telephone:	8009871064
Mailing Name:	Not reported
Mailing Address:	2111 VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	Not reported
TSD EPA ID:	CAT080022148
TSD County:	Not reported
Waste Category:	Waste oil and mixed oil
Disposal Method:	Transfer Station
Tons:	0.45
Facility County:	San Bernardino

F22 **5 STAR AUTO BODY & PAINT SHOP INC** **HAZNET** **S113144825**
319 REXFORD ST **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 4 of 15 in cluster F

Relative: HAZNET:
Higher

Year:	2011
Gepaid:	CAL000312525
Actual: Contact:	HOVO MAKARYAN
1084 ft. Telephone:	8187551725
Mailing Name:	Not reported
Mailing Address:	319 REXFORD ST
Mailing City,St,Zip:	COLTON, CA 923241804
Gen County:	Not reported
TSD EPA ID:	CAD028409019
TSD County:	Not reported
Waste Category:	Off-specification, aged or surplus organics
Disposal Method:	Fuel Blending Prior To Energy Recovery At Another Site
Tons:	0.099
Facility County:	San Bernardino

Year:	2010
Gepaid:	CAL000312525
Contact:	HOVO MAKARYAN
Telephone:	8187551725
Mailing Name:	Not reported
Mailing Address:	319 REXFORD ST
Mailing City,St,Zip:	COLTON, CA 923241804
Gen County:	Not reported
TSD EPA ID:	CAD008252405
TSD County:	Not reported
Waste Category:	Unspecified solvent mixture
Disposal Method:	Fuel Blending Prior To Energy Recovery At Another Site
Tons:	0.1584
Facility County:	San Bernardino

Year:	2009

5 STAR AUTO BODY & PAINT SHOP INC (Continued) **S113144825**

Gepaid:	CAL000312525
Contact:	HOVO MAKARYAN
Telephone:	8187551725
Mailing Name:	Not reported
Mailing Address:	319 REXFORD ST
Mailing City,St,Zip:	COLTON, CA 923241804
Gen County:	Not reported
TSD EPA ID:	CAD008252405
TSD County:	Not reported
Waste Category:	Unspecified solvent mixture
Disposal Method:	Fuel Blending Prior To Energy Recovery At Another Site
Tons:	0.144
Facility County:	San Bernardino

Year:	2008
Gepaid:	CAL000312525
Contact:	HOVO MAKARYAN
Telephone:	8187551725
Mailing Name:	Not reported
Mailing Address:	319 REXFORD ST
Mailing City,St,Zip:	COLTON, CA 923241804
Gen County:	Not reported
TSD EPA ID:	CAD008252405
TSD County:	Not reported
Waste Category:	Unspecified solvent mixture
Disposal Method:	Fuel Blending Prior To Energy Recovery At Another Site
Tons:	0.0504
Facility County:	San Bernardino

Year:	2008
Gepaid:	CAL000312525
Contact:	HOVO MAKARYAN
Telephone:	8187551725
Mailing Name:	Not reported
Mailing Address:	319 REXFORD ST
Mailing City,St,Zip:	COLTON, CA 923241804
Gen County:	Not reported
TSD EPA ID:	CAD008252405
TSD County:	Not reported
Waste Category:	Unspecified solvent mixture
Disposal Method:	Solvents Recovery
Tons:	0.3276
Facility County:	San Bernardino

Click this hyperlink while viewing on your computer to access
1 additional CA_HAZNET: record(s) in the EDR Site Report.

F23 **REPUBLIC MACHINE & FABRICATION** **HAZNET** **S113120053**
313 REXFORD ST **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 5 of 15 in cluster F

Relative:
Higher

Actual:
1084 ft.

HAZNET:

Year:	2005
Gepaid:	CAL000253695
Contact:	JOHN BARRETT
Telephone:	9093700555

REPUBLIC MACHINE & FABRICATION (Continued) **S113120053**

Mailing Name: Not reported
Mailing Address: 313 REXFORD ST
Mailing City,St,Zip: COLTON, CA 92324
Gen County: Not reported
TSD EPA ID: CAT080013352
TSD County: Not reported
Waste Category: Unspecified organic liquid mixture
Disposal Method: Recycler
Tons: 0.22
Facility County: San Bernardino

F24 **5-STAR AUTO BODY** **San Bern. Co. Permit** **S109422543**
319 REXFORD ST **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 6 of 15 in cluster F

Relative: Higher

Actual: 1084 ft.

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0013094
Owner: MAKARYAN, SAM
Permit Number: PT0023018
Permit Category: CONDITIONALLY EXEMPT SMALL QUANTITY GENERATOR
Facility Status: ACTIVE
Expiration Date: 04/30/2013

B25 **MOSS BROS FORD** **HAZNET** **S113123370**
1900 W VALLEY BLVD **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 6 of 12 in cluster B

Relative: Lower

Actual: 1067 ft.

HAZNET:
Year: 2008
Gepaid: CAL000262514
Contact: MIKE DAWE, MGR
Telephone: 9098251212
Mailing Name: Not reported
Mailing Address: 1900 W VALLEY
Mailing City,St,Zip: COLTON, CA 923240000
Gen County: Not reported
TSD EPA ID: CAD093459485
TSD County: Not reported
Waste Category: Unspecified solvent mixture
Disposal Method: Not reported
Tons: 1.8108
Facility County: San Bernardino

Year: 2007
Gepaid: CAL000262514
Contact: MIKE DAWE, MGR
Telephone: 9098251212
Mailing Name: Not reported
Mailing Address: 1900 W VALLEY
Mailing City,St,Zip: COLTON, CA 923240000
Gen County: Not reported

MOSS BROS FORD (Continued) **S113123370**

TSD EPA ID: CAT080013352
TSD County: Not reported
Waste Category: Oil/water separation sludge
Disposal Method: Discharge To Sewer/Potw Or Npdes(With Prior Storage--With Or Without Treatment)
Tons: 5.21
Facility County: San Bernardino

Year: 2006
Gepaid: CAL000262514
Contact: MIKE DAWE, MGR
Telephone: 9098251212
Mailing Name: Not reported
Mailing Address: 1900 W VALLEY
Mailing City,St,Zip: COLTON, CA 923240000
Gen County: Not reported
TSD EPA ID: CAD981696420
TSD County: Not reported
Waste Category: Other organic solids
Disposal Method: Not reported
Tons: 0.12
Facility County: San Bernardino

Year: 2006
Gepaid: CAL000262514
Contact: MIKE DAWE, MGR
Telephone: 9098251212
Mailing Name: Not reported
Mailing Address: 1900 W VALLEY
Mailing City,St,Zip: COLTON, CA 923240000
Gen County: Not reported
TSD EPA ID: CAD028409019
TSD County: Not reported
Waste Category: Unspecified solvent mixture
Disposal Method: Transfer Station
Tons: 1.14
Facility County: San Bernardino

Year: 2006
Gepaid: CAL000262514
Contact: MIKE DAWE, MGR
Telephone: 9098251212
Mailing Name: Not reported
Mailing Address: 1900 W VALLEY
Mailing City,St,Zip: COLTON, CA 923240000
Gen County: Not reported
TSD EPA ID: CAD028409019
TSD County: Not reported
Waste Category: Unspecified solvent mixture
Disposal Method: Transfer Station
Tons: 0.45
Facility County: San Bernardino

Click this hyperlink while viewing on your computer to access
13 additional CA_HAZNET: record(s) in the EDR Site Report.

C26 **TELCO FOOD PRODUCTS** **FINDS** **1011980047**
2111 WEST VALLEY BLVD. **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 9 of 21 in cluster C

Relative: FINDS:
Lower

Registry ID: 110000529312

Actual:
1073 ft.

Environmental Interest/Information System
The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

CRITERIA AND HAZARDOUS AIR POLLUTANT INVENTORY

US EPA Risk Management Plan (RMP) database stores the risk management plans reported by companies that handle, manufacture, use, or store certain flammable or toxic substances, as required under section 112(r) of the Clean Air Act (CAA).

C27 **OROWEAT FOODS CO/RIALTO** **SWEEPS UST** **S102041385**
2036 W VALLEY BLVD **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 10 of 21 in cluster C

Relative: SWEEPS UST:
Lower

Status:	Active
Comp Number:	8398
Number:	1
Board Of Equalization:	Not reported
Referral Date:	03-24-92
Action Date:	03-24-92
Created Date:	09-21-88
Tank Status:	A
Owner Tank Id:	Not reported
Swrcb Tank Id:	36-000-008398-000001
Actv Date:	09-21-88
Capacity:	1
Tank Use:	UNKNOWN
Stg:	P
Content:	UNKNOWN
Number Of Tanks:	1

Actual:
1069 ft.

D28 **DELSOL AUTO SALES** **HAZNET** **S112963365**
1998 W VALLEY BLVD **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 4 of 10 in cluster D

Relative: HAZNET:
Lower

Year:	2007
Gepaid:	CAC002619713
Contact:	LUIS ALFONZO
Telephone:	9093764606

Actual:
1068 ft.

DELSOL AUTO SALES (Continued) **S112963365**

Mailing Name:	Not reported
Mailing Address:	1998 W VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 92324
Gen County:	Not reported
TSD EPA ID:	CAD097030993
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.05
Facility County:	San Bernardino

C29 **PRICE CLUB** **SWEEPS UST** **S106930885**
2109 W VALLEY **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 11 of 21 in cluster C

Relative:
Lower

Actual:
1073 ft.

SWEEPS UST:

Status:	Active
Comp Number:	13847
Number:	1
Board Of Equalization:	44-020518
Referral Date:	03-24-92
Action Date:	03-24-92
Created Date:	09-23-88
Tank Status:	A
Owner Tank Id:	Not reported
Swrcb Tank Id:	36-000-013847-000001
Actv Date:	09-23-88
Capacity:	1
Tank Use:	UNKNOWN
Stg:	P
Content:	UNKNOWN
Number Of Tanks:	3

Status:	Active
Comp Number:	13847
Number:	1
Board Of Equalization:	44-020518
Referral Date:	03-24-92
Action Date:	03-24-92
Created Date:	09-23-88
Tank Status:	A
Owner Tank Id:	Not reported
Swrcb Tank Id:	36-000-013847-000002
Actv Date:	09-23-88
Capacity:	1
Tank Use:	UNKNOWN
Stg:	P
Content:	UNKNOWN
Number Of Tanks:	Not reported

Status:	Active
Comp Number:	13847
Number:	1
Board Of Equalization:	44-020518
Referral Date:	03-24-92

PRICE CLUB (Continued) **S106930885**

Action Date:	03-24-92
Created Date:	09-23-88
Tank Status:	A
Owner Tank Id:	Not reported
Swrcb Tank Id:	36-000-013847-000003
Actv Date:	09-23-88
Capacity:	1
Tank Use:	UNKNOWN
Stg:	P
Content:	UNKNOWN
Number Of Tanks:	Not reported

D30 **VALLEY TRUCK FILTERS & PARTS** **AST** **A100346242**
2006 W. VALLEY BLVD **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 5 of 10 in cluster D

Relative: AST:
Lower

Owner:	VASQUEZ, JOSE
Total Gallons:	1,865
Certified Unified Program Agencies:	San Bernardino

Actual:
1068 ft.

D31 **EDR US Hist Auto Stat** **1015298825**
1998 W VALLEY BLVD **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 6 of 10 in cluster D

Relative: EDR Historical Auto Stations:
Lower

Name:	WEST AUTO ENTERPRISES INC
Year:	2003
Address:	1998 W VALLEY BLVD

Actual:
1068 ft.

D32 **EDR US Hist Auto Stat** **1015304032**
2006 W VALLEY BLVD **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 7 of 10 in cluster D

Relative: EDR Historical Auto Stations:
Lower

Name:	TEXACAL AUTO & TRUCK REPAIR
Year:	1999
Address:	2006 W VALLEY BLVD

Actual:
1068 ft.

Name:	TEXACAL AUTO & TRUCK REPAIR
Year:	2000
Address:	2006 W VALLEY BLVD

B33 **COLTON GOLF CLUB** **HAZNET** **S112886419**
1901 W VALLEY BLVD **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 7 of 12 in cluster B

Relative: HAZNET:
Lower

Year:	1998
Gepaid:	CAC001380464
Contact:	BOB JAMES
Telephone:	9098771712
Mailing Name:	Not reported
Mailing Address:	1901 W VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	Not reported
TSD EPA ID:	CAT080022148
TSD County:	Not reported
Waste Category:	Off-specification, aged or surplus organics
Disposal Method:	Transfer Station
Tons:	.0834
Facility County:	San Bernardino

Actual:
1067 ft.

Year:	1998
Gepaid:	CAC001380464
Contact:	BOB JAMES
Telephone:	9098771712
Mailing Name:	Not reported
Mailing Address:	1901 W VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	Not reported
TSD EPA ID:	CAD982444481
TSD County:	Not reported
Waste Category:	Unspecified oil-containing waste
Disposal Method:	Transfer Station
Tons:	.0834
Facility County:	San Bernardino

Year:	1998
Gepaid:	CAC001380464
Contact:	BOB JAMES
Telephone:	9098771712
Mailing Name:	Not reported
Mailing Address:	1901 W VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	Not reported
TSD EPA ID:	CAD982444481
TSD County:	Not reported
Waste Category:	Waste oil and mixed oil
Disposal Method:	Transfer Station
Tons:	.5004
Facility County:	San Bernardino

Year:	1998
Gepaid:	CAC001380464
Contact:	BOB JAMES
Telephone:	9098771712
Mailing Name:	Not reported
Mailing Address:	1901 W VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 923240000

COLTON GOLF CLUB (Continued) **S112886419**

Gen County: Not reported
TSD EPA ID: CAD982444481
TSD County: Not reported
Waste Category: Off-specification, aged or surplus organics
Disposal Method: Transfer Station
Tons: .0834
Facility County: San Bernardino

F34 **UNIVERSAL MACK SALES SERVICE** **RCRA-SQG 1000431647**
220 N REX FORD **FINDS CAD982522609**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 7 of 15 in cluster F

Relative: Lower

Actual: 1079 ft.

RCRA-SQG:
Date form received by agency: 04/05/1989
Facility name: UNIVERSAL MACK SALES SERVICE
Facility address: 220 N REX FORD
COLTON, CA 92324
EPA ID: CAD982522609
Mailing address: N REX FORD
COLTON, CA 92324
Contact: ENVIRONMENTAL MANAGER
Contact address: 220 N REX FORD
COLTON, CA 92324
Contact country: US
Contact telephone: (714) 825-8750
Contact email: Not reported
EPA Region: 09
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: UNIVERSAL MACK INC
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

UNIVERSAL MACK SALES SERVICE (Continued) **1000431647**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110002841373

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

C35 **ERNS** **2008881798**
2111 WEST VALLEY BLVD **N/A**
< 1/8 **COLTON, CA**
1 ft.

Site 12 of 21 in cluster C

Relative: Lower

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

Actual: 1073 ft.

F36 **REPUBLIC MACHINE & FABRICATION** **San Bern. Co. Permit** **S104769514**
313 REXFORD ST **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 8 of 15 in cluster F

Relative: Higher

Actual: 1084 ft.

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0005670
Owner: BARRETT, JOHN
Permit Number: PT0000484
Permit Category: SPECIAL GENERATOR
Facility Status: ACTIVE
Expiration Date: 11/30/2013

Region: SAN BERNARDINO

REPUBLIC MACHINE & FABRICATION (Continued) **S104769514**

Facility ID: FA0005670
Owner: BARRETT, JOHN
Permit Number: PT0000483
Permit Category: SPECIAL HANDLER
Facility Status: ACTIVE
Expiration Date: 11/30/2013

F37 **FIRST COMMERCIAL BANK USA** **HAZNET** **S112992565**
1759 W VALLEY BLVD **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 9 of 15 in cluster F

Relative: HAZNET:
Lower
Year: 2011
Gepaid: CAC002674830
Actual: Contact: HUILING CHEN EXT 121
1078 ft. Telephone: 6263006000
Mailing Name: Not reported
Mailing Address: 200 E MAIN ST
Mailing City,St,Zip: ALHAMBRA, CA 918013517
Gen County: Not reported
TSD EPA ID: CAD982444481
TSD County: Not reported
Waste Category: Other organic solids
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.0325
Facility County: San Bernardino

Year: 2011
Gepaid: CAC002674830
Contact: HUILING CHEN EXT 121
Telephone: 6263006000
Mailing Name: Not reported
Mailing Address: 200 E MAIN ST
Mailing City,St,Zip: ALHAMBRA, CA 918013517
Gen County: Not reported
TSD EPA ID: CAD982444481
TSD County: Not reported
Waste Category: Off-specification, aged or surplus organics
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.297
Facility County: San Bernardino

G38 **SLOVER MT HIGH SCHOOL** **HAZNET** **S113027305**
325 HERMOSA **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 1 of 7 in cluster G

Relative: HAZNET:
Lower
Year: 1994
Gepaid: CAL000016219
Actual: Contact: COLTON JOINT UNIFIED
1044 ft.

SLOVER MT HIGH SCHOOL (Continued) **S113027305**

Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 1212 VALENCIA DRIVE
Mailing City,St,Zip: COLTON, CA 923240000
Gen County: Not reported
TSD EPA ID: CAD067786749
TSD County: Not reported
Waste Category: Asbestos containing waste
Disposal Method: Not reported
Tons: 8.4280
Facility County: San Bernardino

Year: 1994
Gepaid: CAL000016219
Contact: COLTON JOINT UNIFIED
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 1212 VALENCIA DRIVE
Mailing City,St,Zip: COLTON, CA 923240000
Gen County: Not reported
TSD EPA ID: CAD067786749
TSD County: Not reported
Waste Category: Asbestos containing waste
Disposal Method: Disposal, Land Fill
Tons: 21.0700
Facility County: San Bernardino

B39 **HMIRS** **95101485**
1849 W VALLEY BLVD **N/A**
< 1/8 **COLTON, CA**
1 ft.

Site 8 of 12 in cluster B

Relative: Higher

Click this hyperlink while viewing on your computer to access additional HMIRS detail in the EDR Site Report.

Actual: 1081 ft.

F40 **EDR US Hist Auto Stat** **1015421565**
320 REXFORD ST **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 10 of 15 in cluster F

Relative: Higher

Actual: 1084 ft.

EDR Historical Auto Stations:
Name: AMCAL AUTOMOTIVE
Year: 2000
Address: 320 REXFORD ST

Name: AMCAL AUTOMOTIVE
Year: 2003
Address: 320 REXFORD ST

Name: AMCAL AUTOMOTIVE
Year: 2004
Address: 320 REXFORD ST

Name: AMCAL AUTOMOTIVE
Year: 2005

(Continued) **1015421565**

Address: 320 REXFORD ST

B41 **MOSS BROS FORD** **RCRA NonGen / NLR** **1012175848**
1900 W VALLEY BLVD **HAZNET** **CAR000130690**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 9 of 12 in cluster B

Relative: Lower

Actual: 1067 ft.

RCRA NonGen / NLR:

Date form received by agency:	05/26/2009
Facility name:	MOSS BROS FORD
Facility address:	1900 W VALLEY BLVD COLTON, CA 92324
EPA ID:	CAR000130690
Mailing address:	8146 AUTO DR RIVERSIDE, CA 92504
Contact:	SUSAN MCAULEY
Contact address:	8146 AUTO DR RIVERSIDE, CA 92504
Contact country:	US
Contact telephone:	951-688-6200
Telephone ext.:	1613
Contact email:	SMCAULEY@MOSSSAVINGS.COM
EPA Region:	09
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	MIKE DAWE
Owner/operator address:	1900 W VALLEY BLVD COLTON, CA 92324
Owner/operator country:	US
Owner/operator telephone:	(909) 825-1212
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	11/18/2002
Owner/Op end date:	Not reported

Owner/operator name:	GLENN MOSS
Owner/operator address:	1900 W VALLEY BLVD COLTON, CA 92324
Owner/operator country:	US
Owner/operator telephone:	(909) 825-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	11/18/2002
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No

MOSS BROS FORD (Continued) **1012175848**

Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 11/18/2002
Facility name: MOSS BROS FORD
Classification: Small Quantity Generator

Violation Status: No violations found

HAZNET:
Year: 2008
Gepaid: CAR000130690
Contact: MIKE DANE, MGR
Telephone: 9098251212
Mailing Name: Not reported
Mailing Address: 8146 AUTO DR
Mailing City,St,Zip: RIVERSIDE, CA 925044104
Gen County: Not reported
TSD EPA ID: CAD028409019
TSD County: Not reported
Waste Category: Off-specification, aged or surplus organics
Disposal Method: Fuel Blending Prior To Energy Recovery At Another Site
Tons: 1.1385
Facility County: San Bernardino

Year: 2008
Gepaid: CAR000130690
Contact: MIKE DANE, MGR
Telephone: 9098251212
Mailing Name: Not reported
Mailing Address: 8146 AUTO DR
Mailing City,St,Zip: RIVERSIDE, CA 925044104
Gen County: Not reported
TSD EPA ID: CAD028409019
TSD County: Not reported
Waste Category: Unspecified organic liquid mixture
Disposal Method: Fuel Blending Prior To Energy Recovery At Another Site
Tons: 0.374
Facility County: San Bernardino

Year: 2008
Gepaid: CAR000130690
Contact: MIKE DANE, MGR
Telephone: 9098251212
Mailing Name: Not reported
Mailing Address: 8146 AUTO DR
Mailing City,St,Zip: RIVERSIDE, CA 925044104
Gen County: Not reported
TSD EPA ID: CAD028409019
TSD County: Not reported
Waste Category: Other organic solids

MOSS BROS FORD (Continued) **1012175848**

Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.275
Facility County:	San Bernardino
Year:	2008
Gepaid:	CAR000130690
Contact:	MIKE DANE, MGR
Telephone:	9098251212
Mailing Name:	Not reported
Mailing Address:	8146 AUTO DR
Mailing City,St,Zip:	RIVERSIDE, CA 925044104
Gen County:	Not reported
TSD EPA ID:	CAD028409019
TSD County:	Not reported
Waste Category:	Waste oil and mixed oil
Disposal Method:	Fuel Blending Prior To Energy Recovery At Another Site
Tons:	0.114
Facility County:	San Bernardino
Year:	2008
Gepaid:	CAR000130690
Contact:	MIKE DANE, MGR
Telephone:	9098251212
Mailing Name:	Not reported
Mailing Address:	8146 AUTO DR
Mailing City,St,Zip:	RIVERSIDE, CA 925044104
Gen County:	Not reported
TSD EPA ID:	CAD008252405
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues 10 percent or more
Disposal Method:	Fuel Blending Prior To Energy Recovery At Another Site
Tons:	0.01251
Facility County:	San Bernardino

Click this hyperlink while viewing on your computer to access
5 additional CA_HAZNET: record(s) in the EDR Site Report.

B42 **HMIRS** **94030500**
1849 W VALLEY BLVD **N/A**
< 1/8 **COLTON, CA**
1 ft.

Site 10 of 12 in cluster B

Relative:
Higher

Click this hyperlink while viewing on your computer to access
additional HMIRS detail in the EDR Site Report.

Actual:
1081 ft.

C43 **TELCO FOODS** **LUST** **S108723555**
2111 VALLEY BOULEVARD WEST **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 13 of 21 in cluster C

Relative:
Lower

Actual:
1073 ft.

LUST:

Region:	STATE
Global Id:	T0607105014
Latitude:	34.071483
Longitude:	-117.365655
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	07/30/2007
Lead Agency:	SAN BERNARDINO COUNTY
Case Worker:	JC
Local Agency:	SAN BERNARDINO COUNTY
RB Case Number:	Not reported
LOC Case Number:	2006010
File Location:	Local Agency
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607105014
Contact Type:	Local Agency Caseworker
Contact Name:	JACKSON CRUTSINGER
Organization Name:	SAN BERNARDINO COUNTY
Address:	620 SOUTH E STREET
City:	SAN BERNARDINO
Email:	jcrutsinger@sbcfire.org
Phone Number:	Not reported

Global Id:	T0607105014
Contact Type:	Regional Board Caseworker
Contact Name:	Ken Williams
Organization Name:	SANTA ANA RWQCB (REGION 8)
Address:	3737 MAIN STREET, SUITE 500
City:	RIVERSIDE
Email:	kwilliams@waterboards.ca.gov
Phone Number:	Not reported

Regulatory Activities:

Global Id:	T0607105014
Action Type:	Other
Date:	01/01/1950
Action:	Leak Discovery

Global Id:	T0607105014
Action Type:	REMEDIATION
Date:	01/01/1950
Action:	Not reported

Global Id:	T0607105014
Action Type:	Other
Date:	01/01/1950

TELCO FOODS (Continued) **S108723555**

Action: Leak Reported

B44 **CC WESTERN/CENTRAL TRANSPORT INC** **HAZNET** **S112933410**
1849 W VALLEY BLVD **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 11 of 12 in cluster B

Relative: Lower

Actual: 1070 ft.

HAZNET:

Year:	2003
Gepaid:	CAC002571114
Contact:	DAVE MATTHEWS
Telephone:	9098747040
Mailing Name:	Not reported
Mailing Address:	1849 W VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 923241810
Gen County:	Not reported
TSD EPA ID:	CAT080013352
TSD County:	Not reported
Waste Category:	Unspecified organic liquid mixture
Disposal Method:	Recycler
Tons:	0.2
Facility County:	San Bernardino

Year:	2003
Gepaid:	CAC002571114
Contact:	DAVE MATTHEWS
Telephone:	9098747040
Mailing Name:	Not reported
Mailing Address:	1849 W VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 923241810
Gen County:	Not reported
TSD EPA ID:	CAT080033681
TSD County:	Not reported
Waste Category:	Unspecified organic liquid mixture
Disposal Method:	Disposal, Land Fill
Tons:	0.07
Facility County:	San Bernardino

Year:	2003
Gepaid:	CAC002571114
Contact:	DAVE MATTHEWS
Telephone:	9098747040
Mailing Name:	Not reported
Mailing Address:	1849 W VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 923241810
Gen County:	Not reported
TSD EPA ID:	CAT080033681
TSD County:	Not reported
Waste Category:	Liquids with pH <= 2 with metals
Disposal Method:	Recycler
Tons:	0.03
Facility County:	San Bernardino

Year:	2003
Gepaid:	CAC002571114
Contact:	DAVE MATTHEWS

CC WESTERN/CENTRAL TRANSPORT INC (Continued) **S112933410**

Telephone: 9098747040
Mailing Name: Not reported
Mailing Address: 1849 W VALLEY BLVD
Mailing City,St,Zip: COLTON, CA 923241810
Gen County: Not reported
TSD EPA ID: CAT080033681
TSD County: Not reported
Waste Category: Other organic solids
Disposal Method: Disposal, Land Fill
Tons: 0.75
Facility County: San Bernardino

Year: 2003
Gepaid: CAC002571114
Contact: DAVE MATTHEWS
Telephone: 9098747040
Mailing Name: Not reported
Mailing Address: 1849 W VALLEY BLVD
Mailing City,St,Zip: COLTON, CA 923241810
Gen County: Not reported
TSD EPA ID: CAT080033681
TSD County: Not reported
Waste Category: Unspecified organic liquid mixture
Disposal Method: Recycler
Tons: 0.2
Facility County: San Bernardino

Click this hyperlink while viewing on your computer to access additional CA_HAZNET: detail in the EDR Site Report.

D45 **COLTON AUTO SALES** **HAZNET** **S113101249**
1998 W. VALLEY BLVD **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 8 of 10 in cluster D

Relative: HAZNET:
Lower
Year: 2001
Gepaid: CAL000194592
Actual: Contact: LINDA RAWDING/OWNER
1068 ft. Telephone: 9098209981
Mailing Name: Not reported
Mailing Address: 1998 W. VALLEY BLVD
Mailing City,St,Zip: COLTON, CA 923240000
Gen County: Not reported
TSD EPA ID: CAD008302903
TSD County: Not reported
Waste Category: Waste oil and mixed oil
Disposal Method: Recycler
Tons: 0.22
Facility County: San Bernardino

Year: 2000
Gepaid: CAL000194592
Contact: LINDA RAWDING/OWNER
Telephone: 9098209981
Mailing Name: Not reported
Mailing Address: 1998 W. VALLEY BLVD

COLTON AUTO SALES (Continued) **S113101249**

Mailing City,St,Zip: COLTON, CA 923240000
Gen County: Not reported
TSD EPA ID: CAD008302903
TSD County: Not reported
Waste Category: Waste oil and mixed oil
Disposal Method: Recycler
Tons: 0.52
Facility County: San Bernardino

Year: 1999
Gepaid: CAL000194592
Contact: LINDA RAWDING
Telephone: 9098209981
Mailing Name: Not reported
Mailing Address: 1998 W. VALLEY BLVD
Mailing City,St,Zip: COLTON, CA 923240000
Gen County: Not reported
TSD EPA ID: CAD008302903
TSD County: Not reported
Waste Category: Waste oil and mixed oil
Disposal Method: Recycler
Tons: .4170
Facility County: San Bernardino

Year: 1998
Gepaid: CAL000194592
Contact: LINDA RAWDING
Telephone: 9098209981
Mailing Name: Not reported
Mailing Address: 1998 W. VALLEY BLVD
Mailing City,St,Zip: COLTON, CA 923240000
Gen County: Not reported
TSD EPA ID: CAD008302903
TSD County: Not reported
Waste Category: Other organic solids
Disposal Method: Transfer Station
Tons: .2000
Facility County: San Bernardino

Year: 1998
Gepaid: CAL000194592
Contact: LINDA RAWDING
Telephone: 9098209981
Mailing Name: Not reported
Mailing Address: 1998 W. VALLEY BLVD
Mailing City,St,Zip: COLTON, CA 923240000
Gen County: Not reported
TSD EPA ID: CAD008302903
TSD County: Not reported
Waste Category: Waste oil and mixed oil
Disposal Method: Recycler
Tons: .1668
Facility County: San Bernardino

Click this hyperlink while viewing on your computer to access additional CA_HAZNET: detail in the EDR Site Report.

C46 **CHMIRS** **S110418810**
N/A

2111 WEST VALLEY BLVD.
< 1/8 **COLTON, CA**
1 ft.

Site 14 of 21 in cluster C

Relative: CHMIRS:
Lower

OES Incident Number:	'08-6202	
OES notification:	08/25/2008	
Actual: OES Date:	Not reported	
1073 ft. OES Time:	Not reported	
Incident Date:	Not reported	
Date Completed:	**Not reported**	
Property Use:	Not reported	
Agency Id Number:	Not reported	
Agency Incident Number:	Not reported	
Time Notified:	Not reported	
Time Completed:	Not reported	
Surrounding Area:	Not reported	
Estimated Temperature:	Not reported	
Property Management:	Not reported	
Special Studies 1:	Not reported	
Special Studies 2:	Not reported	
Special Studies 3:	Not reported	
Special Studies 4:	Not reported	
Special Studies 5:	Not reported	
Special Studies 6:	Not reported	
More Than Two Substances Involved?:		Not reported
Resp Agncy Personel # Of Decontaminated:		Not reported
Responding Agency Personel # Of Injuries:		Not reported
Responding Agency Personel # Of Fatalities:		Not reported
Others Number Of Decontaminated:		Not reported
Others Number Of Injuries:		Not reported
Others Number Of Fatalities:		Not reported
Vehicle Make/year:	Not reported	
Vehicle License Number:	Not reported	
Vehicle State:	Not reported	
Vehicle Id Number:	Not reported	
CA/DOT/PUC/ICC Number:	Not reported	
Company Name:	Not reported	
Reporting Officer Name/ID:	Not reported	
Report Date:	Not reported	
Comments:	Not reported	
Facility Telephone:	Not reported	
Waterway Involved:	No	
Waterway:	Not reported	
Spill Site:	Merchant/Business	
Cleanup By:	Contractor	
Containment:	Not reported	
What Happened:	Not reported	
Type:	Not reported	
Measure:	Lbs.	
Other:	Not reported	
Date/Time:	1600	
Year:	2008	
Agency:	Telco Food Products	
Incident Date:	8/25/2008	
Admin Agency:	San Bernardino County Health Department	
Amount:	Not reported	

(Continued) **S110418810**

Contained:	Yes
Site Type:	Not reported
E Date:	Not reported
Substance:	Ammonia
Quantity Released:	unknown
BBLS:	Not reported
Cups:	Not reported
CUFT:	Not reported
Gallons:	Not reported
Grams:	Not reported
Pounds:	Not reported
Liters:	Not reported
Ounces:	Not reported
Pints:	Not reported
Quarts:	Not reported
Sheen:	Not reported
Tons:	Not reported
Unknown:	Not reported
Evacuations:	150
Number of Injuries:	0
Number of Fatalities:	0
Description:	An alarm sounded in a containment room and its unknown if a leak occured. The room is currently being ventilated so that a crew may enter and inspect for a leak. If a leak has occurred it should be within the containment area.

H47 **1X COUNTY OF SAN BERNARDINO** **HAZNET** **S112851506**
1500 W SAN BERNARDINO AVE **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 1 of 2 in cluster H

Relative:
Higher

Actual:
1101 ft.

HAZNET:

Year:	1994
Gepaid:	CAC000902760
Contact:	Not reported
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	825 E 3RD ST
Mailing City,St,Zip:	SAN BERNARDINO, CA 924150849
Gen County:	Not reported
TSD EPA ID:	CAD980883177
TSD County:	Not reported
Waste Category:	Tank bottom waste
Disposal Method:	Recycler
Tons:	1.0425
Facility County:	San Bernardino

C48 **LANDJET MOTOR CARRIERS** **San Bern. Co. Permit** **S102683578**
2048 W VALLEY BLVD **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 15 of 21 in cluster C

Relative:
Lower

Actual:
1070 ft.

San Bern. Co. Permit:

Region:	SAN BERNARDINO
Facility ID:	FA0004376
Owner:	SACALAS, BARRY
Permit Number:	PT0009073
Permit Category:	SPECIAL GENERATOR
Facility Status:	INACTIVE
Expiration Date:	11/30/2011

Region:	SAN BERNARDINO
Facility ID:	FA0004376
Owner:	SACALAS, BARRY
Permit Number:	PT0009072
Permit Category:	SPECIAL HANDLER
Facility Status:	INACTIVE
Expiration Date:	11/30/2011

C49 **TELCO FOOD PRODUCTS** **EMI** **S108433425**
2111 W VALLEY BLVD **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 16 of 21 in cluster C

Relative:
Lower

Actual:
1073 ft.

EMI:

Year:	2005
County Code:	36
Air Basin:	SC
Facility ID:	141077
Air District Name:	SC
SIC Code:	2051
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	3.064
Reactive Organic Gases Tons/Yr:	2.0313324
Carbon Monoxide Emissions Tons/Yr:	1.98
NOX - Oxides of Nitrogen Tons/Yr:	1.44
SOX - Oxides of Sulphur Tons/Yr:	.0339
Particulate Matter Tons/Yr:	.664
Part. Matter 10 Micrometers & Smllr Tons/Yr:	.63704

Year:	2007
County Code:	36
Air Basin:	SC
Facility ID:	141077
Air District Name:	SC
SIC Code:	2051
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	9.809227645247861900
Reactive Organic Gases Tons/Yr:	6.6105
Carbon Monoxide Emissions Tons/Yr:	1.87
NOX - Oxides of Nitrogen Tons/Yr:	1.37

TELCO FOOD PRODUCTS (Continued) **S108433425**

SOX - Oxides of Sulphur Tons/Yr: .03
Particulate Matter Tons/Yr: .83
Part. Matter 10 Micrometers & Smllr Tons/Yr: .681

E50 **BISHOP'S CENTRAL STORES** **UST** **U003971288**
791 N PEPPER AVE **SWEEPS UST** **N/A**
< 1/8 **COLTON, CA 92324** **San Bern. Co. Permit**
1 ft.

Site 2 of 2 in cluster E

Relative:
Lower

Actual:
1078 ft.

UST:
Facility ID: 87013607
Latitude: 34.07464
Longitude: -117.353

SWEEPS UST:
Status: Active
Comp Number: 608
Number: 1
Board Of Equalization: Not reported
Referral Date: 03-23-92
Action Date: 03-23-92
Created Date: 03-28-90
Tank Status: A
Owner Tank Id: 6D2
Swrcb Tank Id: 36-000-000608-000001
Actv Date: 03-28-90
Capacity: 6000
Tank Use: M.V. FUEL
Stg: P
Content: DIESEL
Number Of Tanks: 4

Status: Active
Comp Number: 608
Number: 1
Board Of Equalization: Not reported
Referral Date: 03-23-92
Action Date: 03-23-92
Created Date: 03-28-90
Tank Status: A
Owner Tank Id: 6D5
Swrcb Tank Id: 36-000-000608-000002
Actv Date: 03-28-90
Capacity: 250
Tank Use: M.V. FUEL
Stg: P
Content: DIESEL
Number Of Tanks: Not reported

Status: Active
Comp Number: 608
Number: 1
Board Of Equalization: Not reported
Referral Date: 03-23-92
Action Date: 03-23-92
Created Date: 03-28-90

BISHOP'S CENTRAL STORES (Continued) **U003971288**

Tank Status: A
Owner Tank Id: 6D5
Swrcb Tank Id: 36-000-000608-000003
Actv Date: 03-28-90
Capacity: 12000
Tank Use: M.V. FUEL
Stg: P
Content: DIESEL
Number Of Tanks: Not reported

Status: Active
Comp Number: 608
Number: 1
Board Of Equalization: Not reported
Referral Date: 03-23-92
Action Date: 03-23-92
Created Date: 03-28-90
Tank Status: A
Owner Tank Id: 6D5
Swrcb Tank Id: 36-000-000608-000004
Actv Date: 03-28-90
Capacity: 500
Tank Use: M.V. FUEL
Stg: P
Content: DIESEL
Number Of Tanks: Not reported

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0001493
Owner: CHURCH OF JESUS CHRIST OF LATTER DAY SAINTS
Permit Number: PT0003330
Permit Category: HAZMAT HANDLER 0-10 EMPLOYEES
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0001493
Owner: CHURCH OF JESUS CHRIST OF LATTER DAY SAINTS
Permit Number: PT0003331
Permit Category: APSA 100,001-1,000,000 GAL FAC CAPACITY
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0001493
Owner: CHURCH OF JESUS CHRIST OF LATTER DAY SAINTS
Permit Number: PT0024293
Permit Category: EPCRA FACILITY
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0001493
Owner: CHURCH OF JESUS CHRIST OF LATTER DAY SAINTS
Permit Number: PT0011245
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)

BISHOP'S CENTRAL STORES (Continued) **U003971288**

Facility Status: ACTIVE
Expiration Date: 10/31/2013

C51 **TELCO FOOD PRODUCTS, INC.** **AST** **S104770949**
2111 W VALLEY **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 17 of 21 in cluster C

Relative: AST:
Lower Owner: BEST BRANDS CORP.
Total Gallons: 28,885
Actual: Certified Unified Program Agencies: San Bernardino
1073 ft.

B52 **HMIRS** **95060019**
1849 WEST VALLEY BLVD **N/A**
< 1/8 **COLTON, CA**
1 ft.

Site 12 of 12 in cluster B

Relative: Click this hyperlink while viewing on your computer to access
Higher additional HMIRS detail in the EDR Site Report.

Actual:
1081 ft.

I53 **CHMIRS** **S100280750**
CORNER OF PEPPER/SAN BERNARDINO AVE. **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 1 of 6 in cluster I

Relative: CHMIRS:
Higher

OES Incident Number:	9990861
OES notification:	Not reported
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	20-FEB-88
Date Completed:	**20-FEB-88**
Property Use:	962
Agency Id Number:	36709
Agency Incident Number:	0
Time Notified:	1855
Time Completed:	2000
Surrounding Area:	400
Estimated Temperature:	55
Property Management:	C
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Involved?:	N
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported

Actual:
1081 ft.

(Continued) **S100280750**

Others Number Of Injuries:		Not reported
Others Number Of Fatalities:		Not reported
Vehicle Make/year:	Not reported	
Vehicle License Number:	Not reported	
Vehicle State:	Not reported	
Vehicle Id Number:	Not reported	
CA/DOT/PUC/ICC Number:	Not reported	
Company Name:	Not reported	
Reporting Officer Name/ID:	LYNETTE E. REICHERT	
Report Date:	07-MAY-88	
Comments:	Y	
Facility Telephone:	714 387-3044	
Waterway Involved:	Not reported	
Waterway:	Not reported	
Spill Site:	Not reported	
Cleanup By:	Not reported	
Containment:	Not reported	
What Happened:	Not reported	
Type:	Not reported	
Measure:	Not reported	
Other:	Not reported	
Date/Time:	Not reported	
Year:	88-92	
Agency:	Not reported	
Incident Date:	Not reported	
Admin Agency:	Not reported	
Amount:	Not reported	
Contained:	Not reported	
Site Type:	Not reported	
E Date:	03-MAY-89	
Substance:	Not reported	
Quantity Released:	Not reported	
BBLS:	Not reported	
Cups:	Not reported	
CUFT:	Not reported	
Gallons:	Not reported	
Grams:	Not reported	
Pounds:	Not reported	
Liters:	Not reported	
Ounces:	Not reported	
Pints:	Not reported	
Quarts:	Not reported	
Sheen:	Not reported	
Tons:	Not reported	
Unknown:	Not reported	
Evacuations:	Not reported	
Number of Injuries:	Not reported	
Number of Fatalities:	Not reported	
Description:	Not reported	

D54 **GRACE WR & CO DISTRIB SVCS** **RCRA NonGen / NLR** **1000168595**
1988 W VALLEY BLVD **FINDS** **CAT000612168**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 9 of 10 in cluster D

Relative:
Lower

Actual:
1068 ft.

RCRA NonGen / NLR:

Date form received by agency:	08/18/1980
Facility name:	GRACE WR & CO DISTRIB SVCS
Facility address:	1988 W VALLEY BLVD COLTON, CA 92324
EPA ID:	CAT000612168
Mailing address:	W VALLEY BLVD COLTON, CA 92324
Contact:	ENVIRONMENTAL MANAGER
Contact address:	1988 W VALLEY BLVD COLTON, CA 92324
Contact country:	US
Contact telephone:	(803) 433-2107
Contact email:	Not reported
EPA Region:	09
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	NOT REQUIRED
Owner/operator address:	NOT REQUIRED NOT REQUIRED, ME 99999
Owner/operator country:	Not reported
Owner/operator telephone:	(415) 555-1212
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	W R GRACE & CO
Owner/operator address:	NOT REQUIRED NOT REQUIRED, ME 99999
Owner/operator country:	Not reported
Owner/operator telephone:	(415) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	Yes
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No

GRACE WR & CO DISTRIB SVCS (Continued) **1000168595**

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110002942941

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

C55 **PEGGIE MERRIMAN** **HAZNET** **S112981376**
2040 VALLEY BLVD **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 18 of 21 in cluster C

Relative:
Lower

Actual:
1069 ft.

HAZNET:
Year: 2009
Gepaid: CAC002648212
Contact: PEGGIE MERRIMAN
Telephone: 9098218605
Mailing Name: Not reported
Mailing Address: 1202 E 40TH ST
Mailing City,St,Zip: SAN BERNARDINO, CA 924041523
Gen County: Not reported
TSD EPA ID: CAD982444481
TSD County: Not reported
Waste Category: Unspecified oil-containing waste
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 1.4595
Facility County: San Bernardino

D56 **VALLEY TRUCK FILTERS & PARTS** **SWEEPS UST** **S106112121**
2006 W VALLEY BLVD **San Bern. Co. Permit** **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 10 of 10 in cluster D

Relative:
Lower

Actual:
1068 ft.

SWEEPS UST:
Status: Active
Comp Number: 7907
Number: 2
Board Of Equalization: 44-020027
Referral Date: 03-24-92
Action Date: 03-24-92
Created Date: 09-15-88
Tank Status: A

VALLEY TRUCK FILTERS & PARTS (Continued) **S106112121**

Owner Tank Id: Not reported
Swrcb Tank Id: 36-000-007907-000001
Actv Date: 09-15-88
Capacity: 1
Tank Use: UNKNOWN
Stg: P
Content: UNKNOWN
Number Of Tanks: 1

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0007517
Owner: VASQUEZ, JOSE
Permit Number: PT0012879
Permit Category: SPECIAL GENERATOR
Facility Status: ACTIVE
Expiration Date: 11/30/2013

Region: SAN BERNARDINO
Facility ID: FA0007517
Owner: VASQUEZ, JOSE
Permit Number: PT0012880
Permit Category: SPECIAL HANDLER
Facility Status: ACTIVE
Expiration Date: 11/30/2013

Region: SAN BERNARDINO
Facility ID: FA0007517
Owner: VASQUEZ, JOSE
Permit Number: PT0012881
Permit Category: APSA 1,320-10,000 GAL FAC CAPACITY
Facility Status: ACTIVE
Expiration Date: 11/30/2013

C57 **TELCO FOOD PRODUCTS, INC.** **RMP** **1011838991**
2111 WEST VALLEY BLVD. **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 19 of 21 in cluster C

Relative:
Lower

Actual:
1073 ft.

Risk Management Plan (RMP) Facility Details:
Facility ID: 19245
LEPC city: Region VI LEPC
Facility decimal latitude: 34.071944
Facility decimal longitude: -117.364722
Is facility in county box: T
LatLong method: I4
LatLong description: CE
Home page web address: Not reported
Facility telephone: Not reported
Facility email: Not reported
Facility DUNS #: 9648304
Parent's name: Not reported
Partner's name: Not reported
Parent's DUNS #: 0
Partner's DUNS #: 0
Operator's name: Tim Telliard

TELCO FOOD PRODUCTS, INC. (Continued) **1011838991**

Operator's telephone:	9098257343
Operator's address:	2111 West Valley Blvd.
Operators City,St,Zip:	Colton, CA 92324
RMP implementation contact:	Tim Telliard
RMP contact title:	President
Emergency contact:	Tim Telliard
Emergency contact title:	President
Emergency contact telephone:	9098257343
24 hour emergency telephone:	9092046659
Emergency contact ext/pin #:	Not reported
Number of full time employees:	100
EPA ID:	Not reported
Facility ID provided by CEPPO:	100000164412
Is facility covered by OSHA PSM:	T
Is facility covered by EPCRA 302:	T
Is fac. covered by CAA Title V 112(2):	F
Clean air op. permit/State ID:	Not reported
Last safety insp. dat:	Not reported
Inspected by:	Fire Department
Is it OSHA approved with star/merit ranking:	False
Will RMP involve predictive filing:	False
Submission type:	First Time
RMP description:	Not reported
Facility has no accident hist. recs:	True
Foreign owner's address:	Not reported
Foreign owner's zip:	Not reported
Foreign owner's country:	Not reported
Claim # of employees as CBI:	False
Date RMP accepted by EPA:	12/15/1999
Date of error Report:	Not reported
Date RMP received:	12/14/1999
Does RMP contain graphics files:	False
Does RMP contain attachments:	False
Was certification letter received:	True
RMP submission method:	Commercial Software Vendor
Does RMP contain CBI substantiation:	False
Does RMP contain electronic waiver:	False
Date RMP postmarked:	12/13/1999
Is RMP complete:	True
Date of de-registration:	Not reported
Date de-registration is effective:	Not reported
Aniversary date:	12/13/2004
Does RMP contain CBI data:	False
Does RMP contain unsanitized CBI version:	False
RMP version #:	1.1.7
FRS latitude:	34.07051
FRS longitude:	-117.36537
FRS Description:	PLANT ENTRANCE (GENERAL)
FRS Method:	ADDRESS MATCHING-HOUSE NUMBER

Process Details:

Process ID:	27081
NA & Industry Classification Sys.code(s):	31181
NAICS code description:	Bread and Bakery Product Manufacturing
Optional facility description:	Bakery Manufacturer
Program level:	3
Record contains CBI data:	False

TELCO FOOD PRODUCTS, INC. (Continued) **1011838991**

Process chemical(s):
- Chemical name: Ammonia (anhydrous)
- Process chemical qty in 100s lbs: 14200
- Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Toxics Worst Case:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported

TELCO FOOD PRODUCTS, INC. (Continued) **1011838991**

Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

TELCO FOOD PRODUCTS, INC. (Continued) **1011838991**

Process Toxic Alt. Releases:
- Percent weight of chemical: Not reported
- Physical state: c
- Analytical basic: EPA's RMP Guidance for Ammonia Refrigeration Reference Tables or Equations
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: 3
- Stability class: D
- Topography: a
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Emergency Procedures

Process Toxics Worst Case:
- Percent weight of chemical: Not reported
- Physical state: c
- Analytical basic: EPA's RMP Guidance for Ammonia Refrigeration Reference Tables or Equations
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: 10
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: 1.5
- Stability class: F
- Topography: a
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Enclosures

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported
- Most recent PHA date: Not reported

TELCO FOOD PRODUCTS, INC. (Continued) **1011838991**

Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported

Emergency Response Details:

ER plan:	Not reported
ER plan most recent review date:	Not reported
ER plan most recent employee training date:	Not reported
Local agency coordinating ER plan:	San Bernardino County Fire Dept.
Telephone of the coordinating local agency:	9093874631
Federal regulation:	True
OSHA 1910 120:	False

TELCO FOOD PRODUCTS, INC. (Continued) **1011838991**

SPCC:	False
RCRA:	False
OPA 90:	False
EPCRA:	True
Other Regulations:	Not reported

Risk Management Plan (RMP) Facility Details:

Facility ID:	20355
LEPC city:	Region VI LEPC
Facility decimal latitude:	34.071944
Facility decimal longitude:	-117.364722
Is facility in county box:	T
LatLong method:	I4
LatLong description:	CE
Home page web address:	Not reported
Facility telephone:	Not reported
Facility email:	Not reported
Facility DUNS #:	9648304
Parent's name:	Not reported
Partner's name:	Not reported
Parent's DUNS #:	0
Partner's DUNS #:	0
Operator's name:	Tim Telliard
Operator's telephone:	9098257343
Operator's address:	2111 West Valley Blvd.
Operators City,St,Zip:	Colton, CA 92324
RMP implementation contact:	Tim Telliard
RMP contact title:	President
Emergency contact:	Tim Telliard
Emergency contact title:	President
Emergency contact telephone:	9098257343
24 hour emergency telephone:	9092046659
Emergency contact ext/pin #:	Not reported
Number of full time employees:	100
EPA ID:	Not reported
Facility ID provided by CEPPO:	100000164412
Is facility covered by OSHA PSM:	T
Is facility covered by EPCRA 302:	T
Is fac. covered by CAA Title V 112(2):	F
Clean air op. permit/State ID:	Not reported
Last safety insp. dat:	Not reported
Inspected by:	Fire Department
Is it OSHA approved with star/merit ranking:	False
Will RMP involve predictive filing:	False
Submission type:	Resubmission
RMP description:	Not reported
Facility has no accident hist. recs:	True
Foreign owner's address:	Not reported
Foreign owner's zip:	Not reported
Foreign owner's country:	Not reported
Claim # of employees as CBI:	False
Date RMP accepted by EPA:	10/18/2000
Date of error Report:	Not reported
Date RMP received:	10/16/2000
Does RMP contain graphics files:	False
Does RMP contain attachments:	False
Was certification letter received:	True

TELCO FOOD PRODUCTS, INC. (Continued) **1011838991**

RMP submission method: Commercial Software Vendor
Does RMP contain CBI substantiation: False
Does RMP contain electronic waiver: False
Date RMP postmarked: 10/15/2000
Is RMP complete: True
Date of de-registration: Not reported
Date de-registration is effective: Not reported
Aniversary date: 10/15/2005
Does RMP contain CBI data: False
Does RMP contain unsanitized CBI version: False
RMP version #: 1.2.5
FRS latitude: 34.07051
FRS longitude: -117.36537
FRS Description: PLANT ENTRANCE (GENERAL)
FRS Method: ADDRESS MATCHING-HOUSE NUMBER

Process Details:
Process ID: 28485
NA & Industry Classification Sys.code(s): 31181
NAICS code description: Bread and Bakery Product Manufacturing
Optional facility description: Bakery Manufacturer
Program level: 3
Record contains CBI data: False

Process chemical(s):
Chemical name: Ammonia (anhydrous)
Process chemical qty in 100s lbs: 19100
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported

TELCO FOOD PRODUCTS, INC. (Continued) **1011838991**

Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported

TELCO FOOD PRODUCTS, INC. (Continued) **1011838991**

Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	c
Analytical basic:	EPA’s RMP Guidance for Ammonia Refrigeration Reference Tables or Equations
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	3
Stability class:	D
Topography:	a
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Emergency Procedures

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	c
Analytical basic:	EPA’s RMP Guidance for Ammonia Refrigeration Reference Tables or Equations
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	10
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	1.5
Stability class:	F
Topography:	a
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Enclosures

TELCO FOOD PRODUCTS, INC. (Continued) **1011838991**

Process Flammables Alt. Releases:

Endpoint used:	Not reported
LFL value:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Flammables Worst Case:

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported

TELCO FOOD PRODUCTS, INC. (Continued) **1011838991**

Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported

Emergency Response Details:

ER plan:	Not reported
ER plan most recent review date:	Not reported
ER plan most recent employee training date:	Not reported
Local agency coordinating ER plan:	San Bernardino County Fire Dept.
Telephone of the coordinating local agency:	9093874631
Federal regulation:	True
OSHA 1910 120:	False
SPCC:	False
RCRA:	False
OPA 90:	False
EPCRA:	True
Other Regulations:	Not reported

Risk Management Plan (RMP) Facility Details:

Facility ID:	24214
LEPC city:	Region VI LEPC
Facility decimal latitude:	34.071944
Facility decimal longitude:	-117.364722
Is facility in county box:	T
LatLong method:	I4
LatLong description:	CE
Home page web address:	Not reported
Facility telephone:	Not reported
Facility email:	Not reported
Facility DUNS #:	9648304
Parent's name:	Not reported
Partner's name:	Not reported
Parent's DUNS #:	0
Partner's DUNS #:	0
Operator's name:	Tim Telliard
Operator's telephone:	9098257343
Operator's address:	2111 West Valley Blvd.
Operators City,St,Zip:	Colton, CA 92324
RMP implementation contact:	Tim Telliard
RMP contact title:	President
Emergency contact:	Tim Telliard
Emergency contact title:	President
Emergency contact telephone:	9098257343
24 hour emergency telephone:	9092046659
Emergency contact ext/pin #:	Not reported

TELCO FOOD PRODUCTS, INC. (Continued) **1011838991**

Number of full time employees:	100
EPA ID:	Not reported
Facility ID provided by CEPPO:	100000164412
Is facility covered by OSHA PSM:	T
Is facility covered by EPCRA 302:	T
Is fac. covered by CAA Title V 112(2):	F
Clean air op. permit/State ID:	Not reported
Last safety insp. dat:	Not reported
Inspected by:	Fire Department
Is it OSHA approved with star/merit ranking:	False
Will RMP involve predictive filing:	False
Submission type:	Resubmission
RMP description:	Not reported
Facility has no accident hist. recs:	True
Foreign owner's address:	Not reported
Foreign owner's zip:	Not reported
Foreign owner's country:	Not reported
Claim # of employees as CBI:	False
Date RMP accepted by EPA:	9/27/2001
Date of error Report:	Not reported
Date RMP received:	9/26/2001
Does RMP contain graphics files:	False
Does RMP contain attachments:	False
Was certification letter received:	True
RMP submission method:	Commercial Software Vendor
Does RMP contain CBI substantiation:	False
Does RMP contain electronic waiver:	False
Date RMP postmarked:	8/1/2001
Is RMP complete:	True
Date of de-registration:	Not reported
Date de-registration is effective:	Not reported
Aniversary date:	8/1/2006
Does RMP contain CBI data:	False
Does RMP contain unsanitized CBI version:	False
RMP version #:	1.2.5
FRS latitude:	34.07051
FRS longitude:	-117.36537
FRS Description:	PLANT ENTRANCE (GENERAL)
FRS Method:	ADDRESS MATCHING-HOUSE NUMBER

Process Details:

Process ID:	34595
NA & Industry Classification Sys.code(s):	31181
NAICS code description:	Bread and Bakery Product Manufacturing
Optional facility description:	Bakery Manufacturer
Program level:	3
Record contains CBI data:	False

Process chemical(s):

Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	c
Analytical basic:	EPA's RMP Guidance for Ammonia Refrigeration Reference Tables or Equations
Scenario:	Not reported

TELCO FOOD PRODUCTS, INC. (Continued) **1011838991**

Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	3
Stability class:	D
Topography:	a
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Emergency Procedures
Percent weight of chemical:	Not reported
Physical state:	c
Analytical basic:	EPA's RMP Guidance for Ammonia Refrigeration Reference Tables or Equations
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	3
Stability class:	D
Topography:	a
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported

Process Flammables Alt. Releases:

Endpoint used:	Not reported
LFL value:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

TELCO FOOD PRODUCTS, INC. (Continued) **1011838991**

Process Flammables Worst Case:

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported

TELCO FOOD PRODUCTS, INC. (Continued) **1011838991**

Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Ammonia (anhydrous)
Process chemical qty in 100s lbs: 19000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported

TELCO FOOD PRODUCTS, INC. (Continued) **1011838991**

Public receptors:	Not reported	
Environmental receptors:	Not reported	
Passive mitigation:	Not reported	
Safety review date:		Not reported
Most recent PHA date:		Not reported
Process Hazard Analysis:		Not reported
Expected PHA changes completion date:		Not reported
Major Hazard:		Not reported
Process Control:		Not reported
Mitigation Systems:		Not reported
Monitoring/Detection:		Not reported
Changes since the last process hazard analysis:		Not reported
Most recent review of op. procedures:		Not reported
Most recent training progs review/update:		Not reported
Training:		Not reported
Competency testing:		Not reported
Most recent maintenance review date:		Not reported
Most recent equipment inspection date:		Not reported
Equipment tested:		Not reported
Most recent changes by mgmt:		Not reported
Date of most recent review/update:		Not reported
Date of pre-start review:		Not reported
Most recent compliance audit date:		Not reported
Expected date of audit completion:		Not reported
Most recent incident investigation:		Not reported
Expected date of investigation changes:		Not reported
Date of participation plan review:		Not reported
Date of hot work permit review:		Not reported
Date of contractor safety review:		Not reported
Date of contractor safety eval. review:		Not reported
Record has CBI data:		Not reported
Safety review date:		Not reported
Federal Regulation:		Not reported
Federal regulation comment:		Not reported
Major Hazard:		Not reported
Process Control:		Not reported
Mitigation Systems:		Not reported
Monitoring/Detection:		Not reported
Changes since the last process hazard analysis:		Not reported
Most recent hazard review/update:		Not reported
Most recent review of op. procedures:		Not reported
Most recent training progs review/update:		Not reported
Expected completion of review changes:		Not reported
Training:		Not reported
Competency testing:		Not reported
Most recent maintenance review date:		Not reported
Most recent equipment inspection date:		Not reported
Equipment tested:		Not reported
Most recent compliance audit date:		Not reported
Expected date of audit completion:		Not reported
Most recent incident investigation:		Not reported
Expected date of investigation changes:		Not reported
Record has CBI data:		Not reported
Date of most recent changes:		Not reported
Process ID:	34596	
NA & Industry Classification Sys.code(s):	31181	
NAICS code description:	Bread and Bakery Product Manufacturing	

TELCO FOOD PRODUCTS, INC. (Continued) **1011838991**

Optional facility description: Bakery Manufacturer
Program level: 3
Record contains CBI data: False

Process chemical(s):
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: c
Analytical basic: EPA’s RMP Guidance for Ammonia Refrigeration Reference Tables or Equations
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: 10
Release rate in pounds per second: Not reported
Wind speed in meters/second: 1.5
Stability class: F
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Enclosures

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported

TELCO FOOD PRODUCTS, INC. (Continued) **1011838991**

Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Ammonia (anhydrous)

TELCO FOOD PRODUCTS, INC. (Continued) **1011838991**

Process chemical qty in 100s lbs: 21000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

TELCO FOOD PRODUCTS, INC. (Continued) **1011838991**

Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported

Emergency Response Details:

ER plan:	Not reported
ER plan most recent review date:	Not reported
ER plan most recent employee training date:	Not reported
Local agency coordinating ER plan:	San Bernardino County Fire Dept.
Telephone of the coordinating local agency:	9093874631

TELCO FOOD PRODUCTS, INC. (Continued) **1011838991**

Federal regulation:	True
OSHA 1910 120:	False
SPCC:	False
RCRA:	False
OPA 90:	False
EPCRA:	True
Other Regulations:	Not reported

Risk Management Plan (RMP) Facility Details:

Facility ID:	42194
LEPC city:	Region VI LEPC
Facility decimal latitude:	34.071944
Facility decimal longitude:	-117.364722
Is facility in county box:	T
LatLong method:	I4
LatLong description:	CE
Home page web address:	Not reported
Facility telephone:	Not reported
Facility email:	Not reported
Facility DUNS #:	9648304
Parent's name:	Not reported
Partner's name:	Not reported
Parent's DUNS #:	0
Partner's DUNS #:	0
Operator's name:	Tim Telliard
Operator's telephone:	9098257343
Operator's address:	2111 West Valley Blvd.
Operators City,St,Zip:	Colton, CA 92324
RMP implementation contact:	Tim Telliard
RMP contact title:	President
Emergency contact:	Tim Telliard
Emergency contact title:	President
Emergency contact telephone:	9098257343
24 hour emergency telephone:	8005057010
Emergency contact ext/pin #:	Not reported
Number of full time employees:	100
EPA ID:	Not reported
Facility ID provided by CEPPO:	100000164412
Is facility covered by OSHA PSM:	T
Is facility covered by EPCRA 302:	T
Is fac. covered by CAA Title V 112(2):	F
Clean air op. permit/State ID:	Not reported
Last safety insp. dat:	Not reported
Inspected by:	Fire Department
Is it OSHA approved with star/merit ranking:	False
Will RMP involve predictive filing:	False
Submission type:	Correction
RMP description:	Not reported
Facility has no accident hist. recs:	True
Foreign owner's address:	Not reported
Foreign owner's zip:	Not reported
Foreign owner's country:	Not reported
Claim # of employees as CBI:	False
Date RMP accepted by EPA:	3/4/2005
Date of error Report:	Not reported
Date RMP received:	2/24/2005
Does RMP contain graphics files:	False

TELCO FOOD PRODUCTS, INC. (Continued) **1011838991**

Does RMP contain attachments: False
Was certification letter received: True
RMP submission method: RMP*Submit
Does RMP contain CBI substantiation: False
Does RMP contain electronic waiver: False
Date RMP postmarked: 2/22/2005
Is RMP complete: True
Date of de-registration: Not reported
Date de-registration is effective: Not reported
Aniversary date: 8/1/2006
Does RMP contain CBI data: False
Does RMP contain unsanitized CBI version: False
RMP version #: 3.5
FRS latitude: 34.07051
FRS longitude: -117.36537
FRS Description: PLANT ENTRANCE (GENERAL)
FRS Method: ADDRESS MATCHING-HOUSE NUMBER

Process Details:
Process ID: 60584
NA & Industry Classification Sys.code(s): 31181
NAICS code description: Bread and Bakery Product Manufacturing
Optional facility description: Bakery Manufacturer
Program level: 3
Record contains CBI data: False

Process chemical(s):
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: c
Analytical basic: EPA’s RMP Guidance for Ammonia Refrigeration Reference Tables or Equations
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Emergency Procedures
Percent weight of chemical: Not reported
Physical state: c
Analytical basic: EPA’s RMP Guidance for Ammonia Refrigeration Reference Tables or Equations
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a

TELCO FOOD PRODUCTS, INC. (Continued) **1011838991**

Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported

TELCO FOOD PRODUCTS, INC. (Continued) **1011838991**

Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Ammonia (anhydrous)
Process chemical qty in 100s lbs:	19000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

TELCO FOOD PRODUCTS, INC. (Continued) **1011838991**

Process Toxics Worst Case:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported
- Most recent PHA date: Not reported
- Process Hazard Analysis: Not reported
- Expected PHA changes completion date: Not reported
- Major Hazard: Not reported
- Process Control: Not reported
- Mitigation Systems: Not reported
- Monitoring/Detection: Not reported
- Changes since the last process hazard analysis: Not reported
- Most recent review of op. procedures: Not reported
- Most recent training progs review/update: Not reported
- Training: Not reported
- Competency testing: Not reported
- Most recent maintenance review date: Not reported
- Most recent equipment inspection date: Not reported
- Equipment tested: Not reported
- Most recent changes by mgmt: Not reported
- Date of most recent review/update: Not reported
- Date of pre-start review: Not reported
- Most recent compliance audit date: Not reported

TELCO FOOD PRODUCTS, INC. (Continued) **1011838991**

Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Process ID: 60585	
NA & Industry Classification Sys.code(s):	31181
NAICS code description:	Bread and Bakery Product Manufacturing
Optional facility description:	Bakery Manufacturer
Program level:	3
Record contains CBI data:	False

Process chemical(s):

Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported

TELCO FOOD PRODUCTS, INC. (Continued) **1011838991**

Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: c
Analytical basic: EPA's RMP Guidance for Ammonia Refrigeration Reference Tables or Equations
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: 10
Release rate in pounds per second: Not reported
Wind speed in meters/second: 1.5
Stability class: F
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Enclosures

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported

TELCO FOOD PRODUCTS, INC. (Continued) **1011838991**

Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Ammonia (anhydrous)
Process chemical qty in 100s lbs: 21000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported

TELCO FOOD PRODUCTS, INC. (Continued) **1011838991**

Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported

TELCO FOOD PRODUCTS, INC. (Continued) **1011838991**

Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported

Emergency Response Details:

ER plan:	Not reported
ER plan most recent review date:	Not reported
ER plan most recent employee training date:	Not reported
Local agency coordinating ER plan:	San Bernardino County Fire Dept.
Telephone of the coordinating local agency:	9093874631
Federal regulation:	True
OSHA 1910 120:	False
SPCC:	False
RCRA:	False
OPA 90:	False
EPCRA:	True
Other Regulations:	Not reported

Risk Management Plan (RMP) Facility Details:

Facility ID:	48744
LEPC city:	Region VI LEPC
Facility decimal latitude:	34.071944
Facility decimal longitude:	-117.364722
Is facility in county box:	T
LatLong method:	I4
LatLong description:	CE
Home page web address:	Not reported
Facility telephone:	Not reported
Facility email:	Not reported
Facility DUNS #:	9648304
Parent’s name:	Best Brands, Inc.
Partner’s name:	Not reported

TELCO FOOD PRODUCTS, INC. (Continued) **1011838991**

Parent's DUNS #:	0
Partner's DUNS #:	0
Operator's name:	Tim Telliard
Operator's telephone:	9098257343
Operator's address:	2111 West Valley Blvd.
Operators City,St,Zip:	Colton, CA 92324
RMP implementation contact:	Tim Telliard
RMP contact title:	President
Emergency contact:	Tim Telliard
Emergency contact title:	President
Emergency contact telephone:	9098257343
24 hour emergency telephone:	9092046659
Emergency contact ext/pin #:	Not reported
Number of full time employees:	550
EPA ID:	Not reported
Facility ID provided by CEPPO:	100000164412
Is facility covered by OSHA PSM:	T
Is facility covered by EPCRA 302:	T
Is fac. covered by CAA Title V 112(2):	F
Clean air op. permit/State ID:	Not reported
Last safety insp. dat:	5/6/2007
Inspected by:	City Fire Department
Is it OSHA approved with star/merit ranking:	False
Will RMP involve predictive filing:	False
Submission type:	Resubmission
RMP description:	2006 Update 12/06
Facility has no accident hist. recs:	False
Foreign owner's address:	Not reported
Foreign owner's zip:	Not reported
Foreign owner's country:	Not reported
Claim # of employees as CBI:	False
Date RMP accepted by EPA:	6/22/2007
Date of error Report:	Not reported
Date RMP received:	6/21/2007
Does RMP contain graphics files:	False
Does RMP contain attachments:	False
Was certification letter received:	True
RMP submission method:	RMP*Submit
Does RMP contain CBI substantiation:	False
Does RMP contain electronic waiver:	False
Date RMP postmarked:	6/20/2007
Is RMP complete:	True
Date of de-registration:	Not reported
Date de-registration is effective:	Not reported
Aniversary date:	6/20/2012
Does RMP contain CBI data:	False
Does RMP contain unsanitized CBI version:	False
RMP version #:	3.8
FRS latitude:	34.07051
FRS longitude:	-117.36537
FRS Description:	PLANT ENTRANCE (GENERAL)
FRS Method:	ADDRESS MATCHING-HOUSE NUMBER

Accident History Details:

Accident History ID:	7806
X:	48744
Accident Date:	3/17/2002

TELCO FOOD PRODUCTS, INC. (Continued) **1011838991**

Accident Time:	1817
NAICS code:	31181
Accident release duration:	00643
Chemical released:	Ammonia (anhydrous)
Flammable chemical name:	Not reported
Quantity of chemical released in pounds:	1000
Percent weight of chemical released:	Not reported
Release Event:	Gas, Spill
Release Source:	Storage Vessel, Valve
Wind speed:	Not reported
Wind speed units:	c
Wind direction:	Not reported
Temperature:	Not reported
Stability class:	Not reported
Precipitation was present:	False
Weather was unknown:	True
Num. of on-site workers killed:	0
Num. of responders killed:	0
Num. of public deaths:	0
Num. of on-site workers injured:	0
Num. of responders injured:	0
Num. of public injured:	0
Property damage in dollars:	0
Num. of on-site deaths:	0
Num. of hospitalizations:	0
Num. of other medical treatments:	0
Num. of evacuated:	0
Num. of sheltered in place:	0
Off-site property damage in dollars:	0
Environmental damage:	Not reported
Initiating event:	a
Contributing factor:	Equipment failure, Human error, Process design failure, Unsuitable equipment
Were offsite responders notified:	Notified and Responded
Changes Made:	Improved equipment, Revised maintenance
Record contains CBI data:	False

Process Details:

Process ID:	70638
NA & Industry Classification Sys.code(s):	31181
NAICS code description:	Bread and Bakery Product Manufacturing
Optional facility description:	Bakery Manufacturer
Program level:	3
Record contains CBI data:	False

Process chemical(s):

Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	c
Analytical basic:	EPA’s General Guidance on Risk Management Programs for Chemical Accident Prevention
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	3

TELCO FOOD PRODUCTS, INC. (Continued) **1011838991**

Stability class:	D
Topography:	a
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Emergency Procedures
Percent weight of chemical:	Not reported
Physical state:	c
Analytical basic:	EPA's RMP Guidance for Ammonia Refrigeration Reference Tables or Equations
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	3
Stability class:	D
Topography:	a
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported

Process Flammables Alt. Releases:

Endpoint used:	Not reported
LFL value:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Flammables Worst Case:

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported

TELCO FOOD PRODUCTS, INC. (Continued) **1011838991**

Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Ammonia (anhydrous)
Process chemical qty in 100s lbs:	19000

TELCO FOOD PRODUCTS, INC. (Continued) **1011838991**

Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Toxics Worst Case:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported

TELCO FOOD PRODUCTS, INC. (Continued) **1011838991**

Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Process ID: 70639	
NA & Industry Classification Sys.code(s): 31181	
NAICS code description: Bread and Bakery Product Manufacturing	
Optional facility description: Bakery Manufacturer	
Program level: 3	
Record contains CBI data: False	

TELCO FOOD PRODUCTS, INC. (Continued) **1011838991**

Process chemical(s):
- Chemical name: Public OCA Chemical
- Process chemical qty in 100s lbs: 0
- Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Toxics Worst Case:
- Percent weight of chemical: Not reported
- Physical state: c
- Analytical basic: EPA’s General Guidance on Risk Management Programs for Chemical Accident Prevention
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: 10
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: 1.5
- Stability class: F
- Topography: a
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Enclosures

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported

TELCO FOOD PRODUCTS, INC. (Continued) **1011838991**

Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Ammonia (anhydrous)
Process chemical qty in 100s lbs:	22000
Process flammable chemical name:	Not reported

TELCO FOOD PRODUCTS, INC. (Continued) **1011838991**

Process Toxic Alt. Releases:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Toxics Worst Case:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported
- Most recent PHA date: Not reported

TELCO FOOD PRODUCTS, INC. (Continued) **1011838991**

Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported

Emergency Response Details:

ER plan:	Not reported
ER plan most recent review date:	Not reported
ER plan most recent employee training date:	Not reported
Local agency coordinating ER plan:	San Bernardino County Fire Dept.
Telephone of the coordinating local agency:	9093874631
Federal regulation:	True
OSHA 1910 120:	False

TELCO FOOD PRODUCTS, INC. (Continued) **1011838991**

SPCC: False
RCRA: False
OPA 90: False
EPCRA: True
Other Regulations: Not reported

G58 **SLOVER MOUNTAIN HIGH (CONTINUATION)** **FINDS** **1008292459**
325 HERMOSA ST **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 2 of 7 in cluster G

Relative: Lower

Actual: 1044 ft.

FINDS:

Registry ID: 110036688457

Environmental Interest/Information System
NCES (National Center for Education Statistics) is the primary federal entity for collecting and analyzing data related to education in the United States and other nations and the institute of education sciences.

C59 **BEST BRAND CORP** **NPDES** **S100871248**
2111 W VALLEY BLVD **San Bern. Co. Permit** **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 20 of 21 in cluster C

Relative: Lower

Actual: 1073 ft.

NPDES:

Npdes Number:	CAS000001
Facility Status:	Active
Agency Id:	0
Region:	8
Regulatory Measure Id:	343026
Order No:	97-03-DWQ
Regulatory Measure Type:	Enrollee
Place Id:	Not reported
WDID:	8 36I021507
Program Type:	Industrial
Adoption Date Of Regulatory Measure:	Not reported
Effective Date Of Regulatory Measure:	03/25/2008
Expiration Date Of Regulatory Measure:	Not reported
Termination Date Of Regulatory Measure:	Not reported
Discharge Name:	Telco Best Brands Corp
Discharge Address:	2111 W Valley BLVD
Discharge City:	Colton
Discharge State:	California
Discharge Zip:	92324

San Bern. Co. Permit:

Region:	SAN BERNARDINO
Facility ID:	FA0006607
Owner:	BEST BRANDS CORP.
Permit Number:	PT0020522
Permit Category:	SPECIAL GENERATOR

BEST BRAND CORP (Continued) **S100871248**

Facility Status: INACTIVE
Expiration Date: 09/30/2011

Region: SAN BERNARDINO
Facility ID: FA0006607
Owner: BEST BRANDS CORP.
Permit Number: PT0009723
Permit Category: EPCRA FACILITY
Facility Status: INACTIVE
Expiration Date: 09/30/2011

Region: SAN BERNARDINO
Facility ID: FA0006607
Owner: BEST BRANDS CORP.
Permit Number: PT0009738
Permit Category: CALARP FACILITY PERMIT
Facility Status: INACTIVE
Expiration Date: 09/30/2011

Region: SAN BERNARDINO
Facility ID: FA0006607
Owner: BEST BRANDS CORP.
Permit Number: PT0009722
Permit Category: RISK MANAGEMENT PLAN - LEVEL III
Facility Status: INACTIVE
Expiration Date: 09/30/2011

Region: SAN BERNARDINO
Facility ID: FA0006607
Owner: BEST BRANDS CORP.
Permit Number: PT0009736
Permit Category: HAZMAT HANDLER- 100+ EMPLOYEES
Facility Status: INACTIVE
Expiration Date: 09/30/2011

Region: SAN BERNARDINO
Facility ID: FA0006607
Owner: BEST BRANDS CORP.
Permit Number: PT0020808
Permit Category: RISK MANAGEMENT PLAN - LEVEL III
Facility Status: INACTIVE
Expiration Date: 09/30/2011

Region: SAN BERNARDINO
Facility ID: FA0006607
Owner: BEST BRANDS CORP.
Permit Number: PT0020809
Permit Category: RISK MANAGEMENT PLAN - LEVEL II
Facility Status: INACTIVE
Expiration Date: 09/30/2011

Region: SAN BERNARDINO
Facility ID: FA0006607
Owner: BEST BRANDS CORP.
Permit Number: PT0020807
Permit Category: ABOVEGROUND PETROLEUM STORAGE (AST) (SPCC)
Facility Status: INACTIVE

BEST BRAND CORP (Continued) **S100871248**

Expiration Date: 09/30/2010

Region: SAN BERNARDINO
Facility ID: FA0013654
Owner: CSM BAKERY PRODUCTS
Permit Number: PT0023962
Permit Category: SPECIAL GENERATOR
Facility Status: ACTIVE
Expiration Date: 12/31/2013

Region: SAN BERNARDINO
Facility ID: FA0013654
Owner: CSM BAKERY PRODUCTS
Permit Number: PT0023961
Permit Category: EPCRA FACILITY
Facility Status: ACTIVE
Expiration Date: 12/31/2013

Region: SAN BERNARDINO
Facility ID: FA0013654
Owner: CSM BAKERY PRODUCTS
Permit Number: PT0023963
Permit Category: CALARP FACILITY PERMIT
Facility Status: ACTIVE
Expiration Date: 12/31/2013

Region: SAN BERNARDINO
Facility ID: FA0013654
Owner: CSM BAKERY PRODUCTS
Permit Number: PT0023960
Permit Category: HAZMAT HANDLER- 100+ EMPLOYEES
Facility Status: ACTIVE
Expiration Date: 12/31/2013

Region: SAN BERNARDINO
Facility ID: FA0013654
Owner: CSM BAKERY PRODUCTS
Permit Number: PT0023964
Permit Category: RISK MANAGEMENT PLAN - LEVEL III
Facility Status: ACTIVE
Expiration Date: 12/31/2013

Region: SAN BERNARDINO
Facility ID: FA0013654
Owner: CSM BAKERY PRODUCTS
Permit Number: PT0023965
Permit Category: RISK MANAGEMENT PLAN - LEVEL III
Facility Status: ACTIVE
Expiration Date: 12/31/2013

Region: SAN BERNARDINO
Facility ID: FA0013654
Owner: CSM BAKERY PRODUCTS
Permit Number: PT0024462
Permit Category: RISK MANAGEMENT PLAN - LEVEL II
Facility Status: ACTIVE
Expiration Date: 12/31/2013

C60 **ERNS** **2002597380**
2111 WEST VALLEY BLVD **N/A**
< 1/8 **COLTON, CA 0**
1 ft.

Site 21 of 21 in cluster C

Relative: **Lower**

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

Actual: **1073 ft.**

G61 **AT&T MOBILITY COLTON #13829** **San Bern. Co. Permit** **S106718013**
1205 1/2 W VALLEY BLVD **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 3 of 7 in cluster G

Relative: **Lower**

Actual: **1036 ft.**

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0009029
Owner: NEW CINGULAR WIRELESS PCS, LLC
Permit Number: PT0015897
Permit Category: HAZMAT HANDLER 0-10 EMPLOYEES
Facility Status: ACTIVE
Expiration Date: 08/31/2013

G62 **EDR US Hist Auto Stat** **1015349761**
235 HERMOSA AVE **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 4 of 7 in cluster G

Relative: **Lower**

Actual: **1042 ft.**

EDR Historical Auto Stations:
Name: QUALITY AUTO UPHOLSTERY
Year: 2010
Address: 235 HERMOSA AVE

Name: QUALITY AUTO UPHOLSTERY
Year: 2011
Address: 235 HERMOSA AVE

Name: QUALITY AUTO UPHOLSTERY
Year: 2012
Address: 235 HERMOSA AVE

G63 **EDR US Hist Auto Stat** **1015181620**
1205 W VALLEY BLVD **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 5 of 7 in cluster G

Relative: **Lower**

Actual: **1036 ft.**

EDR Historical Auto Stations:
Name: AUTO PALACE USA
Year: 2009
Address: 1205 W VALLEY BLVD

J64 **COLTON MEDICAL BUILDING** **NPDES** **S113450043**
1405 W VALLEY BLVD **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 1 of 4 in cluster J

Relative:
Lower

Actual:
1045 ft.

NPDES:

Npdes Number:	CAS000002
Facility Status:	Active
Agency Id:	0
Region:	8
Regulatory Measure Id:	435797
Order No:	2009-0009-DWQ
Regulatory Measure Type:	Enrollee
Place Id:	Not reported
WDID:	8 36W001151
Program Type:	Construction
Adoption Date Of Regulatory Measure:	Not reported
Effective Date Of Regulatory Measure:	03/19/2013
Expiration Date Of Regulatory Measure:	Not reported
Termination Date Of Regulatory Measure:	Not reported
Discharge Name:	Nephrology Associates of Upland & Pomona
Discharge Address:	536 East Foothill Bl
Discharge City:	Upland
Discharge State:	California
Discharge Zip:	91786

K65 **ORANGE SHELL - COLTON** **UST** **U003784724**
1600 W VALLEY BLVD **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 1 of 27 in cluster K

Relative:
Lower

Actual:
1065 ft.

UST:

Facility ID:	86008825
Latitude:	34.0701
Longitude:	-117.35302

K66 **ZAKARIA HAGGAG** **HIST UST** **U001574717**
1600 W VALLEY BLVD **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 2 of 27 in cluster K

Relative:
Lower

Actual:
1065 ft.

HIST UST:

Region:	STATE
Facility ID:	00000018463
Facility Type:	Gas Station
Other Type:	Not reported
Total Tanks:	0005
Contact Name:	ZAKARIA HAGGAG
Telephone:	7148246372
Owner Name:	SHELL OIL COMPANY
Owner Address:	P.O. BOX 4848
Owner City,St,Zip:	ANAHEIM, CA 92803
Tank Num:	001
Container Num:	1

ZAKARIA HAGGAG (Continued) **U001574717**

Year Installed: 1966
Tank Capacity: 00000550
Tank Used for: WASTE
Type of Fuel: WASTE OIL
Tank Construction: 12 gauge
Leak Detection: Stock Inventor, 10

Tank Num: 002
Container Num: 2
Year Installed: 1966
Tank Capacity: 00008000
Tank Used for: PRODUCT
Type of Fuel: UNLEADED
Tank Construction: 1/4 inches
Leak Detection: Stock Inventor, 10

Tank Num: 003
Container Num: 3
Year Installed: 1966
Tank Capacity: 00005000
Tank Used for: PRODUCT
Type of Fuel: PREMIUM
Tank Construction: 1/4 inches
Leak Detection: Stock Inventor, 10

Tank Num: 004
Container Num: 4
Year Installed: 1966
Tank Capacity: 00005000
Tank Used for: PRODUCT
Type of Fuel: PREMIUM
Tank Construction: 1/4 inches
Leak Detection: Stock Inventor, 10

Tank Num: 005
Container Num: 5
Year Installed: 1970
Tank Capacity: 00008000
Tank Used for: PRODUCT
Type of Fuel: REGULAR
Tank Construction: 1/4 inches
Leak Detection: Stock Inventor, 10

G67 **ACACIA RV PERFORMANCE CENTER** **San Bern. Co. Permit** **S107863299**
295 N HERMOSA **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 6 of 7 in cluster G

Relative:
Lower

Actual:
1045 ft.

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0010405
Owner: HARRINGTON, GREG
Permit Number: PT0017706
Permit Category: SPECIAL GENERATOR
Facility Status: INACTIVE
Expiration Date: 05/31/2006

ACACIA RV PERFORMANCE CENTER (Continued) **S107863299**

Region: SAN BERNARDINO
Facility ID: FA0010405
Owner: HARRINGTON, GREG
Permit Number: PT0017707
Permit Category: SPECIAL HANDLER
Facility Status: ACTIVE
Expiration Date: 05/31/2013

Region: SAN BERNARDINO
Facility ID: FA0010405
Owner: HARRINGTON, GREG
Permit Number: PT0017705
Permit Category: SPECIAL GENERATOR
Facility Status: ACTIVE
Expiration Date: 05/31/2013

F68 **UNITED RENTALS BRANCH 513** **NPDES** **S109463452**
1690 VALLEY BLVD **N/A**
< 1/8 **FONTANA, CA 92335**
1 ft.

Site 11 of 15 in cluster F

Relative: **Lower**

Actual: **1068 ft.**

NPDES:

Npdes Number:	CAS000001
Facility Status:	Active
Agency Id:	0
Region:	8
Regulatory Measure Id:	332260
Order No:	97-03-DWQ
Regulatory Measure Type:	Enrollee
Place Id:	Not reported
WDID:	8 36I021161
Program Type:	Industrial
Adoption Date Of Regulatory Measure:	Not reported
Effective Date Of Regulatory Measure:	09/24/2007
Expiration Date Of Regulatory Measure:	Not reported
Termination Date Of Regulatory Measure:	06/29/2010
Discharge Name:	United Rentals Northwest Inc
Discharge Address:	16190 Valley Blvd
Discharge City:	Fontana
Discharge State:	California
Discharge Zip:	92335

K69 **CALIFORNIA AUTO SPECIALITIES** **HAZNET** **S112891128**
1595 W VALLEY BLVD **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 3 of 27 in cluster K

Relative: **Lower**

Actual: **1066 ft.**

HAZNET:

Year:	1999
Gepaid:	CAC001432528
Contact:	ED KELLER
Telephone:	9098253911
Mailing Name:	Not reported
Mailing Address:	1595 W VALLEY BLVD

CALIFORNIA AUTO SPECIALITIES (Continued) **S112891128**

Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	Not reported
TSD EPA ID:	CAD982444481
TSD County:	Not reported
Waste Category:	Unspecified oil-containing waste
Disposal Method:	Recycler
Tons:	.8340
Facility County:	San Bernardino

Year:	1999
Gepaid:	CAC001432528
Contact:	ED KELLER
Telephone:	9098253911
Mailing Name:	Not reported
Mailing Address:	1595 W VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	Not reported
TSD EPA ID:	CAD982444481
TSD County:	Not reported
Waste Category:	Other empty containers 30 gallons or more
Disposal Method:	Recycler
Tons:	.5000
Facility County:	San Bernardino

K70 **DON MORRISON** **HAZNET** **S112857920**
1595 W. VALLEY BLVD **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 4 of 27 in cluster K

Relative: HAZNET:
Lower

Year:	1994
Gepaid:	CAC000977968
Actual: Contact:	DON MORRISON
1066 ft. Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	1090 COLOMA RD.
Mailing City,St,Zip:	PLACERVILLE, CA 956670000
Gen County:	Not reported
TSD EPA ID:	CAT080033681
TSD County:	Not reported
Waste Category:	Unspecified aqueous solution
Disposal Method:	Recycler
Tons:	1.2510
Facility County:	San Bernardino

K71 **SHELL SERVICE STATION** **LUST** **S105850485**
1600 VALLEY BOULEVARD WEST **N/A**
< 1/8 **COLTON, CA 92373**
1 ft.

Site 5 of 27 in cluster K

Relative: LUST:
Lower

Region:	STATE
Global Id:	T0607168722
Actual: Latitude:	34.069852
1065 ft.	

SHELL SERVICE STATION (Continued) **S105850485**

Longitude:	-117.353658
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	07/27/2005
Lead Agency:	SAN BERNARDINO COUNTY
Case Worker:	LH6
Local Agency:	Not reported
RB Case Number:	Not reported
LOC Case Number:	2003014
File Location:	Local Agency
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Gasoline, MTBE / TBA / Other Fuel Oxygenates, * * TERT-BUTYL ALCOHOL (TBA), * TERT-BUTYL ALCOHOL (TBA)
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607168722
Contact Type:	Regional Board Caseworker
Contact Name:	CARL BERNHARDT
Organization Name:	SANTA ANA RWQCB (REGION 8)
Address:	3737 MAIN STREET, SUITE 500
City:	RIVERSIDE
Email:	cbernhardt@waterboards.ca.gov
Phone Number:	9517824495

Regulatory Activities:

Global Id:	T0607168722
Action Type:	Other
Date:	01/01/1950
Action:	Leak Discovery
Global Id:	T0607168722
Action Type:	Other
Date:	01/01/1950
Action:	Leak Reported
Global Id:	T0607168722
Action Type:	REMEDIATION
Date:	01/01/1950
Action:	Excavation
Global Id:	T0607168722
Action Type:	REMEDIATION
Date:	01/01/1950
Action:	Soil Vapor Extraction (SVE)

LUST REG 8:

Region:	8
County:	San Bernardino
Regional Board:	Santa Ana Region
Facility Status:	Pollution Characterization
Case Number:	Not reported
Local Case Num:	2003014
Case Type:	Soil only

SHELL SERVICE STATION (Continued) **S105850485**

Substance:	8006619, MTB
Qty Leaked:	Not reported
Abate Method:	Not reported
Cross Street:	PEPPER AVENUE
Enf Type:	Not reported
Funding:	Not reported
How Discovered:	SAS
How Stopped:	Not reported
Leak Cause:	UNK
Leak Source:	UNK
Global ID:	T0607168722
How Stopped Date:	Not reported
Enter Date:	Not reported
Review Date:	Not reported
Prelim Assess:	Not reported
Discover Date:	3/20/2003
Enforcement Date:	Not reported
Close Date:	Not reported
Workplan:	Not reported
Pollution Char:	4/21/2003
Remed Plan:	Not reported
Remed Action:	Not reported
Monitoring:	Not reported
Enter Date:	Not reported
GW Qualifies:	Not reported
Soil Qualifies:	=
Operator:	Not reported
Facility Contact:	Not reported
Interim:	Not reported
Oversite Program:	LUST
Latitude:	0
Longitude:	0
MTBE Date:	Not reported
Max MTBE GW:	Not reported
MTBE Concentration:	0
Max MTBE Soil:	3900
MTBE Fuel:	0
MTBE Tested:	MTBE Detected. Site tested for MTBE & MTBE detected
MTBE Class:	*
Staff:	CAB
Staff Initials:	LH6
Lead Agency:	Local Agency
Local Agency:	36000L
Hydr Basin #:	Not reported
Beneficial:	MUN
Priority:	A2
Cleanup Fund Id:	Not reported
Work Suspended:	Not reported

Summary: Not reported

K72 **CHMIRS** **S105663913**
N/A

1599 VALLEY BLVD
< 1/8 **FONTANA, CA**
1 ft.

Site 6 of 27 in cluster K

Relative: CHMIRS:
Lower

OES Incident Number:	00-5999	
OES notification:	12/18/2000	
Actual: OES Date:	Not reported	
1065 ft. OES Time:	Not reported	
Incident Date:	Not reported	
Date Completed:	**Not reported**	
Property Use:	Not reported	
Agency Id Number:	Not reported	
Agency Incident Number:	Not reported	
Time Notified:	Not reported	
Time Completed:	Not reported	
Surrounding Area:	Not reported	
Estimated Temperature:	Not reported	
Property Management:	Not reported	
Special Studies 1:	Not reported	
Special Studies 2:	Not reported	
Special Studies 3:	Not reported	
Special Studies 4:	Not reported	
Special Studies 5:	Not reported	
Special Studies 6:	Not reported	
More Than Two Substances Involved?:		Not reported
Resp Agncy Personel # Of Decontaminated:		Not reported
Responding Agency Personel # Of Injuries:		Not reported
Responding Agency Personel # Of Fatalities:		Not reported
Others Number Of Decontaminated:		Not reported
Others Number Of Injuries:		Not reported
Others Number Of Fatalities:		Not reported
Vehicle Make/year:	Not reported	
Vehicle License Number:	Not reported	
Vehicle State:	Not reported	
Vehicle Id Number:	Not reported	
CA/DOT/PUC/ICC Number:	Not reported	
Company Name:	Not reported	
Reporting Officer Name/ID:	Not reported	
Report Date:	Not reported	
Comments:	Not reported	
Facility Telephone:	Not reported	
Waterway Involved:	No	
Waterway:	Not reported	
Spill Site:	Not reported	
Cleanup By:	County Roads	
Containment:	Not reported	
What Happened:	Not reported	
Type:	Not reported	
Measure:	Not reported	
Other:	Not reported	
Date/Time:	Not reported	
Year:	2000	
Agency:	CHP Inland	
Incident Date:	12/18/200012:00:00 AM	
Admin Agency:	San Bernardino County Health Department	
Amount:	Not reported	

(Continued) **S105663913**

Contained:	Yes
Site Type:	Road
E Date:	Not reported
Substance:	Diesel fuel
Quantity Released:	Not reported
BBLS:	0
Cups:	0
CUFT:	0
Gallons:	68
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	Big rig punctured saddle tank.

J73 **COLTON JOINT USD/WAREHOUSE** **HAZNET** **S113014645**
1313 W VALLEY BLVD **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 2 of 4 in cluster J

Relative:
Lower

Actual:
1031 ft.

HAZNET:

Year:	2011
Gepaid:	CAD982331746
Contact:	E LERMA DIR OF MAINT & OPS
Telephone:	9095805000
Mailing Name:	Not reported
Mailing Address:	1313 W VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	Not reported
TSD EPA ID:	TXD055135388
TSD County:	Not reported
Waste Category:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.0155
Facility County:	San Bernardino

Year:	2011
Gepaid:	CAD982331746
Contact:	E LERMA DIR OF MAINT & OPS
Telephone:	9095805000
Mailing Name:	Not reported
Mailing Address:	1313 W VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	Not reported
TSD EPA ID:	CAD982444481
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery

COLTON JOINT USD/WAREHOUSE (Continued) **S113014645**

	(H010-H129) Or (H131-H135)
Tons:	0.035
Facility County:	San Bernardino
Year:	2010
Gepaid:	CAD982331746
Contact:	E LERMA DIR OF MAINT & OPS
Telephone:	9095805000
Mailing Name:	Not reported
Mailing Address:	1313 W VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	Not reported
TSD EPA ID:	CAD097030993
TSD County:	Not reported
Waste Category:	Alkaline solution without metals pH >= 12.5
Disposal Method:	Discharge To Sewer/Potw Or Npdes(With Prior Storage--With Or Without Treatment)
Tons:	0.06672
Facility County:	San Bernardino
Year:	2010
Gepaid:	CAD982331746
Contact:	E LERMA DIR OF MAINT & OPS
Telephone:	9095805000
Mailing Name:	Not reported
Mailing Address:	1313 W VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	Not reported
TSD EPA ID:	AZC950823111
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.4
Facility County:	San Bernardino
Year:	2010
Gepaid:	CAD982331746
Contact:	E LERMA DIR OF MAINT & OPS
Telephone:	9095805000
Mailing Name:	Not reported
Mailing Address:	1313 W VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	Not reported
TSD EPA ID:	CAD008252405
TSD County:	Not reported
Waste Category:	Off-specification, aged or surplus organics
Disposal Method:	Fuel Blending Prior To Energy Recovery At Another Site
Tons:	0.4825
Facility County:	San Bernardino

Click this hyperlink while viewing on your computer to access
21 additional CA_HAZNET: record(s) in the EDR Site Report.

K74 **SHELL SERVICE STATION** **RCRA-SQG** **1006805337**
1600 W VALLEY **FINDS** **CAR000125997**
< 1/8 **COLTON, CA 92324** **SWEEPS UST**
1 ft. **San Bern. Co. Permit**
Site 7 of 27 in cluster K **HAZNET**

Relative:
Lower

Actual:
1065 ft.

RCRA-SQG:

Date form received by agency:	08/16/2002
Facility name:	SHELL SERVICE STATION
Facility address:	1600 W VALLEY S A P 135180 COLTON, CA 92324
EPA ID:	CAR000125997
Mailing address:	P O BOX 2648 HOUSTON, TX 772522648
Contact:	SONDRA BIENVENU
Contact address:	P O BOX 2648 HOUSTON, TX 772522648
Contact country:	US
Contact telephone:	(713) 241-5036
Contact email:	Not reported
EPA Region:	09
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	EQUILON ENTERPRISES L L C
Owner/operator address:	P O BOX 2648 HOUSTON, TX 77252
Owner/operator country:	Not reported
Owner/operator telephone:	(713) 241-5036
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

SHELL SERVICE STATION (Continued) **1006805337**

Hazardous Waste Summary:
Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D018
Waste name: BENZENE

Violation Status: No violations found

FINDS:

Registry ID: 110013308296

Environmental Interest/Information System
California Hazardous Waste Tracking System - Datamart (HWTS-DATAMART) provides California with information on hazardous waste shipments for generators, transporters, and treatment, storage, and disposal facilities.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

SWEEPS UST:
Status: Active
Comp Number: 18463
Number: 9
Board Of Equalization: 44-020681
Referral Date: 07-28-92
Action Date: 07-28-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 1
Swrcb Tank Id: 36-000-018463-000001
Actv Date: 07-07-88
Capacity: 550
Tank Use: OIL
Stg: W
Content: WASTE OIL
Number Of Tanks: 5

Status: Active
Comp Number: 18463
Number: 9
Board Of Equalization: 44-020681
Referral Date: 07-28-92
Action Date: 07-28-92

SHELL SERVICE STATION (Continued) **1006805337**

Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 2
Swrcb Tank Id: 36-000-018463-000002
Actv Date: 07-07-88
Capacity: 8000
Tank Use: M.V. FUEL
Stg: P
Content: REG UNLEADED
Number Of Tanks: Not reported

Status: Active
Comp Number: 18463
Number: 9
Board Of Equalization: 44-020681
Referral Date: 07-28-92
Action Date: 07-28-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 3
Swrcb Tank Id: 36-000-018463-000003
Actv Date: 07-07-88
Capacity: 5000
Tank Use: M.V. FUEL
Stg: P
Content: REG UNLEADED
Number Of Tanks: Not reported

Status: Active
Comp Number: 18463
Number: 9
Board Of Equalization: 44-020681
Referral Date: 07-28-92
Action Date: 07-28-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 4
Swrcb Tank Id: 36-000-018463-000004
Actv Date: 07-07-88
Capacity: 5000
Tank Use: M.V. FUEL
Stg: P
Content: REG UNLEADED
Number Of Tanks: Not reported

Status: Active
Comp Number: 18463
Number: 9
Board Of Equalization: 44-020681
Referral Date: 07-28-92
Action Date: 07-28-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 5
Swrcb Tank Id: 36-000-018463-000005
Actv Date: 07-07-88
Capacity: 8000

SHELL SERVICE STATION (Continued) **1006805337**

Tank Use: M.V. FUEL
Stg: P
Content: LEADED
Number Of Tanks: Not reported

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0005114
Owner: ORANGE OIL CO. COLTON
Permit Number: PT0002229
Permit Category: HAZMAT HANDLER 0-10 EMPLOYEES
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0005114
Owner: ORANGE OIL CO. COLTON
Permit Number: PT0025146
Permit Category: WASTE INCIDENTAL UST OPERATION ONLY
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0005114
Owner: ORANGE OIL CO. COLTON
Permit Number: PT0012134
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0005114
Owner: ORANGE OIL CO. COLTON
Permit Number: PT0012135
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0005114
Owner: ORANGE OIL CO. COLTON
Permit Number: PT0012136
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 10/31/2013

HAZNET:
Year: 2003
Gepaid: CAR000125997
Contact: N CORTEZ/ENVT'L DATA ANALYST
Telephone: 2818742224
Mailing Name: Not reported
Mailing Address: 12700 NORTHBOROUGH DRIVE MFT240-G
Mailing City,St,Zip: Houston, TX 770672508
Gen County: Not reported
TSD EPA ID: CAD028409019

SHELL SERVICE STATION (Continued) **1006805337**

TSD County: Not reported
Waste Category: Aqueous solution with total organic residues less than 10 percent
Disposal Method: Treatment, Tank
Tons: 0.91
Facility County: San Bernardino

Year: 2003
Gepaid: CAR000125997
Contact: N CORTEZ/ENVT'L DATA ANALYST
Telephone: 2818742224
Mailing Name: Not reported
Mailing Address: 12700 NORTHBOROUGH DRIVE MFT240-G
Mailing City,St,Zip: Houston, TX 770672508
Gen County: Not reported
TSD EPA ID: CAD982484933
TSD County: Not reported
Waste Category: Other empty containers 30 gallons or more
Disposal Method: Disposal, Other
Tons: 2
Facility County: San Bernardino

Year: 2002
Gepaid: CAR000125997
Contact: N CORTEZ/ENVT'L DATA ANALYST
Telephone: 2818742224
Mailing Name: Not reported
Mailing Address: 12700 NORTHBOROUGH DRIVE MFT240-G
Mailing City,St,Zip: Houston, TX 770672508
Gen County: Not reported
TSD EPA ID: CAD028409019
TSD County: Not reported
Waste Category: Tank bottom waste
Disposal Method: Treatment, Tank
Tons: 0.68
Facility County: San Bernardino

J75 **COLTON JOINT USD WAREHOUSE** **San Bern. Co. Permit** **S108202874**
1313 W VALLEY BLVD **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 3 of 4 in cluster J

Relative: Lower

Actual: 1031 ft.

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0005966
Owner: COLTON JOINT USD
Permit Number: PT0004263
Permit Category: HAZMAT HANDLER 51-100 EMPLOYEES (W/GEN PRMT)
Facility Status: ACTIVE
Expiration Date: 05/31/2013

Region: SAN BERNARDINO
Facility ID: FA0005966
Owner: COLTON JOINT USD
Permit Number: PT0023560
Permit Category: UW HANDLER W/ ANOTHER HAZ WASTE GENERATOR FEE
Facility Status: ACTIVE
Expiration Date: 05/31/2013

COLTON JOINT USD WAREHOUSE (Continued) **S108202874**

Region: SAN BERNARDINO
Facility ID: FA0005966
Owner: COLTON JOINT USD
Permit Number: PT0004262
Permit Category: HAZARDOUS WASTE GENERATOR - 51-100 EMPLOYEES
Facility Status: ACTIVE
Expiration Date: 05/31/2013

K76 **B AND G AUTO SALES** **RCRA-SQG 1004677065**
1630 W VALLEY BLVD **FINDS CAR000092825**
< 1/8 **COLTON, CA 92324** **San Bern. Co. Permit**
1 ft. **HAZNET**

Site 8 of 27 in cluster K

Relative: Lower

Actual: 1068 ft.

RCRA-SQG:
Date form received by agency: 05/21/2001
Facility name: B AND G AUTO SALES
Facility address: 1630 W VALLEY BLVD
COLTON, CA 92324
EPA ID: CAR000092825
Mailing address: P O BOX 590
COLTON, CA 92324
Contact: SHIRLEY CHADWICK
Contact address: P O BOX 590
COLTON, CA 92324
Contact country: US
Contact telephone: (909) 825-1173
Contact email: Not reported
EPA Region: 09
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: SHIRLEY CHADWICK
Owner/operator address: 1630 W VALLEY BLVD P O BOX 590
COLTON, CA 92324
Owner/operator country: Not reported
Owner/operator telephone: (909) 825-1173
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No

B AND G AUTO SALES (Continued) **1004677065**

Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Hazardous Waste Summary:
Waste code: D039
Waste name: TETRACHLOROETHYLENE

Violation Status: No violations found

FINDS:

Registry ID: 110012195999

Environmental Interest/Information System
California Hazardous Waste Tracking System - Datamart (HWTS-DATAMART) provides California with information on hazardous waste shipments for generators, transporters, and treatment, storage, and disposal facilities.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0010926
Owner: JEFF SCHWARTZ
Permit Number: PT0018841
Permit Category: SPECIAL GENERATOR
Facility Status: INACTIVE
Expiration Date: 05/31/2008

Region: SAN BERNARDINO
Facility ID: FA0010926
Owner: JEFF SCHWARTZ
Permit Number: PT0018842
Permit Category: SPECIAL HANDLER
Facility Status: INACTIVE
Expiration Date: 05/31/2008

Region: SAN BERNARDINO
Facility ID: FA0001283
Owner: CHADWICK, SHIRLEY & SCOTT
Permit Number: PT0005412
Permit Category: SPECIAL HANDLER
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO

B AND G AUTO SALES (Continued) **1004677065**

Facility ID: FA0001283
Owner: CHADWICK, SHIRLEY & SCOTT
Permit Number: PT0005413
Permit Category: CONDITIONALLY EXEMPT SMALL QUANTITY GENERATOR
Facility Status: ACTIVE
Expiration Date: 10/31/2013

HAZNET:
Year: 2003
Gepaid: CAR000092825
Contact: SHIRLEY CHADWICK
Telephone: 9098251173
Mailing Name: Not reported
Mailing Address: PO BOX 590
Mailing City,St,Zip: COLTON, CA 923240000
Gen County: Not reported
TSD EPA ID: CAT000613927
TSD County: Not reported
Waste Category: Aqueous solution with total organic residues less than 10 percent
Disposal Method: Transfer Station
Tons: 0.03
Facility County: San Bernardino

Year: 2002
Gepaid: CAR000092825
Contact: SHIRLEY CHADWICK
Telephone: 9098251173
Mailing Name: Not reported
Mailing Address: PO BOX 590
Mailing City,St,Zip: COLTON, CA 923240000
Gen County: Not reported
TSD EPA ID: CAT000613927
TSD County: Not reported
Waste Category: Aqueous solution with total organic residues less than 10 percent
Disposal Method: Transfer Station
Tons: 0.08
Facility County: San Bernardino

Year: 2001
Gepaid: CAR000092825
Contact: SHIRLEY CHADWICK
Telephone: 9098251173
Mailing Name: Not reported
Mailing Address: PO BOX 590
Mailing City,St,Zip: COLTON, CA 923240000
Gen County: Not reported
TSD EPA ID: CAT000613927
TSD County: Not reported
Waste Category: Aqueous solution with total organic residues less than 10 percent
Disposal Method: Transfer Station
Tons: 0.18
Facility County: San Bernardino

K77 **BAKER'S DRIVE THRU #117** **San Bern. Co. Permit** **S109598414**
1620 W VALLEY BLVD **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 9 of 27 in cluster K

Relative:
Lower

Actual:
1068 ft.

San Bern. Co. Permit:

Region:	SAN BERNARDINO
Facility ID:	FA0012317
Owner:	BAKER'S BURGERS INC
Permit Number:	PT0021845
Permit Category:	BULK CO2 AT RETAIL FOOD FACILITIES
Facility Status:	ACTIVE
Expiration Date:	05/31/2010

F78 **BUDGET TRUCK RENTAL** **HAZNET** **S113141068**
1700 W VALLEY BLVD **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 12 of 15 in cluster F

Relative:
Lower

Actual:
1069 ft.

HAZNET:

Year:	2011
Gepaid:	CAL000303183
Contact:	JOE UNGARO
Telephone:	9098242308
Mailing Name:	Not reported
Mailing Address:	1700 W VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 923241809
Gen County:	Not reported
TSD EPA ID:	TXD077603371
TSD County:	Not reported
Waste Category:	Unspecified organic liquid mixture
Disposal Method:	Fuel Blending Prior To Energy Recovery At Another Site
Tons:	0.75
Facility County:	San Bernardino

Year:	2009
Gepaid:	CAL000303183
Contact:	JOE UNGARO
Telephone:	9098242308
Mailing Name:	Not reported
Mailing Address:	1700 W VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 923241809
Gen County:	Not reported
TSD EPA ID:	TXD077603371
TSD County:	Not reported
Waste Category:	Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method:	Fuel Blending Prior To Energy Recovery At Another Site
Tons:	0.475
Facility County:	San Bernardino

Year:	2008
Gepaid:	CAL000303183
Contact:	JOE UNGARO
Telephone:	9098242308
Mailing Name:	Not reported
Mailing Address:	1700 W VALLEY BLVD
Mailing City,St,Zip:	COLTON, CA 923241809
Gen County:	Not reported

BUDGET TRUCK RENTAL (Continued) **S113141068**

TSD EPA ID: TXD077603371
TSD County: Not reported
Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method: Fuel Blending Prior To Energy Recovery At Another Site
Tons: 0.825
Facility County: San Bernardino

Year: 2007
Gepaid: CAL000303183
Contact: JOE UNGARO
Telephone: 9098242308
Mailing Name: Not reported
Mailing Address: 1700 W VALLEY BLVD
Mailing City,St,Zip: COLTON, CA 923241809
Gen County: Not reported
TSD EPA ID: TXD077603371
TSD County: Not reported
Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method: Fuel Blending Prior To Energy Recovery At Another Site
Tons: 1.32
Facility County: San Bernardino

Year: 2007
Gepaid: CAL000303183
Contact: JOE UNGARO
Telephone: 9098242308
Mailing Name: Not reported
Mailing Address: 1700 W VALLEY BLVD
Mailing City,St,Zip: COLTON, CA 923241809
Gen County: Not reported
TSD EPA ID: TXD077603371
TSD County: Not reported
Waste Category: Organic liquids with metals (Alkaline solution (pH >= 12.5) with metals)
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.15
Facility County: San Bernardino

Click this hyperlink while viewing on your computer to access
2 additional CA_HAZNET: record(s) in the EDR Site Report.

F79 **INLAND EMPIRE TOYOTA** **RCRA-SQG** **1000151918**
1700 VALLEY RD **FINDS** **CAD982002883**
< 1/8 **COLTON, CA 92324** **HIST UST**
1 ft. **SWEEPS UST**
Site 13 of 15 in cluster F **San Bern. Co. Permit**

Relative: Lower

Actual: 1069 ft.

RCRA-SQG:
Date form received by agency: 06/01/1987
Facility name: INLAND EMPIRE TOYOTA
Facility address: 1700 VALLEY RD
COLTON, CA 92324
EPA ID: CAD982002883
Mailing address: VALLEY RD
COLTON, CA 92324
Contact: ENVIRONMENTAL MANAGER
Contact address: 1700 VALLEY RD

INLAND EMPIRE TOYOTA (Continued) **1000151918**

COLTON, CA 92324
Contact country: US
Contact telephone: (714) 825-7777
Contact email: Not reported
EPA Region: 09
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: DICK JOYCE
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110002773115

Environmental Interest/Information System

INLAND EMPIRE TOYOTA (Continued) **1000151918**

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HIST UST:

Region:	STATE
Facility ID:	00000066383
Facility Type:	Other
Other Type:	AUTO DEALER
Total Tanks:	0005
Contact Name:	THOMAS TRACY V.P.
Telephone:	7148257777
Owner Name:	BILL N. ELLIS
Owner Address:	1700 W. VALLEY
Owner City,St,Zip:	COLTON, CA 92324
Tank Num:	001
Container Num:	3
Year Installed:	Not reported
Tank Capacity:	00000500
Tank Used for:	WASTE
Type of Fuel:	5
Tank Construction:	3 centimeters
Leak Detection:	None
Tank Num:	002
Container Num:	1
Year Installed:	Not reported
Tank Capacity:	00000500
Tank Used for:	PRODUCT
Type of Fuel:	06
Tank Construction:	Not reported
Leak Detection:	None
Tank Num:	003
Container Num:	2
Year Installed:	Not reported
Tank Capacity:	00000500
Tank Used for:	PRODUCT
Type of Fuel:	06
Tank Construction:	Not reported
Leak Detection:	None
Tank Num:	004
Container Num:	4
Year Installed:	Not reported
Tank Capacity:	00003000
Tank Used for:	PRODUCT
Type of Fuel:	REGULAR
Tank Construction:	Not reported
Leak Detection:	None
Tank Num:	005

INLAND EMPIRE TOYOTA (Continued) **1000151918**

Container Num: 5
Year Installed: Not reported
Tank Capacity: 00003000
Tank Used for: PRODUCT
Type of Fuel: UNLEADED
Tank Construction: Not reported
Leak Detection: None

SWEEPS UST:
Status: Not reported
Comp Number: 8826
Number: Not reported
Board Of Equalization: 44-021441
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 36-000-008826-000001
Actv Date: Not reported
Capacity: 500
Tank Use: OIL
Stg: WASTE
Content: WASTE OIL
Number Of Tanks: 5

Status: Not reported
Comp Number: 8826
Number: Not reported
Board Of Equalization: 44-021441
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 36-000-008826-000002
Actv Date: Not reported
Capacity: 500
Tank Use: OIL
Stg: PRODUCT
Content: NEW OIL
Number Of Tanks: Not reported

Status: Not reported
Comp Number: 8826
Number: Not reported
Board Of Equalization: 44-021441
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 36-000-008826-000003
Actv Date: Not reported
Capacity: 500
Tank Use: PETROLEUM
Stg: PRODUCT

INLAND EMPIRE TOYOTA (Continued) **1000151918**

Content: TRAN. FLUID
Number Of Tanks: Not reported

Status: Not reported
Comp Number: 8826
Number: Not reported
Board Of Equalization: 44-021441
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 36-000-008826-000004
Actv Date: Not reported
Capacity: 3000
Tank Use: M.V. FUEL
Stg: PRODUCT
Content: LEADED
Number Of Tanks: Not reported

Status: Not reported
Comp Number: 8826
Number: Not reported
Board Of Equalization: 44-021441
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 36-000-008826-000005
Actv Date: Not reported
Capacity: 3000
Tank Use: M.V. FUEL
Stg: PRODUCT
Content: REG UNLEADED
Number Of Tanks: Not reported

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0008099
Owner: BERKI, EDWARD OR CONNIE L
Permit Number: PT0014210
Permit Category: SPECIAL GENERATOR
Facility Status: INACTIVE
Expiration Date: 08/31/2005

Region: SAN BERNARDINO
Facility ID: FA0008099
Owner: BERKI, EDWARD OR CONNIE L
Permit Number: PT0014211
Permit Category: SPECIAL HANDLER
Facility Status: INACTIVE
Expiration Date: 08/31/2005

Region: SAN BERNARDINO
Facility ID: FA0004328
Owner: MOSS BROS FORD INC.

INLAND EMPIRE TOYOTA (Continued) **1000151918**

Permit Number: PT0005717
Permit Category: SPECIAL GENERATOR
Facility Status: INACTIVE
Expiration Date: 05/31/2003

Region: SAN BERNARDINO
Facility ID: FA0004328
Owner: MOSS BROS FORD INC.
Permit Number: PT0005716
Permit Category: SPECIAL HANDLER
Facility Status: INACTIVE
Expiration Date: 05/31/2003

Region: SAN BERNARDINO
Facility ID: FA0010766
Owner: BUDGET RENT A CAR
Permit Number: PT0018519
Permit Category: HAZARDOUS WASTE GENERATOR - 11-25 EMPLOYEES
Facility Status: ACTIVE
Expiration Date: 01/31/2014

Region: SAN BERNARDINO
Facility ID: FA0010766
Owner: BUDGET RENT A CAR
Permit Number: PT0018520
Permit Category: HAZMAT HANDLER 11-25 EMPLOYEES (W/GEN PRMT)
Facility Status: ACTIVE
Expiration Date: 01/31/2014

G80 **PARKHOUSE TIRE** **HAZNET** **S113084915**
1205 W. VALLEY BLVD. **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 7 of 7 in cluster G

Relative: **Lower**

Actual: **1036 ft.**

HAZNET:
Year: 1999
Gepaid: CAL000159476
Contact: JIM PARKHOUSE
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: BOX 2430
Mailing City,St,Zip: BELL GARDENS, CA 902012430
Gen County: Not reported
TSD EPA ID: CAT080025711
TSD County: Not reported
Waste Category: Aqueous solution with total organic residues less than 10 percent
Disposal Method: Transfer Station
Tons: .2293
Facility County: San Bernardino

Year: 1998
Gepaid: CAL000159476
Contact: JIM PARKHOUSE
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: BOX 2430
Mailing City,St,Zip: BELL GARDENS, CA 902012430

PARKHOUSE TIRE (Continued) **S113084915**

Gen County: Not reported
TSD EPA ID: CAT080013352
TSD County: Not reported
Waste Category: Aqueous solution with total organic residues 10 percent or more
Disposal Method: Recycler
Tons: .2293
Facility County: San Bernardino

Year: 1995
Gepaid: CAL000159476
Contact: JIM PARKHOUSE
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: BOX 2430
Mailing City,St,Zip: BELL GARDENS, CA 902012430
Gen County: Not reported
TSD EPA ID: CAT080013352
TSD County: Not reported
Waste Category: Oil/water separation sludge
Disposal Method: Recycler
Tons: .4587
Facility County: San Bernardino

J81 **COLTON JOINT UNIFIED SCHOOL DISTRICT** **FTTS** **1009512654**
1313 W VALLEY BLVD **HIST FTTS** **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 4 of 4 in cluster J

Relative: Lower

Actual: 1031 ft.

FTTS INSP:
Inspection Number: 1991102301231 3
Region: 09
Inspection Date: 10/23/91
Inspector: LGARCIA
Violation occurred: Yes
Investigation Type: Section 6 PCB State Conducted
Investigation Reason: Neutral Scheme, State
Legislation Code: TSCA
Facility Function: User

HIST FTTS INSP:
Inspection Number: 1991102301231 3
Region: 09
Inspection Date: Not reported
Inspector: LGARCIA
Violation occurred: Yes
Investigation Type: Section 6 PCB State Conducted
Investigation Reason: Neutral Scheme, State
Legislation Code: TSCA
Facility Function: User

F82 **NEW WEST CONSOLIDATED, INC.** **SWEEPS UST** **S102058059**
1700 W VALLEY BLVD **LOS ANGELES CO. HMS** **N/A**
< 1/8 **ALHAMBRA, CA**
1 ft.

Site 14 of 15 in cluster F

Relative:
Lower

Actual:
1069 ft.

SWEEPS UST:

Status:	Active
Comp Number:	9542
Number:	9
Board Of Equalization:	Not reported
Referral Date:	06-30-89
Action Date:	Not reported
Created Date:	06-30-89
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	Not reported
Actv Date:	Not reported
Capacity:	Not reported
Tank Use:	Not reported
Stg:	Not reported
Content:	Not reported
Number Of Tanks:	Not reported

LOS ANGELES CO. HMS:

Region:	LA
Facility Id:	009709-009542
Facility Type:	Not reported
Facility Status:	Removed
Area:	3I
Permit Number:	Not reported
Permit Status:	Not reported

F83 **CALIFORNIA AUTO SPECIALIST** **HAZNET** **S113123620**
1700 W VALLEY RD **N/A**
< 1/8 **COLTON, CA 92324**
1 ft.

Site 15 of 15 in cluster F

Relative:
Lower

Actual:
1069 ft.

HAZNET:

Year:	2004
Gepaid:	CAL000263127
Contact:	EDWARD BERKI
Telephone:	9092540436
Mailing Name:	Not reported
Mailing Address:	1370 N LACADENA
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	Not reported
TSD EPA ID:	CAT080013352
TSD County:	Not reported
Waste Category:	Oil/water separation sludge
Disposal Method:	Recycler
Tons:	1.41
Facility County:	San Bernardino

Year:	2004
Gepaid:	CAL000263127
Contact:	EDWARD BERKI
Telephone:	9092540436

CALIFORNIA AUTO SPECIALIST (Continued) **S113123620**

Mailing Name: Not reported
Mailing Address: 1370 N LACADENA
Mailing City,St,Zip: COLTON, CA 923240000
Gen County: Not reported
TSD EPA ID: CAD982444481
TSD County: Not reported
Waste Category: Waste oil and mixed oil
Disposal Method: Recycler
Tons: 0.5
Facility County: San Bernardino

Year: 2004
Gepaid: CAL000263127
Contact: EDWARD BERKI
Telephone: 9092540436
Mailing Name: Not reported
Mailing Address: 1370 N LACADENA
Mailing City,St,Zip: COLTON, CA 923240000
Gen County: Not reported
TSD EPA ID: CAD982444481
TSD County: Not reported
Waste Category: Aqueous solution with total organic residues 10 percent or more
Disposal Method: Transfer Station
Tons: 0.45
Facility County: San Bernardino

Year: 2004
Gepaid: CAL000263127
Contact: EDWARD BERKI
Telephone: 9092540436
Mailing Name: Not reported
Mailing Address: 1370 N LACADENA
Mailing City,St,Zip: COLTON, CA 923240000
Gen County: Not reported
TSD EPA ID: CAD982444481
TSD County: Not reported
Waste Category: Waste oil and mixed oil
Disposal Method: Transfer Station
Tons: 2.07
Facility County: San Bernardino

Year: 2003
Gepaid: CAL000263127
Contact: EDWARD BERKI
Telephone: 9092540436
Mailing Name: Not reported
Mailing Address: 1370 N LACADENA
Mailing City,St,Zip: COLTON, CA 923240000
Gen County: Not reported
TSD EPA ID: CAD981696420
TSD County: Not reported
Waste Category: Waste oil and mixed oil
Disposal Method: Recycler
Tons: 0.91
Facility County: San Bernardino

CALIFORNIA AUTO SPECIALIST (Continued) **S113123620**

Click this hyperlink while viewing on your computer to access
2 additional CA_HAZNET: record(s) in the EDR Site Report.

---

84 **WEST VALLEY WATER DIST WELL #18A** **San Bern. Co. Permit** **S109349367**
1783 S SYCAMORE AVE **N/A**
< 1/8 **RIALTO, CA 92376**
0.000 mi.
2 ft.

Relative:
Lower

Actual:
1063 ft.

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0011875
Owner: WEST VALLEY WATER DISTRICT
Permit Number: PT0020901
Permit Category: HAZMAT HANDLER 0-10 EMPLOYEES
Facility Status: ACTIVE
Expiration Date: 10/31/2013

A85 **INLAND EMPIRE EQUIPT, INC** **RCRA-SQG** **1000151901**
1762 S SYCAMORE **CA FID UST** **CAD981375249**
< 1/8 **RIALTO, CA 92376** **HIST UST**
0.001 mi. **SWEEPS UST**
5 ft. **Site 2 of 18 in cluster A** **San Bern. Co. Permit**

Relative:
Lower

Actual:
1064 ft.

RCRA-SQG:
Date form received by agency: 01/29/1986
Facility name: INLAND EMPIRE EQUIPT, INC
Facility address: 1762 S SYCAMORE
RIALTO, CA 92376
EPA ID: CAD981375249
Mailing address: P O BOX 640
RIALTO, CA 92376
Contact: ENVIRONMENTAL MANAGER
Contact address: 1762 S SYCAMORE
RIALTO, CA 92376
Contact country: US
Contact telephone: (714) 877-0657
Contact email: Not reported
EPA Region: 09
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: INLAND EMPIRE EQUIPT
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

INLAND EMPIRE EQUIPT, INC (Continued) **1000151901**

Owner/operator name: NOT REQUIRED
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

CA FID UST:
Facility ID: 36002637
Regulated By: UTNKA
Regulated ID: 00039009
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: Not reported
Mail To: Not reported
Mailing Address: P O BOX
Mailing Address 2: Not reported
Mailing City,St,Zip: RIALTO 92376
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Active

HIST UST:
Region: STATE
Facility ID: 00000039009
Facility Type: Other
Other Type: SALES, SERVICE
Total Tanks: 0003
Contact Name: TROY MARSHALL
Telephone: 7148770657
Owner Name: INLAND EMPIRE EQUIPMENT, INC.

INLAND EMPIRE EQUIPT, INC (Continued) **1000151901**

Owner Address: 1762 S. SYCAMORE AVE.
Owner City,St,Zip: RIALTO, CA 92376

Tank Num: 001
Container Num: G-1
Year Installed: Not reported
Tank Capacity: 00005000
Tank Used for: PRODUCT
Type of Fuel: REGULAR
Tank Construction: Not reported
Leak Detection: Stock Inventor

Tank Num: 002
Container Num: G-2
Year Installed: Not reported
Tank Capacity: 00001000
Tank Used for: Not reported
Type of Fuel: Not reported
Tank Construction: Not reported
Leak Detection: Stock Inventor

Tank Num: 003
Container Num: S-1
Year Installed: Not reported
Tank Capacity: 00000900
Tank Used for: WASTE
Type of Fuel: Not reported
Tank Construction: 4 inches
Leak Detection: None

SWEEPS UST:
Status: Not reported
Comp Number: 39009
Number: Not reported
Board Of Equalization: 44-020962
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 36-000-039009-000001
Actv Date: Not reported
Capacity: 5000
Tank Use: M.V. FUEL
Stg: PRODUCT
Content: REG UNLEADED
Number Of Tanks: 1

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0003957
Owner: CLARKLIFT OF CALIFORNIA, INC.
Permit Number: PT0001968
Permit Category: HAZMAT HANDLER 11-25 EMPLOYEES
Facility Status: INACTIVE
Expiration Date: 05/31/2008

INLAND EMPIRE EQUIPT, INC (Continued) **1000151901**

Region: SAN BERNARDINO
Facility ID: FA0003957
Owner: CLARKLIFT OF CALIFORNIA, INC.
Permit Number: PT0001969
Permit Category: SPECIAL GENERATOR
Facility Status: INACTIVE
Expiration Date: 05/31/2008

Region: SAN BERNARDINO
Facility ID: FA0011513
Owner: SELECT EQUIPMENT SALES, INC.
Permit Number: PT0019919
Permit Category: SPECIAL GENERATOR
Facility Status: ACTIVE
Expiration Date: 04/30/2013

Region: SAN BERNARDINO
Facility ID: FA0011513
Owner: SELECT EQUIPMENT SALES, INC.
Permit Number: PT0019920
Permit Category: HAZMAT HANDLER 11-25 EMPLOYEES
Facility Status: ACTIVE
Expiration Date: 04/30/2013

A86 **CLARKLIFT OF CALIFORNIA INC** **FINDS** **1007738539**
1762 S SYCAMORE **N/A**
< 1/8 **RIALTO, CA 92376**
0.001 mi.
5 ft. **Site 3 of 18 in cluster A**

Relative:
Lower

Actual:
1064 ft.

FINDS:

Registry ID: 110018985598

Environmental Interest/Information System
California Hazardous Waste Tracking System - Datamart (HWTS-DATAMART) provides California with information on hazardous waste shipments for generators, transporters, and treatment, storage, and disposal facilities.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

A87
< 1/8
0.001 mi.
5 ft.

SELECT EQUIPMENT SALES INC DBA MYERS SELECT MATERIAL HANDLIN
1762 S SYCAMORE AVE
RIALTO, CA 92376

Site 4 of 18 in cluster A

HAZNET | **S113149700** | **N/A**

Relative:
Lower

Actual:
1064 ft.

HAZNET:

Year:	2011
Gepaid:	CAL000324485
Contact:	SAM WINKLER
Telephone:	9093573328
Mailing Name:	Not reported
Mailing Address:	6911 8TH ST
Mailing City,St,Zip:	BUENA PARK, CA 906201037
Gen County:	Not reported
TSD EPA ID:	CAD097030993
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	1.55
Facility County:	San Bernardino

Year:	2010
Gepaid:	CAL000324485
Contact:	SAM WINKLER
Telephone:	9093573328
Mailing Name:	Not reported
Mailing Address:	6911 8TH ST
Mailing City,St,Zip:	BUENA PARK, CA 906201037
Gen County:	Not reported
TSD EPA ID:	CAD097030993
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.2
Facility County:	San Bernardino

Year:	2009
Gepaid:	CAL000324485
Contact:	SAM WINKLER
Telephone:	9093573328
Mailing Name:	Not reported
Mailing Address:	3044 S KILSON DR
Mailing City,St,Zip:	SANTA ANA, CA 92707
Gen County:	Not reported
TSD EPA ID:	CAD097030993
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.85
Facility County:	San Bernardino

Year:	2008
Gepaid:	CAL000324485
Contact:	SAM WINKLER
Telephone:	9093573328

SELECT EQUIPMENT SALES INC DBA MYERS SELECT MATERIAL HANDLIN (Continued) **S113149700**

Mailing Name:	Not reported
Mailing Address:	3044 S KILSON DR
Mailing City,St,Zip:	SANTA ANA, CA 92707
Gen County:	Not reported
TSD EPA ID:	CAD097030993
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.35
Facility County:	San Bernardino

A88 **INLAND EMPIRE EQUIP INC** **EMI** **S106833040**
1762 S. SYCAMORE **N/A**
< 1/8 **RIALTO, CA 92376**
0.001 mi.
5 ft. **Site 5 of 18 in cluster A**

Relative:
Lower

Actual:
1064 ft.

EMI:

Year:	1987
County Code:	36
Air Basin:	SC
Facility ID:	20131
Air District Name:	SC
SIC Code:	5311
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2
Reactive Organic Gases Tons/Yr:	2
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1990
County Code:	36
Air Basin:	SC
Facility ID:	20131
Air District Name:	SC
SIC Code:	5084
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2
Reactive Organic Gases Tons/Yr:	2
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

A89
< 1/8
0.001 mi.
5 ft.

Relative:
Lower

Actual:
1064 ft.

CLARKLIFT OF CALIFORNIA
1762 S SYCAMORE
RIALTO, CA 92376

Site 6 of 18 in cluster A

HAZNET | **S113004000** | **N/A**

HAZNET:

Year:	2007
Gepaid:	CAD981375249
Contact:	BRANDIE LUJAN
Telephone:	5629412225
Mailing Name:	Not reported
Mailing Address:	10620 SPRINGDALE AVE
Mailing City,St,Zip:	SANTA FE SPRINGS, CA 906700000
Gen County:	Not reported
TSD EPA ID:	CAT080013352
TSD County:	Not reported
Waste Category:	Oil/water separation sludge
Disposal Method:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons:	11.67
Facility County:	San Bernardino

Year:	2000
Gepaid:	CAD981375249
Contact:	RUDY NAVARRO/GENERAL PARTS MGR
Telephone:	5629412225
Mailing Name:	Not reported
Mailing Address:	10620 SPRINGDALE AVE
Mailing City,St,Zip:	SANTA FE SPRINGS, CA 906700000
Gen County:	Not reported
TSD EPA ID:	CAT080013352
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues less than 10 percent
Disposal Method:	Transfer Station
Tons:	0.22
Facility County:	San Bernardino

Year:	1999
Gepaid:	CAD981375249
Contact:	CLARKLIFT OF CALIFORNIA INC
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	10620 SPRINGDALE AVE
Mailing City,St,Zip:	SANTA FE SPRINGS, CA 906700000
Gen County:	Not reported
TSD EPA ID:	CAT080013352
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues 10 percent or more
Disposal Method:	Transfer Station
Tons:	.2293
Facility County:	San Bernardino

Year:	1999
Gepaid:	CAD981375249
Contact:	CLARKLIFT OF CALIFORNIA INC
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	10620 SPRINGDALE AVE

CLARKLIFT OF CALIFORNIA (Continued) **S113004000**

Mailing City,St,Zip: SANTA FE SPRINGS, CA 906700000
Gen County: Not reported
TSD EPA ID: CAT080025711
TSD County: Not reported
Waste Category: Aqueous solution with total organic residues less than 10 percent
Disposal Method: Not reported
Tons: .2293
Facility County: San Bernardino

Year: 1998
Gepaid: CAD981375249
Contact: CLARKLIFT OF CALIFORNIA INC
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 10620 SPRINGDALE AVE
Mailing City,St,Zip: SANTA FE SPRINGS, CA 906700000
Gen County: Not reported
TSD EPA ID: CAT080025711
TSD County: Not reported
Waste Category: Aqueous solution with total organic residues less than 10 percent
Disposal Method: Recycler
Tons: .2293
Facility County: San Bernardino

Click this hyperlink while viewing on your computer to access
6 additional CA_HAZNET: record(s) in the EDR Site Report.

L90 **CARPENTERS JOINT APPRENT & TRNG** **San Bern. Co. Permit** **S104764690**
North **1750 SAN BERNARDINO AVE** **N/A**
< 1/8 **COLTON, CA 92324**
0.002 mi.
8 ft. **Site 1 of 3 in cluster L**

Relative:
Higher

Actual:
1103 ft.

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0001789
Owner: CARPENTERS JOINT APPRENT & TRN
Permit Number: PT0007921
Permit Category: HAZMAT HANDLER 0-10 EMPLOYEES
Facility Status: INACTIVE
Expiration Date: 05/31/2007

Region: SAN BERNARDINO
Facility ID: FA0001789
Owner: CARPENTERS JOINT APPRENT & TRN
Permit Number: PT0007920
Permit Category: SPECIAL GENERATOR
Facility Status: INACTIVE
Expiration Date: 05/31/2004

K91 **ALLIANCE COLTON, LLC** **EMI** **S106825644**
ESE **559 PEPPER AVE** **N/A**
< 1/8 **COLTON, CA 92324**
0.002 mi.
10 ft. **Site 10 of 27 in cluster K**

Relative:
Lower

Actual:
1073 ft.

EMI:

Year:	2002
County Code:	36
Air Basin:	SC
Facility ID:	127380
Air District Name:	SC
SIC Code:	4911
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	24
Reactive Organic Gases Tons/Yr:	2
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	5
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	2
Part. Matter 10 Micrometers & Smllr Tons/Yr:	2

Year:	2003
County Code:	36
Air Basin:	SC
Facility ID:	127380
Air District Name:	SC
SIC Code:	4911
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	24
Reactive Organic Gases Tons/Yr:	2
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	5
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	2
Part. Matter 10 Micrometers & Smllr Tons/Yr:	2

Year:	2004
County Code:	36
Air Basin:	SC
Facility ID:	127380
Air District Name:	SC
SIC Code:	4911
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	23.756
Reactive Organic Gases Tons/Yr:	2.16
Carbon Monoxide Emissions Tons/Yr:	0.025535
NOX - Oxides of Nitrogen Tons/Yr:	5.4872
SOX - Oxides of Sulphur Tons/Yr:	0.31573
Particulate Matter Tons/Yr:	1.9926
Part. Matter 10 Micrometers & Smllr Tons/Yr:	1.98

K92 **PUREENERGY OPERATING SERVICES LLC** **FINDS** **1010344275**
ESE **559 PEPPER AVE** **US AIRS** **N/A**
< 1/8 **COLTON, CA 92324**
0.002 mi.
10 ft. **Site 11 of 27 in cluster K**

Relative:
Lower

Actual:
1073 ft.

FINDS:

Registry ID: 110030747841

Environmental Interest/Information System
AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

AIRS (AFS):

Compliance and Violation Data Major Sources:

EPA plant ID:	110001189801
Plant name:	PUREENERGY OPERATING SERVICES LLC
Plant address:	559 PEPPER AVE COLTON, CA 92324
County:	SAN BERNARDINO
Region code:	09
Dunn & Bradst #:	Not reported
Air quality cntrl region:	024
Sic code:	4911
Sic code desc:	ELECTRIC SERVICES
North Am. industrial classf:	337215
NAIC code description:	Showcase, Partition, Shelving, and Locker Manufacturing
Default compliance status:	IN COMPLIANCE - INSPECTION
Default classification:	ACTUAL OR POTENTIAL EMISSIONS ARE ABOVE THE APPLICABLE MAJOR SOURCE THRESHOLDS
Govt facility:	ALL OTHER FACILITIES NOT OWNED OR OPERATED BY A FEDERAL, STATE, OR LOCAL GOVERNMENT
Current HPV:	Not reported

Compliance and Enforcement Major Issues:

Air program:	PSD
National action type:	OTHER ADDRESSING ACTION
Date achieved:	010427
Penalty amount:	Not reported
Air program:	PSD
National action type:	SV RESOLVED
Date achieved:	010427
Penalty amount:	Not reported
Air program:	PSD

PUREENERGY OPERATING SERVICES LLC (Continued) **1010344275**

National action type: FEDERAL DAY ZERO
Date achieved: 010427
Penalty amount: Not reported

Air program: PSD
National action type: 113A ORDER ISSUED
Date achieved: 010427
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: MULTI MEDIA INSPECTION - LEVEL 2 OR GREATER
Date achieved: 011010
Penalty amount: 000000000

Air program: TITLE V PERMITS
National action type: STATE DAY 0
Date achieved: 020911
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: NXXXXX
Date achieved: 021031
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: NXXXXX
Date achieved: 021107
Penalty amount: 000011660

Air program: TITLE V PERMITS
National action type: SV RESOLVED
Date achieved: 030211
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 080211
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 080211
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V COMPLIANCE CERT DUE/RECEIVED BY
Date achieved: 080214
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 080620
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 080620

PUREENERGY OPERATING SERVICES LLC (Continued) **1010344275**

Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 080620
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 080620
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V COMPLIANCE CERT DUE/RECEIVED BY
Date achieved: 090219
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 100223
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 100223
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V COMPLIANCE CERT DUE/RECEIVED BY
Date achieved: 100302
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 100527
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 100527
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 100527
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 100527
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 100527
Penalty amount: Not reported

PUREENERGY OPERATING SERVICES LLC (Continued) **1010344275**

Air program: TITLE V PERMITS
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 100527
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 110128
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 110128
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 110324
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 110324
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 110505
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 110505
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 110512
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 110512
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 120221
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 120221
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: COMPLIANCE CERTIFICATION STATE REVIEW

PUREENERGY OPERATING SERVICES LLC (Continued) **1010344275**

Date achieved: 120509
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 120509
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 120510
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 120510
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 120510
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 120510
Penalty amount: Not reported

Historical Compliance Minor Sources:
State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1001
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1001
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1002
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1002
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1003
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1003
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1004
Air prog code hist file: 0

PUREENERGY OPERATING SERVICES LLC (Continued) **1010344275**

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1004
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1101
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1101
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1102
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1102
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1103
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1103
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1104
Air prog code hist file: 6

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1104
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1201
Air prog code hist file: 6

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1201
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1202
Air prog code hist file: 6

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1202
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1203
Air prog code hist file: 6

State compliance status: IN COMPLIANCE - INSPECTION

PUREENERGY OPERATING SERVICES LLC (Continued) **1010344275**

Hist compliance date: 1203
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1204
Air prog code hist file: 6

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1204
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1001
Air prog code hist file: 6

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1002
Air prog code hist file: 6

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1003
Air prog code hist file: 6

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1004
Air prog code hist file: 6

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1101
Air prog code hist file: 6

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1102
Air prog code hist file: 6

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1103
Air prog code hist file: 6

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1104
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1201
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1202
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1203
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1204

PUREENERGY OPERATING SERVICES LLC (Continued) **1010344275**

Air prog code hist file: 0

Permit Information:
Compliance plant ID: CA183
Permit number: 132192
Permit category: V
Permit category desc: TITLE V PERMIT - PLANT SP

Permit Source:
Compliance plant ID: CA183
Plant name: PUREENERGY OPERATING SERVICES LLC
Plant address: 559 PEPPER AVE
COLTON, CA 92324

Event Information:
Compliance permit ID: CA183
Permit number: 132192
Event action type: IF
Event description: *PERMIT AUTHORITY ISSUES FINAL PERMIT
Event action #: 001
Event date: 20011018

K93 **DREWS ENERGY FACILITY** **NPDES** **S106800899**
ESE **559 S PEPPER AVE** **San Bern. Co. Permit** **N/A**
< 1/8 **COLTON, CA 92324** **WDS**
0.002 mi.
10 ft. **Site 12 of 27 in cluster K**

Relative:
Lower

Actual:
1073 ft.

NPDES:
Npdes Number: CAS000001
Facility Status: Active
Agency Id: 0
Region: 8
Regulatory Measure Id: 213791
Order No: 97-03-DWQ
Regulatory Measure Type: Enrollee
Place Id: Not reported
WDID: 8 36I019113
Program Type: Industrial
Adoption Date Of Regulatory Measure: Not reported
Effective Date Of Regulatory Measure: 11/05/2004
Expiration Date Of Regulatory Measure: Not reported
Termination Date Of Regulatory Measure: Not reported
Discharge Name: Colton Power LP
Discharge Address: 1732 W Genesee St
Discharge City: Syracuse
Discharge State: New York
Discharge Zip: 13204

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0002437
Owner: COLTON POWER LP
Permit Number: PT0009955
Permit Category: HAZMAT HANDLER 0-10 EMPLOYEES

DREWS ENERGY FACILITY (Continued) **S106800899**

Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0002437
Owner: COLTON POWER LP
Permit Number: PT0009956
Permit Category: SPECIAL GENERATOR
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0002437
Owner: COLTON POWER LP
Permit Number: PT0009958
Permit Category: CALARP FACILITY PERMIT
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0002437
Owner: COLTON POWER LP
Permit Number: PT0023933
Permit Category: APSA 1,320-10,000 GAL FAC CAPACITY
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0002437
Owner: COLTON POWER LP
Permit Number: PT0009954
Permit Category: RISK MANAGEMENT PLAN - LEVEL II
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0014683
Owner: CITY OF COLTON
Permit Number: PT0025618
Permit Category: HAZMAT HANDLER 0-10 EMPLOYEES
Facility Status: ACTIVE
Expiration Date: 09/30/2013

CA WDS:
Facility ID: Santa Ana River 36I019113
Facility Type: Industrial - Facility that treats and/or disposes of liquid or semisolid wastes from any servicing, producing, manufacturing or processing operation of whatever nature, including mining, gravel washing, geothermal operations, air conditioning, ship building and repairing, oil production, storage and disposal operations, water pumping.
Facility Status: Active - Any facility with a continuous or seasonal discharge that is under Waste Discharge Requirements.
NPDES Number: CAS000001 The 1st 2 characters designate the state. The remaining 7 are assigned by the Regional Board
Subregion: 8
Facility Telephone: 9518241942

DREWS ENERGY FACILITY (Continued) **S106800899**

Facility Contact:	Joel Lepoutre
Agency Name:	COLTON POWER LP
Agency Address:	1732 W Genesee St
Agency City,St,Zip:	Syracuse 13204
Agency Contact:	Tom Murphy
Agency Telephone:	3154482266
Agency Type:	Private
SIC Code:	4911
SIC Code 2:	Not reported
Primary Waste:	Not reported
Primary Waste Type:	Not reported
Secondary Waste:	Not reported
Secondary Waste Type:	Not reported
Design Flow:	0
Baseline Flow:	0
Reclamation:	Not reported
POTW:	Not reported
Treat To Water:	Minor Threat to Water Quality. A violation of a regional board order should cause a relatively minor impairment of beneficial uses compared to a major or minor threat. Not: All nurds without a TTWQ will be considered a minor threat to water quality unless coded at a higher Level. A Zero (0) may be used to code those NURDS that are found to represent no threat to water quality.
Complexity:	Category C - Facilities having no waste treatment systems, such as cooling water dischargers or thosewho must comply through best management practices, facilities with passive waste treatment and disposal systems, such as septic systems with subsurface disposal, or dischargers having waste storage systems with land disposal such as dairy waste ponds.

K94 **PURENERGY OPERATING SERVICES, LLC** **EMI** **S108432930**
ESE **559 PEPPER AVE** **N/A**
< 1/8 **COLTON, CA 92324**
0.002 mi.
10 ft. **Site 13 of 27 in cluster K**

Relative:
Lower

Actual:
1073 ft.

EMI:

Year:	2005
County Code:	36
Air Basin:	SC
Facility ID:	132192
Air District Name:	SC
SIC Code:	4911
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.02403
Reactive Organic Gases Tons/Yr:	.002196342
Carbon Monoxide Emissions Tons/Yr:	.001685
NOX - Oxides of Nitrogen Tons/Yr:	.651
SOX - Oxides of Sulphur Tons/Yr:	.1459
Particulate Matter Tons/Yr:	.1556
Part. Matter 10 Micrometers & Smllr Tons/Yr:	.1546664
Year:	2006
County Code:	36
Air Basin:	SC
Facility ID:	132192

PURENERGY OPERATING SERVICES, LLC (Continued) **S108432930**

Air District Name:	SC
SIC Code:	4911
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.0984682713347921225
Reactive Organic Gases Tons/Yr:	.009
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	.3
SOX - Oxides of Sulphur Tons/Yr:	.055
Particulate Matter Tons/Yr:	.059
Part. Matter 10 Micrometers & Smllr Tons/Yr:	.058646

Year:	2007
County Code:	36
Air Basin:	SC
Facility ID:	132192
Air District Name:	SC
SIC Code:	4911
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.0652631291028446389
Reactive Organic Gases Tons/Yr:	.00596505
Carbon Monoxide Emissions Tons/Yr:	.0004186
NOX - Oxides of Nitrogen Tons/Yr:	.16
SOX - Oxides of Sulphur Tons/Yr:	.0362089
Particulate Matter Tons/Yr:	.038413
Part. Matter 10 Micrometers & Smllr Tons/Yr:	.038182522

Year:	2007
County Code:	36
Air Basin:	SC
Facility ID:	132192
Air District Name:	SC
SIC Code:	4911
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.0984682713347921225
Reactive Organic Gases Tons/Yr:	.009
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	.3
SOX - Oxides of Sulphur Tons/Yr:	.055
Particulate Matter Tons/Yr:	.059
Part. Matter 10 Micrometers & Smllr Tons/Yr:	.058646

K95 **ALLIANCE COLTON - DREWS SUBSTATION** **ICIS 1011567459**
ESE **559 PEPPER AVE COLTON CA 92324** **N/A**
< 1/8 **COLTON, CA 92324**
0.002 mi.
10 ft. **Site 14 of 27 in cluster K**

Relative:
Lower

Actual:
1073 ft.

ICIS:

Enforcement Action ID:	09-2001-0096
FRS ID:	110012174235
Program ID:	FRS 110012174235
Action Name:	ALLIANCE COLTON

ALLIANCE COLTON - DREWS SUBSTATION (Continued) **1011567459**

Facility Name:	ALLIANCE COLTON - DREWS SUBSTATION
Facility Address:	559 PEPPER AVE COLTON CA 92324 COLTON, California 92324
Enforcement Action Type:	CAA 113A Admin Compliance Order (Non-Penalty)
Facility County:	San Bernardino
EPA Region #:	9

Program ID:	FRS 110012174235
Facility Name:	ALLIANCE COLTON - DREWS SUBSTATION
Address:	559 PEPPER AVE
Tribal Indicator:	N
Fed Facility:	Not reported
NAIC Code:	Not reported
SIC Code:	4911
Latitude:	34.072299
Longitude:	-117.352983

K96 **ALLIANCE COLTON - DREWS SUBSTATION** **FINDS** **1005692353**
ESE **559 PEPPER AVE** **N/A**
< 1/8 **COLTON, CA 92324**
0.002 mi.
10 ft. **Site 15 of 27 in cluster K**

Relative:
Lower

Actual:
1073 ft.

FINDS:

Registry ID: 110012174235

Environmental Interest/Information System

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

K97 **PURENERGY OPERATING SERVICES, LLC** **FINDS** **1011985281**
ESE **559 PEPPER AVE** **N/A**
< 1/8 **COLTON, CA 92324**
0.002 mi.
10 ft. **Site 16 of 27 in cluster K**

Relative:
Lower

Actual:
1073 ft.

FINDS:

Registry ID: 110037984571

Environmental Interest/Information System

PURENERGY OPERATING SERVICES, LLC (Continued) **1011985281**

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

CRITERIA AND HAZARDOUS AIR POLLUTANT INVENTORY

K98 **MCNEILUS TRUCK & MANUFACTURING INC** **FINDS** **1005845561**
ESE **401 N. PEPPER AVE.** **N/A**
< 1/8 **COLTON, CA 92324**
0.003 mi.
16 ft. **Site 17 of 27 in cluster K**

Relative:
Lower

Actual:
1072 ft.

FINDS:

Registry ID: 110008061970

Environmental Interest/Information System

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

US EPA TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.

CRITERIA AND HAZARDOUS AIR POLLUTANT INVENTORY

K99 **MCNEILUS TRK & MFG** **HAZNET** **S113025170**
ESE **401 N PEPPER PO BOX 1588** **N/A**
< 1/8 **COLTON, CA 92324**
0.003 mi.
16 ft. **Site 18 of 27 in cluster K**

Relative:
Lower

Actual:
1072 ft.

HAZNET:

Year:	2011
Gepaid:	CAL000010235
Contact:	MATTHEW GREGORY, ENVT'L MGR
Telephone:	5073748744
Mailing Name:	Not reported
Mailing Address:	PO BOX 70
Mailing City,St,Zip:	DODGE CTR, MN 559270000
Gen County:	Not reported
TSD EPA ID:	TXD077603371
TSD County:	Not reported
Waste Category:	Unspecified sludge waste
Disposal Method:	Fuel Blending Prior To Energy Recovery At Another Site
Tons:	0.5
Facility County:	San Bernardino

Year:	2011
Gepaid:	CAL000010235
Contact:	MATTHEW GREGORY, ENVT'L MGR
Telephone:	5073748744

MCNEILUS TRK & MFG (Continued) **S113025170**

Mailing Name: Not reported
Mailing Address: PO BOX 70
Mailing City,St,Zip: DODGE CTR, MN 559270000
Gen County: Not reported
TSD EPA ID: NVT330010000
TSD County: Not reported
Waste Category: Other organic solids
Disposal Method: Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons: 0.225
Facility County: San Bernardino

Year: 2009
Gepaid: CAL000010235
Contact: MATTHEW GREGORY, ENVT'L MGR
Telephone: 5073748744
Mailing Name: Not reported
Mailing Address: PO BOX 70
Mailing City,St,Zip: DODGE CENTER, MN 559270000
Gen County: Not reported
TSD EPA ID: ARD981057870
TSD County: Not reported
Waste Category: Other organic solids
Disposal Method: Fuel Blending Prior To Energy Recovery At Another Site
Tons: 0.95
Facility County: San Bernardino

Year: 2009
Gepaid: CAL000010235
Contact: MATTHEW GREGORY, ENVT'L MGR
Telephone: 5073748744
Mailing Name: Not reported
Mailing Address: PO BOX 70
Mailing City,St,Zip: DODGE CENTER, MN 559270000
Gen County: Not reported
TSD EPA ID: ARD981057870
TSD County: Not reported
Waste Category: Not reported
Disposal Method: Fuel Blending Prior To Energy Recovery At Another Site
Tons: 1.14675
Facility County: San Bernardino

Year: 2008
Gepaid: CAL000010235
Contact: MATTHEW GREGORY, ENVT'L MGR
Telephone: 5073748744
Mailing Name: Not reported
Mailing Address: PO BOX 70
Mailing City,St,Zip: DODGE CENTER, MN 559270000
Gen County: Not reported
TSD EPA ID: ARD981057870
TSD County: Not reported
Waste Category: Not reported
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.0125
Facility County: San Bernardino

MCNEILUS TRK & MFG (Continued) **S113025170**

Click this hyperlink while viewing on your computer to access
6 additional CA_HAZNET: record(s) in the EDR Site Report.

K100 **MCNEILUS TRUCK & MFG INC** **NPDES** **1005452064**
ESE **401 N PEPPER AVE** **San Bern. Co. Permit** **N/A**
< 1/8 **COLTON, CA 92324** **EMI**
0.003 mi. **WDS**
16 ft. **Site 19 of 27 in cluster K**

Relative:
Lower

Actual:
1072 ft.

NPDES:

Npdes Number:	CAS000001
Facility Status:	Terminated
Agency Id:	0
Region:	8
Regulatory Measure Id:	213311
Order No:	97-03-DWQ
Regulatory Measure Type:	Enrollee
Place Id:	Not reported
WDID:	8 36I011331
Program Type:	Industrial
Adoption Date Of Regulatory Measure:	Not reported
Effective Date Of Regulatory Measure:	01/04/1995
Expiration Date Of Regulatory Measure:	Not reported
Termination Date Of Regulatory Measure:	02/03/2012
Discharge Name:	McNeilus Truck & Manufacturing Inc
Discharge Address:	PO Box 70
Discharge City:	Dodge Center
Discharge State:	Minnesota
Discharge Zip:	55927

San Bern. Co. Permit:

Region:	SAN BERNARDINO
Facility ID:	FA0004643
Owner:	OSHKOSH TRUCK CORPORATION
Permit Number:	PT0005344
Permit Category:	HAZARDOUS WASTE GENERATOR - 0-10 EMPLOYEES
Facility Status:	ACTIVE
Expiration Date:	09/30/2014

Region:	SAN BERNARDINO
Facility ID:	FA0004643
Owner:	OSHKOSH TRUCK CORPORATION
Permit Number:	PT0025559
Permit Category:	WASTE-GENERATING RECYCLER (ONSITE)
Facility Status:	ACTIVE
Expiration Date:	09/30/2013

Region:	SAN BERNARDINO
Facility ID:	FA0004643
Owner:	OSHKOSH TRUCK CORPORATION
Permit Number:	PT0005343
Permit Category:	HAZMAT HANDLER 0-10 EMPLOYEES (W/GEN PRMT)
Facility Status:	ACTIVE
Expiration Date:	09/30/2013

EMI:

Year:	1997

MCNEILUS TRUCK & MFG INC (Continued) **1005452064**

County Code:	36
Air Basin:	SC
Facility ID:	83870
Air District Name:	SC
SIC Code:	3479
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	3
Reactive Organic Gases Tons/Yr:	2
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1998
County Code:	36
Air Basin:	SC
Facility ID:	83870
Air District Name:	SC
SIC Code:	3479
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1999
County Code:	36
Air Basin:	SC
Facility ID:	83870
Air District Name:	SC
SIC Code:	3479
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	3
Reactive Organic Gases Tons/Yr:	2
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	2000
County Code:	36
Air Basin:	SC
Facility ID:	83870
Air District Name:	SC
SIC Code:	3479
Air District Name:	SOUTH COAST AQMD

MCNEILUS TRUCK & MFG INC (Continued) **1005452064**

Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	3
Reactive Organic Gases Tons/Yr:	2
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	2001
County Code:	36
Air Basin:	SC
Facility ID:	83870
Air District Name:	SC
SIC Code:	3479
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	3
Reactive Organic Gases Tons/Yr:	2
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

CA WDS:

Facility ID:	Santa Ana River 36I011331
Facility Type:	Industrial - Facility that treats and/or disposes of liquid or semisolid wastes from any servicing, producing, manufacturing or processing operation of whatever nature, including mining, gravel washing, geothermal operations, air conditioning, ship building and repairing, oil production, storage and disposal operations, water pumping.
Facility Status:	Active - Any facility with a continuous or seasonal discharge that is under Waste Discharge Requirements.
NPDES Number:	CAS000001 The 1st 2 characters designate the state. The remaining 7 are assigned by the Regional Board
Subregion:	8
Facility Telephone:	9093702100
Facility Contact:	TOM VATTER
Agency Name:	MC NEILUS TRUCK & MFG INC
Agency Address:	PO Box 70
Agency City,St,Zip:	Dodge Center 559270070
Agency Contact:	BRUCE NORTON
Agency Telephone:	5073746321
Agency Type:	Private
SIC Code:	0
SIC Code 2:	Not reported
Primary Waste:	Not reported
Primary Waste Type:	Not reported
Secondary Waste:	Not reported
Secondary Waste Type:	Not reported
Design Flow:	0
Baseline Flow:	0
Reclamation:	Not reported

MCNEILUS TRUCK & MFG INC (Continued) **1005452064**

POTW: Not reported
Treat To Water: Minor Threat to Water Quality. A violation of a regional board order should cause a relatively minor impairment of beneficial uses compared to a major or minor threat. Not: All nurds without a TTWQ will be considered a minor threat to water quality unless coded at a higher Level. A Zero (0) may be used to code those NURDS that are found to represent no threat to water quality.
Complexity: Category C - Facilities having no waste treatment systems, such as cooling water dischargers or thosewho must comply through best management practices, facilities with passive waste treatment and disposal systems, such as septic systems with subsurface disposal, or dischargers having waste storage systems with land disposal such as dairy waste ponds.

---

101 **EDR US Hist Cleaners** **1015015544**
NW **2069 SAN BERNARDINO AVE** **N/A**
< 1/8 **COLTON, CA 92324**
0.004 mi.
22 ft.

Relative: **Higher**

Actual: **1116 ft.**

EDR Historical Cleaners:
Name: BASEL HI TOUCH CARPET CLEANING
Year: 2001
Address: 2069 SAN BERNARDINO AVE

K102 **ARRHOWHEAD REGIONAL MEDICAL CENTER** **RMP** **1011815750**
ESE **400 NORTH PEPPER** **N/A**
< 1/8 **COLTON, CA 92324**
0.013 mi.
66 ft. **Site 20 of 27 in cluster K**

Relative: **Lower**

Actual: **1070 ft.**

Risk Management Plan (RMP) Facility Details:

Facility ID:	17480
LEPC city:	Colton/San Bernardino County F
Facility decimal latitude:	0
Facility decimal longitude:	0
Is facility in county box:	F
LatLong method:	Not reported
LatLong description:	Not reported
Home page web address:	WWW.County of San Bernardino.cpm
Facility telephone:	9095801000
Facility email:	Not reported
Facility DUNS #:	0
Parent's name:	Not reported
Partner's name:	Not reported
Parent's DUNS #:	0
Partner's DUNS #:	0
Operator's name:	County of San Bernardino
Operator's telephone:	9093872020
Operator's address:	385 North Arrowhead Avenue
Operators City,St,Zip:	San Bernardino, CA 92415 0120
RMP implementation contact:	Mike Robertson
RMP contact title:	Facilities/Maintenance Supervisor
Emergency contact:	Bruce Rainey
Emergency contact title:	Associate Hospital Administrator
Emergency contact telephone:	9095806180

ARRHOWHEAD REGIONAL MEDICAL CENTER (Continued) **1011815750**

24 hour emergency telephone: 9093185042
Emergency contact ext/pin #: 9092761796
Number of full time employees: 2000
EPA ID: Not reported
Facility ID provided by CEPPO: 100000161512
Is facility covered by OSHA PSM: T
Is facility covered by EPCRA 302: T
Is fac. covered by CAA Title V 112(2): F
Clean air op. permit/State ID: Not reported
Last safety insp. dat: 4/1/1999
Inspected by: Fire Department
Is it OSHA approved with star/merit ranking: False
Will RMP involve predictive filing: False
Submission type: First Time
RMP description: Not reported
Facility has no accident hist. recs: True
Foreign owner's address: Not reported
Foreign owner's zip: Not reported
Foreign owner's country: Not reported
Claim # of employees as CBI: False
Date RMP accepted by EPA: 9/10/1999
Date of error Report: 9/10/1999
Date RMP received: 9/7/1999
Does RMP contain graphics files: False
Does RMP contain attachments: False
Was certification letter received: True
RMP submission method: Paper
Does RMP contain CBI substantiation: False
Does RMP contain electronic waiver: True
Date RMP postmarked: 9/3/1999
Is RMP complete: False
Date of de-registration: 7/2/2004
Date de-registration is effective: 6/1/2004
Aniversary date: 9/3/2004
Does RMP contain CBI data: False
Does RMP contain unsanitized CBI version: False
RMP version #: 1.1.7
FRS latitude: 34.07213
FRS longitude: -117.35291
FRS Description: PLANT ENTRANCE (GENERAL)
FRS Method: ADDRESS MATCHING-HOUSE NUMBER

Process Details:
Process ID: 24621
NA & Industry Classification Sys.code(s): 62211
NAICS code description: General Medical and Surgical Hospitals
Optional facility description: Back -up Fuel System
Program level: 2
Record contains CBI data: False

Process chemical(s):
Chemical name: Propane
Process chemical qty in 100s lbs: 60000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported

ARRHOWHEAD REGIONAL MEDICAL CENTER (Continued) **1011815750**

Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported

ARRHOWHEAD REGIONAL MEDICAL CENTER (Continued) **1011815750**

Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported

ARRHOWHEAD REGIONAL MEDICAL CENTER (Continued) **1011815750**

Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: EPA's RMP Guidance for Propane Storage Facilities Reference Tables or Equations
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Installed Underground
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported

ARRHOWHEAD REGIONAL MEDICAL CENTER (Continued) **1011815750**

Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported

Emergency Response Details:

ER plan:	Not reported
ER plan most recent review date:	4/1/1999
ER plan most recent employee training date:	9/5/1998
Local agency coordinating ER plan:	Colton F.D.
Telephone of the coordinating local agency:	9098254221
Federal regulation:	False
OSHA 1910 120:	False
SPCC:	False
RCRA:	False
OPA 90:	False
EPCRA:	False
Other Regulations:	Not reported

K103 **CO-ARROWHEAD REG.MED.CTR** **UST** **U003785473**
ESE **400 N PEPPER AVE** **WDS** **N/A**
< 1/8 **COLTON, CA 92324**
0.013 mi.
66 ft. **Site 21 of 27 in cluster K**

Relative:
Lower

Actual:
1070 ft.

UST:
Facility ID: 98046597
Latitude: 34.07091
Longitude: -117.35283

CA WDS:

Facility ID:	Santa Ana River 362794001
Facility Type:	Other - Does not fall into the category of Municipal/Domestic, Industrial, Agricultural or Solid Waste (Class I, II or III)
Facility Status:	Active - Any facility with a continuous or seasonal discharge that is under Waste Discharge Requirements.
NPDES Number:	CAG998001 The 1st 2 characters designate the state. The remaining 7 are assigned by the Regional Board
Subregion:	8
Facility Telephone:	9095800037
Facility Contact:	MICHAEL HEINE
Agency Name:	ARROWHEAD REG. MEDICAL CENTER
Agency Address:	400 N. PEPPER AVENUE
Agency City,St,Zip:	COLTON 92324
Agency Contact:	MICHAEL HEINE
Agency Telephone:	9095800037
Agency Type:	Private
SIC Code:	0
SIC Code 2:	Not reported
Primary Waste:	Not reported
Primary Waste Type:	Not reported
Secondary Waste:	Not reported
Secondary Waste Type:	Not reported
Design Flow:	0
Baseline Flow:	0
Reclamation:	No reclamation requirements associated with this facility.
POTW:	The facility is not a POTW.
Treat To Water:	Minor Threat to Water Quality. A violation of a regional board order should cause a relatively minor impairment of beneficial uses compared to a major or minor threat. Not: All nurds without a TTWQ will be considered a minor threat to water quality unless coded at a higher Level. A Zero (0) may be used to code those NURDS that are found to represent no threat to water quality.
Complexity:	Category C - Facilities having no waste treatment systems, such as cooling water dischargers or thosewho must comply through best management practices, facilities with passive waste treatment and disposal systems, such as septic systems with subsurface disposal, or dischargers having waste storage systems with land disposal such as dairy waste ponds.

K104 **ARROWHEAD REGIONAL MEDICAL CENTER** **RCRA-SQG** **1014387404**
ESE **400 N PEPPER AVE** **CAR000209296**
< 1/8 **COLTON, CA 92324**
0.013 mi.
66 ft. **Site 22 of 27 in cluster K**

Relative:
Lower

Actual:
1070 ft.

RCRA-SQG:

Date form received by agency:	07/02/2010
Facility name:	ARROWHEAD REGIONAL MEDICAL CENTER
Facility address:	400 N PEPPER AVE COLTON, CA 92324
EPA ID:	CAR000209296
Contact:	CHRIS COOK
Contact address:	400 N PEPPER AVE COLTON, CA 92324
Contact country:	US
Contact telephone:	909-580-0081
Contact email:	COOKCH@ARMC.SBCOUNTY.GOV
EPA Region:	09
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	COUNT OF SAN BERNARDINO
Owner/operator address:	385 N ARROWHEAD AVE SAN BERNARDINO, CA 92415
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	County
Owner/Operator Type:	Owner
Owner/Op start date:	01/01/1800
Owner/Op end date:	Not reported

Owner/operator name:	ARROWHEAD REGIONAL MEDICAL CENTER
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	County
Owner/Operator Type:	Operator
Owner/Op start date:	03/31/1999
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No

ARROWHEAD REGIONAL MEDICAL CENTER (Continued) **1014387404**

User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Universal Waste Summary:
Waste type: Batteries
Accumulated waste on-site: No
Generated waste on-site: Not reported

Waste type: Lamps
Accumulated waste on-site: No
Generated waste on-site: Not reported

Waste type: Pesticides
Accumulated waste on-site: No
Generated waste on-site: Not reported

Waste type: Thermostats
Accumulated waste on-site: No
Generated waste on-site: Not reported

Hazardous Waste Summary:
Waste code: 181
Waste name: 181

Waste code: 291
Waste name: 291

Waste code: 311
Waste name: 311

Waste code: 331
Waste name: 331

Waste code: 341
Waste name: 341

Waste code: 551
Waste name: 551

Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002
Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS

ARROWHEAD REGIONAL MEDICAL CENTER (Continued) **1014387404**

USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Waste code: D003
Waste name: A MATERIAL IS CONSIDERED TO BE A REACTIVE HAZARDOUS WASTE IF IT IS NORMALLY UNSTABLE, REACTS VIOLENTLY WITH WATER, GENERATES TOXIC GASES WHEN EXPOSED TO WATER OR CORROSIVE MATERIALS, OR IF IT IS CAPABLE OF DETONATION OR EXPLOSION WHEN EXPOSED TO HEAT OR A FLAME. ONE EXAMPLE OF SUCH WASTE WOULD BY WASTE GUNPOWDER.

Waste code: D008
Waste name: LEAD

Violation Status: No violations found

K105
ESE
< 1/8
0.013 mi.
66 ft.

Relative:
Lower

Actual:
1070 ft.

ARROWHEAD REGIONAL MEDICAL CENTER **FINDS 1005611485**
400 W PEPPER ST **US AIRS N/A**
COLTON, CA 92324

Site 23 of 27 in cluster K

FINDS:

Registry ID: 110000528769

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CRITERIA AND HAZARDOUS AIR POLLUTANT INVENTORY

US EPA Risk Management Plan (RMP) database stores the risk management plans reported by companies that handle, manufacture, use, or store certain flammable or toxic substances, as required under section 112(r) of the Clean Air Act (CAA).

ARROWHEAD REGIONAL MEDICAL CENTER (Continued) **1005611485**

AIRS (AFS):

Compliance and Violation Data Major Sources:

EPA plant ID:	110017210980
Plant name:	ARROWHEAD REGIONAL MEDICAL CENTER
Plant address:	400 W PEPPER ST COLTON, CA 92324
County:	SAN BERNARDINO
Region code:	09
Dunn & Bradst #:	Not reported
Air quality cntrl region:	024
Sic code:	8062
Sic code desc:	Not reported
North Am. industrial classf:	622110
NAIC code description:	General Medical and Surgical Hospitals
Default compliance status:	IN COMPLIANCE - INSPECTION
Default classification:	ACTUAL OR POTENTIAL EMISSIONS ARE ABOVE THE APPLICABLE MAJOR SOURCE THRESHOLDS
Govt facility:	ALL OTHER FACILITIES NOT OWNED OR OPERATED BY A FEDERAL, STATE, OR LOCAL GOVERNMENT
Current HPV:	ADDRESSED-STATE/LOCAL HAS LEAD ENFORCEMENT

Compliance and Enforcement Major Issues:

Air program:	TITLE V PERMITS
National action type:	MULTI MEDIA INSPECTION - LEVEL 2 OR GREATER
Date achieved:	011010
Penalty amount:	000000000
Air program:	TITLE V PERMITS
National action type:	STATE CONDUCTED PCE/ ON-SITE
Date achieved:	040407
Penalty amount:	Not reported
Air program:	SIP SOURCE
National action type:	STATE CONDUCTED FCE / ON-SITE
Date achieved:	040407
Penalty amount:	Not reported
Air program:	TITLE V PERMITS
National action type:	STATE CONDUCTED FCE / ON-SITE
Date achieved:	040407
Penalty amount:	Not reported
Air program:	SIP SOURCE
National action type:	STATE CONDUCTED PCE/ ON-SITE
Date achieved:	040407
Penalty amount:	Not reported
Air program:	SIP SOURCE
National action type:	STATE CONDUCTED FCE / ON-SITE
Date achieved:	050708
Penalty amount:	Not reported
Air program:	TITLE V PERMITS
National action type:	STATE CONDUCTED FCE / ON-SITE
Date achieved:	050708

ARROWHEAD REGIONAL MEDICAL CENTER (Continued) **1005611485**

Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 050708
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 050708
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 060915
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 060915
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 060915
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 060915
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 060915
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 060915
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: NXXXXX
Date achieved: 061031
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: NXXXXX
Date achieved: 061031
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: S/L REQ (O/O COND) STACK TEST/NOT OBSV BUT REVWD
Date achieved: 061204
Penalty amount: Not reported

ARROWHEAD REGIONAL MEDICAL CENTER (Continued) **1005611485**

Air program: SIP SOURCE
National action type: S/L REQ (O/O COND) STACK TEST/NOT OBSV BUT REVWD
Date achieved: 061204
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE DAY 0
Date achieved: 070124
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE DAY 0
Date achieved: 070124
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: NXXXXX
Date achieved: 070207
Penalty amount: 000001000

Air program: SIP SOURCE
National action type: NXXXXX
Date achieved: 070207
Penalty amount: 000001000

Air program: TITLE V PERMITS
National action type: TITLE V COMPLIANCE CERT DUE/RECEIVED BY
Date achieved: 070307
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 070307
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 070307
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V COMPLIANCE CERT DUE/RECEIVED BY
Date achieved: 070327
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: NXXXXX
Date achieved: 070809
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: NXXXXX
Date achieved: 070809
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED FCE / ON-SITE

ARROWHEAD REGIONAL MEDICAL CENTER (Continued) **1005611485**

Date achieved: 070809
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 070809
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 070809
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 070809
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: S/L REQ (O/O COND) STACK TEST/NOT OBSV BUT REVWD
Date achieved: 070822
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: S/L REQ (O/O COND) STACK TEST/NOT OBSV BUT REVWD
Date achieved: 070822
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: SV RESOLVED
Date achieved: 071129
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: SV RESOLVED
Date achieved: 071129
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 080228
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 080228
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V COMPLIANCE CERT DUE/RECEIVED BY
Date achieved: 080306
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE DAY 0
Date achieved: 080323
Penalty amount: Not reported

ARROWHEAD REGIONAL MEDICAL CENTER (Continued) **1005611485**

Air program: TITLE V PERMITS
National action type: STATE DAY 0
Date achieved: 080323
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: NXXXXX
Date achieved: 080326
Penalty amount: 000000500

Air program: TITLE V PERMITS
National action type: NXXXXX
Date achieved: 080326
Penalty amount: 000000500

Air program: TITLE V PERMITS
National action type: SV RESOLVED
Date achieved: 080529
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: SV RESOLVED
Date achieved: 080529
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 080807
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 080807
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: NXXXXX
Date achieved: 080813
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: NXXXXX
Date achieved: 080813
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 080912
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 080912
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: S/L REQ (O/O COND) STACK TEST/NOT OBSV BUT REVWD

ARROWHEAD REGIONAL MEDICAL CENTER (Continued) **1005611485**

Date achieved: 081024
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: S/L REQ (O/O COND) STACK TEST/NOT OBSV BUT REVWD
Date achieved: 081024
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE DAY 0
Date achieved: 081106
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE DAY 0
Date achieved: 081106
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: NXXXXX
Date achieved: 081107
Penalty amount: 000001000

Air program: SIP SOURCE
National action type: NXXXXX
Date achieved: 081107
Penalty amount: 000001000

Air program: TITLE V PERMITS
National action type: S/L REQ (O/O COND) STACK TEST/NOT OBSV BUT REVWD
Date achieved: 081110
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: S/L REQ (O/O COND) STACK TEST/NOT OBSV BUT REVWD
Date achieved: 081110
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: S/L REQ (O/O COND) STACK TEST/NOT OBSV BUT REVWD
Date achieved: 081120
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: S/L REQ (O/O COND) STACK TEST/NOT OBSV BUT REVWD
Date achieved: 081120
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 090227
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 090227
Penalty amount: Not reported

ARROWHEAD REGIONAL MEDICAL CENTER (Continued) **1005611485**

Air program: TITLE V PERMITS
National action type: TITLE V COMPLIANCE CERT DUE/RECEIVED BY
Date achieved: 090305
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 090514
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 090514
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 090514
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 090514
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 090514
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 090514
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 100111
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 100111
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V COMPLIANCE CERT DUE/RECEIVED BY
Date achieved: 100121
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 100713
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED PCE/ ON-SITE

ARROWHEAD REGIONAL MEDICAL CENTER (Continued) **1005611485**

Date achieved: 100713
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 100713
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 100713
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: NXXXXX
Date achieved: 100721
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: NXXXXX
Date achieved: 100721
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 100910
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 100910
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE DAY 0
Date achieved: 101008
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE DAY 0
Date achieved: 101008
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: NXXXXX
Date achieved: 101118
Penalty amount: 000000500

Air program: TITLE V PERMITS
National action type: NXXXXX
Date achieved: 101118
Penalty amount: 000000500

Air program: SIP SOURCE
National action type: S/L REQ (O/O COND) STACK TEST/NOT OBSV BUT REVWD
Date achieved: 101208
Penalty amount: Not reported

ARROWHEAD REGIONAL MEDICAL CENTER (Continued) **1005611485**

Air program: TITLE V PERMITS
National action type: S/L REQ (O/O COND) STACK TEST/NOT OBSV BUT REVWD
Date achieved: 101208
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: SV RESOLVED
Date achieved: 110111
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: SV RESOLVED
Date achieved: 110111
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 110215
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 110215
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 110927
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 110927
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 110927
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 110927
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 110927
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 110927
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: S/L REQ (O/O COND) STACK TEST/NOT OBSV BUT REVWD

ARROWHEAD REGIONAL MEDICAL CENTER (Continued) **1005611485**

Date achieved: 111221
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: S/L REQ (O/O COND) STACK TEST/NOT OBSV BUT REVWD
Date achieved: 111221
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 120224
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 120224
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: S/L REQ (O/O COND) STACK TEST/NOT OBSV BUT REVWD
Date achieved: 120404
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: S/L REQ (O/O COND) STACK TEST/NOT OBSV BUT REVWD
Date achieved: 120404
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 120906
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 120906
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 120906
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 120906
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 120906
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 120906
Penalty amount: Not reported

ARROWHEAD REGIONAL MEDICAL CENTER (Continued) **1005611485**

Historical Compliance Minor Sources:

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1001
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1001
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1002
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1003
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1004
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1004
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1101
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1102
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1103
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1103
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1104
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1201
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1202
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1203
Air prog code hist file: 0

ARROWHEAD REGIONAL MEDICAL CENTER (Continued) **1005611485**

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1203
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1204
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1002
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1003
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1101
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1102
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1104
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1201
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1202
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1204
Air prog code hist file: 0

Permit Information:
Compliance plant ID: CA182
Permit number: 118379
Permit category: V
Permit category desc: TITLE V PERMIT - PLANT SP

Permit Source:
Compliance plant ID: CA182
Plant name: ARROWHEAD REGIONAL MEDICAL CENTER
Plant address: 400 W PEPPER ST
COLTON, CA 92324

Event Information:
Compliance permit ID: CA182
Permit number: 118379
Event action type: IF

ARROWHEAD REGIONAL MEDICAL CENTER (Continued) **1005611485**

Event description: *PERMIT AUTHORITY ISSUES FINAL PERMIT
Event action #: 001
Event date: 20050621

K106 **ARROWHEAD REGIONAL MED CTR** **San Bern. Co. Permit** **S104765310**
ESE **400 N PEPPER AVE** **EMI** **N/A**
< 1/8 **COLTON, CA 92324**
0.013 mi.
66 ft. **Site 24 of 27 in cluster K**

Relative:
Lower

Actual:
1070 ft.

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0002241
Owner: CO-SAN BDNO MEDICAL CTR
Permit Number: PT0010690
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: INACTIVE
Expiration Date: 10/31/2011

Region: SAN BERNARDINO
Facility ID: FA0002241
Owner: CO-SAN BDNO MEDICAL CTR
Permit Number: PT0009430
Permit Category: HAZMAT HANDLER 500+ EMPLOYEES (W/GEN PRMT)
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0002241
Owner: CO-SAN BDNO MEDICAL CTR
Permit Number: PT0023331
Permit Category: UW HANDLER W/ ANOTHER HAZ WASTE GENERATOR FEE
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0002241
Owner: CO-SAN BDNO MEDICAL CTR
Permit Number: PT0009431
Permit Category: HAZARDOUS WASTE GENERATOR - 500+ EMPLOYEES
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0002241
Owner: CO-SAN BDNO MEDICAL CTR
Permit Number: PT0021923
Permit Category: EPCRA FACILITY
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0002241
Owner: CO-SAN BDNO MEDICAL CTR
Permit Number: PT0010686
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE

ARROWHEAD REGIONAL MED CTR (Continued) **S104765310**

Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0002241
Owner: CO-SAN BDNO MEDICAL CTR
Permit Number: PT0010687
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0002241
Owner: CO-SAN BDNO MEDICAL CTR
Permit Number: PT0010688
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0002241
Owner: CO-SAN BDNO MEDICAL CTR
Permit Number: PT0010689
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0002241
Owner: CO-SAN BDNO MEDICAL CTR
Permit Number: PT0010684
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0002241
Owner: CO-SAN BDNO MEDICAL CTR
Permit Number: PT0010685
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 10/31/2013

EMI:

Year:	2002
County Code:	36
Air Basin:	SC
Facility ID:	118379
Air District Name:	SC
SIC Code:	8062
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2
Reactive Organic Gases Tons/Yr:	2
Carbon Monoxide Emissions Tons/Yr:	9
NOX - Oxides of Nitrogen Tons/Yr:	12
SOX - Oxides of Sulphur Tons/Yr:	0

ARROWHEAD REGIONAL MED CTR (Continued) **S104765310**

Particulate Matter Tons/Yr:	2
Part. Matter 10 Micrometers & Smllr Tons/Yr:	1
Year:	2003
County Code:	36
Air Basin:	SC
Facility ID:	118379
Air District Name:	SC
SIC Code:	8062
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2
Reactive Organic Gases Tons/Yr:	2
Carbon Monoxide Emissions Tons/Yr:	9
NOX - Oxides of Nitrogen Tons/Yr:	12
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	2
Part. Matter 10 Micrometers & Smllr Tons/Yr:	1
Year:	2004
County Code:	36
Air Basin:	SC
Facility ID:	118379
Air District Name:	SC
SIC Code:	8062
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2.4003836
Reactive Organic Gases Tons/Yr:	1.52
Carbon Monoxide Emissions Tons/Yr:	8.73595
NOX - Oxides of Nitrogen Tons/Yr:	11.7221
SOX - Oxides of Sulphur Tons/Yr:	0.255441
Particulate Matter Tons/Yr:	1.52227
Part. Matter 10 Micrometers & Smllr Tons/Yr:	1.5
Year:	2005
County Code:	36
Air Basin:	SC
Facility ID:	118379
Air District Name:	SC
SIC Code:	8062
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.15187
Reactive Organic Gases Tons/Yr:	.784197922
Carbon Monoxide Emissions Tons/Yr:	7.46543
NOX - Oxides of Nitrogen Tons/Yr:	8.8802
SOX - Oxides of Sulphur Tons/Yr:	.17469
Particulate Matter Tons/Yr:	1.12316
Part. Matter 10 Micrometers & Smllr Tons/Yr:	1.107656
Year:	2006
County Code:	36
Air Basin:	SC

ARROWHEAD REGIONAL MED CTR (Continued) **S104765310**

Facility ID:	118379
Air District Name:	SC
SIC Code:	8062
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.915671018494185884
Reactive Organic Gases Tons/Yr:	1.28
Carbon Monoxide Emissions Tons/Yr:	12.069
NOX - Oxides of Nitrogen Tons/Yr:	10.46
SOX - Oxides of Sulphur Tons/Yr:	.211
Particulate Matter Tons/Yr:	1.458
Part. Matter 10 Micrometers & Smllr Tons/Yr:	1.4034

Year:	2007
County Code:	36
Air Basin:	SC
Facility ID:	118379
Air District Name:	SC
SIC Code:	8062
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2.000691227231568381
Reactive Organic Gases Tons/Yr:	1.221564785430000000
Carbon Monoxide Emissions Tons/Yr:	11.14
NOX - Oxides of Nitrogen Tons/Yr:	7.64
SOX - Oxides of Sulphur Tons/Yr:	.15
Particulate Matter Tons/Yr:	1.154275
Part. Matter 10 Micrometers & Smllr Tons/Yr:	1.1019925

Year:	2007
County Code:	36
Air Basin:	SC
Facility ID:	118379
Air District Name:	SC
SIC Code:	8062
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.915671018494185884
Reactive Organic Gases Tons/Yr:	1.28
Carbon Monoxide Emissions Tons/Yr:	12.069
NOX - Oxides of Nitrogen Tons/Yr:	10.46
SOX - Oxides of Sulphur Tons/Yr:	.211
Particulate Matter Tons/Yr:	1.458
Part. Matter 10 Micrometers & Smllr Tons/Yr:	1.4034

K107
ESE
< 1/8
0.013 mi.
66 ft.

ARROWHEAD REGIONAL MEDICAL CENTER
400 NORTH PEPPER AVE.
COLTON, CA 92324

Site 25 of 27 in cluster K

MWMP **S111859469**
N/A

Relative:
Lower

Actual:
1070 ft.

MWMP:

Facility Type:	CDPH Permitted Transfer and Treatment Facilities
Sr No:	7
Contact Name:	909-580-0081
Contact Phone:	Chris Cook
Method:	Treatment
Registration Number:	34

K108
ESE
< 1/8
0.013 mi.
66 ft.

ARROWHEAD REGIONAL MED CTR
400 N PEPPER AVE
COLTON, CA 92324

Site 26 of 27 in cluster K

HAZNET **S113108713**
N/A

Relative:
Lower

Actual:
1070 ft.

HAZNET:

Year:	2011
Gepaid:	CAL000214531
Contact:	CHRIS COOK/EVS/LINEN MANAGER
Telephone:	9095800080
Mailing Name:	Not reported
Mailing Address:	400 N PEPPER AVE
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	Not reported
TSD EPA ID:	CAD028409019
TSD County:	Not reported
Waste Category:	Other inorganic solid waste
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	1.1825
Facility County:	San Bernardino

Year:	2011
Gepaid:	CAL000214531
Contact:	CHRIS COOK/EVS/LINEN MANAGER
Telephone:	9095800080
Mailing Name:	Not reported
Mailing Address:	400 N PEPPER AVE
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	Not reported
TSD EPA ID:	CAD028409019
TSD County:	Not reported
Waste Category:	Unspecified solvent mixture
Disposal Method:	Fuel Blending Prior To Energy Recovery At Another Site
Tons:	0.18
Facility County:	San Bernardino

Year:	2011
Gepaid:	CAL000214531
Contact:	CHRIS COOK/EVS/LINEN MANAGER
Telephone:	9095800080
Mailing Name:	Not reported
Mailing Address:	400 N PEPPER AVE
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	Not reported

ARROWHEAD REGIONAL MED CTR (Continued) **S113108713**

TSD EPA ID:	ARD069748192
TSD County:	Not reported
Waste Category:	Pharmaceutical waste
Disposal Method:	Incineration--Thermal Destruction Other Than Use As A Fuel
Tons:	0.8787
Facility County:	San Bernardino
Year:	2011
Gepaid:	CAL000214531
Contact:	CHRIS COOK/EVS/LINEN MANAGER
Telephone:	9095800080
Mailing Name:	Not reported
Mailing Address:	400 N PEPPER AVE
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	Not reported
TSD EPA ID:	CAD028409019
TSD County:	Not reported
Waste Category:	Off-specification, aged or surplus organics
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	2.7027
Facility County:	San Bernardino
Year:	2010
Gepaid:	CAL000214531
Contact:	CHRIS COOK/EVS/LINEN MANAGER
Telephone:	9095800080
Mailing Name:	Not reported
Mailing Address:	400 N PEPPER AVE
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	Not reported
TSD EPA ID:	UTD981552177
TSD County:	Not reported
Waste Category:	Pharmaceutical waste
Disposal Method:	Incineration--Thermal Destruction Other Than Use As A Fuel
Tons:	0.075
Facility County:	San Bernardino

Click this hyperlink while viewing on your computer to access
97 additional CA_HAZNET: record(s) in the EDR Site Report.

K109 **CHMIRS** **S105669914**
ESE **400 N. PEPPER AVE** **N/A**
< 1/8 **COLTON, CA 92324**
0.013 mi.
66 ft. **Site 27 of 27 in cluster K**

Relative:
Lower

Actual:
1070 ft.

CHMIRS:

OES Incident Number:	01-7296
OES notification:	12/17/2001
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported

(Continued) **S105669914**

Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	No
Waterway:	Not reported
Spill Site:	Not reported
Cleanup By:	Reporting Party
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	2001
Agency:	Arrowhead Regional Medical Center
Incident Date:	12/13/200112:00:00 AM
Admin Agency:	San Bernardino County Health Department
Amount:	Not reported
Contained:	Yes
Site Type:	Other
E Date:	Not reported
Substance:	Potassium Hydroxide;;;
Quantity Released:	Not reported
BBLS:	0
Cups:	0
CUFT:	0
Gallons:	0
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0

(Continued) **S105669914**

Sheen:	0
Tons:	0
Unknown:	0.000000
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	A bottle of the substance was dropped and spilled on the floor.

A110 **CLUTCH MASTERS** **San Bern. Co. Permit** **S102041351**
WSW **267 E VALLEY BLVD** **N/A**
< 1/8 **RIALTO, CA 92376**
0.034 mi.
179 ft. **Site 7 of 18 in cluster A**

Relative:
Lower

Actual:
1068 ft.

San Bern. Co. Permit:

Region:	SAN BERNARDINO
Facility ID:	FA0002237
Owner:	CLUTCH MASTERS
Permit Number:	PT0003834
Permit Category:	SPECIAL HANDLER
Facility Status:	ACTIVE
Expiration Date:	08/31/2013

Region:	SAN BERNARDINO
Facility ID:	FA0002237
Owner:	CLUTCH MASTERS
Permit Number:	PT0003833
Permit Category:	SPECIAL GENERATOR
Facility Status:	ACTIVE
Expiration Date:	08/31/2013

A111 **P & S TRUCK SUPPLY INC** **HAZNET** **S113017790**
West **245 E VALLEY BLVD** **N/A**
< 1/8 **RIALTO, CA 92376**
0.045 mi.
236 ft. **Site 8 of 18 in cluster A**

Relative:
Lower

Actual:
1069 ft.

HAZNET:

Year:	2001
Gepaid:	CAD983597956
Contact:	STEVE HEATER/PARTS MGR
Telephone:	9098742000
Mailing Name:	Not reported
Mailing Address:	161 E VALLEY BLVD
Mailing City,St,Zip:	RIALTO, CA 923760000
Gen County:	Not reported
TSD EPA ID:	CAD982444481
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Transfer Station
Tons:	0.22
Facility County:	San Bernardino

Year:	2000
Gepaid:	CAD983597956
Contact:	STEVE HEATER/PARTS MGR

P & S TRUCK SUPPLY INC (Continued) **S113017790**

Telephone: 9098742000
Mailing Name: Not reported
Mailing Address: 161 E VALLEY BLVD
Mailing City,St,Zip: RIALTO, CA 923760000
Gen County: Not reported
TSD EPA ID: CAD044429835
TSD County: Not reported
Waste Category: Waste oil and mixed oil
Disposal Method: Recycler
Tons: 1.37
Facility County: San Bernardino

Year: 2000
Gepaid: CAD983597956
Contact: STEVE HEATER/PARTS MGR
Telephone: 9098742000
Mailing Name: Not reported
Mailing Address: 161 E VALLEY BLVD
Mailing City,St,Zip: RIALTO, CA 923760000
Gen County: Not reported
TSD EPA ID: CAD982444481
TSD County: Not reported
Waste Category: Oil/water separation sludge
Disposal Method: Recycler
Tons: 0.91
Facility County: San Bernardino

Year: 2000
Gepaid: CAD983597956
Contact: STEVE HEATER/PARTS MGR
Telephone: 9098742000
Mailing Name: Not reported
Mailing Address: 161 E VALLEY BLVD
Mailing City,St,Zip: RIALTO, CA 923760000
Gen County: Not reported
TSD EPA ID: CAD982444481
TSD County: Not reported
Waste Category: Unspecified organic liquid mixture
Disposal Method: Recycler
Tons: 1.14
Facility County: San Bernardino

Year: 1999
Gepaid: CAD983597956
Contact: LYLE MCKEE
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 161 E VALLEY BLVD
Mailing City,St,Zip: RIALTO, CA 923760000
Gen County: Not reported
TSD EPA ID: CAD981696420
TSD County: Not reported
Waste Category: Aqueous solution with total organic residues less than 10 percent
Disposal Method: Not reported
Tons: .2293
Facility County: San Bernardino

P & S TRUCK SUPPLY INC (Continued) **S113017790**

Click this hyperlink while viewing on your computer to access
15 additional CA_HAZNET: record(s) in the EDR Site Report.

A112 **LUCKY FARMS** **San Bern. Co. Permit** **S108087303**
West **245 E VALLEY BLVD** **N/A**
< 1/8 **RIALTO, CA 92376**
0.045 mi.
236 ft. **Site 9 of 18 in cluster A**

Relative:
Lower

Actual:
1069 ft.

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0010571
Owner: LUCKY FARMS INC
Permit Number: PT0017970
Permit Category: SPECIAL HANDLER
Facility Status: ACTIVE
Expiration Date: 09/30/2013

Region: SAN BERNARDINO
Facility ID: FA0010571
Owner: LUCKY FARMS INC
Permit Number: PT0017969
Permit Category: SPECIAL GENERATOR
Facility Status: ACTIVE
Expiration Date: 09/30/2013

A113 **P S TRUCK SUPPLY INC** **RCRA-SQG** **1000595840**
West **245 E VALLEY BLVD** **FINDS** **CAD983597956**
< 1/8 **RIALTO, CA 92376**
0.045 mi.
236 ft. **Site 10 of 18 in cluster A**

Relative:
Lower

Actual:
1069 ft.

RCRA-SQG:
Date form received by agency: 07/26/1991
Facility name: P S TRUCK SUPPLY INC
Facility address: 245 E VALLEY BLVD
RIALTO, CA 92376
EPA ID: CAD983597956
Contact: LYLE MCKEE
Contact address: 245 E VALLEY BLVD
RIALTO, CA 92376
Contact country: US
Contact telephone: (714) 874-2000
Contact email: Not reported
EPA Region: 09
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: P S TRUCK SUPPLY INC
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999

P S TRUCK SUPPLY INC (Continued) **1000595840**

Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110002855223

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

A114 **LUCKY FARMS INC** **HAZNET** **S113128798**
West **245 E VALLEY BLVD** **N/A**
< 1/8 **RIALTO, CA 92376**
0.045 mi.
236 ft. **Site 11 of 18 in cluster A**

Relative:
Lower

Actual:
1069 ft.

HAZNET:

Year:	2004
Gepaid:	CAL000275670
Contact:	PHIL HAIRE OR CYNDI ARISTA
Telephone:	9099108687
Mailing Name:	Not reported
Mailing Address:	PO BOX 985
Mailing City,St,Zip:	LOMA LINDA, CA 923540985
Gen County:	Not reported
TSD EPA ID:	CAD028409019
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Transfer Station
Tons:	0.5
Facility County:	San Bernardino

I115 **WORLD PROPHETIC MINISTRY** **RCRA-SQG** **1001967567**
NNE **1099 N PEPPER AVE** **FINDS** **CAR000070615**
< 1/8 **COLTON, CA 92324** **HAZNET**
0.061 mi.
323 ft. **Site 2 of 6 in cluster I**

Relative:
Higher

Actual:
1094 ft.

RCRA-SQG:

Date form received by agency:	04/17/2000
Facility name:	WORLD PROPHETIC MINISTRY
Facility address:	1099 N PEPPER AVE COLTON, CA 92324
EPA ID:	CAR000070615
Contact:	LIDGE GIBBSON
Contact address:	1099 N PEPPER AVE COLTON, CA 92324
Contact country:	US
Contact telephone:	(909) 825-2767
Contact email:	Not reported
EPA Region:	09
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	WORLD PROPHETIC MINISTRY
Owner/operator address:	1099 N PEPPER AVE COLTON, CA 92324
Owner/operator country:	Not reported
Owner/operator telephone:	(909) 825-2767
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

WORLD PROPHETIC MINISTRY (Continued) **1001967567**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Hazardous Waste Summary:
Waste code: D000
Waste name: Not Defined

Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D018
Waste name: BENZENE

Waste code: D039
Waste name: TETRACHLOROETHYLENE

Waste code: D040
Waste name: TRICHLOROETHYLENE

Violation Status: No violations found

FINDS:

Registry ID: 110002935389

Environmental Interest/Information System
California Hazardous Waste Tracking System - Datamart (HWTS-DATAMART) provides California with information on hazardous waste shipments for generators, transporters, and treatment, storage, and disposal facilities.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

WORLD PROPHETIC MINISTRY (Continued) **1001967567**

HAZNET:

Year:	2002
Gepaid:	CAR000070615
Contact:	B.H. GIBSON V.P., GEN. MGR.
Telephone:	9098252767
Mailing Name:	Not reported
Mailing Address:	PO BOX 907
Mailing City,St,Zip:	COLTON, CA 923240907
Gen County:	Not reported
TSD EPA ID:	CAT000613976
TSD County:	Not reported
Waste Category:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method:	Transfer Station
Tons:	0.07
Facility County:	San Bernardino

Year:	2001
Gepaid:	CAR000070615
Contact:	B.H. GIBSON V.P., GEN. MGR.
Telephone:	9098252767
Mailing Name:	Not reported
Mailing Address:	PO BOX 907
Mailing City,St,Zip:	COLTON, CA 923240907
Gen County:	Not reported
TSD EPA ID:	CAT000613976
TSD County:	Not reported
Waste Category:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method:	Transfer Station
Tons:	0.47
Facility County:	San Bernardino

Year:	2001
Gepaid:	CAR000070615
Contact:	B.H. GIBSON V.P., GEN. MGR.
Telephone:	9098252767
Mailing Name:	Not reported
Mailing Address:	PO BOX 907
Mailing City,St,Zip:	COLTON, CA 923240907
Gen County:	Not reported
TSD EPA ID:	CAT080013352
TSD County:	Not reported
Waste Category:	Waste oil and mixed oil
Disposal Method:	Recycler
Tons:	0.22
Facility County:	San Bernardino

Year:	2000
Gepaid:	CAR000070615
Contact:	B.H. GIBSON V.P., GEN. MGR.
Telephone:	9098252767
Mailing Name:	Not reported
Mailing Address:	PO BOX 907
Mailing City,St,Zip:	COLTON, CA 923240907
Gen County:	Not reported
TSD EPA ID:	CAT000613976
TSD County:	Not reported
Waste Category:	Liquids with halogenated organic compounds >= 1,000 Mg./L

WORLD PROPHETIC MINISTRY (Continued) **1001967567**

Disposal Method: Transfer Station
Tons: 0.14
Facility County: San Bernardino

116
ENE
< 1/8
0.064 mi.
338 ft.

987 N CYPRESS ST
COLTON, CA 92324

CDL **S107537386**
N/A

Relative:
Higher

Actual:
1088 ft.

CDL:
Facility ID: 200307097
Lab Type: Illegal Drug Lab (L) - location where an illegal drug lab was operated or drug lab equipment and/or materials were stored.

I117
NNE
< 1/8
0.065 mi.
344 ft.

INTOWN PROPERTIES INC/HUD
1001 WHISTLE STOP DR
COLTON, CA 92324

Site 3 of 6 in cluster I

HAZNET **S112887289**
N/A

Relative:
Higher

Actual:
1101 ft.

HAZNET:
Year: 1998
Gepaid: CAC001389840
Contact: HUD
Telephone: 7149577333
Mailing Name: Not reported
Mailing Address: 2086 SOUTH E ST STE 204
Mailing City,St,Zip: SAN BERNARDINO, CA 924080000
Gen County: Not reported
TSD EPA ID: CAD982444481
TSD County: Not reported
Waste Category: Household waste
Disposal Method: Transfer Station
Tons: .0208
Facility County: San Bernardino

L118
NNE
< 1/8
0.067 mi.
352 ft.

HUD IN TOWN PROPERTIES
1065 AGUA CALIENTE LN
COLTON, CA 92324

Site 2 of 3 in cluster L

HAZNET **S112883869**
N/A

Relative:
Higher

Actual:
1103 ft.

HAZNET:
Year: 1997
Gepaid: CAC001346304
Contact: HUD
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 2086 S E ST STE 204
Mailing City,St,Zip: SAN BERNARDINO, CA 920480000
Gen County: Not reported
TSD EPA ID: CAD028409019
TSD County: Not reported
Waste Category: Household waste

HUD IN TOWN PROPERTIES (Continued) **S112883869**

Disposal Method: Treatment, Tank
Tons: .0250
Facility County: San Bernardino

A119 **ERNS** **91241843**
West **195 E VALLEY BLVD** **N/A**
< 1/8 **RIALTO, CA 92376**
0.069 mi.
366 ft. **Site 12 of 18 in cluster A**

Relative:
Lower

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

Actual:
1069 ft.

A120 **10-10 TRUCK STOP** **HIST UST** **U001575515**
West **195 E VALLEY RIALTO, CA .92376** **N/A**
< 1/8 **RIALTO, CA 92376**
0.069 mi.
366 ft. **Site 13 of 18 in cluster A**

Relative:
Lower

Actual:
1069 ft.

HIST UST:
Region: STATE
Facility ID: 00000057683
Facility Type: Gas Station
Other Type: Not reported
Total Tanks: 0005
Contact Name: Not reported
Telephone: 7148771171
Owner Name: ROBERT W. CASTALOI
Owner Address: 195 E. VALLEY
Owner City,St,Zip: RIALTO, CA 92376

Tank Num: 001
Container Num: 1
Year Installed: Not reported
Tank Capacity: 00000000
Tank Used for: PRODUCT
Type of Fuel: UNLEADED
Tank Construction: Not reported
Leak Detection: Pressure Test

Tank Num: 002
Container Num: 2
Year Installed: Not reported
Tank Capacity: 00000000
Tank Used for: PRODUCT
Type of Fuel: REGULAR
Tank Construction: Not reported
Leak Detection: None

Tank Num: 003
Container Num: 3
Year Installed: Not reported
Tank Capacity: 00000000
Tank Used for: PRODUCT
Type of Fuel: DIESEL
Tank Construction: Not reported
Leak Detection: None

10-10 TRUCK STOP (Continued) **U001575515**

Tank Num: 004
Container Num: 4
Year Installed: Not reported
Tank Capacity: 00000000
Tank Used for: PRODUCT
Type of Fuel: DIESEL
Tank Construction: Not reported
Leak Detection: None

Tank Num: 005
Container Num: 5
Year Installed: Not reported
Tank Capacity: 00000000
Tank Used for: PRODUCT
Type of Fuel: UNLEADED
Tank Construction: Not reported
Leak Detection: None

A121 **10-10 TRUCK STOP** **SWEEPS UST** **S106922226**
West **195 E VALLEY RIALTO CA 92376** **N/A**
< 1/8 **RIALTO, CA 92376**
0.069 mi.
366 ft. **Site 14 of 18 in cluster A**

Relative:
Lower

Actual:
1069 ft.

SWEEPS UST:
Status: Active
Comp Number: 57683
Number: 9
Board Of Equalization: 44-021261
Referral Date: 07-28-92
Action Date: 07-28-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 1
Swrcb Tank Id: 36-000-057683-000001
Actv Date: 08-25-88
Capacity: 1
Tank Use: M.V. FUEL
Stg: P
Content: REG UNLEADED
Number Of Tanks: 5

Status: Active
Comp Number: 57683
Number: 9
Board Of Equalization: 44-021261
Referral Date: 07-28-92
Action Date: 07-28-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 2
Swrcb Tank Id: 36-000-057683-000002
Actv Date: 08-25-88
Capacity: 1
Tank Use: M.V. FUEL
Stg: P
Content: LEADED
Number Of Tanks: Not reported

10-10 TRUCK STOP (Continued) **S106922226**

Status:	Active
Comp Number:	57683
Number:	9
Board Of Equalization:	44-021261
Referral Date:	07-28-92
Action Date:	07-28-92
Created Date:	02-29-88
Tank Status:	A
Owner Tank Id:	3
Swrcb Tank Id:	36-000-057683-000003
Actv Date:	08-25-88
Capacity:	1
Tank Use:	M.V. FUEL
Stg:	P
Content:	DIESEL
Number Of Tanks:	Not reported

Status:	Active
Comp Number:	57683
Number:	9
Board Of Equalization:	44-021261
Referral Date:	07-28-92
Action Date:	07-28-92
Created Date:	02-29-88
Tank Status:	A
Owner Tank Id:	4
Swrcb Tank Id:	36-000-057683-000004
Actv Date:	08-25-88
Capacity:	1
Tank Use:	M.V. FUEL
Stg:	P
Content:	DIESEL
Number Of Tanks:	Not reported

Status:	Active
Comp Number:	57683
Number:	9
Board Of Equalization:	44-021261
Referral Date:	07-28-92
Action Date:	07-28-92
Created Date:	02-29-88
Tank Status:	A
Owner Tank Id:	5
Swrcb Tank Id:	36-000-057683-000005
Actv Date:	08-25-88
Capacity:	1
Tank Use:	M.V. FUEL
Stg:	P
Content:	REG UNLEADED
Number Of Tanks:	Not reported

A122 **10-10 TRUCK STOP** **CA FID UST** **S101591815**
West **195 E VALLEY RIALTO CA** **N/A**
< 1/8 **RIALTO, CA 92376**
0.069 mi.
366 ft. **Site 15 of 18 in cluster A**

Relative:
Lower

Actual:
1069 ft.

CA FID UST:

Facility ID:	36009174
Regulated By:	UTNKA
Regulated ID:	00057683
Cortese Code:	Not reported
SIC Code:	Not reported
Facility Phone:	Not reported
Mail To:	Not reported
Mailing Address:	195 E VALLEY RIALTO CA
Mailing Address 2:	Not reported
Mailing City,St,Zip:	RIALTO 92376
Contact:	Not reported
Contact Phone:	Not reported
DUNs Number:	Not reported
NPDES Number:	Not reported
EPA ID:	Not reported
Comments:	Not reported
Status:	Active

A123 **I-10 TRUCK STOP** **UST** **U004061579**
West **195 E VALLEY BLVD** **N/A**
< 1/8 **RIALTO, CA 92376**
0.069 mi.
366 ft. **Site 16 of 18 in cluster A**

Relative:
Lower

Actual:
1069 ft.

UST:

Facility ID:	86008453
Latitude:	34.0705
Longitude:	-117.37238

A124 **I-10 TRUCK STOP** **LUST** **S108087034**
West **195 VALLEY BOULEVARD EAST** **N/A**
< 1/8 **RIALTO, CA 92376**
0.069 mi.
366 ft. **Site 17 of 18 in cluster A**

Relative:
Lower

Actual:
1069 ft.

LUST:

Region:	STATE
Global Id:	T0607199509
Latitude:	34.070516
Longitude:	-117.372369
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	06/01/2007
Lead Agency:	SAN BERNARDINO COUNTY
Case Worker:	JC
Local Agency:	SAN BERNARDINO COUNTY
RB Case Number:	Not reported
LOC Case Number:	2006007
File Location:	Local Agency
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Gasoline, Diesel

I-10 TRUCK STOP (Continued) **S108087034**

Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0607199509
Contact Type: Local Agency Caseworker
Contact Name: JACKSON CRUTSINGER
Organization Name: SAN BERNARDINO COUNTY
Address: 620 SOUTH E STREET
City: SAN BERNARDINO
Email: jcrutsinger@sbcfire.org
Phone Number: Not reported

Global Id: T0607199509
Contact Type: Regional Board Caseworker
Contact Name: Ken Williams
Organization Name: SANTA ANA RWQCB (REGION 8)
Address: 3737 MAIN STREET, SUITE 500
City: RIVERSIDE
Email: kwilliams@waterboards.ca.gov
Phone Number: Not reported

Regulatory Activities:
Global Id: T0607199509
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

Global Id: T0607199509
Action Type: ENFORCEMENT
Date: 06/07/2007
Action: Closure/No Further Action Letter

Global Id: T0607199509
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

Global Id: T0607199509
Action Type: REMEDIATION
Date: 01/01/1950
Action: Not reported

A125 **I-10 TRUCK STOP** **HAZNET** **S113076873**
West **195 E VALLEY BLVD** **N/A**
< 1/8 **RIALTO, CA 92376**
0.071 mi.
377 ft. **Site 18 of 18 in cluster A**

Relative:
Lower

Actual:
1068 ft.

HAZNET:
Year: 2008
Gepaid: CAL000140570
Contact: JILL YI-MGR
Telephone: 9098771171
Mailing Name: Not reported
Mailing Address: 195 E VALLEY BLVD

I-10 TRUCK STOP (Continued) **S113076873**

Mailing City,St,Zip:	RIALTO, CA 923760000
Gen County:	Not reported
TSD EPA ID:	CAD982444481
TSD County:	Not reported
Waste Category:	Unspecified aqueous solution
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.357
Facility County:	San Bernardino

Year:	2005
Gepaid:	CAL000140570
Contact:	JILL YI-MGR
Telephone:	9098771171
Mailing Name:	Not reported
Mailing Address:	195 E VALLEY BLVD
Mailing City,St,Zip:	RIALTO, CA 923760000
Gen County:	Not reported
TSD EPA ID:	CAT080025711
TSD County:	Not reported
Waste Category:	Waste oil and mixed oil
Disposal Method:	Transfer Station
Tons:	2.08
Facility County:	San Bernardino

Year:	2004
Gepaid:	CAL000140570
Contact:	JILL YI-MGR
Telephone:	9098771171
Mailing Name:	Not reported
Mailing Address:	195 E VALLEY BLVD
Mailing City,St,Zip:	RIALTO, CA 923760000
Gen County:	Not reported
TSD EPA ID:	CAT080025711
TSD County:	Not reported
Waste Category:	Waste oil and mixed oil
Disposal Method:	Transfer Station
Tons:	22.88
Facility County:	San Bernardino

Year:	2003
Gepaid:	CAL000140570
Contact:	JILL YI-MGR
Telephone:	9098771171
Mailing Name:	Not reported
Mailing Address:	195 E VALLEY BLVD
Mailing City,St,Zip:	RIALTO, CA 923760000
Gen County:	Not reported
TSD EPA ID:	AZD980892731
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Disposal, Land Fill
Tons:	1
Facility County:	San Bernardino

Year:	2003
Gepaid:	CAL000140570

I-10 TRUCK STOP (Continued) **S113076873**

Contact:	JILL YI-MGR
Telephone:	9098771171
Mailing Name:	Not reported
Mailing Address:	195 E VALLEY BLVD
Mailing City,St,Zip:	RIALTO, CA 923760000
Gen County:	Not reported
TSD EPA ID:	CAT080025711
TSD County:	Not reported
Waste Category:	Waste oil and mixed oil
Disposal Method:	Transfer Station
Tons:	61.24
Facility County:	San Bernardino

Click this hyperlink while viewing on your computer to access
14 additional CA_HAZNET: record(s) in the EDR Site Report.

H126 **EDR US Hist Cleaners** **1014971997**
NE **1062 BEL CANTO CT** **N/A**
< 1/8 **COLTON, CA 92324**
0.072 mi.
381 ft. **Site 2 of 2 in cluster H**

Relative:
Higher

Actual:
1095 ft.

EDR Historical Cleaners:

Name:	LOPEZ CARPET CLEANING
Year:	2003
Address:	1062 BEL CANTO CT

I127 **O'REILLY AUTO PARTS #3681** **San Bern. Co. Permit** **S108724333**
NNE **1100 N PEPPER AVE** **N/A**
< 1/8 **COLTON, CA 92324**
0.088 mi.
463 ft. **Site 4 of 6 in cluster I**

Relative:
Higher

Actual:
1095 ft.

San Bern. Co. Permit:

Region:	SAN BERNARDINO
Facility ID:	FA0011114
Owner:	CSK AUTO, INC.
Permit Number:	PT0019218
Permit Category:	HAZARDOUS WASTE GENERATOR - 0-10 EMPLOYEES
Facility Status:	ACTIVE
Expiration Date:	09/30/2013

Region:	SAN BERNARDINO
Facility ID:	FA0011114
Owner:	CSK AUTO, INC.
Permit Number:	PT0019217
Permit Category:	HAZMAT HANDLER 0-10 EMPLOYEES (W/GEN PRMT)
Facility Status:	ACTIVE
Expiration Date:	09/30/2013

I128 **SCHNEIDER NATIONAL CORP** **HAZNET** **S112978990**
NNE **1100 N PEPPER AVE** **N/A**
< 1/8 **COLTON, CA 92324**
0.088 mi.
463 ft. **Site 5 of 6 in cluster I**

Relative:
Higher

Actual:
1095 ft.

HAZNET:

Year:	2009
Gepaid:	CAC002644071
Contact:	CHARLIE BURRETT
Telephone:	8002854237
Mailing Name:	Not reported
Mailing Address:	PO BOX 2545
Mailing City,St,Zip:	GREEN BAY, WI 543062545
Gen County:	Not reported
TSD EPA ID:	CAD028409019
TSD County:	Not reported
Waste Category:	Unspecified oil-containing waste
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	3
Facility County:	San Bernardino

I129 **KRAGEN AUTO PARTS** **FINDS** **1010694082**
NNE **1100 N. PEPPER AVENUE** **N/A**
< 1/8 **COLTON, CA 92324**
0.088 mi.
463 ft. **Site 6 of 6 in cluster I**

Relative:
Higher

Actual:
1095 ft.

FINDS:

Registry ID: 110033211389

Environmental Interest/Information System
UORS (California - Used Oil Recycling System). California Integrated Waste Management Board (CIWMB) helps communities establish and promote convenient collection opportunities for used oil and used oil filters.

L130 **INTOWN PROPERTIES INC** **HAZNET** **S112879159**
North **1081 TRUJILLO LN** **N/A**
< 1/8 **COLTON, CA 92324**
0.088 mi.
466 ft. **Site 3 of 3 in cluster L**

Relative:
Higher

Actual:
1123 ft.

HAZNET:

Year:	1997
Gepaid:	CAC001265736
Contact:	INTOWN PROPERTIES
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	2086 S E ST STE 204
Mailing City,St,Zip:	SAN BERNARDINO, CA 924080000
Gen County:	Not reported
TSD EPA ID:	Not reported
TSD County:	Not reported
Waste Category:	Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method:	Transfer Station

INTOWN PROPERTIES INC (Continued) **S112879159**

Tons: .0291
Facility County: San Bernardino

Year: 1997
Gepaid: CAC001265736
Contact: INTOWN PROPERTIES
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 2086 S E ST STE 204
Mailing City,St,Zip: SAN BERNARDINO, CA 924080000
Gen County: Not reported
TSD EPA ID: CAD000088252
TSD County: Not reported
Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method: Not reported
Tons: .0291
Facility County: San Bernardino

M131 **CUMMINS WEST INC** **CA FID UST** **1000300226**
West **161 E VALLEY BLVD** **HIST UST** **N/A**
< 1/8 **RIALTO, CA 92376** **SWEEPS UST**
0.089 mi. **San Bern. Co. Permit**
468 ft. **Site 1 of 31 in cluster M**

Relative:
Lower

Actual:
1067 ft.

CA FID UST:
Facility ID: 36002536
Regulated By: UTNKA
Regulated ID: 00008519
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: Not reported
Mail To: Not reported
Mailing Address: 161 E VALLEY BLVD
Mailing Address 2: Not reported
Mailing City,St,Zip: RIALTO 92376
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Active

HIST UST:
Region: STATE
Facility ID: 00000008519
Facility Type: Other
Other Type: CUMMINS DIESEL SALES
Total Tanks: 0003
Contact Name: PHILLIP WEST
Telephone: 7148770433
Owner Name: C.S.S. INVESTMENTS
Owner Address: 710 SILVER SPUR RD. SUITE #298
Owner City,St,Zip: ROLLING HILLS ESTATE, CA 90274

Tank Num: 001
Container Num: #1

CUMMINS WEST INC (Continued) **1000300226**

Year Installed: 1979
Tank Capacity: 00000250
Tank Used for: WASTE
Type of Fuel: WASTE OIL
Tank Construction: Not reported
Leak Detection: None

Tank Num: 002
Container Num: #2
Year Installed: 1979
Tank Capacity: 00000250
Tank Used for: WASTE
Type of Fuel: WASTE OIL
Tank Construction: Not reported
Leak Detection: None

Tank Num: 003
Container Num: 3
Year Installed: 1979
Tank Capacity: 00001500
Tank Used for: WASTE
Type of Fuel: WASTE OIL
Tank Construction: Not reported
Leak Detection: None

SWEEPS UST:
Status: Active
Comp Number: 8519
Number: 9
Board Of Equalization: 44-020070
Referral Date: 07-28-92
Action Date: 07-28-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: #1
Swrcb Tank Id: 36-000-008519-000001
Actv Date: 08-25-88
Capacity: 250
Tank Use: OIL
Stg: W
Content: WASTE OIL
Number Of Tanks: 2

Status: Active
Comp Number: 8519
Number: 9
Board Of Equalization: 44-020070
Referral Date: 07-28-92
Action Date: 07-28-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: #2
Swrcb Tank Id: 36-000-008519-000002
Actv Date: 08-25-88
Capacity: 250
Tank Use: OIL
Stg: W

CUMMINS WEST INC (Continued) **1000300226**

Content: WASTE OIL
Number Of Tanks: Not reported

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0005146
Owner: MCKEE, MARY
Permit Number: PT0001405
Permit Category: SPECIAL HANDLER
Facility Status: ACTIVE
Expiration Date: 09/30/2013

Region: SAN BERNARDINO
Facility ID: FA0005146
Owner: MCKEE, MARY
Permit Number: PT0001406
Permit Category: SPECIAL GENERATOR
Facility Status: ACTIVE
Expiration Date: 09/30/2013

M132 **CUMMINS CAL PACIFIC** **HAZNET** **S113002597**
West **161 EAST VALLEY BLVD** **N/A**
< 1/8 **RIALTO, CA 92376**
0.089 mi.
468 ft. **Site 2 of 31 in cluster M**

Relative:
Lower

Actual:
1067 ft.

HAZNET:
Year: 2000
Gepaid: CAD149773418
Contact: DAVID ARMSTRONG/OPS MANAGER
Telephone: 9098770433
Mailing Name: Not reported
Mailing Address: 3061 S. RIVERSIDE AVE.
Mailing City,St,Zip: BLOOMINGTON, CA 923160000
Gen County: Not reported
TSD EPA ID: CAD008252405
TSD County: Not reported
Waste Category: Unspecified organic liquid mixture
Disposal Method: Recycler
Tons: 0.22
Facility County: San Bernardino

Year: 2000
Gepaid: CAD149773418
Contact: DAVID ARMSTRONG/OPS MANAGER
Telephone: 9098770433
Mailing Name: Not reported
Mailing Address: 3061 S. RIVERSIDE AVE.
Mailing City,St,Zip: BLOOMINGTON, CA 923160000
Gen County: Not reported
TSD EPA ID: CAD982444481
TSD County: Not reported
Waste Category: Other inorganic solid waste
Disposal Method: Recycler
Tons: 0.92
Facility County: San Bernardino

CUMMINS CAL PACIFIC (Continued) **S113002597**

Year:	2000
Gepaid:	CAD149773418
Contact:	DAVID ARMSTRONG/OPS MANAGER
Telephone:	9098770433
Mailing Name:	Not reported
Mailing Address:	3061 S. RIVERSIDE AVE.
Mailing City,St,Zip:	BLOOMINGTON, CA 923160000
Gen County:	Not reported
TSD EPA ID:	Not reported
TSD County:	Not reported
Waste Category:	Waste oil and mixed oil
Disposal Method:	Recycler
Tons:	3.33
Facility County:	San Bernardino

Year:	1999
Gepaid:	CAD149773418
Contact:	CUMMINS CAL PACIFIC
Telephone:	7142536000
Mailing Name:	Not reported
Mailing Address:	3061 S. RIVERSIDE AVE.
Mailing City,St,Zip:	BLOOMINGTON, CA 923160000
Gen County:	Not reported
TSD EPA ID:	CAT080025711
TSD County:	Not reported
Waste Category:	Waste oil and mixed oil
Disposal Method:	Transfer Station
Tons:	10.4250
Facility County:	San Bernardino

Year:	1999
Gepaid:	CAD149773418
Contact:	CUMMINS CAL PACIFIC
Telephone:	7142536000
Mailing Name:	Not reported
Mailing Address:	3061 S. RIVERSIDE AVE.
Mailing City,St,Zip:	BLOOMINGTON, CA 923160000
Gen County:	Not reported
TSD EPA ID:	CAD097854541
TSD County:	Not reported
Waste Category:	Liquids with pH <= 2 with metals
Disposal Method:	Recycler
Tons:	.4200
Facility County:	San Bernardino

Click this hyperlink while viewing on your computer to access
38 additional CA_HAZNET: record(s) in the EDR Site Report.

N133 **EDR US Hist Auto Stat** **1015147724**
North **1086 BAUTISTA LN** **N/A**
< 1/8 **COLTON, CA 92324**
0.093 mi.
492 ft. **Site 1 of 3 in cluster N**

Relative:
Higher

Actual:
1128 ft.

EDR Historical Auto Stations:
Name: J & J AUTO CUSTOMIZING
Year: 2011
Address: 1086 BAUTISTA LN

M134 **CDL** **S107528686**
West **145 E VALLEY BLVD, #215 (AMERICAN INN)** **N/A**
< 1/8 **RIALTO, CA 92376**
0.097 mi.
511 ft. **Site 3 of 31 in cluster M**

Relative:
Lower

Actual:
1067 ft.

CDL:
Facility ID: 200206053
Lab Type: Illegal Drug Lab (L) - location where an illegal drug lab was operated or drug lab equipment and/or materials were stored.

O135 **HUD INTOWN PROPERTIES** **HAZNET** **S112896130**
North **1801 DE CARMEN DR** **N/A**
< 1/8 **COLTON, CA 92324**
0.101 mi.
532 ft. **Site 1 of 5 in cluster O**

Relative:
Higher

Actual:
1111 ft.

HAZNET:
Year: 1998
Gepaid: CAC001498240
Contact: HUD
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 2086 S E ST STE 204
Mailing City,St,Zip: SAN BERNARDINO, CA 924080000
Gen County: Not reported
TSD EPA ID: CAD982444481
TSD County: Not reported
Waste Category: Household waste
Disposal Method: Transfer Station
Tons: .0125
Facility County: San Bernardino

N136 **HUD** **HAZNET** **S112880342**
North **1927 DE CARMEN DR** **N/A**
< 1/8 **COLTON, CA 92324**
0.102 mi.
541 ft. **Site 2 of 3 in cluster N**

Relative:
Higher

Actual:
1128 ft.

HAZNET:
Year: 1997
Gepaid: CAC001299888
Contact: HUD
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: INTOWN PROPERTIES

HUD (Continued) **S112880342**

Mailing City,St,Zip: RANCHO CUCAMONGA, CA 917300000
Gen County: Not reported
TSD EPA ID: CAD000088252
TSD County: Not reported
Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method: Transfer Station
Tons: .0041
Facility County: San Bernardino

N137 **HUD INTOWN PROPERTIES** **HAZNET** **S112896069**
North **1897 DE CARMEN DR** **N/A**
< 1/8 **COLTON, CA 92324**
0.102 mi.
541 ft. **Site 3 of 3 in cluster N**

Relative:
Higher

Actual:
1127 ft.

HAZNET:
Year: 1998
Gepaid: CAC001497344
Contact: HUD
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 2086 S E ST STE 204
Mailing City,St,Zip: SAN BERNARDINO, CA 924080000
Gen County: Not reported
TSD EPA ID: CAD982444481
TSD County: Not reported
Waste Category: Household waste
Disposal Method: Transfer Station
Tons: .0625
Facility County: San Bernardino

M138 **EDR US Hist Auto Stat** **1015197599**
West **128 E VALLEY BLVD** **N/A**
< 1/8 **RIALTO, CA 92376**
0.105 mi.
553 ft. **Site 4 of 31 in cluster M**

Relative:
Lower

Actual:
1066 ft.

EDR Historical Auto Stations:
Name: HERNANDEZ AUTO REPAIR
Year: 2003
Address: 128 E VALLEY BLVD

P139 **CHMIRS** **S109041249**
SE **9900 PEPPER ST** **N/A**
< 1/8 **COLTON, CA**
0.106 mi.
561 ft. **Site 1 of 2 in cluster P**

Relative:
Lower

Actual:
1063 ft.

CHMIRS:
OES Incident Number: 06-1783
OES notification: 03/26/2006
OES Date: Not reported
OES Time: Not reported
Incident Date: Not reported
Date Completed: **Not reported**

(Continued) **S109041249**

Property Use:	Not reported	
Agency Id Number:	Not reported	
Agency Incident Number:	Not reported	
Time Notified:	Not reported	
Time Completed:	Not reported	
Surrounding Area:	Not reported	
Estimated Temperature:	Not reported	
Property Management:	Not reported	
Special Studies 1:	Not reported	
Special Studies 2:	Not reported	
Special Studies 3:	Not reported	
Special Studies 4:	Not reported	
Special Studies 5:	Not reported	
Special Studies 6:	Not reported	
More Than Two Substances Involved?:		Not reported
Resp Agncy Personel # Of Decontaminated:		Not reported
Responding Agency Personel # Of Injuries:		Not reported
Responding Agency Personel # Of Fatalities:		Not reported
Others Number Of Decontaminated:		Not reported
Others Number Of Injuries:		Not reported
Others Number Of Fatalities:		Not reported
Vehicle Make/year:	Not reported	
Vehicle License Number:	Not reported	
Vehicle State:	Not reported	
Vehicle Id Number:	Not reported	
CA/DOT/PUC/ICC Number:	Not reported	
Company Name:	Not reported	
Reporting Officer Name/ID:	Not reported	
Report Date:	Not reported	
Comments:	Not reported	
Facility Telephone:	Not reported	
Waterway Involved:	Not reported	
Waterway:	Not reported	
Spill Site:	Not reported	
Cleanup By:	Unknown	
Containment:	Not reported	
What Happened:	Not reported	
Type:	Not reported	
Measure:	Not reported	
Other:	Not reported	
Date/Time:	Not reported	
Year:	2006	
Agency:	UPRR	
Incident Date:	3/26/2006 12:00:00 AM	
Admin Agency:	San Bernardino County Health Department	
Amount:	Not reported	
Contained:	Unknown	
Site Type:	Rail Road	
E Date:	Not reported	
Substance:	Train Derailment	
Quantity Released:	Not reported	
BBLS:	0	
Cups:	0	
CUFT:	0	
Gallons:	0.000000	
Grams:	0	
Pounds:	0	

(Continued) **S109041249**

Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	Per caller, cause of the derailment is unknown. 2 cars derailed containing liquid petroleum gas. No release.

Q140 **EDR US Hist Cleaners** **1014977248**
NNE **1130 N PEPPER AVE** **N/A**
< 1/8 **COLTON, CA 92324**
0.110 mi.
583 ft. **Site 1 of 7 in cluster Q**

Relative: **Higher**

Actual: **1098 ft.**

EDR Historical Cleaners:

Name:	DRY CLEAN EXPRESS
Year:	2010
Address:	1130 N PEPPER AVE
Name:	DRY CLEAN EXPRESS
Year:	2011
Address:	1130 N PEPPER AVE
Name:	DRY CLEAN EXPRESS
Year:	2012
Address:	1130 N PEPPER AVE

P141 **SOUTHERN CALIF. BISHOPS CENTRA** **HIST UST** **U001574701**
SE **9908 PEPPER AVE** **SWEEPS UST** **N/A**
< 1/8 **COLTON, CA 92324**
0.113 mi.
595 ft. **Site 2 of 2 in cluster P**

Relative: **Lower**

Actual: **1063 ft.**

HIST UST:

Region:	STATE
Facility ID:	00000067062
Facility Type:	Other
Other Type:	CHURCH
Total Tanks:	0003
Contact Name:	Not reported
Telephone:	7148240486
Owner Name:	CHURCH OF JESUS CHRIST OF LATT
Owner Address:	9908 PEPPER AVE.
Owner City,St,Zip:	COLTON, CA 92324
Tank Num:	001
Container Num:	6D4
Year Installed:	1977
Tank Capacity:	00000250
Tank Used for:	WASTE
Type of Fuel:	5

SOUTHERN CALIF. BISHOPS CENTRA (Continued) **U001574701**

Tank Construction: Unkown centimeters
Leak Detection: Visual, Stock Inventor

Tank Num: 002
Container Num: 6D1
Year Installed: 1977
Tank Capacity: 00012000
Tank Used for: PRODUCT
Type of Fuel: DIESEL
Tank Construction: Not reported
Leak Detection: Visual, Stock Inventor

Tank Num: 003
Container Num: 6D2
Year Installed: 1977
Tank Capacity: 00006000
Tank Used for: PRODUCT
Type of Fuel: DIESEL
Tank Construction: Not reported
Leak Detection: Visual, Stock Inventor

SWEEPS UST:
Status: Active
Comp Number: 67062
Number: 9
Board Of Equalization: 44-021460
Referral Date: 08-28-91
Action Date: 08-28-91
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 6D2
Swrcb Tank Id: 36-000-067062-000003
Actv Date: 06-28-88
Capacity: 6000
Tank Use: M.V. FUEL
Stg: P
Content: DIESEL
Number Of Tanks: 1

M142 **JUST GAS INC** **CA FID UST** **S101590968**
West **102 E VALLEY BLVD** **SWEEPS UST** **N/A**
< 1/8 **RIALTO, CA 92376**
0.118 mi.
623 ft. **Site 5 of 31 in cluster M**

Relative:
Lower

Actual:
1065 ft.

CA FID UST:
Facility ID: 36000394
Regulated By: UTNKI
Regulated ID: 00051115
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: Not reported
Mail To: Not reported
Mailing Address: 102 E VALLEY BLVD
Mailing Address 2: Not reported
Mailing City,St,Zip: RIALTO 92376
Contact: Not reported

JUST GAS INC (Continued) **S101590968**

Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Inactive

SWEEPS UST:
Status: Not reported
Comp Number: 51115
Number: Not reported
Board Of Equalization: 44-021150
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 36-000-051115-000001
Actv Date: Not reported
Capacity: 12000
Tank Use: M.V. FUEL
Stg: PRODUCT
Content: DIESEL
Number Of Tanks: 6

Status: Not reported
Comp Number: 51115
Number: Not reported
Board Of Equalization: 44-021150
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 36-000-051115-000002
Actv Date: Not reported
Capacity: 280
Tank Use: OIL
Stg: WASTE
Content: WASTE OIL
Number Of Tanks: Not reported

Status: Not reported
Comp Number: 51115
Number: Not reported
Board Of Equalization: 44-021150
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 36-000-051115-000003
Actv Date: Not reported
Capacity: 4000
Tank Use: M.V. FUEL
Stg: PRODUCT
Content: LEADED

JUST GAS INC (Continued) **S101590968**

Number Of Tanks: Not reported

Status: Not reported
Comp Number: 51115
Number: Not reported
Board Of Equalization: 44-021150
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 36-000-051115-000004
Actv Date: Not reported
Capacity: 4000
Tank Use: M.V. FUEL
Stg: PRODUCT
Content: LEADED
Number Of Tanks: Not reported

Status: Not reported
Comp Number: 51115
Number: Not reported
Board Of Equalization: 44-021150
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 36-000-051115-000005
Actv Date: Not reported
Capacity: 6000
Tank Use: M.V. FUEL
Stg: PRODUCT
Content: LEADED
Number Of Tanks: Not reported

Status: Not reported
Comp Number: 51115
Number: Not reported
Board Of Equalization: 44-021150
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 36-000-051115-000006
Actv Date: Not reported
Capacity: 10000
Tank Use: M.V. FUEL
Stg: PRODUCT
Content: REG UNLEADED
Number Of Tanks: Not reported

M143 **RIALTO, CITY OF (TEXACO)** **LUST** **S111760398**
West **102 E VALLEY BLVD** **N/A**
< 1/8 **RIALTO, CA 92376**
0.118 mi.
623 ft. **Site 6 of 31 in cluster M**

Relative:
Lower

Actual:
1065 ft.

LUST:

Region:	STATE
Global Id:	T0607100101
Latitude:	34.0705954
Longitude:	-117.3700098
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	08/25/1992
Lead Agency:	SAN BERNARDINO COUNTY
Case Worker:	DG4
Local Agency:	Not reported
RB Case Number:	083600955T
LOC Case Number:	91033
File Location:	Local Agency
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607100101
Contact Type:	Regional Board Caseworker
Contact Name:	VALERIE JAHN-BULL
Organization Name:	SANTA ANA RWQCB (REGION 8)
Address:	3737 MAIN STREET, SUITE 500
City:	RIVERSIDE
Email:	vjahn-bull@waterboards.ca.gov
Phone Number:	9517824903

Regulatory Activities:

Global Id:	T0607100101
Action Type:	ENFORCEMENT
Date:	08/25/1992
Action:	Closure/No Further Action Letter

Global Id:	T0607100101
Action Type:	Other
Date:	01/01/1950
Action:	Leak Stopped

Global Id:	T0607100101
Action Type:	Other
Date:	01/01/1950
Action:	Leak Discovery

Global Id:	T0607100101
Action Type:	Other
Date:	01/01/1950
Action:	Leak Reported

M144
West
< 1/8
0.119 mi.
628 ft.

CHEVRON STATION #96969
101 EAST VALLEY BLVD
RIALTO, CA 92376

Site 7 of 31 in cluster M

HAZNET **S113043122**
N/A

Relative:
Lower

Actual:
1065 ft.

HAZNET:

Year:	1997
Gepaid:	CAL000055527
Contact:	R L COPELAND
Telephone:	9098747638
Mailing Name:	Not reported
Mailing Address:	101 E VALLEY BLVD
Mailing City,St,Zip:	RIALTO, CA 923760000
Gen County:	Not reported
TSD EPA ID:	CAD008302903
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues 10 percent or more
Disposal Method:	Recycler
Tons:	.2293
Facility County:	San Bernardino

Year:	1994
Gepaid:	CAL000055527
Contact:	R L COPELAND
Telephone:	9098747638
Mailing Name:	Not reported
Mailing Address:	101 E VALLEY BLVD
Mailing City,St,Zip:	RIALTO, CA 923760000
Gen County:	Not reported
TSD EPA ID:	CAT080013352
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues less than 10 percent
Disposal Method:	Recycler
Tons:	.2293
Facility County:	San Bernardino

Year:	1993
Gepaid:	CAL000055527
Contact:	R L COPELAND
Telephone:	9098747638
Mailing Name:	Not reported
Mailing Address:	101 E VALLEY BLVD
Mailing City,St,Zip:	RIALTO, CA 923760000
Gen County:	Not reported
TSD EPA ID:	CAT080025711
TSD County:	Not reported
Waste Category:	Waste oil and mixed oil
Disposal Method:	Recycler
Tons:	0.2293
Facility County:	San Bernardino

M145
West
< 1/8
0.119 mi.
628 ft.

CHEVRON 96969
101 EAST VALLEY BLVD
RIALTO, CA 92376

Site 8 of 31 in cluster M

HAZNET **S113094762**
N/A

Relative:
Lower

Actual:
1065 ft.

HAZNET:

Year:	1999
Gepaid:	CAL000179093
Contact:	CHERVON PRODUCTS CO
Telephone:	9258425931
Mailing Name:	Not reported
Mailing Address:	PO BOX 6004
Mailing City,St,Zip:	SAN RAMON, CA 945830000
Gen County:	Not reported
TSD EPA ID:	CAD008302903
TSD County:	Not reported
Waste Category:	Tank bottom waste
Disposal Method:	Recycler
Tons:	6.2550
Facility County:	San Bernardino

Year:	1999
Gepaid:	CAL000179093
Contact:	CHERVON PRODUCTS CO
Telephone:	9258425931
Mailing Name:	Not reported
Mailing Address:	PO BOX 6004
Mailing City,St,Zip:	SAN RAMON, CA 945830000
Gen County:	Not reported
TSD EPA ID:	CAD982484933
TSD County:	Not reported
Waste Category:	Other empty containers 30 gallons or more
Disposal Method:	Recycler
Tons:	1.0000
Facility County:	San Bernardino

Year:	1999
Gepaid:	CAL000179093
Contact:	CHERVON PRODUCTS CO
Telephone:	9258425931
Mailing Name:	Not reported
Mailing Address:	PO BOX 6004
Mailing City,St,Zip:	SAN RAMON, CA 945830000
Gen County:	Not reported
TSD EPA ID:	CAD982484933
TSD County:	Not reported
Waste Category:	Other empty containers 30 gallons or more
Disposal Method:	Disposal, Other
Tons:	11.2500
Facility County:	San Bernardino

Year:	1999
Gepaid:	CAL000179093
Contact:	CHERVON PRODUCTS CO
Telephone:	9258425931
Mailing Name:	Not reported
Mailing Address:	PO BOX 6004
Mailing City,St,Zip:	SAN RAMON, CA 945830000

CHEVRON 96969 (Continued) **S113094762**

Gen County:	Not reported
TSD EPA ID:	CAD982484933
TSD County:	Not reported
Waste Category:	Empty containers less than 30 gallons
Disposal Method:	Disposal, Other
Tons:	4.5000
Facility County:	San Bernardino
Year:	1998
Gepaid:	CAL000179093
Contact:	CHERVON PRODUCTS CO
Telephone:	9258425931
Mailing Name:	Not reported
Mailing Address:	PO BOX 6004
Mailing City,St,Zip:	SAN RAMON, CA 945830000
Gen County:	Not reported
TSD EPA ID:	CAD008302903
TSD County:	Not reported
Waste Category:	Hydrocarbon solvents (benzene, hexane, Stoddard, Etc.)
Disposal Method:	Recycler
Tons:	.3336
Facility County:	San Bernardino

Click this hyperlink while viewing on your computer to access additional CA_HAZNET: detail in the EDR Site Report.

M146 **CHEVRON STATION #6969** **CA FID UST** **S101591821**
West **101 E VALLEY BLVD** **N/A**
< 1/8 **RIALTO, CA 92376**
0.119 mi.
628 ft. **Site 9 of 31 in cluster M**

Relative:
Lower

Actual:
1065 ft.

CA FID UST:

Facility ID:	36009223
Regulated By:	UTNKA
Regulated ID:	00062941
Cortese Code:	Not reported
SIC Code:	Not reported
Facility Phone:	Not reported
Mail To:	Not reported
Mailing Address:	101 E VALLEY BLVD
Mailing Address 2:	Not reported
Mailing City,St,Zip:	RIALTO 92376
Contact:	Not reported
Contact Phone:	Not reported
DUNs Number:	Not reported
NPDES Number:	Not reported
EPA ID:	Not reported
Comments:	Not reported
Status:	Active

M147 **96969** **LUST** **U001575517**
West **101 E VALLEY BLVD** **HIST UST** **N/A**
< 1/8 **RIALTO, CA 92376** **San Bern. Co. Permit**
0.119 mi.
628 ft. **Site 10 of 31 in cluster M**

Relative:
Lower

Actual:
1065 ft.

LUST:

Region:	STATE
Global Id:	T0607100325
Latitude:	34.070107
Longitude:	-117.369794
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	04/28/2000
Lead Agency:	SAN BERNARDINO COUNTY
Case Worker:	CB
Local Agency:	SAN BERNARDINO COUNTY
RB Case Number:	083602453T
LOC Case Number:	92045
File Location:	Local Agency
Potential Media Affect:	Well used for drinking water supply
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607100325
Contact Type:	Local Agency Caseworker
Contact Name:	CURTIS BRUNDAGE
Organization Name:	SAN BERNARDINO COUNTY
Address:	620 S. E STREET
City:	SAN BERNARDINO
Email:	cbrundage@sbcfire.org
Phone Number:	Not reported

Global Id:	T0607100325
Contact Type:	Regional Board Caseworker
Contact Name:	TOM E. MBEKE-EKANEM
Organization Name:	SANTA ANA RWQCB (REGION 8)
Address:	3737 MAIN STREET, SUITE 500
City:	RIVERSIDE
Email:	tmbeke-ekanem@waterboards.ca.gov
Phone Number:	9513202007

Regulatory Activities:

Global Id:	T0607100325
Action Type:	ENFORCEMENT
Date:	04/28/2000
Action:	Closure/No Further Action Letter

Global Id:	T0607100325
Action Type:	Other
Date:	01/01/1950
Action:	Leak Stopped

Global Id:	T0607100325
Action Type:	Other
Date:	01/01/1950

96969 (Continued) **U001575517**

Action: Leak Discovery

Global Id: T0607100325
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

HIST UST:
Region: STATE
Facility ID: 00000062941
Facility Type: Gas Station
Other Type: Not reported
Total Tanks: 0004
Contact Name: COPELAND,RAYMOND L
Telephone: 7148775083
Owner Name: CHEVRON U.S.A. INC.
Owner Address: 575 MARKET
Owner City,St,Zip: SAN FRANCISCO, CA 94105

Tank Num: 001
Container Num: 1
Year Installed: 1961
Tank Capacity: 00010000
Tank Used for: PRODUCT
Type of Fuel: Not reported
Tank Construction: 0000250 unknown
Leak Detection: Stock Inventor

Tank Num: 002
Container Num: 2
Year Installed: 1961
Tank Capacity: 00008000
Tank Used for: PRODUCT
Type of Fuel: Not reported
Tank Construction: 0000250 unknown
Leak Detection: Stock Inventor

Tank Num: 003
Container Num: 3
Year Installed: 1961
Tank Capacity: 00004000
Tank Used for: PRODUCT
Type of Fuel: Not reported
Tank Construction: 0000170 unknown
Leak Detection: Stock Inventor

Tank Num: 004
Container Num: 4
Year Installed: 1961
Tank Capacity: 00000550
Tank Used for: WASTE
Type of Fuel: Not reported
Tank Construction: 0000100 unknown
Leak Detection: Stock Inventor

96969 (Continued) **U001575517**

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0001899
Owner: CHEVRON PRODUCTS CO
Permit Number: PT0012202
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0001899
Owner: CHEVRON PRODUCTS CO
Permit Number: PT0012203
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0001899
Owner: CHEVRON PRODUCTS CO
Permit Number: PT0012204
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0001899
Owner: CHEVRON PRODUCTS CO
Permit Number: PT0002003
Permit Category: HAZMAT HANDLER - UST ONLY
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0001899
Owner: CHEVRON PRODUCTS CO
Permit Number: PT0025160
Permit Category: WASTE INCIDENTAL UST OPERATION ONLY
Facility Status: ACTIVE
Expiration Date: 10/31/2013

M148 **CHEVRON STATION #6969** **SWEEPS UST** **U003938912**
West **101 E VALLEY BLVD** **N/A**
< 1/8 **RIALTO, CA 92376**
0.119 mi.
628 ft. **Site 11 of 31 in cluster M**

Relative:
Lower

Actual:
1065 ft.

SWEEPS UST:
Status: Active
Comp Number: 62941
Number: 9
Board Of Equalization: 44-021353
Referral Date: 07-28-92
Action Date: 07-28-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 1

CHEVRON STATION #6969 (Continued) **U003938912**

Swrcb Tank Id: 36-000-062941-000001
Actv Date: 08-25-88
Capacity: 10000
Tank Use: UNKNOWN
Stg: P
Content: Not reported
Number Of Tanks: 4

Status: Active
Comp Number: 62941
Number: 9
Board Of Equalization: 44-021353
Referral Date: 07-28-92
Action Date: 07-28-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 2
Swrcb Tank Id: 36-000-062941-000002
Actv Date: 08-25-88
Capacity: 8000
Tank Use: UNKNOWN
Stg: P
Content: Not reported
Number Of Tanks: Not reported

Status: Active
Comp Number: 62941
Number: 9
Board Of Equalization: 44-021353
Referral Date: 07-28-92
Action Date: 07-28-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 3
Swrcb Tank Id: 36-000-062941-000003
Actv Date: 08-25-88
Capacity: 4000
Tank Use: UNKNOWN
Stg: P
Content: Not reported
Number Of Tanks: Not reported

Status: Active
Comp Number: 62941
Number: 9
Board Of Equalization: 44-021353
Referral Date: 07-28-92
Action Date: 07-28-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 4
Swrcb Tank Id: 36-000-062941-000004
Actv Date: 08-25-88
Capacity: 550
Tank Use: UNKNOWN
Stg: W
Content: Not reported

CHEVRON STATION #6969 (Continued) **U003938912**

Number Of Tanks: Not reported

M149 **CHEVRON STATION NO 96969** **RCRA-SQG** **1005904248**
West **101 E VALLEY BLVD** **FINDS** **CAR000118208**
< 1/8 **RIALTO, CA 92376** **HAZNET**
0.119 mi.
628 ft. **Site 12 of 31 in cluster M**

Relative:
Lower

Actual:
1065 ft.

RCRA-SQG:

Date form received by agency:	05/16/2002
Facility name:	CHEVRON STATION NO 96969
Facility address:	101 E VALLEY BLVD RIALTO, CA 923767721
EPA ID:	CAR000118208
Mailing address:	P O BOX 6004 SAN RAMON, CA 94583
Contact:	KATHY NORRIS
Contact address:	P O BOX 6004 SAN RAMON, CA 94583
Contact country:	US
Contact telephone:	(925) 842-5931
Contact email:	Not reported
EPA Region:	09
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	CHEVRON PRODUCTS CO
Owner/operator address:	P O BOX 6004 SAN RAMON, CA 94583
Owner/operator country:	Not reported
Owner/operator telephone:	(925) 842-5931
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

CHEVRON STATION NO 96969 (Continued) **1005904248**

Hazardous Waste Summary:
Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D018
Waste name: BENZENE

Violation Status: No violations found

FINDS:

Registry ID: 110012544933

Environmental Interest/Information System
California Hazardous Waste Tracking System - Datamart (HWTS-DATAMART) provides California with information on hazardous waste shipments for generators, transporters, and treatment, storage, and disposal facilities.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZNET:
Year: 2011
Gepaid: CAR000118208
Contact: Waste Tracking Personnel
Telephone: 8773866044
Mailing Name: Not reported
Mailing Address: PO BOX 6004
Mailing City,St,Zip: SAN RAMON, CA 945830000
Gen County: Not reported
TSD EPA ID: CAD044429835
TSD County: Not reported
Waste Category: Unspecified organic liquid mixture
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.187
Facility County: San Bernardino

Year: 2011
Gepaid: CAR000118208
Contact: Waste Tracking Personnel
Telephone: 8773866044
Mailing Name: Not reported
Mailing Address: PO BOX 6004
Mailing City,St,Zip: SAN RAMON, CA 945830000

CHEVRON STATION NO 96969 (Continued) **1005904248**

Gen County: Not reported
TSD EPA ID: CAD044429835
TSD County: Not reported
Waste Category: Unspecified oil-containing waste
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.04
Facility County: San Bernardino

Year: 2011
Gepaid: CAR000118208
Contact: Waste Tracking Personnel
Telephone: 8773866044
Mailing Name: Not reported
Mailing Address: PO BOX 6004
Mailing City,St,Zip: SAN RAMON, CA 945830000
Gen County: Not reported
TSD EPA ID: CAD008302903
TSD County: Not reported
Waste Category: Aqueous solution with total organic residues less than 10 percent
Disposal Method: Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons: 1.848
Facility County: San Bernardino

Year: 2011
Gepaid: CAR000118208
Contact: Waste Tracking Personnel
Telephone: 8773866044
Mailing Name: Not reported
Mailing Address: PO BOX 6004
Mailing City,St,Zip: SAN RAMON, CA 945830000
Gen County: Not reported
TSD EPA ID: CAD982444481
TSD County: Not reported
Waste Category: Other organic solids
Disposal Method: Other Treatment
Tons: 0.0075
Facility County: San Bernardino

Year: 2010
Gepaid: CAR000118208
Contact: Waste Tracking Personnel
Telephone: 8773866044
Mailing Name: Not reported
Mailing Address: PO BOX 6004
Mailing City,St,Zip: SAN RAMON, CA 945830000
Gen County: Not reported
TSD EPA ID: CAD982444481
TSD County: Not reported
Waste Category: Other organic solids
Disposal Method: Other Treatment
Tons: 0.0125
Facility County: San Bernardino

CHEVRON STATION NO 96969 (Continued) **1005904248**

Click this hyperlink while viewing on your computer to access
14 additional CA_HAZNET: record(s) in the EDR Site Report.

M150
West
< 1/8
0.119 mi.
628 ft.

101 E VALLEY BLVD
RIALTO, CA 92376

Site 13 of 31 in cluster M

EDR US Hist Auto Stat **1015125186**
N/A

Relative:
Lower

Actual:
1065 ft.

EDR Historical Auto Stations:

Name:	GATEWAY CHEVRON
Year:	1999
Address:	101 E VALLEY BLVD
Name:	CHEVRON STATIONS INCORPORATED
Year:	2000
Address:	101 E VALLEY BLVD
Name:	CHEVRON STATIONS INC
Year:	2001
Address:	101 E VALLEY BLVD
Name:	CHEVRON STATIONS INC
Year:	2003
Address:	101 E VALLEY BLVD
Name:	CHEVRON STATION INC
Year:	2004
Address:	101 E VALLEY BLVD
Name:	CHEVRON STATIONS INC
Year:	2005
Address:	101 E VALLEY BLVD
Name:	CHEVRONTEXACO CORP
Year:	2006
Address:	101 E VALLEY BLVD
Name:	CHEVRON CORP
Year:	2008
Address:	101 E VALLEY BLVD
Name:	CHEVRON STATION
Year:	2009
Address:	101 E VALLEY BLVD
Name:	CHEVRON
Year:	2010
Address:	101 E VALLEY BLVD
Name:	CHEVRON
Year:	2011
Address:	101 E VALLEY BLVD
Name:	CHEVRON
Year:	2012
Address:	101 E VALLEY BLVD

M151 **CHEVRON NO 96969** **RCRA-LQG** **1007200511**
West **101 E VALLEY BLVD.** **CAP000067413**
< 1/8 **RIALTO, CA 92376**
0.119 mi.
628 ft. **Site 14 of 31 in cluster M**

Relative:
Lower

Actual:
1065 ft.

RCRA-LQG:

Date form received by agency:	10/12/2000
Facility name:	CHEVRON NO 96969
Site name:	CHEVRON 96969
Facility address:	101 E VALLEY BLVD. RIALTO, CA 92376
EPA ID:	CAP000067413
Mailing address:	PO BOX 6004 SAN RAMON, CA 94583
Contact:	KATHY L. NORRIS
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(925) 842-5931
Contact email:	Not reported
EPA Region:	09
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Violation Status: No violations found

M152 **CHEVRON STATION #6969** **UST** **U004061578**
West **101 E VALLEY BLVD** **N/A**
< 1/8 **RIALTO, CA 92376**
0.119 mi.
628 ft. **Site 15 of 31 in cluster M**

Relative:
Lower

Actual:
1065 ft.

UST:
Facility ID: 86008451
Latitude: 34.10923
Longitude: -117.37651

O153 **HUD INTOWN PROPERTIES** **HAZNET** **S112899035**
NNE **1174 EXPRESS CIR** **N/A**
< 1/8 **COLTON, CA 92324**
0.123 mi.
648 ft. **Site 2 of 5 in cluster O**

Relative:
Higher

Actual:
1112 ft.

HAZNET:
Year: 1998
Gepaid: CAC002125832
Contact: HUD
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 2086 S E T STE 204
Mailing City,St,Zip: SAN BERNARDINO, CA 924080000
Gen County: Not reported
TSD EPA ID: CAD028409019
TSD County: Not reported
Waste Category: Household waste
Disposal Method: Treatment, Tank
Tons: .0025
Facility County: San Bernardino

Year: 1998
Gepaid: CAC002125832
Contact: HUD
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 2086 S E T STE 204
Mailing City,St,Zip: SAN BERNARDINO, CA 924080000
Gen County: Not reported
TSD EPA ID: CAD028409019
TSD County: Not reported
Waste Category: Household waste
Disposal Method: Transfer Station
Tons: .0075
Facility County: San Bernardino

Q154 **FOOD 4 LESS #786** **SWRCY** **S108207042**
NNE **1150 N PEPPER AVE** **San Bern. Co. Permit** **N/A**
1/8-1/4 **COLTON, CA 92324**
0.126 mi.
663 ft. **Site 2 of 7 in cluster Q**

Relative:
Higher

Actual:
1102 ft.

SWRCY:
Reg Id: 155990
Cert Id: RC155990.001
Org Or Agency Reg Id: 151891

FOOD 4 LESS #786 (Continued) **S108207042**

Organization Or Agency Name:	rePLANET LLC
Mailing Address:	150 Klug Cir
Mailing City:	Corona
Mailing State:	CA
Mailing Zip Code:	92880
Website:	http://www.replanetusa.com
Email:	Not reported
Phone Number:	(951) 520-1700
Grand Father:	N
Rural:	N
Operation Begin Date:	05/01/2012
Aluminium:	Y
Glass:	Y
Plastic:	Y
Bimetal:	Y
Agency:	N/A
Monday Hours Of Operation:	CLOSED
Tuesday Hours Of Operation:	10:00 am - 4:30 pm; Closed 1:00 pm - 1:30 pm
Wednesday Hours Of Operation:	10:00 am - 4:30 pm; Closed 1:00 pm - 1:30 pm
Thursday Hours Of Operation:	10:00 am - 4:30 pm; Closed 1:00 pm - 1:30 pm
Friday Hours Of Operation:	10:00 am - 4:30 pm; Closed 1:00 pm - 1:30 pm
Saturday Hours Of Operation:	10:00 am - 4:30 pm; Closed 1:00 pm - 1:30 pm
Sunday Hours Of Operation:	CLOSED

San Bern. Co. Permit:

Region:	SAN BERNARDINO
Facility ID:	FA0012685
Owner:	RALPHS GROCERY COMPANY
Permit Number:	PT0022117
Permit Category:	CONDITIONALLY EXEMPT SMALL QUANTITY GENERATOR
Facility Status:	ACTIVE
Expiration Date:	10/31/2013

Region:	SAN BERNARDINO
Facility ID:	FA0012685
Owner:	RALPHS GROCERY COMPANY
Permit Number:	PT0022116
Permit Category:	HAZMAT HANDLER 26-50 EMPLOYEES
Facility Status:	ACTIVE
Expiration Date:	10/31/2013

Q155 **FOOD 4 LESS #786** **HAZNET** **S113130507**
NNE **1150 N PEPPER AVE** **N/A**
1/8-1/4 **COLTON, CA 92324**
0.126 mi.
663 ft. **Site 3 of 7 in cluster Q**

Relative:
Higher

Actual:
1102 ft.

HAZNET:

Year:	2009
Gepaid:	CAL000278830
Contact:	MELISSA PENA
Telephone:	3108849000
Mailing Name:	Not reported
Mailing Address:	1100 W ARTESIA BLVD
Mailing City,St,Zip:	COMPTON, CA 902200000
Gen County:	Not reported
TSD EPA ID:	CAD008364432

FOOD 4 LESS #786 (Continued) **S113130507**

TSD County: Not reported
Waste Category: Off-specification, aged or surplus organics
Disposal Method: Fuel Blending Prior To Energy Recovery At Another Site
Tons: 0.007
Facility County: San Bernardino

Year: 2009
Gepaid: CAL000278830
Contact: MELISSA PENA
Telephone: 3108849000
Mailing Name: Not reported
Mailing Address: 1100 W ARTESIA BLVD
Mailing City,St,Zip: COMPTON, CA 902200000
Gen County: Not reported
TSD EPA ID: CAD008364432
TSD County: Not reported
Waste Category: Not reported
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: Not reported
Facility County: San Bernardino

Year: 2009
Gepaid: CAL000278830
Contact: MELISSA PENA
Telephone: 3108849000
Mailing Name: Not reported
Mailing Address: 1100 W ARTESIA BLVD
Mailing City,St,Zip: COMPTON, CA 902200000
Gen County: Not reported
TSD EPA ID: CAD008302903
TSD County: Not reported
Waste Category: Other organic solids
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.13
Facility County: San Bernardino

Year: 2009
Gepaid: CAL000278830
Contact: MELISSA PENA
Telephone: 3108849000
Mailing Name: Not reported
Mailing Address: 1100 W ARTESIA BLVD
Mailing City,St,Zip: COMPTON, CA 902200000
Gen County: Not reported
TSD EPA ID: CAD008364432
TSD County: Not reported
Waste Category: Unspecified solvent mixture
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.0225
Facility County: San Bernardino

Year: 2009
Gepaid: CAL000278830
Contact: MELISSA PENA

FOOD 4 LESS #786 (Continued) **S113130507**

Telephone:	3108849000
Mailing Name:	Not reported
Mailing Address:	1100 W ARTESIA BLVD
Mailing City,St,Zip:	COMPTON, CA 902200000
Gen County:	Not reported
TSD EPA ID:	CAT080013352
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues less than 10 percent
Disposal Method:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons:	0.231
Facility County:	San Bernardino

Click this hyperlink while viewing on your computer to access
20 additional CA_HAZNET: record(s) in the EDR Site Report.

R156 **HUD** **HAZNET** **S112880338**
NNW **1989 FIG TREE RD** **N/A**
1/8-1/4 **COLTON, CA 92324**
0.127 mi.
670 ft. **Site 1 of 3 in cluster R**

Relative: **Higher**

Actual: **1130 ft.**

HAZNET:

Year:	1997
Gepaid:	CAC001299856
Contact:	HUD
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	INTOWN PROPERTIES
Mailing City,St,Zip:	SAN BERNARDINO, CA 924080000
Gen County:	Not reported
TSD EPA ID:	CAD000088252
TSD County:	Not reported
Waste Category:	Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method:	Transfer Station
Tons:	.0291
Facility County:	San Bernardino

R157 **HUN/INTOWN PROP** **HAZNET** **S112885429**
NNW **1994 FIG TREE RD** **N/A**
1/8-1/4 **COLTON, CA 92376**
0.129 mi.
681 ft. **Site 2 of 3 in cluster R**

Relative: **Higher**

Actual: **1130 ft.**

HAZNET:

Year:	1997
Gepaid:	CAC001365032
Contact:	HUD/INTOWN PORP
Telephone:	9098243723
Mailing Name:	Not reported
Mailing Address:	2086 S E ST STE 204
Mailing City,St,Zip:	SAN BERNARDINO, CA 924080000
Gen County:	Not reported
TSD EPA ID:	CAD028409019
TSD County:	Not reported
Waste Category:	Household waste

HUN/INTOWN PROP (Continued) **S112885429**

Disposal Method: Treatment, Tank
Tons: .0300
Facility County: San Bernardino

Year: 1997
Gepaid: CAC001365032
Contact: HUD/INTOWN PORP
Telephone: 9098243723
Mailing Name: Not reported
Mailing Address: 2086 S E ST STE 204
Mailing City,St,Zip: SAN BERNARDINO, CA 924080000
Gen County: Not reported
TSD EPA ID: CAD028409019
TSD County: Not reported
Waste Category: Household waste
Disposal Method: Transfer Station
Tons: .0375
Facility County: San Bernardino

O158 **HUD INTOWN PROPERTIES** **HAZNET** **S112896499**
NNE **1187 EXPRESS CIR** **N/A**
1/8-1/4 **COLTON, CA 92324**
0.132 mi.
697 ft. **Site 3 of 5 in cluster O**

Relative:
Higher

Actual:
1115 ft.

HAZNET:
Year: 1998
Gepaid: CAC001503536
Contact: HUD
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 2086 S E ST STE 204
Mailing City,St,Zip: SAN BERNARDINO, CA 924080000
Gen County: Not reported
TSD EPA ID: CAD982444481
TSD County: Not reported
Waste Category: Household waste
Disposal Method: Transfer Station
Tons: .0208
Facility County: San Bernardino

M159 **CHEVRON #9-6969** **LUST** **S106784791**
WSW **101 VALLEY BLVD** **N/A**
1/8-1/4 **RIALTO, CA 92376**
0.133 mi.
702 ft. **Site 16 of 31 in cluster M**

Relative:
Lower

Actual:
1064 ft.

LUST REG 8:
Region: 8
County: San Bernardino
Regional Board: Santa Ana Region
Facility Status: Case Closed
Case Number: 083602453T
Local Case Num: 92045
Case Type: Drinking water wells have been affected
Substance: Gasoline

CHEVRON #9-6969 (Continued) **S106784791**

Qty Leaked:	Not reported
Abate Method:	Not reported
Cross Street:	RIVERSIDE
Enf Type:	CLOS
Funding:	Federal Funds
How Discovered:	Tank Closure
How Stopped:	Not reported
Leak Cause:	UNK
Leak Source:	UNK
Global ID:	T0607100325
How Stopped Date:	9/16/1993
Enter Date:	6/16/1994
Review Date:	9/16/1993
Prelim Assess:	10/5/1993
Discover Date:	9/16/1993
Enforcement Date:	Not reported
Close Date:	4/28/2000
Workplan:	Not reported
Pollution Char:	Not reported
Remed Plan:	Not reported
Remed Action:	Not reported
Monitoring:	Not reported
Enter Date:	6/16/1994
GW Qualifies:	Not reported
Soil Qualifies:	Not reported
Operator:	Not reported
Facility Contact:	Not reported
Interim:	Not reported
Oversite Program:	LUST
Latitude:	34.0703024
Longitude:	-117.3700508
MTBE Date:	Not reported
Max MTBE GW:	Not reported
MTBE Concentration:	0
Max MTBE Soil:	Not reported
MTBE Fuel:	1
MTBE Tested:	Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.
MTBE Class:	*
Staff:	TME
Staff Initials:	CB5
Lead Agency:	Local Agency
Local Agency:	36000L
Hydr Basin #:	UPPER SANTA ANA VALL
Beneficial:	Not reported
Priority:	Not reported
Cleanup Fund Id:	Not reported
Work Suspended:	Not reported
Summary:	Site closed on April 28, 2000.

M160 **RIALTO, CITY OF (TEXACO)** **HIST CORTESE** **S101301260**
WSW **102 VALLEY** **LUST** **N/A**
1/8-1/4 **RIALTO, CA 92376**
0.133 mi.
702 ft. **Site 17 of 31 in cluster M**

Relative:
Lower

Actual:
1064 ft.

CORTESE:

Region:	CORTESE
Facility County Code:	36
Reg By:	LTNKA
Reg Id:	083600955T

LUST REG 8:

Region:	8
County:	San Bernardino
Regional Board:	Santa Ana Region
Facility Status:	Case Closed
Case Number:	083600955T
Local Case Num:	91033
Case Type:	Soil only
Substance:	Regular Gasoline
Qty Leaked:	Not reported
Abate Method:	Not reported
Cross Street:	RIVERSIDE
Enf Type:	CLOS
Funding:	Not reported
How Discovered:	Tank Closure
How Stopped:	Not reported
Leak Cause:	UNK
Leak Source:	UNK
Global ID:	T0607100101
How Stopped Date:	4/29/1991
Enter Date:	2/11/1992
Review Date:	4/29/1991
Prelim Assess:	Not reported
Discover Date:	4/29/1991
Enforcement Date:	Not reported
Close Date:	8/25/1992
Workplan:	1/28/1992
Pollution Char:	Not reported
Remed Plan:	Not reported
Remed Action:	Not reported
Monitoring:	Not reported
Enter Date:	2/11/1992
GW Qualifies:	Not reported
Soil Qualifies:	Not reported
Operator:	Not reported
Facility Contact:	Not reported
Interim:	Not reported
Oversite Program:	LUST
Latitude:	34.0705254
Longitude:	-117.3700108
MTBE Date:	Not reported
Max MTBE GW:	Not reported
MTBE Concentration:	0
Max MTBE Soil:	Not reported
MTBE Fuel:	1
MTBE Tested:	Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.
MTBE Class:	*

RIALTO, CITY OF (TEXACO) (Continued) **S101301260**

Staff: VJJ
Staff Initials: DG4
Lead Agency: Local Agency
Local Agency: 36000L
Hydr Basin #: UPPER SANTA ANA VALL
Beneficial: Not reported
Priority: Not reported
Cleanup Fund Id: Not reported
Work Suspended: Not reported
Summary: FORMER CAL TARGET ENTERPRISES SITE

S161 **WAL-MART #1862** **San Bern. Co. Permit** **S103994808**
West **1610 S RIVERSIDE AVE** **N/A**
1/8-1/4 **RIALTO, CA 92376**
0.134 mi.
707 ft. **Site 1 of 14 in cluster S**

Relative: Higher

Actual: 1083 ft.

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0007198
Owner: WAL-MART STORES, INC.
Permit Number: PT0006891
Permit Category: SPECIAL HANDLER
Facility Status: ACTIVE
Expiration Date: 11/30/2013

Region: SAN BERNARDINO
Facility ID: FA0007198
Owner: WAL-MART STORES, INC.
Permit Number: PT0006890
Permit Category: SPECIAL GENERATOR
Facility Status: ACTIVE
Expiration Date: 11/30/2013

Region: SAN BERNARDINO
Facility ID: FA0007198
Owner: WAL-MART STORES, INC.
Permit Number: PT0020772
Permit Category: ABOVEGROUND PETROLEUM STORAGE (AST) (SPCC)
Facility Status: ACTIVE
Expiration Date: 11/30/2013

S162 **WALMART NO 1862** **FINDS** **1012219609**
West **1610 S RIVERSIDE AVE** **N/A**
1/8-1/4 **RIALTO, CA 92376**
0.134 mi.
707 ft. **Site 2 of 14 in cluster S**

Relative: Higher

Actual: 1083 ft.

FINDS:

Registry ID: 110043849663

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport,

WALMART NO 1862 (Continued) **1012219609**

and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

S163 **WAL-MART #2401** **FTTS** **1005622893**
West **1600 S MOUNTAIN** **HIST FTTS** **N/A**
1/8-1/4 **DUARTE, CA 91010** **FINDS**
0.134 mi.
707 ft. **Site 3 of 14 in cluster S**

Relative:
Higher

Actual:
1083 ft.

FTTS INSP:

Inspection Number:	199704113269 1
Region:	09
Inspection Date:	04/11/97
Inspector:	KCARRILLO
Violation occurred:	No
Investigation Type:	Specific Product Review
Investigation Reason:	For Cause, Government
Legislation Code:	FIFRA
Facility Function:	Marketplace

HIST FTTS INSP:

Inspection Number:	199704113269 1
Region:	09
Inspection Date:	Not reported
Inspector:	KCARRILLO
Violation occurred:	No
Investigation Type:	Specific Product Review
Investigation Reason:	For Cause, Government
Legislation Code:	FIFRA
Facility Function:	Marketplace

FINDS:

Registry ID: 110011645728

Environmental Interest/Information System

NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

S164 **WALMART #1862** **HAZNET** **S113178948**
West **1610 S RIVERSIDE AVE** **N/A**
1/8-1/4 **RIALTO, CA 92376**
0.134 mi.
707 ft. **Site 4 of 14 in cluster S**

Relative:
Higher

Actual:
1083 ft.

HAZNET:

Year:	2011
Gepaid:	CAR000205393
Contact:	CHRIS STEWART
Telephone:	4792040402
Mailing Name:	Not reported
Mailing Address:	PO BOX 8041
Mailing City,St,Zip:	BENTONVILLE, AR 727128041
Gen County:	Not reported
TSD EPA ID:	OHD083377010
TSD County:	Not reported
Waste Category:	Pharmaceutical waste
Disposal Method:	Not reported
Tons:	0.003
Facility County:	San Bernardino

Year:	2011
Gepaid:	CAR000205393
Contact:	CHRIS STEWART
Telephone:	4792040402
Mailing Name:	Not reported
Mailing Address:	PO BOX 8041
Mailing City,St,Zip:	BENTONVILLE, AR 727128041
Gen County:	Not reported
TSD EPA ID:	NVD980895338
TSD County:	Not reported
Waste Category:	Off-specification, aged or surplus inorganics
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.0135
Facility County:	San Bernardino

Year:	2011
Gepaid:	CAR000205393
Contact:	CHRIS STEWART
Telephone:	4792040402
Mailing Name:	Not reported
Mailing Address:	PO BOX 8041
Mailing City,St,Zip:	BENTONVILLE, AR 727128041
Gen County:	Not reported
TSD EPA ID:	CAD008364432
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Fuel Blending Prior To Energy Recovery At Another Site
Tons:	0.11
Facility County:	San Bernardino

Year:	2011
Gepaid:	CAR000205393
Contact:	CHRIS STEWART
Telephone:	4792040402
Mailing Name:	Not reported
Mailing Address:	PO BOX 8041

WALMART #1862 (Continued) **S113178948**

Mailing City,St,Zip:	BENTONVILLE, AR 727128041
Gen County:	Not reported
TSD EPA ID:	CAD008364432
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Fuel Blending Prior To Energy Recovery At Another Site
Tons:	0.11
Facility County:	San Bernardino

Year:	2011
Gepaid:	CAR000205393
Contact:	CHRIS STEWART
Telephone:	4792040402
Mailing Name:	Not reported
Mailing Address:	PO BOX 8041
Mailing City,St,Zip:	BENTONVILLE, AR 727128041
Gen County:	Not reported
TSD EPA ID:	CAD008364432
TSD County:	Not reported
Waste Category:	Off-specification, aged or surplus organics
Disposal Method:	Fuel Blending Prior To Energy Recovery At Another Site
Tons:	0.013
Facility County:	San Bernardino

Click this hyperlink while viewing on your computer to access
20 additional CA_HAZNET: record(s) in the EDR Site Report.

S165 **WALMART NO 1862** **RCRA-SQG** **1014387099**
West **1610 S RIVERSIDE AVE** **CAR000205393**
1/8-1/4 **RIALTO, CA 92376**
0.134 mi.
707 ft. **Site 5 of 14 in cluster S**

Relative:
Higher

Actual:
1083 ft.

RCRA-SQG:

Date form received by agency:	01/03/2012
Facility name:	WALMART NO 1862
Facility address:	1610 S RIVERSIDE AVE RIALTO, CA 92376
EPA ID:	CAR000205393
Mailing address:	PO BOX 8041 BENTONVILLE, AR 72712 8041
Contact:	CHRIS STEWART
Contact address:	PO BOX 8041 BENTONVILLE, AR 72712 8041
Contact country:	US
Contact telephone:	479-204-0402
Contact email:	CHRISTOPHER.STEWART@WAL-MART.COM
EPA Region:	09
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	WALMART STORES INC

WALMART NO 1862 (Continued) **1014387099**

Owner/operator address: Not reported
Not reported
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 02/02/1993
Owner/Op end date: Not reported

Owner/operator name: WALMART STORES INC
Owner/operator address: PO BOX 8041
BENTONVILLE, AR 72712
Owner/operator country: US
Owner/operator telephone: 479-204-0402
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 02/02/1993
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 06/27/2011
Facility name: WALMART NO 1862
Classification: Large Quantity Generator

Date form received by agency: 02/25/2010
Facility name: WALMART NO 1862
Classification: Small Quantity Generator

Hazardous Waste Summary:
Waste code: 122
Waste name: 122

Waste code: 135
Waste name: 135

Waste code: 141
Waste name: 141

Waste code: 181

WALMART NO 1862 (Continued) **1014387099**

Waste name: 181

Waste code: 212
Waste name: 212

Waste code: 213
Waste name: 213

Waste code: 214
Waste name: 214

Waste code: 221
Waste name: 221

Waste code: 223
Waste name: 223

Waste code: 232
Waste name: 232

Waste code: 281
Waste name: 281

Waste code: 291
Waste name: 291

Waste code: 311
Waste name: 311

Waste code: 331
Waste name: 331

Waste code: 343
Waste name: 343

Waste code: 352
Waste name: 352

Waste code: 561
Waste name: 561

Waste code: 791
Waste name: 791

Waste code: 792
Waste name: 792

Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002

WALMART NO 1862 (Continued) **1014387099**

Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Waste code: D003
Waste name: A MATERIAL IS CONSIDERED TO BE A REACTIVE HAZARDOUS WASTE IF IT IS NORMALLY UNSTABLE, REACTS VIOLENTLY WITH WATER, GENERATES TOXIC GASES WHEN EXPOSED TO WATER OR CORROSIVE MATERIALS, OR IF IT IS CAPABLE OF DETONATION OR EXPLOSION WHEN EXPOSED TO HEAT OR A FLAME. ONE EXAMPLE OF SUCH WASTE WOULD BY WASTE GUNPOWDER.

Waste code: D004
Waste name: ARSENIC

Waste code: D005
Waste name: BARIUM

Waste code: D006
Waste name: CADMIUM

Waste code: D007
Waste name: CHROMIUM

Waste code: D008
Waste name: LEAD

Waste code: D009
Waste name: MERCURY

Waste code: D010
Waste name: SELENIUM

Waste code: D011
Waste name: SILVER

Waste code: D016
Waste name: 2,4-D

Waste code: D018
Waste name: BENZENE

Waste code: D022
Waste name: CHLOROFORM

Waste code: D024
Waste name: M-CRESOL

Waste code: D026
Waste name: CRESOL

Waste code: D027
Waste name: 1,4-DICHLOROBENZENE

WALMART NO 1862 (Continued) **1014387099**

Waste code: D035
Waste name: METHYL ETHYL KETONE

Waste code: D039
Waste name: TETRACHLOROETHYLENE

Waste code: P001
Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Waste code: P075
Waste name: NICOTINE, & SALTS

Waste code: U002
Waste name: ACETONE (I)

Waste code: U034
Waste name: ACETALDEHYDE, TRICHLORO-

Waste code: U035
Waste name: BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]-

Waste code: U058
Waste name: CYCLOPHOSPHAMIDE

Waste code: U072
Waste name: BENZENE, 1,4-DICHLORO-

Waste code: U080
Waste name: METHANE, DICHLORO-

Waste code: U122
Waste name: FORMALDEHYDE

Waste code: U129
Waste name: CYCLOHEXANE, 1,2,3,4,5,6-HEXACHLORO-, (1ALPHA,2ALPHA,3BETA,4ALPHA,5ALPHA,6BETA)-

Waste code: U132
Waste name: HEXACHLOROPHENE

Waste code: U150
Waste name: MELPHALAN

Waste code: U154
Waste name: METHANOL (I)

Waste code: U159
Waste name: 2-BUTANONE (I,T)

Waste code: U165
Waste name: NAPHTHALENE

Waste code: U182
Waste name: PARALDEHYDE

Waste code: U188

WALMART NO 1862 (Continued) **1014387099**

Waste name: PHENOL

Waste code: U200
Waste name: RESERPINE

Waste code: U205
Waste name: SELENIUM SULFIDE

Waste code: U248
Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYL-BUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS OF 0.3% OR LESS

Waste code: U249
Waste name: ZINC PHOSPHIDE ZN3P2, WHEN PRESENT AT CONCENTRATIONS OF 10% OR LESS

Waste code: U279
Waste name: CARBARYL (OR) 1-NAPHTHALENOL, METHYLCARBAMATE

Waste code: U409
Waste name: CARBAMIC ACID, [1,2-PHENYLENEBIS (IMINOCARBONOTHIOYL)]BIS-, DIMETHYL ESTER (OR) THIOPHANATE-METHYL

Waste code: U411
Waste name: PHENOL, 2-(1-METHYLETHOXY)-, METHYLCARBAMATE (OR) PROPOXUR

Violation Status: No violations found

S166 **WAL-MART #1862** **RCRA-LQG** **1012175601**
West **1610 SOUTH RIVERSIDE AVENUE** **CAL000098423**
1/8-1/4 **RIALTO, CA 92376**
0.134 mi.
707 ft. **Site 6 of 14 in cluster S**

Relative:
Higher

Actual:
1083 ft.

RCRA-LQG:
Date form received by agency: 02/25/2008
Facility name: WAL-MART #1862
Facility address: 1610 SOUTH RIVERSIDE AVENUE
RIALTO, CA 92376
EPA ID: CAL000098423
Mailing address: 1300 SE 8TH STREET
MAIL STOP 0605
BENTONVILLE, AR 727160605
Contact: RICH DAILEY
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (479) 204-9914
Contact email: RICH.DAILEY@WAL-MART.COM
EPA Region: 09
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting

WAL-MART #1862 (Continued) **1012175601**

from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	WAL-MART STORES, INC.
Owner/operator address:	1300 SE 8TH STREET
	BENTONVILLE, AR 72716
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	02/02/1993
Owner/Op end date:	Not reported

Owner/operator name:	WAL-MART STORES, INC.
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	02/02/1993
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Hazardous Waste Summary:

Waste code:	D001
Waste name:	IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code:	D002
Waste name:	A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN

WAL-MART #1862 (Continued) **1012175601**

OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Waste code: D005
Waste name: BARIUM

Waste code: D007
Waste name: CHROMIUM

Waste code: D008
Waste name: LEAD

Waste code: D009
Waste name: MERCURY

Waste code: D011
Waste name: SILVER

Waste code: D016
Waste name: 2,4-D

Waste code: D018
Waste name: BENZENE

Waste code: D035
Waste name: METHYL ETHYL KETONE

Violation Status: No violations found

S167 **WAL-MART STORE #1862** **HAZNET** **S113169463**
West **1610 SOUTH RIVERSIDE AVENUE** **N/A**
1/8-1/4 **RIALTO, CA 92376**
0.134 mi.
707 ft. **Site 7 of 14 in cluster S**

Relative:
Higher

Actual:
1083 ft.

HAZNET:
Year: 1994
Gepaid: CAL930786278
Contact: WALMART CORPORATION
Telephone: 5012738833
Mailing Name: Not reported
Mailing Address: 702 SOUTHWEST 8TH ST
Mailing City,St,Zip: BENTONVILLE, AZ 727168094
Gen County: Not reported
TSD EPA ID: CAD003963592
TSD County: Not reported
Waste Category: Metal sludge (Alkaline solution (pH >= 12.5) with metals)
Disposal Method: Recycler
Tons: .0350
Facility County: San Bernardino

Year: 1993
Gepaid: CAL930786278
Contact: WALMART CORPORATION
Telephone: 5012738833
Mailing Name: Not reported
Mailing Address: 702 SOUTHWEST 8TH ST

WAL-MART STORE #1862 (Continued) **S113169463**

Mailing City,St,Zip: BENTONVILLE, AZ 727168094
Gen County: Not reported
TSD EPA ID: CAD003963592
TSD County: Not reported
Waste Category: Metal sludge (Alkaline solution (pH >= 12.5) with metals)
Disposal Method: Recycler
Tons: 3.50000000000
Facility County: San Bernardino

S168 **WAL-MART STORE #1862** **AST** **A100346207**
West **1610 S. RIVERSIDE AVE** **N/A**
1/8-1/4 **RIALTO, CA 92376**
0.134 mi.
707 ft. **Site 8 of 14 in cluster S**

Relative:
Higher

Actual:
1083 ft.

AST:
Owner: WAL-MART STORES INC.
Total Gallons: 1,550
Certified Unified Program Agencies: San Bernardino

S169 **WAL-MART #1862** **FINDS** **1012077304**
West **1610 SOUTH RIVERSIDE AVENUE** **N/A**
1/8-1/4 **RIALTO, CA 92376**
0.134 mi.
707 ft. **Site 9 of 14 in cluster S**

Relative:
Higher

Actual:
1083 ft.

FINDS:

Registry ID: 110038862656

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

S170 **WAL-MART STORE #1862** **HAZNET** **S113059286**
West **1610 S RIVERSIDE AVE** **N/A**
1/8-1/4 **RIALTO, CA 92376**
0.134 mi.
707 ft. **Site 10 of 14 in cluster S**

Relative:
Higher

Actual:
1083 ft.

HAZNET:
Year: 2009
Gepaid: CAL000098423
Contact: CHRIS STEWART/PROJECT MGR
Telephone: 4792040402
Mailing Name: Not reported
Mailing Address: 508 SW 8TH ST
Mailing City,St,Zip: BENTONVILLE, AR 727160505

WAL-MART STORE #1862 (Continued) **S113059286**

Gen County: Not reported
TSD EPA ID: CAD008364432
TSD County: Not reported
Waste Category: Other organic solids
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 1.7765
Facility County: San Bernardino

Year: 2009
Gepaid: CAL000098423
Contact: CHRIS STEWART/PROJECT MGR
Telephone: 4792040402
Mailing Name: Not reported
Mailing Address: 508 SW 8TH ST
Mailing City,St,Zip: BENTONVILLE, AR 727160505
Gen County: Not reported
TSD EPA ID: CAD008364432
TSD County: Not reported
Waste Category: Unspecified solvent mixture
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.017
Facility County: San Bernardino

Year: 2009
Gepaid: CAL000098423
Contact: CHRIS STEWART/PROJECT MGR
Telephone: 4792040402
Mailing Name: Not reported
Mailing Address: 508 SW 8TH ST
Mailing City,St,Zip: BENTONVILLE, AR 727160505
Gen County: Not reported
TSD EPA ID: CAD008364432
TSD County: Not reported
Waste Category: Other organic solids
Disposal Method: Fuel Blending Prior To Energy Recovery At Another Site
Tons: 0.2225
Facility County: San Bernardino

Year: 2009
Gepaid: CAL000098423
Contact: CHRIS STEWART/PROJECT MGR
Telephone: 4792040402
Mailing Name: Not reported
Mailing Address: 508 SW 8TH ST
Mailing City,St,Zip: BENTONVILLE, AR 727160505
Gen County: Not reported
TSD EPA ID: CAD008364432
TSD County: Not reported
Waste Category: Off-specification, aged or surplus organics
Disposal Method: Fuel Blending Prior To Energy Recovery At Another Site
Tons: 0.3445
Facility County: San Bernardino

Year: 2009
Gepaid: CAL000098423

WAL-MART STORE #1862 (Continued) **S113059286**

Contact:	CHRIS STEWART/PROJECT MGR
Telephone:	4792040402
Mailing Name:	Not reported
Mailing Address:	508 SW 8TH ST
Mailing City,St,Zip:	BENTONVILLE, AR 727160505
Gen County:	Not reported
TSD EPA ID:	CAD008364432
TSD County:	Not reported
Waste Category:	Off-specification, aged or surplus organics
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.006
Facility County:	San Bernardino

Click this hyperlink while viewing on your computer to access
70 additional CA_HAZNET: record(s) in the EDR Site Report.

S171
West
1/8-1/4
0.134 mi.
707 ft.

WAL-MART **HAZNET** **S113052528**
1610 S RIVERSIDE AVE **N/A**
RIALTO, CA 92376

Site 11 of 14 in cluster S

Relative:
Higher

Actual:
1083 ft.

HAZNET:

Year:	1993
Gepaid:	CAL000079986
Contact:	WAL-MART STORES INC
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	DEPT 8013
Mailing City,St,Zip:	BENTONVILLE, AR 727168013
Gen County:	Not reported
TSD EPA ID:	CAD000088252
TSD County:	Not reported
Waste Category:	Hydrocarbon solvents (benzene, hexane, Stoddard, Etc.)
Disposal Method:	Transfer Station
Tons:	2.07999999999
Facility County:	San Bernardino

Year:	1993
Gepaid:	CAL000079986
Contact:	WAL-MART STORES INC
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	DEPT 8013
Mailing City,St,Zip:	BENTONVILLE, AR 727168013
Gen County:	Not reported
TSD EPA ID:	CAD000088252
TSD County:	Not reported
Waste Category:	Paint sludge
Disposal Method:	Transfer Station
Tons:	0.12509999999
Facility County:	San Bernardino

S172 **CHMIRS** **S100221431**
West **1521 S. RIVERSIDE** **N/A**
1/8-1/4 **RIALTO, CA 92376**
0.136 mi.
719 ft. **Site 12 of 14 in cluster S**

Relative:
Higher

Actual:
1085 ft.

CHMIRS:

OES Incident Number:	9099412
OES notification:	Not reported
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	08-AUG-90
Date Completed:	**08-AUG-90**
Property Use:	500
Agency Id Number:	36185
Agency Incident Number:	903745
Time Notified:	821
Time Completed:	1029
Surrounding Area:	300
Estimated Temperature:	89
Property Management:	P
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Involved?:	N
Resp Agncy Personel # Of Decontaminated:	0
Responding Agency Personel # Of Injuries:	0
Responding Agency Personel # Of Fatalities:	0
Others Number Of Decontaminated:	0
Others Number Of Injuries:	0
Others Number Of Fatalities:	0
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	CAPT. NASH BRIONES
Report Date:	08-AUG-90
Comments:	Y
Facility Telephone:	714 820-2501
Waterway Involved:	Not reported
Waterway:	Not reported
Spill Site:	Not reported
Cleanup By:	Not reported
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	88-92
Agency:	Not reported
Incident Date:	Not reported
Admin Agency:	Not reported
Amount:	Not reported

(Continued) **S100221431**

Contained:	Not reported
Site Type:	Not reported
E Date:	30-MAY-91
Substance:	Not reported
Quantity Released:	Not reported
BBLS:	Not reported
Cups:	Not reported
CUFT:	Not reported
Gallons:	Not reported
Grams:	Not reported
Pounds:	Not reported
Liters:	Not reported
Ounces:	Not reported
Pints:	Not reported
Quarts:	Not reported
Sheen:	Not reported
Tons:	Not reported
Unknown:	Not reported
Evacuations:	Not reported
Number of Injuries:	Not reported
Number of Fatalities:	Not reported
Description:	Not reported

S173 **CRESTVIEW CONVALESCENT HOSPITAL** **San Bern. Co. Permit** **S109598531**
West **1471 S RIVERSIDE AVE** **N/A**
1/8-1/4 **RIALTO, CA 92376**
0.136 mi.
719 ft. **Site 13 of 14 in cluster S**

Relative:
Higher

Actual:
1085 ft.

San Bern. Co. Permit:

Region:	SAN BERNARDINO
Facility ID:	FA0012353
Owner:	CRESTVIEW CONVALESCENT HOSP
Permit Number:	PT0021649
Permit Category:	BULK CO2 AT RETAIL FOOD FACILITIES
Facility Status:	ACTIVE
Expiration Date:	05/31/2010

S174 **RIALTO MED SUPPLIES INC** **San Bern. Co. Permit** **S103820663**
West **1517 S RIVERSIDE AVE** **N/A**
1/8-1/4 **RIALTO, CA 92376**
0.136 mi.
719 ft. **Site 14 of 14 in cluster S**

Relative:
Higher

Actual:
1085 ft.

San Bern. Co. Permit:

Region:	SAN BERNARDINO
Facility ID:	FA0005698
Owner:	RIALTO MED SUPPLIES INC
Permit Number:	PT0009481
Permit Category:	HAZMAT HANDLER 0-10 EMPLOYEES
Facility Status:	INACTIVE
Expiration Date:	09/30/2012

O175
NNE
1/8-1/4
0.139 mi.
732 ft.

1610 NORTH BENT RAIL CIRCLE
COLTON, CA 92324

Site 4 of 5 in cluster O

Relative:
Higher

Actual:
1103 ft.

CDL **S107529298**
N/A

CDL:
Facility ID: 199705022
Lab Type: Illegal Drug Lab (L) - location where an illegal drug lab was operated or drug lab equipment and/or materials were stored.

Q176
NNE
1/8-1/4
0.141 mi.
743 ft.

FOOD 4 LESS GAS STATION
1170 N PEPPER AVE
COLTON, CA 92324

Site 4 of 7 in cluster Q

Relative:
Higher

Actual:
1102 ft.

San Bern. Co. Permit **S106229966**
N/A

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0007698
Owner: RALPHS GROCERY COMPANY
Permit Number: PT0021350
Permit Category: WASTE INCIDENTAL UST OPERATION ONLY
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0007698
Owner: RALPHS GROCERY COMPANY
Permit Number: PT0014182
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0007698
Owner: RALPHS GROCERY COMPANY
Permit Number: PT0014183
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0007698
Owner: RALPHS GROCERY COMPANY
Permit Number: PT0014184
Permit Category: HAZMAT HANDLER - UST ONLY
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Q177
NNE
1/8-1/4
0.141 mi.
743 ft.

FOOD 4 LESS #786 FUEL CENTER
1170 N PEPPER AVE
COLTON, CA 92324

Site 5 of 7 in cluster Q

HAZNET **S113160674**
N/A

Relative:
Higher

Actual:
1102 ft.

HAZNET:

Year:	2011
Gepaid:	CAL000359419
Contact:	MELISSA PENA
Telephone:	3108849000
Mailing Name:	Not reported
Mailing Address:	1100 W ARTESIA BLVD
Mailing City,St,Zip:	COMPTON, CA 902205108
Gen County:	Not reported
TSD EPA ID:	NVT330010000
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.1625
Facility County:	San Bernardino

Year:	2011
Gepaid:	CAL000359419
Contact:	MELISSA PENA
Telephone:	3108849000
Mailing Name:	Not reported
Mailing Address:	1100 W ARTESIA BLVD
Mailing City,St,Zip:	COMPTON, CA 902205108
Gen County:	Not reported
TSD EPA ID:	CAT080013352
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues less than 10 percent
Disposal Method:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons:	3.3852
Facility County:	San Bernardino

Year:	2011
Gepaid:	CAL000359419
Contact:	MELISSA PENA
Telephone:	3108849000
Mailing Name:	Not reported
Mailing Address:	1100 W ARTESIA BLVD
Mailing City,St,Zip:	COMPTON, CA 902205108
Gen County:	Not reported
TSD EPA ID:	CAD008302903
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.2
Facility County:	San Bernardino

M178
West
1/8-1/4
0.144 mi.
762 ft.

ARCO STN. #323
111 W VALLEY BLVD
RIALTO, CA 92376

Site 18 of 31 in cluster M

HIST UST **U001575522**
N/A

Relative:
Lower

Actual:
1063 ft.

HIST UST:

Region:	STATE
Facility ID:	00000002500
Facility Type:	Gas Station
Other Type:	Not reported
Total Tanks:	0005
Contact Name:	Not reported
Telephone:	2139239876
Owner Name:	THRIFTY OIL CO.
Owner Address:	1000 LAKEWOOD BLVD.
Owner City,St,Zip:	DOWNEY, CA 90240

Tank Num:	001
Container Num:	323-1
Year Installed:	Not reported
Tank Capacity:	00008136
Tank Used for:	PRODUCT
Type of Fuel:	REGULAR
Tank Construction:	1/4 inches
Leak Detection:	Stock Inventor

Tank Num:	002
Container Num:	323-2
Year Installed:	1981
Tank Capacity:	00015000
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Tank Construction:	.267 inches
Leak Detection:	Stock Inventor

Tank Num:	003
Container Num:	323-5
Year Installed:	Not reported
Tank Capacity:	00008136
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Tank Construction:	1/4 inches
Leak Detection:	Stock Inventor

Tank Num:	004
Container Num:	323-6
Year Installed:	Not reported
Tank Capacity:	00006259
Tank Used for:	PRODUCT
Type of Fuel:	REGULAR
Tank Construction:	1/4 inches
Leak Detection:	Stock Inventor

Tank Num:	005
Container Num:	323-10
Year Installed:	Not reported
Tank Capacity:	00000550
Tank Used for:	WASTE

ARCO STN. #323 (Continued) **U001575522**

Type of Fuel: WASTE OIL
Tank Construction: 12 gauge
Leak Detection: Stock Inventor

M179 **EDR US Hist Auto Stat** **1015157291**
West **111 W VALLEY BLVD** **N/A**
1/8-1/4 **RIALTO, CA 92376**
0.144 mi.
762 ft. **Site 19 of 31 in cluster M**

Relative:
Lower

Actual:
1063 ft.

EDR Historical Auto Stations:
Name: ARCO
Year: 2010
Address: 111 W VALLEY BLVD

M180 **BP WEST COAST PRODUCTS LLC 9695** **HAZNET** **S113176165**
West **111 W VALLEY BLVD** **N/A**
1/8-1/4 **RIALTO, CA 92376**
0.144 mi.
762 ft. **Site 20 of 31 in cluster M**

Relative:
Lower

Actual:
1063 ft.

HAZNET:
Year: 2011
Gepaid: CAR000104000
Contact: WASTE SPECIALIST
Telephone: 5035246191
Mailing Name: Not reported
Mailing Address: PO BOX 80249
Mailing City,St,Zip: RCHO STA MARG, CA 926880000
Gen County: Not reported
TSD EPA ID: CAT080013352
TSD County: Not reported
Waste Category: Aqueous solution with total organic residues less than 10 percent
Disposal Method: Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons: 1.4826
Facility County: San Bernardino

Year: 2010
Gepaid: CAR000104000
Contact: WASTE SPECIALIST
Telephone: 5035246191
Mailing Name: Not reported
Mailing Address: PO BOX 80249
Mailing City,St,Zip: RCHO STA MARG, CA 926880000
Gen County: Not reported
TSD EPA ID: CAT080013352
TSD County: Not reported
Waste Category: Aqueous solution with total organic residues less than 10 percent
Disposal Method: Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons: 0.1008
Facility County: San Bernardino

Year: 2009
Gepaid: CAR000104000

BP WEST COAST PRODUCTS LLC 9695 (Continued) **S113176165**

Contact:	Waste Specialist
Telephone:	5035246191
Mailing Name:	Not reported
Mailing Address:	PO BOX 80249
Mailing City,St,Zip:	RCHO STA MARG, CA 926880000
Gen County:	Not reported
TSD EPA ID:	CAT080013352
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues less than 10 percent
Disposal Method:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons:	0.462
Facility County:	San Bernardino

Year:	2009
Gepaid:	CAR000104000
Contact:	Waste Specialist
Telephone:	5035246191
Mailing Name:	Not reported
Mailing Address:	PO BOX 80249
Mailing City,St,Zip:	RCHO STA MARG, CA 926880000
Gen County:	Not reported
TSD EPA ID:	CAD008302903
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.0075
Facility County:	San Bernardino

Year:	2008
Gepaid:	CAR000104000
Contact:	RUTH HA / WASTE SPECIALIST
Telephone:	5035246191
Mailing Name:	Not reported
Mailing Address:	PO BOX 80249
Mailing City,St,Zip:	RCHO STA MARG, CA 926880000
Gen County:	Not reported
TSD EPA ID:	CAD008302903
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.05
Facility County:	San Bernardino

Click this hyperlink while viewing on your computer to access
14 additional CA_HAZNET: record(s) in the EDR Site Report.

M181 **THRIFTY OIL CO #323** **LUST** **S101591044**
West **111 W VALLEY** **CA FID UST** **N/A**
1/8-1/4 **RIALTO, CA 92376** **SWEEPS UST**
0.144 mi. **San Bern. Co. Permit**
762 ft. **Site 21 of 31 in cluster M**

Relative:
Lower

Actual:
1063 ft.

LUST:

Region:	STATE
Global Id:	T0607100519
Latitude:	34.0702467333333
Longitude:	-117.370627233333
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	09/17/2008
Lead Agency:	SAN BERNARDINO COUNTY
Case Worker:	LH6
Local Agency:	Not reported
RB Case Number:	083603296T
LOC Case Number:	98096
File Location:	Local Agency
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Gasoline, MTBE / TBA / Other Fuel Oxygenates
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Regulatory Activities:

Global Id:	T0607100519
Action Type:	Other
Date:	01/01/1950
Action:	Leak Stopped
Global Id:	T0607100519
Action Type:	Other
Date:	01/01/1950
Action:	Leak Discovery
Global Id:	T0607100519
Action Type:	RESPONSE
Date:	07/23/2007
Action:	Other Report / Document
Global Id:	T0607100519
Action Type:	ENFORCEMENT
Date:	09/17/2008
Action:	Closure/No Further Action Letter - #98096
Global Id:	T0607100519
Action Type:	Other
Date:	01/01/1950
Action:	Leak Reported
Global Id:	T0607100519
Action Type:	REMEDIATION
Date:	01/01/1950
Action:	Soil Vapor Extraction (SVE)
Global Id:	T0607100519
Action Type:	REMEDIATION
Date:	01/01/1950

THRIFTY OIL CO #323 (Continued) **S101591044**

Action: Soil Vapor Extraction (SVE)

CA FID UST:

Facility ID:	36000967
Regulated By:	UTNKA
Regulated ID:	00002500
Cortese Code:	Not reported
SIC Code:	Not reported
Facility Phone:	Not reported
Mail To:	Not reported
Mailing Address:	10000 LAKEWOOD BLVD
Mailing Address 2:	Not reported
Mailing City,St,Zip:	RIALTO 92376
Contact:	Not reported
Contact Phone:	Not reported
DUNs Number:	Not reported
NPDES Number:	Not reported
EPA ID:	Not reported
Comments:	Not reported
Status:	Active

SWEEPS UST:

Status:	Active
Comp Number:	2500
Number:	9
Board Of Equalization:	44-007386
Referral Date:	07-28-92
Action Date:	07-28-92
Created Date:	02-29-88
Tank Status:	A
Owner Tank Id:	323-1
Swrcb Tank Id:	36-000-002500-000001
Actv Date:	08-25-88
Capacity:	8136
Tank Use:	M.V. FUEL
Stg:	P
Content:	LEADED
Number Of Tanks:	5

Status:	Active
Comp Number:	2500
Number:	9
Board Of Equalization:	44-007386
Referral Date:	07-28-92
Action Date:	07-28-92
Created Date:	02-29-88
Tank Status:	A
Owner Tank Id:	323-2
Swrcb Tank Id:	36-000-002500-000002
Actv Date:	08-25-88
Capacity:	15000
Tank Use:	M.V. FUEL
Stg:	P
Content:	REG UNLEADED
Number Of Tanks:	Not reported

THRIFTY OIL CO #323 (Continued) **S101591044**

Status: Active
Comp Number: 2500
Number: 9
Board Of Equalization: 44-007386
Referral Date: 07-28-92
Action Date: 07-28-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 323-5
Swrcb Tank Id: 36-000-002500-000003
Actv Date: 08-25-88
Capacity: 8136
Tank Use: M.V. FUEL
Stg: P
Content: REG UNLEADED
Number Of Tanks: Not reported

Status: Active
Comp Number: 2500
Number: 9
Board Of Equalization: 44-007386
Referral Date: 07-28-92
Action Date: 07-28-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 323-6
Swrcb Tank Id: 36-000-002500-000004
Actv Date: 08-25-88
Capacity: 6259
Tank Use: M.V. FUEL
Stg: P
Content: LEADED
Number Of Tanks: Not reported

Status: Active
Comp Number: 2500
Number: 9
Board Of Equalization: 44-007386
Referral Date: 07-28-92
Action Date: 07-28-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 323-10
Swrcb Tank Id: 36-000-002500-000005
Actv Date: 08-25-88
Capacity: 550
Tank Use: OIL
Stg: W
Content: WASTE OIL
Number Of Tanks: Not reported

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0001024
Owner: TESORO SOUTH COAST COMPANY, LLC
Permit Number: PT0012212
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)

THRIFTY OIL CO #323 (Continued) **S101591044**

Facility Status: INACTIVE
Expiration Date: 05/31/2006

Region: SAN BERNARDINO
Facility ID: FA0001024
Owner: TESORO SOUTH COAST COMPANY, LLC
Permit Number: PT0002006
Permit Category: HAZMAT HANDLER 0-10 EMPLOYEES (W/GEN PRMT)
Facility Status: ACTIVE
Expiration Date: 05/31/2013

Region: SAN BERNARDINO
Facility ID: FA0001024
Owner: TESORO SOUTH COAST COMPANY, LLC
Permit Number: PT0012209
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 05/31/2013

Region: SAN BERNARDINO
Facility ID: FA0001024
Owner: TESORO SOUTH COAST COMPANY, LLC
Permit Number: PT0012210
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 05/31/2013

Region: SAN BERNARDINO
Facility ID: FA0001024
Owner: TESORO SOUTH COAST COMPANY, LLC
Permit Number: PT0012211
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 05/31/2013

Region: SAN BERNARDINO
Facility ID: FA0001024
Owner: TESORO SOUTH COAST COMPANY, LLC
Permit Number: PT0013702
Permit Category: SPECIAL GENERATOR
Facility Status: ACTIVE
Expiration Date: 05/31/2013

M182 **ARCO #9695** **UST** **U003937821**
West **111 W VALLEY BLVD** **N/A**
1/8-1/4 **RIALTO, CA 92376**
0.144 mi.
762 ft. **Site 22 of 31 in cluster M**

Relative:
Lower

Actual:
1063 ft.

UST:
Facility ID: 86008454
Latitude: 34.07045
Longitude: -117.37061

M183 **ARCO FACILITY NO 09695** **RCRA-SQG** **1004678016**
West **111 W VALLEY BLVD** **FINDS** **CAR000104000**
1/8-1/4 **RIALTO, CA 92376**
0.144 mi.
762 ft. **Site 23 of 31 in cluster M**

Relative:
Lower

Actual:
1063 ft.

RCRA-SQG:

Date form received by agency:	07/10/2002
Facility name:	ARCO FACILITY NO 09695
Facility address:	111 W VALLEY BLVD RIALTO, CA 92376
EPA ID:	CAR000104000
Mailing address:	P O BOX 6038 ARTESIA, CA 907026038
Contact:	JACK OMAN
Contact address:	P O BOX 6038 ARTESIA, CA 907026038
Contact country:	US
Contact telephone:	(714) 690-2425
Contact email:	Not reported
EPA Region:	09
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	B P W COAST PRODUCTS LLC
Owner/operator address:	P O BOX 6038 ARTESIA, CA 90702
Owner/operator country:	Not reported
Owner/operator telephone:	(714) 690-2425
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Hazardous Waste Summary:

Waste code:	D000

ARCO FACILITY NO 09695 (Continued) **1004678016**

Waste name: Not Defined

Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D018
Waste name: BENZENE

Violation Status: No violations found

FINDS:

Registry ID: 110012191350

Environmental Interest/Information System

California Hazardous Waste Tracking System - Datamart (HWTS-DATAMART) provides California with information on hazardous waste shipments for generators, transporters, and treatment, storage, and disposal facilities.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

T184 **COLTON OFFICE PLAZA** **NPDES** **S109440203**
ESE **105 CYPRESS AVE** **N/A**
1/8-1/4 **COLTON, CA**
0.147 mi.
775 ft. **Site 1 of 5 in cluster T**

Relative:
Lower

Actual:
1020 ft.

NPDES:

Npdes Number:	CAS000002
Facility Status:	Terminated
Agency Id:	0
Region:	8
Regulatory Measure Id:	322953
Order No:	2009-0009-DWQ
Regulatory Measure Type:	Enrollee
Place Id:	Not reported
WDID:	8 36C346458
Program Type:	Construction
Adoption Date Of Regulatory Measure:	Not reported
Effective Date Of Regulatory Measure:	04/06/2007
Expiration Date Of Regulatory Measure:	Not reported
Termination Date Of Regulatory Measure:	09/02/2010
Discharge Name:	105 Cypress Assoc LLP
Discharge Address:	105 Cypress Ave
Discharge City:	Colton

COLTON OFFICE PLAZA (Continued) **S109440203**

Discharge State: California
Discharge Zip: 92411

M185 **WHITING DOOR MANUFACTURING CORP** **NPDES** **S109465432**
West **113 WEST VALLEY BLVD** **N/A**
1/8-1/4 **RIALTO, CA 92376**
0.147 mi.
775 ft. **Site 24 of 31 in cluster M**

Relative:
Lower

Actual:
1063 ft.

NPDES:

Npdes Number:	CAS000001
Facility Status:	Terminated
Agency Id:	0
Region:	8
Regulatory Measure Id:	354639
Order No:	97-03-DWQ
Regulatory Measure Type:	Enrollee
Place Id:	Not reported
WDID:	8 36I021911
Program Type:	Industrial
Adoption Date Of Regulatory Measure:	Not reported
Effective Date Of Regulatory Measure:	11/04/2008
Expiration Date Of Regulatory Measure:	Not reported
Termination Date Of Regulatory Measure:	08/23/2012
Discharge Name:	Whiting Door Manufacturing Corp
Discharge Address:	113 Cedar St
Discharge City:	Akron
Discharge State:	New York
Discharge Zip:	14001

T186 **KENNETH MICHAEL GARCIA** **HAZNET** **S113182546**
ESE **1087 W VALLEY BLVD RM 18** **N/A**
1/8-1/4 **COLTON, CA 92324**
0.149 mi.
789 ft. **Site 2 of 5 in cluster T**

Relative:
Lower

Actual:
1020 ft.

HAZNET:

Year:	1997
Gepaid:	CLU970017919
Contact:	Not reported
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	PO BOX 806
Mailing City,St,Zip:	SACRAMENTO, CA 958120806
Gen County:	Not reported
TSD EPA ID:	CAD050806850
TSD County:	Not reported
Waste Category:	Other inorganic solid waste
Disposal Method:	Transfer Station
Tons:	.0100
Facility County:	San Bernardino

Year:	1997
Gepaid:	CLU970017919
Contact:	Not reported
Telephone:	0000000000

KENNETH MICHAEL GARCIA (Continued) **S113182546**

Mailing Name:	Not reported
Mailing Address:	PO BOX 806
Mailing City,St,Zip:	SACRAMENTO, CA 958120806
Gen County:	Not reported
TSD EPA ID:	CAD050806850
TSD County:	Not reported
Waste Category:	Liquids with pH <= 2
Disposal Method:	Transfer Station
Tons:	.0075
Facility County:	San Bernardino

Year:	1997
Gepaid:	CLU970017919
Contact:	Not reported
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	PO BOX 806
Mailing City,St,Zip:	SACRAMENTO, CA 958120806
Gen County:	Not reported
TSD EPA ID:	CAD050806850
TSD County:	Not reported
Waste Category:	Off-specification, aged or surplus organics
Disposal Method:	Recycler
Tons:	.0225
Facility County:	San Bernardino

T187 **CDL** **S107527098**
ESE **1087 WEST VALLEY BLVD #18** **N/A**
1/8-1/4 **COLTON, CA 92324**
0.149 mi.
789 ft. **Site 3 of 5 in cluster T**

Relative:
Lower

Actual:
1020 ft.

CDL:

Facility ID:	199706045
Lab Type:	Illegal Drug Lab (L) - location where an illegal drug lab was operated or drug lab equipment and/or materials were stored.

U188 **CDL** **S103656929**
East **393 CYPRESS** **N/A**
1/8-1/4 **COLTON, CA 92324**
0.151 mi.
799 ft. **Site 1 of 3 in cluster U**

Relative:
Lower

Actual:
1022 ft.

CDL:

Facility ID:	199602051
Lab Type:	Illegal Drug Lab (L) - location where an illegal drug lab was operated or drug lab equipment and/or materials were stored.

U189 **EVA JEAN HORRIDGE** **HAZNET** **S113180982**
East **393 CYPRESS** **N/A**
1/8-1/4 **COLTON, CA 92324**
0.151 mi.
799 ft. **Site 2 of 3 in cluster U**

Relative:
Lower

Actual:
1022 ft.

HAZNET:

Year:	1996
Gepaid:	CLU960003968
Contact:	EVA JEAN HOLTON
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	DTSC CLU/ERU
Mailing City,St,Zip:	SACRAMENTO, CA 958120806
Gen County:	Not reported
TSD EPA ID:	CAT080010101
TSD County:	Not reported
Waste Category:	Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method:	Transfer Station
Tons:	.0250
Facility County:	San Bernardino

Year:	1996
Gepaid:	CLU960003968
Contact:	EVA JEAN HOLTON
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	DTSC CLU/ERU
Mailing City,St,Zip:	SACRAMENTO, CA 958120806
Gen County:	Not reported
TSD EPA ID:	CAT080010101
TSD County:	Not reported
Waste Category:	Other inorganic solid waste
Disposal Method:	Treatment, Tank
Tons:	.0050
Facility County:	San Bernardino

Year:	1996
Gepaid:	CLU960003968
Contact:	EVA JEAN HOLTON
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	DTSC CLU/ERU
Mailing City,St,Zip:	SACRAMENTO, CA 958120806
Gen County:	Not reported
TSD EPA ID:	CAT080010101
TSD County:	Not reported
Waste Category:	Liquids with pH <= 2
Disposal Method:	Treatment, Tank
Tons:	.0125
Facility County:	San Bernardino

Year:	1996
Gepaid:	CLU960003968
Contact:	EVA JEAN HOLTON
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	DTSC CLU/ERU
Mailing City,St,Zip:	SACRAMENTO, CA 958120806

EVA JEAN HORRIDGE (Continued) **S113180982**

Gen County: Not reported
TSD EPA ID: CAT080010101
TSD County: Not reported
Waste Category: Alkaline solution without metals pH >= 12.5
Disposal Method: Treatment, Tank
Tons: .0050
Facility County: San Bernardino

U190 **INTOWN PROPERTIES INC/HUD** **HAZNET** **S112877826**
East **515 CYPRESS AVE** **N/A**
1/8-1/4 **COLTON, CA 92324**
0.155 mi.
816 ft. **Site 3 of 3 in cluster U**

Relative:
Lower

Actual:
1030 ft.

HAZNET:
Year: 1997
Gepaid: CAC001250072
Contact: HUD
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 6850 BROCKTON AVE #215
Mailing City,St,Zip: RIVERSIDE, CA 925060000
Gen County: Not reported
TSD EPA ID: CAD000088252
TSD County: Not reported
Waste Category: Household waste
Disposal Method: Transfer Station
Tons: .4586
Facility County: San Bernardino

M191 **TEXACO SERVICE STATION** **HIST CORTESE** **S102438785**
West **120 VALLEY** **LUST** **N/A**
1/8-1/4 **RIALTO, CA**
0.155 mi.
820 ft. **Site 25 of 31 in cluster M**

Relative:
Lower

Actual:
1063 ft.

CORTESE:
Region: CORTESE
Facility County Code: 36
Reg By: LTNKA
Reg Id: 083602887T

LUST REG 8:
Region: 8
County: San Bernardino
Regional Board: Santa Ana Region
Facility Status: Case Closed
Case Number: 083602887T
Local Case Num: 96045
Case Type: Soil only
Substance: Waste Oil
Qty Leaked: Not reported
Abate Method: Excavate and Treat - remove contaminated soil and treat (includes spreading or land farming)
Cross Street: RIVERSIDE
Enf Type: CLOS

TEXACO SERVICE STATION (Continued) **S102438785**

Funding:	Not reported
How Discovered:	OM
How Stopped:	Not reported
Leak Cause:	UNK
Leak Source:	UNK
Global ID:	T0607100424
How Stopped Date:	Not reported
Enter Date:	9/19/1996
Review Date:	12/11/1990
Prelim Assess:	Not reported
Discover Date:	12/11/1990
Enforcement Date:	Not reported
Close Date:	3/5/1997
Workplan:	Not reported
Pollution Char:	9/10/1996
Remed Plan:	Not reported
Remed Action:	Not reported
Monitoring:	Not reported
Enter Date:	9/19/1996
GW Qualifies:	Not reported
Soil Qualifies:	Not reported
Operator:	Not reported
Facility Contact:	Not reported
Interim:	Not reported
Oversite Program:	LUST
Latitude:	34.0705584
Longitude:	-117.3698618
MTBE Date:	Not reported
Max MTBE GW:	Not reported
MTBE Concentration:	0
Max MTBE Soil:	Not reported
MTBE Fuel:	0
MTBE Tested:	Not Required to be Tested.
MTBE Class:	*
Staff:	RS
Staff Initials:	BM7
Lead Agency:	Local Agency
Local Agency:	36000L
Hydr Basin #:	UPPER SANTA ANA VALL
Beneficial:	Not reported
Priority:	Not reported
Cleanup Fund Id:	Not reported
Work Suspended:	Not reported

Summary: Not reported

M192 **THRIFTY OIL #323/ ARCO #9695** **LUST** **S103464083**
West **111 VALLEY BLVD** **N/A**
1/8-1/4 **RIALTO, CA 92376**
0.161 mi.
850 ft. **Site 26 of 31 in cluster M**

Relative:
Lower

Actual:
1063 ft.

LUST REG 8:

Region:	8
County:	San Bernardino
Regional Board:	Santa Ana Region
Facility Status:	Preliminary site assessment underway
Case Number:	083603296T
Local Case Num:	98096

THRIFTY OIL #323/ ARCO #9695 (Continued) **S103464083**

Case Type:	Soil only
Substance:	8006619, MTB
Qty Leaked:	Not reported
Abate Method:	Not reported
Cross Street:	RIVERSIDE
Enf Type:	Not reported
Funding:	Not reported
How Discovered:	Not reported
How Stopped:	Not reported
Leak Cause:	Not reported
Leak Source:	Not reported
Global ID:	T0607100519
How Stopped Date:	Not reported
Enter Date:	11/6/1998
Review Date:	Not reported
Prelim Assess:	1/1/1965
Discover Date:	12/29/1997
Enforcement Date:	Not reported
Close Date:	Not reported
Workplan:	Not reported
Pollution Char:	Not reported
Remed Plan:	Not reported
Remed Action:	Not reported
Monitoring:	Not reported
Enter Date:	11/6/1998
GW Qualifies:	=
Soil Qualifies:	=
Operator:	Not reported
Facility Contact:	Not reported
Interim:	Not reported
Oversite Program:	LUST
Latitude:	34.0703134
Longitude:	-117.3703439
MTBE Date:	11/15/2001
Max MTBE GW:	2.2
MTBE Concentration:	0
Max MTBE Soil:	10300
MTBE Fuel:	0
MTBE Tested:	MTBE Detected. Site tested for MTBE & MTBE detected
MTBE Class:	*
Staff:	VJJ
Staff Initials:	LH6
Lead Agency:	Local Agency
Local Agency:	36000L
Hydr Basin #:	UPPER SANTA ANA VALL
Beneficial:	MUN
Priority:	A2
Cleanup Fund Id:	Not reported
Work Suspended:	Not reported
Summary:	Not reported

M193 **HOMETOWN BUFFET #753** **San Bern. Co. Permit** **S102818483**
West **127 W VALLEY BLVD** **N/A**
1/8-1/4 **RIALTO, CA 92376**
0.164 mi.
866 ft. **Site 27 of 31 in cluster M**

Relative:
Lower

Actual:
1062 ft.

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0011224
Owner: BUFFETS, INC.
Permit Number: PT0019535
Permit Category: BULK CO2 AT RETAIL FOOD FACILITIES
Facility Status: ACTIVE
Expiration Date: 09/30/2010

M194 **VALLEY ANIMAL HOSPITAL** **HAZNET** **S113061777**
West **127 W VALLEY BLVD** **N/A**
1/8-1/4 **RIALTO, CA 92376**
0.164 mi.
866 ft. **Site 28 of 31 in cluster M**

Relative:
Lower

Actual:
1062 ft.

HAZNET:
Year: 1996
Gepaid: CAL000106539
Contact: KENNETH COX
Telephone: 9098732384
Mailing Name: Not reported
Mailing Address: 127 W VALLEY BLVD
Mailing City,St,Zip: RIALTO, CA 923760000
Gen County: Not reported
TSD EPA ID: CAD983604000
TSD County: Not reported
Waste Category: Photochemicals/photoprocessing waste
Disposal Method: Recycler
Tons: .0625
Facility County: San Bernardino

Year: 1995
Gepaid: CAL000106539
Contact: KENNETH COX
Telephone: 9098732384
Mailing Name: Not reported
Mailing Address: 127 W VALLEY BLVD
Mailing City,St,Zip: RIALTO, CA 923760000
Gen County: Not reported
TSD EPA ID: CAD983604000
TSD County: Not reported
Waste Category: Photochemicals/photoprocessing waste
Disposal Method: Recycler
Tons: .0834
Facility County: San Bernardino

T195 **CIRCLE K STORE #627** **RCRA-SQG** **1000174015**
ESE **990 VALLEY BLVD** **FINDS** **CAD981679590**
1/8-1/4 **COLTON, CA 92324** **HIST UST**
0.168 mi.
888 ft. **Site 4 of 5 in cluster T**

Relative:
Lower

Actual:
1019 ft.

RCRA-SQG:

Date form received by agency:	09/01/1996
Facility name:	CIRCLE K STORE #627
Facility address:	990 VALLEY BLVD COLTON, CA 92324
EPA ID:	CAD981679590
Mailing address:	5811 MANZANITA AVE CARMICHAEL, CA 95608
Contact:	Not reported
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	09
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	NOT REQUIRED
Owner/operator address:	NOT REQUIRED NOT REQUIRED, ME 99999
Owner/operator country:	Not reported
Owner/operator telephone:	(415) 555-1212
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	CIRCLE K CORP
Owner/operator address:	NOT REQUIRED NOT REQUIRED, ME 99999
Owner/operator country:	Not reported
Owner/operator telephone:	(415) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No

CIRCLE K STORE #627 (Continued) **1000174015**

Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 10/16/1986
Facility name: CIRCLE K STORE #627
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110002748849

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HIST UST:
Region: STATE
Facility ID: 00000013599
Facility Type: Gas Station
Other Type: Not reported
Total Tanks: 0002
Contact Name: KEN ZIMMERMAN
Telephone: 7148252135
Owner Name: CIRCLE K CORPORATION
Owner Address: 4500 SOUTH 40TH STREET
Owner City,St,Zip: PHOENIX, AZ 85040

Tank Num: 001
Container Num: 1
Year Installed: Not reported
Tank Capacity: 00009940
Tank Used for: PRODUCT
Type of Fuel: REGULAR
Tank Construction: Not reported
Leak Detection: Stock Inventor

Tank Num: 002
Container Num: 2
Year Installed: Not reported
Tank Capacity: 00009940
Tank Used for: PRODUCT
Type of Fuel: UNLEADED
Tank Construction: Not reported
Leak Detection: Stock Inventor

M196
West
1/8-1/4
0.170 mi.
896 ft.

TEXACO SERVICE STATION
120 W VALLEY BLVD
RIALTO, CA 92376

Site 29 of 31 in cluster M

LUST **S100946308**
N/A

Relative:
Lower

Actual:
1062 ft.

LUST:

Region:	STATE
Global Id:	T0607100424
Latitude:	34.070942
Longitude:	-117.370748
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	03/05/1997
Lead Agency:	SAN BERNARDINO COUNTY
Case Worker:	BM7
Local Agency:	Not reported
RB Case Number:	083602887T
LOC Case Number:	96045
File Location:	Local Agency
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Waste Oil / Motor / Hydraulic / Lubricating
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607100424
Contact Type:	Regional Board Caseworker
Contact Name:	ROSE SCOTT
Organization Name:	SANTA ANA RWQCB (REGION 8)
Address:	3737 MAIN STREET, SUITE 500
City:	RIVERSIDE
Email:	rscott@waterboards.ca.gov
Phone Number:	9513206375

Regulatory Activities:

Global Id:	T0607100424
Action Type:	ENFORCEMENT
Date:	03/05/1997
Action:	Closure/No Further Action Letter

Global Id:	T0607100424
Action Type:	Other
Date:	01/01/1950
Action:	Leak Discovery

Global Id:	T0607100424
Action Type:	Other
Date:	01/01/1950
Action:	Leak Reported

Q197
NNE
1/8-1/4
0.178 mi.
941 ft.

HUD
1641 IRON HORSE CIR
COLTON, CA 92324

Site 6 of 7 in cluster Q

HAZNET **S112880836**
N/A

Relative:
Higher

Actual:
1111 ft.

HAZNET:

Year:	1997
Gepaid:	CAC001304672
Contact:	HUD
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	2086 SOUTH E ST STE 204
Mailing City,St,Zip:	SAN BERNARDINO, CA 924080000
Gen County:	Not reported
TSD EPA ID:	CAD000088252
TSD County:	Not reported
Waste Category:	Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method:	Transfer Station
Tons:	.0125
Facility County:	San Bernardino

Year:	1997
Gepaid:	CAC001304672
Contact:	HUD
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	2086 SOUTH E ST STE 204
Mailing City,St,Zip:	SAN BERNARDINO, CA 924080000
Gen County:	Not reported
TSD EPA ID:	CAD000088252
TSD County:	Not reported
Waste Category:	Alkaline solution without metals pH >= 12.5
Disposal Method:	Transfer Station
Tons:	.0041
Facility County:	San Bernardino

Q198
NNE
1/8-1/4
0.180 mi.
951 ft.

ASSETT MANAGEMENT SPECIALIST
1620 IRON HORSE CIRCLE
COLTON, CA 92324

Site 7 of 7 in cluster Q

HAZNET **S112890634**
N/A

Relative:
Higher

Actual:
1107 ft.

HAZNET:

Year:	1999
Gepaid:	CAC001427424
Contact:	ERNIE STEFKOVIC
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	1141 POMONA RD STE D
Mailing City,St,Zip:	CORONA, CA 917200000
Gen County:	Not reported
TSD EPA ID:	CAD982444481
TSD County:	Not reported
Waste Category:	Household waste
Disposal Method:	Transfer Station
Tons:	.0675
Facility County:	San Bernardino

M199
West
1/8-1/4
0.188 mi.
991 ft.

PAUL HUBBS CONSTRUCTION CO.
140 W VALLEY BLVD
RIALTO, CA 92376

Site 30 of 31 in cluster M

HIST UST | **U001575550** | **N/A**

Relative:
Lower

Actual:
1061 ft.

HIST UST:

Region:	STATE
Facility ID:	00000035560
Facility Type:	Other
Other Type:	CONSTRUCTION YARD
Total Tanks:	0004
Contact Name:	JAY HUBBS
Telephone:	7148772726
Owner Name:	PAUL J. HUBBS
Owner Address:	140 WEST VALLEY BLVD.
Owner City,St,Zip:	RIALTO, CA 92376

Tank Num:	001
Container Num:	1
Year Installed:	1964
Tank Capacity:	00010000
Tank Used for:	PRODUCT
Type of Fuel:	DIESEL
Tank Construction:	Not reported
Leak Detection:	Vapor Sniff Well

Tank Num:	002
Container Num:	2
Year Installed:	1964
Tank Capacity:	00006000
Tank Used for:	PRODUCT
Type of Fuel:	DIESEL
Tank Construction:	Not reported
Leak Detection:	Vapor Sniff Well

Tank Num:	003
Container Num:	3
Year Installed:	1964
Tank Capacity:	00004000
Tank Used for:	PRODUCT
Type of Fuel:	REGULAR
Tank Construction:	Not reported
Leak Detection:	Vapor Sniff Well

Tank Num:	004
Container Num:	4
Year Installed:	1964
Tank Capacity:	00004000
Tank Used for:	PRODUCT
Type of Fuel:	REGULAR
Tank Construction:	Not reported
Leak Detection:	Vapor Sniff Well

M200
West
1/8-1/4
0.188 mi.
991 ft.

PAUL HUBBS CONSTRUCTION CO.
140 W VALLEY BLVD
RIALTO, CA 92376

Site 31 of 31 in cluster M

CA FID UST
SWEEPS UST
EMI

S101619402
N/A

Relative:
Lower

Actual:
1061 ft.

CA FID UST:

Facility ID:	36002127
Regulated By:	UTNKI
Regulated ID:	00035560
Cortese Code:	Not reported
SIC Code:	Not reported
Facility Phone:	Not reported
Mail To:	Not reported
Mailing Address:	140 W VALLEY BLVD
Mailing Address 2:	Not reported
Mailing City,St,Zip:	RIALTO 92376
Contact:	Not reported
Contact Phone:	Not reported
DUNs Number:	Not reported
NPDES Number:	Not reported
EPA ID:	Not reported
Comments:	Not reported
Status:	Inactive

SWEEPS UST:

Status:	Not reported
Comp Number:	35560
Number:	Not reported
Board Of Equalization:	44-020912
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	36-000-035560-000001
Actv Date:	Not reported
Capacity:	10000
Tank Use:	M.V. FUEL
Stg:	PRODUCT
Content:	DIESEL
Number Of Tanks:	5

Status:	Not reported
Comp Number:	35560
Number:	Not reported
Board Of Equalization:	44-020912
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	36-000-035560-000002
Actv Date:	Not reported
Capacity:	6000
Tank Use:	M.V. FUEL
Stg:	PRODUCT
Content:	DIESEL
Number Of Tanks:	Not reported

PAUL HUBBS CONSTRUCTION CO. (Continued) **S101619402**

Status: Not reported
Comp Number: 35560
Number: Not reported
Board Of Equalization: 44-020912
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 36-000-035560-000003
Actv Date: Not reported
Capacity: 4000
Tank Use: M.V. FUEL
Stg: PRODUCT
Content: LEADED
Number Of Tanks: Not reported

Status: Not reported
Comp Number: 35560
Number: Not reported
Board Of Equalization: 44-020912
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 36-000-035560-000004
Actv Date: Not reported
Capacity: 4000
Tank Use: M.V. FUEL
Stg: PRODUCT
Content: LEADED
Number Of Tanks: Not reported

Status: Not reported
Comp Number: 35560
Number: Not reported
Board Of Equalization: 44-020912
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 36-000-035560-000005
Actv Date: Not reported
Capacity: 4000
Tank Use: M.V. FUEL
Stg: PRODUCT
Content: LEADED
Number Of Tanks: Not reported

EMI:
Year: 1990
County Code: 36
Air Basin: SC
Facility ID: 30510
Air District Name: SC

PAUL HUBBS CONSTRUCTION CO. (Continued) **S101619402**

SIC Code:	0
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	1
NOX - Oxides of Nitrogen Tons/Yr:	2
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

O201 **HUD** **HAZNET** **S112880341**
North **1851 GOLDEN SPIKE DR** **N/A**
1/8-1/4 **COLTON, CA 92324**
0.188 mi.
993 ft. **Site 5 of 5 in cluster O**

Relative:
Higher

Actual:
1130 ft.

HAZNET:

Year:	1997
Gepaid:	CAC001299880
Contact:	HUD
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	INTOWN PROPERTIES
Mailing City,St,Zip:	SAN BERNARDINO, CA 924080000
Gen County:	Not reported
TSD EPA ID:	CAD000088252
TSD County:	Not reported
Waste Category:	Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method:	Transfer Station
Tons:	.0417
Facility County:	San Bernardino

---

202 **INTOWN PROPERTIES** **HAZNET** **S112842291**
NE **1201 CANTARA ST** **N/A**
1/8-1/4 **COLTON, CA 92324**
0.195 mi.
1028 ft.

Relative:
Higher

Actual:
1101 ft.

HAZNET:

Year:	1997
Gepaid:	CAC000744872
Contact:	INTOWN PROPERTIES
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	2086 SOUTH E ST STE 204
Mailing City,St,Zip:	SAN BERNARDINO, CA 924080000
Gen County:	Not reported
TSD EPA ID:	CAD028409019
TSD County:	Not reported
Waste Category:	Household waste
Disposal Method:	Transfer Station
Tons:	.0550
Facility County:	San Bernardino

INTOWN PROPERTIES (Continued) **S112842291**

Year:	1997
Gepaid:	CAC000744872
Contact:	INTOWN PROPERTIES
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	2086 SOUTH E ST STE 204
Mailing City,St,Zip:	SAN BERNARDINO, CA 924080000
Gen County:	Not reported
TSD EPA ID:	CAD028409019
TSD County:	Not reported
Waste Category:	Household waste
Disposal Method:	Treatment, Tank
Tons:	.4000
Facility County:	San Bernardino

203
East
1/8-1/4
0.195 mi.
1031 ft.

981 W C ST, APT 9
COLTON, CA 92324

CDL **S107537359**
N/A

Relative:
Lower

Actual:
1038 ft.

CDL:

Facility ID:	200111082
Lab Type:	Illegal Drug Lab (L) - location where an illegal drug lab was operated or drug lab equipment and/or materials were stored.

204
WNW
1/8-1/4
0.196 mi.
1033 ft.

RIALTO VALUE CENTER
1505 SOUTH RIVERSIDE AVENUE
RIALTO, CA 92376

HAZNET **S112840417**
N/A

Relative:
Higher

Actual:
1086 ft.

HAZNET:

Year:	1994
Gepaid:	CAC000724160
Contact:	DAVE BACA
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	7119 ARLINGTON
Mailing City,St,Zip:	RIVERSIDE, CA 925030000
Gen County:	Not reported
TSD EPA ID:	CAD000088252
TSD County:	Not reported
Waste Category:	Unspecified solvent mixture
Disposal Method:	Transfer Station
Tons:	.4586
Facility County:	San Bernardino

R205
NNW
1/8-1/4
0.223 mi.
1178 ft.

INTOWN PROPERTIES, INC/HUD
1988 CLUSTER PINE RD
COLTON, CA 92324

Site 3 of 3 in cluster R

HAZNET **S112865845**
N/A

Relative:
Higher

Actual:
1140 ft.

HAZNET:

Year:	1998
Gepaid:	CAC001082016
Contact:	HUD
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	2086 S "E" ST, STE 204
Mailing City,St,Zip:	SAN BERNARDINO, CA 924080000
Gen County:	Not reported
TSD EPA ID:	CAD982444481
TSD County:	Not reported
Waste Category:	Household waste
Disposal Method:	Transfer Station
Tons:	.0291
Facility County:	San Bernardino

206
ENE
1/8-1/4
0.227 mi.
1199 ft.

R. A. DEAN & ASSOC.

SAN BERNARDINO (County), CA

UIC **S111646368**
N/A

Relative:
Higher

Actual:
1094 ft.

UIC:

API Number:	07100048
Confidential Well:	N
Well Number:	1
Lease Name:	Higgs
Well Located On A BLW Lease:	N
Field Name:	Any Field
Area Name:	Any Area
Section:	18
Township:	01S
Range:	04W
Base And Meridian; Part Of The PLSS:	SB
Elevation:	Not reported
Location Desc:	Not reported
Latitude:	34.07914
Longitude:	-117.3449
GIS Source Code:	hud
Comments:	Not reported

V207
SW
1/8-1/4
0.233 mi.
1228 ft.

SOUTHERN PACIFIC TRAN/CLT
200 MARION WAY
BLOOMINGTON, CA 92316

Site 1 of 4 in cluster V

Toxic Pits **S100676364**
HIST CORTESE **N/A**
LUST
SWEEPS UST
EMI

Relative:
Lower

Actual:
1047 ft.

Toxic Pits:

Region:	08
Task #:	88005
Owner:	SOUTHERN PACIFIC TRANS. CO.
1/2 Mi Limit:	Y

SOUTHERN PACIFIC TRAN/CLT (Continued) **S100676364**

Num. of Pits: 1
Cease Discharge Due: 06/30/90
Cease Discharge Complete: 04/11/89
Closure Due: 06/30/90
Closure Completed: 02/21/91
Status: CLOSED
Hydro Geological Assessment Report Due: / /
Final Hydro Geological Assessment Review Completed: / /

CORTESE:
Region: CORTESE
Facility County Code: 36
Reg By: LTNKA
Reg Id: 083600986T

LUST:
Region: STATE
Global Id: T0607100106
Latitude: 34.0665474
Longitude: -117.3680969
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 03/28/1991
Lead Agency: SAN BERNARDINO COUNTY
Case Worker: CR2
Local Agency: SAN BERNARDINO COUNTY
RB Case Number: 083600986T
LOC Case Number: 87003
File Location: Local Agency
Potential Media Affect: Soil
Potential Contaminants of Concern: Diesel
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0607100106
Contact Type: Local Agency Caseworker
Contact Name: CATHERINE RICHARDS
Organization Name: SAN BERNARDINO COUNTY
Address: 620 SOUTH E STREET
City: SAN BERNARDINO
Email: crichards@sbcfire.org
Phone Number: 9093868419

Global Id: T0607100106
Contact Type: Regional Board Caseworker
Contact Name: PATRICIA HANNON
Organization Name: SANTA ANA RWQCB (REGION 8)
Address: 3737 MAIN STREET, SUITE 500
City: RIVERSIDE
Email: phannon@waterboards.ca.gov
Phone Number: Not reported

Regulatory Activities:
Global Id: T0607100106

SOUTHERN PACIFIC TRAN/CLT (Continued) **S100676364**

Action Type:	ENFORCEMENT
Date:	03/28/1991
Action:	Closure/No Further Action Letter
Global Id:	T0607100106
Action Type:	Other
Date:	01/01/1950
Action:	Leak Stopped
Global Id:	T0607100106
Action Type:	Other
Date:	01/01/1950
Action:	Leak Discovery
Global Id:	T0607100106
Action Type:	Other
Date:	01/01/1950
Action:	Leak Reported

LUST REG 8:

Region:	8
County:	San Bernardino
Regional Board:	Santa Ana Region
Facility Status:	Case Closed
Case Number:	083600986T
Local Case Num:	87003
Case Type:	Soil only
Substance:	Diesel
Qty Leaked:	Not reported
Abate Method:	Not reported
Cross Street:	ONE SPOT
Enf Type:	CLOS
Funding:	Not reported
How Discovered:	Tank Closure
How Stopped:	Not reported
Leak Cause:	UNK
Leak Source:	UNK
Global ID:	T0607100106
How Stopped Date:	3/22/1988
Enter Date:	8/24/1988
Review Date:	Not reported
Prelim Assess:	Not reported
Discover Date:	7/20/1988
Enforcement Date:	Not reported
Close Date:	3/28/1991
Workplan:	Not reported
Pollution Char:	8/24/1988
Remed Plan:	Not reported
Remed Action:	Not reported
Monitoring:	Not reported
Enter Date:	8/24/1988
GW Qualifies:	Not reported
Soil Qualifies:	Not reported
Operator:	Not reported
Facility Contact:	Not reported
Interim:	Not reported

SOUTHERN PACIFIC TRAN/CLT (Continued) **S100676364**

Oversite Program: LUST
Latitude: 34.0672235
Longitude: -117.3679377
MTBE Date: Not reported
Max MTBE GW: Not reported
MTBE Concentration: 0
Max MTBE Soil: Not reported
MTBE Fuel: 0
MTBE Tested: Not Required to be Tested.
MTBE Class: *
Staff: PAH
Staff Initials: CR2
Lead Agency: Local Agency
Local Agency: 36000L
Hydr Basin #: UPPER SANTA ANA VALL
Beneficial: Not reported
Priority: Not reported
Cleanup Fund Id: Not reported
Work Suspended: Not reported
Summary: Not reported

SWEEPS UST:
Status: Active
Comp Number: 5231
Number: 1
Board Of Equalization: 44-019903
Referral Date: 03-19-92
Action Date: 03-19-92
Created Date: 09-13-88
Tank Status: A
Owner Tank Id: Not reported
Swrcb Tank Id: 36-000-005231-000001
Actv Date: 09-13-88
Capacity: 1
Tank Use: UNKNOWN
Stg: P
Content: UNKNOWN
Number Of Tanks: 1

EMI:
Year: 1987
County Code: 36
Air Basin: SC
Facility ID: 1625
Air District Name: SC
SIC Code: 4463
Air District Name: SOUTH COAST AQMD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported
Total Organic Hydrocarbon Gases Tons/Yr: 0
Reactive Organic Gases Tons/Yr: 0
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers & Smllr Tons/Yr: 0

T208 **CIRCLE K #627** **SWEEPS UST** **S103956583**
ESE **990 VALLEY BLVD** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.251 mi.
1325 ft. **Site 5 of 5 in cluster T**

Relative:
Lower

Actual:
1016 ft.

SWEEPS UST:

Status:	Active
Comp Number:	13599
Number:	9
Board Of Equalization:	44-020476
Referral Date:	07-28-92
Action Date:	07-28-92
Created Date:	02-29-88
Tank Status:	A
Owner Tank Id:	1
Swrcb Tank Id:	36-000-013599-000001
Actv Date:	07-01-85
Capacity:	9940
Tank Use:	M.V. FUEL
Stg:	P
Content:	LEADED
Number Of Tanks:	2

Status:	Active
Comp Number:	13599
Number:	9
Board Of Equalization:	44-020476
Referral Date:	07-28-92
Action Date:	07-28-92
Created Date:	02-29-88
Tank Status:	A
Owner Tank Id:	2
Swrcb Tank Id:	36-000-013599-000002
Actv Date:	07-01-85
Capacity:	9940
Tank Use:	M.V. FUEL
Stg:	P
Content:	REG UNLEADED
Number Of Tanks:	Not reported

W209 **DUNCAN BROS INC** **San Bern. Co. Permit** **S103368013**
SW **1966 S DATE** **N/A**
1/4-1/2 **RIALTO, CA 92376**
0.258 mi.
1361 ft. **Site 1 of 9 in cluster W**

Relative:
Lower

Actual:
1037 ft.

San Bern. Co. Permit:

Region:	SAN BERNARDINO
Facility ID:	FA0002801
Owner:	DUNCAN BROS INC
Permit Number:	PT0004812
Permit Category:	HAZMAT HANDLER 11-25 EMPLOYEES
Facility Status:	ACTIVE
Expiration Date:	05/31/2013

Region:	SAN BERNARDINO
Facility ID:	FA0002801
Owner:	DUNCAN BROS INC
Permit Number:	PT0021605

DUNCAN BROS INC (Continued) **S103368013**

Permit Category: CONDITIONALLY EXEMPT SMALL QUANTITY GENERATOR
Facility Status: ACTIVE
Expiration Date: 05/31/2013

X210 **CDL** **S107537190**
East **941 W. F STREET** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.262 mi.
1383 ft. **Site 1 of 3 in cluster X**

Relative:
Lower

Actual:
1026 ft.

CDL:
Facility ID: 199602001
Lab Type: Illegal Drug Lab (L) - location where an illegal drug lab was operated or drug lab equipment and/or materials were stored.

V211 **VULCAN STEEL CO** **San Bern. Co. Permit** **S104772095**
SW **270 E CAMERON WAY** **N/A**
1/4-1/2 **RIALTO, CA 92376**
0.264 mi.
1394 ft. **Site 2 of 4 in cluster V**

Relative:
Lower

Actual:
1043 ft.

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0007170
Owner: VSC INC
Permit Number: PT0004818
Permit Category: HAZARDOUS WASTE GENERATOR - 0-10 EMPLOYEES
Facility Status: ACTIVE
Expiration Date: 05/31/2013

Region: SAN BERNARDINO
Facility ID: FA0007170
Owner: VSC INC
Permit Number: PT0004817
Permit Category: HAZMAT HANDLER 0-10 EMPLOYEES (W/GEN PRMT)
Facility Status: ACTIVE
Expiration Date: 05/31/2013

V212 **VSC INC DBA VULCAN STEEL COMPANY** **HAZNET** **S113143833**
SW **270 CAMERON WAY** **N/A**
1/4-1/2 **BLOOMINGTON, CA 92316**
0.266 mi.
1407 ft. **Site 3 of 4 in cluster V**

Relative:
Lower

Actual:
1046 ft.

HAZNET:
Year: 2009
Gepaid: CAL000309926
Contact: CONNIE GONZALES
Telephone: 9098770975
Mailing Name: Not reported
Mailing Address: PO BOX 386
Mailing City,St,Zip: BLOOMINGTON, CA 923160000
Gen County: Not reported
TSD EPA ID: CAD982444481
TSD County: Not reported

VSC INC DBA VULCAN STEEL COMPANY (Continued) **S113143833**

Waste Category:	Other inorganic solid waste
Disposal Method:	Other Treatment
Tons:	0.1
Facility County:	San Bernardino
Year:	2009
Gepaid:	CAL000309926
Contact:	CONNIE GONZALES
Telephone:	9098770975
Mailing Name:	Not reported
Mailing Address:	PO BOX 386
Mailing City,St,Zip:	BLOOMINGTON, CA 923160000
Gen County:	Not reported
TSD EPA ID:	CAD982444481
TSD County:	Not reported
Waste Category:	Waste oil and mixed oil
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.969
Facility County:	San Bernardino
Year:	2009
Gepaid:	CAL000309926
Contact:	CONNIE GONZALES
Telephone:	9098770975
Mailing Name:	Not reported
Mailing Address:	PO BOX 386
Mailing City,St,Zip:	BLOOMINGTON, CA 923160000
Gen County:	Not reported
TSD EPA ID:	CAD982444481
TSD County:	Not reported
Waste Category:	Other empty containers 30 gallons or more
Disposal Method:	Other Treatment
Tons:	0.025
Facility County:	San Bernardino
Year:	2008
Gepaid:	CAL000309926
Contact:	CONNIE GONZALES
Telephone:	9098770975
Mailing Name:	Not reported
Mailing Address:	PO BOX 386
Mailing City,St,Zip:	BLOOMINGTON, CA 923160000
Gen County:	Not reported
TSD EPA ID:	CAD028409019
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.9
Facility County:	San Bernardino

Y213 **CLEM TRANS INC** **LUST** **S105050725**
West **213 VALLEY BLVD.** **N/A**
1/4-1/2 **RIALTO, CA 92376**
0.270 mi.
1423 ft. **Site 1 of 16 in cluster Y**

Relative:
Lower

Actual:
1060 ft.

LUST REG 8:

Region:	8
County:	San Bernardino
Regional Board:	Santa Ana Region
Facility Status:	Case Closed
Case Number:	083603808T
Local Case Num:	2000021
Case Type:	Soil only
Substance:	Diesel
Qty Leaked:	Not reported
Abate Method:	Not reported
Cross Street:	Not reported
Enf Type:	Not reported
Funding:	Not reported
How Discovered:	Tank Closure
How Stopped:	Not reported
Leak Cause:	UNK
Leak Source:	UNK
Global ID:	T0607199297
How Stopped Date:	3/20/2000
Enter Date:	Not reported
Review Date:	9/15/2000
Prelim Assess:	Not reported
Discover Date:	3/20/2000
Enforcement Date:	Not reported
Close Date:	8/26/2004
Workplan:	Not reported
Pollution Char:	4/22/2004
Remed Plan:	Not reported
Remed Action:	Not reported
Monitoring:	Not reported
Enter Date:	Not reported
GW Qualifies:	Not reported
Soil Qualifies:	Not reported
Operator:	Not reported
Facility Contact:	Not reported
Interim:	Not reported
Oversite Program:	LUST
Latitude:	34.070363
Longitude:	-117.371411
MTBE Date:	Not reported
Max MTBE GW:	Not reported
MTBE Concentration:	0
Max MTBE Soil:	Not reported
MTBE Fuel:	0
MTBE Tested:	Not Required to be Tested.
MTBE Class:	*
Staff:	RS
Staff Initials:	JC3
Lead Agency:	Local Agency
Local Agency:	36000L
Hydr Basin #:	UPPER SANTA ANA VALL
Beneficial:	GWR, MUN

CLEM TRANS INC (Continued) **S105050725**

Priority: Not reported
Cleanup Fund Id: Not reported
Work Suspended: Not reported
Summary: Haz Mat incident report filed : SAN BERNARDINO COUNTY FIRE DEPT. HAZMAT HAS ORDERED A SITE INVESTIGATION

Y214 **CLEMONS, G.** **CA FID UST** **S101619398**
West **213 W VALLEY BLVD** **SWEEPS UST** **N/A**
1/4-1/2 **RIALTO, CA 92376**
0.270 mi.
1423 ft. **Site 2 of 16 in cluster Y**

Relative:
Lower

Actual:
1060 ft.

CA FID UST:
Facility ID: 36009284
Regulated By: UTNKA
Regulated ID: 00068692
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: Not reported
Mail To: Not reported
Mailing Address: P O BOX
Mailing Address 2: Not reported
Mailing City,St,Zip: RIALTO 92376
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Active

SWEEPS UST:
Status: Active
Comp Number: 68692
Number: 9
Board Of Equalization: 44-021507
Referral Date: 09-10-91
Action Date: 09-10-91
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 2001
Swrcb Tank Id: 36-000-068692-000001
Actv Date: 08-25-88
Capacity: 10000
Tank Use: M.V. FUEL
Stg: P
Content: DIESEL
Number Of Tanks: 2

Status: Active
Comp Number: 68692
Number: 9
Board Of Equalization: 44-021507
Referral Date: 09-10-91
Action Date: 09-10-91
Created Date: 02-29-88
Tank Status: A

CLEMONS, G. (Continued) **S101619398**

Owner Tank Id:	2002
Swrcb Tank Id:	36-000-068692-000002
Actv Date:	08-25-88
Capacity:	10000
Tank Use:	M.V. FUEL
Stg:	P
Content:	DIESEL
Number Of Tanks:	Not reported

Y215 **CLEM-TRANS, INC.** **LUST** **U001575529**
West **213 W VALLEY BLVD** **HIST UST** **N/A**
1/4-1/2 **RIALTO, CA 92376** **San Bern. Co. Permit**
0.270 mi.
1423 ft. **Site 3 of 16 in cluster Y**

Relative:
Lower

Actual:
1060 ft.

LUST:

Region:	STATE
Global Id:	T0607199297
Latitude:	34.070363
Longitude:	-117.371411
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	08/26/2004
Lead Agency:	SAN BERNARDINO COUNTY
Case Worker:	JC
Local Agency:	SAN BERNARDINO COUNTY
RB Case Number:	083603808T
LOC Case Number:	2000021
File Location:	Local Agency
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Diesel
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607199297
Contact Type:	Local Agency Caseworker
Contact Name:	JACKSON CRUTSINGER
Organization Name:	SAN BERNARDINO COUNTY
Address:	620 SOUTH E STREET
City:	SAN BERNARDINO
Email:	jcrutsinger@sbcfire.org
Phone Number:	Not reported

Global Id:	T0607199297
Contact Type:	Regional Board Caseworker
Contact Name:	ROSE SCOTT
Organization Name:	SANTA ANA RWQCB (REGION 8)
Address:	3737 MAIN STREET, SUITE 500
City:	RIVERSIDE
Email:	rscott@waterboards.ca.gov
Phone Number:	9513206375

Regulatory Activities:

Global Id:	T0607199297
Action Type:	Other
Date:	01/01/1950

CLEM-TRANS, INC. (Continued) **U001575529**

Action: Leak Stopped

Global Id: T0607199297
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

Global Id: T0607199297
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

Global Id: T0607199297
Action Type: REMEDIATION
Date: 01/01/1950
Action: Not reported

HIST UST:
Region: STATE
Facility ID: 00000068692
Facility Type: Other
Other Type: PARCEL DELIVERY
Total Tanks: 0002
Contact Name: G. M. CLEMONS
Telephone: 7148774450
Owner Name: CLEM-TRANS, INC.
Owner Address: 213 WEST VALLEY BOULEVARD
Owner City,St,Zip: RIALTO, CA 92376

Tank Num: 001
Container Num: 2001
Year Installed: 1978
Tank Capacity: 00010000
Tank Used for: WASTE
Type of Fuel: 4
Tank Construction: Unkown inches
Leak Detection: Pressure Test

Tank Num: 002
Container Num: 2002
Year Installed: 1978
Tank Capacity: 00010000
Tank Used for: PRODUCT
Type of Fuel: DIESEL
Tank Construction: Not reported
Leak Detection: Pressure Test

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0002227
Owner: CLEMONS, GLORY
Permit Number: PT0002373
Permit Category: SPECIAL GENERATOR
Facility Status: INACTIVE
Expiration Date: 11/30/2011

CLEM-TRANS, INC. (Continued) **U001575529**

Region: SAN BERNARDINO
Facility ID: FA0002227
Owner: CLEMONS, GLORY
Permit Number: PT0002372
Permit Category: SPECIAL HANDLER
Facility Status: INACTIVE
Expiration Date: 11/30/2010

Z216 **MILES PRESERVATION LLC** **HAZNET** **S112973151**
NNW **2070 BUTTONWOOD ST** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.270 mi.
1426 ft. **Site 1 of 3 in cluster Z**

Relative:
Higher

Actual:
1138 ft.

HAZNET:
Year: 2008
Gepaid: CAC002634932
Contact: JOSH BIGALOW
Telephone: 9518083346
Mailing Name: Not reported
Mailing Address: PO BOX 1162
Mailing City,St,Zip: NUEVO, CA 925671162
Gen County: Not reported
TSD EPA ID: CAD982444481
TSD County: Not reported
Waste Category: Household waste
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.01
Facility County: San Bernardino

AA217 **CDL** **S108723644**
North **1822 W ADMIRALTY ST** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.272 mi.
1435 ft. **Site 1 of 4 in cluster AA**

Relative:
Higher

Actual:
1134 ft.

CDL:
Facility ID: 200706020
Lab Type: Illegal Drug Lab (L) - location where an illegal drug lab was operated or drug lab equipment and/or materials were stored.

AA218 **1822 ADMIRALTY STREET** **US CDL** **1011858678**
North **1822 ADMIRALTY STREET** **N/A**
1/4-1/2 **COLTON, CA**
0.272 mi.
1435 ft. **Site 2 of 4 in cluster AA**

Relative:
Higher

Actual:
1134 ft.

US CDL:
Seizure Date: 6/15/2007

AA219 **US RE-ESTATE SERVICES INC** **HAZNET** **S112972144**
North **1800 ADMIRALTY ST** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.272 mi.
1435 ft. **Site 3 of 4 in cluster AA**

Relative:
Higher

Actual:
1134 ft.

HAZNET:

Year:	2008
Gepaid:	CAC002633319
Contact:	RYAN CURTIS
Telephone:	9495989920
Mailing Name:	Not reported
Mailing Address:	25520 COMMERCENTRE DR
Mailing City,St,Zip:	LAKE FOREST, CA 926308884
Gen County:	Not reported
TSD EPA ID:	CAD008364432
TSD County:	Not reported
Waste Category:	Other inorganic solid waste
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.005
Facility County:	San Bernardino

Year:	2008
Gepaid:	CAC002633319
Contact:	RYAN CURTIS
Telephone:	9495989920
Mailing Name:	Not reported
Mailing Address:	25520 COMMERCENTRE DR
Mailing City,St,Zip:	LAKE FOREST, CA 926308884
Gen County:	Not reported
TSD EPA ID:	CAD008364432
TSD County:	Not reported
Waste Category:	Unspecified organic liquid mixture
Disposal Method:	Fuel Blending Prior To Energy Recovery At Another Site
Tons:	0.075
Facility County:	San Bernardino

Year:	2008
Gepaid:	CAC002633319
Contact:	RYAN CURTIS
Telephone:	9495989920
Mailing Name:	Not reported
Mailing Address:	25520 COMMERCENTRE DR
Mailing City,St,Zip:	LAKE FOREST, CA 926308884
Gen County:	Not reported
TSD EPA ID:	CAD008364432
TSD County:	Not reported
Waste Category:	Waste oil and mixed oil
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.0375
Facility County:	San Bernardino

AA220
NNE
1/4-1/2
0.272 mi.
1435 ft.

1748 W ADMIRALTY ST
COLTON, CA 92324

Site 4 of 4 in cluster AA

EDR US Hist Auto Stat **1015272536**
N/A

Relative:
Higher

Actual:
1136 ft.

EDR Historical Auto Stations:
Name: UNIVERSAL MOBIL D J SERVICE
Year: 2001
Address: 1748 W ADMIRALTY ST

W221
SW
1/4-1/2
0.276 mi.
1456 ft.

DUNCAN BROS INC
1966 S DATE ST
BLOOMINGTON, CA 92316

Site 2 of 9 in cluster W

FINDS **1005692322**
SWEEPS UST **N/A**
San Bern. Co. Permit
EMI
US AIRS

Relative:
Lower

Actual:
1035 ft.

FINDS:

Registry ID: 110006176315

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

CRITERIA AND HAZARDOUS AIR POLLUTANT INVENTORY

SWEEPS UST:
Status: Active
Comp Number: 54092
Number: 9
Board Of Equalization: Not reported
Referral Date: 03-19-92
Action Date: 03-19-92
Created Date: 02-29-88
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: Not reported
Actv Date: Not reported
Capacity: Not reported
Tank Use: Not reported
Stg: Not reported
Content: Not reported
Number Of Tanks: Not reported

DUNCAN BROS INC (Continued) **1005692322**

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0005665
Owner: GILSON, JERRY
Permit Number: PT0000419
Permit Category: SPECIAL GENERATOR
Facility Status: ACTIVE
Expiration Date: 04/30/2013

Region: SAN BERNARDINO
Facility ID: FA0005665
Owner: GILSON, JERRY
Permit Number: PT0000420
Permit Category: SPECIAL HANDLER
Facility Status: ACTIVE
Expiration Date: 04/30/2013

EMI:

Year:	1987
County Code:	36
Air Basin:	SC
Facility ID:	50869
Air District Name:	SC
SIC Code:	3444
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	7
Reactive Organic Gases Tons/Yr:	6
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1990
County Code:	36
Air Basin:	SC
Facility ID:	50869
Air District Name:	SC
SIC Code:	3599
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	11
Reactive Organic Gases Tons/Yr:	3
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1993
County Code:	36
Air Basin:	SC
Facility ID:	50869

DUNCAN BROS INC (Continued) **1005692322**

Air District Name:	SC
SIC Code:	3599
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	9
Reactive Organic Gases Tons/Yr:	5
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1995
County Code:	36
Air Basin:	SC
Facility ID:	50869
Air District Name:	SC
SIC Code:	3599
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	9
Reactive Organic Gases Tons/Yr:	5
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1997
County Code:	36
Air Basin:	SC
Facility ID:	50869
Air District Name:	SC
SIC Code:	3599
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	19
Reactive Organic Gases Tons/Yr:	13
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1998
County Code:	36
Air Basin:	SC
Facility ID:	50869
Air District Name:	SC
SIC Code:	3599
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	19

DUNCAN BROS INC (Continued) **1005692322**

Reactive Organic Gases Tons/Yr:	13
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1999
County Code:	36
Air Basin:	SC
Facility ID:	50869
Air District Name:	SC
SIC Code:	3599
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	19
Reactive Organic Gases Tons/Yr:	13
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	2000
County Code:	36
Air Basin:	SC
Facility ID:	50869
Air District Name:	SC
SIC Code:	3599
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	19
Reactive Organic Gases Tons/Yr:	13
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	2001
County Code:	36
Air Basin:	SC
Facility ID:	50869
Air District Name:	SC
SIC Code:	3599
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	8
Reactive Organic Gases Tons/Yr:	7
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

DUNCAN BROS INC (Continued) **1005692322**

Year:	2002
County Code:	36
Air Basin:	SC
Facility ID:	50869
Air District Name:	SC
SIC Code:	3599
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	5
Reactive Organic Gases Tons/Yr:	5
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	2003
County Code:	36
Air Basin:	SC
Facility ID:	50869
Air District Name:	SC
SIC Code:	3599
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	5
Reactive Organic Gases Tons/Yr:	5
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	2004
County Code:	36
Air Basin:	SC
Facility ID:	50869
Air District Name:	SC
SIC Code:	3599
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	5.21056
Reactive Organic Gases Tons/Yr:	5.15
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	2005
County Code:	36
Air Basin:	SC
Facility ID:	50869
Air District Name:	SC
SIC Code:	3599

DUNCAN BROS INC (Continued) **1005692322**

Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.8003
Reactive Organic Gases Tons/Yr:	1.77851637
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	2006
County Code:	36
Air Basin:	SC
Facility ID:	50869
Air District Name:	SC
SIC Code:	3599
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2.258325741471808887
Reactive Organic Gases Tons/Yr:	2.231
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	2007
County Code:	36
Air Basin:	SC
Facility ID:	50869
Air District Name:	SC
SIC Code:	3599
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2.258325741471808887
Reactive Organic Gases Tons/Yr:	2.231
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	2007
County Code:	36
Air Basin:	SC
Facility ID:	50869
Air District Name:	SC
SIC Code:	3441
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.318300182204676586
Reactive Organic Gases Tons/Yr:	1.3
Carbon Monoxide Emissions Tons/Yr:	0

DUNCAN BROS INC (Continued) **1005692322**

NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers & Smllr Tons/Yr: 0

AIRS (AFS):

Compliance and Violation Data Major Sources:

EPA plant ID:	110002414138
Plant name:	DUNCAN BROS INC
Plant address:	1966 S DATE ST BLOOMINGTON, CA 92316
County:	SAN BERNARDINO
Region code:	09
Dunn & Bradst #:	Not reported
Air quality cntrl region:	024
Sic code:	3599
Sic code desc:	INDUSTRIAL MACHINERY, NEC
North Am. industrial classf:	221112
NAIC code description:	Fossil Fuel Electric Power Generation
Default compliance status:	IN COMPLIANCE - INSPECTION
Default classification:	ACTUAL OR POTENTIAL EMISSIONS ARE ABOVE THE APPLICABLE MAJOR SOURCE THRESHOLDS
Govt facility:	ALL OTHER FACILITIES NOT OWNED OR OPERATED BY A FEDERAL, STATE, OR LOCAL GOVERNMENT
Current HPV:	Not reported

Compliance and Enforcement Major Issues:

Air program:	TITLE V PERMITS
National action type:	MULTI MEDIA INSPECTION - LEVEL 2 OR GREATER
Date achieved:	010509
Penalty amount:	000000000
Air program:	TITLE V PERMITS
National action type:	COMPLIANCE CERTIFICATION EPA REVIEW
Date achieved:	020805
Penalty amount:	Not reported
Air program:	TITLE V PERMITS
National action type:	COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved:	050215
Penalty amount:	Not reported
Air program:	SIP SOURCE
National action type:	COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved:	050215
Penalty amount:	Not reported
Air program:	TITLE V PERMITS
National action type:	STATE CONDUCTED FCE / ON-SITE
Date achieved:	050610
Penalty amount:	Not reported
Air program:	SIP SOURCE
National action type:	STATE CONDUCTED FCE / ON-SITE
Date achieved:	050610

DUNCAN BROS INC (Continued) **1005692322**

Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 050610
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 050610
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V COMPLIANCE CERT DUE/RECEIVED BY
Date achieved: 060310
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 070223
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 070223
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V COMPLIANCE CERT DUE/RECEIVED BY
Date achieved: 070301
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 070301
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 070301
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 070301
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 070301
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 080124
Penalty amount: Not reported

DUNCAN BROS INC (Continued) **1005692322**

Air program: TITLE V PERMITS
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 080124
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V COMPLIANCE CERT DUE/RECEIVED BY
Date achieved: 080131
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 080527
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 080527
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 080527
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 080527
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 090220
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 090220
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V COMPLIANCE CERT DUE/RECEIVED BY
Date achieved: 090224
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 090603
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 090603
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED PCE/ ON-SITE

DUNCAN BROS INC (Continued) **1005692322**

Date achieved: 090604
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 090604
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 090604
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 090604
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 100226
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 100226
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V COMPLIANCE CERT DUE/RECEIVED BY
Date achieved: 100305
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 100603
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 100603
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 100603
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 100603
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 100603
Penalty amount: Not reported

DUNCAN BROS INC (Continued) **1005692322**

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 100603
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 110128
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 110128
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 110512
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 110512
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 110512
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 110512
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 110512
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 110512
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 120218
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 120218
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED FCE / ON-SITE

DUNCAN BROS INC (Continued) **1005692322**

Date achieved: 120605
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 120605
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 120605
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 120605
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 120605
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 120605
Penalty amount: Not reported

Historical Compliance Minor Sources:
State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1001
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1001
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1002
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1002
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1003
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1003
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1004
Air prog code hist file: 0

DUNCAN BROS INC (Continued) **1005692322**

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1004
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1101
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1101
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1102
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1102
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1103
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1103
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1104
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1104
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1201
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1201
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1202
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1202
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1203
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION

DUNCAN BROS INC (Continued) **1005692322**

Hist compliance date: 1203
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1204
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1204
Air prog code hist file: V

Permit Information:
Compliance plant ID: CA158
Permit number: 50869
Permit category: V
Permit category desc: TITLE V PERMIT - PLANT SP

Permit Source:
Compliance plant ID: CA158
Plant name: DUNCAN BROS INC
Plant address: 1966 S DATE ST
BLOOMINGTON, CA 92316

Event Information:
Compliance permit ID: CA158
Permit number: 50869
Event action type: IF
Event description: *PERMIT AUTHORITY ISSUES FINAL PERMIT
Event action #: 001
Event date: 20020204

W222 **1X DUNCAN BROS INC** **HAZNET** **S112836850**
SW **1966 SOUTH DATE STREET** **N/A**
1/4-1/2 **BLOOMINGTON, CA 92316**
0.276 mi.
1456 ft. **Site 3 of 9 in cluster W**

Relative:
Lower

Actual:
1035 ft.

HAZNET:
Year: 2002
Gepaid: CAC000033860
Contact: NORM GRABDNER
Telephone: 7148771911
Mailing Name: Not reported
Mailing Address: 1966 SOUTH DATE ST
Mailing City,St,Zip: BLOOMINGTON, CA 923160000
Gen County: Not reported
TSD EPA ID: CAD008252405
TSD County: Not reported
Waste Category: Unspecified solvent mixture
Disposal Method: Recycler
Tons: 0.22
Facility County: San Bernardino

Year: 1999
Gepaid: CAC000033860

1X DUNCAN BROS INC (Continued) **S112836850**

Contact:	Not reported
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	1966 SOUTH DATE ST
Mailing City,St,Zip:	BLOOMINGTON, CA 923160000
Gen County:	Not reported
TSD EPA ID:	CAD008252405
TSD County:	Not reported
Waste Category:	Unspecified solvent mixture
Disposal Method:	Not reported
Tons:	.2085
Facility County:	San Bernardino

W223 **DUNCAN BROS INC** **HAZNET** **S112900873**
SW **1966 S DATE ST** **N/A**
1/4-1/2 **BLOOMINGTON, CA 92316**
0.276 mi.
1456 ft. **Site 4 of 9 in cluster W**

Relative:
Lower

Actual:
1035 ft.

HAZNET:

Year:	1999
Gepaid:	CAC002175257
Contact:	DUNCAN BROS INC
Telephone:	9098771904
Mailing Name:	Not reported
Mailing Address:	1966 S DATE ST
Mailing City,St,Zip:	BLOOMINGTON, CA 923160000
Gen County:	Not reported
TSD EPA ID:	CAD008252405
TSD County:	Not reported
Waste Category:	Off-specification, aged or surplus organics
Disposal Method:	Recycler
Tons:	.8000
Facility County:	San Bernardino

Year:	1999
Gepaid:	CAC002175257
Contact:	DUNCAN BROS INC
Telephone:	9098771904
Mailing Name:	Not reported
Mailing Address:	1966 S DATE ST
Mailing City,St,Zip:	BLOOMINGTON, CA 923160000
Gen County:	Not reported
TSD EPA ID:	CAD008252405
TSD County:	Not reported
Waste Category:	Off-specification, aged or surplus organics
Disposal Method:	Recycler
Tons:	.5000
Facility County:	San Bernardino

Year:	1999
Gepaid:	CAC002175257
Contact:	DUNCAN BROS INC
Telephone:	9098771904
Mailing Name:	Not reported
Mailing Address:	1966 S DATE ST
Mailing City,St,Zip:	BLOOMINGTON, CA 923160000
Gen County:	Not reported

DUNCAN BROS INC (Continued) **S112900873**

TSD EPA ID: CAD008252405
TSD County: Not reported
Waste Category: Unspecified organic liquid mixture
Disposal Method: Not reported
Tons: .0000
Facility County: San Bernardino

W224 **DUNCAN BROS., INC.** **HIST UST** **U001574572**
SW **1966 S DATE AVE** **N/A**
1/4-1/2 **BLOOMINGTON, CA 92316**
0.276 mi.
1456 ft. **Site 5 of 9 in cluster W**

Relative:
Lower

Actual:
1035 ft.

HIST UST:
Region: STATE
Facility ID: 00000054092
Facility Type: Other
Other Type: STEEL FABRICATION
Total Tanks: 0001
Contact Name: MICHAEL DUNCAN
Telephone: 7148771904
Owner Name: CECIL D. OR CAROLYN L. DUNCAN
Owner Address: 1966 S. DATE ST.
Owner City,St,Zip: BLOOMINGTON, CA 92316

Tank Num: 001
Container Num: 1
Year Installed: Not reported
Tank Capacity: 00001000
Tank Used for: PRODUCT
Type of Fuel: DIESEL
Tank Construction: 10 gauge
Leak Detection: Stock Inventor

W225 **REMCO MACHINING & FABRICATION, INC** **HAZNET** **S113108611**
SW **1966 S DATE ST** **N/A**
1/4-1/2 **BLOOMINGTON, CA 92316**
0.276 mi.
1456 ft. **Site 6 of 9 in cluster W**

Relative:
Lower

Actual:
1035 ft.

HAZNET:
Year: 2009
Gepaid: CAL000214363
Contact: JERRY GILSON-PRESIDENT
Telephone: 9098773530
Mailing Name: Not reported
Mailing Address: 1966 S DATE ST
Mailing City,St,Zip: BLOOMINGTON, CA 923160000
Gen County: Not reported
TSD EPA ID: AZR000501510
TSD County: Not reported
Waste Category: Organic solids with halogens
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.1
Facility County: San Bernardino

REMCO MACHINING & FABRICATION, INC (Continued) **S113108611**

Year:	2007
Gepaid:	CAL000214363
Contact:	JERRY GILSON-PRESIDENT
Telephone:	9098773530
Mailing Name:	Not reported
Mailing Address:	1966 S DATE ST
Mailing City,St,Zip:	BLOOMINGTON, CA 923160000
Gen County:	Not reported
TSD EPA ID:	AZR000501510
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.06
Facility County:	San Bernardino

Year:	2006
Gepaid:	CAL000214363
Contact:	JERRY GILSON-PRESIDENT
Telephone:	9098773530
Mailing Name:	Not reported
Mailing Address:	1966 S DATE ST
Mailing City,St,Zip:	BLOOMINGTON, CA 923160000
Gen County:	Not reported
TSD EPA ID:	AZR000501510
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Absorption
Tons:	0.03
Facility County:	San Bernardino

Year:	2006
Gepaid:	CAL000214363
Contact:	JERRY GILSON-PRESIDENT
Telephone:	9098773530
Mailing Name:	Not reported
Mailing Address:	1966 S DATE ST
Mailing City,St,Zip:	BLOOMINGTON, CA 923160000
Gen County:	Not reported
TSD EPA ID:	CAT080033681
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Disposal, Land Fill
Tons:	0.15
Facility County:	San Bernardino

Year:	2001
Gepaid:	CAL000214363
Contact:	JERRY GILSON-PRESIDENT
Telephone:	9098773530
Mailing Name:	Not reported
Mailing Address:	1966 S DATE ST
Mailing City,St,Zip:	BLOOMINGTON, CA 923160000
Gen County:	Not reported
TSD EPA ID:	CAT000613927
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues less than 10 percent

REMCO MACHINING & FABRICATION, INC (Continued) **S113108611**

Disposal Method: Transfer Station
Tons: 0.13
Facility County: San Bernardino

Click this hyperlink while viewing on your computer to access
1 additional CA_HAZNET: record(s) in the EDR Site Report.

226
ESE
1/4-1/2
0.277 mi.
1463 ft.

SOUTHWESTERN BANDAG INC **EMI** **S106839822**
933 W. VALLEY BLVD. **N/A**
COLTON, CA 92324

Relative:
Lower

Actual:
1015 ft.

EMI:

Year:	1987
County Code:	36
Air Basin:	SC
Facility ID:	23430
Air District Name:	SC
SIC Code:	3011
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	1
Part. Matter 10 Micrometers & Smllr Tons/Yr:	1

Y227
West
1/4-1/2
0.279 mi.
1473 ft.

220 W VALLEY BLVD, UNIT #127 **CDL** **S107531053**
RIALTO, CA 92376 **N/A**

Site 4 of 16 in cluster Y

Relative:
Lower

Actual:
1060 ft.

CDL:

Facility ID:	200301070
Lab Type:	Illegal Drug Lab (L) - location where an illegal drug lab was operated or drug lab equipment and/or materials were stored.

Y228
West
1/4-1/2
0.279 mi.
1473 ft.

220 W. VALLEY BLVD **CHMIRS** **S100275374**
RIALTO, CA 92376 **N/A**

Site 5 of 16 in cluster Y

Relative:
Lower

Actual:
1060 ft.

CHMIRS:

OES Incident Number:	8910513
OES notification:	Not reported
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	28-JUN-89
Date Completed:	**28-JUN-89**

(Continued) **S100275374**

Property Use:	800
Agency Id Number:	36185
Agency Incident Number:	2764
Time Notified:	1619
Time Completed:	2145
Surrounding Area:	Not reported
Estimated Temperature:	85
Property Management:	P
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Involved?:	N
Resp Agncy Personel # Of Decontaminated:	0
Responding Agency Personel # Of Injuries:	0
Responding Agency Personel # Of Fatalities:	0
Others Number Of Decontaminated:	0
Others Number Of Injuries:	0
Others Number Of Fatalities:	0
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	KARL F. KOLODZIK
Report Date:	28-JUN-89
Comments:	Not reported
Facility Telephone:	714 820-2501
Waterway Involved:	Not reported
Waterway:	Not reported
Spill Site:	Not reported
Cleanup By:	Not reported
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	88-92
Agency:	Not reported
Incident Date:	Not reported
Admin Agency:	Not reported
Amount:	Not reported
Contained:	Not reported
Site Type:	Not reported
E Date:	15-MAY-90
Substance:	Not reported
Quantity Released:	Not reported
BBLS:	Not reported
Cups:	Not reported
CUFT:	Not reported
Gallons:	Not reported
Grams:	Not reported
Pounds:	Not reported

(Continued) **S100275374**

Liters:	Not reported
Ounces:	Not reported
Pints:	Not reported
Quarts:	Not reported
Sheen:	Not reported
Tons:	Not reported
Unknown:	Not reported
Evacuations:	Not reported
Number of Injuries:	Not reported
Number of Fatalities:	Not reported
Description:	Not reported

AB229 **CHMIRS** **S112829156**
WSW **1800 SOUTH RIVERSIDE AVENUE** **N/A**
1/4-1/2 **BLOOMINGTON, CA**
0.280 mi.
1480 ft. **Site 1 of 3 in cluster AB**

Relative:
Lower

Actual:
1075 ft.

CHMIRS:

OES Incident Number:	'12-4052	
OES notification:	07/12/2012	
OES Date:	Not reported	
OES Time:	Not reported	
Incident Date:	Not reported	
Date Completed:	**Not reported**	
Property Use:	Not reported	
Agency Id Number:	Not reported	
Agency Incident Number:	Not reported	
Time Notified:	Not reported	
Time Completed:	Not reported	
Surrounding Area:	Not reported	
Estimated Temperature:	Not reported	
Property Management:	Not reported	
Special Studies 1:	Not reported	
Special Studies 2:	Not reported	
Special Studies 3:	Not reported	
Special Studies 4:	Not reported	
Special Studies 5:	Not reported	
Special Studies 6:	Not reported	
More Than Two Substances Involved?:		Not reported
Resp Agncy Personel # Of Decontaminated:		Not reported
Responding Agency Personel # Of Injuries:		Not reported
Responding Agency Personel # Of Fatalities:		Not reported
Others Number Of Decontaminated:		Not reported
Others Number Of Injuries:		Not reported
Others Number Of Fatalities:		Not reported
Vehicle Make/year:	Not reported	
Vehicle License Number:	Not reported	
Vehicle State:	Not reported	
Vehicle Id Number:	Not reported	
CA/DOT/PUC/ICC Number:	Not reported	
Company Name:	Not reported	
Reporting Officer Name/ID:	Not reported	
Report Date:	Not reported	
Comments:	Not reported	
Facility Telephone:	Not reported	
Waterway Involved:	No	
Waterway:	Not reported	

(Continued) **S112829156**

Spill Site:	Merchant/Business
Cleanup By:	Patriot Environmental Contractor
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Gal(s)
Other:	Not reported
Date/Time:	1700
Year:	2012
Agency:	FedEx Ground
Incident Date:	7/12/2012
Admin Agency:	San Bernardino County Health Department
Amount:	Not reported
Contained:	Yes
Site Type:	Not reported
E Date:	Not reported
Substance:	Diesel Fuel
Quantity Released:	60
BBLS:	Not reported
Cups:	Not reported
CUFT:	Not reported
Gallons:	Not reported
Grams:	Not reported
Pounds:	Not reported
Liters:	Not reported
Ounces:	Not reported
Pints:	Not reported
Quarts:	Not reported
Sheen:	Not reported
Tons:	Not reported
Unknown:	Not reported
Evacuations:	Not reported
Number of Injuries:	Not reported
Number of Fatalities:	Not reported
Description:	Caller states a single vehicle accident resulted in a punctured big rig saddle tank. This resulted in the release of substance to the asphalt roadway.

X230 **CDL** **S103960333**
East **926 F ST** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.287 mi.
1514 ft. **Site 2 of 3 in cluster X**

Relative:
Lower

Actual:
1025 ft.

CDL:

Facility ID:	199702025
Lab Type:	Illegal Drug Lab (L) - location where an illegal drug lab was operated or drug lab equipment and/or materials were stored.

X231 **DENISE BOURNS** **HAZNET** **S113182073**
East **926 F STREET** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.287 mi.
1514 ft. **Site 3 of 3 in cluster X**

Relative:
Lower

Actual:
1025 ft.

HAZNET:

Year:	1997
Gepaid:	CLU970013751
Contact:	Not reported
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	PO BOX 806
Mailing City,St,Zip:	SACRAMENTO, CA 958120806
Gen County:	Not reported
TSD EPA ID:	CAD008302903
TSD County:	Not reported
Waste Category:	Other inorganic solid waste
Disposal Method:	Transfer Station
Tons:	.0500
Facility County:	San Bernardino

Year:	1997
Gepaid:	CLU970013751
Contact:	Not reported
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	PO BOX 806
Mailing City,St,Zip:	SACRAMENTO, CA 958120806
Gen County:	Not reported
TSD EPA ID:	CAD008302903
TSD County:	Not reported
Waste Category:	Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method:	Recycler
Tons:	.0500
Facility County:	San Bernardino

Year:	1997
Gepaid:	CLU970013751
Contact:	Not reported
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	PO BOX 806
Mailing City,St,Zip:	SACRAMENTO, CA 958120806
Gen County:	Not reported
TSD EPA ID:	CAD008302903
TSD County:	Not reported
Waste Category:	Liquids with pH <= 2
Disposal Method:	Transfer Station
Tons:	.0500
Facility County:	San Bernardino

W232
SW
1/4-1/2
0.287 mi.
1516 ft.

RIALTO RUBBISH — **HIST UST** — **1000292651**
210 CAMERON WAY — **N/A**
BLOOMINGTON, CA 92316

Site 7 of 9 in cluster W

Relative:
Lower

Actual:
1036 ft.

HIST UST:

Region:	STATE
Facility ID:	00000006636
Facility Type:	Other
Other Type:	REFUSE REMOVAL
Total Tanks:	0002
Contact Name:	COLE BURR
Telephone:	6192877555
Owner Name:	EDCO DISPOSAL CORP.
Owner Address:	6670 FEDERAL BLVD
Owner City,St,Zip:	LEMON GROVE, CA 92045
Tank Num:	001
Container Num:	17
Year Installed:	Not reported
Tank Capacity:	00010000
Tank Used for:	PRODUCT
Type of Fuel:	DIESEL
Tank Construction:	Not reported
Leak Detection:	Stock Inventor
Tank Num:	002
Container Num:	18
Year Installed:	Not reported
Tank Capacity:	00001000
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Tank Construction:	Not reported
Leak Detection:	Stock Inventor

AC233
NW
1/4-1/2
0.311 mi.
1640 ft.

1155 S RIVERSIDE AVE, #131 — **CDL** — **S107527457**
RIALTO, CA 92376 — **N/A**

Site 1 of 3 in cluster AC

Relative:
Higher

Actual:
1121 ft.

CDL:

Facility ID:	199710112
Lab Type:	Illegal Drug Lab (L) - location where an illegal drug lab was operated or drug lab equipment and/or materials were stored.

AC234
NW
1/4-1/2
0.311 mi.
1640 ft.

SANTIAGO PARKSIDE ESTATE INC — **HAZNET** — **S112974013**
1155 S RIVERSIDE AVE — **N/A**
RIALTO, CA 92376

Site 2 of 3 in cluster AC

Relative:
Higher

Actual:
1121 ft.

HAZNET:

Year:	2008
Gepaid:	CAC002636306
Contact:	WAYNE SIMMS
Telephone:	7149200180

SANTIAGO PARKSIDE ESTATE INC (Continued) **S112974013**

Mailing Name: Not reported
Mailing Address: 1155 S RIVERSIDE AVE
Mailing City,St,Zip: RIALTO, CA 92376
Gen County: Not reported
TSD EPA ID: CAD028409019
TSD County: Not reported
Waste Category: Off-specification, aged or surplus inorganics
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.00417
Facility County: San Bernardino

Year: 2008
Gepaid: CAC002636306
Contact: WAYNE SIMMS
Telephone: 7149200180
Mailing Name: Not reported
Mailing Address: 1155 S RIVERSIDE AVE
Mailing City,St,Zip: RIALTO, CA 92376
Gen County: Not reported
TSD EPA ID: CAD982444481
TSD County: Not reported
Waste Category: Off-specification, aged or surplus organics
Disposal Method: Other Treatment
Tons: 0.1749
Facility County: San Bernardino

Year: 2008
Gepaid: CAC002636306
Contact: WAYNE SIMMS
Telephone: 7149200180
Mailing Name: Not reported
Mailing Address: 1155 S RIVERSIDE AVE
Mailing City,St,Zip: RIALTO, CA 92376
Gen County: Not reported
TSD EPA ID: CAD008252405
TSD County: Not reported
Waste Category: Off-specification, aged or surplus organics
Disposal Method: Fuel Blending Prior To Energy Recovery At Another Site
Tons: 0.0594
Facility County: San Bernardino

Year: 2008
Gepaid: CAC002636306
Contact: WAYNE SIMMS
Telephone: 7149200180
Mailing Name: Not reported
Mailing Address: 1155 S RIVERSIDE AVE
Mailing City,St,Zip: RIALTO, CA 92376
Gen County: Not reported
TSD EPA ID: CAD028409019
TSD County: Not reported
Waste Category: Off-specification, aged or surplus organics
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.0066
Facility County: San Bernardino

Z235 **INTOWN PROPERTIES INC/HUD** **HAZNET** **S112887325**
NNW **1355 WHITEOAK** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.315 mi.
1662 ft. **Site 2 of 3 in cluster Z**

Relative:
Higher

Actual:
1142 ft.

HAZNET:

Year:	1998
Gepaid:	CAC001390160
Contact:	HUD
Telephone:	7149577333
Mailing Name:	Not reported
Mailing Address:	6850 BROCKTON AVE STE 215
Mailing City,St,Zip:	RIVERSIDE, CA 925060000
Gen County:	Not reported
TSD EPA ID:	CAD000088252
TSD County:	Not reported
Waste Category:	Household waste
Disposal Method:	Transfer Station
Tons:	.2293
Facility County:	San Bernardino

---

236 **HUD** **HAZNET** **S112880340**
North **1918 QUARTERMASTER** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.315 mi.
1663 ft.

Relative:
Higher

Actual:
1135 ft.

HAZNET:

Year:	1997
Gepaid:	CAC001299872
Contact:	HUD
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	INTOWN PROPERTIES
Mailing City,St,Zip:	SAN BERNARDINO, CA 924080000
Gen County:	Not reported
TSD EPA ID:	CAD000088252
TSD County:	Not reported
Waste Category:	Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method:	Transfer Station
Tons:	.0125
Facility County:	San Bernardino

AD237 **DALE JONES PHOTOGRAPHY** **RCRA-SQG** **1000197253**
East **915 W C ST** **FINDS** **CAD982483729**
1/4-1/2 **COLTON, CA 92324** **HAZNET**
0.316 mi.
1669 ft. **Site 1 of 2 in cluster AD**

Relative:
Lower

Actual:
1035 ft.

RCRA-SQG:

Date form received by agency:	03/09/1990
Facility name:	DALE JONES PHOTOGRAPHY
Facility address:	915 W C ST COLTON, CA 92324
EPA ID:	CAD982483729
Mailing address:	785 N LA CADENA SUITE A COLTON, CA 92324

DALE JONES PHOTOGRAPHY (Continued) **1000197253**

Contact: ENVIRONMENTAL MANAGER
Contact address: 915 W C ST
COLTON, CA 92324
Contact country: US
Contact telephone: (714) 825-6516
Contact email: Not reported
EPA Region: 09
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: DALE JONES
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110002826540

DALE JONES PHOTOGRAPHY (Continued) **1000197253**

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZNET:

Year:	1993
Gepaid:	CAD982483729
Contact:	Not reported
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	785 N LA CADENA #A
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	Not reported
TSD EPA ID:	CAD108040858
TSD County:	Not reported
Waste Category:	Photochemicals/photoprocessing waste
Disposal Method:	Recycler
Tons:	0.25009999999
Facility County:	San Bernardino

V238 **CHMIRS** **S111755511**
SW **2000 SOUTH SYCAMORE AVE** **N/A**
1/4-1/2 **BLOOMINGTON, CA 92316**
0.317 mi.
1672 ft. **Site 4 of 4 in cluster V**

Relative:
Lower

Actual:
1044 ft.

CHMIRS:

OES Incident Number:	11-3440
OES notification:	06/08/2011
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported

(Continued) **S111755511**

Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	No
Waterway:	Not reported
Spill Site:	Rail Road
Cleanup By:	Reporting Party
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Gal(s)
Other:	Not reported
Date/Time:	1237
Year:	2011
Agency:	UPRR
Incident Date:	6/8/2011
Admin Agency:	San Bernardino County Health Department
Amount:	Not reported
Contained:	Yes
Site Type:	Not reported
E Date:	Not reported
Substance:	Engine Oil
Quantity Released:	2-Jan
BBLS:	Not reported
Cups:	Not reported
CUFT:	Not reported
Gallons:	Not reported
Grams:	Not reported
Pounds:	Not reported
Liters:	Not reported
Ounces:	Not reported
Pints:	Not reported
Quarts:	Not reported
Sheen:	Not reported
Tons:	Not reported
Unknown:	Not reported
Evacuations:	Not reported
Number of Injuries:	Not reported
Number of Fatalities:	Not reported
Description:	RP states that locomotive UP2421 released 1-2 gallons of engine oil inside the Colton Railyard onto absorbent mats inside of the maintenance facility.

Z239 **HUD** **HAZNET** **S112880337**
NW **1401 CHERRYTREE RD** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.320 mi.
1689 ft. **Site 3 of 3 in cluster Z**

Relative:
Higher

Actual:
1128 ft.

HAZNET:

Year:	1997
Gepaid:	CAC001299848
Contact:	HUD
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	INTOWN PROPERTIES
Mailing City,St,Zip:	SAN BERNARDINO, CA 924080000
Gen County:	Not reported
TSD EPA ID:	CAD000088252
TSD County:	Not reported
Waste Category:	Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method:	Transfer Station
Tons:	.0834
Facility County:	San Bernardino

Year:	1997
Gepaid:	CAC001299848
Contact:	HUD
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	INTOWN PROPERTIES
Mailing City,St,Zip:	SAN BERNARDINO, CA 924080000
Gen County:	Not reported
TSD EPA ID:	CAD000088252
TSD County:	Not reported
Waste Category:	Alkaline solution without metals pH >= 12.5
Disposal Method:	Transfer Station
Tons:	.0166
Facility County:	San Bernardino

Year:	1997
Gepaid:	CAC001299848
Contact:	HUD
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	INTOWN PROPERTIES
Mailing City,St,Zip:	SAN BERNARDINO, CA 924080000
Gen County:	Not reported
TSD EPA ID:	CAD000088252
TSD County:	Not reported
Waste Category:	Unspecified solvent mixture
Disposal Method:	Transfer Station
Tons:	.0025
Facility County:	San Bernardino

AE240
NNW
1/4-1/2
0.326 mi.
1723 ft.

HUD
1365 CHRISTOBAL LN
COLTON, CA 92324

Site 1 of 2 in cluster AE

Relative:
Higher

Actual:
1143 ft.

HAZNET **S112880339**
N/A

HAZNET:

Year:	1997
Gepaid:	CAC001299864
Contact:	HUD
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	INTOWN PROPERTIES
Mailing City,St,Zip:	SAN BERNARDINO, CA 924080000
Gen County:	Not reported
TSD EPA ID:	CAD000088252
TSD County:	Not reported
Waste Category:	Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method:	Transfer Station
Tons:	.0834
Facility County:	San Bernardino

AE241
NNW
1/4-1/2
0.326 mi.
1723 ft.

HUD INTOWN PROPERTIES
1365 CHRISTOBAL LN N
COLTON, CA 92324

Site 2 of 2 in cluster AE

Relative:
Higher

Actual:
1143 ft.

HAZNET **S112898837**
N/A

HAZNET:

Year:	1998
Gepaid:	CAC002123312
Contact:	HUD
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	2086 S E ST STE 204
Mailing City,St,Zip:	SAN BERNARDINO, CA 924080000
Gen County:	Not reported
TSD EPA ID:	CAD982444481
TSD County:	Not reported
Waste Category:	Household waste
Disposal Method:	Transfer Station
Tons:	.0208
Facility County:	San Bernardino

Year:	1998
Gepaid:	CAC002123312
Contact:	HUD
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	2086 S E ST STE 204
Mailing City,St,Zip:	SAN BERNARDINO, CA 924080000
Gen County:	Not reported
TSD EPA ID:	CAD028409019
TSD County:	Not reported
Waste Category:	Household waste
Disposal Method:	Treatment, Tank
Tons:	.1042
Facility County:	San Bernardino

242
WNW
1/4-1/2
0.332 mi.
1752 ft.

1200 BLK N RIVERSIDE
RIALTO, CA

CHMIRS **S100223043**
N/A

Relative:
Higher

Actual:
1099 ft.

CHMIRS:

OES Incident Number:	9991950
OES notification:	Not reported
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	16-FEB-88
Date Completed:	**16-FEB-88**
Property Use:	Not reported
Agency Id Number:	36185
Agency Incident Number:	646
Time Notified:	926
Time Completed:	1115
Surrounding Area:	Not reported
Estimated Temperature:	77
Property Management:	C
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Involved?:	N
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	FREIGHT LINER/1980
Vehicle License Number:	16077P
Vehicle State:	NV
Vehicle Id Number:	185450
CA/DOT/PUC/ICC Number:	138206
Company Name:	TRULINE CORP
Reporting Officer Name/ID:	KARL F KOLODZIK
Report Date:	16-FEB-88
Comments:	N
Facility Telephone:	714 820-2501
Waterway Involved:	Not reported
Waterway:	Not reported
Spill Site:	Not reported
Cleanup By:	Not reported
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	88-92
Agency:	Not reported
Incident Date:	Not reported
Admin Agency:	Not reported
Amount:	Not reported

(Continued) **S100223043**

Contained:	Not reported
Site Type:	Not reported
E Date:	Not reported
Substance:	Not reported
Quantity Released:	Not reported
BBLS:	Not reported
Cups:	Not reported
CUFT:	Not reported
Gallons:	Not reported
Grams:	Not reported
Pounds:	Not reported
Liters:	Not reported
Ounces:	Not reported
Pints:	Not reported
Quarts:	Not reported
Sheen:	Not reported
Tons:	Not reported
Unknown:	Not reported
Evacuations:	Not reported
Number of Injuries:	Not reported
Number of Fatalities:	Not reported
Description:	Not reported

W243 **RIALTO RUBBISH SERVICES INC** **San Bern. Co. Permit** **S103962336**
SW **210 E CAMERON WAY** **N/A**
1/4-1/2 **RIALTO, CA 92376**
0.338 mi.
1785 ft. **Site 8 of 9 in cluster W**

Relative:
Lower

Actual:
1030 ft.

San Bern. Co. Permit:

Region:	SAN BERNARDINO
Facility ID:	FA0005700
Owner:	EDCO DISPOSAL CORP
Permit Number:	PT0002092
Permit Category:	SPECIAL HANDLER
Facility Status:	INACTIVE
Expiration Date:	05/31/2008

Region:	SAN BERNARDINO
Facility ID:	FA0005700
Owner:	EDCO DISPOSAL CORP
Permit Number:	PT0002091
Permit Category:	SPECIAL GENERATOR
Facility Status:	INACTIVE
Expiration Date:	05/31/2008

W244 **RIALTO RUBBISH** **SWEEPS UST** **S103641202**
SW **210 E CAMERON** **N/A**
1/4-1/2 **BLOOMINGTON, CA 92316**
0.339 mi.
1790 ft. **Site 9 of 9 in cluster W**

Relative:
Lower

Actual:
1028 ft.

SWEEPS UST:

Status:	Active
Comp Number:	6636
Number:	9

RIALTO RUBBISH (Continued) **S103641202**

Board Of Equalization: 44-019933
Referral Date: 03-19-92
Action Date: 03-19-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 17
Swrcb Tank Id: 36-000-006636-000001
Actv Date: 08-25-88
Capacity: 10000
Tank Use: M.V. FUEL
Stg: P
Content: DIESEL
Number Of Tanks: 2

Status: Active
Comp Number: 6636
Number: 9
Board Of Equalization: 44-019933
Referral Date: 03-19-92
Action Date: 03-19-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 18
Swrcb Tank Id: 36-000-006636-000002
Actv Date: 08-25-88
Capacity: 1000
Tank Use: M.V. FUEL
Stg: P
Content: REG UNLEADED
Number Of Tanks: Not reported

AD245 **CDL** **S107535526**
East **639 GRAND AVE** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.341 mi.
1798 ft. **Site 2 of 2 in cluster AD**

Relative:
Lower

Actual:
1031 ft.

CDL:
Facility ID: 199905061
Lab Type: Illegal Drug Lab (L) - location where an illegal drug lab was operated or drug lab equipment and/or materials were stored.

---

246 **FIRST PRIORITY PROPERTIES PRESERVATION** **HAZNET** **S112973880**
NNE **1398 N TOPSAIL AVE** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.344 mi.
1814 ft.

Relative:
Higher

Actual:
1134 ft.

HAZNET:
Year: 2008
Gepaid: CAC002636088
Contact: AARON SMITH
Telephone: 9516793311
Mailing Name: Not reported
Mailing Address: 25060 HANCOCK AVE STE 103-120
Mailing City,St,Zip: MURRIETA, CA 92562

FIRST PRIORITY PROPERTIES PRESERVATION (Continued) **S112973880**

Gen County: Not reported
TSD EPA ID: CAD982444481
TSD County: Not reported
Waste Category: Household waste
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.0025
Facility County: San Bernardino

AB247 **AMERIGAS PROPANE LP** **HAZNET** **S113154153**
WSW **1975 S RIVERSIDE AVE** **N/A**
1/4-1/2 **BLOOMINGTON, CA 92316**
0.346 mi.
1829 ft. **Site 2 of 3 in cluster AB**

Relative:
Lower

Actual:
1038 ft.

HAZNET:
Year: 2009
Gepaid: CAL000336896
Contact: MARC STEINBUCH
Telephone: 9098772642
Mailing Name: Not reported
Mailing Address: PO BOX 1300
Mailing City,St,Zip: COMMERCE CITY, CO 800220000
Gen County: Not reported
TSD EPA ID: CAD028409019
TSD County: Not reported
Waste Category: Off-specification, aged or surplus organics
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.1914
Facility County: San Bernardino

Year: 2009
Gepaid: CAL000336896
Contact: MARC STEINBUCH
Telephone: 9098772642
Mailing Name: Not reported
Mailing Address: PO BOX 1300
Mailing City,St,Zip: COMMERCE CITY, CO 800220000
Gen County: Not reported
TSD EPA ID: CAD982444481
TSD County: Not reported
Waste Category: Other inorganic solid waste
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.005
Facility County: San Bernardino

Year: 2009
Gepaid: CAL000336896
Contact: MARC STEINBUCH
Telephone: 9098772642
Mailing Name: Not reported
Mailing Address: PO BOX 1300
Mailing City,St,Zip: COMMERCE CITY, CO 800220000
Gen County: Not reported
TSD EPA ID: CAD982444481
TSD County: Not reported

AMERIGAS PROPANE LP (Continued) **S113154153**

Waste Category:	Waste oil and mixed oil
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.114
Facility County:	San Bernardino
Year:	2009
Gepaid:	CAL000336896
Contact:	MARC STEINBUCH
Telephone:	9098772642
Mailing Name:	Not reported
Mailing Address:	PO BOX 1300
Mailing City,St,Zip:	COMMERCE CITY, CO 800220000
Gen County:	Not reported
TSD EPA ID:	CAD982444481
TSD County:	Not reported
Waste Category:	Latex waste
Disposal Method:	Other Treatment
Tons:	0.417
Facility County:	San Bernardino
Year:	2009
Gepaid:	CAL000336896
Contact:	MARC STEINBUCH
Telephone:	9098772642
Mailing Name:	Not reported
Mailing Address:	PO BOX 1300
Mailing City,St,Zip:	COMMERCE CITY, CO 800220000
Gen County:	Not reported
TSD EPA ID:	CAD982444481
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.05
Facility County:	San Bernardino

Click this hyperlink while viewing on your computer to access
1 additional CA_HAZNET: record(s) in the EDR Site Report.

AB248 **PETROLANE** **HIST UST** **U001574588**
WSW **1975 S RIVERSIDE AVE** **EMI** **N/A**
1/4-1/2 **BLOOMINGTON, CA 92316**
0.346 mi.
1829 ft. **Site 3 of 3 in cluster AB**

Relative:
Lower

Actual:
1038 ft.

HIST UST:

Region:	STATE
Facility ID:	00000007028
Facility Type:	Other
Other Type:	PROPANE DISTRIBUTION
Total Tanks:	0000
Contact Name:	HARVEY C. ENOS
Telephone:	7148772642
Owner Name:	PETROLANE
Owner Address:	1600 EAST HILL STREET
Owner City,St,Zip:	LONG BEACH, CA 90806

PETROLANE (Continued) **U001574588**

Tank Num: 001
Container Num: 01
Year Installed: 1964
Tank Capacity: 00002000
Tank Used for: Not reported
Type of Fuel: Not reported
Tank Construction: Not reported
Leak Detection: None

EMI:

Year:	1987
County Code:	36
Air Basin:	SC
Facility ID:	51860
Air District Name:	SC
SIC Code:	5311
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1990
County Code:	36
Air Basin:	SC
Facility ID:	51860
Air District Name:	SC
SIC Code:	5172
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

AF249 **VULCAN STEEL COMPANY** **NPDES** **S109464594**
SW **2038 S SYCAMORE AVE** **N/A**
1/4-1/2 **BLOOMINGTON, CA 92316**
0.348 mi.
1837 ft. **Site 1 of 11 in cluster AF**

Relative:
Lower

Actual:
1043 ft.

NPDES:

Npdes Number:	CAS000001
Facility Status:	Active
Agency Id:	0
Region:	8
Regulatory Measure Id:	354186
Order No:	97-03-DWQ

VULCAN STEEL COMPANY (Continued) **S109464594**

Regulatory Measure Type:	Enrollee
Place Id:	Not reported
WDID:	8 36I021897
Program Type:	Industrial
Adoption Date Of Regulatory Measure:	Not reported
Effective Date Of Regulatory Measure:	10/23/2008
Expiration Date Of Regulatory Measure:	Not reported
Termination Date Of Regulatory Measure:	Not reported
Discharge Name:	Vulcan Steel Company
Discharge Address:	PO Box 386
Discharge City:	Bloomington
Discharge State:	California
Discharge Zip:	92316

Y250 **HMIRS** **9998060050**
West **280 WEST VALLEY BLVD** **N/A**
1/4-1/2 **RIALTO, CA**
0.350 mi.
1846 ft. **Site 6 of 16 in cluster Y**

Relative:
Lower

Click this hyperlink while viewing on your computer to access additional HMIRS detail in the EDR Site Report.

Actual:
1064 ft.

Y251 **HMIRS** **9999041195**
West **280 W. VALLEY BLVD** **N/A**
1/4-1/2 **RIALTO, CA**
0.350 mi.
1846 ft. **Site 7 of 16 in cluster Y**

Relative:
Lower

Click this hyperlink while viewing on your computer to access additional HMIRS detail in the EDR Site Report.

Actual:
1064 ft.

Y252 **280 W VALLEY BLVD** **HMIRS** **2008452095**
West **280 W VALLEY BLVD** **N/A**
1/4-1/2 **RIALTO, CA**
0.350 mi.
1846 ft. **Site 8 of 16 in cluster Y**

Relative:
Lower

Click this hyperlink while viewing on your computer to access additional HMIRS detail in the EDR Site Report.

Actual:
1064 ft.

Y253 **280 W. VALLEY BLVD** **HMIRS** **2009049087**
West **280 W. VALLEY BLVD** **N/A**
1/4-1/2 **RIALTO, CA 92376**
0.350 mi.
1846 ft. **Site 9 of 16 in cluster Y**

Relative:
Lower

Click this hyperlink while viewing on your computer to access additional HMIRS detail in the EDR Site Report.

Actual:
1064 ft.

Y254 **FEDERAL EXPRESS CORP** **CA FID UST** **S101591325**
West **280 W VALLEY BLVD** **N/A**
1/4-1/2 **RIALTO, CA 92376**
0.350 mi.
1846 ft. **Site 10 of 16 in cluster Y**

Relative:
Lower

Actual:
1064 ft.

CA FID UST:

Facility ID:	36004790
Regulated By:	UTNKA
Regulated ID:	Not reported
Cortese Code:	Not reported
SIC Code:	Not reported
Facility Phone:	Not reported
Mail To:	Not reported
Mailing Address:	164 S JEFFERSON
Mailing Address 2:	Not reported
Mailing City,St,Zip:	RIALTO 92376
Contact:	Not reported
Contact Phone:	Not reported
DUNs Number:	Not reported
NPDES Number:	Not reported
EPA ID:	Not reported
Comments:	Not reported
Status:	Active

Y255 **FEDERAL EXPRESS CORP** **UST** **U003784963**
West **280 W VALLEY BLVD** **SWEEPS UST** **N/A**
1/4-1/2 **RIALTO, CA 92376** **WDS**
0.350 mi.
1846 ft. **Site 11 of 16 in cluster Y**

Relative:
Lower

Actual:
1064 ft.

UST:

Facility ID:	87013790
Latitude:	34.07053
Longitude:	-117.3741

SWEEPS UST:

Status:	Active
Comp Number:	13790
Number:	1
Board Of Equalization:	44-020511
Referral Date:	03-24-92
Action Date:	03-24-92
Created Date:	09-16-88
Tank Status:	A
Owner Tank Id:	Not reported
Swrcb Tank Id:	36-000-013790-000001
Actv Date:	09-16-88
Capacity:	1
Tank Use:	UNKNOWN
Stg:	P
Content:	UNKNOWN
Number Of Tanks:	1

CA WDS:

Facility ID:	Santa Ana River 36I005977
Facility Type:	Industrial - Facility that treats and/or disposes of liquid or semisolid wastes from any servicing, producing, manufacturing or processing operation of whatever nature, including mining, gravel

FEDERAL EXPRESS CORP (Continued) **U003784963**

	washing, geothermal operations, air conditioning, ship building and repairing, oil production, storage and disposal operations, water pumping.
Facility Status:	Active - Any facility with a continuous or seasonal discharge that is under Waste Discharge Requirements.
NPDES Number:	CAS000001 The 1st 2 characters designate the state. The remaining 7 are assigned by the Regional Board
Subregion:	8
Facility Telephone:	9098743030
Facility Contact:	SR MANAGER
Agency Name:	FEDERAL EXPRESS - RIALTO
Agency Address:	280 W Valley Blvd
Agency City,St,Zip:	Rialto 923767714
Agency Contact:	SR MGR
Agency Telephone:	9098743030
Agency Type:	Private
SIC Code:	0
SIC Code 2:	Not reported
Primary Waste:	Not reported
Primary Waste Type:	Not reported
Secondary Waste:	Not reported
Secondary Waste Type:	Not reported
Design Flow:	0
Baseline Flow:	0
Reclamation:	Not reported
POTW:	Not reported
Treat To Water:	Minor Threat to Water Quality. A violation of a regional board order should cause a relatively minor impairment of beneficial uses compared to a major or minor threat. Not: All nurds without a TTWQ will be considered a minor threat to water quality unless coded at a higher Level. A Zero (0) may be used to code those NURDS that are found to represent no threat to water quality.
Complexity:	Category C - Facilities having no waste treatment systems, such as cooling water dischargers or thosewho must comply through best management practices, facilities with passive waste treatment and disposal systems, such as septic systems with subsurface disposal, or dischargers having waste storage systems with land disposal such as dairy waste ponds.

Y256 **FED EX** **NPDES** **S103649087**
West **280 W VALLEY BLVD** **San Bern. Co. Permit** **N/A**
1/4-1/2 **RIALTO, CA 92376**
0.350 mi.
1846 ft. **Site 12 of 16 in cluster Y**

Relative:
Lower

Actual:
1064 ft.

NPDES:

Npdes Number:	CAS000001
Facility Status:	Terminated
Agency Id:	0
Region:	8
Regulatory Measure Id:	213225
Order No:	97-03-DWQ
Regulatory Measure Type:	Enrollee
Place Id:	Not reported
WDID:	8 36I005977
Program Type:	Industrial
Adoption Date Of Regulatory Measure:	Not reported
Effective Date Of Regulatory Measure:	04/17/1992

FED EX (Continued) **S103649087**

Expiration Date Of Regulatory Measure: Not reported
Termination Date Of Regulatory Measure: 10/23/2012
Discharge Name: Fed Ex
Discharge Address: 280 W Valley Blvd
Discharge City: Rialto
Discharge State: California
Discharge Zip: 92376

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0003196
Owner: FEDERAL EXPRESS CORP
Permit Number: PT0011255
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: INACTIVE
Expiration Date: 09/30/2006

Region: SAN BERNARDINO
Facility ID: FA0003196
Owner: FEDERAL EXPRESS CORP
Permit Number: PT0003357
Permit Category: SPECIAL HANDLER
Facility Status: ACTIVE
Expiration Date: 09/30/2012

Region: SAN BERNARDINO
Facility ID: FA0003196
Owner: FEDERAL EXPRESS CORP
Permit Number: PT0003356
Permit Category: SPECIAL GENERATOR
Facility Status: ACTIVE
Expiration Date: 09/30/2012

Y257 **HMIRS** **2001011285**
West **280 W VALLEY BLVD** **N/A**
1/4-1/2 **RIALTO, CA**
0.350 mi.
1846 ft. **Site 13 of 16 in cluster Y**

Relative:
Lower

Click this hyperlink while viewing on your computer to access additional HMIRS detail in the EDR Site Report.

Actual:
1064 ft.

Y258 **ABILITY HEAVY MOVERS INC** **CA FID UST** **S101591360**
West **285 W VALLEY BLVD** **SWEEPS UST** **N/A**
1/4-1/2 **RIALTO, CA 92376**
0.354 mi.
1871 ft. **Site 14 of 16 in cluster Y**

Relative:
Lower

CA FID UST:
Facility ID: 36005571
Regulated By: UTNKA

Actual:
1064 ft.

Regulated ID: Not reported
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: Not reported
Mail To: Not reported

ABILITY HEAVY MOVERS INC (Continued) **S101591360**

Mailing Address: PO BOX 449
Mailing Address 2: Not reported
Mailing City,St,Zip: RIALTO 92376
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Active

SWEEPS UST:
Status: Active
Comp Number: 11399
Number: 1
Board Of Equalization: 44-020339
Referral Date: 03-24-92
Action Date: 03-24-92
Created Date: 09-09-88
Tank Status: A
Owner Tank Id: Not reported
Swrcb Tank Id: 36-000-011399-000001
Actv Date: 09-09-88
Capacity: 1
Tank Use: UNKNOWN
Stg: P
Content: UNKNOWN
Number Of Tanks: 1

Y259 **EDR US Hist Auto Stat** **1015272183**
West **1743 S WILLOW AVE** **N/A**
1/4-1/2 **RIALTO, CA 92376**
0.375 mi.
1981 ft. **Site 15 of 16 in cluster Y**

Relative:
Lower

Actual:
1067 ft.

EDR Historical Auto Stations:
Name: TIMS MOBILE TRUCK REPAIR INCORPORATED
Year: 1999
Address: 1743 S WILLOW AVE

Name: TIMS MOBILE TRUCK REPAIR INCORPORATED
Year: 2000
Address: 1743 S WILLOW AVE

Y260 **R THOMPSON TRUCKING** **CA FID UST** **S101591343**
West **1743 S WILLOW** **SWEEPS UST** **N/A**
1/4-1/2 **RIALTO, CA 92376**
0.375 mi.
1981 ft. **Site 16 of 16 in cluster Y**

Relative:
Lower

Actual:
1067 ft.

CA FID UST:
Facility ID: 36005016
Regulated By: UTNKA
Regulated ID: Not reported
Cortese Code: Not reported
SIC Code: Not reported

R THOMPSON TRUCKING (Continued) **S101591343**

Facility Phone:	Not reported
Mail To:	Not reported
Mailing Address:	PO BOX 191
Mailing Address 2:	Not reported
Mailing City,St,Zip:	RIALTO 92376
Contact:	Not reported
Contact Phone:	Not reported
DUNs Number:	Not reported
NPDES Number:	Not reported
EPA ID:	Not reported
Comments:	Not reported
Status:	Active

SWEEPS UST:

Status:	Active
Comp Number:	10188
Number:	1
Board Of Equalization:	44-020245
Referral Date:	03-24-92
Action Date:	03-24-92
Created Date:	09-21-88
Tank Status:	A
Owner Tank Id:	Not reported
Swrcb Tank Id:	36-000-010188-000001
Actv Date:	09-21-88
Capacity:	1
Tank Use:	UNKNOWN
Stg:	P
Content:	UNKNOWN
Number Of Tanks:	1

AC261 **1062 S RIVERSIDE AVE** **NPDES** **S109433917**
NW **1062 S RIVERSIDE AVE** **N/A**
1/4-1/2 **RIALTO, CA 92376**
0.378 mi.
1996 ft. **Site 3 of 3 in cluster AC**

Relative:
Higher

Actual:
1126 ft.

NPDES:

Npdes Number:	CAS000002
Facility Status:	Terminated
Agency Id:	0
Region:	8
Regulatory Measure Id:	318259
Order No:	2009-0009-DWQ
Regulatory Measure Type:	Enrollee
Place Id:	Not reported
WDID:	8 36C345140
Program Type:	Construction
Adoption Date Of Regulatory Measure:	Not reported
Effective Date Of Regulatory Measure:	01/03/2007
Expiration Date Of Regulatory Measure:	Not reported
Termination Date Of Regulatory Measure:	09/02/2010
Discharge Name:	Noriega Development Inc
Discharge Address:	PO Box 4620
Discharge City:	Rancho Cucamonga
Discharge State:	California
Discharge Zip:	91729

262
SW
1/4-1/2
0.384 mi.
2025 ft.

2071 SOUTH DATE
RIALTO, CA 92376

CDL **S107530694**
N/A

Relative:
Lower

Actual:
1029 ft.

CDL:
Facility ID: 199608003
Lab Type: Illegal Drug Lab (L) - location where an illegal drug lab was operated or drug lab equipment and/or materials were stored.

AG263
West
1/4-1/2
0.387 mi.
2046 ft.

VERIZON WIRELESS (SITE:RIALTO)
1531 S WILLOW AVE
RIALTO, CA 92376

Site 1 of 7 in cluster AG

San Bern. Co. Permit **S104763368**
N/A

Relative:
Lower

Actual:
1079 ft.

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0000736
Owner: VERIZON WIRELESS
Permit Number: PT0009044
Permit Category: HAZMAT HANDLER - UNSTAFFED REMOTE FACILITY
Facility Status: ACTIVE
Expiration Date: 04/30/2013

AF264
SW
1/4-1/2
0.390 mi.
2059 ft.

2051 SLOWER AVENUE
COLTON, CA 92324

Site 2 of 11 in cluster AF

CHMIRS **S100220399**
N/A

Relative:
Lower

Actual:
1043 ft.

CHMIRS:
OES Incident Number: 9012647
OES notification: Not reported
OES Date: Not reported
OES Time: Not reported
Incident Date: 27-AUG-90
Date Completed: 27-AUG-90
Property Use: 600
Agency Id Number: 36193
Agency Incident Number: 082790-1
Time Notified: 1300
Time Completed: 0
Surrounding Area: 600
Estimated Temperature: 85
Property Management: P
Special Studies 1: Not reported
Special Studies 2: Not reported
Special Studies 3: Not reported
Special Studies 4: Not reported
Special Studies 5: Not reported
Special Studies 6: Not reported
More Than Two Substances Involved?: N
Resp Agncy Personel # Of Decontaminated: 0
Responding Agency Personel # Of Injuries: 0
Responding Agency Personel # Of Fatalities: 0
Others Number Of Decontaminated: 0

(Continued) **S100220399**

Others Number Of Injuries:	0
Others Number Of Fatalities:	0
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	CATHERINE B. RICHARDS
Report Date:	11-SEP-90
Comments:	Y
Facility Telephone:	714 356-3440
Waterway Involved:	Not reported
Waterway:	Not reported
Spill Site:	Not reported
Cleanup By:	Not reported
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	88-92
Agency:	Not reported
Incident Date:	Not reported
Admin Agency:	Not reported
Amount:	Not reported
Contained:	Not reported
Site Type:	Not reported
E Date:	04-JUN-91
Substance:	Not reported
Quantity Released:	Not reported
BBLS:	Not reported
Cups:	Not reported
CUFT:	Not reported
Gallons:	Not reported
Grams:	Not reported
Pounds:	Not reported
Liters:	Not reported
Ounces:	Not reported
Pints:	Not reported
Quarts:	Not reported
Sheen:	Not reported
Tons:	Not reported
Unknown:	Not reported
Evacuations:	Not reported
Number of Injuries:	Not reported
Number of Fatalities:	Not reported
Description:	Not reported

AH265 **WHITING DOOR MANUFACTURING COR** **FINDS** **1014680417**
West **311 VALLEY BL** **N/A**
1/4-1/2 **RIALTO, CA 92376**
0.391 mi.
2066 ft. **Site 1 of 12 in cluster AH**

Relative:
Lower

Actual:
1067 ft.

FINDS:

Registry ID: 110040900184

Environmental Interest/Information System
CRITERIA AND HAZARDOUS AIR POLLUTANT INVENTORY

AH266 **WHITING DOOR MFG CORP** **RCRA-SQG** **1000455622**
West **311 W VALLEY BLVD** **FINDS** **CAD982493231**
1/4-1/2 **RIALTO, CA 92376** **HAZNET**
0.391 mi.
2066 ft. **Site 2 of 12 in cluster AH**

Relative:
Lower

Actual:
1067 ft.

RCRA-SQG:

Date form received by agency:	07/03/1990
Facility name:	WHITING DOOR MFG CORP
Facility address:	311 W VALLEY BLVD RIALTO, CA 92376
EPA ID:	CAD982493231
Contact:	ENVIRONMENTAL MANAGER
Contact address:	311 W VALLEY BLVD RIALTO, CA 92376
Contact country:	US
Contact telephone:	(714) 877-0120
Contact email:	Not reported
EPA Region:	09
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	DON WHITING
Owner/operator address:	NOT REQUIRED NOT REQUIRED, ME 99999
Owner/operator country:	Not reported
Owner/operator telephone:	(415) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported
Owner/operator name:	NOT REQUIRED
Owner/operator address:	NOT REQUIRED NOT REQUIRED, ME 99999
Owner/operator country:	Not reported
Owner/operator telephone:	(415) 555-1212
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported

WHITING DOOR MFG CORP (Continued) **1000455622**

Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110002144493

Environmental Interest/Information System

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

US EPA TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.

California Hazardous Waste Tracking System - Datamart (HWTS-DATAMART) provides California with information on hazardous waste shipments for generators, transporters, and treatment, storage, and disposal facilities.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZNET:
Year: 2011
Gepaid: CAD982493231
Contact: ART GONZALES
Telephone: 9098770120
Mailing Name: Not reported
Mailing Address: 301 S MILLIKEN AVE
Mailing City,St,Zip: ONTARIO, CA 91761
Gen County: Not reported

WHITING DOOR MFG CORP (Continued) **1000455622**

TSD EPA ID: CAT000613893
TSD County: Not reported
Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.0275
Facility County: San Bernardino

Year: 2010
Gepaid: CAD982493231
Contact: ART GONZALES
Telephone: 9098770120
Mailing Name: Not reported
Mailing Address: 311 W VALLEY BLVD
Mailing City,St,Zip: RIALTO, CA 923767715
Gen County: Not reported
TSD EPA ID: CAT000613893
TSD County: Not reported
Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method: Not reported
Tons: 0.0075
Facility County: San Bernardino

Year: 2010
Gepaid: CAD982493231
Contact: ART GONZALES
Telephone: 9098770120
Mailing Name: Not reported
Mailing Address: 311 W VALLEY BLVD
Mailing City,St,Zip: RIALTO, CA 923767715
Gen County: Not reported
TSD EPA ID: CAT000613893
TSD County: Not reported
Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.036
Facility County: San Bernardino

Year: 2009
Gepaid: CAD982493231
Contact: ART GONZALES
Telephone: 9098770120
Mailing Name: Not reported
Mailing Address: 311 W VALLEY BLVD
Mailing City,St,Zip: RIALTO, CA 923767715
Gen County: Not reported
TSD EPA ID: CAT000613893
TSD County: Not reported
Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.0875
Facility County: San Bernardino

Year: 2008
Gepaid: CAD982493231

WHITING DOOR MFG CORP (Continued) **1000455622**

Contact:	ART GONZALES
Telephone:	9098770120
Mailing Name:	Not reported
Mailing Address:	311 W VALLEY BLVD
Mailing City,St,Zip:	RIALTO, CA 923767715
Gen County:	Not reported
TSD EPA ID:	CAT000613893
TSD County:	Not reported
Waste Category:	Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.077
Facility County:	San Bernardino

Click this hyperlink while viewing on your computer to access
25 additional CA_HAZNET: record(s) in the EDR Site Report.

AH267 **WHITING DOOR MFG CORP** **RCRA-SQG** **1000455623**
West **311 W VALLEY BLVD** **San Bern. Co. Permit** **CAD982493553**
1/4-1/2 **RIALTO, CA 92376** **HAZNET**
0.391 mi. **EMI**
2066 ft. **Site 3 of 12 in cluster AH**

Relative:
Lower

Actual:
1067 ft.

RCRA-SQG:

Date form received by agency:	07/11/1990
Facility name:	WHITING DOOR MFG CORP
Facility address:	311 W VALLEY BLVD RIALTO, CA 92376
EPA ID:	CAD982493553
Mailing address:	W VALLEY BLVD RIALTO, CA 92376
Contact:	ENVIRONMENTAL MANAGER
Contact address:	311 W VALLEY BLVD RIALTO, CA 92376
Contact country:	US
Contact telephone:	(714) 877-0120
Contact email:	Not reported
EPA Region:	09
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	DON WHITING
Owner/operator address:	NOT REQUIRED NOT REQUIRED, ME 99999
Owner/operator country:	Not reported
Owner/operator telephone:	(415) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	NOT REQUIRED

WHITING DOOR MFG CORP (Continued) **1000455623**

Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0007295
Owner: WHITING DOOR MFG CORP
Permit Number: PT0001518
Permit Category: CONDITIONALLY EXEMPT SMALL QUANTITY GENERATOR
Facility Status: INACTIVE
Expiration Date: 08/31/2012

Region: SAN BERNARDINO
Facility ID: FA0007295
Owner: WHITING DOOR MFG CORP
Permit Number: PT0001519
Permit Category: HAZMAT HANDLER 11-25 EMPLOYEES
Facility Status: INACTIVE
Expiration Date: 08/31/2012

HAZNET:
Year: 1998
Gepaid: CAD982493553
Contact: DON WHITING
Telephone: 4155551212
Mailing Name: Not reported
Mailing Address: 311 W VALLEY BLVD
Mailing City,St,Zip: RIALTO, CA 923767715
Gen County: Not reported
TSD EPA ID: CAT000613893
TSD County: Not reported
Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)

WHITING DOOR MFG CORP (Continued) **1000455623**

Disposal Method: Transfer Station
Tons: .0290
Facility County: San Bernardino

Year: 1997
Gepaid: CAD982493553
Contact: DON WHITING
Telephone: 4155551212
Mailing Name: Not reported
Mailing Address: 311 W VALLEY BLVD
Mailing City,St,Zip: RIALTO, CA 923767715
Gen County: Not reported
TSD EPA ID: CAT000613893
TSD County: Not reported
Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method: Transfer Station
Tons: .1160
Facility County: San Bernardino

Year: 1996
Gepaid: CAD982493553
Contact: DON WHITING
Telephone: 4155551212
Mailing Name: Not reported
Mailing Address: 311 W VALLEY BLVD
Mailing City,St,Zip: RIALTO, CA 923767715
Gen County: Not reported
TSD EPA ID: CAT000613893
TSD County: Not reported
Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method: Transfer Station
Tons: .1305
Facility County: San Bernardino

Year: 1995
Gepaid: CAD982493553
Contact: DON WHITING
Telephone: 4155551212
Mailing Name: Not reported
Mailing Address: 311 W VALLEY BLVD
Mailing City,St,Zip: RIALTO, CA 923767715
Gen County: Not reported
TSD EPA ID: CAT000613893
TSD County: Not reported
Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method: Transfer Station
Tons: .1885
Facility County: San Bernardino

Year: 1994
Gepaid: CAD982493553
Contact: DON WHITING
Telephone: 4155551212
Mailing Name: Not reported
Mailing Address: 311 W VALLEY BLVD
Mailing City,St,Zip: RIALTO, CA 923767715
Gen County: Not reported

WHITING DOOR MFG CORP (Continued) **1000455623**

TSD EPA ID: CAT000613893
TSD County: Not reported
Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method: Not reported
Tons: .0290
Facility County: San Bernardino

Click this hyperlink while viewing on your computer to access
1 additional CA_HAZNET: record(s) in the EDR Site Report.

EMI:

Year:	1987
County Code:	36
Air Basin:	SC
Facility ID:	45757
Air District Name:	SC
SIC Code:	3714
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	8
Reactive Organic Gases Tons/Yr:	6
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1990
County Code:	36
Air Basin:	SC
Facility ID:	45757
Air District Name:	SC
SIC Code:	3714
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	19
Reactive Organic Gases Tons/Yr:	2
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1995
County Code:	36
Air Basin:	SC
Facility ID:	45757
Air District Name:	SC
SIC Code:	3714
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	11
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0

WHITING DOOR MFG CORP (Continued) **1000455623**

NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1996
County Code:	36
Air Basin:	SC
Facility ID:	45757
Air District Name:	SC
SIC Code:	3714
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	3
Reactive Organic Gases Tons/Yr:	3
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1997
County Code:	36
Air Basin:	SC
Facility ID:	45757
Air District Name:	SC
SIC Code:	3714
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	4
Reactive Organic Gases Tons/Yr:	4
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1998
County Code:	36
Air Basin:	SC
Facility ID:	45757
Air District Name:	SC
SIC Code:	3714
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	4
Reactive Organic Gases Tons/Yr:	4
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1999

WHITING DOOR MFG CORP (Continued) **1000455623**

County Code:	36
Air Basin:	SC
Facility ID:	45757
Air District Name:	SC
SIC Code:	3714
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	4
Reactive Organic Gases Tons/Yr:	4
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	2000
County Code:	36
Air Basin:	SC
Facility ID:	45757
Air District Name:	SC
SIC Code:	3714
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	4
Reactive Organic Gases Tons/Yr:	4
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	2001
County Code:	36
Air Basin:	SC
Facility ID:	45757
Air District Name:	SC
SIC Code:	3714
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	2005
County Code:	36
Air Basin:	SC
Facility ID:	45757
Air District Name:	SC
SIC Code:	2341
Air District Name:	SOUTH COAST AQMD

WHITING DOOR MFG CORP (Continued) **1000455623**

Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2.62991
Reactive Organic Gases Tons/Yr:	2.589783953
Carbon Monoxide Emissions Tons/Yr:	.039
NOX - Oxides of Nitrogen Tons/Yr:	.145
SOX - Oxides of Sulphur Tons/Yr:	.000665
Particulate Matter Tons/Yr:	.28636
Part. Matter 10 Micrometers & Smllr Tons/Yr:	.27524

AF268 **KMPP TANK FARM** **SLIC** **S101541259**
SW **2720 SLOVER** **N/A**
1/4-1/2 **COLTON, CA**
0.394 mi.
2079 ft. **Site 3 of 11 in cluster AF**

Relative:
Lower

Actual:
1043 ft.

SLIC:

Region:	STATE
Facility Status:	**Open - Site Assessment**
Status Date:	02/03/2009
Global Id:	SLT8R1754101
Lead Agency:	SANTA ANA RWQCB (REGION 8)
Lead Agency Case Number:	Not reported
Latitude:	34.063191
Longitude:	-117.364752
Case Type:	Cleanup Program Site
Case Worker:	RS
Local Agency:	Not reported
RB Case Number:	SLT8R175
File Location:	Not reported
Potential Media Affected:	Not reported
Potential Contaminants of Concern:	Other Petroleum
Site History:	.

Click here to access the California GeoTracker records for this facility:

SLIC REG 8:

Type:	Soil
Facility Status:	6
Region:	8
Staff:	RTS
Substance:	RTS
Lead Agency:	RTS
Location Code:	RTS
Thomas Bros Code:	RTS

AF269 **ERNS** **92281848**
SW **2151 WEST SLOVER AVENUE** **N/A**
1/4-1/2 **COLTON, CA 92412**
0.400 mi.
2113 ft. **Site 4 of 11 in cluster AF**

Relative:
Lower

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

Actual:
1043 ft.

AI270 **ERNS** **2011967513**
SSW **2051 EAST SLOVER AVENUE** **N/A**
1/4-1/2 **BLOOMINGTON, CA**
0.401 mi.
2116 ft. **Site 1 of 30 in cluster AI**

Relative:
Lower

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

Actual:
1037 ft.

AI271 **ERNS** **2006811068**
SSW **2051 E. SLOVER AVE** **N/A**
1/4-1/2 **BLOOMINGTON, CA 92316**
0.401 mi.
2116 ft. **Site 2 of 30 in cluster AI**

Relative:
Lower

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

Actual:
1037 ft.

AI272 **ERNS** **2010935704**
SSW **2051 E. SLOVER AVE.** **N/A**
1/4-1/2 **BLOOMINGTON, CA**
0.401 mi.
2116 ft. **Site 3 of 30 in cluster AI**

Relative:
Lower

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

Actual:
1037 ft.

AI273 **ERNS** **94392469**
SSW **2051 EAST SLOVER AVE COLTON TERMINAL** **N/A**
1/4-1/2 **BLOOMINGTON, CA 92316**
0.401 mi.
2116 ft. **Site 4 of 30 in cluster AI**

Relative:
Lower

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

Actual:
1037 ft.

AI274 **ERNS** **2010945154**
SSW **2051 E. SLOVER AVE.** **N/A**
1/4-1/2 **BLOOMINGTON, CA 92316**
0.401 mi.
2116 ft. **Site 5 of 30 in cluster AI**

Relative:
Lower

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

Actual:
1037 ft.

AI275 **ERNS** **2006806861**
SSW **2051 E. SLOVER** **N/A**
1/4-1/2 **BLOOMINGTON, CA 92316**
0.401 mi.
2116 ft. **Site 6 of 30 in cluster AI**

Relative:
Lower

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

Actual:
1037 ft.

AI276 **CHMIRS** **S109037205**
SSW **2051 EAST SLOVER AVE** **N/A**
1/4-1/2 **BLOOMINGTON, CA 92316**
0.401 mi.
2116 ft. **Site 7 of 30 in cluster AI**

Relative:
Lower

Actual:
1037 ft.

CHMIRS:

OES Incident Number:	06-6048	
OES notification:	10/11/2006	
OES Date:	Not reported	
OES Time:	Not reported	
Incident Date:	Not reported	
Date Completed:	**Not reported**	
Property Use:	Not reported	
Agency Id Number:	Not reported	
Agency Incident Number:	Not reported	
Time Notified:	Not reported	
Time Completed:	Not reported	
Surrounding Area:	Not reported	
Estimated Temperature:	Not reported	
Property Management:	Not reported	
Special Studies 1:	Not reported	
Special Studies 2:	Not reported	
Special Studies 3:	Not reported	
Special Studies 4:	Not reported	
Special Studies 5:	Not reported	
Special Studies 6:	Not reported	
More Than Two Substances Involved?:		Not reported
Resp Agncy Personel # Of Decontaminated:		Not reported
Responding Agency Personel # Of Injuries:		Not reported
Responding Agency Personel # Of Fatalities:		Not reported
Others Number Of Decontaminated:		Not reported
Others Number Of Injuries:		Not reported
Others Number Of Fatalities:		Not reported
Vehicle Make/year:	Not reported	
Vehicle License Number:	Not reported	
Vehicle State:	Not reported	
Vehicle Id Number:	Not reported	
CA/DOT/PUC/ICC Number:	Not reported	
Company Name:	Not reported	
Reporting Officer Name/ID:	Not reported	
Report Date:	Not reported	
Comments:	Not reported	
Facility Telephone:	Not reported	
Waterway Involved:	Not reported	
Waterway:	Not reported	
Spill Site:	Not reported	
Cleanup By:	Reporting Party	
Containment:	Not reported	
What Happened:	Not reported	
Type:	Not reported	

(Continued) **S109037205**

Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	2006
Agency:	Kinder Morgan
Incident Date:	10/11/2006 12:00:00 AM
Admin Agency:	San Bernardino County Health Department
Amount:	Not reported
Contained:	Yes
Site Type:	Other
E Date:	Not reported
Substance:	diesel product
Quantity Released:	Not reported
BBLS:	0
Cups:	0
CUFT:	0
Gallons:	0.000000
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	1
Tons:	0
Unknown:	0
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	Released due to a loose fitting. Released into a bucket and a small stain on the ground.
OES Incident Number:	'08-8769
OES notification:	12/09/2008
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported

(Continued) **S109037205**

Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	No
Waterway:	Not reported
Spill Site:	Refinery
Cleanup By:	Reporting Party
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	N/A
Other:	Not reported
Date/Time:	0701
Year:	2008
Agency:	Kinder Morgan
Incident Date:	12/9/2008
Admin Agency:	San Bernardino County Health Department
Amount:	Not reported
Contained:	Unknown
Site Type:	Not reported
E Date:	Not reported
Substance:	Suspicious stain
Quantity Released:	2ft x 2ft
BBLS:	Not reported
Cups:	Not reported
CUFT:	Not reported
Gallons:	Not reported
Grams:	Not reported
Pounds:	Not reported
Liters:	Not reported
Ounces:	Not reported
Pints:	Not reported
Quarts:	Not reported
Sheen:	Not reported
Tons:	Not reported
Unknown:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	Suspicious stain found on the ground near one of the valves on a storage tank that is currently empty. Tank previously held gasoline.
OES Incident Number:	06-5415
OES notification:	09/11/2006
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported
Date Completed:	**Not reported**

(Continued) **S109037205**

Property Use:	Not reported	
Agency Id Number:	Not reported	
Agency Incident Number:	Not reported	
Time Notified:	Not reported	
Time Completed:	Not reported	
Surrounding Area:	Not reported	
Estimated Temperature:	Not reported	
Property Management:	Not reported	
Special Studies 1:	Not reported	
Special Studies 2:	Not reported	
Special Studies 3:	Not reported	
Special Studies 4:	Not reported	
Special Studies 5:	Not reported	
Special Studies 6:	Not reported	
More Than Two Substances Involved?:		Not reported
Resp Agncy Personel # Of Decontaminated:		Not reported
Responding Agency Personel # Of Injuries:		Not reported
Responding Agency Personel # Of Fatalities:		Not reported
Others Number Of Decontaminated:		Not reported
Others Number Of Injuries:		Not reported
Others Number Of Fatalities:		Not reported
Vehicle Make/year:	Not reported	
Vehicle License Number:	Not reported	
Vehicle State:	Not reported	
Vehicle Id Number:	Not reported	
CA/DOT/PUC/ICC Number:	Not reported	
Company Name:	Not reported	
Reporting Officer Name/ID:	Not reported	
Report Date:	Not reported	
Comments:	Not reported	
Facility Telephone:	Not reported	
Waterway Involved:	Not reported	
Waterway:	Not reported	
Spill Site:	Not reported	
Cleanup By:	Unknown	
Containment:	Not reported	
What Happened:	Not reported	
Type:	Not reported	
Measure:	Not reported	
Other:	Not reported	
Date/Time:	Not reported	
Year:	2006	
Agency:	Kinder Morgan	
Incident Date:	9/11/2006 12:00:00 AM	
Admin Agency:	San Bernardino County Health Department	
Amount:	Not reported	
Contained:	Yes	
Site Type:	Pipe Line	
E Date:	Not reported	
Substance:	potential release of fuel oil	
Quantity Released:	Not reported	
BBLS:	0	
Cups:	0	
CUFT:	0	
Gallons:	0.000000	
Grams:	0	
Pounds:	0	

(Continued) **S109037205**

Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	They discovered a small amount of product around the valve seal of an underground 12-inch round valve can.

AI277 **CALNEV PIPE LINE COMPANY COLTON TERMINAL** **RCRA-LQG** **1000314453**
SSW **2051 E SLOVER AVE** **FINDS** **CAD007907322**
1/4-1/2 **COLTON, CA 92324** **SWEEPS UST**
0.401 mi. **US AIRS**
2116 ft. **Site 8 of 30 in cluster AI**

Relative:
Lower

Actual:
1037 ft.

RCRA-LQG:

Date form received by agency:	04/27/2012
Facility name:	CALNEV PIPE LINE, LLC - COLTON NORTH
Facility address:	2051 N. SLOVER AVENUE BLOOMINGTON, CA 92316
EPA ID:	CAD007907322
Mailing address:	TOWN AND COUNTRY ROAD ORANGE, CA 92868
Contact:	RICH BRITO
Contact address:	TOWN AND COUNTRY ROAD ORANGE, CA 92868
Contact country:	Not reported
Contact telephone:	(714) 560-4875
Contact email:	RICH_BRITO@KINDERMORGAN.COM
EPA Region:	09
Land type:	Private
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	CALNEV PIPE LINE, LLC
Owner/operator address:	TOWN AND COUNTRY ROAD ORANGE, CA 92868
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator

CALNEV PIPE LINE COMPANY COLTON TERMINAL (Continued) **1000314453**

Owner/Op start date: 03/30/2001
Owner/Op end date: Not reported

Owner/operator name: CALNEV PIPE LINE, LLC
Owner/operator address: TOWN AND COUNTRY ROAD
ORANGE, CA 92868
Owner/operator country: Not reported
Owner/operator telephone: (714) 560-4875
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 03/30/2001
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 06/15/2010
Facility name: CALNEV PIPE LINE, LLC - COLTON NORTH
Site name: CALNEV PIPE LINE, LLC - COLTON
Classification: Large Quantity Generator

Date form received by agency: 02/29/2008
Facility name: CALNEV PIPE LINE, LLC - COLTON NORTH
Site name: CALNEV PIPE LINE LLC COLTON TERMINAL
Classification: Large Quantity Generator

Date form received by agency: 02/28/2006
Facility name: CALNEV PIPE LINE, LLC - COLTON NORTH
Site name: CALNEV PIPE LINE, LLC COLTON TERMINAL
Classification: Large Quantity Generator

Date form received by agency: 10/12/2000
Facility name: CALNEV PIPE LINE, LLC - COLTON NORTH
Site name: CALNEV PIPE LINE COMPANY COLTON TERMINAL
Classification: Large Quantity Generator

Date form received by agency: 04/15/1999
Facility name: CALNEV PIPE LINE, LLC - COLTON NORTH
Site name: CALNEV PIPE LINE CO, COLTON TERMINAL
Classification: Large Quantity Generator

CALNEV PIPE LINE COMPANY COLTON TERMINAL (Continued) **1000314453**

Date form received by agency: 09/01/1996
Facility name: CALNEV PIPE LINE, LLC - COLTON NORTH
Site name: CALNEV PIPE LINE CO
Classification: Small Quantity Generator

Date form received by agency: 03/27/1990
Facility name: CALNEV PIPE LINE, LLC - COLTON NORTH
Site name: CALNEV PIPE LINE CO/COLTON TERMINAL
Classification: Large Quantity Generator

Date form received by agency: 07/15/1980
Facility name: CALNEV PIPE LINE, LLC - COLTON NORTH
Site name: CALNEV PIPE LINE CO
Classification: Large Quantity Generator

Hazardous Waste Summary:
Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D008
Waste name: LEAD

Waste code: D018
Waste name: BENZENE

Biennial Reports:

Last Biennial Reporting Year: 2013

Annual Waste Handled:
Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.
Amount (Lbs): 41.5

Waste code: D008
Waste name: LEAD
Amount (Lbs): 30

Waste code: D018
Waste name: BENZENE
Amount (Lbs): 40080.4

Violation Status: No violations found

CALNEV PIPE LINE COMPANY COLTON TERMINAL (Continued) **1000314453**

Evaluation Action Summary:

Evaluation date:	01/17/2006
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State

Evaluation date:	11/08/2005
Evaluation:	NOT A SIGNIFICANT NON-COMPLIER
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	EPA

Evaluation date:	08/26/2005
Evaluation:	SIGNIFICANT NON-COMPLIER
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	EPA

Evaluation date:	08/26/2005
Evaluation:	NON-FINANCIAL RECORD REVIEW
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	EPA

FINDS:

Registry ID: 110000908484

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

California Hazardous Waste Tracking System - Datamart (HWTS-DATAMART) provides California with information on hazardous waste shipments for generators, transporters, and treatment, storage, and disposal facilities.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CALNEV PIPE LINE COMPANY COLTON TERMINAL (Continued) **1000314453**

HAZARDOUS WASTE BIENNIAL REPORTER

CRITERIA AND HAZARDOUS AIR POLLUTANT INVENTORY

SWEEPS UST:

Status:	Active
Comp Number:	20392
Number:	9
Board Of Equalization:	44-020737
Referral Date:	08-28-91
Action Date:	08-28-91
Created Date:	02-29-88
Tank Status:	A
Owner Tank Id:	CU-07
Swrcb Tank Id:	36-000-020392-000004
Actv Date:	06-28-88
Capacity:	5000
Tank Use:	UNKNOWN
Stg:	P
Content:	Not reported
Number Of Tanks:	1

AIRS (AFS):

Compliance and Violation Data Major Sources:

EPA plant ID:	110001159086
Plant name:	CALNEV PIPELINE CO
Plant address:	2051 W SLOVER AVE BLOOMINGTON, CA 92316
County:	SAN BERNARDINO
Region code:	09
Dunn & Bradst #:	Not reported
Air quality cntrl region:	024
Sic code:	5171
Sic code desc:	PETROLEUM BULK STATIONS AND TERMINALS
North Am. industrial classf:	493190
NAIC code description:	Other Warehousing and Storage
Default compliance status:	IN COMPLIANCE - INSPECTION
Default classification:	ACTUAL OR POTENTIAL EMISSIONS ARE ABOVE THE APPLICABLE MAJOR SOURCE THRESHOLDS
Govt facility:	ALL OTHER FACILITIES NOT OWNED OR OPERATED BY A FEDERAL, STATE, OR LOCAL GOVERNMENT
Current HPV:	Not reported

Compliance and Enforcement Major Issues:

Air program:	TITLE V PERMITS
National action type:	MULTI MEDIA INSPECTION - LEVEL 2 OR GREATER
Date achieved:	000126
Penalty amount:	000000000
Air program:	TITLE V PERMITS
National action type:	MULTI MEDIA INSPECTION - LEVEL 2 OR GREATER
Date achieved:	010927
Penalty amount:	000000000

CALNEV PIPE LINE COMPANY COLTON TERMINAL (Continued) **1000314453**

Air program: TITLE V PERMITS
National action type: STATE DAY 0
Date achieved: 020411
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: NXXXXX
Date achieved: 020411
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: NXXXXX
Date achieved: 020822
Penalty amount: 000002500

Air program: TITLE V PERMITS
National action type: SV RESOLVED
Date achieved: 021106
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 030228
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 030527
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: S/L REQ (O/O COND) STACK TEST/NOT OBSV BUT REVWD
Date achieved: 030925
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 030930
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 040301
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 040301
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 040924
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED PCE/ ON-SITE

CALNEV PIPE LINE COMPANY COLTON TERMINAL (Continued) **1000314453**

Date achieved: 040924
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 040930
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 040930
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 060228
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 060228
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 061221
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 061221
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 061221
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 061221
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V COMPLIANCE CERT DUE/RECEIVED BY
Date achieved: 080212
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: S/L REQ (O/O COND) STACK TEST/NOT OBSV BUT REVWD
Date achieved: 081031
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: S/L REQ (O/O COND) STACK TEST/NOT OBSV BUT REVWD
Date achieved: 081031
Penalty amount: Not reported

CALNEV PIPE LINE COMPANY COLTON TERMINAL (Continued) **1000314453**

Air program: SIP SOURCE
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 090226
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 090226
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 090227
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 090227
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V COMPLIANCE CERT DUE/RECEIVED BY
Date achieved: 090302
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 090310
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 090310
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 090310
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 090310
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 100224
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 100224
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V COMPLIANCE CERT DUE/RECEIVED BY

CALNEV PIPE LINE COMPANY COLTON TERMINAL (Continued) **1000314453**

Date achieved: 100305
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 100928
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 100928
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 100928
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 100928
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 100928
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 100928
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 110225
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 110225
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: S/L REQ (O/O COND) STACK TEST/NOT OBSV BUT REVWD
Date achieved: 110606
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: S/L REQ (O/O COND) STACK TEST/NOT OBSV BUT REVWD
Date achieved: 110606
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 110812
Penalty amount: Not reported

CALNEV PIPE LINE COMPANY COLTON TERMINAL (Continued) **1000314453**

Air program: SIP SOURCE
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 110812
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: NXXXXX
Date achieved: 110901
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: NXXXXX
Date achieved: 110901
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 110921
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 110921
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 110921
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 110921
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE DAY 0
Date achieved: 111118
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE DAY 0
Date achieved: 111118
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: NXXXXX
Date achieved: 111122
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: NXXXXX
Date achieved: 111122
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: S/L REQ (O/O COND) STACK TEST/NOT OBSV BUT REVWD

CALNEV PIPE LINE COMPANY COLTON TERMINAL (Continued) **1000314453**

Date achieved: 111207
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: S/L REQ (O/O COND) STACK TEST/NOT OBSV BUT REVWD
Date achieved: 111207
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 120130
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 120130
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: SV RESOLVED
Date achieved: 120507
Penalty amount: 000010000

Air program: TITLE V PERMITS
National action type: SV RESOLVED
Date achieved: 120507
Penalty amount: 000010000

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 120827
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 120827
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 120919
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 120919
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 120919
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 120919
Penalty amount: Not reported

CALNEV PIPE LINE COMPANY COLTON TERMINAL (Continued) **1000314453**

Air program: TITLE V PERMITS
National action type: MULTI MEDIA INSPECTION - LEVEL 2 OR GREATER
Date achieved: 990113
Penalty amount: 000000000

Historical Compliance Minor Sources:
State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1001
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1001
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1002
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1003
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1004
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1101
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1101
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1102
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1103
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1104
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1104
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1201
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1202
Air prog code hist file: 0

CALNEV PIPE LINE COMPANY COLTON TERMINAL (Continued) **1000314453**

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1203
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1203
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1204
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1002
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1003
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1004
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1102
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1103
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1201
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1202
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1204
Air prog code hist file: 0

Permit Information:
Compliance plant ID: CA135
Permit number: 800022
Permit category: V
Permit category desc: TITLE V PERMIT - PLANT SP

Permit Source:
Compliance plant ID: CA135
Plant name: CALNEV PIPELINE CO
Plant address: 2051 W SLOVER AVE
BLOOMINGTON, CA 92316

CALNEV PIPE LINE COMPANY COLTON TERMINAL (Continued) **1000314453**

Event Information:
Compliance permit ID: CA135
Permit number: 800022
Event action type: IF
Event description: *PERMIT AUTHORITY ISSUES FINAL PERMIT
Event action #: 001
Event date: 20010416

AI278 **ERNS** **2009902906**
SSW **2051 E. SLOVER AVE.** **N/A**
1/4-1/2 **BLOOMINGTON, CA 92316**
0.401 mi.
2116 ft. **Site 9 of 30 in cluster AI**

Relative:
Lower

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

Actual:
1037 ft.

AI279 **KINDER MORGAN COLTON TERMINAL NORTH** **FINDS** **1010044877**
SSW **2051 E SLOVER AVENUE** **N/A**
1/4-1/2 **BLOOMINGTON, CA 92316**
0.401 mi.
2116 ft. **Site 10 of 30 in cluster AI**

Relative:
Lower

FINDS:

Registry ID: 110028151602

Actual:
1037 ft.

Environmental Interest/Information System

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

AI280
SSW
1/4-1/2
0.401 mi.
2116 ft.

2051 E. SLOVER AVE.
BLOOMINGTON, CA 92316

Site 11 of 30 in cluster AI

ERNS **2008902906**
N/A

Relative:
Lower

Actual:
1037 ft.

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

AI281
SSW
1/4-1/2
0.401 mi.
2116 ft.

2051 EAST SLOVER
BLOOMINGTON, CA 92316

Site 12 of 30 in cluster AI

CHMIRS **S110418771**
N/A

Relative:
Lower

Actual:
1037 ft.

CHMIRS:

OES Incident Number:	'10-2111	
OES notification:	03/31/2010	
OES Date:	Not reported	
OES Time:	Not reported	
Incident Date:	Not reported	
Date Completed:	**Not reported**	
Property Use:	Not reported	
Agency Id Number:	Not reported	
Agency Incident Number:	Not reported	
Time Notified:	Not reported	
Time Completed:	Not reported	
Surrounding Area:	Not reported	
Estimated Temperature:	Not reported	
Property Management:	Not reported	
Special Studies 1:	Not reported	
Special Studies 2:	Not reported	
Special Studies 3:	Not reported	
Special Studies 4:	Not reported	
Special Studies 5:	Not reported	
Special Studies 6:	Not reported	
More Than Two Substances Involved?:		Not reported
Resp Agncy Personel # Of Decontaminated:		Not reported
Responding Agency Personel # Of Injuries:		Not reported
Responding Agency Personel # Of Fatalities:		Not reported
Others Number Of Decontaminated:		Not reported
Others Number Of Injuries:		Not reported
Others Number Of Fatalities:		Not reported
Vehicle Make/year:	Not reported	
Vehicle License Number:	Not reported	
Vehicle State:	Not reported	
Vehicle Id Number:	Not reported	
CA/DOT/PUC/ICC Number:	Not reported	
Company Name:	Not reported	
Reporting Officer Name/ID:	Not reported	
Report Date:	Not reported	
Comments:	Not reported	
Facility Telephone:	Not reported	
Waterway Involved:	No	
Waterway:	Not reported	
Spill Site:	Other	
Cleanup By:	Unknown	
Containment:	Not reported	
What Happened:	Not reported	
Type:	Not reported	

(Continued) **S110418771**

Measure:	Unknown
Other:	Not reported
Date/Time:	1215
Year:	2010
Agency:	Kinder Morgan
Incident Date:	3/31/2010
Admin Agency:	San Bernardino County Health Department
Amount:	Not reported
Contained:	Unknown
Site Type:	Not reported
E Date:	Not reported
Substance:	Threatened release: Fuel Product
Quantity Released:	Not reported
BBLS:	Not reported
Cups:	Not reported
CUFT:	Not reported
Gallons:	Not reported
Grams:	Not reported
Pounds:	Not reported
Liters:	Not reported
Ounces:	Not reported
Pints:	Not reported
Quarts:	Not reported
Sheen:	Not reported
Tons:	Not reported
Unknown:	Not reported
Evacuations:	Not reported
Number of Injuries:	Not reported
Number of Fatalities:	Not reported
Description:	RP states that a 3' X 3' stain was discovered in the ground during excavation. The area is part of the manifold and is not pressurized.
OES Incident Number:	'10-2447
OES notification:	04/19/2010
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported

(Continued) **S110418771**

Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	No
Waterway:	Not reported
Spill Site:	Other
Cleanup By:	Reporting Party
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	N/A
Other:	Not reported
Date/Time:	955
Year:	2010
Agency:	Kinder Morgan
Incident Date:	4/19/2010
Admin Agency:	San Bernardino County Health Department
Amount:	Not reported
Contained:	Unknown
Site Type:	Not reported
E Date:	Not reported
Substance:	Unknown petroleum fuel
Quantity Released:	Not reported
BBLS:	Not reported
Cups:	Not reported
CUFT:	Not reported
Gallons:	Not reported
Grams:	Not reported
Pounds:	Not reported
Liters:	Not reported
Ounces:	Not reported
Pints:	Not reported
Quarts:	Not reported
Sheen:	Not reported
Tons:	Not reported
Unknown:	Not reported
Evacuations:	Not reported
Number of Injuries:	Not reported
Number of Fatalities:	Not reported
Description:	***Potential Release*** RP states that they discovered a potential release to soil within their facility. They have identified a shovel or two scoops of soil which has been contaminated. Investigation is ongoing.
OES Incident Number:	'08-1822
OES notification:	03/04/2008
OES Date:	Not reported
OES Time:	Not reported

(Continued) **S110418771**

Incident Date:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	No
Waterway:	Not reported
Spill Site:	Pipe Line
Cleanup By:	Unknown
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	N/A
Other:	Not reported
Date/Time:	1437
Year:	2008
Agency:	Kinder Morgan
Incident Date:	3/4/2008
Admin Agency:	San Bernardino County Health Department
Amount:	Not reported
Contained:	Unknown
Site Type:	Not reported
E Date:	Not reported
Substance:	Gasoline potential release
Quantity Released:	unknown
BBLS:	Not reported
Cups:	Not reported
CUFT:	Not reported
Gallons:	Not reported

(Continued) **S110418771**

Grams:	Not reported
Pounds:	Not reported
Liters:	Not reported
Ounces:	Not reported
Pints:	Not reported
Quarts:	Not reported
Sheen:	Not reported
Tons:	Not reported
Unknown:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	RP states they were doing hand excavation around a manifold at their facility and discovered contaminated soil.

AI282 **CAL NEV PIPELINE COLTON** **San Bern. Co. Permit** **S102038736**
SSW **2051 E SLOVER AVE** **N/A**
1/4-1/2 **COLTON, CA 92316**
0.401 mi.
2116 ft. **Site 13 of 30 in cluster AI**

Relative:
Lower

Actual:
1037 ft.

San Bern. Co. Permit:

Region:	SAN BERNARDINO
Facility ID:	FA0001679
Owner:	CAL NEV PIPELINE COMPANY
Permit Number:	PT0002633
Permit Category:	CE ANNUAL FEE
Facility Status:	INACTIVE
Expiration Date:	09/30/2007

Region:	SAN BERNARDINO
Facility ID:	FA0001679
Owner:	CAL NEV PIPELINE COMPANY
Permit Number:	PT0002634
Permit Category:	HAZMAT HANDLER 0-10 EMPLOYEES (W/GEN PRMT)
Facility Status:	ACTIVE
Expiration Date:	09/30/2013

Region:	SAN BERNARDINO
Facility ID:	FA0001679
Owner:	CAL NEV PIPELINE COMPANY
Permit Number:	PT0002635
Permit Category:	HAZARDOUS WASTE GENERATOR - 0-10 EMPLOYEES
Facility Status:	ACTIVE
Expiration Date:	09/30/2013

Region:	SAN BERNARDINO
Facility ID:	FA0001679
Owner:	CAL NEV PIPELINE COMPANY
Permit Number:	PT0002631
Permit Category:	EPCRA FACILITY
Facility Status:	ACTIVE
Expiration Date:	09/30/2013

Region:	SAN BERNARDINO
Facility ID:	FA0001679
Owner:	CAL NEV PIPELINE COMPANY
Permit Number:	PT0002632

CAL NEV PIPELINE COLTON (Continued) **S102038736**

Permit Category: APSA EXEMPT TANK(S)
Facility Status: ACTIVE
Expiration Date: 09/30/2013

AI283 **ERNS** **2010937467**
SSW **2051 E. SLOVER AVE.** **N/A**
1/4-1/2 **BLOOMINGTON, CA 92316**
0.401 mi.
2116 ft. **Site 14 of 30 in cluster AI**

Relative:
Lower

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

Actual:
1037 ft.

AI284 **ERNS** **2008892012**
SSW **2051 E. SLOVER AVE.** **N/A**
1/4-1/2 **BLOOMINGTON, CA 92316**
0.401 mi.
2116 ft. **Site 15 of 30 in cluster AI**

Relative:
Lower

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

Actual:
1037 ft.

AI285 **ERNS** **2006814398**
SSW **2051 E. SLOVER AVE.** **N/A**
1/4-1/2 **BLOOMINGTON, CA**
0.401 mi.
2116 ft. **Site 16 of 30 in cluster AI**

Relative:
Lower

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

Actual:
1037 ft.

AI286 **CALNEV PIPE LINE, LLC** **EMI** **S108431292**
SSW **2051 E SLOVER AVE** **N/A**
1/4-1/2 **BLOOMINGTON, CA 92324**
0.401 mi.
2116 ft. **Site 17 of 30 in cluster AI**

Relative:
Lower

Actual:
1037 ft.

EMI:

Year:	2005
County Code:	36
Air Basin:	SC
Facility ID:	800022
Air District Name:	SC
SIC Code:	4226
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	15.1092
Reactive Organic Gases Tons/Yr:	14.057056798
Carbon Monoxide Emissions Tons/Yr:	.797175
NOX - Oxides of Nitrogen Tons/Yr:	.3177
SOX - Oxides of Sulphur Tons/Yr:	.000905
Particulate Matter Tons/Yr:	.007575
Part. Matter 10 Micrometers & Smllr Tons/Yr:	.0072726

CALNEV PIPE LINE, LLC (Continued) **S108431292**

Year:	2006
County Code:	36
Air Basin:	SC
Facility ID:	800022
Air District Name:	SC
SIC Code:	4226
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	24.24364441269467832
Reactive Organic Gases Tons/Yr:	18.981
Carbon Monoxide Emissions Tons/Yr:	.216
NOX - Oxides of Nitrogen Tons/Yr:	.291
SOX - Oxides of Sulphur Tons/Yr:	.001
Particulate Matter Tons/Yr:	.007
Part. Matter 10 Micrometers & Smllr Tons/Yr:	.00672

Year:	2007
County Code:	36
Air Basin:	SC
Facility ID:	800022
Air District Name:	SC
SIC Code:	4789
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	18.66651704055848124
Reactive Organic Gases Tons/Yr:	17.2335595783545
Carbon Monoxide Emissions Tons/Yr:	.0500992
NOX - Oxides of Nitrogen Tons/Yr:	.1103968
SOX - Oxides of Sulphur Tons/Yr:	.0004975
Particulate Matter Tons/Yr:	.00409003
Part. Matter 10 Micrometers & Smllr Tons/Yr:	.0039920776

Year:	2007
County Code:	36
Air Basin:	SC
Facility ID:	800022
Air District Name:	SC
SIC Code:	4226
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	23.84671973642540500
Reactive Organic Gases Tons/Yr:	18.981
Carbon Monoxide Emissions Tons/Yr:	.216
NOX - Oxides of Nitrogen Tons/Yr:	.291
SOX - Oxides of Sulphur Tons/Yr:	.001
Particulate Matter Tons/Yr:	.007
Part. Matter 10 Micrometers & Smllr Tons/Yr:	.00672

AI287 **CHMIRS** **S105641951**
SSW **CAL NEV COLTON TERMINAL 2051 EAST SLOVER AVE** **N/A**
1/4-1/2 **BLOOMINGTON, CA 92316**
0.401 mi.
2116 ft. **Site 18 of 30 in cluster AI**

Relative:
Lower

Actual:
1037 ft.

CHMIRS:

OES Incident Number:	006728	
OES notification:	Not reported	
OES Date:	2/10/1995	
OES Time:	10:35:17 AM	
Incident Date:	Not reported	
Date Completed:	**Not reported**	
Property Use:	Not reported	
Agency Id Number:	Not reported	
Agency Incident Number:	Not reported	
Time Notified:	Not reported	
Time Completed:	Not reported	
Surrounding Area:	Not reported	
Estimated Temperature:	Not reported	
Property Management:	Not reported	
Special Studies 1:	Not reported	
Special Studies 2:	Not reported	
Special Studies 3:	Not reported	
Special Studies 4:	Not reported	
Special Studies 5:	Not reported	
Special Studies 6:	Not reported	
More Than Two Substances Involved?:		Not reported
Resp Agncy Personel # Of Decontaminated:		Not reported
Responding Agency Personel # Of Injuries:		Not reported
Responding Agency Personel # Of Fatalities:		Not reported
Others Number Of Decontaminated:		Not reported
Others Number Of Injuries:		Not reported
Others Number Of Fatalities:		Not reported
Vehicle Make/year:	Not reported	
Vehicle License Number:	Not reported	
Vehicle State:	Not reported	
Vehicle Id Number:	Not reported	
CA/DOT/PUC/ICC Number:	Not reported	
Company Name:	Not reported	
Reporting Officer Name/ID:	Not reported	
Report Date:	Not reported	
Comments:	Not reported	
Facility Telephone:	Not reported	
Waterway Involved:	YES	
Waterway:	Not reported	
Spill Site:	Not reported	
Cleanup By:	on scene personnel/priv cont	
Containment:	Not reported	
What Happened:	Not reported	
Type:	Not reported	
Measure:	Not reported	
Other:	Not reported	
Date/Time:	Not reported	
Year:	1995	
Agency:	cal nev p/l	
Incident Date:	2/9/95 0900	
Admin Agency:	Not reported	
Amount:	2800 gal	

(Continued) **S105641951**

Contained:	NO
Site Type:	Not reported
E Date:	Not reported
Substance:	diesel fuel
Quantity Released:	Not reported
BBLS:	Not reported
Cups:	Not reported
CUFT:	Not reported
Gallons:	Not reported
Grams:	Not reported
Pounds:	Not reported
Liters:	Not reported
Ounces:	Not reported
Pints:	Not reported
Quarts:	Not reported
Sheen:	Not reported
Tons:	Not reported
Unknown:	Not reported
Evacuations:	NO
Number of Injuries:	NO
Number of Fatalities:	NO
Description:	tank 133 being put back into service found to be faulty during filling
	Not reported

AG288 **CITY OF RIALTO REDEVELOPMENT AGENCY** **HAZNET** **S112985839**
West **1485 S WILLOW AVE** **N/A**
1/4-1/2 **RIALTO, CA 92376**
0.401 mi.
2116 ft. **Site 2 of 7 in cluster AG**

Relative:
Higher

Actual:
1083 ft.

HAZNET:

Year:	2011
Gepaid:	CAC002666173
Contact:	ROBERT WATSON
Telephone:	9098202505
Mailing Name:	Not reported
Mailing Address:	131 S RIVERSIDE AVE
Mailing City,St,Zip:	RIALTO, CA 923766413
Gen County:	Not reported
TSD EPA ID:	CAD009007626
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	3.2
Facility County:	San Bernardino

AG289 **SOCAL STRUCTURAL STEEL FABRICATION INC** **HAZNET** **S113115275**
West **1485 S WILLOW AVE** **N/A**
1/4-1/2 **RIALTO, CA 92376**
0.401 mi.
2116 ft. **Site 3 of 7 in cluster AG**

Relative:
Higher

Actual:
1083 ft.

HAZNET:

Year:	2005
Gepaid:	CAL000231915
Contact:	MIKE VAN BLANKENSTEIN
Telephone:	9098771299
Mailing Name:	Not reported
Mailing Address:	130 S SPRUCE AVE
Mailing City,St,Zip:	RIALTO, CA 923760000
Gen County:	Not reported
TSD EPA ID:	CAD980884183
TSD County:	Not reported
Waste Category:	Waste oil and mixed oil
Disposal Method:	Transfer Station
Tons:	0.68
Facility County:	San Bernardino

Year:	2002
Gepaid:	CAL000231915
Contact:	MIKE VAN BLANKENSTEIN
Telephone:	9098771299
Mailing Name:	Not reported
Mailing Address:	130 S SPRUCE AVE
Mailing City,St,Zip:	RIALTO, CA 923760000
Gen County:	Not reported
TSD EPA ID:	CAD050086850
TSD County:	Not reported
Waste Category:	Unspecified organic liquid mixture
Disposal Method:	Transfer Station
Tons:	0.2
Facility County:	San Bernardino

Year:	2002
Gepaid:	CAL000231915
Contact:	MIKE VAN BLANKENSTEIN
Telephone:	9098771299
Mailing Name:	Not reported
Mailing Address:	130 S SPRUCE AVE
Mailing City,St,Zip:	RIALTO, CA 923760000
Gen County:	Not reported
TSD EPA ID:	CAD050086850
TSD County:	Not reported
Waste Category:	Waste oil and mixed oil
Disposal Method:	Transfer Station
Tons:	0.2
Facility County:	San Bernardino

AG290 **HALSEY MACHINE & MFR COMPANY** **HAZNET** **S112961576**
West **1485 S WILLOW AVE** **N/A**
1/4-1/2 **RIALTO, CA 92376**
0.401 mi.
2116 ft. **Site 4 of 7 in cluster AG**

Relative:
Higher

Actual:
1083 ft.

HAZNET:

Year:	2007
Gepaid:	CAC002616895
Contact:	SCOTT TAYLOR
Telephone:	9492468276
Mailing Name:	Not reported
Mailing Address:	9400 CHERRY AVE BLDG C
Mailing City,St,Zip:	FONTANA, CA 923350000
Gen County:	Not reported
TSD EPA ID:	CAD982444481
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.12
Facility County:	San Bernardino

Year:	2007
Gepaid:	CAC002616895
Contact:	SCOTT TAYLOR
Telephone:	9492468276
Mailing Name:	Not reported
Mailing Address:	9400 CHERRY AVE BLDG C
Mailing City,St,Zip:	FONTANA, CA 923350000
Gen County:	Not reported
TSD EPA ID:	CAD008252405
TSD County:	Not reported
Waste Category:	Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method:	Fuel Blending Prior To Energy Recovery At Another Site
Tons:	0.13
Facility County:	San Bernardino

AG291 **HALSEY MACHINERY** **CA FID UST** **S101591121**
West **1485 S WILLOW** **SLIC** **N/A**
1/4-1/2 **RIALTO, CA 92376** **SWEEPS UST**
0.401 mi. **San Bern. Co. Permit**
2116 ft. **Site 5 of 7 in cluster AG**

Relative:
Higher

Actual:
1083 ft.

CA FID UST:

Facility ID:	36001650
Regulated By:	UTNKA
Regulated ID:	Not reported
Cortese Code:	Not reported
SIC Code:	Not reported
Facility Phone:	7148771660
Mail To:	Not reported
Mailing Address:	1485 S WILLOW
Mailing Address 2:	Not reported
Mailing City,St,Zip:	RIALTO 92376
Contact:	Not reported
Contact Phone:	Not reported
DUNs Number:	Not reported
NPDES Number:	Not reported
EPA ID:	Not reported

HALSEY MACHINERY (Continued) **S101591121**

Comments: Not reported
Status: Active

SLIC:

Region:	STATE
Facility Status:	**Open - Site Assessment**
Status Date:	03/26/2012
Global Id:	T10000001676
Lead Agency:	SAN BERNARDINO COUNTY
Lead Agency Case Number:	RO0001336V
Latitude:	34.074556
Longitude:	-117.373502
Case Type:	Cleanup Program Site
Case Worker:	CB
Local Agency:	SAN BERNARDINO COUNTY
RB Case Number:	Not reported
File Location:	Local Library
Potential Media Affected:	Not reported
Potential Contaminants of Concern:	Other Solvent or Non-Petroleum Hydrocarbon, Other Metal, Other Petroleum
Site History:	The City of Rialto (City) Redevelopment Agency is applying for a $200,000 EPA Brownfield Cleanup Grant to mitigate contamination at a 4.76-acre site located at 1485 S. Willow Avenue, Rialto, California within the Rialto Redevelopment Agencys Gateway Redevelopment Project Area. The City acquired the property on September 15, 2008 after completing Phase I and Phase II Environmental Site Assessments on the property. The Citys goal is to remediate and prepare the Site for a redevelopment project that will involve the consolidation of the Site with the adjacent 13.5 acres of land, which is also under City ownership. The Phase I identified 11 Areas of Concern. The Phase II investigated these 11 areas and identified 3 areas that will require the removal of contaminated soils, additional remedial excavation of buried materials, and removal and disposal of asbestos construction materials and lead based paint. The Regional Water Quality Control Board encourages the City in its efforts to identify and remediate contaminated properties within redevelopment areas of the City. We also recognize the value of mitigating contamination to allow for redevelopment of blighted areas. Therefore, we support your EPA Brownfield Cleanup Grant application and will cooperate with the City to resolve potential contamination issues in order to facilitate the incorporation of the 4.76-acre site into the Rialto Gateway Redevelopment Project. The City of Rialto (City) Redevelopment Agency is applying for a $400,000 EPA Brownfield Assessment Grant to assist in the investigation of various brownfield sites that exist within the community. The City will use the grant funds to inventory, characterize, assess, and conduct cleanup planning on targeted brownfield sites that are located within the historic rail transport center and the older downtown central business district, along Foothill Boulevard (Historic Route 66), as well as other sites in the community that may be identified and selected as a result of the community outreach and participation process. If the grant is awarded, the City will use the grant funds to hire certified environmental professionals to prepare Phase I and Phase II site investigations on previously developed brownfield sites within the community. Based upon the size of the grant, the City anticipates that it will be able to investigate between 10 to 20 brownfield sites in the community depending upon the size and scope of the

HALSEY MACHINERY (Continued) **S101591121**

investigations. The Regional Water Quality Control Board recognizes the need to identify historical sources of contamination in our Region that may have contributed to groundwater contamination. The Regional Water Quality Control Board encourages the City in its efforts to identify and remediate contaminated properties within redevelopment areas of the City. We, therefore, support your EPA Brownfield Assessment Grant application and will cooperate with the City to resolve potential contamination issues. In this manner, the City will be able to facilitate redevelopment of various sites in the community, including sites along historic Route 66.

Click here to access the California GeoTracker records for this facility:

SWEEPS UST:

Status:	Active
Comp Number:	27957
Number:	9
Board Of Equalization:	Not reported
Referral Date:	09-10-91
Action Date:	09-10-91
Created Date:	09-14-90
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	Not reported
Actv Date:	Not reported
Capacity:	Not reported
Tank Use:	Not reported
Stg:	Not reported
Content:	Not reported
Number Of Tanks:	Not reported

Status:	Not reported
Comp Number:	27957
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	36-000-027957-000001
Actv Date:	Not reported
Capacity:	5000
Tank Use:	M.V. FUEL
Stg:	PRODUCT
Content:	DIESEL
Number Of Tanks:	1

San Bern. Co. Permit:

Region:	SAN BERNARDINO
Facility ID:	FA0007177
Owner:	W C BROWN WELDING, INC.
Permit Number:	PT0002011
Permit Category:	CONDITIONALLY EXEMPT SMALL QUANTITY GENERATOR
Facility Status:	INACTIVE
Expiration Date:	11/30/2013

HALSEY MACHINERY (Continued) **S101591121**

Region: SAN BERNARDINO
Facility ID: FA0007177
Owner: W C BROWN WELDING, INC.
Permit Number: PT0002012
Permit Category: HAZMAT HANDLER 0-10 EMPLOYEES (W/GEN PRMT)
Facility Status: INACTIVE
Expiration Date: 11/30/2012

Region: SAN BERNARDINO
Facility ID: FA0010122
Owner: PLASTIC PILINGS, INC
Permit Number: PT0022075
Permit Category: HAZARDOUS WASTE GENERATOR - 0-10 EMPLOYEES
Facility Status: INACTIVE
Expiration Date: 01/31/2010

Region: SAN BERNARDINO
Facility ID: FA0010122
Owner: PLASTIC PILINGS, INC
Permit Number: PT0017288
Permit Category: HAZMAT HANDLER 11-25 EMPLOYEES
Facility Status: INACTIVE
Expiration Date: 01/31/2009

Region: SAN BERNARDINO
Facility ID: FA0011709
Owner: AMERICAN TOWER CORP
Permit Number: PT0020292
Permit Category: HAZMAT HANDLER - UNSTAFFED REMOTE FACILITY
Facility Status: ACTIVE
Expiration Date: 08/31/2013

AG292 **WDLJ SOUTH PROPERTY** **EMI** **S106832301**
West **1485 SOUTH WILLOW STREET** **ENVIROSTOR** **N/A**
1/4-1/2 **RIALTO, CA 92316**
0.401 mi.
2116 ft. **Site 6 of 7 in cluster AG**

Relative:
Higher

Actual:
1083 ft.

EMI:

Year:	1987
County Code:	36
Air Basin:	SC
Facility ID:	23251
Air District Name:	SC
SIC Code:	3444
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1990
County Code:	36

WDLJ SOUTH PROPERTY (Continued) **S106832301**

Air Basin:	SC
Facility ID:	23251
Air District Name:	SC
SIC Code:	3444
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

ENVIROSTOR:

Site Type:	Evaluation
Site Type Detailed:	Evaluation
Acres:	8.17
NPL:	NO
Regulatory Agencies:	SMBRP
Lead Agency:	SMBRP
Program Manager:	Eileen Mananian
Supervisor:	Emad Yemut
Division Branch:	Southern California Schools & Brownfields Outreach
Facility ID:	60001766
Site Code:	401620
Assembly:	62
Senate:	32
Special Program:	EPA - Target Site Investigation
Status:	Active
Status Date:	08/08/2012
Restricted Use:	NO
Site Mgmt. Req.:	NONE SPECIFIED
Funding:	EPA Grant
Latitude:	34.07455
Longitude:	-117.3735
APN:	NONE SPECIFIED
Past Use:	WASTE - SEWAGE TREATMENT PLANT
Potential COC:	NONE SPECIFIED
Confirmed COC:	NONE SPECIFIED
Potential Description:	SOIL
Alias Name:	401620
Alias Type:	Project Code (Site Code)
Alias Name:	60001766
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Technical Report
Completed Date:	07/20/2008
Comments:	Document prepared by the City of Rialto Redevelopment Agency (former) and was submitted to DTSC for review in preparation for additional investigation under the TSI Grant.
Completed Area Name:	PROJECT WIDE

WDLJ SOUTH PROPERTY (Continued) **S106832301**

Completed Sub Area Name:	Not reported
Completed Document Type:	Application
Completed Date:	06/30/2012
Comments:	TSI Application received by DTSC.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Site Characterization Workplan
Completed Date:	01/16/2013
Comments:	Workplan approved by DTSC.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Correspondence
Completed Date:	08/03/2012
Comments:	Letter sent to TSI applicant notifying them of being awarded TSI funds for their project.
Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Schedule Area Name:	PROJECT WIDE
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Site Characterization Report
Schedule Due Date:	05/22/2013
Schedule Revised Date:	Not reported

AG293 **HALSEY MACHINE & MFR COMPANY** **HAZNET** **S113041228**
West **1485 SOUTH WILLOW AVENUE** **N/A**
1/4-1/2 **RIALTO, CA 92376**
0.401 mi.
2116 ft. **Site 7 of 7 in cluster AG**

Relative:
Higher

Actual:
1083 ft.

HAZNET:

Year:	1996
Gepaid:	CAL000047914
Contact:	IVANS WAYNE
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	9400 CHERRY AVE BLDG C
Mailing City,St,Zip:	FONTANA, CA 923350000
Gen County:	Not reported
TSD EPA ID:	CAD089446710
TSD County:	Not reported
Waste Category:	Waste oil and mixed oil
Disposal Method:	Transfer Station
Tons:	.5838
Facility County:	San Bernardino
Year:	1996
Gepaid:	CAL000047914
Contact:	IVANS WAYNE
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	9400 CHERRY AVE BLDG C
Mailing City,St,Zip:	FONTANA, CA 923350000
Gen County:	Not reported

HALSEY MACHINE & MFR COMPANY (Continued) **S113041228**

TSD EPA ID: CAD089446710
TSD County: Not reported
Waste Category: Other organic solids
Disposal Method: Transfer Station
Tons: 2.1750
Facility County: San Bernardino

Year: 1996
Gepaid: CAL000047914
Contact: IVANS WAYNE
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 9400 CHERRY AVE BLDG C
Mailing City,St,Zip: FONTANA, CA 923350000
Gen County: Not reported
TSD EPA ID: CAD089446710
TSD County: Not reported
Waste Category: Off-specification, aged or surplus organics
Disposal Method: Transfer Station
Tons: .8380
Facility County: San Bernardino

Year: 1996
Gepaid: CAL000047914
Contact: IVANS WAYNE
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 9400 CHERRY AVE BLDG C
Mailing City,St,Zip: FONTANA, CA 923350000
Gen County: Not reported
TSD EPA ID: CAT080011059
TSD County: Not reported
Waste Category: Waste oil and mixed oil
Disposal Method: Recycler
Tons: 6.2550
Facility County: San Bernardino

Year: 1993
Gepaid: CAL000047914
Contact: IVANS WAYNE
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 9400 CHERRY AVE BLDG C
Mailing City,St,Zip: FONTANA, CA 923350000
Gen County: Not reported
TSD EPA ID: CAT080011059
TSD County: Not reported
Waste Category: Waste oil and mixed oil
Disposal Method: Not reported
Tons: 0.75
Facility County: San Bernardino

Click this hyperlink while viewing on your computer to access
3 additional CA_HAZNET: record(s) in the EDR Site Report.

AI294 **CHMIRS** **S105668311**
SSW **2051 E SLOVER AVE.** **N/A**
1/4-1/2 **COLTON, CA 92408**
0.401 mi.
2119 ft. **Site 19 of 30 in cluster AI**

Relative:
Lower

Actual:
1039 ft.

CHMIRS:

OES Incident Number:	00-1416	
OES notification:	03/26/2000	
OES Date:	Not reported	
OES Time:	Not reported	
Incident Date:	Not reported	
Date Completed:	**Not reported**	
Property Use:	Not reported	
Agency Id Number:	Not reported	
Agency Incident Number:	Not reported	
Time Notified:	Not reported	
Time Completed:	Not reported	
Surrounding Area:	Not reported	
Estimated Temperature:	Not reported	
Property Management:	Not reported	
Special Studies 1:	Not reported	
Special Studies 2:	Not reported	
Special Studies 3:	Not reported	
Special Studies 4:	Not reported	
Special Studies 5:	Not reported	
Special Studies 6:	Not reported	
More Than Two Substances Involved?:		Not reported
Resp Agncy Personel # Of Decontaminated:		Not reported
Responding Agency Personel # Of Injuries:		Not reported
Responding Agency Personel # Of Fatalities:		Not reported
Others Number Of Decontaminated:		Not reported
Others Number Of Injuries:		Not reported
Others Number Of Fatalities:		Not reported
Vehicle Make/year:	Not reported	
Vehicle License Number:	Not reported	
Vehicle State:	Not reported	
Vehicle Id Number:	Not reported	
CA/DOT/PUC/ICC Number:	Not reported	
Company Name:	Not reported	
Reporting Officer Name/ID:	Not reported	
Report Date:	Not reported	
Comments:	Not reported	
Facility Telephone:	Not reported	
Waterway Involved:	No	
Waterway:	Not reported	
Spill Site:	Not reported	
Cleanup By:	Reporting Party	
Containment:	Not reported	
What Happened:	Not reported	
Type:	Not reported	
Measure:	Not reported	
Other:	Not reported	
Date/Time:	Not reported	
Year:	2000	
Agency:	Calnev Pipeline Co.	
Incident Date:	3/26/200012:00:00 AM	
Admin Agency:	San Bernardino County Health Department	
Amount:	Not reported	

(Continued) **S105668311**

Contained:	Yes
Site Type:	Pipe Line
E Date:	Not reported
Substance:	Diesel
Quantity Released:	Not reported
BBLS:	0
Cups:	0
CUFT:	0
Gallons:	200
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	A leaking flange inside terminal

AI295 **ERNS** **2006808769**
SSW **2051 E. SLOVER** **N/A**
1/4-1/2 **SAN BERNARDINO, CA**
0.401 mi.
2119 ft. **Site 20 of 30 in cluster AI**

Relative:
Lower

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

Actual:
1039 ft.

AI296 **CHMIRS** **S105677456**
SSW **2051 W. SLOVER AVE.** **N/A**
1/4-1/2 **COLTON, CA 92412**
0.401 mi.
2119 ft. **Site 21 of 30 in cluster AI**

Relative:
Lower

Actual:
1039 ft.

CHMIRS:

OES Incident Number:	01-0500
OES notification:	01/24/2001
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported

(Continued) **S105677456**

Special Studies 5:	Not reported	
Special Studies 6:	Not reported	
More Than Two Substances Involved?:		Not reported
Resp Agncy Personel # Of Decontaminated:		Not reported
Responding Agency Personel # Of Injuries:		Not reported
Responding Agency Personel # Of Fatalities:		Not reported
Others Number Of Decontaminated:		Not reported
Others Number Of Injuries:		Not reported
Others Number Of Fatalities:		Not reported
Vehicle Make/year:	Not reported	
Vehicle License Number:	Not reported	
Vehicle State:	Not reported	
Vehicle Id Number:	Not reported	
CA/DOT/PUC/ICC Number:	Not reported	
Company Name:	Not reported	
Reporting Officer Name/ID:	Not reported	
Report Date:	Not reported	
Comments:	Not reported	
Facility Telephone:	Not reported	
Waterway Involved:	No	
Waterway:	Not reported	
Spill Site:	Not reported	
Cleanup By:	Unknown	
Containment:	Not reported	
What Happened:	Not reported	
Type:	Not reported	
Measure:	Not reported	
Other:	Not reported	
Date/Time:	Not reported	
Year:	2001	
Agency:	NRC	
Incident Date:	1/24/200112:00:00 AM	
Admin Agency:	San Bernardino County Health Department	
Amount:	Not reported	
Contained:	Yes	
Site Type:	Pipe Line	
E Date:	Not reported	
Substance:	Gasoline	
Quantity Released:	Not reported	
BBLS:	0	
Cups:	0	
CUFT:	0	
Gallons:	0	
Grams:	0	
Pounds:	0	
Liters:	0	
Ounces:	0	
Pints:	0	
Quarts:	0	
Sheen:	0	
Tons:	0	
Unknown:	Unknown	
Evacuations:	0	
Number of Injuries:	0	
Number of Fatalities:	0	
Description:	A leak was discovered on a pipeline while doing maintenance	

AI297 **ERNS** **2007311141**
SSW **2051 EAST SLOVER** **N/A**
1/4-1/2 **BLOOMINGTON, CA**
0.401 mi.
2119 ft. **Site 22 of 30 in cluster AI**

Relative:
Lower

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

Actual:
1039 ft.

AI298 **CHMIRS** **S100275088**
SSW **2051 W. SLOVER AVE** **N/A**
1/4-1/2 **SOLTON, CA 92324**
0.401 mi.
2119 ft. **Site 23 of 30 in cluster AI**

Relative:
Lower

Actual:
1039 ft.

CHMIRS:

OES Incident Number:	8907724
OES notification:	Not reported
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	31-AUG-89
Date Completed:	**31-AUG-89**
Property Use:	800
Agency Id Number:	36709
Agency Incident Number:	892200262
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	600
Estimated Temperature:	80
Property Management:	P
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Involved?:	N
Resp Agncy Personel # Of Decontaminated:	0
Responding Agency Personel # Of Injuries:	0
Responding Agency Personel # Of Fatalities:	0
Others Number Of Decontaminated:	0
Others Number Of Injuries:	0
Others Number Of Fatalities:	0
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	CATHERINE B. RICHARDS ENV. HEALTH SPECIALIST
Report Date:	27-OCT-89
Comments:	Not reported
Facility Telephone:	714 387-3044
Waterway Involved:	Not reported
Waterway:	Not reported
Spill Site:	Not reported
Cleanup By:	Not reported
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported

(Continued) **S100275088**

Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	88-92
Agency:	Not reported
Incident Date:	Not reported
Admin Agency:	Not reported
Amount:	Not reported
Contained:	Not reported
Site Type:	Not reported
E Date:	18-MAY-90
Substance:	Not reported
Quantity Released:	Not reported
BBLS:	Not reported
Cups:	Not reported
CUFT:	Not reported
Gallons:	Not reported
Grams:	Not reported
Pounds:	Not reported
Liters:	Not reported
Ounces:	Not reported
Pints:	Not reported
Quarts:	Not reported
Sheen:	Not reported
Tons:	Not reported
Unknown:	Not reported
Evacuations:	Not reported
Number of Injuries:	Not reported
Number of Fatalities:	Not reported
Description:	Not reported

AI299 **ERNS** **92280739**
SSW **2051 SLOVER AVE** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.401 mi.
2119 ft. **Site 24 of 30 in cluster AI**

Relative:
Lower

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

Actual:
1039 ft.

AI300 **ERNS** **90179352**
SSW **2051 W. SLOVER AVENUE** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.401 mi.
2119 ft. **Site 25 of 30 in cluster AI**

Relative:
Lower

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

Actual:
1039 ft.

AI301 **CHMIRS** **S109037204**
SSW **2051 EAST SLOBER AVE** **N/A**
1/4-1/2 **BLOOMINGTON, CA 92316**
0.401 mi.
2119 ft. **Site 26 of 30 in cluster AI**

Relative:
Lower

Actual:
1039 ft.

CHMIRS:

OES Incident Number:	07-2769	
OES notification:	05/07/2007	
OES Date:	Not reported	
OES Time:	Not reported	
Incident Date:	Not reported	
Date Completed:	**Not reported**	
Property Use:	Not reported	
Agency Id Number:	Not reported	
Agency Incident Number:	Not reported	
Time Notified:	Not reported	
Time Completed:	Not reported	
Surrounding Area:	Not reported	
Estimated Temperature:	Not reported	
Property Management:	Not reported	
Special Studies 1:	Not reported	
Special Studies 2:	Not reported	
Special Studies 3:	Not reported	
Special Studies 4:	Not reported	
Special Studies 5:	Not reported	
Special Studies 6:	Not reported	
More Than Two Substances Involved?:		Not reported
Resp Agncy Personel # Of Decontaminated:		Not reported
Responding Agency Personel # Of Injuries:		Not reported
Responding Agency Personel # Of Fatalities:		Not reported
Others Number Of Decontaminated:		Not reported
Others Number Of Injuries:		Not reported
Others Number Of Fatalities:		Not reported
Vehicle Make/year:	Not reported	
Vehicle License Number:	Not reported	
Vehicle State:	Not reported	
Vehicle Id Number:	Not reported	
CA/DOT/PUC/ICC Number:	Not reported	
Company Name:	Not reported	
Reporting Officer Name/ID:	Not reported	
Report Date:	Not reported	
Comments:	Not reported	
Facility Telephone:	Not reported	
Waterway Involved:	Not reported	
Waterway:	Not reported	
Spill Site:	Not reported	
Cleanup By:	Reporting Party	
Containment:	Not reported	
What Happened:	Not reported	
Type:	Not reported	
Measure:	Not reported	
Other:	Not reported	
Date/Time:	Not reported	
Year:	2007	
Agency:	Kinder Morgan	
Incident Date:	5/7/2007 12:00:00 AM	
Admin Agency:	San Bernardino County Health Department	
Amount:	Not reported	

(Continued) **S109037204**

Contained:	Unknown
Site Type:	Pipe Line
E Date:	Not reported
Substance:	Threat of release
Quantity Released:	Not reported
BBLS:	0
Cups:	0
CUFT:	0
Gallons:	0.000000
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	hydro test with a possible threat of a release during the test no release at this time

---

AI302 **ERNS** **2008864054**
SSW **2051 EAST SLOVER** **N/A**
1/4-1/2 **BLOOMINGTON, CA**
0.401 mi.
2119 ft. **Site 27 of 30 in cluster AI**

Relative:
Lower

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

Actual:
1039 ft.

AI303 **CALNEV PIPE LINE CO** **EMI** **S105936980**
SSW **2051 W SLOVER AVE** **N/A**
1/4-1/2 **BLOOMINGTON, CA 92324**
0.402 mi.
2121 ft. **Site 28 of 30 in cluster AI**

Relative:
Lower

Actual:
1039 ft.

EMI:

Year:	1993
County Code:	36
Air Basin:	SC
Facility ID:	800022
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

CALNEV PIPE LINE CO (Continued) **S105936980**

Year:	1995
County Code:	36
Air Basin:	SC
Facility ID:	800022
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1996
County Code:	36
Air Basin:	SC
Facility ID:	800022
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	22
Reactive Organic Gases Tons/Yr:	21
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1997
County Code:	36
Air Basin:	SC
Facility ID:	800022
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	41
Reactive Organic Gases Tons/Yr:	26
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1998
County Code:	36
Air Basin:	SC
Facility ID:	800022
Air District Name:	SC
SIC Code:	5171

CALNEV PIPE LINE CO (Continued) **S105936980**

Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	41
Reactive Organic Gases Tons/Yr:	26
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1999
County Code:	36
Air Basin:	SC
Facility ID:	800022
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	41
Reactive Organic Gases Tons/Yr:	26
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	2000
County Code:	36
Air Basin:	SC
Facility ID:	800022
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	41
Reactive Organic Gases Tons/Yr:	26
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	2001
County Code:	36
Air Basin:	SC
Facility ID:	800022
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Y
Consolidated Emission Reporting Rule:	B
Total Organic Hydrocarbon Gases Tons/Yr:	42
Reactive Organic Gases Tons/Yr:	23
Carbon Monoxide Emissions Tons/Yr:	0

CALNEV PIPE LINE CO (Continued) **S105936980**

NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	5
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0
Year:	2002
County Code:	36
Air Basin:	SC
Facility ID:	800022
Air District Name:	SC
SIC Code:	4226
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	24
Reactive Organic Gases Tons/Yr:	19
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0
Year:	2003
County Code:	36
Air Basin:	SC
Facility ID:	800022
Air District Name:	SC
SIC Code:	4226
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	24
Reactive Organic Gases Tons/Yr:	19
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0
Year:	2004
County Code:	36
Air Basin:	SC
Facility ID:	800022
Air District Name:	SC
SIC Code:	4226
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Y
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	23.637945
Reactive Organic Gases Tons/Yr:	23
Carbon Monoxide Emissions Tons/Yr:	0.101
NOX - Oxides of Nitrogen Tons/Yr:	0.37
SOX - Oxides of Sulphur Tons/Yr:	0.216
Particulate Matter Tons/Yr:	0.0131
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0.01

AI304
SSW
1/4-1/2
0.402 mi.
2121 ft.
Relative: Lower
Actual: 1039 ft.

2051 W. SLOVER AVE.
COLTON, CA

Site 29 of 30 in cluster AI

ERNS **2001554630**
N/A

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

AJ305
East
1/4-1/2
0.402 mi.
2122 ft.
Relative: Lower
Actual: 1018 ft.

862 W G ST
COLTON, CA 92324

Site 1 of 2 in cluster AJ

EDR US Hist Auto Stat **1015658538**
N/A

EDR Historical Auto Stations:
Name: ARTIES ALLISSON TRANSMISSIONS
Year: 2005
Address: 862 W G ST

AI306
SSW
1/4-1/2
0.402 mi.
2125 ft.
Relative: Lower
Actual: 1037 ft.

CONOCOPHILLIPS COLTON TERMINAL-SLOVER
2050 SLOVER AVENUE
BLOOMINGTON, CA 92316

Site 30 of 30 in cluster AI

FINDS **1010044884**
N/A

FINDS:

Registry ID: 110028151719

Environmental Interest/Information System
ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

AK307
NW
1/4-1/2
0.404 mi.
2132 ft.
Relative: Higher
Actual: 1128 ft.

1025 S RIVERSIDE AVE
RIALTO, CA 92376

Site 1 of 2 in cluster AK

EDR US Hist Cleaners **1014969317**
N/A

EDR Historical Cleaners:
Name: BARAJAS CARPET CLEANING
Year: 2004
Address: 1025 S RIVERSIDE AVE

AF308 **CONOCO PHILLIPS COLTON TERMINAL EAST** **RCRA-LQG** **1006805684**
SW **271 E SLOVER AVE** **FINDS** **CAR000131086**
1/4-1/2 **RIALTO, CA 92376** **US AIRS**
0.406 mi.
2145 ft. **Site 5 of 11 in cluster AF**

Relative:
Lower

Actual:
1039 ft.

RCRA-LQG:

Date form received by agency:	04/25/2012
Facility name:	PHILLIPS 66 COLTON TERMINAL EAST
Facility address:	271 E SLOVER AVE RIALTO, CA 92376
EPA ID:	CAR000131086
Mailing address:	3900 KILROY AIRPORT WAY STE 210 LONG BEACH, CA 90806
Contact:	JIM A ADAMS
Contact address:	3900 KILROY AIRPORT WAY STE 210 LONG BEACH, CA 90806
Contact country:	US
Contact telephone:	562-290-1516
Contact email:	JADAMS3@P66.COM
EPA Region:	09
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	PHILLIPS 66
Owner/operator address:	3900 KILROY AIRPORT WAY STE 210 LONG BEACH, CA 90806
Owner/operator country:	US
Owner/operator telephone:	562-290-1500
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	05/01/2012
Owner/Op end date:	Not reported

Owner/operator name:	PHILLIPS 66
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	05/01/2012
Owner/Op end date:	Not reported

Handler Activities Summary:

CONOCO PHILLIPS COLTON TERMINAL EAST (Continued) **1006805684**

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/15/2003
Facility name: PHILLIPS 66 COLTON TERMINAL EAST
Site name: CONOCO PHILLIPS COLTON TERMINAL EAST
Classification: Small Quantity Generator

Hazardous Waste Summary:
Waste code: 133
Waste name: 133

Waste code: 352
Waste name: 352

Waste code: 611
Waste name: 611

Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D007
Waste name: CHROMIUM

Waste code: D008
Waste name: LEAD

Waste code: D009
Waste name: MERCURY

Waste code: D018
Waste name: BENZENE

Violation Status: No violations found

FINDS:

CONOCO PHILLIPS COLTON TERMINAL EAST (Continued) **1006805684**

Registry ID: 110014368102

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

California Hazardous Waste Tracking System - Datamart (HWTS-DATAMART) provides California with information on hazardous waste shipments for generators, transporters, and treatment, storage, and disposal facilities.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CRITERIA AND HAZARDOUS AIR POLLUTANT INVENTORY

US Facility Response Plan (FRP) contains plans for responding, to the maximum extent practical, to worst case discharges of oil.

AIRS (AFS):

Compliance and Violation Data Major Sources:

EPA plant ID:	110038082302
Plant name:	CONOCOPHILLIPS-COLTON TERMINAL EAST
Plant address:	271 E SLOVER RIALTO, CA 92376
County:	SAN BERNARDINO
Region code:	09
Dunn & Bradst #:	Not reported
Air quality cntrl region:	024
Sic code:	2999
Sic code desc:	PETROLEUM AND COAL PRODUCTS, NEC
North Am. industrial classf:	324199
NAIC code description:	All Other Petroleum and Coal Products Manufacturing
Default compliance status:	IN COMPLIANCE - INSPECTION
Default classification:	ACTUAL OR POTENTIAL EMISSIONS ARE ABOVE THE APPLICABLE MAJOR SOURCE THRESHOLDS
Govt facility:	ALL OTHER FACILITIES NOT OWNED OR OPERATED BY A FEDERAL, STATE, OR LOCAL GOVERNMENT

CONOCO PHILLIPS COLTON TERMINAL EAST (Continued) **1006805684**

Current HPV: Not reported

Compliance and Enforcement Major Issues:

Air program: SIP SOURCE
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 100223
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 100223
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 100223
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 100223
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 100302
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 100302
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 100302
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 100302
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 110222
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 110222
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 110608

CONOCO PHILLIPS COLTON TERMINAL EAST (Continued) **1006805684**

Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 110608
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 110610
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 110610
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 110610
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 110610
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 120208
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 120208
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 120424
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 120424
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 120427
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 120427
Penalty amount: Not reported

CONOCO PHILLIPS COLTON TERMINAL EAST (Continued) **1006805684**

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 120427
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 120427
Penalty amount: Not reported

Historical Compliance Minor Sources:
State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1001
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1001
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1002
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1002
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1003
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1003
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1004
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1004
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1101
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1101
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1102
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1102

CONOCO PHILLIPS COLTON TERMINAL EAST (Continued) **1006805684**

Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1103
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1103
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1104
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1104
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1201
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1201
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1202
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1202
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1203
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1203
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1204
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1204
Air prog code hist file: V

Permit Information:
Compliance plant ID: CA211
Permit number: 18503
Permit category: V
Permit category desc: TITLE V PERMIT - PLANT SP

CONOCO PHILLIPS COLTON TERMINAL EAST (Continued) **1006805684**

Permit Source:
- Compliance plant ID: CA211
- Plant name: CONOCOPHILLIPS-COLTON TERMINAL EAST
- Plant address: 271 E SLOVER
  RIALTO, CA 92376

Event Information:
- Compliance permit ID: CA211
- Permit number: 18503
- Event action type: IF
- Event description: *PERMIT AUTHORITY ISSUES FINAL PERMIT
- Event action #: 001
- Event date: 20090213

AF309 **STORMRIALTO** **HIST UST** **U001575531**
SW **271 E. SLOVER AVENUE** **WDS** **N/A**
1/4-1/2 **RIALTO, CA 0**
0.406 mi.
2145 ft. **Site 6 of 11 in cluster AF**

Relative:
Lower

Actual:
1039 ft.

HIST UST:
- Region: STATE
- Facility ID: 00000008220
- Facility Type: Other
- Other Type: PRODUCT TERMINAL
- Total Tanks: 0002
- Contact Name: B.G. HAZLEWOOD
- Telephone: 7148771666
- Owner Name: TOSCO CORPORATION
- Owner Address: 2401 COLORADO AVENUE
- Owner City,St,Zip: SANTA MONICA, CA 90406

- Tank Num: 001
- Container Num: 201
- Year Installed: 1972
- Tank Capacity: 00000600
- Tank Used for: WASTE
- Type of Fuel: DIESEL
- Tank Construction: 3/16 inches
- Leak Detection: None

- Tank Num: 002
- Container Num: 202
- Year Installed: 1972
- Tank Capacity: 00000550
- Tank Used for: WASTE
- Type of Fuel: DIESEL
- Tank Construction: 3/16 centimeters
- Leak Detection: None

CA WDS:
- Facility ID: Santa Ana River 36I006067
- Facility Type: Industrial - Facility that treats and/or disposes of liquid or semisolid wastes from any servicing, producing, manufacturing or processing operation of whatever nature, including mining, gravel

STORMRIALTO (Continued) **U001575531**

	washing, geothermal operations, air conditioning, ship building and repairing, oil production, storage and disposal operations, water pumping.
Facility Status:	Active - Any facility with a continuous or seasonal discharge that is under Waste Discharge Requirements.
NPDES Number:	CAS000001 The 1st 2 characters designate the state. The remaining 7 are assigned by the Regional Board
Subregion:	8
Facility Telephone:	Not reported
Facility Contact:	HENRY JOHNSON
Agency Name:	TOSCO CORPORATION
Agency Address:	PO BOX 2628
Agency City,St,Zip:	SANTA FE SPRINGS 90670
Agency Contact:	HENRY JOHNSON
Agency Telephone:	Not reported
Agency Type:	Private
SIC Code:	9999
SIC Code 2:	Not reported
Primary Waste:	Stormwater Runoff
Primary Waste Type:	Designated/Influent or Solid Wastes that pose a significant threat to water quality because of their high concentrations (E.G., BOD, Hardness, TRF, Chloride). 'Manageable' hazardous wastes (E.G., inorganic salts and heavy metals) are included in this category.
Secondary Waste:	Not reported
Secondary Waste Type:	Not reported
Design Flow:	0
Baseline Flow:	0
Reclamation:	No reclamation requirements associated with this facility.
POTW:	The facility is not a POTW.
Treat To Water:	Minor Threat to Water Quality. A violation of a regional board order should cause a relatively minor impairment of beneficial uses compared to a major or minor threat. Not: All nurds without a TTWQ will be considered a minor threat to water quality unless coded at a higher Level. A Zero (0) may be used to code those NURDS that are found to represent no threat to water quality.
Complexity:	Category C - Facilities having no waste treatment systems, such as cooling water dischargers or thosewho must comply through best management practices, facilities with passive waste treatment and disposal systems, such as septic systems with subsurface disposal, or dischargers having waste storage systems with land disposal such as dairy waste ponds.

AL310 **CALNEV PIPE LINE CO (NSR USE)** **EMI** **S106827890**
SSW **1901 SLOVER AVE.** **N/A**
1/4-1/2 **BLOOMINGTON, CA 92324**
0.407 mi.
2148 ft. **Site 1 of 5 in cluster AL**

Relative:
Lower

Actual:
1022 ft.

EMI:

Year:	1987
County Code:	36
Air Basin:	SC
Facility ID:	800022
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported

CALNEV PIPE LINE CO (NSR USE) (Continued) **S106827890**

Total Organic Hydrocarbon Gases Tons/Yr:	78
Reactive Organic Gases Tons/Yr:	74
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1990
County Code:	36
Air Basin:	SC
Facility ID:	800022
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	34
Reactive Organic Gases Tons/Yr:	31
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

AF311 **CONOCO PHILLIPS CO. - COLTON TERMINAL** **NPDES** **S106841248**
SW **271 E. SLOVER AVE.** **LUST** **N/A**
1/4-1/2 **BLOOMINGTON, CA 92316** **EMI**
0.407 mi.
2151 ft. **Site 7 of 11 in cluster AF**

Relative:
Lower

Actual:
1038 ft.

NPDES:

Npdes Number:	CAS000001
Facility Status:	Active
Agency Id:	0
Region:	8
Regulatory Measure Id:	213229
Order No:	97-03-DWQ
Regulatory Measure Type:	Enrollee
Place Id:	Not reported
WDID:	8 36I006067
Program Type:	Industrial
Adoption Date Of Regulatory Measure:	Not reported
Effective Date Of Regulatory Measure:	04/20/1992
Expiration Date Of Regulatory Measure:	Not reported
Termination Date Of Regulatory Measure:	Not reported
Discharge Name:	ConocoPhillips Santa Fe Springs
Discharge Address:	2301 S. Riverside Ave.
Discharge City:	Bloomington
Discharge State:	California
Discharge Zip:	92316

LUST:

Region:	STATE
Global Id:	SL0607169415
Latitude:	34.0619
Longitude:	-117.3662

CONOCO PHILLIPS CO. - COLTON TERMINAL (Continued) **S106841248**

Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	05/21/2008
Lead Agency:	SANTA ANA RWQCB (REGION 8)
Case Worker:	RS
Local Agency:	SAN BERNARDINO COUNTY
RB Case Number:	Not reported
LOC Case Number:	Not reported
File Location:	Regional Board
Potential Media Affect:	Aquifer used for drinking water supply
Potential Contaminants of Concern:	* Petroleum - Other, * Petroleum - Automotive gasolines
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	SL0607169415
Contact Type:	Local Agency Caseworker
Contact Name:	JACKSON CRUTSINGER
Organization Name:	SAN BERNARDINO COUNTY
Address:	620 SOUTH E STREET
City:	SAN BERNARDINO
Email:	jcrutsinger@sbcfire.org
Phone Number:	Not reported

Global Id:	SL0607169415
Contact Type:	Regional Board Caseworker
Contact Name:	ROSE SCOTT
Organization Name:	SANTA ANA RWQCB (REGION 8)
Address:	3737 MAIN STREET, SUITE 500
City:	RIVERSIDE
Email:	rscott@waterboards.ca.gov
Phone Number:	9513206375

Regulatory Activities:

Global Id:	SL0607169415
Action Type:	ENFORCEMENT
Date:	07/13/2007
Action:	Staff Letter

Global Id:	SL0607169415
Action Type:	Other
Date:	01/01/1950
Action:	Leak Began

Global Id:	SL0607169415
Action Type:	Other
Date:	01/01/1950
Action:	Leak Discovery

Global Id:	SL0607169415
Action Type:	Other
Date:	01/01/1950
Action:	Leak Reported

Global Id:	SL0607169415
Action Type:	ENFORCEMENT

CONOCO PHILLIPS CO. - COLTON TERMINAL (Continued) **S106841248**

Date:	08/12/2007
Action:	Notification - Public Notice of Case Closure
Global Id:	SL0607169415
Action Type:	ENFORCEMENT
Date:	05/21/2008
Action:	Closure/No Further Action Letter
Global Id:	SL0607169415
Action Type:	REMEDIATION
Date:	01/01/1950
Action:	Free Product Removal
Global Id:	SL0607169415
Action Type:	Other
Date:	01/01/1950
Action:	Leak Stopped

EMI:

Year:	1990
County Code:	36
Air Basin:	SC
Facility ID:	18503
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	11
Reactive Organic Gases Tons/Yr:	10
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

AF312 **LION OIL, DIV TOSCO CORP TS-91** **EMI** **S106834551**
SW **271 E. SLOVER** **N/A**
1/4-1/2 **BLOOMINGTON, CA 92316**
0.407 mi.
2151 ft. **Site 8 of 11 in cluster AF**

Relative:
Lower

Actual:
1038 ft.

EMI:

Year:	1987
County Code:	36
Air Basin:	SC
Facility ID:	18503
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	4
Reactive Organic Gases Tons/Yr:	4
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0

LION OIL, DIV TOSCO CORP TS-91 (Continued) **S106834551**

SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers & Smllr Tons/Yr: 0

AF313 **TOSCO CORPORATION, COLTON TERMINAL** **RCRA-SQG** **1000175606**
SW **271 EAST SLOVER AVE** **San Bern. Co. Permit** **CAD000628917**
1/4-1/2 **RIALTO, CA 92376** **EMI**
0.407 mi.
2151 ft. **Site 9 of 11 in cluster AF**

Relative:
Lower

Actual:
1038 ft.

RCRA-SQG:
Date form received by agency: 10/12/2000
Facility name: TOSCO CORPORATION, COLTON TERMINAL
Site name: TOSCO COLTON TERMINAL (EAST)
Facility address: 271 EAST SLOVER AVE
RIALTO, CA 92376
EPA ID: CAD000628917
Mailing address: 2301 SOUTH RIVERSIDE AVE
BLOOMINGTON, CA 92316
Contact: HEATHER M. S. RANDOL
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (562) 906-7560
Contact email: Not reported
EPA Region: 09
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 03/04/1999
Facility name: TOSCO CORPORATION, COLTON TERMINAL
Site name: TOSCO COLTON TERMINAL (EAST)
Classification: Large Quantity Generator

TOSCO CORPORATION, COLTON TERMINAL (Continued) **1000175606**

Date form received by agency: 09/01/1996
Facility name: TOSCO CORPORATION, COLTON TERMINAL
Classification: Small Quantity Generator

Date form received by agency: 08/18/1980
Facility name: TOSCO CORPORATION, COLTON TERMINAL
Classification: Large Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 10/13/1994
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State Contractor/Grantee

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0006728
Owner: PHILLIPS 66 REFINING CO
Permit Number: PT0001973
Permit Category: HAZMAT HANDLER 0-10 EMPLOYEES
Facility Status: ACTIVE
Expiration Date: 09/30/2013

Region: SAN BERNARDINO
Facility ID: FA0006728
Owner: PHILLIPS 66 REFINING CO
Permit Number: PT0001974
Permit Category: APSA 1,000,001-10,000,000 GAL FAC CAPACITY
Facility Status: ACTIVE
Expiration Date: 09/30/2013

EMI:
Year: 1995
County Code: 36
Air Basin: SC
Facility ID: 18503
Air District Name: SC
SIC Code: 5171
Air District Name: SOUTH COAST AQMD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported
Total Organic Hydrocarbon Gases Tons/Yr: 15
Reactive Organic Gases Tons/Yr: 10
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers & Smllr Tons/Yr: 0

Year: 1996
County Code: 36
Air Basin: SC
Facility ID: 18503
Air District Name: SC

TOSCO CORPORATION, COLTON TERMINAL (Continued) **1000175606**

SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	49
Reactive Organic Gases Tons/Yr:	46
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1997
County Code:	36
Air Basin:	SC
Facility ID:	18503
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	12
Reactive Organic Gases Tons/Yr:	9
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1998
County Code:	36
Air Basin:	SC
Facility ID:	18503
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	12
Reactive Organic Gases Tons/Yr:	9
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1999
County Code:	36
Air Basin:	SC
Facility ID:	18503
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	12
Reactive Organic Gases Tons/Yr:	9

TOSCO CORPORATION, COLTON TERMINAL (Continued) **1000175606**

Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	2000
County Code:	36
Air Basin:	SC
Facility ID:	18503
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	12
Reactive Organic Gases Tons/Yr:	9
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	2001
County Code:	36
Air Basin:	SC
Facility ID:	18503
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	8
Reactive Organic Gases Tons/Yr:	6
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	2002
County Code:	36
Air Basin:	SC
Facility ID:	18503
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	6
Reactive Organic Gases Tons/Yr:	6
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

TOSCO CORPORATION, COLTON TERMINAL (Continued) **1000175606**

Year:	2003
County Code:	36
Air Basin:	SC
Facility ID:	18503
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	6
Reactive Organic Gases Tons/Yr:	6
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	2004
County Code:	36
Air Basin:	SC
Facility ID:	18503
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	5.876756
Reactive Organic Gases Tons/Yr:	5.79
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	2005
County Code:	36
Air Basin:	SC
Facility ID:	18503
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	5.77982
Reactive Organic Gases Tons/Yr:	5.68602956
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	2006
County Code:	36
Air Basin:	SC
Facility ID:	18503
Air District Name:	SC
SIC Code:	5171

TOSCO CORPORATION, COLTON TERMINAL (Continued) **1000175606**

Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	7.140370145812267633
Reactive Organic Gases Tons/Yr:	6.248
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	2007
County Code:	36
Air Basin:	SC
Facility ID:	18503
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	6.464999387375648478
Reactive Organic Gases Tons/Yr:	6.248
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	2007
County Code:	36
Air Basin:	SC
Facility ID:	18503
Air District Name:	SC
SIC Code:	5541
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	6.007035415991195450
Reactive Organic Gases Tons/Yr:	5.85114
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

AF314 **TOSCO CORP** **EMI** **S106841249**
SW **271 EAST SLOVER AV** **N/A**
1/4-1/2 **RIALTO, CA 92316**
0.407 mi.
2151 ft. **Site 10 of 11 in cluster AF**

Relative:
Lower

Actual:
1038 ft.

EMI:

Year:	1987
County Code:	36
Air Basin:	SC
Facility ID:	3517
Air District Name:	SC
SIC Code:	5171

TOSCO CORP (Continued) **S106841249**

Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1990
County Code:	36
Air Basin:	SC
Facility ID:	3517
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

AL315 **HMIRS** **94030905**
SSW **1900 SLOVER AVE** **N/A**
1/4-1/2 **BLOOMINGTON, CA**
0.408 mi.
2152 ft. **Site 2 of 5 in cluster AL**

Relative:
Lower

Click this hyperlink while viewing on your computer to access additional HMIRS detail in the EDR Site Report.

Actual:
1022 ft.

AL316 **ERNS** **2008876889**
SSW **1900 SLOVER AVE.** **N/A**
1/4-1/2 **SAN BERNARDINO (County), CA**
0.408 mi.
2152 ft. **Site 3 of 5 in cluster AL**

Relative:
Lower

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

Actual:
1022 ft.

AL317 **COLTON TERMINAL** **HIST UST** **U001574659**
SSW **1901 SLOVER AVENUE** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.408 mi.
2152 ft. **Site 4 of 5 in cluster AL**

Relative:
Lower

Actual:
1022 ft.

HIST UST:

Region:	STATE
Facility ID:	00000020392
Facility Type:	Other
Other Type:	PIPELINE TERMINAL
Total Tanks:	0005
Contact Name:	HAROLD MOYE
Telephone:	7148772414
Owner Name:	CALNEV PIPE LINE COMPANY
Owner Address:	412 HOSPITALITY LANE
Owner City,St,Zip:	SAN BERNARDINO, CA 92408
Tank Num:	001
Container Num:	CU-01
Year Installed:	Not reported
Tank Capacity:	00001000
Tank Used for:	PRODUCT
Type of Fuel:	Not reported
Tank Construction:	Not reported
Leak Detection:	Visual
Tank Num:	002
Container Num:	CU-02
Year Installed:	Not reported
Tank Capacity:	00010000
Tank Used for:	PRODUCT
Type of Fuel:	REGULAR
Tank Construction:	Not reported
Leak Detection:	Visual
Tank Num:	003
Container Num:	CU-03
Year Installed:	Not reported
Tank Capacity:	00003000
Tank Used for:	PRODUCT
Type of Fuel:	06
Tank Construction:	Not reported
Leak Detection:	Visual, Stock Inventor
Tank Num:	004
Container Num:	CU-06
Year Installed:	1985
Tank Capacity:	00005000
Tank Used for:	PRODUCT
Type of Fuel:	Not reported
Tank Construction:	250 2 inches
Leak Detection:	None
Tank Num:	005
Container Num:	CU-07
Year Installed:	1985
Tank Capacity:	00005000
Tank Used for:	PRODUCT

COLTON TERMINAL (Continued) **U001574659**

Type of Fuel: Not reported
Tank Construction: .250 inches
Leak Detection: None

AL318 **HMIRS** **94030918**
SSW **1900 SLOVER AVE** **N/A**
1/4-1/2 **BLOOMINGTON, CA**
0.408 mi.
2152 ft. **Site 5 of 5 in cluster AL**

Relative:
Lower

Click this hyperlink while viewing on your computer to access additional HMIRS detail in the EDR Site Report.

Actual:
1022 ft.

AF319 **CDL** **S107531882**
SW **258 E SLOVER AVE** **N/A**
1/4-1/2 **RIALTO, CA 92324**
0.408 mi.
2152 ft. **Site 11 of 11 in cluster AF**

Relative:
Lower

CDL:
Facility ID: 200001009
Lab Type: Illegal Drug Lab (L) - location where an illegal drug lab was operated or drug lab equipment and/or materials were stored.

Actual:
1036 ft.

AM320 **A & M AUTO REPAIR** **NPDES** **S106230229**
SW **2075 S RIVERSIDE AVE** **San Bern. Co. Permit** **N/A**
1/4-1/2 **RIALTO, CA 92376**
0.412 mi.
2175 ft. **Site 1 of 11 in cluster AM**

Relative:
Lower

NPDES:

Npdes Number:	CAS000002
Facility Status:	Terminated
Agency Id:	0
Region:	8
Regulatory Measure Id:	352159
Order No:	2009-0009-DWQ
Regulatory Measure Type:	Enrollee
Place Id:	Not reported
WDID:	8 36C353399
Program Type:	Construction
Adoption Date Of Regulatory Measure:	Not reported
Effective Date Of Regulatory Measure:	09/15/2008
Expiration Date Of Regulatory Measure:	Not reported
Termination Date Of Regulatory Measure:	09/02/2010
Discharge Name:	Egia Manukyan
Discharge Address:	111 N Main St Bldg B
Discharge City:	RIverside
Discharge State:	California
Discharge Zip:	92501

Actual:
1021 ft.

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0008075
Owner: IANNIZZOTTO, JOE

A & M AUTO REPAIR (Continued) **S106230229**

Permit Number: PT0014209
Permit Category: SPECIAL HANDLER
Facility Status: INACTIVE
Expiration Date: 02/28/2009

Region: SAN BERNARDINO
Facility ID: FA0008075
Owner: IANNIZZOTTO, JOE
Permit Number: PT0014208
Permit Category: SPECIAL GENERATOR
Facility Status: INACTIVE
Expiration Date: 02/28/2009

AN321 **CHMIRS** **S110418473**
South **1800 SLOVER AVE** **N/A**
1/4-1/2 **BLOOMINGTON, CA 92316**
0.413 mi.
2182 ft. **Site 1 of 2 in cluster AN**

Relative:
Lower

Actual:
1046 ft.

CHMIRS:

OES Incident Number:	'08-2696	
OES notification:	04/10/2008	
OES Date:	Not reported	
OES Time:	Not reported	
Incident Date:	Not reported	
Date Completed:	**Not reported**	
Property Use:	Not reported	
Agency Id Number:	Not reported	
Agency Incident Number:	Not reported	
Time Notified:	Not reported	
Time Completed:	Not reported	
Surrounding Area:	Not reported	
Estimated Temperature:	Not reported	
Property Management:	Not reported	
Special Studies 1:	Not reported	
Special Studies 2:	Not reported	
Special Studies 3:	Not reported	
Special Studies 4:	Not reported	
Special Studies 5:	Not reported	
Special Studies 6:	Not reported	
More Than Two Substances Involved?:		Not reported
Resp Agncy Personel # Of Decontaminated:		Not reported
Responding Agency Personel # Of Injuries:		Not reported
Responding Agency Personel # Of Fatalities:		Not reported
Others Number Of Decontaminated:		Not reported
Others Number Of Injuries:		Not reported
Others Number Of Fatalities:		Not reported
Vehicle Make/year:	Not reported	
Vehicle License Number:	Not reported	
Vehicle State:	Not reported	
Vehicle Id Number:	Not reported	
CA/DOT/PUC/ICC Number:	Not reported	
Company Name:	Not reported	
Reporting Officer Name/ID:	Not reported	
Report Date:	Not reported	
Comments:	Not reported	
Facility Telephone:	Not reported	
Waterway Involved:	No	

(Continued) **S110418473**

Waterway:	Not reported
Spill Site:	Merchant/Business
Cleanup By:	Responsible Party
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Qt.(s)
Other:	Not reported
Date/Time:	0926
Year:	2008
Agency:	HAZMAT 1
Incident Date:	4/10/2008
Admin Agency:	San Bernardino County Health Department
Amount:	Not reported
Contained:	Yes
Site Type:	Not reported
E Date:	Not reported
Substance:	Bondo
Quantity Released:	1/2
BBLS:	Not reported
Cups:	Not reported
CUFT:	Not reported
Gallons:	Not reported
Grams:	Not reported
Pounds:	Not reported
Liters:	Not reported
Ounces:	Not reported
Pints:	Not reported
Quarts:	Not reported
Sheen:	Not reported
Tons:	Not reported
Unknown:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	Container fell off the pallet causing this release within the trailer which was contained in the trailer

---

AN322 **ERNS** **92280900**
South **2051 SLOVER AVE** **N/A**
1/4-1/2 **COLTEN, CA 92412**
0.415 mi.
2192 ft. **Site 2 of 2 in cluster AN**

Relative:
Lower

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

Actual:
1060 ft.

AO323 **GATX RAIL** **RCRA-TSDF** **1015732747**
SSE **20878 SLOVER AVENUE** **CERC-NFRAP** **CAD055698815**
1/4-1/2 **COLTON, CA 92324** **CORRACTS**
0.417 mi. **RCRA-LQG**
2204 ft. **Site 1 of 13 in cluster AO**

Relative:
Lower

Actual:
1004 ft.

RCRA-TSDF:

Date form received by agency:	02/17/2012
Facility name:	GATX RAIL
Facility address:	20878 SLOVER AVENUE COLTON, CA 92324
EPA ID:	CAD055698815
Mailing address:	SLOVER AVENUE COLTON, CA 92324
Contact:	MIKE JONES
Contact address:	SLOVER STREET COLTON, CA 92324
Contact country:	Not reported
Contact telephone:	(909) 777-5123
Contact email:	MIKE.JONES@GATX.COM
EPA Region:	09
Land type:	Private
Classification:	TSDF
Description:	Handler is engaged in the treatment, storage or disposal of hazardous waste
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	GATX RAIL
Owner/operator address:	SLOVER AVENUE COLTON, CA 92324
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	01/01/1948
Owner/Op end date:	Not reported

Owner/operator name:	GATX CORPORATION
Owner/operator address:	WEST ADAMS STREET CHICAGO, IL 92324
Owner/operator country:	Not reported
Owner/operator telephone:	(312) 499-7765
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	01/01/1948
Owner/Op end date:	Not reported

GATX RAIL (Continued) **1015732747**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/25/2010
Facility name: GATX RAIL
Classification: Large Quantity Generator

Date form received by agency: 02/07/2008
Facility name: GATX RAIL
Classification: Large Quantity Generator

Date form received by agency: 02/10/2006
Facility name: GATX RAIL
Classification: Large Quantity Generator

Date form received by agency: 01/30/2004
Facility name: GATX RAIL
Classification: Large Quantity Generator

Date form received by agency: 02/01/2002
Facility name: GATX RAIL
Classification: Large Quantity Generator

Date form received by agency: 10/12/2000
Facility name: GATX RAIL
Classification: Large Quantity Generator

Date form received by agency: 04/05/2000
Facility name: GATX RAIL
Classification: Large Quantity Generator

Date form received by agency: 04/15/1999
Facility name: GATX RAIL
Site name: GENERAL AMERICAN TRANSPORT CO.
Classification: Large Quantity Generator

Date form received by agency: 09/01/1996
Facility name: GATX RAIL
Classification: Large Quantity Generator

Date form received by agency: 02/26/1996

GATX RAIL (Continued) **1015732747**

Facility name: GATX RAIL
Site name: GENERAL AMERICAN TRANSPORTATION
Classification: Large Quantity Generator

Date form received by agency: 03/31/1994
Facility name: GATX RAIL
Site name: GENERAL AMERICAN TRANSPORTATION
Classification: Large Quantity Generator

Date form received by agency: 02/27/1992
Facility name: GATX RAIL
Site name: GENERAL AMERICAN TRANSPORTATIO
Classification: Large Quantity Generator

Date form received by agency: 04/12/1990
Facility name: GATX RAIL
Site name: GENERAL AMERICAN TRANSPORTATION CORP.
Classification: Large Quantity Generator

Date form received by agency: 08/18/1980
Facility name: GATX RAIL
Classification: Large Quantity Generator

Date form received by agency: 08/18/1980
Facility name: GATX RAIL
Classification: Large Quantity Generator

Hazardous Waste Summary:
Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D007
Waste name: CHROMIUM

Waste code: D035
Waste name: METHYL ETHYL KETONE

Waste code: F003
Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste code: F005
Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL

GATX RAIL (Continued) **1015732747**

KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Biennial Reports:

Last Biennial Reporting Year: 2013

Annual Waste Handled:

Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.
Amount (Lbs): 21700.6

Waste code: D007
Waste name: CHROMIUM
Amount (Lbs): 100

Waste code: D035
Waste name: METHYL ETHYL KETONE
Amount (Lbs): 16600.6

Waste code: F003
Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Amount (Lbs): 16600.6

Waste code: F005
Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Amount (Lbs): 16600.6

Corrective Action Summary:

Event date: 06/21/1989
Event: CA049PA

GATX RAIL (Continued) **1015732747**

Event date: 06/21/1989
Event: CA Prioritization, Facility or area was assigned a low corrective action priority.

Event date: 06/21/1989
Event: CA029ST

Event date: 06/21/1989
Event: RFA Completed, Assessment was a PA-Plus.

Event date: 06/21/1989
Event: CA074LO

Event date: 12/15/1991
Event: RFI Imposition

Event date: 07/01/1992
Event: RFI Workplan Approved

Event date: 09/24/1992
Event: RFI Workplan Approved

Event date: 12/15/1993
Event: RFI Approved

Event date: 12/15/1993
Event: Corrective Action Process Terminated, No Further Action

Event date: 08/06/2010
Event: Current Human Exposures under Control, Yes, Current Human Exposures Under Control has been verified. Based on a review of information contained in the EI determination, current human exposures are expected to be under control at the facility under current and reasonably expected conditions. This determination will be re-evaluated when the Agency/State becomes aware of significant changes at the facility.

Event date: 08/06/2010
Event: Current Human Exposures under Control, Yes, Current Human Exposures Under Control has been verified. Based on a review of information contained in the EI determination, current human exposures are expected to be under control at the facility under current and reasonably expected conditions. This determination will be re-evaluated when the Agency/State becomes aware of significant changes at the facility.

Event date: 12/29/2010
Event: CA550RC

Event date: 12/29/2010
Event: Igration of Contaminated Groundwater under Control, Yes, Migration of Contaminated Groundwater Under Control has been verified. Based on a review of information contained in the EI determination, it has been determined that migration of contaminated groundwater is under control at the facility. Specifically, this determination indicates that the migration of contaminated groundwater is under control, and that monitoring will be conducted to confirm that contaminated groundwater

GATX RAIL (Continued) **1015732747**

remains within the existing area of contaminated groundwater. This determination will be re-evaluated when the Agency becomes aware of significant changes at the facility.

Event date: 12/29/2010
Event: CA550RC

Event date: 12/29/2010
Event: Igration of Contaminated Groundwater under Control, Yes, Migration of Contaminated Groundwater Under Control has been verified. Based on a review of information contained in the EI determination, it has been determined that migration of contaminated groundwater is under control at the facility. Specifically, this determination indicates that the migration of contaminated groundwater is under control, and that monitoring will be conducted to confirm that contaminated groundwater remains within the existing area of contaminated groundwater. This determination will be re-evaluated when the Agency becomes aware of significant changes at the facility.

Event date: Not reported
Event: CA048ST

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 06/25/2008
Date achieved compliance: 09/30/2008
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/25/2008
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 03/29/2005
Date achieved compliance: 05/16/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/29/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 03/29/2005
Date achieved compliance: 05/16/2005
Violation lead agency: State
Enforcement action: INITIAL 3008(A) COMPLIANCE

GATX RAIL (Continued) **1015732747**

Enforcement action date: 10/28/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 14100
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Manifest
Date violation determined: 03/29/2005
Date achieved compliance: 03/30/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/29/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 03/29/2005
Date achieved compliance: 05/16/2005
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 02/17/2006
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: 10000
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 03/29/2005
Date achieved compliance: 05/16/2005
Violation lead agency: State
Enforcement action: LETTER OF INTENT TO INITIATE ENFORCEMENT ACTION
Enforcement action date: 06/23/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Contingency Plan and Emergency Procedures
Date violation determined: 08/19/2003
Date achieved compliance: 09/18/2003
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 08/19/2003

GATX RAIL (Continued) **1015732747**

Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General Facility Standards
Date violation determined: 08/19/2003
Date achieved compliance: 09/18/2003
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 08/19/2003
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Contingency Plan and Emergency Procedures
Date violation determined: 09/04/2002
Date achieved compliance: 01/15/2003
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/04/2002
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General Facility Standards
Date violation determined: 09/04/2002
Date achieved compliance: 01/15/2003
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/04/2002
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General Facility Standards
Date violation determined: 11/14/2000
Date achieved compliance: 12/19/2000
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 11/15/2000
Enf. disposition status: Not reported

GATX RAIL (Continued) **1015732747**

Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Contingency Plan and Emergency Procedures
Date violation determined: 11/14/2000
Date achieved compliance: 12/19/2000
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 11/15/2000
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Financial Requirements
Date violation determined: 11/14/2000
Date achieved compliance: 12/19/2000
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 11/15/2000
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Container Use and Management
Date violation determined: 11/14/2000
Date achieved compliance: 12/19/2000
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 11/15/2000
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Financial Requirements
Date violation determined: 10/31/2000
Date achieved compliance: 12/19/2000
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 11/15/2000
Enf. disposition status: Not reported
Enf. disp. status date: Not reported

GATX RAIL (Continued) **1015732747**

Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 264.170-177.I
Area of violation: TSD - General
Date violation determined: 04/09/1996
Date achieved compliance: 04/09/1996
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/09/1996
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 264.190-201.J
Area of violation: TSD - General
Date violation determined: 04/09/1996
Date achieved compliance: 04/09/1996
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/09/1996
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: F - 264.400-406.Q
Area of violation: TSD IS-Chemical, Physical, AND Treatment
Date violation determined: 04/09/1996
Date achieved compliance: 04/09/1996
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/09/1996
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: F - 264.30-37.C
Area of violation: TSD - General
Date violation determined: 04/09/1996
Date achieved compliance: 04/09/1996
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/09/1996
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State

GATX RAIL (Continued) **1015732747**

Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 264.110-120.G
Area of violation: TSD - Closure/Post-Closure
Date violation determined: 04/09/1996
Date achieved compliance: 04/09/1996
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/09/1996
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 264.10-18.B
Area of violation: TSD - General
Date violation determined: 10/07/1994
Date achieved compliance: 05/05/1995
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 05/01/1995
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: 1000
Paid penalty amount: 1000

Regulation violated: FR - 264.190-201.J
Area of violation: TSD - General
Date violation determined: 10/07/1994
Date achieved compliance: 05/05/1995
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 10/07/1994
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 264.190-201.J
Area of violation: TSD - General
Date violation determined: 10/07/1994
Date achieved compliance: 05/05/1995
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 05/01/1995
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported

GATX RAIL (Continued) **1015732747**

Final penalty amount: 1000
Paid penalty amount: 1000

Regulation violated: FR - 270
Area of violation: TSD - General
Date violation determined: 10/07/1994
Date achieved compliance: 05/05/1995
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 05/01/1995
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: 1000
Paid penalty amount: 1000

Regulation violated: FR - 264.10-18.B
Area of violation: TSD - General
Date violation determined: 10/07/1994
Date achieved compliance: 05/05/1995
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 10/07/1994
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 270
Area of violation: TSD - General
Date violation determined: 10/07/1994
Date achieved compliance: 05/05/1995
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 10/07/1994
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: F - 270
Area of violation: TSD - General
Date violation determined: 02/24/1992
Date achieved compliance: 03/13/1992
Violation lead agency: State
Enforcement action: INITIAL 3008(A) COMPLIANCE
Enforcement action date: 02/24/1992
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 900
Final penalty amount: 900

GATX RAIL (Continued) **1015732747**

Paid penalty amount: Not reported

Regulation violated: F - 264.140-150.H
Area of violation: TSD - Financial Requirements
Date violation determined: 11/21/1991
Date achieved compliance: 04/07/1994
Violation lead agency: EPA
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 270
Area of violation: TSD - General
Date violation determined: 06/15/1989
Date achieved compliance: 08/08/1989
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/12/1989
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: F - 270
Area of violation: TSD - General
Date violation determined: 11/23/1987
Date achieved compliance: 10/24/1989
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 12/30/1987
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: F - 270
Area of violation: TSD - General
Date violation determined: 11/23/1987
Date achieved compliance: 10/24/1989
Violation lead agency: State
Enforcement action: INITIAL 3008(A) COMPLIANCE
Enforcement action date: 01/30/1989
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

GATX RAIL (Continued) **1015732747**

Evaluation Action Summary:

Evaluation date:	06/25/2008
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Generators - General
Date achieved compliance:	09/30/2008
Evaluation lead agency:	State
Evaluation date:	01/18/2007
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	05/11/2006
Evaluation:	FINANCIAL RECORD REVIEW
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	03/15/2006
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	05/16/2005
Evaluation:	NOT A SIGNIFICANT NON-COMPLIER
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	03/29/2005
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Generators - General
Date achieved compliance:	05/16/2005
Evaluation lead agency:	State
Evaluation date:	03/29/2005
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Generators - Manifest
Date achieved compliance:	03/30/2005
Evaluation lead agency:	State
Evaluation date:	03/29/2005
Evaluation:	SIGNIFICANT NON-COMPLIER
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	03/23/2005
Evaluation:	FINANCIAL RECORD REVIEW
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State
Evaluation date:	08/19/2003
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE

GATX RAIL (Continued) **1015732747**

Area of violation: TSD - General Facility Standards
Date achieved compliance: 09/18/2003
Evaluation lead agency: State

Evaluation date: 08/19/2003
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - Contingency Plan and Emergency Procedures
Date achieved compliance: 09/18/2003
Evaluation lead agency: State

Evaluation date: 08/05/2003
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 09/04/2002
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - Contingency Plan and Emergency Procedures
Date achieved compliance: 01/15/2003
Evaluation lead agency: State

Evaluation date: 09/04/2002
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General Facility Standards
Date achieved compliance: 01/15/2003
Evaluation lead agency: State

Evaluation date: 07/15/2002
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 11/14/2000
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - Financial Requirements
Date achieved compliance: 12/19/2000
Evaluation lead agency: State

Evaluation date: 11/14/2000
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General Facility Standards
Date achieved compliance: 12/19/2000
Evaluation lead agency: State

Evaluation date: 11/14/2000
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - Container Use and Management
Date achieved compliance: 12/19/2000
Evaluation lead agency: State

Evaluation date: 11/14/2000
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - Contingency Plan and Emergency Procedures
Date achieved compliance: 12/19/2000
Evaluation lead agency: State

GATX RAIL (Continued) **1015732747**

Evaluation date: 10/31/2000
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: TSD - Financial Requirements
Date achieved compliance: 12/19/2000
Evaluation lead agency: State

Evaluation date: 06/12/1996
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 04/03/1996
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD IS-Chemical, Physical, AND Treatment
Date achieved compliance: 04/09/1996
Evaluation lead agency: State

Evaluation date: 04/03/1996
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - Closure/Post-Closure
Date achieved compliance: 04/09/1996
Evaluation lead agency: State

Evaluation date: 04/03/1996
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General
Date achieved compliance: 04/09/1996
Evaluation lead agency: State

Evaluation date: 08/23/1994
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General
Date achieved compliance: 05/05/1995
Evaluation lead agency: State

Evaluation date: 12/10/1991
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General
Date achieved compliance: 03/13/1992
Evaluation lead agency: State

Evaluation date: 11/21/1991
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: TSD - Financial Requirements
Date achieved compliance: 04/07/1994
Evaluation lead agency: EPA Contractor/Grantee

Evaluation date: 06/15/1989
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General
Date achieved compliance: 08/08/1989
Evaluation lead agency: State

Evaluation date: 06/12/1989
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: Not reported

GATX RAIL (Continued) **1015732747**

Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 06/30/1988
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 11/23/1987
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General
Date achieved compliance: 10/24/1989
Evaluation lead agency: State

CERC-NFRAP:
Site ID: 0903282
Federal Facility: Not a Federal Facility
NPL Status: Not on the NPL
Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information

CERCLIS-NFRAP Site Contact Details:
Contact Sequence ID: 13053084.00000
Person ID: 9271184.00000

Contact Sequence ID: 13288191.00000
Person ID: 13003854.00000

Contact Sequence ID: 13293786.00000
Person ID: 13003858.00000

Contact Sequence ID: 13299644.00000
Person ID: 13004003.00000

CERCLIS-NFRAP Assessment History:
Action: DISCOVERY
Date Started: / /
Date Completed: 07/12/89
Priority Level: Not reported

Action: ARCHIVE SITE
Date Started: / /
Date Completed: 09/21/90
Priority Level: Not reported

Action: PRELIMINARY ASSESSMENT
Date Started: / /
Date Completed: 09/21/90
Priority Level: NFRAP-Site does not qualify for the NPL based on existing information

CORRACTS:

EPA ID: CAD055698815
EPA Region: 09
Area Name: ENTIRE FACILITY
Actual Date: 19890621

GATX RAIL (Continued) **1015732747**

Action: CA075LO - CA Prioritization, Facility or area was assigned a low corrective action priority
NAICS Code(s): 48821
Support Activities for Rail Transportation
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: CAD055698815
EPA Region: 09
Area Name: ENTIRE FACILITY
Actual Date: 19920701
Action: CA150 - RFI Workplan Approved
NAICS Code(s): 48821
Support Activities for Rail Transportation
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: CAD055698815
EPA Region: 09
Area Name: ENTIRE FACILITY
Actual Date: 20100806
Action: CA725YE - Current Human Exposures Under Control, Yes, Current Human Exposures Under Control has been verified
NAICS Code(s): 48821
Support Activities for Rail Transportation
Original schedule date: 20100806
Schedule end date: Not reported

EPA ID: CAD055698815
EPA Region: 09
Area Name: ENTIRE FACILITY
Actual Date: 19920924
Action: CA150 - RFI Workplan Approved
NAICS Code(s): 48821
Support Activities for Rail Transportation
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: CAD055698815
EPA Region: 09
Area Name: ENTIRE FACILITY
Actual Date: 19931215
Action: CA999NF - Corrective Action Process Terminated, No Further Action
NAICS Code(s): 48821
Support Activities for Rail Transportation
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: CAD055698815
EPA Region: 09
Area Name: ENTIRE FACILITY
Actual Date: 19931215
Action: CA200 - RFI Approved
NAICS Code(s): 48821
Support Activities for Rail Transportation
Original schedule date: Not reported
Schedule end date: Not reported

GATX RAIL (Continued) **1015732747**

EPA ID: CAD055698815
EPA Region: 09
Area Name: ENTIRE FACILITY
Actual Date: 20101229
Action: CA750YE - Migration of Contaminated Groundwater under Control, Yes, Migration of Contaminated Groundwater Under Control has been verified
NAICS Code(s): 48821
Support Activities for Rail Transportation
Original schedule date: 20101229
Schedule end date: Not reported

EPA ID: CAD055698815
EPA Region: 09
Area Name: ENTIRE FACILITY
Actual Date: 20101229
Action: CA550RC
NAICS Code(s): 48821
Support Activities for Rail Transportation
Original schedule date: 20101229
Schedule end date: Not reported

AO324 **CITY OF COLTON** **HAZNET** **S112958594**
SSE **20878 SLOVER ST** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.417 mi.
2204 ft. **Site 2 of 13 in cluster AO**

Relative:
Lower

Actual:
1004 ft.

HAZNET:
Year: 2007
Gepaid: CAC002612014
Contact: DANNY PAGDILAO
Telephone: 9093706107
Mailing Name: Not reported
Mailing Address: 650 N LA CADENA DR
Mailing City,St,Zip: COLTON, CA 923242823
Gen County: Not reported
TSD EPA ID: CAD982444481
TSD County: Not reported
Waste Category: Unspecified oil-containing waste
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 1.12
Facility County: San Bernardino

Year: 2007
Gepaid: CAC002612014
Contact: DANNY PAGDILAO
Telephone: 9093706107
Mailing Name: Not reported
Mailing Address: 650 N LA CADENA DR
Mailing City,St,Zip: COLTON, CA 923242823
Gen County: Not reported
TSD EPA ID: CAD028409019
TSD County: Not reported
Waste Category: Unspecified solvent mixture
Disposal Method: Fuel Blending Prior To Energy Recovery At Another Site
Tons: 0.46
Facility County: San Bernardino

AO325 **GATX RAIL CORPORATION** **AST** **S104766487**
SSE **20878 SLOVER AVE** **San Bern. Co. Permit** **N/A**
1/4-1/2 **COLTON, CA 92324** **EMI**
0.417 mi.
2204 ft. **Site 3 of 13 in cluster AO**

Relative:
Lower

Actual:
1004 ft.

AST:
Owner: GATX RAIL CORPORATION
Total Gallons: 67,275
Certified Unified Program Agencies: San Bernardino

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0003431
Owner: GATX RAIL CORPORATION
Permit Number: PT0012460
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: INACTIVE
Expiration Date: 09/30/2009

Region: SAN BERNARDINO
Facility ID: FA0003431
Owner: GATX RAIL CORPORATION
Permit Number: PT0012461
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: INACTIVE
Expiration Date: 09/30/2009

Region: SAN BERNARDINO
Facility ID: FA0009719
Owner: GOODYEAR RUBBER CO/ GOODWEST
Permit Number: PT0016561
Permit Category: CONDITIONALLY EXEMPT SMALL QUANTITY GENERATOR
Facility Status: INACTIVE
Expiration Date: 05/31/2009

Region: SAN BERNARDINO
Facility ID: FA0003431
Owner: GATX RAIL CORPORATION
Permit Number: PT0012462
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: INACTIVE
Expiration Date: 09/30/2004

Region: SAN BERNARDINO
Facility ID: FA0003431
Owner: GATX RAIL CORPORATION
Permit Number: PT0001553
Permit Category: RISK MANAGEMENT PLAN - LEVEL III
Facility Status: ACTIVE
Expiration Date: 09/30/2013

Region: SAN BERNARDINO
Facility ID: FA0003431
Owner: GATX RAIL CORPORATION
Permit Number: PT0001557
Permit Category: HAZARDOUS WASTE GENERATOR - 51-100 EMPLOYEES
Facility Status: ACTIVE
Expiration Date: 09/30/2013

GATX RAIL CORPORATION (Continued) **S104766487**

Region: SAN BERNARDINO
Facility ID: FA0003431
Owner: GATX RAIL CORPORATION
Permit Number: PT0018708
Permit Category: RISK MANAGEMENT PLAN - LEVEL III
Facility Status: ACTIVE
Expiration Date: 09/30/2013

Region: SAN BERNARDINO
Facility ID: FA0003431
Owner: GATX RAIL CORPORATION
Permit Number: PT0018709
Permit Category: RISK MANAGEMENT PLAN - LEVEL III
Facility Status: ACTIVE
Expiration Date: 09/30/2013

Region: SAN BERNARDINO
Facility ID: FA0003431
Owner: GATX RAIL CORPORATION
Permit Number: PT0018710
Permit Category: RISK MANAGEMENT PLAN - LEVEL III
Facility Status: ACTIVE
Expiration Date: 09/30/2013

Region: SAN BERNARDINO
Facility ID: FA0003431
Owner: GATX RAIL CORPORATION
Permit Number: PT0001556
Permit Category: HAZMAT HANDLER 51-100 EMPLOYEES (W/GEN PRMT)
Facility Status: ACTIVE
Expiration Date: 09/30/2013

Region: SAN BERNARDINO
Facility ID: FA0003431
Owner: GATX RAIL CORPORATION
Permit Number: PT0001560
Permit Category: APSA 10,001-100,000 GAL FAC CAPACITY
Facility Status: ACTIVE
Expiration Date: 09/30/2013

Region: SAN BERNARDINO
Facility ID: FA0003431
Owner: GATX RAIL CORPORATION
Permit Number: PT0020663
Permit Category: HAZARDOUS WASTE GENERATOR RCRA LQG
Facility Status: ACTIVE
Expiration Date: 09/30/2013

Region: SAN BERNARDINO
Facility ID: FA0003431
Owner: GATX RAIL CORPORATION
Permit Number: PT0001558
Permit Category: CALARP FACILITY PERMIT
Facility Status: ACTIVE
Expiration Date: 09/30/2013

Region: SAN BERNARDINO

GATX RAIL CORPORATION (Continued) **S104766487**

Facility ID: FA0003431
Owner: GATX RAIL CORPORATION
Permit Number: PT0001566
Permit Category: EPCRA FACILITY
Facility Status: ACTIVE
Expiration Date: 09/30/2013

EMI:

Year:	1996
County Code:	36
Air Basin:	SC
Facility ID:	12332
Air District Name:	SC
SIC Code:	3714
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	27
Reactive Organic Gases Tons/Yr:	22
Carbon Monoxide Emissions Tons/Yr:	14
NOX - Oxides of Nitrogen Tons/Yr:	5
SOX - Oxides of Sulphur Tons/Yr:	1
Particulate Matter Tons/Yr:	2
Part. Matter 10 Micrometers & Smllr Tons/Yr:	1

Year:	1997
County Code:	36
Air Basin:	SC
Facility ID:	12332
Air District Name:	SC
SIC Code:	3714
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	25
Reactive Organic Gases Tons/Yr:	25
Carbon Monoxide Emissions Tons/Yr:	7
NOX - Oxides of Nitrogen Tons/Yr:	4
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	1
Part. Matter 10 Micrometers & Smllr Tons/Yr:	1

Year:	1998
County Code:	36
Air Basin:	SC
Facility ID:	12332
Air District Name:	SC
SIC Code:	3714
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	25
Reactive Organic Gases Tons/Yr:	25
Carbon Monoxide Emissions Tons/Yr:	7
NOX - Oxides of Nitrogen Tons/Yr:	4
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	1

GATX RAIL CORPORATION (Continued) **S104766487**

Part. Matter 10 Micrometers & Smllr Tons/Yr:	1
Year:	1999
County Code:	36
Air Basin:	SC
Facility ID:	12332
Air District Name:	SC
SIC Code:	3714
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	25
Reactive Organic Gases Tons/Yr:	25
Carbon Monoxide Emissions Tons/Yr:	7
NOX - Oxides of Nitrogen Tons/Yr:	4
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	1
Part. Matter 10 Micrometers & Smllr Tons/Yr:	1
Year:	2000
County Code:	36
Air Basin:	SC
Facility ID:	12332
Air District Name:	SC
SIC Code:	3714
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	25
Reactive Organic Gases Tons/Yr:	25
Carbon Monoxide Emissions Tons/Yr:	7
NOX - Oxides of Nitrogen Tons/Yr:	4
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	1
Part. Matter 10 Micrometers & Smllr Tons/Yr:	1
Year:	2001
County Code:	36
Air Basin:	SC
Facility ID:	12332
Air District Name:	SC
SIC Code:	3714
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	6
Reactive Organic Gases Tons/Yr:	6
Carbon Monoxide Emissions Tons/Yr:	2
NOX - Oxides of Nitrogen Tons/Yr:	1
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	1
Part. Matter 10 Micrometers & Smllr Tons/Yr:	1
Year:	2002
County Code:	36
Air Basin:	SC
Facility ID:	12332

GATX RAIL CORPORATION (Continued) **S104766487**

Air District Name:	SC
SIC Code:	3743
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	9
Reactive Organic Gases Tons/Yr:	8
Carbon Monoxide Emissions Tons/Yr:	6
NOX - Oxides of Nitrogen Tons/Yr:	3
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	1
Part. Matter 10 Micrometers & Smllr Tons/Yr:	1

Year:	2003
County Code:	36
Air Basin:	SC
Facility ID:	12332
Air District Name:	SC
SIC Code:	3743
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	9
Reactive Organic Gases Tons/Yr:	8
Carbon Monoxide Emissions Tons/Yr:	6
NOX - Oxides of Nitrogen Tons/Yr:	3
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	1
Part. Matter 10 Micrometers & Smllr Tons/Yr:	1

Year:	2004
County Code:	36
Air Basin:	SC
Facility ID:	12332
Air District Name:	SC
SIC Code:	3743
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	8.578442
Reactive Organic Gases Tons/Yr:	7.94
Carbon Monoxide Emissions Tons/Yr:	5.7675
NOX - Oxides of Nitrogen Tons/Yr:	2.9874
SOX - Oxides of Sulphur Tons/Yr:	0.0331244
Particulate Matter Tons/Yr:	1.42047
Part. Matter 10 Micrometers & Smllr Tons/Yr:	1.19

Year:	2005
County Code:	36
Air Basin:	SC
Facility ID:	12332
Air District Name:	SC
SIC Code:	3743
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	11.10066

GATX RAIL CORPORATION (Continued) **S104766487**

Reactive Organic Gases Tons/Yr:	10.602243786
Carbon Monoxide Emissions Tons/Yr:	10.42735
NOX - Oxides of Nitrogen Tons/Yr:	2.84125
SOX - Oxides of Sulphur Tons/Yr:	.048475
Particulate Matter Tons/Yr:	.9573
Part. Matter 10 Micrometers & Smllr Tons/Yr:	.91681768

Year:	2006
County Code:	36
Air Basin:	SC
Facility ID:	12332
Air District Name:	SC
SIC Code:	3743
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	6.265727492493193453
Reactive Organic Gases Tons/Yr:	6.024
Carbon Monoxide Emissions Tons/Yr:	5.835
NOX - Oxides of Nitrogen Tons/Yr:	3.805
SOX - Oxides of Sulphur Tons/Yr:	.25
Particulate Matter Tons/Yr:	.756
Part. Matter 10 Micrometers & Smllr Tons/Yr:	.71048

Year:	2007
County Code:	36
Air Basin:	SC
Facility ID:	12332
Air District Name:	SC
SIC Code:	3743
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	6.175369279801290847
Reactive Organic Gases Tons/Yr:	6.024
Carbon Monoxide Emissions Tons/Yr:	5.835
NOX - Oxides of Nitrogen Tons/Yr:	3.805
SOX - Oxides of Sulphur Tons/Yr:	.25
Particulate Matter Tons/Yr:	.756
Part. Matter 10 Micrometers & Smllr Tons/Yr:	.712832

Year:	2007
County Code:	36
Air Basin:	SC
Facility ID:	12332
Air District Name:	SC
SIC Code:	4789
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	6.243159396977274858
Reactive Organic Gases Tons/Yr:	6.0853076
Carbon Monoxide Emissions Tons/Yr:	6.5056
NOX - Oxides of Nitrogen Tons/Yr:	4.28
SOX - Oxides of Sulphur Tons/Yr:	.3391445
Particulate Matter Tons/Yr:	.7738735
Part. Matter 10 Micrometers & Smllr Tons/Yr:	.7309589

AO326 **GATX RAIL CORPORATION** **UST** **U003784558**
SSE **20878 SLOVER ST** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.417 mi.
2204 ft. **Site 4 of 13 in cluster AO**

Relative:
Lower

Actual:
1004 ft.

UST:
Facility ID: 85004255
Latitude: 34.06316
Longitude: -117.34987

AO327 **GATX - COLTON, CA TANK CAR FACILITY** **RMP** **1012125917**
SSE **20878 SLOVER AVENUE** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.417 mi.
2204 ft. **Site 5 of 13 in cluster AO**

Relative:
Lower

Actual:
1004 ft.

Risk Management Plan (RMP) Facility Details:

Facility ID:	1000004904
LEPC city:	San Bernardino County Fire Dpt
Facility decimal latitude:	34.065361
Facility decimal longitude:	-117.349833
Is facility in county box:	T
LatLong method:	I1
LatLong description:	CE
Home page web address:	www.gatx.com/rail/index.asp
Facility telephone:	3126216200
Facility email:	Not reported
Facility DUNS #:	0
Parent's name:	GATX Corporation
Partner's name:	General American Transportation Corporation
Parent's DUNS #:	20040630
Partner's DUNS #:	5161476
Operator's name:	GATX Corporation
Operator's telephone:	3126216200
Operator's address:	222 West Adams Street
Operators City,St,Zip:	Chicago, IL 60606
RMP implementation contact:	J. Jay Grove
RMP contact title:	Director Env., Health & Safety
Emergency contact:	Michael Grubbs
Emergency contact title:	Env., Health and Safety Manager
Emergency contact telephone:	9097775123
24 hour emergency telephone:	9099083440
Emergency contact ext/pin #:	Not reported
Number of full time employees:	60
EPA ID:	CAD 055 698 815
Facility ID provided by CEPPO:	100000049351
Is facility covered by OSHA PSM:	T
Is facility covered by EPCRA 302:	T
Is fac. covered by CAA Title V 112(2):	T
Clean air op. permit/State ID:	12332
Last safety insp. dat:	3/9/2009
Inspected by:	OSHA
Is it OSHA approved with star/merit ranking:	False
Will RMP involve predictive filing:	False
Submission type:	Resubmission
RMP description:	Not reported
Facility has no accident hist. recs:	False
Foreign owner's address:	Not reported
Foreign owner's zip:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Foreign owner's country:	Not reported
Claim # of employees as CBI:	False
Date RMP accepted by EPA:	6/18/2009
Date of error Report:	Not reported
Date RMP received:	6/18/2009
Does RMP contain graphics files:	False
Does RMP contain attachments:	False
Was certification letter received:	True
RMP submission method:	RMP*eSubmit
Does RMP contain CBI substantiation:	False
Does RMP contain electronic waiver:	False
Date RMP postmarked:	6/18/2009
Is RMP complete:	True
Date of de-registration:	Not reported
Date de-registration is effective:	Not reported
Aniversary date:	6/18/2014
Does RMP contain CBI data:	False
Does RMP contain unsanitized CBI version:	False
RMP version #:	1.0
FRS latitude:	34.06534
FRS longitude:	-117.3507
FRS Description:	FACILITY CENTROID
FRS Method:	INTERPOLATION-MAP

Accident History Details:

Accident History ID:	1000003614
X:	1000004904
Accident Date:	9/9/2008
Accident Time:	0130
NAICS code:	48821
Accident release duration:	00030
Chemical released:	Ammonia (anhydrous)
Flammable chemical name:	Not reported
Quantity of chemical released in pounds:	250
Percent weight of chemical released:	100
Release Event:	Gas
Release Source:	Storage Vessel
Wind speed:	Not reported
Wind speed units:	Not reported
Wind direction:	Not reported
Temperature:	Not reported
Stability class:	Not reported
Precipitation was present:	False
Weather was unknown:	True
Num. of on-site workers killed:	0
Num. of responders killed:	0
Num. of public deaths:	0
Num. of on-site workers injured:	3
Num. of responders injured:	0
Num. of public injured:	0
Property damage in dollars:	0
Num. of on-site deaths:	0
Num. of hospitalizations:	0
Num. of other medical treatments:	0
Num. of evacuated:	0
Num. of sheltered in place:	0
Off-site property damage in dollars:	0

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Environmental damage: Not reported
Initiating event: a
Contributing factor: Human error
Were offsite responders notified: Notified Only
Changes Made: Improved equipment, Revised maintenance, Revised training, Revised operating procedure, New process control, Reduced inventory
Record contains CBI data: False

Process Details:
Process ID: 1000005928
NA & Industry Classification Sys.code(s): 48821
NAICS code description: Support Activities for Rail Transportation
Optional facility description: Not reported
Program level: 3
Record contains CBI data: False

Process chemical(s):
Chemical name: Vinyl chloride [Ethene, chloro-]
Process chemical qty in 100s lbs: 200000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Ammonia (anhydrous)
Process chemical qty in 100s lbs: 170000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: 1,3-Butadiene
Process chemical qty in 100s lbs: 170000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Chemical name: Butane
Process chemical qty in 100s lbs: 160000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Butene
Process chemical qty in 100s lbs: 160000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	1-Butene
Process chemical qty in 100s lbs:	160000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	2-Butene
Process chemical qty in 100s lbs:	160000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	2-Butene-cis
Process chemical qty in 100s lbs:	160000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	2-Butene-trans [2-Butene, (E)]
Process chemical qty in 100s lbs:	160000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Chlorine
Process chemical qty in 100s lbs:	200000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Hydrochloric acid (conc 37% or greater)
Process chemical qty in 100s lbs:	100000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Process Flammables Alt. Releases:

Endpoint used:	Not reported
LFL value:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Flammables Worst Case:

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Isobutane [Propane, 2-methyl]
Process chemical qty in 100s lbs: 150000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Isopentane [Butane, 2-methyl-]
Process chemical qty in 100s lbs: 180000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Active mitigation: Not reported

Process Flammables Worst Case:

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Isoprene [1,3-Butadiene, 2-methyl-]
Process chemical qty in 100s lbs: 190000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	2-Methyl-1-butene
Process chemical qty in 100s lbs:	180000

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Toxics Worst Case:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	3-Methyl-1-butene
Process chemical qty in 100s lbs:	170000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: 2-Methylpropene [1-Propene, 2-methyl-]
Process chemical qty in 100s lbs: 170000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Nitric acid (conc 80% or greater)
Process chemical qty in 100s lbs:	180000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: 1,3-Pentadiene
Process chemical qty in 100s lbs: 190000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Pentane
Process chemical qty in 100s lbs: 180000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	1-Pentene
Process chemical qty in 100s lbs:	180000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: 2-Pentene, (E)-
Process chemical qty in 100s lbs: 180000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: 2-Pentene, (Z)-
Process chemical qty in 100s lbs: 180000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Propane
Process chemical qty in 100s lbs: 140000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Chemical name: Propylene [1-Propene]
Process chemical qty in 100s lbs: 140000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Dimethylamine [Methanamine, N-methyl-]
Process chemical qty in 100s lbs: 190000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Ethylamine [Ethanamine]
Process chemical qty in 100s lbs:	190000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Methylamine [Methanamine]
Process chemical qty in 100s lbs:	190000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Oleum (Fuming Sulfuric acid) [Sulfuric acid, mixture with sulfur trioxide]
Process chemical qty in 100s lbs:	60000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Trimethylamine [Methanamine, N,N-dimethyl-]
Process chemical qty in 100s lbs: 140000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Bromine
Process chemical qty in 100s lbs:	210000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Carbon disulfide
Process chemical qty in 100s lbs:	240000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Process Flammables Alt. Releases:

Endpoint used:	Not reported
LFL value:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Flammables Worst Case:

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Chloroform [Methane, trichloro-]
Process chemical qty in 100s lbs: 240000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Ethyl chloride [Ethane, chloro-]
Process chemical qty in 100s lbs: 190000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Active mitigation: Not reported

Process Flammables Worst Case:

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Ethylene oxide [Oxirane]
Process chemical qty in 100s lbs: 250000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Formaldehyde (solution)
Process chemical qty in 100s lbs:	80000

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Toxics Worst Case:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Hydrazine
Process chemical qty in 100s lbs:	210000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Hydrogen chloride (anhydrous) [Hydrochloric acid]
Process chemical qty in 100s lbs: 270000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Hydrogen fluoride/Hydrofluoric acid (conc 50% or greater) [Hydrofluoric acid]
Process chemical qty in 100s lbs:	190000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Hydrogen sulfide
Process chemical qty in 100s lbs: 240000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Methyl chloride [Methane, chloro-]
Process chemical qty in 100s lbs: 200000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Methyl mercaptan [Methanethiol]
Process chemical qty in 100s lbs:	210000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Methyltrichlorosilane [Silane, trichloromethyl-]
Process chemical qty in 100s lbs: 210000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Phosphorus trichloride [Phosphorous trichloride]
Process chemical qty in 100s lbs: 220000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Sulfur dioxide (anhydrous)
Process chemical qty in 100s lbs: 190000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Chemical name: Titanium tetrachloride [Titanium chloride (TiCl4) (T-4)-]
Process chemical qty in 100s lbs: 190000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Toluene diisocyanate (unspecified isomer) [Benzene, 1,3-diisocyanatomethyl-]
Process chemical qty in 100s lbs: 200000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Trichlorosilane [Silane, trichloro-]
Process chemical qty in 100s lbs: 220000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Vinylidene chloride [Ethene, 1,1-dichloro-]
Process chemical qty in 100s lbs:	230000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Acetaldehyde
Process chemical qty in 100s lbs:	220000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Ethyl ether [Ethane, 1,1'-oxybis-]
Process chemical qty in 100s lbs: 180000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Methyl ether [Methane, oxybis-]
Process chemical qty in 100s lbs:	180000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Propylene oxide [Oxirane, methyl-]
Process chemical qty in 100s lbs:	180000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Process Flammables Alt. Releases:

Endpoint used:	Not reported
LFL value:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Flammables Worst Case:

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Acrylonitrile [2-Propenenitrile]
Process chemical qty in 100s lbs: 180000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Epichlorohydrin [Oxirane, (chloromethyl)-]
Process chemical qty in 100s lbs: 230000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Active mitigation: Not reported

Process Flammables Worst Case:

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Ethylenediamine [1,2-Ethanediamine]
Process chemical qty in 100s lbs: 210000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Vinyl acetate monomer [Acetic acid ethenyl ester]
Process chemical qty in 100s lbs:	200000

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Toxics Worst Case:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: c
Analytical basic: EPA’s RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: c
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: 38

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Release mitigation involves closing a hand valve upstream of the chemical pump and the outlet valve

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Process Flammables Alt. Releases:

Endpoint used:	Not reported
LFL value:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Flammables Worst Case:

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: 90
Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Release mitigation involves closing a hand valve upstream of the chemical pump and the outlet valve

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Active mitigation: Not reported

Process Flammables Worst Case:

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: EPA's RMP*Comp(TM)
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Toxics Worst Case:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: 30
Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Release mitigation involves closing a hand valve upstream of the chemical pump and the outlet valve

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: 61.200001
Release rate in pounds per second: Not reported
Wind speed in meters/second: 1.5
Stability class: F
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA’s RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	c
Analytical basic:	EPA’s RMP*Comp(TM)
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	3
Stability class:	D
Topography:	a
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	b
Analytical basic:	EPA's RMP*Comp(TM)
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	3
Stability class:	D
Topography:	a
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: c
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Process Flammables Alt. Releases:

Endpoint used:	Not reported
LFL value:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Flammables Worst Case:

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: c
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: c
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Active mitigation: Not reported

Process Flammables Worst Case:

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: c
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
- Percent weight of chemical: Not reported
- Physical state: c
- Analytical basic: EPA's RMP*Comp(TM)
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: 3
- Stability class: D
- Topography: a
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Toxics Worst Case:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	b
Analytical basic:	EPA’s RMP*Comp(TM)

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	b
Analytical basic:	EPA’s RMP*Comp(TM)
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	3
Stability class:	D

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	c
Analytical basic:	EPA's RMP*Comp(TM)
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	3
Stability class:	D
Topography:	a
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	b
Analytical basic:	EPA’s RMP*Comp(TM)
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	3
Stability class:	D
Topography:	a
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	b
Analytical basic:	EPA's RMP*Comp(TM)
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	3
Stability class:	D
Topography:	a
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA’s RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA’s RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	b
Analytical basic:	EPA’s RMP*Comp(TM)
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	3
Stability class:	D
Topography:	a
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported

GATX - COLTON, CA TANK CAR FACILITY (Continued) **1012125917**

Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported

Emergency Response Details:

ER plan:	Not reported
ER plan most recent review date:	9/10/2008
ER plan most recent employee training date:	9/10/2008
Local agency coordinating ER plan:	San Bernardino County Fire Dept.
Telephone of the coordinating local agency:	9093874631
Federal regulation:	True
OSHA 1910 120:	True
SPCC:	True
RCRA:	True
OPA 90:	True
EPCRA:	True
Other Regulations:	Not reported

AO328 **CHMIRS** **S109037244**
SSE **20878 SLOVER** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.417 mi.
2204 ft. **Site 6 of 13 in cluster AO**

Relative:
Lower

Actual:
1004 ft.

CHMIRS:

OES Incident Number:	07-6769
OES notification:	11/03/2007
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported

(Continued) **S109037244**

Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	Not reported
Waterway:	Not reported
Spill Site:	Not reported
Cleanup By:	Release dissipated, no clean-up necessary
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	2007
Agency:	GATX, Colton
Incident Date:	11/2/2007 12:00:00 AM
Admin Agency:	San Bernardino County Health Department
Amount:	Not reported
Contained:	Yes
Site Type:	Rail Road
E Date:	Not reported
Substance:	Anhydrous Ammonia
Quantity Released:	Not reported
BBLS:	0
Cups:	0
CUFT:	0
Gallons:	5
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0

(Continued) **S109037244**

Unknown:	0
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	Improper operation of flare rack by flare rack operator resulted in the release. Release occurred in Colton service center rail yard repair facility.

AO329 **GATX RAIL - COLTON, CA TANK CAR FACILITY** **RMP** **1011825641**
SSE **20878 SLOVER AVENUE** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.417 mi.
2204 ft. **Site 7 of 13 in cluster AO**

Relative:
Lower

Actual:
1004 ft.

Risk Management Plan (RMP) Facility Details:

Facility ID:	33106
LEPC city:	San Bernardino County Fire Dpt
Facility decimal latitude:	34.065361
Facility decimal longitude:	-117.349833
Is facility in county box:	T
LatLong method:	I1
LatLong description:	CE
Home page web address:	www.gatx.com/rail/index.asp
Facility telephone:	3126216200
Facility email:	Not reported
Facility DUNS #:	0
Parent's name:	GATX Rail Corporation
Partner's name:	General American Transportation Corporation
Parent's DUNS #:	20040630
Partner's DUNS #:	5161476
Operator's name:	GATX Rail Corporation
Operator's telephone:	3126216200
Operator's address:	500 West Monroe Street
Operators City,St,Zip:	Chicago, IL 60661 3677
RMP implementation contact:	J. Jay Grove
RMP contact title:	Director Env., Health & Safety
Emergency contact:	Terry Ralston
Emergency contact title:	Env., Hlth, Sfty & Qual. Coord.
Emergency contact telephone:	9097775123
24 hour emergency telephone:	9098641774
Emergency contact ext/pin #:	Not reported
Number of full time employees:	55
EPA ID:	CAD 055 698 815
Facility ID provided by CEPPO:	100000049351
Is facility covered by OSHA PSM:	T
Is facility covered by EPCRA 302:	T
Is fac. covered by CAA Title V 112(2):	T
Clean air op. permit/State ID:	12332
Last safety insp. dat:	6/1/2002
Inspected by:	Fire Department
Is it OSHA approved with star/merit ranking:	False
Will RMP involve predictive filing:	False
Submission type:	Resubmission
RMP description:	Not reported
Facility has no accident hist. recs:	True
Foreign owner's address:	Not reported
Foreign owner's zip:	Not reported
Foreign owner's country:	Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Claim # of employees as CBI:	False
Date RMP accepted by EPA:	7/16/2004
Date of error Report:	Not reported
Date RMP received:	6/18/2004
Does RMP contain graphics files:	False
Does RMP contain attachments:	True
Was certification letter received:	True
RMP submission method:	RMP*Submit
Does RMP contain CBI substantiation:	False
Does RMP contain electronic waiver:	False
Date RMP postmarked:	6/14/2004
Is RMP complete:	True
Date of de-registration:	Not reported
Date de-registration is effective:	Not reported
Aniversary date:	6/14/2009
Does RMP contain CBI data:	False
Does RMP contain unsanitized CBI version:	False
RMP version #:	3.1
FRS latitude:	34.06534
FRS longitude:	-117.3507
FRS Description:	FACILITY CENTROID
FRS Method:	INTERPOLATION-MAP

Process Details:

Process ID:	47776
NA & Industry Classification Sys.code(s):	48821
NAICS code description:	Support Activities for Rail Transportation
Optional facility description:	Not reported
Program level:	3
Record contains CBI data:	False

Process chemical(s):

Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: c
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: c
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: 38
Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Release mitigation involves closing a hand valve upstream of the chemical pump and the outlet valve

Process Toxics Worst Case:
Percent weight of chemical: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported
- Most recent PHA date: Not reported
- Process Hazard Analysis: Not reported
- Expected PHA changes completion date: Not reported
- Major Hazard: Not reported
- Process Control: Not reported
- Mitigation Systems: Not reported
- Monitoring/Detection: Not reported
- Changes since the last process hazard analysis: Not reported
- Most recent review of op. procedures: Not reported
- Most recent training progs review/update: Not reported
- Training: Not reported
- Competency testing: Not reported
- Most recent maintenance review date: Not reported
- Most recent equipment inspection date: Not reported
- Equipment tested: Not reported
- Most recent changes by mgmt: Not reported
- Date of most recent review/update: Not reported
- Date of pre-start review: Not reported
- Most recent compliance audit date: Not reported
- Expected date of audit completion: Not reported
- Most recent incident investigation: Not reported
- Expected date of investigation changes: Not reported
- Date of participation plan review: Not reported
- Date of hot work permit review: Not reported
- Date of contractor safety review: Not reported
- Date of contractor safety eval. review: Not reported
- Record has CBI data: Not reported
- Safety review date: Not reported
- Federal Regulation: Not reported
- Federal regulation comment: Not reported
- Major Hazard: Not reported
- Process Control: Not reported
- Mitigation Systems: Not reported
- Monitoring/Detection: Not reported
- Changes since the last process hazard analysis: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
- Percent weight of chemical: 90
- Physical state: b
- Analytical basic: EPA's RMP*Comp(TM)
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: 3
- Stability class: D
- Topography: a
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Release mitigation involves closing a hand valve upstream of the chemical pump and the outlet valve

Process Toxics Worst Case:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: EPA's RMP*Comp(TM)
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: 30

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Release mitigation involves closing a hand valve upstream of the chemical pump and the outlet valve

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	b
Analytical basic:	EPA’s RMP*Comp(TM)
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	3
Stability class:	D
Topography:	a
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Physical state: b
Analytical basic: EPA's RMP*Comp
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: 61.200001
Release rate in pounds per second: Not reported
Wind speed in meters/second: 1.5
Stability class: F
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported
- Most recent PHA date: Not reported
- Process Hazard Analysis: Not reported
- Expected PHA changes completion date: Not reported
- Major Hazard: Not reported
- Process Control: Not reported
- Mitigation Systems: Not reported
- Monitoring/Detection: Not reported
- Changes since the last process hazard analysis: Not reported
- Most recent review of op. procedures: Not reported
- Most recent training progs review/update: Not reported
- Training: Not reported
- Competency testing: Not reported
- Most recent maintenance review date: Not reported
- Most recent equipment inspection date: Not reported
- Equipment tested: Not reported
- Most recent changes by mgmt: Not reported
- Date of most recent review/update: Not reported
- Date of pre-start review: Not reported
- Most recent compliance audit date: Not reported
- Expected date of audit completion: Not reported
- Most recent incident investigation: Not reported
- Expected date of investigation changes: Not reported
- Date of participation plan review: Not reported
- Date of hot work permit review: Not reported
- Date of contractor safety review: Not reported
- Date of contractor safety eval. review: Not reported
- Record has CBI data: Not reported
- Safety review date: Not reported
- Federal Regulation: Not reported
- Federal regulation comment: Not reported
- Major Hazard: Not reported
- Process Control: Not reported
- Mitigation Systems: Not reported
- Monitoring/Detection: Not reported
- Changes since the last process hazard analysis: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: c
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
- Percent weight of chemical: Not reported
- Physical state: c
- Analytical basic: EPA's RMP*Comp(TM)
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: 3
- Stability class: D
- Topography: a
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Toxics Worst Case:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	c
Analytical basic:	EPA's RMP*Comp(TM)

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: c
Analytical basic: EPA’s RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: c
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: c
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: c
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Process Flammables Alt. Releases:

Endpoint used:	Not reported
LFL value:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Flammables Worst Case:

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Active mitigation: Not reported

Process Flammables Worst Case:

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Vinyl chloride [Ethene, chloro-]
Process chemical qty in 100s lbs:	200000

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Toxics Worst Case:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Ammonia (anhydrous)
Process chemical qty in 100s lbs:	170000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: 1,3-Butadiene
Process chemical qty in 100s lbs: 170000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Butane
Process chemical qty in 100s lbs: 160000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Butene
Process chemical qty in 100s lbs: 160000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: 1-Butene
Process chemical qty in 100s lbs: 160000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	2-Butene
Process chemical qty in 100s lbs:	160000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: 2-Butene-cis
Process chemical qty in 100s lbs: 160000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: 2-Butene-trans [2-Butene, (E)]
Process chemical qty in 100s lbs: 160000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Chlorine
Process chemical qty in 100s lbs: 200000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Chemical name: Hydrochloric acid (conc 37% or greater)
Process chemical qty in 100s lbs: 100000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Isobutane [Propane, 2-methyl]
Process chemical qty in 100s lbs: 150000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Isopentane [Butane, 2-methyl-]
Process chemical qty in 100s lbs:	180000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Isoprene [1,3-Butadiene, 2-methyl-]
Process chemical qty in 100s lbs:	190000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: 2-Methyl-1-butene
Process chemical qty in 100s lbs: 180000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: 3-Methyl-1-butene
Process chemical qty in 100s lbs: 170000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: 2-Methylpropene [1-Propene, 2-methyl-]
Process chemical qty in 100s lbs: 170000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Nitric acid (conc 80% or greater)
Process chemical qty in 100s lbs: 180000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Process Flammables Alt. Releases:

Endpoint used:	Not reported
LFL value:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Flammables Worst Case:

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: 1,3-Pentadiene
Process chemical qty in 100s lbs: 190000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Pentane
Process chemical qty in 100s lbs: 180000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: 1-Pentene
Process chemical qty in 100s lbs: 180000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	2-Pentene, (E)-
Process chemical qty in 100s lbs:	180000

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Toxics Worst Case:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	2-Pentene, (Z)-
Process chemical qty in 100s lbs:	180000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Propane
Process chemical qty in 100s lbs:	140000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Propylene [1-Propene]
Process chemical qty in 100s lbs:	140000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Dimethylamine [Methanamine, N-methyl-]
Process chemical qty in 100s lbs: 190000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Ethylamine [Ethanamine]
Process chemical qty in 100s lbs: 190000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Methylamine [Methanamine]
Process chemical qty in 100s lbs: 190000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Oleum (Fuming Sulfuric acid) [Sulfuric acid, mixture with sulfur trioxide]
Process chemical qty in 100s lbs: 60000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Trimethylamine [Methanamine, N,N-dimethyl-]
Process chemical qty in 100s lbs: 140000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Allyl alcohol [2-Propen-1-ol]
Process chemical qty in 100s lbs: 180000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Chemical name: Bromine
Process chemical qty in 100s lbs: 210000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Carbon disulfide
Process chemical qty in 100s lbs: 240000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Chloroform [Methane, trichloro-]
Process chemical qty in 100s lbs: 240000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Ethyl chloride [Ethane, chloro-]
Process chemical qty in 100s lbs:	190000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Ethylene oxide [Oxirane]
Process chemical qty in 100s lbs: 250000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Formaldehyde (solution)
Process chemical qty in 100s lbs: 80000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Hydrazine
Process chemical qty in 100s lbs: 210000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Hydrogen chloride (anhydrous) [Hydrochloric acid]
Process chemical qty in 100s lbs: 270000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported
- Most recent PHA date: Not reported
- Process Hazard Analysis: Not reported
- Expected PHA changes completion date: Not reported
- Major Hazard: Not reported
- Process Control: Not reported
- Mitigation Systems: Not reported
- Monitoring/Detection: Not reported
- Changes since the last process hazard analysis: Not reported
- Most recent review of op. procedures: Not reported
- Most recent training progs review/update: Not reported
- Training: Not reported
- Competency testing: Not reported
- Most recent maintenance review date: Not reported
- Most recent equipment inspection date: Not reported
- Equipment tested: Not reported
- Most recent changes by mgmt: Not reported
- Date of most recent review/update: Not reported
- Date of pre-start review: Not reported
- Most recent compliance audit date: Not reported
- Expected date of audit completion: Not reported
- Most recent incident investigation: Not reported
- Expected date of investigation changes: Not reported
- Date of participation plan review: Not reported
- Date of hot work permit review: Not reported
- Date of contractor safety review: Not reported
- Date of contractor safety eval. review: Not reported
- Record has CBI data: Not reported
- Safety review date: Not reported
- Federal Regulation: Not reported
- Federal regulation comment: Not reported
- Major Hazard: Not reported
- Process Control: Not reported
- Mitigation Systems: Not reported
- Monitoring/Detection: Not reported
- Changes since the last process hazard analysis: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Hydrogen fluoride/Hydrofluoric acid (conc 50% or greater) [Hydrofluoric acid]
Process chemical qty in 100s lbs: 190000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Hydrogen sulfide
Process chemical qty in 100s lbs: 240000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Methyl chloride [Methane, chloro-]
Process chemical qty in 100s lbs: 200000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Methyl isocyanate [Methane, isocyanato-]
Process chemical qty in 100s lbs:	210000

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Toxics Worst Case:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Methyl mercaptan [Methanethiol]
Process chemical qty in 100s lbs:	210000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Methyltrichlorosilane [Silane, trichloromethyl-]
Process chemical qty in 100s lbs: 210000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Phosphorus trichloride [Phosphorous trichloride]
Process chemical qty in 100s lbs:	220000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Sulfur dioxide (anhydrous)
Process chemical qty in 100s lbs: 190000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Titanium tetrachloride [Titanium chloride (TiCl4) (T-4)-]
Process chemical qty in 100s lbs: 190000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Toluene diisocyanate (unspecified isomer) [Benzene, 1,3-diisocyanatomethyl-]
Process chemical qty in 100s lbs: 200000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Trichlorosilane [Silane, trichloro-]
Process chemical qty in 100s lbs: 220000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Vinylidene chloride [Ethene, 1,1-dichloro-]
Process chemical qty in 100s lbs: 230000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Acetaldehyde
Process chemical qty in 100s lbs: 220000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Chemical name: Ethyl ether [Ethane, 1,1'-oxybis-]
Process chemical qty in 100s lbs: 180000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Methyl ether [Methane, oxybis-]
Process chemical qty in 100s lbs: 180000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Propylene oxide [Oxirane, methyl-]
Process chemical qty in 100s lbs: 180000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Acrylonitrile [2-Propenenitrile]
Process chemical qty in 100s lbs:	180000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Epichlorohydrin [Oxirane, (chloromethyl)-]
Process chemical qty in 100s lbs: 230000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Ethylenediamine [1,2-Ethanediamine]
Process chemical qty in 100s lbs: 210000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Vinyl acetate monomer [Acetic acid ethenyl ester]
Process chemical qty in 100s lbs: 200000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported

GATX RAIL - COLTON, CA TANK CAR FACILITY (Continued) **1011825641**

Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported

Emergency Response Details:

ER plan:	Not reported
ER plan most recent review date:	4/1/2004
ER plan most recent employee training date:	5/26/2004
Local agency coordinating ER plan:	San Bernardino County Fire Dept.
Telephone of the coordinating local agency:	9093874631
Federal regulation:	True
OSHA 1910 120:	True
SPCC:	True
RCRA:	True
OPA 90:	True
EPCRA:	True
Other Regulations:	Not reported

AO330 **GATX CORPORATION** **FINDS** **1014674239**
SSE **20878 SLOVER** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.417 mi.
2204 ft. **Site 8 of 13 in cluster AO**

Relative:
Lower

Actual:
1004 ft.

FINDS:

Registry ID: 110041139149

Environmental Interest/Information System
CRITERIA AND HAZARDOUS AIR POLLUTANT INVENTORY

AO331 **GATX** **FINDS** **1000213813**
SSE **PEPPER AVE/SLOVER ST** **HIST UST** **N/A**
1/4-1/2 **COLTON, CA 92324** **US AIRS**
0.417 mi. **2020 COR ACTION**
2204 ft. **Site 9 of 13 in cluster AO**

Relative: Lower

Actual: 1004 ft.

FINDS:

Registry ID: 110000621248

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

California Hazardous Waste Tracking System - Datamart (HWTS-DATAMART) provides California with information on hazardous waste shipments for generators, transporters, and treatment, storage, and disposal facilities.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

US EPA Risk Management Plan (RMP) database stores the risk management plans reported by companies that handle, manufacture, use, or store certain flammable or toxic substances, as required under section

GATX (Continued) **1000213813**

112(r) of the Clean Air Act (CAA).

HIST UST:
Region: STATE
Facility ID: 00000002923
Facility Type: Other
Other Type: RAILCAR REPAIR SHOP
Total Tanks: 0004
Contact Name: ROBERT C. MERCER
Telephone: 7148253043
Owner Name: GENERAL AMERICAN TRANSPORTATIO
Owner Address: 120 SOUTH RIVERSIDE PLAZA
Owner City,St,Zip: CHICAGO, IL 60606

Tank Num: 001
Container Num: 65-89
Year Installed: Not reported
Tank Capacity: 00001000
Tank Used for: PRODUCT
Type of Fuel: DIESEL
Tank Construction: Not reported
Leak Detection: Visual, None

Tank Num: 002
Container Num: 65-187
Year Installed: Not reported
Tank Capacity: 00010000
Tank Used for: PRODUCT
Type of Fuel: DIESEL
Tank Construction: Not reported
Leak Detection: Visual, None

Tank Num: 003
Container Num: 65-19
Year Installed: Not reported
Tank Capacity: 00070684
Tank Used for: WASTE
Type of Fuel: WASTE OIL
Tank Construction: 10 inches
Leak Detection: Visual, None

Tank Num: 004
Container Num: 65-20
Year Installed: Not reported
Tank Capacity: 00058000
Tank Used for: WASTE
Type of Fuel: Not reported
Tank Construction: 12.5 inches
Leak Detection: Visual

AIRS (AFS):

Compliance and Violation Data Major Sources:
EPA plant ID: 110000621248
Plant name: GATX
Plant address: PEPPER AVE/SLOVER ST

GATX (Continued) **1000213813**

COLTON, CA 92324
County: SAN BERNARDINO
Region code: 09
Dunn & Bradst #: 055698815
Air quality cntrl region: 024
Sic code: 3714
Sic code desc: MOTOR VEHICLE PARTS AND ACCESSORIES
North Am. industrial classf: 336510
NAIC code description: Railroad Rolling Stock Manufacturing
Default compliance status: IN COMPLIANCE - INSPECTION
Default classification: ACTUAL OR POTENTIAL EMISSIONS ARE ABOVE THE APPLICABLE MAJOR SOURCE THRESHOLDS
Govt facility: ALL OTHER FACILITIES NOT OWNED OR OPERATED BY A FEDERAL, STATE, OR LOCAL GOVERNMENT
Current HPV: Not reported

Compliance and Enforcement Major Issues:
Air program: TITLE V PERMITS
National action type: MULTI MEDIA INSPECTION - LEVEL 2 OR GREATER
Date achieved: 000224
Penalty amount: 000000000

Air program: TITLE V PERMITS
National action type: STATE DAY 0
Date achieved: 030813
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE DAY 0
Date achieved: 030813
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: NXXXXX
Date achieved: 040122
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: NXXXXX
Date achieved: 040122
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: NXXXXX
Date achieved: 040318
Penalty amount: 000005000

Air program: TITLE V PERMITS
National action type: NXXXXX
Date achieved: 040318
Penalty amount: 000005000

Air program: SIP SOURCE
National action type: SV RESOLVED
Date achieved: 041005
Penalty amount: Not reported

GATX (Continued) **1000213813**

Air program: TITLE V PERMITS
National action type: SV RESOLVED
Date achieved: 041005
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: COMPLIANCE CERTIFICATION EPA REVIEW
Date achieved: 050106
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 060206
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 060206
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V COMPLIANCE CERT DUE/RECEIVED BY
Date achieved: 060214
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 060922
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 060922
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 060922
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 060922
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 070119
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 070119
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V COMPLIANCE CERT DUE/RECEIVED BY

GATX (Continued) **1000213813**

Date achieved: 070125
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 070807
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 070807
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 080220
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 080220
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V COMPLIANCE CERT DUE/RECEIVED BY
Date achieved: 080226
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 080707
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 080707
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 080828
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 080828
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: NXXXXX
Date achieved: 080917
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: NXXXXX
Date achieved: 080917
Penalty amount: Not reported

GATX (Continued) **1000213813**

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 080925
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 080925
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 090129
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 090129
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V COMPLIANCE CERT DUE/RECEIVED BY
Date achieved: 090219
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE DAY 0
Date achieved: 090226
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE DAY 0
Date achieved: 090226
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: NXXXXX
Date achieved: 090227
Penalty amount: 000002000

Air program: SIP SOURCE
National action type: NXXXXX
Date achieved: 090227
Penalty amount: 000002000

Air program: TITLE V PERMITS
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 090702
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 090702
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED PCE/ ON-SITE

GATX (Continued) **1000213813**

Date achieved: 090716
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 090716
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 090716
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 090716
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 100126
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 100126
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: SV RESOLVED
Date achieved: 100326
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: SV RESOLVED
Date achieved: 100326
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 100812
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 100812
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 100812
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 100812
Penalty amount: Not reported

GATX (Continued) **1000213813**

Air program: SIP SOURCE
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 100812
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 100812
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 110128
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 110128
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 110906
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 110906
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 110906
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 110906
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 110906
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 110906
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 120125
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY

GATX (Continued) **1000213813**

Date achieved: 120125
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 120706
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 120706
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 120706
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 120706
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 120706
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 120706
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: MULTI MEDIA INSPECTION - LEVEL 2 OR GREATER
Date achieved: 970213
Penalty amount: 000000000

Historical Compliance Minor Sources:
State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1001
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1001
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1002
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1003
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1003

GATX (Continued) **1000213813**

Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1004
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1101
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1101
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1102
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1103
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1103
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1104
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1201
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1201
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1202
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1203
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1203
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1204
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1002
Air prog code hist file: V

GATX (Continued) **1000213813**

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1004
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1102
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1104
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1202
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1204
Air prog code hist file: 0

Permit Information:
Compliance plant ID: 00010
Permit number: 12332
Permit category: V
Permit category desc: TITLE V PERMIT - PLANT SP

Permit Source:
Compliance plant ID: 00010
Plant name: GATX
Plant address: PEPPER AVE/SLOVER ST
COLTON, CA 92324

Event Information:
Compliance permit ID: 00010
Permit number: 12332
Event action type: IF
Event description: *PERMIT AUTHORITY ISSUES FINAL PERMIT
Event action #: 001
Event date: 20020710

2020 COR ACTION:
EPA ID: CAD055698815
Region: 9
Action: Not reported

AO332 **GATC - COLTON, CA TANK CAR FACILITY** **RMP** **1011825616**
SSE **20878 SLOVER AVENUE** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.417 mi.
2204 ft. **Site 10 of 13 in cluster AO**

Relative:
Lower

Actual:
1004 ft.

Risk Management Plan (RMP) Facility Details:

Facility ID:	10536
LEPC city:	San Bernardino County Fire Dpt
Facility decimal latitude:	34.065361
Facility decimal longitude:	-117.349833
Is facility in county box:	T
LatLong method:	I1
LatLong description:	CE
Home page web address:	Not reported
Facility telephone:	Not reported
Facility email:	Not reported
Facility DUNS #:	0
Parent's name:	General American Transportation Corporation
Partner's name:	GATX Corporation
Parent's DUNS #:	20040630
Partner's DUNS #:	5161476
Operator's name:	General American Transp. Corp.
Operator's telephone:	3126216200
Operator's address:	500 West Monroe Street
Operators City,St,Zip:	Chicago, IL 60661 3677
RMP implementation contact:	Danny Contreras
RMP contact title:	Plant Manager
Emergency contact:	Bill Newman
Emergency contact title:	Environmental and Cleaning Coord.
Emergency contact telephone:	9097775110
24 hour emergency telephone:	7148268782
Emergency contact ext/pin #:	Not reported
Number of full time employees:	75
EPA ID:	CAD 055 698 815
Facility ID provided by CEPPO:	100000049351
Is facility covered by OSHA PSM:	T
Is facility covered by EPCRA 302:	T
Is fac. covered by CAA Title V 112(2):	T
Clean air op. permit/State ID:	Not reported
Last safety insp. dat:	10/15/1995
Inspected by:	State occupational safety agency
Is it OSHA approved with star/merit ranking:	False
Will RMP involve predictive filing:	False
Submission type:	First Time
RMP description:	Not reported
Facility has no accident hist. recs:	True
Foreign owner's address:	Not reported
Foreign owner's zip:	Not reported
Foreign owner's country:	Not reported
Claim # of employees as CBI:	False
Date RMP accepted by EPA:	6/23/1999
Date of error Report:	6/23/1999
Date RMP received:	6/17/1999
Does RMP contain graphics files:	False
Does RMP contain attachments:	False
Was certification letter received:	True
RMP submission method:	RMP*Submit
Does RMP contain CBI substantiation:	False

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Does RMP contain electronic waiver: False
Date RMP postmarked: 6/16/1999
Is RMP complete: False
Date of de-registration: Not reported
Date de-registration is effective: Not reported
Aniversary date: 6/16/2004
Does RMP contain CBI data: False
Does RMP contain unsanitized CBI version: False
RMP version #: 1.1.5
FRS latitude: 34.06534
FRS longitude: -117.3507
FRS Description: FACILITY CENTROID
FRS Method: INTERPOLATION-MAP

Process Details:
Process ID: 13384
NA & Industry Classification Sys.code(s): 81131
NAICS code description: Commercial and Industrial Machinery and Equipment (except Automotive and Electronic) Repa
Optional facility description: Not reported
Program level: 3
Record contains CBI data: False

Process chemical(s):
Chemical name: Ammonia (anhydrous)
Process chemical qty in 100s lbs: 170000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	1,3-Butadiene
Process chemical qty in 100s lbs:	170000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported

Process Flammables Alt. Releases:

Endpoint used:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Butane
Process chemical qty in 100s lbs: 160000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Butene
Process chemical qty in 100s lbs: 160000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of most recent changes: Not reported
Chemical name: 1-Butene
Process chemical qty in 100s lbs: 160000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: 2-Butene
Process chemical qty in 100s lbs: 160000
Process flammable chemical name: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Toxic Alt. Releases:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Toxics Worst Case:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported
- Most recent PHA date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	2-Butene-cis
Process chemical qty in 100s lbs:	160000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: 2-Butene-trans [2-Butene, (E)]
Process chemical qty in 100s lbs: 160000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Chlorine
Process chemical qty in 100s lbs:	200000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Toxics Worst Case:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported
- Most recent PHA date: Not reported
- Process Hazard Analysis: Not reported
- Expected PHA changes completion date: Not reported
- Major Hazard: Not reported
- Process Control: Not reported
- Mitigation Systems: Not reported
- Monitoring/Detection: Not reported
- Changes since the last process hazard analysis: Not reported
- Most recent review of op. procedures: Not reported
- Most recent training progs review/update: Not reported
- Training: Not reported
- Competency testing: Not reported
- Most recent maintenance review date: Not reported
- Most recent equipment inspection date: Not reported
- Equipment tested: Not reported
- Most recent changes by mgmt: Not reported
- Date of most recent review/update: Not reported
- Date of pre-start review: Not reported
- Most recent compliance audit date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Hydrochloric acid (conc 37% or greater)
Process chemical qty in 100s lbs: 100000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Isobutane [Propane, 2-methyl]
Process chemical qty in 100s lbs:	150000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Isopentane [Butane, 2-methyl-]
Process chemical qty in 100s lbs:	180000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Passive mitigation: Not reported

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported
- Most recent PHA date: Not reported
- Process Hazard Analysis: Not reported
- Expected PHA changes completion date: Not reported
- Major Hazard: Not reported
- Process Control: Not reported
- Mitigation Systems: Not reported
- Monitoring/Detection: Not reported
- Changes since the last process hazard analysis: Not reported
- Most recent review of op. procedures: Not reported
- Most recent training progs review/update: Not reported
- Training: Not reported
- Competency testing: Not reported
- Most recent maintenance review date: Not reported
- Most recent equipment inspection date: Not reported
- Equipment tested: Not reported
- Most recent changes by mgmt: Not reported
- Date of most recent review/update: Not reported
- Date of pre-start review: Not reported
- Most recent compliance audit date: Not reported
- Expected date of audit completion: Not reported
- Most recent incident investigation: Not reported
- Expected date of investigation changes: Not reported
- Date of participation plan review: Not reported
- Date of hot work permit review: Not reported
- Date of contractor safety review: Not reported
- Date of contractor safety eval. review: Not reported
- Record has CBI data: Not reported
- Safety review date: Not reported
- Federal Regulation: Not reported
- Federal regulation comment: Not reported
- Major Hazard: Not reported
- Process Control: Not reported
- Mitigation Systems: Not reported
- Monitoring/Detection: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Isoprene [1,3-Butadiene, 2-methyl-]
Process chemical qty in 100s lbs: 190000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: 2-Methyl-1-butene
Process chemical qty in 100s lbs: 180000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: 3-Methyl-1-butene
Process chemical qty in 100s lbs: 170000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	2-Methylpropene [1-Propene, 2-methyl-]

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process chemical qty in 100s lbs: 170000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Nitric acid (conc 80% or greater)
Process chemical qty in 100s lbs:	180000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: 1,3-Pentadiene
Process chemical qty in 100s lbs: 190000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Pentane
Process chemical qty in 100s lbs:	180000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	1-Pentene
Process chemical qty in 100s lbs:	180000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	2-Pentene, (E)-
Process chemical qty in 100s lbs:	180000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	2-Pentene, (Z)-
Process chemical qty in 100s lbs:	180000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Propane
Process chemical qty in 100s lbs:	140000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported

Process Flammables Alt. Releases:

Endpoint used:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Propylene [1-Propene]
Process chemical qty in 100s lbs: 140000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Dimethylamine [Methanamine, N-methyl-]
Process chemical qty in 100s lbs: 190000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of most recent changes: Not reported
Chemical name: Ethylamine [Ethanamine]
Process chemical qty in 100s lbs: 190000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Methylamine [Methanamine]
Process chemical qty in 100s lbs: 190000
Process flammable chemical name: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Toxic Alt. Releases:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Toxics Worst Case:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported
- Most recent PHA date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Oleum (Fuming Sulfuric acid) [Sulfuric acid, mixture with sulfur trioxide]
Process chemical qty in 100s lbs:	60000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Trimethylamine [Methanamine, N,N-dimethyl-]
Process chemical qty in 100s lbs: 140000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Allyl alcohol [2-Propen-1-ol]
Process chemical qty in 100s lbs:	180000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Toxics Worst Case:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported
- Most recent PHA date: Not reported
- Process Hazard Analysis: Not reported
- Expected PHA changes completion date: Not reported
- Major Hazard: Not reported
- Process Control: Not reported
- Mitigation Systems: Not reported
- Monitoring/Detection: Not reported
- Changes since the last process hazard analysis: Not reported
- Most recent review of op. procedures: Not reported
- Most recent training progs review/update: Not reported
- Training: Not reported
- Competency testing: Not reported
- Most recent maintenance review date: Not reported
- Most recent equipment inspection date: Not reported
- Equipment tested: Not reported
- Most recent changes by mgmt: Not reported
- Date of most recent review/update: Not reported
- Date of pre-start review: Not reported
- Most recent compliance audit date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Bromine
Process chemical qty in 100s lbs:	210000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Carbon disulfide
Process chemical qty in 100s lbs:	240000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Chloroform [Methane, trichloro-]
Process chemical qty in 100s lbs:	240000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Passive mitigation: Not reported

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported
- Most recent PHA date: Not reported
- Process Hazard Analysis: Not reported
- Expected PHA changes completion date: Not reported
- Major Hazard: Not reported
- Process Control: Not reported
- Mitigation Systems: Not reported
- Monitoring/Detection: Not reported
- Changes since the last process hazard analysis: Not reported
- Most recent review of op. procedures: Not reported
- Most recent training progs review/update: Not reported
- Training: Not reported
- Competency testing: Not reported
- Most recent maintenance review date: Not reported
- Most recent equipment inspection date: Not reported
- Equipment tested: Not reported
- Most recent changes by mgmt: Not reported
- Date of most recent review/update: Not reported
- Date of pre-start review: Not reported
- Most recent compliance audit date: Not reported
- Expected date of audit completion: Not reported
- Most recent incident investigation: Not reported
- Expected date of investigation changes: Not reported
- Date of participation plan review: Not reported
- Date of hot work permit review: Not reported
- Date of contractor safety review: Not reported
- Date of contractor safety eval. review: Not reported
- Record has CBI data: Not reported
- Safety review date: Not reported
- Federal Regulation: Not reported
- Federal regulation comment: Not reported
- Major Hazard: Not reported
- Process Control: Not reported
- Mitigation Systems: Not reported
- Monitoring/Detection: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Ethyl chloride [Ethane, chloro-]
Process chemical qty in 100s lbs: 190000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Ethylene oxide [Oxirane]
Process chemical qty in 100s lbs: 250000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Formaldehyde (solution)
Process chemical qty in 100s lbs: 80000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Distance to endpoint in miles:	Not reported	
Residential population:	Not reported	
Public receptors:	Not reported	
Environmental receptors:	Not reported	
Passive mitigation:	Not reported	
Safety review date:		Not reported
Most recent PHA date:		Not reported
Process Hazard Analysis:		Not reported
Expected PHA changes completion date:		Not reported
Major Hazard:		Not reported
Process Control:		Not reported
Mitigation Systems:		Not reported
Monitoring/Detection:		Not reported
Changes since the last process hazard analysis:		Not reported
Most recent review of op. procedures:		Not reported
Most recent training progs review/update:		Not reported
Training:		Not reported
Competency testing:		Not reported
Most recent maintenance review date:		Not reported
Most recent equipment inspection date:		Not reported
Equipment tested:		Not reported
Most recent changes by mgmt:		Not reported
Date of most recent review/update:		Not reported
Date of pre-start review:		Not reported
Most recent compliance audit date:		Not reported
Expected date of audit completion:		Not reported
Most recent incident investigation:		Not reported
Expected date of investigation changes:		Not reported
Date of participation plan review:		Not reported
Date of hot work permit review:		Not reported
Date of contractor safety review:		Not reported
Date of contractor safety eval. review:		Not reported
Record has CBI data:		Not reported
Safety review date:		Not reported
Federal Regulation:		Not reported
Federal regulation comment:		Not reported
Major Hazard:		Not reported
Process Control:		Not reported
Mitigation Systems:		Not reported
Monitoring/Detection:		Not reported
Changes since the last process hazard analysis:		Not reported
Most recent hazard review/update:		Not reported
Most recent review of op. procedures:		Not reported
Most recent training progs review/update:		Not reported
Expected completion of review changes:		Not reported
Training:		Not reported
Competency testing:		Not reported
Most recent maintenance review date:		Not reported
Most recent equipment inspection date:		Not reported
Equipment tested:		Not reported
Most recent compliance audit date:		Not reported
Expected date of audit completion:		Not reported
Most recent incident investigation:		Not reported
Expected date of investigation changes:		Not reported
Record has CBI data:		Not reported
Date of most recent changes:		Not reported
Chemical name:	Hydrazine	

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process chemical qty in 100s lbs: 210000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Hydrogen chloride (anhydrous) [Hydrochloric acid]
Process chemical qty in 100s lbs:	270000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Hydrogen fluoride/Hydrofluoric acid (conc 50% or greater) [Hydrofluoric acid]
Process chemical qty in 100s lbs: 190000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Hydrogen sulfide
Process chemical qty in 100s lbs:	240000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Methyl chloride [Methane, chloro-]
Process chemical qty in 100s lbs:	200000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Methyl isocyanate [Methane, isocyanato-]
Process chemical qty in 100s lbs: 210000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Methyl mercaptan [Methanethiol]
Process chemical qty in 100s lbs:	210000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Methyltrichlorosilane [Silane, trichloromethyl-]
Process chemical qty in 100s lbs: 210000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Phosphorus trichloride [Phosphorous trichloride]
Process chemical qty in 100s lbs: 220000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Sulfur dioxide (anhydrous)
Process chemical qty in 100s lbs: 190000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of most recent changes: Not reported
Chemical name: Titanium tetrachloride [Titanium chloride (TiCl4) (T-4)-]
Process chemical qty in 100s lbs: 190000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Toluene diisocyanate (unspecified isomer) [Benzene, 1,3-diisocyanatomethyl-]
Process chemical qty in 100s lbs: 200000
Process flammable chemical name: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Toxic Alt. Releases:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Toxics Worst Case:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported
- Most recent PHA date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Trichlorosilane [Silane, trichloro-]
Process chemical qty in 100s lbs:	220000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Vinylidene chloride [Ethene, 1,1-dichloro-]
Process chemical qty in 100s lbs:	230000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Acetaldehyde
Process chemical qty in 100s lbs:	220000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Toxics Worst Case:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported
- Most recent PHA date: Not reported
- Process Hazard Analysis: Not reported
- Expected PHA changes completion date: Not reported
- Major Hazard: Not reported
- Process Control: Not reported
- Mitigation Systems: Not reported
- Monitoring/Detection: Not reported
- Changes since the last process hazard analysis: Not reported
- Most recent review of op. procedures: Not reported
- Most recent training progs review/update: Not reported
- Training: Not reported
- Competency testing: Not reported
- Most recent maintenance review date: Not reported
- Most recent equipment inspection date: Not reported
- Equipment tested: Not reported
- Most recent changes by mgmt: Not reported
- Date of most recent review/update: Not reported
- Date of pre-start review: Not reported
- Most recent compliance audit date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Ethyl ether [Ethane, 1,1'-oxybis-]
Process chemical qty in 100s lbs:	180000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Methyl ether [Methane, oxybis-]
Process chemical qty in 100s lbs:	180000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Propylene oxide [Oxirane, methyl-]
Process chemical qty in 100s lbs:	180000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Passive mitigation: Not reported

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported
- Most recent PHA date: Not reported
- Process Hazard Analysis: Not reported
- Expected PHA changes completion date: Not reported
- Major Hazard: Not reported
- Process Control: Not reported
- Mitigation Systems: Not reported
- Monitoring/Detection: Not reported
- Changes since the last process hazard analysis: Not reported
- Most recent review of op. procedures: Not reported
- Most recent training progs review/update: Not reported
- Training: Not reported
- Competency testing: Not reported
- Most recent maintenance review date: Not reported
- Most recent equipment inspection date: Not reported
- Equipment tested: Not reported
- Most recent changes by mgmt: Not reported
- Date of most recent review/update: Not reported
- Date of pre-start review: Not reported
- Most recent compliance audit date: Not reported
- Expected date of audit completion: Not reported
- Most recent incident investigation: Not reported
- Expected date of investigation changes: Not reported
- Date of participation plan review: Not reported
- Date of hot work permit review: Not reported
- Date of contractor safety review: Not reported
- Date of contractor safety eval. review: Not reported
- Record has CBI data: Not reported
- Safety review date: Not reported
- Federal Regulation: Not reported
- Federal regulation comment: Not reported
- Major Hazard: Not reported
- Process Control: Not reported
- Mitigation Systems: Not reported
- Monitoring/Detection: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Acrylonitrile [2-Propenenitrile]
Process chemical qty in 100s lbs: 180000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Epichlorohydrin [Oxirane, (chloromethyl)-]
Process chemical qty in 100s lbs: 230000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Ethylenediamine [1,2-Ethanediamine]
Process chemical qty in 100s lbs: 210000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Vinyl acetate monomer [Acetic acid ethenyl ester]

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process chemical qty in 100s lbs: 200000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Vinyl chloride [Ethene, chloro-]
Process chemical qty in 100s lbs:	200000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: c
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: c
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Toxic Alt. Releases:
- Percent weight of chemical: 38
- Physical state: b
- Analytical basic: EPA's RMP*Comp(TM)
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: 3
- Stability class: D
- Topography: a
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Release mitigation involves closing a hand valve upstream of the chemical pump and the outlet valve

Process Toxics Worst Case:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported
- Most recent PHA date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Toxics Worst Case:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported
- Most recent PHA date: Not reported
- Process Hazard Analysis: Not reported
- Expected PHA changes completion date: Not reported
- Major Hazard: Not reported
- Process Control: Not reported
- Mitigation Systems: Not reported
- Monitoring/Detection: Not reported
- Changes since the last process hazard analysis: Not reported
- Most recent review of op. procedures: Not reported
- Most recent training progs review/update: Not reported
- Training: Not reported
- Competency testing: Not reported
- Most recent maintenance review date: Not reported
- Most recent equipment inspection date: Not reported
- Equipment tested: Not reported
- Most recent changes by mgmt: Not reported
- Date of most recent review/update: Not reported
- Date of pre-start review: Not reported
- Most recent compliance audit date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Passive mitigation: Not reported

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported
- Most recent PHA date: Not reported
- Process Hazard Analysis: Not reported
- Expected PHA changes completion date: Not reported
- Major Hazard: Not reported
- Process Control: Not reported
- Mitigation Systems: Not reported
- Monitoring/Detection: Not reported
- Changes since the last process hazard analysis: Not reported
- Most recent review of op. procedures: Not reported
- Most recent training progs review/update: Not reported
- Training: Not reported
- Competency testing: Not reported
- Most recent maintenance review date: Not reported
- Most recent equipment inspection date: Not reported
- Equipment tested: Not reported
- Most recent changes by mgmt: Not reported
- Date of most recent review/update: Not reported
- Date of pre-start review: Not reported
- Most recent compliance audit date: Not reported
- Expected date of audit completion: Not reported
- Most recent incident investigation: Not reported
- Expected date of investigation changes: Not reported
- Date of participation plan review: Not reported
- Date of hot work permit review: Not reported
- Date of contractor safety review: Not reported
- Date of contractor safety eval. review: Not reported
- Record has CBI data: Not reported
- Safety review date: Not reported
- Federal Regulation: Not reported
- Federal regulation comment: Not reported
- Major Hazard: Not reported
- Process Control: Not reported
- Mitigation Systems: Not reported
- Monitoring/Detection: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: 90
Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Release mitigation involves closing a hand valve upstream of the chemical pump and the outlet valve

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: EPA's RMP*Comp(TM)
Quantity released in pounds: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: 30
Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Release mitigation involves closing a hand valve upstream of the chemical pump and the outlet valve

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Toxic Alt. Releases:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Toxics Worst Case:
- Percent weight of chemical: Not reported
- Physical state: b
- Analytical basic: EPA's RMP*Comp(TM)
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: 61.200001
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: 1.5
- Stability class: F
- Topography: a
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported
- Most recent PHA date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Toxics Worst Case:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported
- Most recent PHA date: Not reported
- Process Hazard Analysis: Not reported
- Expected PHA changes completion date: Not reported
- Major Hazard: Not reported
- Process Control: Not reported
- Mitigation Systems: Not reported
- Monitoring/Detection: Not reported
- Changes since the last process hazard analysis: Not reported
- Most recent review of op. procedures: Not reported
- Most recent training progs review/update: Not reported
- Training: Not reported
- Competency testing: Not reported
- Most recent maintenance review date: Not reported
- Most recent equipment inspection date: Not reported
- Equipment tested: Not reported
- Most recent changes by mgmt: Not reported
- Date of most recent review/update: Not reported
- Date of pre-start review: Not reported
- Most recent compliance audit date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Passive mitigation: Not reported

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported
- Most recent PHA date: Not reported
- Process Hazard Analysis: Not reported
- Expected PHA changes completion date: Not reported
- Major Hazard: Not reported
- Process Control: Not reported
- Mitigation Systems: Not reported
- Monitoring/Detection: Not reported
- Changes since the last process hazard analysis: Not reported
- Most recent review of op. procedures: Not reported
- Most recent training progs review/update: Not reported
- Training: Not reported
- Competency testing: Not reported
- Most recent maintenance review date: Not reported
- Most recent equipment inspection date: Not reported
- Equipment tested: Not reported
- Most recent changes by mgmt: Not reported
- Date of most recent review/update: Not reported
- Date of pre-start review: Not reported
- Most recent compliance audit date: Not reported
- Expected date of audit completion: Not reported
- Most recent incident investigation: Not reported
- Expected date of investigation changes: Not reported
- Date of participation plan review: Not reported
- Date of hot work permit review: Not reported
- Date of contractor safety review: Not reported
- Date of contractor safety eval. review: Not reported
- Record has CBI data: Not reported
- Safety review date: Not reported
- Federal Regulation: Not reported
- Federal regulation comment: Not reported
- Major Hazard: Not reported
- Process Control: Not reported
- Mitigation Systems: Not reported
- Monitoring/Detection: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Distance to endpoint in miles:	Not reported	
Residential population:	Not reported	
Public receptors:	Not reported	
Environmental receptors:	Not reported	
Passive mitigation:	Not reported	
Safety review date:		Not reported
Most recent PHA date:		Not reported
Process Hazard Analysis:		Not reported
Expected PHA changes completion date:		Not reported
Major Hazard:		Not reported
Process Control:		Not reported
Mitigation Systems:		Not reported
Monitoring/Detection:		Not reported
Changes since the last process hazard analysis:		Not reported
Most recent review of op. procedures:		Not reported
Most recent training progs review/update:		Not reported
Training:		Not reported
Competency testing:		Not reported
Most recent maintenance review date:		Not reported
Most recent equipment inspection date:		Not reported
Equipment tested:		Not reported
Most recent changes by mgmt:		Not reported
Date of most recent review/update:		Not reported
Date of pre-start review:		Not reported
Most recent compliance audit date:		Not reported
Expected date of audit completion:		Not reported
Most recent incident investigation:		Not reported
Expected date of investigation changes:		Not reported
Date of participation plan review:		Not reported
Date of hot work permit review:		Not reported
Date of contractor safety review:		Not reported
Date of contractor safety eval. review:		Not reported
Record has CBI data:		Not reported
Safety review date:		Not reported
Federal Regulation:		Not reported
Federal regulation comment:		Not reported
Major Hazard:		Not reported
Process Control:		Not reported
Mitigation Systems:		Not reported
Monitoring/Detection:		Not reported
Changes since the last process hazard analysis:		Not reported
Most recent hazard review/update:		Not reported
Most recent review of op. procedures:		Not reported
Most recent training progs review/update:		Not reported
Expected completion of review changes:		Not reported
Training:		Not reported
Competency testing:		Not reported
Most recent maintenance review date:		Not reported
Most recent equipment inspection date:		Not reported
Equipment tested:		Not reported
Most recent compliance audit date:		Not reported
Expected date of audit completion:		Not reported
Most recent incident investigation:		Not reported
Expected date of investigation changes:		Not reported
Record has CBI data:		Not reported
Date of most recent changes:		Not reported
Chemical name:	Public OCA Chemical	

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Toxic Alt. Releases:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Toxics Worst Case:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported
- Most recent PHA date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Toxics Worst Case:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported
- Most recent PHA date: Not reported
- Process Hazard Analysis: Not reported
- Expected PHA changes completion date: Not reported
- Major Hazard: Not reported
- Process Control: Not reported
- Mitigation Systems: Not reported
- Monitoring/Detection: Not reported
- Changes since the last process hazard analysis: Not reported
- Most recent review of op. procedures: Not reported
- Most recent training progs review/update: Not reported
- Training: Not reported
- Competency testing: Not reported
- Most recent maintenance review date: Not reported
- Most recent equipment inspection date: Not reported
- Equipment tested: Not reported
- Most recent changes by mgmt: Not reported
- Date of most recent review/update: Not reported
- Date of pre-start review: Not reported
- Most recent compliance audit date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Passive mitigation: Not reported

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported
- Most recent PHA date: Not reported
- Process Hazard Analysis: Not reported
- Expected PHA changes completion date: Not reported
- Major Hazard: Not reported
- Process Control: Not reported
- Mitigation Systems: Not reported
- Monitoring/Detection: Not reported
- Changes since the last process hazard analysis: Not reported
- Most recent review of op. procedures: Not reported
- Most recent training progs review/update: Not reported
- Training: Not reported
- Competency testing: Not reported
- Most recent maintenance review date: Not reported
- Most recent equipment inspection date: Not reported
- Equipment tested: Not reported
- Most recent changes by mgmt: Not reported
- Date of most recent review/update: Not reported
- Date of pre-start review: Not reported
- Most recent compliance audit date: Not reported
- Expected date of audit completion: Not reported
- Most recent incident investigation: Not reported
- Expected date of investigation changes: Not reported
- Date of participation plan review: Not reported
- Date of hot work permit review: Not reported
- Date of contractor safety review: Not reported
- Date of contractor safety eval. review: Not reported
- Record has CBI data: Not reported
- Safety review date: Not reported
- Federal Regulation: Not reported
- Federal regulation comment: Not reported
- Major Hazard: Not reported
- Process Control: Not reported
- Mitigation Systems: Not reported
- Monitoring/Detection: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported

Emergency Response Details:

ER plan:	Not reported
ER plan most recent review date:	6/20/1999
ER plan most recent employee training date:	4/13/1999
Local agency coordinating ER plan:	San Bernardino County Fire Dept.
Telephone of the coordinating local agency:	9093874631
Federal regulation:	True
OSHA 1910 120:	True
SPCC:	True
RCRA:	True
OPA 90:	True
EPCRA:	True
Other Regulations:	Not reported

Risk Management Plan (RMP) Facility Details:

Facility ID:	19241
LEPC city:	San Bernardino County Fire Dpt
Facility decimal latitude:	34.065361
Facility decimal longitude:	-117.349833
Is facility in county box:	T
LatLong method:	I1
LatLong description:	CE
Home page web address:	Not reported
Facility telephone:	Not reported
Facility email:	Not reported
Facility DUNS #:	0
Parent's name:	General American Transportation Corporation
Partner's name:	GATX Corporation
Parent's DUNS #:	20040630
Partner's DUNS #:	5161476
Operator's name:	General American Transp. Corp.
Operator's telephone:	3126216200
Operator's address:	500 West Monroe Street
Operators City,St,Zip:	Chicago, IL 60661 3677
RMP implementation contact:	Danny Contreras
RMP contact title:	Plant Manager
Emergency contact:	Bill Newman
Emergency contact title:	Environmental and Cleaning Coord.
Emergency contact telephone:	9097775110
24 hour emergency telephone:	7148268782
Emergency contact ext/pin #:	Not reported
Number of full time employees:	75
EPA ID:	CAD 055 698 815
Facility ID provided by CEPPO:	100000049351
Is facility covered by OSHA PSM:	T
Is facility covered by EPCRA 302:	T

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Is fac. covered by CAA Title V 112(2): F
Clean air op. permit/State ID: Not reported
Last safety insp. dat: 10/15/1995
Inspected by: State occupational safety agency
Is it OSHA approved with star/merit ranking: False
Will RMP involve predictive filing: False
Submission type: Correction
RMP description: Not reported
Facility has no accident hist. recs: True
Foreign owner's address: Not reported
Foreign owner's zip: Not reported
Foreign owner's country: Not reported
Claim # of employees as CBI: False
Date RMP accepted by EPA: 12/14/1999
Date of error Report: Not reported
Date RMP received: 12/14/1999
Does RMP contain graphics files: False
Does RMP contain attachments: False
Was certification letter received: True
RMP submission method: Commercial Software Vendor
Does RMP contain CBI substantiation: False
Does RMP contain electronic waiver: False
Date RMP postmarked: 12/9/1999
Is RMP complete: True
Date of de-registration: Not reported
Date de-registration is effective: Not reported
Aniversary date: 6/16/2004
Does RMP contain CBI data: False
Does RMP contain unsanitized CBI version: False
RMP version #: 1.1.7
FRS latitude: 34.06534
FRS longitude: -117.3507
FRS Description: FACILITY CENTROID
FRS Method: INTERPOLATION-MAP

Process Details:
Process ID: 27077
NA & Industry Classification Sys.code(s): 81131
NAICS code description: Commercial and Industrial Machinery and Equipment (except Automotive and Electronic) Repa
Optional facility description: Not reported
Program level: 3
Record contains CBI data: False

Process chemical(s):
Chemical name: Ammonia (anhydrous)
Process chemical qty in 100s lbs: 170000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	1,3-Butadiene
Process chemical qty in 100s lbs:	170000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Butane
Process chemical qty in 100s lbs:	160000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Butene
Process chemical qty in 100s lbs:	160000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	1-Butene
Process chemical qty in 100s lbs:	160000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: 2-Butene
Process chemical qty in 100s lbs: 160000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: 2-Butene-cis
Process chemical qty in 100s lbs: 160000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: 2-Butene-trans [2-Butene, (E)]
Process chemical qty in 100s lbs: 160000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Chemical name: Chlorine
Process chemical qty in 100s lbs: 200000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Hydrochloric acid (conc 37% or greater)
Process chemical qty in 100s lbs: 100000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Isobutane [Propane, 2-methyl]
Process chemical qty in 100s lbs: 150000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Isopentane [Butane, 2-methyl-]
Process chemical qty in 100s lbs:	180000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Isoprene [1,3-Butadiene, 2-methyl-]
Process chemical qty in 100s lbs: 190000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: 2-Methyl-1-butene
Process chemical qty in 100s lbs: 180000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	3-Methyl-1-butene
Process chemical qty in 100s lbs:	170000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	2-Methylpropene [1-Propene, 2-methyl-]
Process chemical qty in 100s lbs:	170000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Flammables Alt. Releases:

Endpoint used:	Not reported
LFL value:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Flammables Worst Case:

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Nitric acid (conc 80% or greater)
Process chemical qty in 100s lbs: 180000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: 1,3-Pentadiene
Process chemical qty in 100s lbs: 190000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Active mitigation: Not reported

Process Flammables Worst Case:

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Pentane
Process chemical qty in 100s lbs: 180000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Residential population:	Not reported	
Public receptors:	Not reported	
Environmental receptors:	Not reported	
Passive mitigation:	Not reported	
Safety review date:		Not reported
Most recent PHA date:		Not reported
Process Hazard Analysis:		Not reported
Expected PHA changes completion date:		Not reported
Major Hazard:		Not reported
Process Control:		Not reported
Mitigation Systems:		Not reported
Monitoring/Detection:		Not reported
Changes since the last process hazard analysis:		Not reported
Most recent review of op. procedures:		Not reported
Most recent training progs review/update:		Not reported
Training:		Not reported
Competency testing:		Not reported
Most recent maintenance review date:		Not reported
Most recent equipment inspection date:		Not reported
Equipment tested:		Not reported
Most recent changes by mgmt:		Not reported
Date of most recent review/update:		Not reported
Date of pre-start review:		Not reported
Most recent compliance audit date:		Not reported
Expected date of audit completion:		Not reported
Most recent incident investigation:		Not reported
Expected date of investigation changes:		Not reported
Date of participation plan review:		Not reported
Date of hot work permit review:		Not reported
Date of contractor safety review:		Not reported
Date of contractor safety eval. review:		Not reported
Record has CBI data:		Not reported
Safety review date:		Not reported
Federal Regulation:		Not reported
Federal regulation comment:		Not reported
Major Hazard:		Not reported
Process Control:		Not reported
Mitigation Systems:		Not reported
Monitoring/Detection:		Not reported
Changes since the last process hazard analysis:		Not reported
Most recent hazard review/update:		Not reported
Most recent review of op. procedures:		Not reported
Most recent training progs review/update:		Not reported
Expected completion of review changes:		Not reported
Training:		Not reported
Competency testing:		Not reported
Most recent maintenance review date:		Not reported
Most recent equipment inspection date:		Not reported
Equipment tested:		Not reported
Most recent compliance audit date:		Not reported
Expected date of audit completion:		Not reported
Most recent incident investigation:		Not reported
Expected date of investigation changes:		Not reported
Record has CBI data:		Not reported
Date of most recent changes:		Not reported
Chemical name:	1-Pentene	
Process chemical qty in 100s lbs:	180000	

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Toxics Worst Case:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	2-Pentene, (E)-
Process chemical qty in 100s lbs:	180000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: 2-Pentene, (Z)-
Process chemical qty in 100s lbs: 180000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Propane
Process chemical qty in 100s lbs:	140000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Propylene [1-Propene]
Process chemical qty in 100s lbs: 140000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Dimethylamine [Methanamine, N-methyl-]
Process chemical qty in 100s lbs:	190000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Federal Regulation:		Not reported
Federal regulation comment:		Not reported
Major Hazard:		Not reported
Process Control:		Not reported
Mitigation Systems:		Not reported
Monitoring/Detection:		Not reported
Changes since the last process hazard analysis:		Not reported
Most recent hazard review/update:		Not reported
Most recent review of op. procedures:		Not reported
Most recent training progs review/update:		Not reported
Expected completion of review changes:		Not reported
Training:		Not reported
Competency testing:		Not reported
Most recent maintenance review date:		Not reported
Most recent equipment inspection date:		Not reported
Equipment tested:		Not reported
Most recent compliance audit date:		Not reported
Expected date of audit completion:		Not reported
Most recent incident investigation:		Not reported
Expected date of investigation changes:		Not reported
Record has CBI data:		Not reported
Date of most recent changes:		Not reported
Chemical name:	Ethylamine	[Ethanamine]
Process chemical qty in 100s lbs:	190000	
Process flammable chemical name:	Not reported	

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Methylamine [Methanamine]
Process chemical qty in 100s lbs: 190000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Oleum (Fuming Sulfuric acid) [Sulfuric acid, mixture with sulfur trioxide]
Process chemical qty in 100s lbs: 60000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Trimethylamine [Methanamine, N,N-dimethyl-]
Process chemical qty in 100s lbs: 140000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Chemical name: Allyl alcohol [2-Propen-1-ol]
Process chemical qty in 100s lbs: 180000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Bromine
Process chemical qty in 100s lbs: 210000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Carbon disulfide
Process chemical qty in 100s lbs: 240000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Training:		Not reported
Competency testing:		Not reported
Most recent maintenance review date:		Not reported
Most recent equipment inspection date:		Not reported
Equipment tested:		Not reported
Most recent changes by mgmt:		Not reported
Date of most recent review/update:		Not reported
Date of pre-start review:		Not reported
Most recent compliance audit date:		Not reported
Expected date of audit completion:		Not reported
Most recent incident investigation:		Not reported
Expected date of investigation changes:		Not reported
Date of participation plan review:		Not reported
Date of hot work permit review:		Not reported
Date of contractor safety review:		Not reported
Date of contractor safety eval. review:		Not reported
Record has CBI data:		Not reported
Safety review date:		Not reported
Federal Regulation:		Not reported
Federal regulation comment:		Not reported
Major Hazard:		Not reported
Process Control:		Not reported
Mitigation Systems:		Not reported
Monitoring/Detection:		Not reported
Changes since the last process hazard analysis:		Not reported
Most recent hazard review/update:		Not reported
Most recent review of op. procedures:		Not reported
Most recent training progs review/update:		Not reported
Expected completion of review changes:		Not reported
Training:		Not reported
Competency testing:		Not reported
Most recent maintenance review date:		Not reported
Most recent equipment inspection date:		Not reported
Equipment tested:		Not reported
Most recent compliance audit date:		Not reported
Expected date of audit completion:		Not reported
Most recent incident investigation:		Not reported
Expected date of investigation changes:		Not reported
Record has CBI data:		Not reported
Date of most recent changes:		Not reported
Chemical name:	Chloroform	[Methane, trichloro-]
Process chemical qty in 100s lbs:	240000	
Process flammable chemical name:	Not reported	

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Ethyl chloride [Ethane, chloro-]
Process chemical qty in 100s lbs:	190000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Ethylene oxide [Oxirane]
Process chemical qty in 100s lbs: 250000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Formaldehyde (solution)
Process chemical qty in 100s lbs:	80000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Hydrazine
Process chemical qty in 100s lbs:	210000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Flammables Alt. Releases:

Endpoint used:	Not reported
LFL value:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Flammables Worst Case:

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Hydrogen chloride (anhydrous) [Hydrochloric acid]
Process chemical qty in 100s lbs: 270000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Hydrogen fluoride/Hydrofluoric acid (conc 50% or greater) [Hydrofluoric acid]
Process chemical qty in 100s lbs: 190000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Active mitigation: Not reported

Process Flammables Worst Case:

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Hydrogen sulfide
Process chemical qty in 100s lbs: 240000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Methyl chloride [Methane, chloro-]
Process chemical qty in 100s lbs:	200000

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Toxics Worst Case:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Methyl isocyanate [Methane, isocyanato-]
Process chemical qty in 100s lbs:	210000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Methyl mercaptan [Methanethiol]
Process chemical qty in 100s lbs: 210000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Methyltrichlorosilane [Silane, trichloromethyl-]
Process chemical qty in 100s lbs:	210000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Phosphorus trichloride [Phosphorous trichloride]
Process chemical qty in 100s lbs: 220000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Sulfur dioxide (anhydrous)
Process chemical qty in 100s lbs:	190000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Titanium tetrachloride [Titanium chloride (TiCl4) (T-4)-]
Process chemical qty in 100s lbs:	190000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Toluene diisocyanate (unspecified isomer) [Benzene, 1,3-diisocyanatomethyl-]
Process chemical qty in 100s lbs: 200000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Trichlorosilane [Silane, trichloro-]
Process chemical qty in 100s lbs: 220000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Vinylidene chloride [Ethene, 1,1-dichloro-]
Process chemical qty in 100s lbs: 230000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Chemical name: Acetaldehyde
Process chemical qty in 100s lbs: 220000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Ethyl ether [Ethane, 1,1'-oxybis-]
Process chemical qty in 100s lbs:	180000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Methyl ether [Methane, oxybis-]
Process chemical qty in 100s lbs: 180000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Propylene oxide [Oxirane, methyl-]
Process chemical qty in 100s lbs:	180000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Acrylonitrile [2-Propenenitrile]
Process chemical qty in 100s lbs:	180000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Epichlorohydrin [Oxirane, (chloromethyl)-]
Process chemical qty in 100s lbs: 230000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Ethylenediamine [1,2-Ethanediamine]
Process chemical qty in 100s lbs:	210000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Vinyl acetate monomer [Acetic acid ethenyl ester]
Process chemical qty in 100s lbs:	200000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Flammables Alt. Releases:

Endpoint used:	Not reported
LFL value:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Flammables Worst Case:

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Vinyl chloride [Ethene, chloro-]
Process chemical qty in 100s lbs: 200000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: c
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Active mitigation: Not reported

Process Flammables Worst Case:

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Toxics Worst Case:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: c
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: 38
Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Release mitigation involves closing a hand valve upstream of the chemical pump and the outlet valve

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: 90
Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Release mitigation involves closing a hand valve upstream of the chemical pump and the outlet valve

Process Toxics Worst Case:
Percent weight of chemical: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: EPA's RMP*Comp(TM)
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Flammables Alt. Releases:

Endpoint used:	Not reported
LFL value:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Flammables Worst Case:

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Active mitigation: Not reported

Process Flammables Worst Case:

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Toxics Worst Case:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: 30
Physical state: b
Analytical basic: EPA’s RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Release mitigation involves closing a hand valve upstream of the chemical pump and the outlet valve

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	b
Analytical basic:	EPA's RMP*Comp(TM)
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	3
Stability class:	D
Topography:	a
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: 61.200001
Release rate in pounds per second: Not reported
Wind speed in meters/second: 1.5
Stability class: F
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Physical state: c
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA’s RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	b
Analytical basic:	EPA's RMP*Comp(TM)
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	3
Stability class:	D
Topography:	a
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	c
Analytical basic:	EPA’s RMP*Comp(TM)
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	3
Stability class:	D
Topography:	a
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: c
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	c
Analytical basic:	EPA's RMP*Comp(TM)
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	3
Stability class:	D
Topography:	a
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	c
Analytical basic:	EPA's RMP*Comp(TM)
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	3
Stability class:	D
Topography:	a
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Flammables Alt. Releases:

Endpoint used:	Not reported
LFL value:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Flammables Worst Case:

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: c
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Active mitigation: Not reported

Process Flammables Worst Case:

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
- Percent weight of chemical: Not reported
- Physical state: b
- Analytical basic: EPA's RMP*Comp(TM)
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: 3
- Stability class: D
- Topography: a
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Toxics Worst Case:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	c
Analytical basic:	EPA’s RMP*Comp(TM)

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA’s RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	b
Analytical basic:	EPA’s RMP*Comp(TM)
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	3
Stability class:	D
Topography:	a
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA’s RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA’s RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported

Emergency Response Details:

ER plan:	Not reported
ER plan most recent review date:	6/20/1999
ER plan most recent employee training date:	4/13/1999
Local agency coordinating ER plan:	San Bernardino County Fire Dept.
Telephone of the coordinating local agency:	9093874631
Federal regulation:	True
OSHA 1910 120:	True
SPCC:	True
RCRA:	True
OPA 90:	True
EPCRA:	True
Other Regulations:	Not reported

Risk Management Plan (RMP) Facility Details:

Facility ID:	17912
LEPC city:	San Bernardino County Fire Dpt
Facility decimal latitude:	34.065361
Facility decimal longitude:	-117.349833
Is facility in county box:	T
LatLong method:	I1
LatLong description:	CE
Home page web address:	Not reported
Facility telephone:	Not reported
Facility email:	Not reported
Facility DUNS #:	0
Parent's name:	General American Transportation Corporation

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Partner's name:	GATX Corporation
Parent's DUNS #:	20040630
Partner's DUNS #:	5161476
Operator's name:	General American Transp. Corp.
Operator's telephone:	3126216200
Operator's address:	500 West Monroe Street
Operators City,St,Zip:	Chicago, IL 60661 3677
RMP implementation contact:	Danny Contreras
RMP contact title:	Plant Manager
Emergency contact:	Bill Newman
Emergency contact title:	Environmental and Cleaning Coord.
Emergency contact telephone:	9097775110
24 hour emergency telephone:	7148268782
Emergency contact ext/pin #:	Not reported
Number of full time employees:	75
EPA ID:	CAD 055 698 815
Facility ID provided by CEPPO:	100000049351
Is facility covered by OSHA PSM:	T
Is facility covered by EPCRA 302:	T
Is fac. covered by CAA Title V 112(2):	F
Clean air op. permit/State ID:	Not reported
Last safety insp. dat:	10/15/1995
Inspected by:	State occupational safety agency
Is it OSHA approved with star/merit ranking:	False
Will RMP involve predictive filing:	False
Submission type:	Correction
RMP description:	Not reported
Facility has no accident hist. recs:	True
Foreign owner's address:	Not reported
Foreign owner's zip:	Not reported
Foreign owner's country:	Not reported
Claim # of employees as CBI:	False
Date RMP accepted by EPA:	10/18/1999
Date of error Report:	Not reported
Date RMP received:	10/15/1999
Does RMP contain graphics files:	False
Does RMP contain attachments:	False
Was certification letter received:	True
RMP submission method:	RMP*Submit
Does RMP contain CBI substantiation:	False
Does RMP contain electronic waiver:	False
Date RMP postmarked:	10/14/1999
Is RMP complete:	True
Date of de-registration:	Not reported
Date de-registration is effective:	Not reported
Aniversary date:	6/16/2004
Does RMP contain CBI data:	False
Does RMP contain unsanitized CBI version:	False
RMP version #:	1.1.7
FRS latitude:	34.06534
FRS longitude:	-117.3507
FRS Description:	FACILITY CENTROID
FRS Method:	INTERPOLATION-MAP

Process Details:

Process ID:	25266
NA & Industry Classification Sys.code(s):	81131

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

NAICS code description: Commercial and Industrial Machinery and Equipment (except Automotive and Electronic) Repa
Optional facility description: Not reported
Program level: 3
Record contains CBI data: False

Process chemical(s):
Chemical name: Ammonia (anhydrous)
Process chemical qty in 100s lbs: 170000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Chemical name: 1,3-Butadiene
Process chemical qty in 100s lbs: 170000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Butane
Process chemical qty in 100s lbs: 160000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Butene
Process chemical qty in 100s lbs:	160000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	1-Butene
Process chemical qty in 100s lbs:	160000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	2-Butene
Process chemical qty in 100s lbs:	160000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	2-Butene-cis
Process chemical qty in 100s lbs:	160000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	2-Butene-trans [2-Butene, (E)]
Process chemical qty in 100s lbs:	160000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Chlorine
Process chemical qty in 100s lbs: 200000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Flammables Alt. Releases:

Endpoint used:	Not reported
LFL value:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Flammables Worst Case:

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Hydrochloric acid (conc 37% or greater)
Process chemical qty in 100s lbs: 100000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Isobutane [Propane, 2-methyl]
Process chemical qty in 100s lbs: 150000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Isopentane [Butane, 2-methyl-]
Process chemical qty in 100s lbs: 180000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Isoprene [1,3-Butadiene, 2-methyl-]
Process chemical qty in 100s lbs:	190000

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Toxics Worst Case:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	2-Methyl-1-butene
Process chemical qty in 100s lbs:	180000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	3-Methyl-1-butene
Process chemical qty in 100s lbs:	170000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	2-Methylpropene [1-Propene, 2-methyl-]
Process chemical qty in 100s lbs:	170000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Nitric acid (conc 80% or greater)
Process chemical qty in 100s lbs:	180000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	1,3-Pentadiene
Process chemical qty in 100s lbs:	190000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Pentane
Process chemical qty in 100s lbs:	180000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	1-Pentene
Process chemical qty in 100s lbs:	180000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported

Process Flammables Alt. Releases:

Endpoint used:	Not reported
LFL value:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: 2-Pentene, (E)-
Process chemical qty in 100s lbs: 180000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: 2-Pentene, (Z)-
Process chemical qty in 100s lbs: 180000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Chemical name: Propane
Process chemical qty in 100s lbs: 140000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Propylene [1-Propene]
Process chemical qty in 100s lbs: 140000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Dimethylamine [Methanamine, N-methyl-]
Process chemical qty in 100s lbs: 190000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Ethylamine [Ethanamine]
Process chemical qty in 100s lbs:	190000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Methylamine [Methanamine]
Process chemical qty in 100s lbs: 190000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Oleum (Fuming Sulfuric acid) [Sulfuric acid, mixture with sulfur trioxide]
Process chemical qty in 100s lbs:	60000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Trimethylamine [Methanamine, N,N-dimethyl-]
Process chemical qty in 100s lbs: 140000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Allyl alcohol [2-Propen-1-ol]
Process chemical qty in 100s lbs:	180000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Flammables Alt. Releases:

Endpoint used:	Not reported
LFL value:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Flammables Worst Case:

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Bromine
Process chemical qty in 100s lbs: 210000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Carbon disulfide
Process chemical qty in 100s lbs: 240000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Active mitigation: Not reported

Process Flammables Worst Case:

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Chloroform [Methane, trichloro-]
Process chemical qty in 100s lbs: 240000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Ethyl chloride [Ethane, chloro-]
Process chemical qty in 100s lbs:	190000

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Toxics Worst Case:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Ethylene oxide [Oxirane]
Process chemical qty in 100s lbs:	250000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Formaldehyde (solution)
Process chemical qty in 100s lbs:	80000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Hydrazine
Process chemical qty in 100s lbs:	210000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Hydrogen chloride (anhydrous) [Hydrochloric acid]
Process chemical qty in 100s lbs:	270000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Hydrogen fluoride/Hydrofluoric acid (conc 50% or greater) [Hydrofluoric acid]
Process chemical qty in 100s lbs:	190000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Hydrogen sulfide
Process chemical qty in 100s lbs:	240000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Methyl chloride [Methane, chloro-]
Process chemical qty in 100s lbs: 200000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Methyl isocyanate [Methane, isocyanato-]
Process chemical qty in 100s lbs: 210000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Methyl mercaptan [Methanethiol]
Process chemical qty in 100s lbs: 210000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Chemical name: Methyltrichlorosilane [Silane, trichloromethyl-]
Process chemical qty in 100s lbs: 210000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Phosphorus trichloride [Phosphorous trichloride]
Process chemical qty in 100s lbs: 220000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Sulfur dioxide (anhydrous)
Process chemical qty in 100s lbs:	190000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Titanium tetrachloride [Titanium chloride (TiCl4) (T-4)-]
Process chemical qty in 100s lbs:	190000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Toluene diisocyanate (unspecified isomer) [Benzene, 1,3-diisocyanatomethyl-]
Process chemical qty in 100s lbs:	200000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Trichlorosilane [Silane, trichloro-]
Process chemical qty in 100s lbs: 220000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Vinylidene chloride [Ethene, 1,1-dichloro-]
Process chemical qty in 100s lbs: 230000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Acetaldehyde
Process chemical qty in 100s lbs:	220000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Flammables Alt. Releases:

Endpoint used:	Not reported
LFL value:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Flammables Worst Case:

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Ethyl ether [Ethane, 1,1'-oxybis-]
Process chemical qty in 100s lbs: 180000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Methyl ether [Methane, oxybis-]
Process chemical qty in 100s lbs: 180000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Active mitigation: Not reported

Process Flammables Worst Case:

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Propylene oxide [Oxirane, methyl-]
Process chemical qty in 100s lbs: 180000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Residential population:	Not reported	
Public receptors:	Not reported	
Environmental receptors:	Not reported	
Passive mitigation:	Not reported	
Safety review date:		Not reported
Most recent PHA date:		Not reported
Process Hazard Analysis:		Not reported
Expected PHA changes completion date:		Not reported
Major Hazard:		Not reported
Process Control:		Not reported
Mitigation Systems:		Not reported
Monitoring/Detection:		Not reported
Changes since the last process hazard analysis:		Not reported
Most recent review of op. procedures:		Not reported
Most recent training progs review/update:		Not reported
Training:		Not reported
Competency testing:		Not reported
Most recent maintenance review date:		Not reported
Most recent equipment inspection date:		Not reported
Equipment tested:		Not reported
Most recent changes by mgmt:		Not reported
Date of most recent review/update:		Not reported
Date of pre-start review:		Not reported
Most recent compliance audit date:		Not reported
Expected date of audit completion:		Not reported
Most recent incident investigation:		Not reported
Expected date of investigation changes:		Not reported
Date of participation plan review:		Not reported
Date of hot work permit review:		Not reported
Date of contractor safety review:		Not reported
Date of contractor safety eval. review:		Not reported
Record has CBI data:		Not reported
Safety review date:		Not reported
Federal Regulation:		Not reported
Federal regulation comment:		Not reported
Major Hazard:		Not reported
Process Control:		Not reported
Mitigation Systems:		Not reported
Monitoring/Detection:		Not reported
Changes since the last process hazard analysis:		Not reported
Most recent hazard review/update:		Not reported
Most recent review of op. procedures:		Not reported
Most recent training progs review/update:		Not reported
Expected completion of review changes:		Not reported
Training:		Not reported
Competency testing:		Not reported
Most recent maintenance review date:		Not reported
Most recent equipment inspection date:		Not reported
Equipment tested:		Not reported
Most recent compliance audit date:		Not reported
Expected date of audit completion:		Not reported
Most recent incident investigation:		Not reported
Expected date of investigation changes:		Not reported
Record has CBI data:		Not reported
Date of most recent changes:		Not reported
Chemical name:	Acrylonitrile	[2-Propenenitrile]
Process chemical qty in 100s lbs:	180000	

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Toxics Worst Case:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Epichlorohydrin [Oxirane, (chloromethyl)-]
Process chemical qty in 100s lbs:	230000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Ethylenediamine [1,2-Ethanediamine]
Process chemical qty in 100s lbs: 210000
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Vinyl acetate monomer [Acetic acid ethenyl ester]
Process chemical qty in 100s lbs:	200000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Vinyl chloride [Ethene, chloro-]
Process chemical qty in 100s lbs:	200000
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: c
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: c
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	38
Physical state:	b
Analytical basic:	EPA’s RMP*Comp(TM)
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	3
Stability class:	D
Topography:	a
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Release mitigation involves closing a hand valve upstream of the chemical pump and the outlet valve

Process Toxics Worst Case:

Percent weight of chemical:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Flammables Alt. Releases:

Endpoint used:	Not reported
LFL value:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Flammables Worst Case:

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Active mitigation: Not reported

Process Flammables Worst Case:

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
- Percent weight of chemical: 90
- Physical state: b
- Analytical basic: EPA's RMP*Comp(TM)
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: 3
- Stability class: D
- Topography: a
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Release mitigation involves closing a hand valve upstream of the chemical pump and the outlet valve

Process Toxics Worst Case:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: EPA's RMP*Comp(TM)
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: 30

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Release mitigation involves closing a hand valve upstream of the chemical pump and the outlet valve

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	b
Analytical basic:	EPA’s RMP*Comp(TM)
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	3
Stability class:	D
Topography:	a
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	b
Analytical basic:	EPA’s RMP*Comp(TM)
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	3
Stability class:	D
Topography:	a
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Physical state:	b
Analytical basic:	EPA's RMP*Comp(TM)
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	61.200001
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	1.5
Stability class:	F
Topography:	a
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported

Process Flammables Alt. Releases:

Endpoint used:	Not reported
LFL value:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Flammables Worst Case:

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	b
Analytical basic:	EPA's RMP*Comp(TM)
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	3
Stability class:	D
Topography:	a
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Flammables Alt. Releases:

Endpoint used:	Not reported
LFL value:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Flammables Worst Case:

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: c
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
- Percent weight of chemical: Not reported
- Physical state: c
- Analytical basic: EPA's RMP*Comp(TM)
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: 3
- Stability class: D
- Topography: a
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Toxics Worst Case:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	c
Analytical basic:	EPA's RMP*Comp(TM)

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	c
Analytical basic:	EPA's RMP*Comp(TM)
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	3
Stability class:	D

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	c
Analytical basic:	EPA’s RMP*Comp(TM)
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	3
Stability class:	D
Topography:	a
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA’s RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	c
Analytical basic:	EPA's RMP*Comp(TM)
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	3
Stability class:	D
Topography:	a
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	b
Analytical basic:	EPA's RMP*Comp(TM)
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	3
Stability class:	D
Topography:	a
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: c
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0
Process flammable chemical name:	Not reported

Process Toxic Alt. Releases:

Percent weight of chemical:	Not reported
Physical state:	b
Analytical basic:	EPA's RMP*Comp(TM)
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	3
Stability class:	D
Topography:	a
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	Not reported
Stability class:	Not reported
Topography:	Not reported
Distance to endpoint in miles:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process Flammables Alt. Releases:

Endpoint used:	Not reported
LFL value:	Not reported
Analytical basic:	Not reported
Scenario:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Not reported

Process Flammables Worst Case:

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Safety review date: Not reported
Most recent PHA date: Not reported
Process Hazard Analysis: Not reported
Expected PHA changes completion date: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Training: Not reported
Competency testing: Not reported
Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent changes by mgmt: Not reported
Date of most recent review/update: Not reported
Date of pre-start review: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Date of participation plan review: Not reported
Date of hot work permit review: Not reported
Date of contractor safety review: Not reported
Date of contractor safety eval. review: Not reported
Record has CBI data: Not reported
Safety review date: Not reported
Federal Regulation: Not reported
Federal regulation comment: Not reported
Major Hazard: Not reported
Process Control: Not reported
Mitigation Systems: Not reported
Monitoring/Detection: Not reported
Changes since the last process hazard analysis: Not reported
Most recent hazard review/update: Not reported
Most recent review of op. procedures: Not reported
Most recent training progs review/update: Not reported
Expected completion of review changes: Not reported
Training: Not reported
Competency testing: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent maintenance review date: Not reported
Most recent equipment inspection date: Not reported
Equipment tested: Not reported
Most recent compliance audit date: Not reported
Expected date of audit completion: Not reported
Most recent incident investigation: Not reported
Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Active mitigation: Not reported

Process Flammables Worst Case:

Analytical basic:	Not reported
Quantity released in pounds:	Not reported
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Expected date of investigation changes: Not reported
Record has CBI data: Not reported
Date of most recent changes: Not reported
Chemical name: Public OCA Chemical
Process chemical qty in 100s lbs: 0
Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
Percent weight of chemical: Not reported
Physical state: b
Analytical basic: EPA's RMP*Comp(TM)
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: 3
Stability class: D
Topography: a
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Toxics Worst Case:
Percent weight of chemical: Not reported
Physical state: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Release duration in minutes: Not reported
Release rate in pounds per second: Not reported
Wind speed in meters/second: Not reported
Stability class: Not reported
Topography: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported

Process Flammables Alt. Releases:
Endpoint used: Not reported
LFL value: Not reported
Analytical basic: Not reported
Scenario: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported
Residential population: Not reported
Public receptors: Not reported
Environmental receptors: Not reported
Passive mitigation: Not reported
Active mitigation: Not reported

Process Flammables Worst Case:
Analytical basic: Not reported
Quantity released in pounds: Not reported
Distance to endpoint in miles: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Safety review date:	Not reported
Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Process flammable chemical name: Not reported

Process Toxic Alt. Releases:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Toxics Worst Case:
- Percent weight of chemical: Not reported
- Physical state: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Release duration in minutes: Not reported
- Release rate in pounds per second: Not reported
- Wind speed in meters/second: Not reported
- Stability class: Not reported
- Topography: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported

Process Flammables Alt. Releases:
- Endpoint used: Not reported
- LFL value: Not reported
- Analytical basic: Not reported
- Scenario: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Active mitigation: Not reported

Process Flammables Worst Case:
- Analytical basic: Not reported
- Quantity released in pounds: Not reported
- Distance to endpoint in miles: Not reported
- Residential population: Not reported
- Public receptors: Not reported
- Environmental receptors: Not reported
- Passive mitigation: Not reported
- Safety review date: Not reported

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

Most recent PHA date:	Not reported
Process Hazard Analysis:	Not reported
Expected PHA changes completion date:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent changes by mgmt:	Not reported
Date of most recent review/update:	Not reported
Date of pre-start review:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Date of participation plan review:	Not reported
Date of hot work permit review:	Not reported
Date of contractor safety review:	Not reported
Date of contractor safety eval. review:	Not reported
Record has CBI data:	Not reported
Safety review date:	Not reported
Federal Regulation:	Not reported
Federal regulation comment:	Not reported
Major Hazard:	Not reported
Process Control:	Not reported
Mitigation Systems:	Not reported
Monitoring/Detection:	Not reported
Changes since the last process hazard analysis:	Not reported
Most recent hazard review/update:	Not reported
Most recent review of op. procedures:	Not reported
Most recent training progs review/update:	Not reported
Expected completion of review changes:	Not reported
Training:	Not reported
Competency testing:	Not reported
Most recent maintenance review date:	Not reported
Most recent equipment inspection date:	Not reported
Equipment tested:	Not reported
Most recent compliance audit date:	Not reported
Expected date of audit completion:	Not reported
Most recent incident investigation:	Not reported
Expected date of investigation changes:	Not reported
Record has CBI data:	Not reported
Date of most recent changes:	Not reported

Emergency Response Details:

ER plan:	Not reported
ER plan most recent review date:	6/20/1999
ER plan most recent employee training date:	4/13/1999
Local agency coordinating ER plan:	San Bernardino County Fire Dept.
Telephone of the coordinating local agency:	9093874631
Federal regulation:	True

GATC - COLTON, CA TANK CAR FACILITY (Continued) **1011825616**

OSHA 1910 120:	True
SPCC:	True
RCRA:	True
OPA 90:	True
EPCRA:	True
Other Regulations:	Not reported

AO333 **ERNS** **2008883409**
SSE **20878 SLOVER AVE** **N/A**
1/4-1/2 **CLOTON, CA**
0.418 mi.
2208 ft. **Site 11 of 13 in cluster AO**

Relative:
Lower

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

Actual:
1004 ft.

AO334 **BRINE FAC,COLTON** **LDS** **S109286762**
SSE **20870 SLOVER** **N/A**
1/4-1/2 **COLTON, CA**
0.420 mi.
2219 ft. **Site 12 of 13 in cluster AO**

Relative:
Lower

LDS:

Global Id:	L10004559727
Latitude:	34.06315
Longitude:	-117.3501
Case Type:	Land Disposal Site
Status:	Open - Verification Monitoring
Status Date:	01/01/2005
Lead Agency:	SANTA ANA RWQCB (REGION 8)
Caseworker:	KDP
Local Agency:	Not reported
RB Case Number:	8 362016002
LOC Case Number:	Not reported
File Location:	Regional Board
Potential Media Affect:	Not reported
Potential Contaminants of Concern:	Not reported
Site History:	This is a brine pond site that is conducting detection monitoring. There has not been a release at the site.

Actual:
1012 ft.

Click here to access the California GeoTracker records for this facility:

AO335 **BRINE FACCOLTON** **WMUDS/SWAT** **S103443302**
SSE **20870 SLOVER AVE** **WDS** **N/A**
1/4-1/2 **COLTON, CA 0**
0.421 mi.
2221 ft. **Site 13 of 13 in cluster AO**

Relative:
Lower

WMUDS/SWAT:

Edit Date:	Not reported
Complexity:	Category C - Facilities having no waste treatment systems, such as cooling water dischargers or thosewho must comply through best management practices, facilities with passive waste treatment and

Actual:
1012 ft.

BRINE FACCOLTON (Continued) **S103443302**

	disposal systems, such as septic systems with subsurface disposal, or dischargers having waste storage systems with land disposal such as dairy waste ponds.
Primary Waste:	Washwater Waste (Product washwater wastes: E.G., photo reuse wastewater, vegetable washwater)
Primary Waste Type:	Designated/Influent or Solid Wastes that pose a significant threat to water quality because of their high concentrations (E.G., BOD, Hardness, TRF, Chloride). 'Manageable' hazardous wastes (E.G., inorganic salts and heavy metals) are included in this category.
Secondary Waste:	Not reported
Secondary Waste Type:	Not reported
Base Meridian:	Not reported
NPID:	Not reported
Tonnage:	0
Regional Board ID:	Not reported
Municipal Solid Waste:	False
Superorder:	False
Open To Public:	False
Waste List:	False
Agency Type:	Private
Agency Name:	GATX RAIL CORPORATION
Agency Department:	Not reported
Agency Address:	PO BOX 590
Agency City,St,Zip:	COLTON CA 923240266
Agency Contact:	DANNY CONTRERAS
Agency Telephone:	9098253043
Land Owner Name:	Not reported
Land Owner Address:	Not reported
Land Owner City,St,Zip:	Not reported
Land Owner Contact:	Not reported
Land Owner Phone:	Not reported
Region:	8
Facility Type:	Industrial - Facility that treats and/or disposes of liquid or semisolid wastes from any servicing, producing, manufacturing or processing operation of whatever nature, including mining, gravel washing, geothermal operations, air conditioning, ship building and repairing, oil production, storage and disposal operations, water pumping.
Facility Description:	Not reported
Facility Telephone:	Not reported
SWAT Facility Name:	Not reported
Primary SIC:	3743
Secondary SIC:	Not reported
Comments:	Not reported
Last Facility Editors:	Not reported
Waste Discharge System:	True
Solid Waste Assessment Test Program:	False
Toxic Pits Cleanup Act Program:	False
Resource Conservation Recovery Act:	False
Department of Defence:	False
Solid Waste Assessment Test Program:	Not reported
Threat to Water Quality:	Minor Threat to Water Quality. A violation of a regional board order should cause a relatively minor impairment of beneficial uses compared to a major or minor threat. Not: All nurds without a TTWQ will be considered a minor threat to water quality unless coded at a higher Level. A Zero (0) may be used to code those NURDS that are found to represent no threat to water quality.

BRINE FACCOLTON (Continued) **S103443302**

Sub Chapter 15:	True
Regional Board Project Officer:	KDP
Number of WMUDS at Facility:	1
Section Range:	Not reported
RCRA Facility:	No
Waste Discharge Requirements:	A
Self-Monitoring Rept. Frequency:	Bimonthly (Every two months)
Waste Discharge System ID:	8 362016002
Solid Waste Information ID:	Not reported

CA WDS:

Facility ID:	Santa Ana River 362016002
Facility Type:	Industrial - Facility that treats and/or disposes of liquid or semisolid wastes from any servicing, producing, manufacturing or processing operation of whatever nature, including mining, gravel washing, geothermal operations, air conditioning, ship building and repairing, oil production, storage and disposal operations, water pumping.
Facility Status:	Active - Any facility with a continuous or seasonal discharge that is under Waste Discharge Requirements.
NPDES Number:	Not reported
Subregion:	8
Facility Telephone:	Not reported
Facility Contact:	JAY GROVE
Agency Name:	GATX RAIL CORPORATION
Agency Address:	PO BOX 590
Agency City,St,Zip:	COLTON 923240266
Agency Contact:	DANNY CONTRERAS
Agency Telephone:	Not reported
Agency Type:	Private
SIC Code:	3743
SIC Code 2:	Not reported
Primary Waste:	Washwater Waste (Product washwater wastes: E.G., photo reuse wastewater, vegetable washwater)
Primary Waste Type:	Designated/Influent or Solid Wastes that pose a significant threat to water quality because of their high concentrations (E.G., BOD, Hardness, TRF, Chloride). 'Manageable' hazardous wastes (E.G., inorganic salts and heavy metals) are included in this category.
Secondary Waste:	Not reported
Secondary Waste Type:	Not reported
Design Flow:	0
Baseline Flow:	0
Reclamation:	No reclamation requirements associated with this facility.
POTW:	The facility is not a POTW.
Treat To Water:	Minor Threat to Water Quality. A violation of a regional board order should cause a relatively minor impairment of beneficial uses compared to a major or minor threat. Not: All nurds without a TTWQ will be considered a minor threat to water quality unless coded at a higher Level. A Zero (0) may be used to code those NURDS that are found to represent no threat to water quality.
Complexity:	Category C - Facilities having no waste treatment systems, such as cooling water dischargers or thosewho must comply through best management practices, facilities with passive waste treatment and disposal systems, such as septic systems with subsurface disposal, or dischargers having waste storage systems with land disposal such as dairy waste ponds.

AP336
ENE
1/4-1/2
0.421 mi.
2223 ft.

1095 STEVENSON AVE
COLTON, CA 92324

Site 1 of 5 in cluster AP

Relative:
Lower

Actual:
1065 ft.

CDL **S107527124**
N/A

CDL:

Facility ID:	200005080
Lab Type:	Illegal Drug Lab (L) - location where an illegal drug lab was operated or drug lab equipment and/or materials were stored.

AQ337
SSE
1/4-1/2
0.429 mi.
2266 ft.

GATX
PEPPER AV/SLOVER ST.
COLTON, CA 92324

Site 1 of 7 in cluster AQ

Relative:
Lower

Actual:
1044 ft.

EMI **S106831541**
N/A

EMI:

Year:	1987
County Code:	36
Air Basin:	SC
Facility ID:	12332
Air District Name:	SC
SIC Code:	3714
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	9
Reactive Organic Gases Tons/Yr:	9
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1990
County Code:	36
Air Basin:	SC
Facility ID:	12332
Air District Name:	SC
SIC Code:	3714
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	7
Reactive Organic Gases Tons/Yr:	6
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	1
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

AQ338 **GENERAL AMERICAN TRANSPORTATION** **SWEEPS UST** **S106926612**
SSE **PEPPER ST & CLOVER AVE** **ENVIROSTOR** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.429 mi.
2266 ft. **Site 2 of 7 in cluster AQ**

Relative:
Lower

Actual:
1044 ft.

SWEEPS UST:

Status:	Active
Comp Number:	2923
Number:	9
Board Of Equalization:	44-019858
Referral Date:	03-19-92
Action Date:	03-19-92
Created Date:	02-29-88
Tank Status:	A
Owner Tank Id:	65-89
Swrcb Tank Id:	36-000-002923-000001
Actv Date:	07-11-88
Capacity:	1000
Tank Use:	M.V. FUEL
Stg:	P
Content:	DIESEL
Number Of Tanks:	3

Status:	Active
Comp Number:	2923
Number:	9
Board Of Equalization:	44-019858
Referral Date:	03-19-92
Action Date:	03-19-92
Created Date:	02-29-88
Tank Status:	A
Owner Tank Id:	65-187
Swrcb Tank Id:	36-000-002923-000002
Actv Date:	07-11-88
Capacity:	10000
Tank Use:	M.V. FUEL
Stg:	P
Content:	DIESEL
Number Of Tanks:	Not reported

Status:	Active
Comp Number:	2923
Number:	9
Board Of Equalization:	44-019858
Referral Date:	03-19-92
Action Date:	03-19-92
Created Date:	02-29-88
Tank Status:	A
Owner Tank Id:	Not reported
Swrcb Tank Id:	36-000-002923-000003
Actv Date:	07-11-88
Capacity:	1
Tank Use:	UNKNOWN
Stg:	P
Content:	Not reported
Number Of Tanks:	Not reported

GENERAL AMERICAN TRANSPORTATION (Continued) **S106926612**

ENVIROSTOR:

Site Type:	Historical
Site Type Detailed:	* Historical
Acres:	Not reported
NPL:	NO
Regulatory Agencies:	NONE SPECIFIED
Lead Agency:	NONE SPECIFIED
Program Manager:	Not reported
Supervisor:	Referred - Not Assigned
Division Branch:	Cleanup Cypress
Facility ID:	36070007
Site Code:	400217
Assembly:	47
Senate:	20
Special Program:	Not reported
Status:	Refer: RCRA
Status Date:	05/01/1995
Restricted Use:	NO
Site Mgmt. Req.:	NONE SPECIFIED
Funding:	Not reported
Latitude:	34.06305
Longitude:	-117.3525
APN:	NONE SPECIFIED
Past Use:	NONE SPECIFIED
Potential COC:	10195
Confirmed COC:	NONE SPECIFIED
Potential Description:	NONE SPECIFIED
Alias Name:	GATX RAIL
Alias Type:	Alternate Name
Alias Name:	CAD055698815
Alias Type:	EPA Identification Number
Alias Name:	400217
Alias Type:	Project Code (Site Code)
Alias Name:	36070007
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Site Screening
Completed Date:	02/09/1995
Comments:	NFA FOR SITE MITIGATION OPERATIONS, THIS IS A RCRA FACILITY.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	* Discovery
Completed Date:	12/21/1982
Comments:	FACILITY IDENTIFIED PHONE DIRECTORY (1945) AGRICULTURAL PEST CONTROL
Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported

GENERAL AMERICAN TRANSPORTATION (Continued) **S106926612**

Schedule Revised Date: Not reported

AQ339 **GATX RAIL** **HAZNET** **S113001055**
SSE **PEPPER & SLOVER ST** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.429 mi.
2266 ft. **Site 3 of 7 in cluster AQ**

Relative:
Lower

Actual:
1044 ft.

HAZNET:

Year:	2011
Gepaid:	CAD055698815
Contact:	MIKE JONES EH&S MGR
Telephone:	9097775123
Mailing Name:	Not reported
Mailing Address:	20878 SLOVER AVE
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	Not reported
TSD EPA ID:	CAD982444481
TSD County:	Not reported
Waste Category:	Waste oil and mixed oil
Disposal Method:	Metals Recovery Including Retoring,Smelting,Chemicals,Ect
Tons:	0.05
Facility County:	San Bernardino

Year:	2011
Gepaid:	CAD055698815
Contact:	MIKE JONES EH&S MGR
Telephone:	9097775123
Mailing Name:	Not reported
Mailing Address:	20878 SLOVER AVE
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	Not reported
TSD EPA ID:	CAT000613927
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues less than 10 percent
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.21
Facility County:	San Bernardino

Year:	2011
Gepaid:	CAD055698815
Contact:	MIKE JONES EH&S MGR
Telephone:	9097775123
Mailing Name:	Not reported
Mailing Address:	20878 SLOVER AVE
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	Not reported
TSD EPA ID:	CAD097030993
TSD County:	Not reported
Waste Category:	Other inorganic solid waste
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.05
Facility County:	San Bernardino

Year:	2011
Gepaid:	CAD055698815

GATX RAIL (Continued) **S113001055**

Contact:	MIKE JONES EH&S MGR
Telephone:	9097775123
Mailing Name:	Not reported
Mailing Address:	20878 SLOVER AVE
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	Not reported
TSD EPA ID:	CAD097030993
TSD County:	Not reported
Waste Category:	Other inorganic solid waste
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.05
Facility County:	San Bernardino

Year:	2011
Gepaid:	CAD055698815
Contact:	MIKE JONES EH&S MGR
Telephone:	9097775123
Mailing Name:	Not reported
Mailing Address:	20878 SLOVER AVE
Mailing City,St,Zip:	COLTON, CA 923240000
Gen County:	Not reported
TSD EPA ID:	CAD008252405
TSD County:	Not reported
Waste Category:	Off-specification, aged or surplus organics
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.05
Facility County:	San Bernardino

Click this hyperlink while viewing on your computer to access
292 additional CA_HAZNET: record(s) in the EDR Site Report.

AQ340 **CHMIRS** **S103679577**
SSE **PEPPER & SLOVER ST** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.429 mi.
2266 ft. **Site 4 of 7 in cluster AQ**

Relative:
Lower

Actual:
1044 ft.

CHMIRS:

OES Incident Number:	2731
OES notification:	Not reported
OES Date:	6/15/1994
OES Time:	08:25:34 PM
Incident Date:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported

(Continued) **S103679577**

Special Studies 5:	Not reported	
Special Studies 6:	Not reported	
More Than Two Substances Involved?:		Not reported
Resp Agncy Personel # Of Decontaminated:		Not reported
Responding Agency Personel # Of Injuries:		Not reported
Responding Agency Personel # Of Fatalities:		Not reported
Others Number Of Decontaminated:		Not reported
Others Number Of Injuries:		Not reported
Others Number Of Fatalities:		Not reported
Vehicle Make/year:	Not reported	
Vehicle License Number:	Not reported	
Vehicle State:	Not reported	
Vehicle Id Number:	Not reported	
CA/DOT/PUC/ICC Number:	Not reported	
Company Name:	Not reported	
Reporting Officer Name/ID:	Not reported	
Report Date:	Not reported	
Comments:	Not reported	
Facility Telephone:	Not reported	
Waterway Involved:	YES	
Waterway:	Not reported	
Spill Site:	Not reported	
Cleanup By:	DISPOSAL CONTROL SERVICES	
Containment:	Not reported	
What Happened:	Not reported	
Type:	CHEMICAL	
Measure:	Not reported	
Other:	Not reported	
Date/Time:	Not reported	
Year:	1994	
Agency:	COLTON FD	
Incident Date:	1206 6/15/94	
Admin Agency:	Not reported	
Amount:	30 GAL	
Contained:	NO	
Site Type:	RD	
E Date:	Not reported	
Substance:	ACID	
Quantity Released:	Not reported	
BBLS:	Not reported	
Cups:	Not reported	
CUFT:	Not reported	
Gallons:	Not reported	
Grams:	Not reported	
Pounds:	Not reported	
Liters:	Not reported	
Ounces:	Not reported	
Pints:	Not reported	
Quarts:	Not reported	
Sheen:	Not reported	
Tons:	Not reported	
Unknown:	Not reported	
Evacuations:	NO	
Number of Injuries:	NO	
Number of Fatalities:	NO	
Description:	ILLEGAL DUMP	

AQ341 **GATX RAIL** **ENVIROSTOR** **S107144613**
SSE **PEPPER & SLOVER ST** **HWP** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.429 mi.
2266 ft. **Site 5 of 7 in cluster AQ**

Relative:
Lower

Actual:
1044 ft.

ENVIROSTOR:

Site Type:	Corrective Action
Site Type Detailed:	Corrective Action
Acres:	29
NPL:	NO
Regulatory Agencies:	SMBRP
Lead Agency:	WM
Program Manager:	Vu Nguyen
Supervisor:	Philip Chandler
Division Branch:	Cleanup Chatsworth
Facility ID:	80001420
Site Code:	400217
Assembly:	47
Senate:	20
Special Program:	Not reported
Status:	Active
Status Date:	01/01/2008
Restricted Use:	NO
Site Mgmt. Req.:	NONE SPECIFIED
Funding:	Not reported
Latitude:	34.06332
Longitude:	-117.3509
APN:	NONE SPECIFIED
Past Use:	ABOVE GROUND STORAGE TANKS, OIL/WATER SEPARATORS, PAINT/DEPAINT FACILITY, RAIL ROAD MAINTENANCE SHOP
Potential COC:	3002502, 30032, 30407
Confirmed COC:	30032,30407,3002502
Potential Description:	SOIL
Alias Name:	GENERAL AMERICAN TRANSPORTATION CORP.
Alias Type:	Alternate Name
Alias Name:	CAD055698815
Alias Type:	EPA Identification Number
Alias Name:	400217
Alias Type:	Project Code (Site Code)
Alias Name:	36070007
Alias Type:	Envirostor ID Number
Alias Name:	80001420
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	RFI Workplan
Completed Date:	09/24/1992
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Preliminary Assessment Report
Completed Date:	06/21/1989
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported

GATX RAIL (Continued) **S107144613**

Completed Document Type: Other Report
Completed Date: 02/02/2010
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: RFI Report
Completed Date: 12/15/1993
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: RFI Workplan
Completed Date: 07/01/1992
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: RCRA Facility Assessment Report
Completed Date: 06/21/1989
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Historical Operating Permit Authority
Completed Date: 12/15/1991
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Other Instrument
Completed Date: 08/06/2010
Comments: Not reported

Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: Remedy Constructed
Future Due Date: 2015
Schedule Area Name: PROJECT WIDE
Schedule Sub Area Name: Not reported
Schedule Document Type: Human Exposure Controlled
Schedule Due Date: 06/03/2013
Schedule Revised Date: Not reported
Schedule Area Name: PROJECT WIDE
Schedule Sub Area Name: Not reported
Schedule Document Type: Groundwater Migration Controlled
Schedule Due Date: 06/03/2013
Schedule Revised Date: Not reported

HWP:
EPA Id: CAD055698815
Latitude: 34.06332
Longitude: -117.3509
Facility Type: Historical - Non-Operating
Cleanup Status: CLOSED
Supervisor: Not reported
Site Code: 400217

GATX RAIL (Continued) **S107144613**

Assembly District: 47
Senate District: 20
Public Information Officer: Not reported

Activities:

EPA Id: CAD055698815
Facility Type: Historical - Non-Operating
Unit Names: CONTAIN2 (GPRA Unit)
Event Description: Renewal - Historical - PUBLIC COMMENT (BEGIN)
Actual Date: 07/16/1991

EPA Id: CAD055698815
Facility Type: Historical - Non-Operating
Unit Names: CONTAIN1, OTHRTRT1-nonRCRA unit (GPRA Unit)
Event Description: New Operating Permit - FINAL PERMIT (EXPIRES)
Actual Date: 05/24/1992

EPA Id: CAD055698815
Facility Type: Historical - Non-Operating
Unit Names: CONTAIN1, OTHRTRT1-nonRCRA unit (GPRA Unit)
Event Description: New Operating Permit - CALL-IN LETTER ISSUED
Actual Date: 06/20/1983

EPA Id: CAD055698815
Facility Type: Historical - Non-Operating
Unit Names: CONTAIN2 (GPRA Unit)
Event Description: Renewal - Historical - TECHNICAL COMPLETE LETTER
Actual Date: 09/27/1996

EPA Id: CAD055698815
Facility Type: Historical - Non-Operating
Unit Names: CONTAIN1, OTHRTRT1-nonRCRA unit (GPRA Unit)
Event Description: New Operating Permit - FINAL PERMIT
Actual Date: 05/24/1987

EPA Id: CAD055698815
Facility Type: Historical - Non-Operating
Unit Names: CONTAIN1, OTHRTRT1-nonRCRA unit (GPRA Unit)
Event Description: New Operating Permit - APPLICATION PART B RECEIVED
Actual Date: 02/05/1986

EPA Id: CAD055698815
Facility Type: Historical - Non-Operating
Unit Names: CONTAIN1, OTHRTRT1-nonRCRA unit (GPRA Unit)
Event Description: New Operating Permit - TECHNICAL COMPLETE LETTER
Actual Date: 07/15/1991

EPA Id: CAD055698815
Facility Type: Historical - Non-Operating
Unit Names: CONTAIN2 (GPRA Unit)
Event Description: Renewal - Historical - PERMIT TERMINATED - TERMINATION APPROVED
Actual Date: 12/30/1999

EPA Id: CAD055698815
Facility Type: Historical - Non-Operating
Unit Names: CONTAIN2 (GPRA Unit)
Event Description: Renewal - Historical - FINAL PERMIT RENEWAL (EXPIRES)
Actual Date: 12/15/2001

GATX RAIL (Continued) **S107144613**

EPA Id: CAD055698815
Facility Type: Historical - Non-Operating
Unit Names: CONTAIN1, OTHRTRT1-nonRCRA unit (GPRA Unit)
Event Description: New Operating Permit - PERMIT TERMINATED - TERMINATION RECEIVED
Actual Date: 11/28/1988

EPA Id: CAD055698815
Facility Type: Historical - Non-Operating
Unit Names: CONTAIN1, OTHRTRT1-nonRCRA unit (GPRA Unit)
Event Description: New Operating Permit - PUBLIC COMMENT (BEGIN)
Actual Date: 07/16/1991

EPA Id: CAD055698815
Facility Type: Historical - Non-Operating
Unit Names: CONTAIN2 (GPRA Unit)
Event Description: Renewal - Historical - FINAL PERMIT RENEWAL (EFFECTIVE)
Actual Date: 12/15/1991

EPA Id: CAD055698815
Facility Type: Historical - Non-Operating
Unit Names: CONTAIN1, OTHRTRT1-nonRCRA unit (GPRA Unit)
Event Description: New Operating Permit - FINAL PERMIT (EFFECTIVE)
Actual Date: 05/24/1987

EPA Id: CAD055698815
Facility Type: Historical - Non-Operating
Unit Names: CONTAIN2 (GPRA Unit)
Event Description: Renewal - Historical - FINAL PERMIT RENEWAL
Actual Date: 12/15/1991

EPA Id: CAD055698815
Facility Type: Historical - Non-Operating
Unit Names: CONTAIN1, OTHRTRT1-nonRCRA unit (GPRA Unit)
Event Description: New Operating Permit - PERMIT TERMINATED - TERMINATION APPROVED
Actual Date: 07/11/1990

EPA Id: CAD055698815
Facility Type: Historical - Non-Operating
Unit Names: CONTAIN1, OTHRTRT1-nonRCRA unit (GPRA Unit)
Event Description: New Operating Permit - APPLICATION PART A RECEIVED
Actual Date: 11/19/1980

EPA Id: CAD055698815
Facility Type: Historical - Non-Operating
Unit Names: CONTAIN2 (GPRA Unit)
Event Description: Renewal - Historical - PERMIT TERMINATED - TERMINATION RECEIVED
Actual Date: 03/23/1999

EPA Id: CAD055698815
Facility Type: Historical - Non-Operating
Unit Names: CONTAIN2 (GPRA Unit)
Event Description: Renewal - Historical - APPLICATION PART A RECEIVED
Actual Date: 11/19/1980

EPA Id: CAD055698815
Facility Type: Historical - Non-Operating
Unit Names: CONTAIN2 (GPRA Unit)

GATX RAIL (Continued) **S107144613**

Event Description: Renewal - Historical - APPLICATION PART B RECEIVED
Actual Date: 01/19/1991

Closure:
EPA Id: CAD055698815
Facility Type: Historical - Non-Operating
Unit Names: CONTAIN2 (GPRA Unit), OTHRTRT1-nonRCRA unit (GPRA Unit), Stcontain, Sttankbasin, TANKSTR1 (GPRA Unit)
Event Description: Closure Final - CLOSURE PLAN RECEIVED
Actual Date: 03/27/1997

EPA Id: CAD055698815
Facility Type: Historical - Non-Operating
Unit Names: CONTAIN1, CONTAIN2 (GPRA Unit), OTHRTRT1-nonRCRA unit (GPRA Unit), Stcontain, Sttankbasin, TANKSTR1 (GPRA Unit)
Event Description: Closure - ISSUE CLOSURE VERIFICATION
Actual Date: 04/10/2006

EPA Id: CAD055698815
Facility Type: Historical - Non-Operating
Unit Names: CONTAIN2 (GPRA Unit), OTHRTRT1-nonRCRA unit (GPRA Unit), Stcontain, Sttankbasin, TANKSTR1 (GPRA Unit)
Event Description: Closure Final - ISSUE CLOSURE VERIFICATION
Actual Date: 04/10/2006

EPA Id: CAD055698815
Facility Type: Historical - Non-Operating
Unit Names: CONTAIN2 (GPRA Unit), OTHRTRT1-nonRCRA unit (GPRA Unit), Stcontain, Sttankbasin, TANKSTR1 (GPRA Unit)
Event Description: Closure Final - RECEIVE CLOSURE CERTIFICATION
Actual Date: 04/08/2005

EPA Id: CAD055698815
Facility Type: Historical - Non-Operating
Unit Names: CONTAIN1, CONTAIN2 (GPRA Unit), OTHRTRT1-nonRCRA unit (GPRA Unit), Stcontain, Sttankbasin, TANKSTR1 (GPRA Unit)
Event Description: Closure - RECEIVE CLOSURE CERTIFICATION
Actual Date: 05/07/1990

Alias:
EPA Id: CAD055698815
Facility Type: Historical - Non-Operating
Alias Type: Project Code (Site Code)
Alias: 400217

EPA Id: CAD055698815
Facility Type: Historical - Non-Operating
Alias Type: Alternate Name
Alias: GENERAL AMERICAN TRANSPORTATION CORP.

EPA Id: CAD055698815
Facility Type: Historical - Non-Operating
Alias Type: Envirostor ID Number
Alias: 36070007

AQ342 **CDL** **S107529259**
SSE **1601 SLOVER AVE** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.430 mi.
2268 ft. **Site 6 of 7 in cluster AQ**

Relative: CDL:
Lower
Facility ID: 199910133
Lab Type: Abandoned Drug Lab Waste (A) - location away from an actual illegal drug lab where drug lab waste and/or equipment were abandoned.

Actual:
1044 ft.

AQ343 **CHMIRS** **S106398795**
SSE **PEPPER & SLOVER AVE.** **N/A**
1/4-1/2 **COLTON, CA**
0.430 mi.
2268 ft. **Site 7 of 7 in cluster AQ**

Relative: CHMIRS:
Lower

OES Incident Number:	03-3799	
OES notification:	07/29/2003	
OES Date:	Not reported	
OES Time:	Not reported	
Incident Date:	Not reported	
Date Completed:	**Not reported**	
Property Use:	Not reported	
Agency Id Number:	Not reported	
Agency Incident Number:	Not reported	
Time Notified:	Not reported	
Time Completed:	Not reported	
Surrounding Area:	Not reported	
Estimated Temperature:	Not reported	
Property Management:	Not reported	
Special Studies 1:	Not reported	
Special Studies 2:	Not reported	
Special Studies 3:	Not reported	
Special Studies 4:	Not reported	
Special Studies 5:	Not reported	
Special Studies 6:	Not reported	
More Than Two Substances Involved?:		Not reported
Resp Agncy Personel # Of Decontaminated:		Not reported
Responding Agency Personel # Of Injuries:		Not reported
Responding Agency Personel # Of Fatalities:		Not reported
Others Number Of Decontaminated:		Not reported
Others Number Of Injuries:		Not reported
Others Number Of Fatalities:		Not reported
Vehicle Make/year:	Not reported	
Vehicle License Number:	Not reported	
Vehicle State:	Not reported	
Vehicle Id Number:	Not reported	
CA/DOT/PUC/ICC Number:	Not reported	
Company Name:	Not reported	
Reporting Officer Name/ID:	Not reported	
Report Date:	Not reported	
Comments:	Not reported	
Facility Telephone:	Not reported	
Waterway Involved:	No	
Waterway:	Not reported	
Spill Site:	Not reported	
Cleanup By:	Contractor	
Containment:	Not reported	

(Continued) **S106398795**

What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	2003
Agency:	UPRR
Incident Date:	7/29/200312:00:00 AM
Admin Agency:	San Bernardino County Health Department
Amount:	Not reported
Contained:	Yes
Site Type:	Rail Road
E Date:	Not reported
Substance:	Paint
Quantity Released:	Not reported
BBLS:	0
Cups:	0
CUFT:	0
Gallons:	30
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	Workers discovered 6 -5 gallon containers abandoned at the rail yard.. Not reported

---

344
NNW
1/4-1/2
0.431 mi.
2276 ft.

935 S SAGE ST
RIALTO, CA

CDL **S107537156**
N/A

Relative:
Higher

Actual:
1143 ft.

CDL:

Facility ID:	200001161
Lab Type:	Illegal Drug Lab (L) - location where an illegal drug lab was operated or drug lab equipment and/or materials were stored.

AR345
ESE
1/4-1/2
0.432 mi.
2282 ft.

DEL TACO #200
834 W VALLEY BLVD
COLTON, CA 92324

Site 1 of 7 in cluster AR

San Bern. Co. Permit **S109849268**
N/A

Relative:
Lower

Actual:
1005 ft.

San Bern. Co. Permit:

Region:	SAN BERNARDINO
Facility ID:	FA0012545
Owner:	DEL TACO INC
Permit Number:	PT0021946

DEL TACO #200 (Continued) **S109849268**

Permit Category: BULK CO2 AT RETAIL FOOD FACILITIES
Facility Status: ACTIVE
Expiration Date: 05/31/2010

AP346 **CDL** **S107527043**
ENE **1073 STEVENSON** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.432 mi.
2283 ft. **Site 2 of 5 in cluster AP**

Relative:
Lower

Actual:
1064 ft.

CDL:
Facility ID: 200206111
Lab Type: Illegal Drug Lab (L) - location where an illegal drug lab was operated or drug lab equipment and/or materials were stored.

AS347 **WILLIAM G. JEHUE MIDDLE** **FINDS** **1008241942**
North **1500 NORTH EUCALYPTUS AVE** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.433 mi.
2285 ft. **Site 1 of 3 in cluster AS**

Relative:
Higher

Actual:
1152 ft.

FINDS:

Registry ID: 110036949620

Environmental Interest/Information System
NCES (National Center for Education Statistics) is the primary federal entity for collecting and analyzing data related to education in the United States and other nations and the institute of education sciences.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

AS348 **WILLIAM G JEHUE MIDDLE SCHOOL** **RCRA-SQG** **1011488137**
North **1500 N EUCALYPTUS** **CAR000192807**
1/4-1/2 **COLTON, CA 92324**
0.433 mi.
2285 ft. **Site 2 of 3 in cluster AS**

Relative:
Higher

Actual:
1152 ft.

RCRA-SQG:
Date form received by agency: 06/05/2008
Facility name: WILLIAM G JEHUE MIDDLE SCHOOL
Facility address: 1500 N EUCALYPTUS
COLTON, CA 92324
EPA ID: CAR000192807
Mailing address: 182 E WLANUT AVE
RIALTO, CA 92376
Contact: GLORIA SHAW
Contact address: 182 E WLANUT AVE

WILLIAM G JEHUE MIDDLE SCHOOL (Continued) **1011488137**

RIALTO, CA 92376
Contact country: US
Contact telephone: 909-820-7700
Telephone ext.: 2110
Contact email: GSHAW@RIALTO.K12.CA.US
EPA Region: 09
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: RIALTO UNIFIED SCHOOL DISTRICT
Owner/operator address: Not reported
Not reported
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Legal status: District
Owner/Operator Type: Operator
Owner/Op start date: 01/01/1960
Owner/Op end date: Not reported

Owner/operator name: RIALTO UNIFIED SCHOOL DISTRICT
Owner/operator address: 182 E WALNUT
RIALTO, CA 92376
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: District
Owner/Operator Type: Owner
Owner/Op start date: 01/01/1960
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Hazardous Waste Summary:
Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE

WILLIAM G JEHUE MIDDLE SCHOOL (Continued) **1011488137**

FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002
Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Waste code: D005
Waste name: BARIUM

Waste code: D007
Waste name: CHROMIUM

Waste code: D011
Waste name: SILVER

Violation Status: No violations found

AS349 **WILLIAM G JEHUE MIDDLE SCHOOL** **HAZNET** **S113178631**
North **1500 N EUCALYPTUS AVE** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.433 mi.
2285 ft. **Site 3 of 3 in cluster AS**

Relative:
Higher

Actual:
1152 ft.

HAZNET:

Year:	2008
Gepaid:	CAR000192807
Contact:	GLORIA SHAW EXT 2110
Telephone:	9098207700
Mailing Name:	Not reported
Mailing Address:	182 E WALNUT AVE
Mailing City,St,Zip:	RIALTO, CA 923763530
Gen County:	Not reported
TSD EPA ID:	CAD028409019
TSD County:	Not reported
Waste Category:	Laboratory waste chemicals
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.005
Facility County:	San Bernardino

Year:	2008
Gepaid:	CAR000192807
Contact:	GLORIA SHAW EXT 2110
Telephone:	9098207700
Mailing Name:	Not reported
Mailing Address:	182 E WALNUT AVE
Mailing City,St,Zip:	RIALTO, CA 923763530
Gen County:	Not reported
TSD EPA ID:	CAD028409019
TSD County:	Not reported
Waste Category:	Laboratory waste chemicals

WILLIAM G JEHUE MIDDLE SCHOOL (Continued) **S113178631**

Disposal Method: Fuel Blending Prior To Energy Recovery At Another Site
Tons: 0.0417
Facility County: San Bernardino

AP350 **CDL** **S107527036**
ENE **1072 STEVENSON ST** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.434 mi.
2292 ft. **Site 3 of 5 in cluster AP**

Relative:
Lower

Actual:
1065 ft.

CDL:
Facility ID: 199801075
Lab Type: Illegal Drug Lab (L) - location where an illegal drug lab was operated or drug lab equipment and/or materials were stored.

AH351 **KODIAK DIESEL REPAIR INC** **San Bern. Co. Permit** **S104532947**
West **350 W VALLEY BLVD** **N/A**
1/4-1/2 **RIALTO, CA 92376**
0.439 mi.
2318 ft. **Site 4 of 12 in cluster AH**

Relative:
Lower

Actual:
1072 ft.

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0011511
Owner: DANIEL V ELLIS
Permit Number: PT0019918
Permit Category: SPECIAL HANDLER
Facility Status: INACTIVE
Expiration Date: 04/30/2008

Region: SAN BERNARDINO
Facility ID: FA0011511
Owner: DANIEL V ELLIS
Permit Number: PT0019917
Permit Category: SPECIAL GENERATOR
Facility Status: INACTIVE
Expiration Date: 04/30/2008

Region: SAN BERNARDINO
Facility ID: FA0001701
Owner: CALICO TRANSPORT INC
Permit Number: PT0002008
Permit Category: SPECIAL HANDLER
Facility Status: INACTIVE
Expiration Date: 11/30/2007

Region: SAN BERNARDINO
Facility ID: FA0001701
Owner: CALICO TRANSPORT INC
Permit Number: PT0002007
Permit Category: SPECIAL GENERATOR
Facility Status: INACTIVE
Expiration Date: 11/30/2007

Region: SAN BERNARDINO
Facility ID: FA0011641

KODIAK DIESEL REPAIR INC (Continued) **S104532947**

Owner: HERRERA, JOSE
Permit Number: PT0020151
Permit Category: SPECIAL HANDLER
Facility Status: ACTIVE
Expiration Date: 05/31/2013

Region: SAN BERNARDINO
Facility ID: FA0011641
Owner: HERRERA, JOSE
Permit Number: PT0020150
Permit Category: SPECIAL GENERATOR
Facility Status: ACTIVE
Expiration Date: 05/31/2013

AH352 **KODIAK DIESEL REPAIR INC** **HAZNET** **S113137700**
West **350 W VALLEY BLVD** **N/A**
1/4-1/2 **RIALTO, CA 92376**
0.439 mi.
2318 ft. **Site 5 of 12 in cluster AH**

Relative:
Lower

Actual:
1072 ft.

HAZNET:
Year: 2008
Gepaid: CAL000295226
Contact: DANIEL ELLIS
Telephone: 9095620904
Mailing Name: Not reported
Mailing Address: 350 W VALLEY BLVD
Mailing City,St,Zip: RIALTO, CA 923767716
Gen County: Not reported
TSD EPA ID: CAD028409019
TSD County: Not reported
Waste Category: Unspecified oil-containing waste
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.2125
Facility County: San Bernardino

AH353 **EDR US Hist Auto Stat** **1015442515**
West **350 W VALLEY BLVD** **N/A**
1/4-1/2 **RIALTO, CA 92376**
0.439 mi.
2318 ft. **Site 6 of 12 in cluster AH**

Relative:
Lower

Actual:
1072 ft.

EDR Historical Auto Stations:
Name: KODIAK DIESEL REPAIR INC
Year: 2006
Address: 350 W VALLEY BLVD

Name: KODIAK DIESEL REPAIR INC
Year: 2007
Address: 350 W VALLEY BLVD

Name: KODIAK DIESEL REPAIR INC
Year: 2008
Address: 350 W VALLEY BLVD

AH354 **DOUGLAS TRUCKING** **FINDS** **1011316580**
West **350 W VALLEY BLVD** **N/A**
1/4-1/2 **RIALTO, CA 92376**
0.439 mi.
2318 ft. **Site 7 of 12 in cluster AH**

Relative:
Lower

Actual:
1072 ft.

FINDS:

Registry ID: 110034211485

Environmental Interest/Information System
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

AH355 **DOUGLAS TRUCKING** **HAZNET** **S113025854**
West **350 W VALLEY BLVD** **N/A**
1/4-1/2 **RIALTO, CA 92376**
0.439 mi.
2318 ft. **Site 8 of 12 in cluster AH**

Relative:
Lower

Actual:
1072 ft.

HAZNET:

Year:	1993
Gepaid:	CAL000012603
Contact:	HAMNER LARRY
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	350 W VALLEY BLVD
Mailing City,St,Zip:	RIALTO, CA 923767716
Gen County:	Not reported
TSD EPA ID:	CAD099452708
TSD County:	Not reported
Waste Category:	Oil/water separation sludge
Disposal Method:	Recycler
Tons:	4.16999999999
Facility County:	San Bernardino

AH356 **CALICO TRANSPORT INC** **HAZNET** **S113119572**
West **350 W VALLEY BLVD** **N/A**
1/4-1/2 **RIALTO, CA 92376**
0.439 mi.
2318 ft. **Site 9 of 12 in cluster AH**

Relative:
Lower

Actual:
1072 ft.

HAZNET:

Year:	2004
Gepaid:	CAL000252548
Contact:	JOHN TURNER
Telephone:	9098776360
Mailing Name:	Not reported
Mailing Address:	350 W VALLEY BLVD
Mailing City,St,Zip:	RIALTO, CA 923760000
Gen County:	Not reported
TSD EPA ID:	CAT080033681

CALICO TRANSPORT INC (Continued) **S113119572**

TSD County: Not reported
Waste Category: Unspecified oil-containing waste
Disposal Method: Disposal, Land Fill
Tons: 0.35
Facility County: San Bernardino

Year: 2003
Gepaid: CAL000252548
Contact: JOHN TURNER
Telephone: 9098776360
Mailing Name: Not reported
Mailing Address: 350 W VALLEY BLVD
Mailing City,St,Zip: RIALTO, CA 923760000
Gen County: Not reported
TSD EPA ID: CAT080033681
TSD County: Not reported
Waste Category: Unspecified oil-containing waste
Disposal Method: Disposal, Land Fill
Tons: Not reported
Facility County: San Bernardino

AH357 **FAT EQUIP RENTAL INC** **CA FID UST** **S101591346**
West **350 W VALLEY BLVD** **SWEEPS UST** **N/A**
1/4-1/2 **RIALTO, CA 92376**
0.439 mi.
2318 ft. **Site 10 of 12 in cluster AH**

Relative:
Lower

Actual:
1072 ft.

CA FID UST:
Facility ID: 36005107
Regulated By: UTNKA
Regulated ID: Not reported
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: Not reported
Mail To: Not reported
Mailing Address: 350 W VALLEY BLVD
Mailing Address 2: Not reported
Mailing City,St,Zip: RIALTO 92376
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Active

SWEEPS UST:
Status: Active
Comp Number: 8456
Number: 1
Board Of Equalization: 44-020063
Referral Date: 03-24-92
Action Date: 03-24-92
Created Date: 09-13-88
Tank Status: A
Owner Tank Id: Not reported
Swrcb Tank Id: 36-000-008456-000001

FAT EQUIP RENTAL INC (Continued) **S101591346**

Actv Date:	09-13-88
Capacity:	1
Tank Use:	UNKNOWN
Stg:	P
Content:	UNKNOWN
Number Of Tanks:	8
Status:	Active
Comp Number:	8456
Number:	1
Board Of Equalization:	44-020063
Referral Date:	03-24-92
Action Date:	03-24-92
Created Date:	09-13-88
Tank Status:	A
Owner Tank Id:	Not reported
Swrcb Tank Id:	36-000-008456-000002
Actv Date:	09-13-88
Capacity:	1
Tank Use:	UNKNOWN
Stg:	P
Content:	UNKNOWN
Number Of Tanks:	Not reported
Status:	Active
Comp Number:	8456
Number:	1
Board Of Equalization:	44-020063
Referral Date:	03-24-92
Action Date:	03-24-92
Created Date:	09-13-88
Tank Status:	A
Owner Tank Id:	Not reported
Swrcb Tank Id:	36-000-008456-000003
Actv Date:	09-13-88
Capacity:	1
Tank Use:	UNKNOWN
Stg:	P
Content:	UNKNOWN
Number Of Tanks:	Not reported
Status:	Active
Comp Number:	8456
Number:	1
Board Of Equalization:	44-020063
Referral Date:	03-24-92
Action Date:	03-24-92
Created Date:	09-13-88
Tank Status:	A
Owner Tank Id:	Not reported
Swrcb Tank Id:	36-000-008456-000004
Actv Date:	09-13-88
Capacity:	1
Tank Use:	UNKNOWN
Stg:	P
Content:	UNKNOWN
Number Of Tanks:	Not reported

FAT EQUIP RENTAL INC (Continued) **S101591346**

Status: Active
Comp Number: 8456
Number: 1
Board Of Equalization: 44-020063
Referral Date: 03-24-92
Action Date: 03-24-92
Created Date: 09-13-88
Tank Status: A
Owner Tank Id: Not reported
Swrcb Tank Id: 36-000-008456-000005
Actv Date: 09-13-88
Capacity: 1
Tank Use: UNKNOWN
Stg: P
Content: UNKNOWN
Number Of Tanks: Not reported

Status: Active
Comp Number: 8456
Number: 1
Board Of Equalization: 44-020063
Referral Date: 03-24-92
Action Date: 03-24-92
Created Date: 09-13-88
Tank Status: A
Owner Tank Id: Not reported
Swrcb Tank Id: 36-000-008456-000006
Actv Date: 09-13-88
Capacity: 1
Tank Use: UNKNOWN
Stg: P
Content: UNKNOWN
Number Of Tanks: Not reported

Status: Active
Comp Number: 8456
Number: 1
Board Of Equalization: 44-020063
Referral Date: 03-24-92
Action Date: 03-24-92
Created Date: 09-13-88
Tank Status: A
Owner Tank Id: Not reported
Swrcb Tank Id: 36-000-008456-000007
Actv Date: 09-13-88
Capacity: 1
Tank Use: UNKNOWN
Stg: P
Content: UNKNOWN
Number Of Tanks: Not reported

Status: Active
Comp Number: 8456
Number: 1
Board Of Equalization: 44-020063
Referral Date: 03-24-92
Action Date: 03-24-92

FAT EQUIP RENTAL INC (Continued) **S101591346**

Created Date:	09-13-88
Tank Status:	A
Owner Tank Id:	Not reported
Swrcb Tank Id:	36-000-008456-000008
Actv Date:	09-13-88
Capacity:	1
Tank Use:	UNKNOWN
Stg:	P
Content:	UNKNOWN
Number Of Tanks:	Not reported

AP358 **CDL** **S107526972**
ENE **1057 STEVENSON ST** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.442 mi.
2332 ft. **Site 4 of 5 in cluster AP**

Relative:
Lower

Actual:
1064 ft.

CDL:

Facility ID:	199701059
Lab Type:	Illegal Drug Lab (L) - location where an illegal drug lab was operated or drug lab equipment and/or materials were stored.

AT359 **GOLDEN L OIL CO** **RCRA NonGen / NLR** **1000186918**
East **850 WEST C ST** **FINDS** **CAD980814172**
1/4-1/2 **COLTON, CA 92324**
0.443 mi.
2337 ft. **Site 1 of 3 in cluster AT**

Relative:
Lower

Actual:
1032 ft.

RCRA NonGen / NLR:

Date form received by agency:	03/18/1983
Facility name:	GOLDEN L OIL CO
Facility address:	850 WEST C ST COLTON, CA 92324
EPA ID:	CAD980814172
Mailing address:	WEST C ST COLTON, CA 92324
Contact:	ENVIRONMENTAL MANAGER
Contact address:	850 WEST C ST COLTON, CA 92324
Contact country:	US
Contact telephone:	(714) 824-5408
Contact email:	Not reported
EPA Region:	09
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	WAYNE A LINDBERG
Owner/operator address:	NOT REQUIRED NOT REQUIRED, ME 99999
Owner/operator country:	Not reported
Owner/operator telephone:	(415) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

GOLDEN L OIL CO (Continued) **1000186918**

Owner/operator name: NOT REQUIRED
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: Yes
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110002672028

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

AM360 **EM AUTO BODY REPAIR** **HAZNET** **S113161105**
SW **2075 S RIVERSIDE AVE** **N/A**
1/4-1/2 **BLOOMINGTON, CA 92316**
0.447 mi.
2358 ft. **Site 2 of 11 in cluster AM**

Relative:
Lower

Actual:
1020 ft.

HAZNET:
Year: 2011
Gepaid: CAL000360701
Contact: DAN NEVIL
Telephone: 9098772012
Mailing Name: Not reported
Mailing Address: 2075 S RIVERSIDE AVE
Mailing City,St,Zip: BLOOMINGTON, CA 923162440
Gen County: Not reported
TSD EPA ID: NVT330010000

EM AUTO BODY REPAIR (Continued) **S113161105**

TSD County:	Not reported
Waste Category:	Organic liquids with metals (Alkaline solution (pH >= 12.5) with metals)
Disposal Method:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons:	0.105
Facility County:	San Bernardino
Year:	2011
Gepaid:	CAL000360701
Contact:	DAN NEVIL
Telephone:	9098772012
Mailing Name:	Not reported
Mailing Address:	2075 S RIVERSIDE AVE
Mailing City,St,Zip:	BLOOMINGTON, CA 923162440
Gen County:	Not reported
TSD EPA ID:	CAD008252405
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues 10 percent or more
Disposal Method:	Fuel Blending Prior To Energy Recovery At Another Site
Tons:	0.07089
Facility County:	San Bernardino
Year:	2011
Gepaid:	CAL000360701
Contact:	DAN NEVIL
Telephone:	9098772012
Mailing Name:	Not reported
Mailing Address:	2075 S RIVERSIDE AVE
Mailing City,St,Zip:	BLOOMINGTON, CA 923162440
Gen County:	Not reported
TSD EPA ID:	CAD008252405
TSD County:	Not reported
Waste Category:	Unspecified solvent mixture
Disposal Method:	Solvents Recovery
Tons:	0.0648
Facility County:	San Bernardino

AM361 **EDR US Hist Auto Stat** **1015315741**
SW **2075 S RIVERSIDE AVE** **N/A**
1/4-1/2 **BLOOMINGTON, CA 92316**
0.447 mi.
2358 ft. **Site 3 of 11 in cluster AM**

Relative:
Lower

Actual:
1020 ft.

EDR Historical Auto Stations:

Name:	AM AUTO REPAIR & MOTOR SERVICE
Year:	2002
Address:	2075 S RIVERSIDE AVE
Name:	AM AUTO REPAIR & MOTOR
Year:	2003
Address:	2075 S RIVERSIDE AVE
Name:	AM AUTO REPAIR
Year:	2005
Address:	2075 S RIVERSIDE AVE
Name:	AM AUTO REPAIR

(Continued) **1015315741**

Year: 2006
Address: 2075 S RIVERSIDE AVE

Name: AM AUTO REPAIR
Year: 2007
Address: 2075 S RIVERSIDE AVE

Name: AM AUTO REPAIR & MOTOR SERVICE
Year: 2008
Address: 2075 S RIVERSIDE AVE

Name: EM AUTO BODY REPAIR
Year: 2011
Address: 2075 S RIVERSIDE AVE

AM362 **SIERRA MFG** **EMI** **S106839370**
SW **2075 S RIVERSIDE AV** **N/A**
1/4-1/2 **BLOOMINGTON, CA 92316**
0.447 mi.
2358 ft. **Site 4 of 11 in cluster AM**

Relative:
Lower

Actual:
1020 ft.

EMI:

Year:	1987
County Code:	36
Air Basin:	SC
Facility ID:	46964
Air District Name:	SC
SIC Code:	7538
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2
Reactive Organic Gases Tons/Yr:	2
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1990
County Code:	36
Air Basin:	SC
Facility ID:	46964
Air District Name:	SC
SIC Code:	7538
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

AU363 **MICHAEL FERGUSON** **HAZNET** **S113181824**
NW **211 EAST MONTROSE STREET** **N/A**
1/4-1/2 **RIALTO, CA 92376**
0.451 mi.
2381 ft. **Site 1 of 2 in cluster AU**

Relative:
Higher

Actual:
1134 ft.

HAZNET:

Year:	1996
Gepaid:	CLU960011351
Contact:	Not reported
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	PO BOX 806
Mailing City,St,Zip:	SACRAMENTO, CA 958120806
Gen County:	Not reported
TSD EPA ID:	CAD008302903
TSD County:	Not reported
Waste Category:	Liquids with pH <= 2
Disposal Method:	Transfer Station
Tons:	.0150
Facility County:	San Bernardino

Year:	1996
Gepaid:	CLU960011351
Contact:	Not reported
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	PO BOX 806
Mailing City,St,Zip:	SACRAMENTO, CA 958120806
Gen County:	Not reported
TSD EPA ID:	CAD008302903
TSD County:	Not reported
Waste Category:	Unspecified organic liquid mixture
Disposal Method:	Transfer Station
Tons:	.0075
Facility County:	San Bernardino

Year:	1996
Gepaid:	CLU960011351
Contact:	Not reported
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	PO BOX 806
Mailing City,St,Zip:	SACRAMENTO, CA 958120806
Gen County:	Not reported
TSD EPA ID:	CAD008302903
TSD County:	Not reported
Waste Category:	Unspecified organic liquid mixture
Disposal Method:	Recycler
Tons:	.0150
Facility County:	San Bernardino

Year:	1996
Gepaid:	CLU960011351
Contact:	Not reported
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	PO BOX 806
Mailing City,St,Zip:	SACRAMENTO, CA 958120806

MICHAEL FERGUSON (Continued) **S113181824**

Gen County: Not reported
TSD EPA ID: CAD008302903
TSD County: Not reported
Waste Category: Other inorganic solid waste
Disposal Method: Transfer Station
Tons: .0050
Facility County: San Bernardino

AU364 **CDL** **S107530804**
NW **211 E MONTROSE ST** **N/A**
1/4-1/2 **RIALTO, CA 92376**
0.451 mi.
2381 ft. **Site 2 of 2 in cluster AU**

Relative:
Higher

Actual:
1134 ft.

CDL:
Facility ID: 199611057
Lab Type: Illegal Drug Lab (L) - location where an illegal drug lab was operated or drug lab equipment and/or materials were stored.

AK365 **EDR US Hist Auto Stat** **1015684253**
NW **959 S RIVERSIDE AVE** **N/A**
1/4-1/2 **RIALTO, CA 92376**
0.453 mi.
2393 ft. **Site 2 of 2 in cluster AK**

Relative:
Higher

Actual:
1131 ft.

EDR Historical Auto Stations:
Name: ECONO LUBE N TUBE 53
Year: 2007
Address: 959 S RIVERSIDE AVE

AP366 **RFS RIO SERVICES** **HAZNET** **S112973923**
ENE **1036 STEVENSON ST** **N/A**
1/4-1/2 **COLTON, CA 92324**
0.456 mi.
2409 ft. **Site 5 of 5 in cluster AP**

Relative:
Lower

Actual:
1063 ft.

HAZNET:
Year: 2008
Gepaid: CAC002636157
Contact: ROBERT PICKERING
Telephone: 7029889600
Mailing Name: Not reported
Mailing Address: 4525 DEAN MARTIN DR UNIT 907
Mailing City,St,Zip: LAS VEGAS, NV 89103
Gen County: Not reported
TSD EPA ID: CAD982444481
TSD County: Not reported
Waste Category: Unspecified oil-containing waste
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.0125
Facility County: San Bernardino

AH367 **EDR US Hist Auto Stat** **1015450403**
West **363 W VALLEY BLVD** **N/A**
1/4-1/2 **RIALTO, CA 92376**
0.459 mi.
2424 ft. **Site 11 of 12 in cluster AH**

Relative:
Lower

Actual:
1073 ft.

EDR Historical Auto Stations:

Name:	UNITED MOBIL REPAIR & TOW
Year:	2010
Address:	363 W VALLEY BLVD

AM368 **POMA AUTOMATED FUELING** **LUST** **S103982182**
SW **2095 S RIVERSIDE AVE** **San Bern. Co. Permit** **N/A**
1/4-1/2 **RIALTO, CA 92376**
0.466 mi.
2459 ft. **Site 5 of 11 in cluster AM**

Relative:
Lower

Actual:
1018 ft.

LUST:

Region:	STATE
Global Id:	T0607100462
Latitude:	34.063455
Longitude:	-117.369614
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	07/17/1998
Lead Agency:	SAN BERNARDINO COUNTY
Case Worker:	CB
Local Agency:	SAN BERNARDINO COUNTY
RB Case Number:	083603105T
LOC Case Number:	97066
File Location:	Local Agency
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607100462
Contact Type:	Local Agency Caseworker
Contact Name:	CURTIS BRUNDAGE
Organization Name:	SAN BERNARDINO COUNTY
Address:	620 S. E STREET
City:	SAN BERNARDINO
Email:	cbrundage@sbcfire.org
Phone Number:	Not reported

Global Id:	T0607100462
Contact Type:	Regional Board Caseworker
Contact Name:	CARL BERNHARDT
Organization Name:	SANTA ANA RWQCB (REGION 8)
Address:	3737 MAIN STREET, SUITE 500
City:	RIVERSIDE
Email:	cbernhardt@waterboards.ca.gov
Phone Number:	9517824495

Regulatory Activities:

Global Id:	T0607100462
Action Type:	Other
Date:	01/01/1950

POMA AUTOMATED FUELING (Continued) **S103982182**

Action: Leak Discovery

Global Id: T0607100462
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0005359
Owner: POMA AUTOMATED FUELING
Permit Number: PT0024692
Permit Category: WASTE INCIDENTAL UST OPERATION ONLY
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0005359
Owner: POMA AUTOMATED FUELING
Permit Number: PT0002097
Permit Category: HAZMAT HANDLER - UST ONLY
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0005359
Owner: POMA AUTOMATED FUELING
Permit Number: PT0012324
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0005359
Owner: POMA AUTOMATED FUELING
Permit Number: PT0012325
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0005359
Owner: POMA AUTOMATED FUELING
Permit Number: PT0012326
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0005359
Owner: POMA AUTOMATED FUELING
Permit Number: PT0012327
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 10/31/2013

AM369 **POMA AUTOMATED FUELING INC** **HAZNET** **S113062973**
SW **2095 S RIVERSIDE AVE** **N/A**
1/4-1/2 **RIALTO, CA 92316**
0.466 mi.
2459 ft. **Site 6 of 11 in cluster AM**

Relative:
Lower

Actual:
1018 ft.

HAZNET:

Year:	2011
Gepaid:	CAL000110896
Contact:	JIM TEBEAU
Telephone:	9094212280
Mailing Name:	Not reported
Mailing Address:	PO BOX 479
Mailing City,St,Zip:	BLOOMINGTON, CA 923160000
Gen County:	Not reported
TSD EPA ID:	NVT330010000
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.4
Facility County:	San Bernardino

Year:	2010
Gepaid:	CAL000110896
Contact:	FELIPE ARREDONDO, OPS MANAGER
Telephone:	9094212280
Mailing Name:	Not reported
Mailing Address:	PO BOX 479
Mailing City,St,Zip:	BLOOMINGTON, CA 923160000
Gen County:	Not reported
TSD EPA ID:	NVT330010000
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.35
Facility County:	San Bernardino

Year:	2009
Gepaid:	CAL000110896
Contact:	FELIPE ARREDONDO, OPS MANAGER
Telephone:	9094212280
Mailing Name:	Not reported
Mailing Address:	PO BOX 479
Mailing City,St,Zip:	BLOOMINGTON, CA 923160000
Gen County:	Not reported
TSD EPA ID:	CAD981696420
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.4
Facility County:	San Bernardino

Year:	2008
Gepaid:	CAL000110896
Contact:	FELIPE ARREDONDO, OPS MANAGER
Telephone:	9094212280

POMA AUTOMATED FUELING INC (Continued) **S113062973**

Mailing Name:	Not reported
Mailing Address:	PO BOX 479
Mailing City,St,Zip:	BLOOMINGTON, CA 923160000
Gen County:	Not reported
TSD EPA ID:	CAD981696420
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.5
Facility County:	San Bernardino
Year:	2007
Gepaid:	CAL000110896
Contact:	FELIPE ARREDONDO, OPS MANAGER
Telephone:	9094212280
Mailing Name:	Not reported
Mailing Address:	P O BOX 479
Mailing City,St,Zip:	BLOOMINGTON, CA 923160000
Gen County:	Not reported
TSD EPA ID:	CAD982444481
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.14
Facility County:	San Bernardino

Click this hyperlink while viewing on your computer to access
23 additional CA_HAZNET: record(s) in the EDR Site Report.

AM370 **POMA DISTRIBUTING CO., INC.** **CA FID UST** **S101619403**
SW **2095 S RIVERSIDE AVE** **SWEEPS UST** **N/A**
1/4-1/2 **RIALTO, CA 92376**
0.469 mi.
2477 ft. **Site 7 of 11 in cluster AM**

Relative:
Lower

Actual:
1018 ft.

CA FID UST:

Facility ID:	36006383
Regulated By:	UTNKA
Regulated ID:	00009131
Cortese Code:	Not reported
SIC Code:	Not reported
Facility Phone:	Not reported
Mail To:	Not reported
Mailing Address:	P O BOX
Mailing Address 2:	Not reported
Mailing City,St,Zip:	RIALTO 92376
Contact:	Not reported
Contact Phone:	Not reported
DUNs Number:	Not reported
NPDES Number:	Not reported
EPA ID:	Not reported
Comments:	Not reported
Status:	Active

SWEEPS UST:

POMA DISTRIBUTING CO., INC. (Continued) **S101619403**

Status: Active
Comp Number: 9131
Number: 9
Board Of Equalization: 44-020163
Referral Date: 07-28-92
Action Date: 07-28-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: CL-1
Swrcb Tank Id: 36-000-009131-000001
Actv Date: 08-26-88
Capacity: 9940
Tank Use: M.V. FUEL
Stg: P
Content: DIESEL
Number Of Tanks: 4

Status: Active
Comp Number: 9131
Number: 9
Board Of Equalization: 44-020163
Referral Date: 07-28-92
Action Date: 07-28-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: CL-2
Swrcb Tank Id: 36-000-009131-000002
Actv Date: 08-26-88
Capacity: 9940
Tank Use: M.V. FUEL
Stg: P
Content: LEADED
Number Of Tanks: Not reported

Status: Active
Comp Number: 9131
Number: 9
Board Of Equalization: 44-020163
Referral Date: 07-28-92
Action Date: 07-28-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: CL-3
Swrcb Tank Id: 36-000-009131-000003
Actv Date: 08-26-88
Capacity: 8000
Tank Use: M.V. FUEL
Stg: P
Content: REG UNLEADED
Number Of Tanks: Not reported

Status: Active
Comp Number: 9131
Number: 9
Board Of Equalization: 44-020163
Referral Date: 07-28-92
Action Date: 07-28-92

POMA DISTRIBUTING CO., INC. (Continued) **S101619403**

Created Date:	02-29-88
Tank Status:	A
Owner Tank Id:	CL-4
Swrcb Tank Id:	36-000-009131-000004
Actv Date:	08-26-88
Capacity:	15000
Tank Use:	M.V. FUEL
Stg:	P
Content:	DIESEL
Number Of Tanks:	Not reported

AJ371 **DEALS RUG CLNRS** **EDR US Hist Cleaners** **1014158155**
East **825 W H ST** **N/A**
1/4-1/2 **COLTON, CA**
0.470 mi.
2482 ft. **Site 2 of 2 in cluster AJ**

Relative:
Lower

Actual:
1011 ft.

EDR Historical Cleaners:

Name:	DEALS RUG CLNRS
Year:	1949
Type:	CARPET CLEANERS AND LAYERS

AH372 **CHMIRS** **S105885957**
West **379 W. VALLEY BLVD.** **N/A**
1/4-1/2 **RIALTO, CA 44310**
0.478 mi.
2525 ft. **Site 12 of 12 in cluster AH**

Relative:
Lower

Actual:
1075 ft.

CHMIRS:

OES Incident Number:	02-4645
OES notification:	08/28/2002
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported

(Continued) **S105885957**

Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	No
Waterway:	Not reported
Spill Site:	Not reported
Cleanup By:	Contractor
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	2002
Agency:	Spill Center
Incident Date:	8/28/200212:00:00 AM
Admin Agency:	San Bernardino County Health Department
Amount:	Not reported
Contained:	No
Site Type:	Road
E Date:	Not reported
Substance:	Diesel Fuel
Quantity Released:	Not reported
BBLS:	0
Cups:	0
CUFT:	0
Gallons:	25-75
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	A bid rig saddle tank was punctured by road debris.

AM373 **NEANDERTHAL CYCLE SALVAGE** **San Bern. Co. Permit** **S104768551**
SW **2192 S RIVERSIDE AVE** **N/A**
1/4-1/2 **RIALTO, CA 92376**
0.484 mi.
2558 ft. **Site 8 of 11 in cluster AM**

Relative:
Lower

Actual:
1017 ft.

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0004952
Owner: HANSON, MARK
Permit Number: PT0006354
Permit Category: CONDITIONALLY EXEMPT SMALL QUANTITY GENERATOR
Facility Status: ACTIVE
Expiration Date: 11/30/2013

---

374 **WEST VALLEY WATER DIST WELL #42** **San Bern. Co. Permit** **S109349370**
WNW **295 W SAN BERNARDINO AVE** **N/A**
1/4-1/2 **RIALTO, CA 92376**
0.487 mi.
2569 ft.

Relative:
Higher

Actual:
1101 ft.

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0011876
Owner: WEST VALLEY WATER DISTRICT
Permit Number: PT0020723
Permit Category: HAZMAT HANDLER 0-10 EMPLOYEES
Facility Status: ACTIVE
Expiration Date: 10/31/2013

AM375 **CARDLOCK FUELS SYSTEM INC** **HAZNET** **S113104181**
SW **2125 S RIVERSIDE AVE** **N/A**
1/4-1/2 **RIALTO, CA 92316**
0.491 mi.
2593 ft. **Site 9 of 11 in cluster AM**

Relative:
Lower

Actual:
1016 ft.

HAZNET:
Year: 2011
Gepaid: CAL000205077
Contact: VIOLA BANKHEAD
Telephone: 8004411215
Mailing Name: Not reported
Mailing Address: PO BOX 7003
Mailing City,St,Zip: LANCASTER, CA 935390000
Gen County: Not reported
TSD EPA ID: CAT080013252
TSD County: Not reported
Waste Category: Unspecified organic liquid mixture
Disposal Method: Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons: 0.017
Facility County: San Bernardino

Year: 2011
Gepaid: CAL000205077
Contact: VIOLA BANKHEAD
Telephone: 8004411215
Mailing Name: Not reported

CARDLOCK FUELS SYSTEM INC (Continued) **S113104181**

Mailing Address:	PO BOX 7003
Mailing City,St,Zip:	LANCASTER, CA 935390000
Gen County:	Not reported
TSD EPA ID:	CAT080013252
TSD County:	Not reported
Waste Category:	Unspecified organic liquid mixture
Disposal Method:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons:	0.017
Facility County:	San Bernardino
Year:	2011
Gepaid:	CAL000205077
Contact:	VIOLA BANKHEAD
Telephone:	8004411215
Mailing Name:	Not reported
Mailing Address:	PO BOX 7003
Mailing City,St,Zip:	LANCASTER, CA 935390000
Gen County:	Not reported
TSD EPA ID:	CAD097030993
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.2
Facility County:	San Bernardino
Year:	2011
Gepaid:	CAL000205077
Contact:	VIOLA BANKHEAD
Telephone:	8004411215
Mailing Name:	Not reported
Mailing Address:	PO BOX 7003
Mailing City,St,Zip:	LANCASTER, CA 935390000
Gen County:	Not reported
TSD EPA ID:	CAD097030993
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.2
Facility County:	San Bernardino
Year:	2010
Gepaid:	CAL000205077
Contact:	VIOLA BANKHEAD
Telephone:	8004411215
Mailing Name:	Not reported
Mailing Address:	PO BOX 7003
Mailing City,St,Zip:	LANCASTER, CA 935390000
Gen County:	Not reported
TSD EPA ID:	CAD097030993
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.2

CARDLOCK FUELS SYSTEM INC (Continued) **S113104181**

Facility County: San Bernardino

Click this hyperlink while viewing on your computer to access
14 additional CA_HAZNET: record(s) in the EDR Site Report.

AM376 **CARDLOCK FUEL SYSTEMS, INC. #165** **San Bern. Co. Permit** **S105159026**
SW **2125 S RIVERSIDE AVE** **N/A**
1/4-1/2 **RIALTO, CA 92376**
0.491 mi.
2593 ft. **Site 10 of 11 in cluster AM**

Relative:
Lower

Actual:
1016 ft.

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0001779
Owner: CARDLOCK FUELS SYSTEM, INC
Permit Number: PT0013889
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: INACTIVE
Expiration Date: 11/30/2009

Region: SAN BERNARDINO
Facility ID: FA0001779
Owner: CARDLOCK FUELS SYSTEM, INC
Permit Number: PT0009970
Permit Category: APSA 10,001-100,000 GAL FAC CAPACITY
Facility Status: ACTIVE
Expiration Date: 11/30/2013

Region: SAN BERNARDINO
Facility ID: FA0001779
Owner: CARDLOCK FUELS SYSTEM, INC
Permit Number: PT0017232
Permit Category: HAZARDOUS WASTE GENERATOR - 0-10 EMPLOYEES
Facility Status: ACTIVE
Expiration Date: 11/30/2013

Region: SAN BERNARDINO
Facility ID: FA0001779
Owner: CARDLOCK FUELS SYSTEM, INC
Permit Number: PT0001045
Permit Category: HAZMAT HANDLER 0-10 EMPLOYEES (W/GEN PRMT)
Facility Status: ACTIVE
Expiration Date: 11/30/2013

AM377 **CIRCLE K GAS STATION** **San Bern. Co. Permit** **S105159193**
SW **2128 S RIVERSIDE AVE** **N/A**
1/2-1 **RIALTO, CA 92376**
0.502 mi.
2648 ft. **Site 11 of 11 in cluster AM**

Relative:
Lower

Actual:
1015 ft.

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0002193
Owner: GALILEE INVESTMENTS
Permit Number: PT0021553
Permit Category: WASTE INCIDENTAL UST OPERATION ONLY

CIRCLE K GAS STATION (Continued) **S105159193**

Facility Status: ACTIVE
Expiration Date: 01/31/2014

Region: SAN BERNARDINO
Facility ID: FA0002193
Owner: GALILEE INVESTMENTS
Permit Number: PT0001089
Permit Category: HAZMAT HANDLER - UST ONLY
Facility Status: ACTIVE
Expiration Date: 01/31/2014

Region: SAN BERNARDINO
Facility ID: FA0002193
Owner: GALILEE INVESTMENTS
Permit Number: PT0012606
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 01/31/2014

Region: SAN BERNARDINO
Facility ID: FA0002193
Owner: GALILEE INVESTMENTS
Permit Number: PT0012607
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 01/31/2014

Region: SAN BERNARDINO
Facility ID: FA0002193
Owner: GALILEE INVESTMENTS
Permit Number: PT0012608
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 01/31/2014

AR378 **ARCO #1569 (FORMER)** **LUST** **S105850454**
ESE **792 VALLEY BOULEVARD WEST** **N/A**
1/2-1 **COLTON, CA 92324**
0.520 mi.
2746 ft. **Site 2 of 7 in cluster AR**

Relative:
Lower

Actual:
1007 ft.

LUST:
Region: STATE
Global Id: T0607135690
Latitude: 34.0685216
Longitude: -117.3355473
Case Type: LUST Cleanup Site
Status: Open - Remediation
Status Date: 08/01/2004
Lead Agency: SANTA ANA RWQCB (REGION 8)
Case Worker: VJB
Local Agency: SAN BERNARDINO COUNTY
RB Case Number: 083604085T
LOC Case Number: Not reported
File Location: Regional Board
Potential Media Affect: Aquifer used for drinking water supply
Potential Contaminants of Concern: Gasoline
Site History: THE CONSULTANT HAS PROPOSED NO FURTHER ACTIVE REMEDIATION AND PLANS

ARCO #1569 (FORMER) (Continued) **S105850454**

TO SUBMIT A WORK PLAN FOR CONFIRMATION SOIL BORINGS. THIS PROPOSAL IS BEING REVIEWED BY THE LOP AGENCY'S CONTRACT GEOLOGIST.

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607135690
Contact Type:	Regional Board Caseworker
Contact Name:	VALERIE JAHN-BULL
Organization Name:	SANTA ANA RWQCB (REGION 8)
Address:	3737 MAIN STREET, SUITE 500
City:	RIVERSIDE
Email:	vjahn-bull@waterboards.ca.gov
Phone Number:	9517824903

Global Id:	T0607135690
Contact Type:	Local Agency Caseworker
Contact Name:	CATHERINE RICHARDS
Organization Name:	SAN BERNARDINO COUNTY
Address:	620 SOUTH E STREET
City:	SAN BERNARDINO
Email:	crichards@sbcfire.org
Phone Number:	9093868419

Regulatory Activities:

Global Id:	T0607135690
Action Type:	ENFORCEMENT
Date:	05/25/2012
Action:	File review

Global Id:	T0607135690
Action Type:	ENFORCEMENT
Date:	01/03/2013
Action:	File review

Global Id:	T0607135690
Action Type:	ENFORCEMENT
Date:	07/19/2011
Action:	Technical Correspondence / Assistance / Other

Global Id:	T0607135690
Action Type:	Other
Date:	01/01/1950
Action:	Leak Stopped

Global Id:	T0607135690
Action Type:	ENFORCEMENT
Date:	03/23/2011
Action:	Referral to Regional Board

Global Id:	T0607135690
Action Type:	ENFORCEMENT
Date:	12/26/2001
Action:	Site Visit / Inspection / Sampling

Global Id:	T0607135690
Action Type:	ENFORCEMENT

ARCO #1569 (FORMER) (Continued) **S105850454**

Date: 07/09/2009
Action: Letter - Notice

Global Id: T0607135690
Action Type: ENFORCEMENT
Date: 07/16/2010
Action: Staff Letter

Global Id: T0607135690
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

Global Id: T0607135690
Action Type: RESPONSE
Date: 01/04/2002
Action: Tank Removal Report / UST Sampling Report

Global Id: T0607135690
Action Type: ENFORCEMENT
Date: 09/25/2009
Action: Staff Letter

Global Id: T0607135690
Action Type: ENFORCEMENT
Date: 03/23/2011
Action: Referral to Regional Board

Global Id: T0607135690
Action Type: RESPONSE
Date: 07/19/2011
Action: Verbal Communication

Global Id: T0607135690
Action Type: RESPONSE
Date: 08/03/2011
Action: Verbal Communication

Global Id: T0607135690
Action Type: RESPONSE
Date: 03/31/2012
Action: Site Assessment Report

Global Id: T0607135690
Action Type: RESPONSE
Date: 10/31/2011
Action: Remedial Progress Report

Global Id: T0607135690
Action Type: RESPONSE
Date: 07/24/2012
Action: Verbal Communication

Global Id: T0607135690
Action Type: ENFORCEMENT
Date: 12/22/2011
Action: Technical Correspondence / Assistance / Other

ARCO #1569 (FORMER) (Continued) **S105850454**

Global Id: T0607135690
Action Type: RESPONSE
Date: 06/29/2010
Action: Correspondence

Global Id: T0607135690
Action Type: RESPONSE
Date: 08/30/2012
Action: Other Report / Document

Global Id: T0607135690
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

Global Id: T0607135690
Action Type: ENFORCEMENT
Date: 08/02/2011
Action: Technical Correspondence / Assistance / Other

Global Id: T0607135690
Action Type: ENFORCEMENT
Date: 08/06/2010
Action: Letter - Notice

Global Id: T0607135690
Action Type: ENFORCEMENT
Date: 11/02/2010
Action: Notification - Public Notice of ROD/RAP/CAP

Global Id: T0607135690
Action Type: ENFORCEMENT
Date: 09/18/2008
Action: Staff Letter

Global Id: T0607135690
Action Type: ENFORCEMENT
Date: 01/12/2009
Action: Staff Letter

Global Id: T0607135690
Action Type: REMEDIATION
Date: 01/01/1950
Action: Soil Vapor Extraction (SVE)

Global Id: T0607135690
Action Type: REMEDIATION
Date: 01/01/1950
Action: Soil Vapor Extraction (SVE)

Global Id: T0607135690
Action Type: ENFORCEMENT
Date: 08/04/2011
Action: Technical Correspondence / Assistance / Other

Global Id: T0607135690
Action Type: ENFORCEMENT

ARCO #1569 (FORMER) (Continued) **S105850454**

Date: 07/24/2012
Action: Technical Correspondence / Assistance / Other

Global Id: T0607135690
Action Type: ENFORCEMENT
Date: 06/06/2012
Action: Technical Correspondence / Assistance / Other

Global Id: T0607135690
Action Type: ENFORCEMENT
Date: 10/24/2012
Action: File review

LUST REG 8:
Region: 8
County: San Bernardino
Regional Board: Santa Ana Region
Facility Status: Pollution Characterization
Case Number: Not reported
Local Case Num: 2002003
Case Type: Aquifer affected
Substance: Gasoline
Qty Leaked: Not reported
Abate Method: Not reported
Cross Street: RANCHO AVENUE
Enf Type: Not reported
Funding: Not reported
How Discovered: Tank Closure
How Stopped: Close Tank
Leak Cause: UNK
Leak Source: UNK
Global ID: T0607135690
How Stopped Date: 12/20/2001
Enter Date: Not reported
Review Date: Not reported
Prelim Assess: Not reported
Discover Date: 12/20/2001
Enforcement Date: Not reported
Close Date: Not reported
Workplan: Not reported
Pollution Char: 1/10/2002
Remed Plan: Not reported
Remed Action: Not reported
Monitoring: Not reported
Enter Date: Not reported
GW Qualifies: =
Soil Qualifies: =
Operator: Not reported
Facility Contact: Not reported
Interim: Not reported
Oversite Program: LUST
Latitude: 0
Longitude: 0
MTBE Date: 11/12/2002
Max MTBE GW: 2100
MTBE Concentration: 0

ARCO #1569 (FORMER) (Continued) **S105850454**

Max MTBE Soil:	62000
MTBE Fuel:	1
MTBE Tested:	MTBE Detected. Site tested for MTBE & MTBE detected
MTBE Class:	*
Staff:	VJJ
Staff Initials:	LH6
Lead Agency:	Local Agency
Local Agency:	36000L
Hydr Basin #:	Not reported
Beneficial:	Not reported
Priority:	Not reported
Cleanup Fund Id:	Not reported
Work Suspended:	Not reported
Summary:	Not reported

AR379 **PRESTIGE STATIONS INC NO 0781** **RCRA NonGen / NLR** **1004677901**
ESE **792 W VALLEY BLVD** **FINDS** **CAR000102806**
1/2-1 **COLTON, CA 92324**
0.520 mi.
2748 ft. **Site 3 of 7 in cluster AR**

Relative:
Lower

Actual:
1007 ft.

RCRA NonGen / NLR:

Date form received by agency:	07/19/2002
Facility name:	PRESTIGE STATIONS INC NO 0781
Facility address:	792 W VALLEY BLVD COLTON, CA 92324
EPA ID:	CAR000102806
Mailing address:	P O BOX 6038 ARTESIA, CA 907026038
Contact:	SHARON ZUNIGA
Contact address:	25422 TRABUCO RD NO 105 LAKE FOREST, CA 926302797
Contact country:	US
Contact telephone:	(949) 450-1010
Contact email:	Not reported
EPA Region:	09
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	ARCO PRODUCTS COMPANY
Owner/operator address:	P O BOX 6038 ARTESIA, CA 90702
Owner/operator country:	Not reported
Owner/operator telephone:	(714) 670-5402
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No

PRESTIGE STATIONS INC NO 0781 (Continued) **1004677901**

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Hazardous Waste Summary:
Waste code: D000
Waste name: Not Defined

Waste code: D018
Waste name: BENZENE

Violation Status: No violations found

FINDS:

Registry ID: 110012215762

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

AR380 **ARCO PETROLEUM PROD #1569** **UST** **U003938000**
ESE **792 W VALLEY BLVD** **N/A**
1/2-1 **COLTON, CA 92324**
0.520 mi.
2748 ft. **Site 4 of 7 in cluster AR**

Relative:
Lower

Actual:
1007 ft.

UST:
Facility ID: 85007474
Latitude: 34.0685
Longitude: -117.33541

AR381 **BALTAZAR CERVANTES** **LUST** **U001574639**
ESE **792 W VALLEY BLVD** **HIST UST** **N/A**
1/2-1 **COLTON, CA 92324** **SWEEPS UST**
0.520 mi.
2748 ft. **Site 5 of 7 in cluster AR**

Relative:
Lower

Actual:
1007 ft.

LUST:
Region: STATE
Global Id: T0607100105
Latitude: 34.0684805
Longitude: -117.3357057
Case Type: LUST Cleanup Site
Status: Completed - Case Closed

BALTAZAR CERVANTES (Continued) **U001574639**

Status Date:	05/11/1994
Lead Agency:	SAN BERNARDINO COUNTY
Case Worker:	LH6
Local Agency:	Not reported
RB Case Number:	083600976T
LOC Case Number:	90122
File Location:	Local Agency
Potential Media Affect:	Aquifer used for drinking water supply
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607100105
Contact Type:	Regional Board Caseworker
Contact Name:	VALERIE JAHN-BULL
Organization Name:	SANTA ANA RWQCB (REGION 8)
Address:	3737 MAIN STREET, SUITE 500
City:	RIVERSIDE
Email:	vjahn-bull@waterboards.ca.gov
Phone Number:	9517824903

Regulatory Activities:

Global Id:	T0607100105
Action Type:	Other
Date:	01/01/1950
Action:	Leak Stopped

Global Id:	T0607100105
Action Type:	Other
Date:	01/01/1950
Action:	Leak Discovery

Global Id:	T0607100105
Action Type:	Other
Date:	01/01/1950
Action:	Leak Reported

HIST UST:

Region:	STATE
Facility ID:	00000026580
Facility Type:	Gas Station
Other Type:	Not reported
Total Tanks:	0004
Contact Name:	Not reported
Telephone:	0000000000
Owner Name:	ARCO PETROLEUM PRODUCTS CO.
Owner Address:	515 SOUTH FLOWER STREET
Owner City,St,Zip:	LOS ANGELES, CA 90071

Tank Num:	001
Container Num:	0000000001
Year Installed:	1974
Tank Capacity:	00010000
Tank Used for:	PRODUCT

BALTAZAR CERVANTES (Continued) **U001574639**

Type of Fuel: 06
Tank Construction: Not reported
Leak Detection: Stock Inventor, 10

Tank Num: 002
Container Num: 0000000002
Year Installed: 1964
Tank Capacity: 00006000
Tank Used for: PRODUCT
Type of Fuel: 06
Tank Construction: 0000240 inches
Leak Detection: Stock Inventor, 10

Tank Num: 003
Container Num: 0000000003
Year Installed: 1964
Tank Capacity: 00006000
Tank Used for: PRODUCT
Type of Fuel: 06
Tank Construction: 0000240 inches
Leak Detection: Stock Inventor, 10

Tank Num: 004
Container Num: 0000000004
Year Installed: 1964
Tank Capacity: 00006000
Tank Used for: PRODUCT
Type of Fuel: 06
Tank Construction: 0000240 inches
Leak Detection: Stock Inventor, 10

SWEEPS UST:
Status: Active
Comp Number: 7474
Number: 1
Board Of Equalization: 44-000506
Referral Date: 07-28-92
Action Date: 07-28-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 1
Swrcb Tank Id: 36-000-007474-000001
Actv Date: 08-03-89
Capacity: 12000
Tank Use: M.V. FUEL
Stg: P
Content: LEADED
Number Of Tanks: 3

Status: Active
Comp Number: 7474
Number: 1
Board Of Equalization: 44-000506
Referral Date: 07-28-92
Action Date: 07-28-92
Created Date: 02-29-88
Tank Status: A

BALTAZAR CERVANTES (Continued) **U001574639**

Owner Tank Id: 3
Swrcb Tank Id: 36-000-007474-000003
Actv Date: 08-03-89
Capacity: 12000
Tank Use: M.V. FUEL
Stg: P
Content: REG UNLEADED
Number Of Tanks: Not reported

Status: Active
Comp Number: 7474
Number: 1
Board Of Equalization: 44-000506
Referral Date: 07-28-92
Action Date: 07-28-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 4
Swrcb Tank Id: 36-000-007474-000004
Actv Date: 08-03-89
Capacity: 12000
Tank Use: M.V. FUEL
Stg: P
Content: REG UNLEADED
Number Of Tanks: Not reported

Status: Not reported
Comp Number: 7474
Number: Not reported
Board Of Equalization: 44-000506
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 36-000-007474-000002
Actv Date: Not reported
Capacity: 10000
Tank Use: M.V. FUEL
Stg: PRODUCT
Content: LEADED
Number Of Tanks: 1

AT382 **STOROS, WALTER** **SWEEPS UST** **S106932631**
East **801 N RANCHO** **N/A**
1/2-1 **COLTON, CA 92324**
0.527 mi.
2782 ft. **Site 2 of 3 in cluster AT**

Relative:
Lower

Actual:
1036 ft.

SWEEPS UST:
Status: Active
Comp Number: 10206
Number: 2
Board Of Equalization: 44-020248
Referral Date: 03-24-92
Action Date: 03-24-92
Created Date: 09-15-88
Tank Status: A

STOROS, WALTER (Continued) **S106932631**

Owner Tank Id:	Not reported
Swrcb Tank Id:	36-000-010206-000001
Actv Date:	09-15-88
Capacity:	1
Tank Use:	UNKNOWN
Stg:	P
Content:	UNKNOWN
Number Of Tanks:	1

AR383 **ARCO #1569** **HIST CORTESE** **S103943718**
ESE **792 VALLEY** **LUST** **N/A**
1/2-1 **COLTON, CA 92324**
0.527 mi.
2785 ft. **Site 6 of 7 in cluster AR**

Relative:
Lower

Actual:
1007 ft.

CORTESE:

Region:	CORTESE
Facility County Code:	36
Reg By:	LTNKA
Reg Id:	083600976T

LUST REG 8:

Region:	8
County:	San Bernardino
Regional Board:	Santa Ana Region
Facility Status:	Case Closed
Case Number:	083600976T
Local Case Num:	90122
Case Type:	Aquifer affected
Substance:	Gasoline
Qty Leaked:	Not reported
Abate Method:	Vapor Extraction
Cross Street:	RANCHO
Enf Type:	Not reported
Funding:	Not reported
How Discovered:	OM
How Stopped:	Not reported
Leak Cause:	Other Cause
Leak Source:	Other Source
Global ID:	T0607100105
How Stopped Date:	5/1/1988
Enter Date:	8/1/1988
Review Date:	5/1/1988
Prelim Assess:	Not reported
Discover Date:	5/1/1988
Enforcement Date:	Not reported
Close Date:	5/11/1994
Workplan:	5/4/1988
Pollution Char:	Not reported
Remed Plan:	Not reported
Remed Action:	Not reported
Monitoring:	Not reported
Enter Date:	8/1/1988
GW Qualifies:	Not reported
Soil Qualifies:	Not reported
Operator:	Not reported
Facility Contact:	Not reported

ARCO #1569 (Continued) **S103943718**

Interim:	Not reported
Oversite Program:	LUST
Latitude:	34.0684187
Longitude:	-117.3356656
MTBE Date:	Not reported
Max MTBE GW:	Not reported
MTBE Concentration:	0
Max MTBE Soil:	Not reported
MTBE Fuel:	1
MTBE Tested:	Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.
MTBE Class:	*
Staff:	VJJ
Staff Initials:	LH6
Lead Agency:	Local Agency
Local Agency:	36000L
Hydr Basin #:	UPPER SANTA ANA VALL
Beneficial:	Not reported
Priority:	Not reported
Cleanup Fund Id:	Not reported
Work Suspended:	Not reported
Summary:	ANOTHER TANK REMOVAL SHOWED LEAK (08/09/91)

AT384 **EDR US Hist Cleaners** **1015101706**
East **859 N RANCHO AVE** **N/A**
1/2-1 **COLTON, CA 92324**
0.531 mi.
2803 ft. **Site 3 of 3 in cluster AT**

Relative:
Lower

Actual:
1038 ft.

EDR Historical Cleaners:

Name:	WESTLAND COIN LAUNDRY
Year:	1999
Address:	859 N RANCHO AVE
Name:	WESTLAND COIN LAUNDRY
Year:	2000
Address:	859 N RANCHO AVE
Name:	WESTLAND COIN LAUNDRY
Year:	2001
Address:	859 N RANCHO AVE
Name:	WESTLAND COIN LAUNDRY
Year:	2002
Address:	859 N RANCHO AVE
Name:	WESTLAND COIN LAUNDRY
Year:	2003
Address:	859 N RANCHO AVE
Name:	WESTLAND COIN LAUNDRY
Year:	2004
Address:	859 N RANCHO AVE
Name:	WESTLAND COIN LAUNDRY
Year:	2005
Address:	859 N RANCHO AVE
Name:	WESTLAND COIN LAUNDRY

(Continued) **1015101706**

Year: 2006
Address: 859 N RANCHO AVE

Name: WESTLAND COIN LAUNDRY
Year: 2007
Address: 859 N RANCHO AVE

Name: WESTLAND COIN LAUNDRY
Year: 2008
Address: 859 N RANCHO AVE

Name: RANCHO COIN LAUNDRY
Year: 2011
Address: 859 N RANCHO AVE

Name: RANCHO COIN LAUNDRY
Year: 2012
Address: 859 N RANCHO AVE

AV385 **DOLLAR GENERAL #13460** **San Bern. Co. Permit** **S111854475**
East **869 N RANCHO AVE** **N/A**
1/2-1 **COLTON, CA 92324**
0.532 mi.
2808 ft. **Site 1 of 2 in cluster AV**

Relative:
Lower

Actual:
1038 ft.

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0014655
Owner: DOLGEN CALIFORNIA LLC
Permit Number: PT0025601
Permit Category: CONDITIONALLY EXEMPT SMALL QUANTITY GENERATOR
Facility Status: ACTIVE
Expiration Date: 08/31/2013

AV386 **PONCE RECYCLING** **SWRCY** **S109612819**
East **875 N RANCHO AVE** **N/A**
1/2-1 **COLTON, CA 92324**
0.532 mi.
2811 ft. **Site 2 of 2 in cluster AV**

Relative:
Lower

Actual:
1039 ft.

SWRCY:
Reg Id: 39722
Cert Id: RC14359
Org Or Agency Reg Id: 39719
Organization Or Agency Name: Ponce Recycling Inc
Mailing Address: 5425 W 64th St
Mailing City: Los Angeles
Mailing State: CA
Mailing Zip Code: 90056
Website: Not reported
Email: Not reported
Phone Number: (323) 533-4862
Grand Father: N
Rural: N
Operation Begin Date: 07/01/2009
Aluminium: Y

PONCE RECYCLING (Continued) **S109612819**

Glass:	Y
Plastic:	Y
Bimetal:	Y
Agency:	N/A
Monday Hours Of Operation:	9:00 am - 5:00 pm
Tuesday Hours Of Operation:	9:00 am - 5:00 pm
Wednesday Hours Of Operation:	9:00 am - 5:00 pm
Thursday Hours Of Operation:	9:00 am - 5:00 pm
Friday Hours Of Operation:	9:00 am - 5:00 pm
Saturday Hours Of Operation:	9:00 am - 5:00 pm
Sunday Hours Of Operation:	9:00 am - 5:00 pm

AR387 **COLTON UNIFIED SCHOOL DISTRICT** **LUST** **S104160684**
ESE **777 VALLEY BLVD** **N/A**
1/2-1 **COLTON, CA 92324**
0.536 mi.
2830 ft. **Site 7 of 7 in cluster AR**

Relative:
Lower

Actual:
1007 ft.

LUST REG 8:

Region:	8
County:	San Bernardino
Regional Board:	Santa Ana Region
Facility Status:	Case Closed
Case Number:	083602538T
Local Case Num:	94047
Case Type:	Soil only
Substance:	Diesel
Qty Leaked:	Not reported
Abate Method:	Not reported
Cross Street:	THIRD STREET
Enf Type:	CLOS
Funding:	Not reported
How Discovered:	Tank Closure
How Stopped:	Not reported
Leak Cause:	UNK
Leak Source:	UNK
Global ID:	T0607100346
How Stopped Date:	8/2/1994
Enter Date:	11/18/1994
Review Date:	8/12/1994
Prelim Assess:	2/5/1996
Discover Date:	8/2/1994
Enforcement Date:	Not reported
Close Date:	7/3/1997
Workplan:	Not reported
Pollution Char:	11/10/1994
Remed Plan:	2/5/1996
Remed Action:	2/5/1996
Monitoring:	Not reported
Enter Date:	11/18/1994
GW Qualifies:	Not reported
Soil Qualifies:	Not reported
Operator:	Not reported
Facility Contact:	Not reported
Interim:	Not reported
Oversite Program:	LUST
Latitude:	34.0685467
Longitude:	-117.3348186

COLTON UNIFIED SCHOOL DISTRICT (Continued) **S104160684**

MTBE Date: Not reported
Max MTBE GW: Not reported
MTBE Concentration: 1
Max MTBE Soil: Not reported
MTBE Fuel: 0
MTBE Tested: MTBE Detected. Site tested for MTBE & MTBE detected
MTBE Class: *
Staff: VJJ
Staff Initials: JC3
Lead Agency: Local Agency
Local Agency: 36000L
Hydr Basin #: UPPER SANTA ANA VALL
Beneficial: Not reported
Priority: Not reported
Cleanup Fund Id: Not reported
Work Suspended: Not reported
Summary: BIOVENTING

AW388 **SC-COLTON USD/TRANS** **UST** **U003785146**
ESE **777 W VALLEY BLVD** **N/A**
1/2-1 **COLTON, CA 92324**
0.559 mi.
2951 ft. **Site 1 of 4 in cluster AW**

Relative:
Lower

Actual:
1005 ft.

UST:
Facility ID: 89019190
Latitude: 34.0685
Longitude: -117.3352

AW389 **COLTON HIGH SCHOOL (BUS GARAGE** **HIST UST** **U001574655**
ESE **777 W VALLEY BLVD** **SWEEPS UST** **N/A**
1/2-1 **COLTON, CA 92324**
0.559 mi.
2951 ft. **Site 2 of 4 in cluster AW**

Relative:
Lower

Actual:
1005 ft.

HIST UST:
Region: STATE
Facility ID: 00000061053
Facility Type: Other
Other Type: SCHOOL DISTRICT
Total Tanks: 0004
Contact Name: AMOS KENT
Telephone: 7148244119
Owner Name: COLTON JOINT UNIFIED SCHOOL DI
Owner Address: 1212 VALENCIA
Owner City,St,Zip: COLTON, CA 92324

Tank Num: 001
Container Num: 1
Year Installed: Not reported
Tank Capacity: 00006000
Tank Used for: PRODUCT
Type of Fuel: UNLEADED
Tank Construction: Not reported
Leak Detection: None

COLTON HIGH SCHOOL (BUS GARAGE (Continued) **U001574655**

Tank Num: 002
Container Num: 2
Year Installed: Not reported
Tank Capacity: 00010000
Tank Used for: PRODUCT
Type of Fuel: PREMIUM
Tank Construction: Not reported
Leak Detection: None

Tank Num: 003
Container Num: 3
Year Installed: Not reported
Tank Capacity: 00010000
Tank Used for: PRODUCT
Type of Fuel: DIESEL
Tank Construction: Not reported
Leak Detection: None

Tank Num: 004
Container Num: 4
Year Installed: 1983
Tank Capacity: 00000550
Tank Used for: WASTE
Type of Fuel: WASTE OIL
Tank Construction: Not reported
Leak Detection: None

SWEEPS UST:
Status: Active
Comp Number: 61053
Number: 4
Board Of Equalization: 44-021311
Referral Date: 08-28-91
Action Date: 08-28-91
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 1
Swrcb Tank Id: 36-000-061053-000001
Actv Date: 07-07-88
Capacity: 6000
Tank Use: M.V. FUEL
Stg: P
Content: REG UNLEADED
Number Of Tanks: 4

Status: Active
Comp Number: 61053
Number: 4
Board Of Equalization: 44-021311
Referral Date: 08-28-91
Action Date: 08-28-91
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 2
Swrcb Tank Id: 36-000-061053-000002
Actv Date: 07-07-88
Capacity: 10000

COLTON HIGH SCHOOL (BUS GARAGE (Continued) **U001574655**

Tank Use: M.V. FUEL
Stg: P
Content: REG UNLEADED
Number Of Tanks: Not reported

Status: Active
Comp Number: 61053
Number: 4
Board Of Equalization: 44-021311
Referral Date: 08-28-91
Action Date: 08-28-91
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 3
Swrcb Tank Id: 36-000-061053-000003
Actv Date: 07-07-88
Capacity: 10000
Tank Use: M.V. FUEL
Stg: P
Content: DIESEL
Number Of Tanks: Not reported

Status: Active
Comp Number: 61053
Number: 4
Board Of Equalization: 44-021311
Referral Date: 08-28-91
Action Date: 08-28-91
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 4
Swrcb Tank Id: 36-000-061053-000004
Actv Date: 07-07-88
Capacity: 550
Tank Use: OIL
Stg: W
Content: WASTE OIL
Number Of Tanks: Not reported

AW390 **COLTON HIGH SCHOOL** **LUST** **S102038874**
ESE **777 W VALLEY BLVD** **San Bern. Co. Permit** **N/A**
1/2-1 **COLTON, CA 92324**
0.559 mi.
2951 ft. **Site 3 of 4 in cluster AW**

Relative:
Lower

Actual:
1005 ft.

LUST:
Region: STATE
Global Id: T0607100346
Latitude: 34.0685483
Longitude: -117.3351811
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 07/03/1997
Lead Agency: SAN BERNARDINO COUNTY
Case Worker: JC
Local Agency: SAN BERNARDINO COUNTY
RB Case Number: 083602538T
LOC Case Number: 94047

COLTON HIGH SCHOOL (Continued) **S102038874**

File Location: Local Agency
Potential Media Affect: Soil
Potential Contaminants of Concern: Diesel
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0607100346
Contact Type: Local Agency Caseworker
Contact Name: JACKSON CRUTSINGER
Organization Name: SAN BERNARDINO COUNTY
Address: 620 SOUTH E STREET
City: SAN BERNARDINO
Email: jcrutsinger@sbcfire.org
Phone Number: Not reported

Global Id: T0607100346
Contact Type: Regional Board Caseworker
Contact Name: VALERIE JAHN-BULL
Organization Name: SANTA ANA RWQCB (REGION 8)
Address: 3737 MAIN STREET, SUITE 500
City: RIVERSIDE
Email: vjahn-bull@waterboards.ca.gov
Phone Number: 9517824903

Regulatory Activities:
Global Id: T0607100346
Action Type: Other
Date: 01/01/1950
Action: Leak Stopped

Global Id: T0607100346
Action Type: RESPONSE
Date: 02/05/1996
Action: Remedial Progress Report

Global Id: T0607100346
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

Global Id: T0607100346
Action Type: RESPONSE
Date: 02/05/1996
Action: Preliminary Site Assessment Report

Global Id: T0607100346
Action Type: RESPONSE
Date: 02/05/1996
Action: CAP/RAP - Final Remediation / Design Plan

Global Id: T0607100346
Action Type: RESPONSE
Date: 08/18/1994
Action: Unauthorized Release Form

COLTON HIGH SCHOOL (Continued) **S102038874**

Global Id: T0607100346
Action Type: ENFORCEMENT
Date: 08/16/1994
Action: Notice of Responsibility

Global Id: T0607100346
Action Type: ENFORCEMENT
Date: 05/27/1997
Action: Technical Correspondence / Assistance / Other

Global Id: T0607100346
Action Type: ENFORCEMENT
Date: 02/05/1996
Action: * No Action

Global Id: T0607100346
Action Type: REMEDIATION
Date: 01/01/1950
Action: Other (Use Description Field)

Global Id: T0607100346
Action Type: ENFORCEMENT
Date: 07/03/1997
Action: Closure/No Further Action Letter

Global Id: T0607100346
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0005965
Owner: COLTON JOINT USD
Permit Number: PT0002892
Permit Category: HAZARDOUS WASTE GENERATOR - 0-10 EMPLOYEES
Facility Status: ACTIVE
Expiration Date: 05/31/2013

Region: SAN BERNARDINO
Facility ID: FA0005965
Owner: COLTON JOINT USD
Permit Number: PT0023832
Permit Category: UW HANDLER W/ ANOTHER HAZ WASTE GENERATOR FEE
Facility Status: ACTIVE
Expiration Date: 05/31/2013

Region: SAN BERNARDINO
Facility ID: FA0005965
Owner: COLTON JOINT USD
Permit Number: PT0002893
Permit Category: HAZMAT HANDLER 0-10 EMPLOYEES (W/GEN PRMT)
Facility Status: ACTIVE
Expiration Date: 05/31/2013

AX391 **TEXACO USA-COLTON TERMINAL** **LUST** **1006093827**
SW **2237 S RIVERSIDE AVE** **SWEEPS UST** **N/A**
1/2-1 **BLOOMINGTON, CA 92316** **San Bern. Co. Permit**
0.562 mi. **EMI**
2968 ft. **Site 1 of 30 in cluster AX** **WDS**

Relative:
Lower

Actual:
1010 ft.

LUST:

Region:	STATE
Global Id:	T0607100567
Latitude:	34.0608105
Longitude:	-117.3702318
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	01/24/2008
Lead Agency:	SAN BERNARDINO COUNTY
Case Worker:	CR2
Local Agency:	SAN BERNARDINO COUNTY
RB Case Number:	083603436T
LOC Case Number:	99057
File Location:	Local Agency
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607100567
Contact Type:	Local Agency Caseworker
Contact Name:	CATHERINE RICHARDS
Organization Name:	SAN BERNARDINO COUNTY
Address:	620 SOUTH E STREET
City:	SAN BERNARDINO
Email:	crichards@sbcfire.org
Phone Number:	9093868419

Global Id:	T0607100567
Contact Type:	Regional Board Caseworker
Contact Name:	ROSE SCOTT
Organization Name:	SANTA ANA RWQCB (REGION 8)
Address:	3737 MAIN STREET, SUITE 500
City:	RIVERSIDE
Email:	rscott@waterboards.ca.gov
Phone Number:	9513206375

Regulatory Activities:

Global Id:	T0607100567
Action Type:	Other
Date:	01/01/1950
Action:	Leak Discovery

Global Id:	T0607100567
Action Type:	Other
Date:	01/01/1950
Action:	Leak Reported

Global Id:	T0607100567
Action Type:	REMEDIATION
Date:	01/01/1950

TEXACO USA-COLTON TERMINAL (Continued) **1006093827**

Action: Excavation

SWEEPS UST:
Status: Active
Comp Number: 33316
Number: 9
Board Of Equalization: 44-020891
Referral Date: 03-19-92
Action Date: 03-19-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 300
Swrcb Tank Id: 36-000-033316-000001
Actv Date: 08-22-88
Capacity: 8136
Tank Use: UNKNOWN
Stg: W
Content: Not reported
Number Of Tanks: 2

Status: Active
Comp Number: 33316
Number: 9
Board Of Equalization: 44-020891
Referral Date: 03-19-92
Action Date: 03-19-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 700
Swrcb Tank Id: 36-000-033316-000003
Actv Date: 08-22-88
Capacity: 10000
Tank Use: M.V. FUEL
Stg: P
Content: REG UNLEADED
Number Of Tanks: Not reported

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0002932
Owner: SHELL OIL PRODUCTS, US.
Permit Number: PT0001496
Permit Category: HAZARDOUS WASTE GENERATOR - 0-10 EMPLOYEES
Facility Status: INACTIVE
Expiration Date: 07/31/2004

Region: SAN BERNARDINO
Facility ID: FA0002932
Owner: SHELL OIL PRODUCTS, US.
Permit Number: PT0010547
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: INACTIVE
Expiration Date: 07/31/2004

Region: SAN BERNARDINO

TEXACO USA-COLTON TERMINAL (Continued) **1006093827**

Facility ID: FA0002932
Owner: SHELL OIL PRODUCTS, US.
Permit Number: PT0001497
Permit Category: HAZMAT HANDLER 0-10 EMPLOYEES (W/GEN PRMT)
Facility Status: INACTIVE
Expiration Date: 07/31/2004

Region: SAN BERNARDINO
Facility ID: FA0002932
Owner: SHELL OIL PRODUCTS, US.
Permit Number: PT0001498
Permit Category: ABOVEGROUND PETROLEUM STORAGE (AST) (SPCC)
Facility Status: INACTIVE
Expiration Date: 07/31/2004

EMI:

Year:	1987
County Code:	36
Air Basin:	SC
Facility ID:	46638
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	30
Reactive Organic Gases Tons/Yr:	30
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1990
County Code:	36
Air Basin:	SC
Facility ID:	46638
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	13
Reactive Organic Gases Tons/Yr:	12
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1995
County Code:	36
Air Basin:	SC
Facility ID:	46638
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD

TEXACO USA-COLTON TERMINAL (Continued) **1006093827**

Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	11
Reactive Organic Gases Tons/Yr:	9
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1996
County Code:	36
Air Basin:	SC
Facility ID:	46638
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	2002
County Code:	36
Air Basin:	SC
Facility ID:	116868
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	10
Reactive Organic Gases Tons/Yr:	9
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	2003
County Code:	36
Air Basin:	SC
Facility ID:	116868
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	10
Reactive Organic Gases Tons/Yr:	9
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0

TEXACO USA-COLTON TERMINAL (Continued) **1006093827**

SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0
Year:	2004
County Code:	36
Air Basin:	SC
Facility ID:	116868
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Y
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	10.36235
Reactive Organic Gases Tons/Yr:	9.38
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

CA WDS:

Facility ID:	Santa Ana River 36I014498
Facility Type:	Industrial - Facility that treats and/or disposes of liquid or semisolid wastes from any servicing, producing, manufacturing or processing operation of whatever nature, including mining, gravel washing, geothermal operations, air conditioning, ship building and repairing, oil production, storage and disposal operations, water pumping.
Facility Status:	Active - Any facility with a continuous or seasonal discharge that is under Waste Discharge Requirements.
NPDES Number:	CAS000001 The 1st 2 characters designate the state. The remaining 7 are assigned by the Regional Board
Subregion:	8
Facility Telephone:	9098773511
Facility Contact:	PATRICIA J JOHNSON
Agency Name:	SHELL OIL PRODUCTS - BLOOMINGT
Agency Address:	2307 S Riverside Ave
Agency City,St,Zip:	Bloomington 923162931
Agency Contact:	MEREDITH JOHNSON
Agency Telephone:	9098773511
Agency Type:	Private
SIC Code:	0
SIC Code 2:	Not reported
Primary Waste:	Not reported
Primary Waste Type:	Not reported
Secondary Waste:	Not reported
Secondary Waste Type:	Not reported
Design Flow:	0
Baseline Flow:	0
Reclamation:	Not reported
POTW:	Not reported
Treat To Water:	Minor Threat to Water Quality. A violation of a regional board order should cause a relatively minor impairment of beneficial uses compared to a major or minor threat. Not: All nurds without a TTWQ will be considered a minor threat to water quality unless coded at a higher Level. A Zero (0) may be used to code those NURDS that are found to

TEXACO USA-COLTON TERMINAL (Continued) **1006093827**

represent no threat to water quality.

Complexity: Category C - Facilities having no waste treatment systems, such as cooling water dischargers or thosewho must comply through best management practices, facilities with passive waste treatment and disposal systems, such as septic systems with subsurface disposal, or dischargers having waste storage systems with land disposal such as dairy waste ponds.

AX392 **EQUILON RIALTO TERMINAL** **RCRA-SQG** **1000144769**
SW **2237 S. RIVERSIDE AVE.** **FINDS** **CAD000626044**
1/2-1 **BLOOMINGTON, CA 92316**
0.562 mi.
2968 ft. **Site 2 of 30 in cluster AX**

Relative:
Lower

Actual:
1010 ft.

RCRA-SQG:

Date form received by agency:	02/19/2004
Facility name:	SHELL OIL PRODUCTS US-RIALTO TERMINAL
Facility address:	2237 S. RIVERSIDE AVENUE BLOOMINGTON, CA 92316
EPA ID:	CAD000626044
Mailing address:	P. O. BOX 2648, TSP1505A HOUSTON, TX 772522648
Contact:	SONDRA E BIENVENU
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(713) 241-5036
Contact email:	SEBIENVENU@SHELLOPUS.COM
EPA Region:	09
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	TEXACO USA
Owner/operator address:	3350 WILSHIRE BLVD PO BOX 3756 CITY NOT REPORTED, CA 99999
Owner/operator country:	Not reported
Owner/operator telephone:	(213) 385-0515
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	EQUILON ENTERPRISES LLC DBA SHELL OIL PR
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	07/01/1998
Owner/Op end date:	Not reported

EQUILON RIALTO TERMINAL (Continued) **1000144769**

Owner/operator name: EQUILON ENTERPRISES L L C
Owner/operator address: P O BOX 2648
HOUSTON, TX 77252
Owner/operator country: Not reported
Owner/operator telephone: (713) 241-5036
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/01/0001
Owner/Op end date: Not reported

Owner/operator name: EQUILON ENTERPRISES LLC DBA SHELL OIL PR
Owner/operator address: P. O. BOX 2648
HOUSTON, TX 77252
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 07/01/1998
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/19/2004
Facility name: SHELL OIL PRODUCTS US-RIALTO TERMINAL
Classification: Small Quantity Generator

Date form received by agency: 10/16/2002
Facility name: SHELL OIL PRODUCTS US-RIALTO TERMINAL
Site name: RIALTO TERMINAL
Classification: Not a generator, verified

Date form received by agency: 10/12/2000
Facility name: SHELL OIL PRODUCTS US-RIALTO TERMINAL
Site name: EQUILON ENTERPRISES LLC/RIALTO TERMINAL
Classification: Large Quantity Generator

Date form received by agency: 03/04/1999
Facility name: SHELL OIL PRODUCTS US-RIALTO TERMINAL
Site name: TEXACO COLTON SALES TERMINAL
Classification: Large Quantity Generator

EQUILON RIALTO TERMINAL (Continued) **1000144769**

Date form received by agency: 09/01/1996
Facility name: SHELL OIL PRODUCTS US-RIALTO TERMINAL
Site name: RIALTO TERMINAL
Classification: Large Quantity Generator

Date form received by agency: 02/29/1996
Facility name: SHELL OIL PRODUCTS US-RIALTO TERMINAL
Site name: TEXACO REFINING AND MARKETING, INC.
Classification: Large Quantity Generator

Date form received by agency: 04/11/1994
Facility name: SHELL OIL PRODUCTS US-RIALTO TERMINAL
Site name: TEXACO REFINING AND MARKETING, INC
Classification: Large Quantity Generator

Date form received by agency: 02/28/1992
Facility name: SHELL OIL PRODUCTS US-RIALTO TERMINAL
Site name: TEXACO REFINING AND MARKETING COLTON SAL
Classification: Large Quantity Generator

Hazardous Waste Summary:
Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D018
Waste name: BENZENE

Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D018
Waste name: BENZENE

Violation Status: No violations found

FINDS:

Registry ID: 110000744099

Environmental Interest/Information System
The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

US EPA TRIS (Toxics Release Inventory System) contains information

EQUILON RIALTO TERMINAL (Continued) **1000144769**

from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.

California Hazardous Waste Tracking System - Datamart (HWTS-DATAMART) provides California with information on hazardous waste shipments for generators, transporters, and treatment, storage, and disposal facilities.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

CRITERIA AND HAZARDOUS AIR POLLUTANT INVENTORY

AX393 **COLTON SALES TERMINAL** **HIST UST** **U001574567**
SW **2237 S. RIVERSIDE AVE.** **N/A**
1/2-1 **RIALTO, CA 92316**
0.562 mi.
2968 ft. **Site 3 of 30 in cluster AX**

Relative:
Lower

Actual:
1010 ft.

HIST UST:

Region:	STATE
Facility ID:	00000033316
Facility Type:	Other
Other Type:	PETROLEUM PRODUCTS
Total Tanks:	0003
Contact Name:	B.K. HOWELL
Telephone:	7148773511
Owner Name:	TEXACO USA
Owner Address:	P.O. BOX 3756-3350 WILSHIRE BL
Owner City,St,Zip:	LOS ANGELES, CA 90010
Tank Num:	001
Container Num:	300
Year Installed:	Not reported
Tank Capacity:	00008136
Tank Used for:	WASTE
Type of Fuel:	Not reported
Tank Construction:	Not reported
Leak Detection:	Stock Inventor
Tank Num:	002
Container Num:	500
Year Installed:	Not reported
Tank Capacity:	00002011
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Tank Construction:	Not reported
Leak Detection:	Stock Inventor
Tank Num:	003

COLTON SALES TERMINAL (Continued) **U001574567**

Container Num: 700
Year Installed: Not reported
Tank Capacity: 00010000
Tank Used for: PRODUCT
Type of Fuel: UNLEADED
Tank Construction: Not reported
Leak Detection: Stock Inventor

AX394 **EQUILON ENT., L.L.C.** **UST** **U003784681**
SW **2237 S RIVERSIDE AVE** **N/A**
1/2-1 **BLOOMINGTON, CA 92316**
0.562 mi.
2968 ft. **Site 4 of 30 in cluster AX**

Relative:
Lower

Actual:
1010 ft.

UST:
Facility ID: 86008627
Latitude: 34.06141
Longitude: -117.37024

AX395 **EDR US Hist Auto Stat** **1015338396**
SW **2237 S RIVERSIDE AVE** **N/A**
1/2-1 **BLOOMINGTON, CA 92316**
0.562 mi.
2968 ft. **Site 5 of 30 in cluster AX**

Relative:
Lower

Actual:
1010 ft.

EDR Historical Auto Stations:
Name: TEXACO REFINERY MS
Year: 2008
Address: 2237 S RIVERSIDE AVE

AX396 **EDR US Hist Auto Stat** **1015331357**
SW **2190 S RIVERSIDE AVE** **N/A**
1/2-1 **BLOOMINGTON, CA 92316**
0.563 mi.
2973 ft. **Site 6 of 30 in cluster AX**

Relative:
Lower

Actual:
1010 ft.

EDR Historical Auto Stations:
Name: UNIVERSAL AUTO COLLISION CTR
Year: 2010
Address: 2190 S RIVERSIDE AVE

Name: UNIVERSAL COLLISION CENTER
Year: 2011
Address: 2190 S RIVERSIDE AVE

Name: UNIVERSAL COLLISION CENTER
Year: 2012
Address: 2190 S RIVERSIDE AVE

AX397 **PENHALL INTERNATIONAL** **HIST UST** **U001574587**
SW **2190 S RIVERSIDE AVE** **SWEEPS UST** **N/A**
1/2-1 **BLOOMINGTON, CA 92316**
0.563 mi.
2973 ft. **Site 7 of 30 in cluster AX**

Relative:
Lower

Actual:
1010 ft.

HIST UST:

Region:	STATE
Facility ID:	00000042679
Facility Type:	Other
Other Type:	CONSTRUCTION
Total Tanks:	0003
Contact Name:	GEORGE BUSH
Telephone:	7148773880
Owner Name:	PENHALL INTERNATIONAL
Owner Address:	2190 SOUTH RIVERSIDE AVE
Owner City,St,Zip:	BLOOMINGTON, CA 92316

Tank Num:	001
Container Num:	#1
Year Installed:	1981
Tank Capacity:	00010000
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Tank Construction:	Not reported
Leak Detection:	None

Tank Num:	002
Container Num:	2
Year Installed:	1981
Tank Capacity:	00005000
Tank Used for:	PRODUCT
Type of Fuel:	DIESEL
Tank Construction:	Not reported
Leak Detection:	None

Tank Num:	003
Container Num:	#3
Year Installed:	1981
Tank Capacity:	00000500
Tank Used for:	WASTE
Type of Fuel:	WASTE OIL
Tank Construction:	Not reported
Leak Detection:	None

SWEEPS UST:

Status:	Active
Comp Number:	42679
Number:	9
Board Of Equalization:	44-021018
Referral Date:	03-19-92
Action Date:	03-19-92
Created Date:	02-29-88
Tank Status:	A
Owner Tank Id:	#1
Swrcb Tank Id:	36-000-042679-000001
Actv Date:	08-23-88
Capacity:	10000
Tank Use:	M.V. FUEL

PENHALL INTERNATIONAL (Continued) **U001574587**

Stg: P
Content: REG UNLEADED
Number Of Tanks: 3

Status: Active
Comp Number: 42679
Number: 9
Board Of Equalization: 44-021018
Referral Date: 03-19-92
Action Date: 03-19-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 2
Swrcb Tank Id: 36-000-042679-000002
Actv Date: 08-23-88
Capacity: 5000
Tank Use: M.V. FUEL
Stg: P
Content: DIESEL
Number Of Tanks: Not reported

Status: Active
Comp Number: 42679
Number: 9
Board Of Equalization: 44-021018
Referral Date: 03-19-92
Action Date: 03-19-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: #3
Swrcb Tank Id: 36-000-042679-000003
Actv Date: 08-23-88
Capacity: 500
Tank Use: OIL
Stg: W
Content: WASTE OIL
Number Of Tanks: Not reported

AY398 **PRECISION TURBOCHARGER CO.** **San Bern. Co. Permit** **S102041401**
West **450 W VALLEY BLVD** **N/A**
1/2-1 **RIALTO, CA 92376**
0.563 mi.
2974 ft. **Site 1 of 12 in cluster AY**

Relative:
Higher

Actual:
1081 ft.

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0008421
Owner: TURNIDGE, RICHARD DAVID
Permit Number: PT0014698
Permit Category: CONDITIONALLY EXEMPT SMALL QUANTITY GENERATOR
Facility Status: INACTIVE
Expiration Date: 10/31/2004

Region: SAN BERNARDINO
Facility ID: FA0003483
Owner: HORNSLEY, GARY D.
Permit Number: PT0006893
Permit Category: SPECIAL HANDLER

PRECISION TURBOCHARGER CO. (Continued) **S102041401**

Facility Status: ACTIVE
Expiration Date: 10/31/2012

Region: SAN BERNARDINO
Facility ID: FA0003483
Owner: HORNSLEY, GARY D.
Permit Number: PT0006894
Permit Category: SPECIAL GENERATOR
Facility Status: ACTIVE
Expiration Date: 10/31/2012

AY399 **EDR US Hist Auto Stat** **1015501953**
West **450 W VALLEY BLVD** **N/A**
1/2-1 **RIALTO, CA 92376**
0.563 mi.
2974 ft. **Site 2 of 12 in cluster AY**

Relative:
Higher

Actual:
1081 ft.

EDR Historical Auto Stations:

Name: GNS DIESEL REPAIR
Year: 2000
Address: 450 W VALLEY BLVD

Name: GNS DIESEL REPAIR
Year: 2001
Address: 450 W VALLEY BLVD

Name: GNS DIESEL REPAIR
Year: 2002
Address: 450 W VALLEY BLVD

Name: GNS DIESEL REPAIR
Year: 2003
Address: 450 W VALLEY BLVD

Name: GNS DIESEL REPAIR
Year: 2004
Address: 450 W VALLEY BLVD

Name: GNS DIESEL REPAIR
Year: 2005
Address: 450 W VALLEY BLVD

Name: GNS DIESEL REPAIR
Year: 2006
Address: 450 W VALLEY BLVD

Name: GNS DIESEL REPAIR
Year: 2008
Address: 450 W VALLEY BLVD

Name: GNS DIESEL REPAIR
Year: 2010
Address: 450 W VALLEY BLVD

Name: GNS DIESEL REPAIR INC
Year: 2011
Address: 450 W VALLEY BLVD

(Continued) **1015501953**

Name: GNS TRUCK & TRAILER REPAIR
Year: 2012
Address: 450 W VALLEY BLVD

AY400 **STEEL UNLIMITED INC** **RCRA-LQG** **1012175909**
West **452 W VALLEY BLVD** **HAZNET** **CAR000197202**
1/2-1 **RIALTO, CA 92376**
0.566 mi.
2986 ft. **Site 3 of 12 in cluster AY**

Relative:
Higher

Actual:
1081 ft.

RCRA-LQG:
Date form received by agency: 12/08/2008
Facility name: STEEL UNLIMITED INC
Facility address: 452 W VALLEY BLVD
RIALTO, CA 92376
EPA ID: CAR000197202
Contact: MIKE JOHNSTON
Contact address: 452 W VALLEY BLVD
RIALTO, CA 92376
Contact country: US
Contact telephone: 909-873-1222
Contact email: MJOHNSTON@STEELUNLIMITED.COM
EPA Region: 09
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:
Owner/operator name: STEEL UNLIMITED INC SUI MANUFACTURING IN
Owner/operator address: Not reported
Not reported
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 07/01/1998
Owner/Op end date: Not reported

Owner/operator name: MD ENTERPRISES
Owner/operator address: 452 W VALLEY BLVD
RIALTO, CA 92376
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 02/21/2001
Owner/Op end date: Not reported

STEEL UNLIMITED INC (Continued) **1012175909**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Hazardous Waste Summary:
Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: F003
Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste code: F005
Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

HAZNET:
Year: 2011
Gepaid: CAR000197202
Contact: MIKE JOHNSTON
Telephone: 9098731222
Mailing Name: Not reported
Mailing Address: 452 W VALLEY BLVD

STEEL UNLIMITED INC (Continued) **1012175909**

Mailing City,St,Zip: RIALTO, CA 923760000
Gen County: Not reported
TSD EPA ID: CAD044429835
TSD County: Not reported
Waste Category: Off-specification, aged or surplus organics
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.066
Facility County: San Bernardino

Year: 2011
Gepaid: CAR000197202
Contact: MIKE JOHNSTON
Telephone: 9098731222
Mailing Name: Not reported
Mailing Address: 452 W VALLEY BLVD
Mailing City,St,Zip: RIALTO, CA 923760000
Gen County: Not reported
TSD EPA ID: CAD982444481
TSD County: Not reported
Waste Category: Other organic solids
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.2
Facility County: San Bernardino

Year: 2011
Gepaid: CAR000197202
Contact: MIKE JOHNSTON
Telephone: 9098731222
Mailing Name: Not reported
Mailing Address: 452 W VALLEY BLVD
Mailing City,St,Zip: RIALTO, CA 923760000
Gen County: Not reported
TSD EPA ID: CAD982444481
TSD County: Not reported
Waste Category: Off-specification, aged or surplus organics
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.132
Facility County: San Bernardino

Year: 2011
Gepaid: CAR000197202
Contact: MIKE JOHNSTON
Telephone: 9098731222
Mailing Name: Not reported
Mailing Address: 452 W VALLEY BLVD
Mailing City,St,Zip: RIALTO, CA 923760000
Gen County: Not reported
TSD EPA ID: CAD982444481
TSD County: Not reported
Waste Category: Waste oil and mixed oil
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.665
Facility County: San Bernardino

STEEL UNLIMITED INC (Continued) **1012175909**

Year:	2011
Gepaid:	CAR000197202
Contact:	MIKE JOHNSTON
Telephone:	9098731222
Mailing Name:	Not reported
Mailing Address:	452 W VALLEY BLVD
Mailing City,St,Zip:	RIALTO, CA 923760000
Gen County:	Not reported
TSD EPA ID:	CAD982444481
TSD County:	Not reported
Waste Category:	Unspecified aqueous solution
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.063
Facility County:	San Bernardino

Click this hyperlink while viewing on your computer to access
8 additional CA_HAZNET: record(s) in the EDR Site Report.

AX401 **BOILERMAKERS LOCAL #92** **San Bern. Co. Permit** **S102041311**
SW **2260 RIVERSIDE AVE** **N/A**
1/2-1 **RIALTO, CA 92376**
0.570 mi.
3007 ft. **Site 8 of 30 in cluster AX**

Relative:
Lower

Actual:
1009 ft.

San Bern. Co. Permit:

Region:	SAN BERNARDINO
Facility ID:	FA0001531
Owner:	BOILERMAKERS LOCAL #92
Permit Number:	PT0006284
Permit Category:	HAZMAT HANDLER 0-10 EMPLOYEES
Facility Status:	ACTIVE
Expiration Date:	11/30/2013

AY402 **EDR US Hist Auto Stat** **1015504888**
West **456 W VALLEY BLVD** **N/A**
1/2-1 **RIALTO, CA 92376**
0.570 mi.
3011 ft. **Site 4 of 12 in cluster AY**

Relative:
Higher

Actual:
1081 ft.

EDR Historical Auto Stations:

Name:	TEDS AUTO
Year:	2002
Address:	456 W VALLEY BLVD

AZ403 **BEALL TRAILERS OF SOCAL** **San Bern. Co. Permit** **S112273997**
SW **225 W SLOVER AVE** **N/A**
1/2-1 **BLOOMINGTON, CA 92316**
0.572 mi.
3020 ft. **Site 1 of 2 in cluster AZ**

Relative:
Lower

Actual:
1023 ft.

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0001391
Owner: BEALL TRAILERS CORP
Permit Number: PT0006330
Permit Category: SPECIAL GENERATOR
Facility Status: ACTIVE
Expiration Date: 11/30/2013

Region: SAN BERNARDINO
Facility ID: FA0001391
Owner: BEALL TRAILERS CORP
Permit Number: PT0006329
Permit Category: HAZMAT HANDLER 11-25 EMPLOYEES
Facility Status: ACTIVE
Expiration Date: 11/30/2013

---

404 **EDR US Hist Auto Stat** **1015415601**
North **3121 W SANTOLINAS ST** **N/A**
1/2-1 **RIALTO, CA 92376**
0.588 mi.
3106 ft.

Relative:
Higher

Actual:
1168 ft.

EDR Historical Auto Stations:
Name: T & D AUTO MOBILE DETAIL
Year: 2003
Address: 3121 W SANTOLINAS ST

Name: T & D AUTO MOBILE DETAIL
Year: 2004
Address: 3121 W SANTOLINAS ST

BA405 **AMERICAN FUEL** **LUST** **S104251281**
ENE **1101 N RANCHO AVE** **San Bern. Co. Permit** **N/A**
1/2-1 **COLTON, CA 92324**
0.590 mi.
3115 ft. **Site 1 of 2 in cluster BA**

Relative:
Lower

Actual:
1049 ft.

LUST:
Region: STATE
Global Id: T0607100545
Latitude: 34.0783014
Longitude: -117.3349057
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 04/07/2000
Lead Agency: SAN BERNARDINO COUNTY
Case Worker: JC
Local Agency: SAN BERNARDINO COUNTY
RB Case Number: 083603378T
LOC Case Number: 99009
File Location: Local Agency

AMERICAN FUEL (Continued) **S104251281**

Potential Media Affect: Soil
Potential Contaminants of Concern: Gasoline
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0607100545
Contact Type: Local Agency Caseworker
Contact Name: JACKSON CRUTSINGER
Organization Name: SAN BERNARDINO COUNTY
Address: 620 SOUTH E STREET
City: SAN BERNARDINO
Email: jcrutsinger@sbcfire.org
Phone Number: Not reported

Global Id: T0607100545
Contact Type: Regional Board Caseworker
Contact Name: TOM E. MBEKE-EKANEM
Organization Name: SANTA ANA RWQCB (REGION 8)
Address: 3737 MAIN STREET, SUITE 500
City: RIVERSIDE
Email: tmbeke-ekanem@waterboards.ca.gov
Phone Number: 9513202007

Regulatory Activities:
Global Id: T0607100545
Action Type: ENFORCEMENT
Date: 04/07/2000
Action: Closure/No Further Action Letter

Global Id: T0607100545
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

Global Id: T0607100545
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0002431
Owner: UPCAROL VENTURES, INC.
Permit Number: PT0004154
Permit Category: HAZARDOUS WASTE GENERATOR - 0-10 EMPLOYEES
Facility Status: INACTIVE
Expiration Date: 10/31/2012

Region: SAN BERNARDINO
Facility ID: FA0002431
Owner: UPCAROL VENTURES, INC.
Permit Number: PT0010997
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: INACTIVE

AMERICAN FUEL (Continued) **S104251281**

Expiration Date: 10/31/2005

Region: SAN BERNARDINO
Facility ID: FA0002431
Owner: UPCAROL VENTURES, INC.
Permit Number: PT0023350
Permit Category: WASTE INCIDENTAL UST OPERATION ONLY
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0002431
Owner: UPCAROL VENTURES, INC.
Permit Number: PT0010995
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0002431
Owner: UPCAROL VENTURES, INC.
Permit Number: PT0010996
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0002431
Owner: UPCAROL VENTURES, INC.
Permit Number: PT0004153
Permit Category: HAZMAT HANDLER - UST ONLY
Facility Status: ACTIVE
Expiration Date: 10/31/2013

BA406 **EDR US Hist Auto Stat** **1015153698**
ENE **1101 N RANCHO AVE** **N/A**
1/2-1 **COLTON, CA 92324**
0.590 mi.
3115 ft. **Site 2 of 2 in cluster BA**

Relative:
Lower

EDR Historical Auto Stations:
Name: ADL GAS
Year: 2003
Address: 1101 N RANCHO AVE

Actual:
1049 ft.

AX407 **KINDER/MORGAN** **UST** **U003784594**
SW **230S S RIVERSIDE AVE** **N/A**
1/2-1 **RIALTO, CA 92376**
0.593 mi.
3132 ft. **Site 9 of 30 in cluster AX**

Relative:
Lower

UST:
Facility ID: 86007821
Latitude: 34.09811
Longitude: -117.37047

Actual:
1007 ft.

AX408 **TERMINAL (EQUILON ENTERPRISES)** **LUST** **S105690146**
SW **2237 RIVERSIDE AVE** **N/A**
1/2-1 **RIALTO, CA 92316**
0.594 mi.
3134 ft. **Site 10 of 30 in cluster AX**

Relative:
Lower

Actual:
1007 ft.

LUST REG 8:

Region:	8
County:	San Bernardino
Regional Board:	Santa Ana Region
Facility Status:	Preliminary site assessment underway
Case Number:	083603436T
Local Case Num:	99057
Case Type:	Soil only
Substance:	Gasoline
Qty Leaked:	Not reported
Abate Method:	Not reported
Cross Street:	Not reported
Enf Type:	Not reported
Funding:	Not reported
How Discovered:	Tank Closure
How Stopped:	Not reported
Leak Cause:	UNK
Leak Source:	UNK
Global ID:	T0607100567
How Stopped Date:	Not reported
Enter Date:	5/11/1999
Review Date:	Not reported
Prelim Assess:	2/22/1999
Discover Date:	2/21/1999
Enforcement Date:	Not reported
Close Date:	Not reported
Workplan:	Not reported
Pollution Char:	Not reported
Remed Plan:	Not reported
Remed Action:	Not reported
Monitoring:	Not reported
Enter Date:	5/11/1999
GW Qualifies:	Not reported
Soil Qualifies:	Not reported
Operator:	Not reported
Facility Contact:	Not reported
Interim:	Not reported
Oversite Program:	LUST
Latitude:	34.0606958
Longitude:	-117.3700158
MTBE Date:	Not reported
Max MTBE GW:	Not reported
MTBE Concentration:	0
Max MTBE Soil:	Not reported
MTBE Fuel:	1
MTBE Tested:	Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.
MTBE Class:	*
Staff:	RS
Staff Initials:	CB5
Lead Agency:	Local Agency
Local Agency:	36000L
Hydr Basin #:	UPPER SANTA ANA VALL
Beneficial:	Not reported

TERMINAL (EQUILON ENTERPRISES) (Continued) **S105690146**

Priority: Not reported
Cleanup Fund Id: Not reported
Work Suspended: Not reported
Summary: Not reported

AY409 **EDR US Hist Auto Stat** **1015512756**
West **476 W VALLEY BLVD** **N/A**
1/2-1 **RIALTO, CA 92376**
0.594 mi.
3135 ft. **Site 5 of 12 in cluster AY**

Relative:
Higher

Actual:
1081 ft.

EDR Historical Auto Stations:

Name: JIMS AUTO
Year: 1999
Address: 476 W VALLEY BLVD

Name: JIMS AUTO
Year: 2000
Address: 476 W VALLEY BLVD

Name: JIMS AUTO
Year: 2001
Address: 476 W VALLEY BLVD

Name: JIMS AUTO
Year: 2002
Address: 476 W VALLEY BLVD

Name: JIMS AUTO
Year: 2003
Address: 476 W VALLEY BLVD

Name: QUALITY TIRE AUTO SERVICE CENTER
Year: 2012
Address: 476 W VALLEY BLVD

AY410 **DISCOUNT TIRE CENTER** **San Bern. Co. Permit** **S102284947**
West **484 W VALLEY BLVD** **N/A**
1/2-1 **RIALTO, CA 92376**
0.597 mi.
3151 ft. **Site 6 of 12 in cluster AY**

Relative:
Higher

Actual:
1082 ft.

San Bern. Co. Permit:

Region: SAN BERNARDINO
Facility ID: FA0002750
Owner: ANDONIAN, ANDY
Permit Number: PT0005208
Permit Category: SPECIAL HANDLER
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0002750
Owner: ANDONIAN, ANDY
Permit Number: PT0005209
Permit Category: SPECIAL GENERATOR

DISCOUNT TIRE CENTER (Continued) **S102284947**

Facility Status: ACTIVE
Expiration Date: 10/31/2013

AY411 **EDR US Hist Auto Stat** **1015515657**
West **484 W VALLEY BLVD** **N/A**
1/2-1 **RIALTO, CA 92376**
0.597 mi.
3151 ft. **Site 7 of 12 in cluster AY**

Relative:
Higher

Actual:
1082 ft.

EDR Historical Auto Stations:

Name:	DISCOUNT TIRE CENTERS
Year:	2001
Address:	484 W VALLEY BLVD
Name:	DISCOUNT TIRE CENTER 17
Year:	2012
Address:	484 W VALLEY BLVD

AZ412 **WEST COLTON YD.** **HIST UST** **U001574599**
WSW **2078 S WILLOW AVE** **N/A**
1/2-1 **BLOOMINGTON, CA 92316**
0.602 mi.
3179 ft. **Site 2 of 2 in cluster AZ**

Relative:
Lower

Actual:
1036 ft.

HIST UST:

Region:	STATE
Facility ID:	00000040184
Facility Type:	Other
Other Type:	TRANS. CO.
Total Tanks:	0008
Contact Name:	D.M. KNOSP
Telephone:	7148775830
Owner Name:	SOUTHERN PACIFIC TRANSPORTATIO
Owner Address:	ONE MARKET PLAZA - ROOM 1007
Owner City,St,Zip:	SAN FRANCISCO, CA 94105
Tank Num:	001
Container Num:	#1
Year Installed:	1972
Tank Capacity:	00007500
Tank Used for:	PRODUCT
Type of Fuel:	REGULAR
Tank Construction:	1/4 inches
Leak Detection:	Visual, Stock Inventor
Tank Num:	002
Container Num:	1
Year Installed:	Not reported
Tank Capacity:	00007500
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Tank Construction:	Not reported
Leak Detection:	Visual, Stock Inventor
Tank Num:	003
Container Num:	2

WEST COLTON YD. (Continued) **U001574599**

Year Installed: Not reported
Tank Capacity: 00007500
Tank Used for: PRODUCT
Type of Fuel: DIESEL
Tank Construction: Not reported
Leak Detection: Visual, Stock Inventor

Tank Num: 004
Container Num: #1
Year Installed: 1972
Tank Capacity: 00007500
Tank Used for: PRODUCT
Type of Fuel: UNLEADED
Tank Construction: 1/4 inches
Leak Detection: Visual, Stock Inventor

Tank Num: 005
Container Num: #2
Year Installed: 1972
Tank Capacity: 00007500
Tank Used for: PRODUCT
Type of Fuel: DIESEL
Tank Construction: 1/4 inches
Leak Detection: Visual, Stock Inventor

Tank Num: 006
Container Num: 3
Year Installed: 1972
Tank Capacity: 00007500
Tank Used for: PRODUCT
Type of Fuel: Not reported
Tank Construction: 1/4 inches
Leak Detection: Visual, Stock Inventor

Tank Num: 007
Container Num: WEST #1
Year Installed: 1980
Tank Capacity: 00012500
Tank Used for: WASTE
Type of Fuel: Not reported
Tank Construction: Not reported
Leak Detection: Visual

Tank Num: 008
Container Num: EAST #2
Year Installed: 1980
Tank Capacity: 00012500
Tank Used for: WASTE
Type of Fuel: Not reported
Tank Construction: Not reported
Leak Detection: Visual

AX413 **CHEVRON USA INC COLTON SUPPLY SITE** **RCRA-SQG** **1000434353**
SW **2297 S. RIVERSIDE AVE.** **HIST UST** **CAD040517732**
1/2-1 **BLOOMINGTON, CA 92316** **SWEEPS UST**
0.605 mi.
3197 ft. **Site 11 of 30 in cluster AX**

Relative:
Lower

Actual:
1007 ft.

RCRA-SQG:

Date form received by agency:	03/04/1999
Facility name:	CHEVRON USA INC COLTON SUPPLY SITE
Site name:	1001657 COLTON TERMINAL-CHEVRON USA PROD
Facility address:	2297 S. RIVERSIDE AVE. BLOOMINGTON, CA 92316
EPA ID:	CAD040517732
Mailing address:	P.O. BOX 6004 SAN RAMON, CA 945830904
Contact:	KATHY NORRIS
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(510) 842-5931
Contact email:	Not reported
EPA Region:	09
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	09/01/1996
Facility name:	CHEVRON USA INC COLTON SUPPLY SITE
Classification:	Large Quantity Generator

Date form received by agency:	09/01/1996
Facility name:	CHEVRON USA INC COLTON SUPPLY SITE
Classification:	Small Quantity Generator

Date form received by agency:	02/14/1996
Facility name:	CHEVRON USA INC COLTON SUPPLY SITE
Site name:	COLTON TERMINAL-CHEVRON RETAIL MARKETING

CHEVRON USA INC COLTON SUPPLY SITE (Continued) **1000434353**

Classification: Large Quantity Generator

Date form received by agency: 02/23/1994
Facility name: CHEVRON USA INC COLTON SUPPLY SITE
Site name: CHEVRON USA PRODUCTS CO
Classification: Large Quantity Generator

Date form received by agency: 02/27/1992
Facility name: CHEVRON USA INC COLTON SUPPLY SITE
Site name: CHEVRON USA INC COLTON SUPPLY
Classification: Large Quantity Generator

Date form received by agency: 08/15/1980
Facility name: CHEVRON USA INC COLTON SUPPLY SITE
Classification: Large Quantity Generator

Violation Status: No violations found

HIST UST:
Region: STATE
Facility ID: 00000021492
Facility Type: Other
Other Type: TERMINAL
Total Tanks: 0003
Contact Name: D.J. HILBURGER
Telephone: 7148771901
Owner Name: CHEVRON USA INC.
Owner Address: 1201 S. BEACH BLVD.
Owner City,St,Zip: LA HABRA, CA 90631

Tank Num: 001
Container Num: 1
Year Installed: Not reported
Tank Capacity: 00005000
Tank Used for: PRODUCT
Type of Fuel: Not reported
Tank Construction: Not reported
Leak Detection: None

Tank Num: 002
Container Num: 2
Year Installed: Not reported
Tank Capacity: 00001000
Tank Used for: PRODUCT
Type of Fuel: 06
Tank Construction: Not reported
Leak Detection: None

Tank Num: 003
Container Num: 3
Year Installed: Not reported
Tank Capacity: 00001000
Tank Used for: PRODUCT
Type of Fuel: Not reported
Tank Construction: Not reported
Leak Detection: None

CHEVRON USA INC COLTON SUPPLY SITE (Continued) **1000434353**

SWEEPS UST:

Status:	Active
Comp Number:	21492
Number:	9
Board Of Equalization:	44-020743
Referral Date:	07-28-92
Action Date:	07-28-92
Created Date:	02-29-88
Tank Status:	A
Owner Tank Id:	2
Swrcb Tank Id:	36-000-021492-000002
Actv Date:	08-23-88
Capacity:	1000
Tank Use:	CHEMICAL
Stg:	W
Content:	VAPOR DROPOU
Number Of Tanks:	2

Status:	Active
Comp Number:	21492
Number:	9
Board Of Equalization:	44-020743
Referral Date:	07-28-92
Action Date:	07-28-92
Created Date:	02-29-88
Tank Status:	A
Owner Tank Id:	3
Swrcb Tank Id:	36-000-021492-000003
Actv Date:	08-23-88
Capacity:	10000
Tank Use:	UNKNOWN
Stg:	P
Content:	Not reported
Number Of Tanks:	Not reported

AX414 **EDR US Hist Auto Stat** **1015343159**
SW **2297 S RIVERSIDE AVE** **N/A**
1/2-1 **BLOOMINGTON, CA 92316**
0.605 mi.
3197 ft. **Site 12 of 30 in cluster AX**

Relative:
Lower

Actual:
1007 ft.

EDR Historical Auto Stations:

Name:	CHEVRON COMPANIES
Year:	1999
Address:	2297 S RIVERSIDE AVE

Name:	CHEVRON CO
Year:	2004
Address:	2297 S RIVERSIDE AVE

Name:	CHEVRON
Year:	2006
Address:	2297 S RIVERSIDE AVE

Name:	CHEVRON
Year:	2007
Address:	2297 S RIVERSIDE AVE

(Continued) **1015343159**

Name: CHEVRON CO
Year: 2009
Address: 2297 S RIVERSIDE AVE

AX415 **INTEGRATED WASTE MGMT** **RCRA NonGen / NLR** **1004675661**
SW **2230 S RIVERSIDE AVE** **FINDS** **CAR000075689**
1/2-1 **RIALTO, CA 92376** **HAZNET**
0.606 mi.
3201 ft. **Site 13 of 30 in cluster AX**

Relative:
Lower

Actual:
1007 ft.

RCRA NonGen / NLR:
Date form received by agency: 06/16/2000
Facility name: INTEGRATED WASTE MGMT
Facility address: 2230 S RIVERSIDE AVE
RIALTO, CA 92376
EPA ID: CAR000075689
Mailing address: P O BOX 1607
COLTON, CA 923241607
Contact: WADE RIDDERING
Contact address: P O BOX 1607
COLTON, CA 923241607
Contact country: US
Contact telephone: (909) 421-7102
Contact email: Not reported
EPA Region: 09
Land type: Private
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: JIM ARNOLD
Owner/operator address: P O BOX 1607
COLTON, CA 92324
Owner/operator country: Not reported
Owner/operator telephone: (909) 873-4143
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: Yes
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

INTEGRATED WASTE MGMT (Continued) **1004675661**

Facility Has Received Notices of Violations:
- Regulation violated: Not reported
- Area of violation: Transporters - Manifest and Recordkeeping
- Date violation determined: 03/13/2006
- Date achieved compliance: 03/28/2006
- Violation lead agency: State
- Enforcement action: WRITTEN INFORMAL
- Enforcement action date: 03/13/2006
- Enf. disposition status: Not reported
- Enf. disp. status date: Not reported
- Enforcement lead agency: State
- Proposed penalty amount: Not reported
- Final penalty amount: Not reported
- Paid penalty amount: Not reported

Evaluation Action Summary:
- Evaluation date: 03/13/2006
- Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
- Area of violation: Transporters - Manifest and Recordkeeping
- Date achieved compliance: 03/28/2006
- Evaluation lead agency: State

FINDS:

Registry ID: 110006486775

Environmental Interest/Information System

California Hazardous Waste Tracking System - Datamart (HWTS-DATAMART) provides California with information on hazardous waste shipments for generators, transporters, and treatment, storage, and disposal facilities.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZNET:
- Year: 2004
- Gepaid: CAR000075689
- Contact: WADE RIDDERING/ENVT CONSULTANT
- Telephone: 9098734141
- Mailing Name: Not reported
- Mailing Address: 2230 S RIVERSIDE AVE
- Mailing City,St,Zip: RIALTO, CA 923160000
- Gen County: Not reported
- TSD EPA ID: CAD982444481
- TSD County: Not reported
- Waste Category: Aqueous solution with total organic residues less than 10 percent
- Disposal Method: Recycler
- Tons: 57.92
- Facility County: San Bernardino

INTEGRATED WASTE MGMT (Continued) **1004675661**

Year:	2004
Gepaid:	CAR000075689
Contact:	WADE RIDDERING/ENVT CONSULTANT
Telephone:	9098734141
Mailing Name:	Not reported
Mailing Address:	2230 S RIVERSIDE AVE
Mailing City,St,Zip:	RIALTO, CA 923160000
Gen County:	Not reported
TSD EPA ID:	CAD982444481
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues less than 10 percent
Disposal Method:	Transfer Station
Tons:	225.73
Facility County:	San Bernardino

Year:	2004
Gepaid:	CAR000075689
Contact:	WADE RIDDERING/ENVT CONSULTANT
Telephone:	9098734141
Mailing Name:	Not reported
Mailing Address:	2230 S RIVERSIDE AVE
Mailing City,St,Zip:	RIALTO, CA 923160000
Gen County:	Not reported
TSD EPA ID:	CAD982444481
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues less than 10 percent
Disposal Method:	Not reported
Tons:	9.06
Facility County:	San Bernardino

Year:	2004
Gepaid:	CAR000075689
Contact:	WADE RIDDERING/ENVT CONSULTANT
Telephone:	9098734141
Mailing Name:	Not reported
Mailing Address:	2230 S RIVERSIDE AVE
Mailing City,St,Zip:	RIALTO, CA 923160000
Gen County:	Not reported
TSD EPA ID:	CAD982444481
TSD County:	Not reported
Waste Category:	Waste oil and mixed oil
Disposal Method:	Recycler
Tons:	0.22
Facility County:	San Bernardino

AX416 **FILTERRECYCLING SERVICES, INC.** **CORRACTS** **1000473043**
SW **180 MONTE AVENUE** **RCRA-LQG** **CAD982444481**
1/2-1 **RIALTO, CA 92316** **PADS**
0.609 mi. **NPDES**
3218 ft. **Site 14 of 30 in cluster AX** **San Bern. Co. Permit**
HAZNET
Relative: **ENVIROSTOR**
Lower **US FIN ASSUR**
HWP
Actual: **Financial Assurance**
1007 ft. **WDS**

FILTERRECYCLING SERVICES, INC. (Continued) **1000473043**

CORRACTS:

EPA ID:	CAD982444481
EPA Region:	09
Area Name:	ENTIRE FACILITY
Actual Date:	19900101
Action:	CA029ST
NAICS Code(s):	562219 562119 Other Nonhazardous Waste Treatment and Disposal Other Waste Collection
Original schedule date:	Not reported
Schedule end date:	Not reported

EPA ID:	CAD982444481
EPA Region:	09
Area Name:	ENTIRE FACILITY
Actual Date:	19911220
Action:	CA075LO - CA Prioritization, Facility or area was assigned a low corrective action priority
NAICS Code(s):	562219 562119 Other Nonhazardous Waste Treatment and Disposal Other Waste Collection
Original schedule date:	Not reported
Schedule end date:	Not reported

RCRA-LQG:

Date form received by agency:	07/24/2012
Facility name:	FILTERRECYCLING SERVICES, INC.
Facility address:	180 MONTE AVENUE RIALTO, CA 92316
EPA ID:	CAD982444481
Mailing address:	MONTE AVENUE BLOOMINGTON, CA 92316
Contact:	WADE RIDDERING
Contact address:	MONTE AVENUE BLOOMINGTON, CA 92316
Contact country:	Not reported
Contact telephone:	(909) 873-4141
Contact email:	WADE@FILTERRECYCLING.COM
EPA Region:	09
Land type:	Private
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

FILTERRECYCLING SERVICES, INC. (Continued) **1000473043**

Owner/Operator Summary:

Owner/operator name:	JON L. BENNETT, JR.
Owner/operator address:	RIVERSIDE AVENUE
	BLOOMINGTON, CA 92316
Owner/operator country:	Not reported
Owner/operator telephone:	(909) 873-4141
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	06/12/1990
Owner/Op end date:	Not reported

Owner/operator name:	JON L BENNETT JR.
Owner/operator address:	RIVERSIDE AVENUE
	BLOOMINGTON, CA 92316
Owner/operator country:	Not reported
Owner/operator telephone:	(909) 873-4141
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	06/12/1990
Owner/Op end date:	Not reported

Owner/operator name:	JON BENNETT JR
Owner/operator address:	P O BOX 449
	COLTON, CA 92324
Owner/operator country:	Not reported
Owner/operator telephone:	(909) 780-8707
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	FILTER RECYCLING SERVICES INC
Owner/operator address:	PO BOX 7780
	MORENO VALLEY, CA 92303
Owner/operator country:	Not reported
Owner/operator telephone:	(714) 877-8820
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	Yes
Treater, storer or disposer of HW:	Yes
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	Yes

FILTERRECYCLING SERVICES, INC. (Continued) **1000473043**

Used oil transporter: Yes

Universal Waste Summary:
Waste type: A
Accumulated waste on-site: Yes
Generated waste on-site: No

Waste type: C
Accumulated waste on-site: Yes
Generated waste on-site: No

Waste type: E
Accumulated waste on-site: Yes
Generated waste on-site: No

Waste type: Batteries
Accumulated waste on-site: Yes
Generated waste on-site: No

Waste type: Lamps
Accumulated waste on-site: Yes
Generated waste on-site: No

Waste type: Thermostats
Accumulated waste on-site: Yes
Generated waste on-site: No

Historical Generators:
Date form received by agency: 02/06/2008
Facility name: FILTERRECYCLING SERVICES, INC.
Site name: FILTER RECYCLING SERVICES INC
Classification: Large Quantity Generator

Date form received by agency: 02/08/2006
Facility name: FILTERRECYCLING SERVICES, INC.
Site name: FILTER RECYCLING SERVICES, INC.
Classification: Large Quantity Generator

Date form received by agency: 02/23/2004
Facility name: FILTERRECYCLING SERVICES, INC.
Site name: FILTER RECYCLING SERVICES, INC.
Classification: Large Quantity Generator

Date form received by agency: 03/22/2002
Facility name: FILTERRECYCLING SERVICES, INC.
Site name: FILTER RECYCLING SERVICES, INC.
Classification: Large Quantity Generator

Date form received by agency: 10/12/2000
Facility name: FILTERRECYCLING SERVICES, INC.
Site name: FILTER RECYCLING SERVICES, INC.
Classification: Large Quantity Generator

Date form received by agency: 09/30/1999
Facility name: FILTERRECYCLING SERVICES, INC.
Site name: FILTER RECYCLING SERVICES INC

FILTERRECYCLING SERVICES, INC. (Continued) **1000473043**

Classification: Large Quantity Generator

Date form received by agency: 06/06/1999
Facility name: FILTERRECYCLING SERVICES, INC.
Site name: FILTER RECYCLING SERVICES, INC.
Classification: Large Quantity Generator

Date form received by agency: 09/01/1996
Facility name: FILTERRECYCLING SERVICES, INC.
Site name: FILTER RECYCLING SERVICES INC
Classification: Small Quantity Generator

Date form received by agency: 03/20/1996
Facility name: FILTERRECYCLING SERVICES, INC.
Site name: FILTER RECYCLING SERVICES, INC.
Classification: Large Quantity Generator

Hazardous Waste Summary:
Waste code: 123
Waste name: 123

Waste code: 133
Waste name: 133

Waste code: 134
Waste name: 134

Waste code: 135
Waste name: 135

Waste code: 141
Waste name: 141

Waste code: 172
Waste name: 172

Waste code: 181
Waste name: 181

Waste code: 221
Waste name: 221

Waste code: 222
Waste name: 222

Waste code: 223
Waste name: 223

Waste code: 232
Waste name: 232

Waste code: 261
Waste name: 261

Waste code: 272
Waste name: 272

FILTERRECYCLING SERVICES, INC. (Continued) **1000473043**

Waste code:	281
Waste name:	281
Waste code:	291
Waste name:	291
Waste code:	331
Waste name:	331
Waste code:	343
Waste name:	343
Waste code:	352
Waste name:	352
Waste code:	451
Waste name:	451
Waste code:	461
Waste name:	461
Waste code:	491
Waste name:	491
Waste code:	512
Waste name:	512
Waste code:	513
Waste name:	513
Waste code:	521
Waste name:	521
Waste code:	541
Waste name:	541
Waste code:	551
Waste name:	551
Waste code:	561
Waste name:	561
Waste code:	611
Waste name:	611
Waste code:	612
Waste name:	612
Waste code:	D001
Waste name:	IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

FILTERRECYCLING SERVICES, INC. (Continued) **1000473043**

Waste code: D002
Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D003
Waste name: A MATERIAL IS CONSIDERED TO BE A REACTIVE HAZARDOUS WASTE IF IT IS NORMALLY UNSTABLE, REACTS VIOLENTLY WITH WATER, GENERATES TOXIC GASES WHEN EXPOSED TO WATER OR CORROSIVE MATERIALS, OR IF IT IS CAPABLE OF DETONATION OR EXPLOSION WHEN EXPOSED TO HEAT OR A FLAME. ONE EXAMPLE OF SUCH WASTE WOULD BY WASTE GUNPOWDER.

Biennial Reports:

Last Biennial Reporting Year: 2013

Annual Waste Handled:
Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.
Amount (Lbs): 4356.1

Waste code: D002
Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.
Amount (Lbs): 0

Corrective Action Summary:
Event date: 01/01/1990
Event: CA029ST

Event date: 01/01/1990
Event: CA029ST

FILTERRECYCLING SERVICES, INC. (Continued) **1000473043**

Event date: 12/20/1991
Event: CA Prioritization, Facility or area was assigned a low corrective action priority.

Event date: 12/20/1991
Event: CA Prioritization, Facility or area was assigned a low corrective action priority.

Event date: 12/20/1991
Event: CA049PA

Event date: 12/20/1991
Event: CA074LO

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Permits - Conditions
Date violation determined: 04/09/2012
Date achieved compliance: Not reported
Violation lead agency: State
Enforcement action: INITIAL CIVIL JUDICIAL ACTION FOR COMPLIANCE AND/OR MONETARY PENALTY
Enforcement action date: 12/05/2012
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Manifest
Date violation determined: 04/09/2012
Date achieved compliance: Not reported
Violation lead agency: State
Enforcement action: INITIAL CIVIL JUDICIAL ACTION FOR COMPLIANCE AND/OR MONETARY PENALTY
Enforcement action date: 12/05/2012
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Listing - Characteristics
Date violation determined: 04/09/2012
Date achieved compliance: Not reported
Violation lead agency: State
Enforcement action: INITIAL CIVIL JUDICIAL ACTION FOR COMPLIANCE AND/OR MONETARY PENALTY
Enforcement action date: 12/05/2012
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

FILTERRECYCLING SERVICES, INC. (Continued) **1000473043**

Regulation violated: Not reported
Area of violation: TSD - Releases from SWMUs
Date violation determined: 04/09/2012
Date achieved compliance: Not reported
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/19/2012
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: State Statute or Regulation
Date violation determined: 04/09/2012
Date achieved compliance: Not reported
Violation lead agency: State
Enforcement action: INITIAL CIVIL JUDICIAL ACTION FOR COMPLIANCE AND/OR MONETARY PENALTY
Enforcement action date: 12/05/2012
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Listing - Characteristics
Date violation determined: 04/09/2012
Date achieved compliance: Not reported
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/19/2012
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: State Statute or Regulation
Date violation determined: 04/09/2012
Date achieved compliance: Not reported
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/19/2012
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported

FILTERRECYCLING SERVICES, INC. (Continued) **1000473043**

Area of violation: TSD - Releases from SWMUs
Date violation determined: 04/09/2012
Date achieved compliance: Not reported
Violation lead agency: State
Enforcement action: INITIAL CIVIL JUDICIAL ACTION FOR COMPLIANCE AND/OR MONETARY PENALTY
Enforcement action date: 12/05/2012
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Permits - Conditions
Date violation determined: 04/09/2012
Date achieved compliance: Not reported
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/19/2012
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Manifest
Date violation determined: 04/09/2012
Date achieved compliance: Not reported
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/19/2012
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: State Statute or Regulation
Date violation determined: 11/16/2009
Date achieved compliance: 11/16/2009
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 11/16/2009
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Pre-transport

FILTERRECYCLING SERVICES, INC. (Continued) **1000473043**

Date violation determined: 06/29/2009
Date achieved compliance: 07/02/2009
Violation lead agency: State
Enforcement action: REFERRAL TO ATTORNEY GENERAL
Enforcement action date: 11/02/2010
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: State Statute or Regulation
Date violation determined: 06/29/2009
Date achieved compliance: 07/02/2009
Violation lead agency: State
Enforcement action: REFERRAL TO ATTORNEY GENERAL
Enforcement action date: 11/02/2010
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: State Statute or Regulation
Date violation determined: 06/29/2009
Date achieved compliance: 07/02/2009
Violation lead agency: State
Enforcement action: INITIAL CIVIL JUDICIAL ACTION FOR COMPLIANCE AND/OR MONETARY PENALTY
Enforcement action date: 12/05/2012
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: State Statute or Regulation
Date violation determined: 06/29/2009
Date achieved compliance: 07/02/2009
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/02/2009
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Pre-transport
Date violation determined: 06/29/2009

FILTERRECYCLING SERVICES, INC. (Continued) **1000473043**

Date achieved compliance: 07/02/2009
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/02/2009
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Pre-transport
Date violation determined: 06/29/2009
Date achieved compliance: 07/02/2009
Violation lead agency: State
Enforcement action: INITIAL CIVIL JUDICIAL ACTION FOR COMPLIANCE AND/OR MONETARY PENALTY
Enforcement action date: 12/05/2012
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: State Statute or Regulation
Date violation determined: 03/25/2008
Date achieved compliance: 05/20/2008
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 05/27/2008
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Financial Requirements
Date violation determined: 06/20/2007
Date achieved compliance: 07/16/2007
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/20/2007
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Preparedness and Prevention
Date violation determined: 06/13/2007
Date achieved compliance: 06/14/2007

FILTERRECYCLING SERVICES, INC. (Continued) **1000473043**

Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/14/2007
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General Facility Standards
Date violation determined: 06/13/2007
Date achieved compliance: 06/14/2007
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/14/2007
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General Facility Standards
Date violation determined: 06/13/2007
Date achieved compliance: 07/14/2007
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/14/2007
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General Facility Standards
Date violation determined: 06/22/2005
Date achieved compliance: 06/23/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/23/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Container Use and Management
Date violation determined: 06/23/2004
Date achieved compliance: 07/01/2004
Violation lead agency: State

FILTERRECYCLING SERVICES, INC. (Continued) **1000473043**

Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/23/2004
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Container Use and Management
Date violation determined: 06/23/2004
Date achieved compliance: 07/23/2004
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/23/2004
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Permits - Application
Date violation determined: 06/23/2004
Date achieved compliance: 07/23/2004
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/23/2004
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Records/Reporting
Date violation determined: 06/30/2003
Date achieved compliance: 07/03/2003
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/03/2003
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General Facility Standards
Date violation determined: 06/30/2003
Date achieved compliance: 07/03/2003
Violation lead agency: State
Enforcement action: FINAL CIVIL JUDICIAL ACTION FOR COMPLIANCE AND/OR MONETARY PENALTY

FILTERRECYCLING SERVICES, INC. (Continued) **1000473043**

Enforcement action date: 11/10/2004
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Records/Reporting
Date violation determined: 06/30/2003
Date achieved compliance: 07/03/2003
Violation lead agency: State
Enforcement action: FINAL CIVIL JUDICIAL ACTION FOR COMPLIANCE AND/OR MONETARY PENALTY
Enforcement action date: 11/10/2004
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General Facility Standards
Date violation determined: 06/30/2003
Date achieved compliance: 07/03/2003
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/03/2003
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General Facility Standards
Date violation determined: 11/15/2001
Date achieved compliance: 01/22/2002
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 11/21/2001
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Financial Requirements
Date violation determined: 11/15/2001
Date achieved compliance: 01/22/2002
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 11/21/2001

FILTERRECYCLING SERVICES, INC. (Continued) **1000473043**

Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Financial Requirements
Date violation determined: 11/15/2001
Date achieved compliance: 01/22/2002
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 11/15/2001
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Container Use and Management
Date violation determined: 11/15/2001
Date achieved compliance: 01/22/2002
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 11/21/2001
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General Facility Standards
Date violation determined: 11/15/2001
Date achieved compliance: 01/22/2002
Violation lead agency: State
Enforcement action: FINAL CIVIL JUDICIAL ACTION FOR COMPLIANCE AND/OR MONETARY PENALTY
Enforcement action date: 11/10/2004
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General Facility Standards
Date violation determined: 12/18/2000
Date achieved compliance: 02/09/2001
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 12/19/2000
Enf. disposition status: Not reported

FILTERRECYCLING SERVICES, INC. (Continued) **1000473043**

Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General Facility Standards
Date violation determined: 06/21/1999
Date achieved compliance: 11/11/1999
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General Facility Standards
Date violation determined: 06/21/1999
Date achieved compliance: 11/11/1999
Violation lead agency: State
Enforcement action: FINAL CIVIL JUDICIAL ACTION FOR COMPLIANCE AND/OR MONETARY PENALTY
Enforcement action date: 11/10/2004
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General Facility Standards
Date violation determined: 06/21/1999
Date achieved compliance: 11/11/1999
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/22/1999
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: F - 263
Area of violation: Transporters - General
Date violation determined: 05/27/1998
Date achieved compliance: 06/19/1998
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 05/27/1998
Enf. disposition status: Not reported
Enf. disp. status date: Not reported

FILTERRECYCLING SERVICES, INC. (Continued) **1000473043**

Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: F - 270
Area of violation: TSD - General
Date violation determined: 01/23/1998
Date achieved compliance: 02/23/1998
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 01/23/1998
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: F - 264.50-56.D
Area of violation: TSD - General
Date violation determined: 04/24/1997
Date achieved compliance: 05/24/1997
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/24/1997
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: F - 264.170-177.I
Area of violation: TSD - General
Date violation determined: 04/24/1997
Date achieved compliance: 05/24/1997
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/24/1997
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: F - 264.30-37.C
Area of violation: TSD - General
Date violation determined: 04/24/1997
Date achieved compliance: 05/24/1997
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/24/1997
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State

FILTERRECYCLING SERVICES, INC. (Continued) **1000473043**

Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: F - 270
Area of violation: TSD - General
Date violation determined: 04/24/1997
Date achieved compliance: 05/24/1997
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/24/1997
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: F - 262.40-43.D
Area of violation: Generators - General
Date violation determined: 04/24/1997
Date achieved compliance: 05/24/1997
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/24/1997
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: F - 264.70-77.E
Area of violation: TSD - General
Date violation determined: 04/24/1997
Date achieved compliance: 05/24/1997
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/24/1997
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Permits - Application
Date violation determined: 04/23/1997
Date achieved compliance: 05/24/1997
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/24/1997
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported

FILTERRECYCLING SERVICES, INC. (Continued) **1000473043**

Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Container Use and Management
Date violation determined: 04/23/1997
Date achieved compliance: 05/24/1997
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/24/1997
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Preparedness and Prevention
Date violation determined: 04/23/1997
Date achieved compliance: 05/24/1997
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/24/1997
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Permits - Application
Date violation determined: 04/23/1997
Date achieved compliance: 05/24/1997
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Contingency Plan and Emergency Procedures
Date violation determined: 04/23/1997
Date achieved compliance: 05/24/1997
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/24/1997
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported

FILTERRECYCLING SERVICES, INC. (Continued) **1000473043**

Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Pre-transport
Date violation determined: 04/23/1997
Date achieved compliance: 05/24/1997
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/24/1997
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Permits - Application
Date violation determined: 04/23/1997
Date achieved compliance: 05/24/1997
Violation lead agency: State
Enforcement action: FINAL CIVIL JUDICIAL ACTION FOR COMPLIANCE AND/OR MONETARY PENALTY
Enforcement action date: 11/10/2004
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Preparedness and Prevention
Date violation determined: 04/23/1997
Date achieved compliance: 05/24/1997
Violation lead agency: State
Enforcement action: FINAL CIVIL JUDICIAL ACTION FOR COMPLIANCE AND/OR MONETARY PENALTY
Enforcement action date: 11/10/2004
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Container Use and Management
Date violation determined: 04/23/1997
Date achieved compliance: 05/24/1997
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

FILTERRECYCLING SERVICES, INC. (Continued) **1000473043**

Regulation violated: Not reported
Area of violation: TSD - Manifest/Records/Reporting
Date violation determined: 04/23/1997
Date achieved compliance: 05/24/1997
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/24/1997
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Container Use and Management
Date violation determined: 04/23/1997
Date achieved compliance: 05/24/1997
Violation lead agency: State
Enforcement action: FINAL CIVIL JUDICIAL ACTION FOR COMPLIANCE AND/OR MONETARY PENALTY
Enforcement action date: 11/10/2004
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Preparedness and Prevention
Date violation determined: 04/23/1997
Date achieved compliance: 05/24/1997
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 264.140-150.H
Area of violation: TSD - Financial Requirements
Date violation determined: 06/26/1995
Date achieved compliance: 09/01/1995
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/26/1995
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 270

FILTERRECYCLING SERVICES, INC. (Continued) **1000473043**

Area of violation: TSD - General
Date violation determined: 06/26/1995
Date achieved compliance: 09/07/1995
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/26/1995
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 04/09/2012
Evaluation: FOLLOW-UP INSPECTION
Area of violation: State Statute or Regulation
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 04/09/2012
Evaluation: FOLLOW-UP INSPECTION
Area of violation: TSD - Releases from SWMUs
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 04/09/2012
Evaluation: FOLLOW-UP INSPECTION
Area of violation: Generators - Manifest
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 04/09/2012
Evaluation: FOLLOW-UP INSPECTION
Area of violation: Listing - Characteristics
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 04/09/2012
Evaluation: FOLLOW-UP INSPECTION
Area of violation: Permits - Conditions
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 11/16/2009
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: State Statute or Regulation
Date achieved compliance: 11/16/2009
Evaluation lead agency: State

Evaluation date: 07/02/2009
Evaluation: NOT A SIGNIFICANT NON-COMPLIER
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 06/30/2009

FILTERRECYCLING SERVICES, INC. (Continued) **1000473043**

Evaluation: FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 06/29/2009
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 07/02/2009
Evaluation lead agency: State

Evaluation date: 06/29/2009
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: State Statute or Regulation
Date achieved compliance: 07/02/2009
Evaluation lead agency: State

Evaluation date: 06/29/2009
Evaluation: SIGNIFICANT NON-COMPLIER
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 04/17/2008
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 03/25/2008
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: State Statute or Regulation
Date achieved compliance: 05/20/2008
Evaluation lead agency: State

Evaluation date: 06/20/2007
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: TSD - Financial Requirements
Date achieved compliance: 07/16/2007
Evaluation lead agency: State

Evaluation date: 06/13/2007
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General Facility Standards
Date achieved compliance: 07/14/2007
Evaluation lead agency: State

Evaluation date: 06/13/2007
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - Preparedness and Prevention
Date achieved compliance: 06/14/2007
Evaluation lead agency: State

Evaluation date: 06/13/2007
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General Facility Standards
Date achieved compliance: 06/14/2007

FILTERRECYCLING SERVICES, INC. (Continued) **1000473043**

Evaluation lead agency: State

Evaluation date: 06/28/2006
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 06/12/2006
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 06/22/2005
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General Facility Standards
Date achieved compliance: 06/23/2005
Evaluation lead agency: State

Evaluation date: 06/03/2005
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 06/23/2004
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - Container Use and Management
Date achieved compliance: 07/01/2004
Evaluation lead agency: State

Evaluation date: 06/23/2004
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - Container Use and Management
Date achieved compliance: 07/23/2004
Evaluation lead agency: State

Evaluation date: 06/23/2004
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Permits - Application
Date achieved compliance: 07/23/2004
Evaluation lead agency: State

Evaluation date: 04/29/2004
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 09/19/2003
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 06/30/2003

FILTERRECYCLING SERVICES, INC. (Continued) **1000473043**

Evaluation: FOLLOW-UP INSPECTION
Area of violation: TSD - General Facility Standards
Date achieved compliance: 07/03/2003
Evaluation lead agency: State

Evaluation date: 06/30/2003
Evaluation: FOLLOW-UP INSPECTION
Area of violation: Generators - Records/Reporting
Date achieved compliance: 07/03/2003
Evaluation lead agency: State

Evaluation date: 05/21/2002
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 01/22/2002
Evaluation: NOT A SIGNIFICANT NON-COMPLIER
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 11/15/2001
Evaluation: FOLLOW-UP INSPECTION
Area of violation: TSD - General Facility Standards
Date achieved compliance: 01/22/2002
Evaluation lead agency: State

Evaluation date: 11/15/2001
Evaluation: SIGNIFICANT NON-COMPLIER
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 11/15/2001
Evaluation: FOLLOW-UP INSPECTION
Area of violation: TSD - Container Use and Management
Date achieved compliance: 01/22/2002
Evaluation lead agency: State

Evaluation date: 11/15/2001
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: TSD - Financial Requirements
Date achieved compliance: 01/22/2002
Evaluation lead agency: State

Evaluation date: 11/15/2001
Evaluation: FOLLOW-UP INSPECTION
Area of violation: TSD - Financial Requirements
Date achieved compliance: 01/22/2002
Evaluation lead agency: State

Evaluation date: 12/18/2000
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General Facility Standards
Date achieved compliance: 02/09/2001

FILTERRECYCLING SERVICES, INC. (Continued) **1000473043**

Evaluation lead agency: State

Evaluation date: 12/15/2000
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 11/11/1999
Evaluation: NOT A SIGNIFICANT NON-COMPLIER
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 06/21/1999
Evaluation: SIGNIFICANT NON-COMPLIER
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 06/21/1999
Evaluation: FOLLOW-UP INSPECTION
Area of violation: TSD - General Facility Standards
Date achieved compliance: 11/11/1999
Evaluation lead agency: State

Evaluation date: 05/20/1999
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

Evaluation date: 05/27/1998
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Transporters - General
Date achieved compliance: 06/19/1998
Evaluation lead agency: State

Evaluation date: 01/22/1998
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General
Date achieved compliance: 02/23/1998
Evaluation lead agency: State

Evaluation date: 04/23/1997
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - Contingency Plan and Emergency Procedures
Date achieved compliance: 05/24/1997
Evaluation lead agency: State

Evaluation date: 04/23/1997
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 05/24/1997
Evaluation lead agency: State

Evaluation date: 04/23/1997

FILTERRECYCLING SERVICES, INC. (Continued) **1000473043**

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - Container Use and Management
Date achieved compliance: 05/24/1997
Evaluation lead agency: State

Evaluation date: 04/23/1997
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General
Date achieved compliance: 05/24/1997
Evaluation lead agency: State

Evaluation date: 04/23/1997
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - Manifest/Records/Reporting
Date achieved compliance: 05/24/1997
Evaluation lead agency: State

Evaluation date: 04/23/1997
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - Preparedness and Prevention
Date achieved compliance: 05/24/1997
Evaluation lead agency: State

Evaluation date: 04/23/1997
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Permits - Application
Date achieved compliance: 05/24/1997
Evaluation lead agency: State

Evaluation date: 04/23/1997
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 05/24/1997
Evaluation lead agency: State

Evaluation date: 01/19/1996
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 06/26/1995
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General
Date achieved compliance: 09/07/1995
Evaluation lead agency: State

Evaluation date: 06/26/1995
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - Financial Requirements
Date achieved compliance: 09/01/1995
Evaluation lead agency: State

Evaluation date: 11/29/1990
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported

FILTERRECYCLING SERVICES, INC. (Continued) **1000473043**

Evaluation lead agency: EPA

PADS:

EPAID:	CAD982444481
Facility name:	FILTER RECYCLING SERVICES, INC.
Facility Address:	180 W. MONTE AVE. RIALTO, CA 92376
Facility country:	US
Generator:	No
Storer:	No
Transporter:	Yes
Disposer:	No
Research facility:	No
Smelter:	No
Facility owner name:	JON L. BENNETT, JR.
Contact title:	Not reported
Contact name:	WADE RIDDERING
Contact tel:	(909)873-4141
Contact extension:	Not reported
Mailing address:	P.O. BOX 449 COLTON, CA
Mailing country:	US
Cert. title:	Not reported
Cert. name:	Not reported
Cert. date:	9/22/2004
Date received:	10/29/2004

NPDES:

Npdes Number:	CAS000001
Facility Status:	Active
Agency Id:	0
Region:	8
Regulatory Measure Id:	213368
Order No:	97-03-DWQ
Regulatory Measure Type:	Enrollee
Place Id:	Not reported
WDID:	8 36I012307
Program Type:	Industrial
Adoption Date Of Regulatory Measure:	Not reported
Effective Date Of Regulatory Measure:	05/16/1996
Expiration Date Of Regulatory Measure:	Not reported
Termination Date Of Regulatory Measure:	04/01/2000
Discharge Name:	Filter Recycling Services Inc
Discharge Address:	2230 Riverside Ave
Discharge City:	Bloomington
Discharge State:	California
Discharge Zip:	92316

San Bern. Co. Permit:

Region:	SAN BERNARDINO
Facility ID:	FA0003215
Owner:	FILTER RECYCLING SVCS INC
Permit Number:	PT0018851
Permit Category:	APPLIANCE RECYCLER
Facility Status:	ACTIVE
Expiration Date:	09/30/2013

FILTERRECYCLING SERVICES, INC. (Continued) **1000473043**

Region: SAN BERNARDINO
Facility ID: FA0003215
Owner: FILTER RECYCLING SVCS INC
Permit Number: PT0005815
Permit Category: SPECIAL GENERATOR
Facility Status: ACTIVE
Expiration Date: 09/30/2013

Region: SAN BERNARDINO
Facility ID: FA0003215
Owner: FILTER RECYCLING SVCS INC
Permit Number: PT0005816
Permit Category: APSA 10,001-100,000 GAL FAC CAPACITY
Facility Status: ACTIVE
Expiration Date: 09/30/2013

Region: SAN BERNARDINO
Facility ID: FA0003215
Owner: FILTER RECYCLING SVCS INC
Permit Number: PT0005814
Permit Category: SPECIAL HANDLER
Facility Status: ACTIVE
Expiration Date: 09/30/2013

HAZNET:
Year: 2011
Gepaid: CAD982444481
Contact: WADE RIDDERING/TRANSPORTATION
Telephone: 9098734141
Mailing Name: Not reported
Mailing Address: PO BOX 449
Mailing City,St,Zip: COLTON, CA 923240449
Gen County: Not reported
TSD EPA ID: CAT080013352
TSD County: Not reported
Waste Category: Off-specification, aged or surplus organics
Disposal Method: Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons: 3.96
Facility County: San Bernardino

Year: 2011
Gepaid: CAD982444481
Contact: WADE RIDDERING/TRANSPORTATION
Telephone: 9098734141
Mailing Name: Not reported
Mailing Address: PO BOX 449
Mailing City,St,Zip: COLTON, CA 923240449
Gen County: Not reported
TSD EPA ID: AZR000504332
TSD County: Not reported
Waste Category: Waste oil and mixed oil
Disposal Method: Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons: 189.62
Facility County: San Bernardino

FILTERRECYCLING SERVICES, INC. (Continued) **1000473043**

Year:	2011
Gepaid:	CAD982444481
Contact:	WADE RIDDERING/TRANSPORTATION
Telephone:	9098734141
Mailing Name:	Not reported
Mailing Address:	PO BOX 449
Mailing City,St,Zip:	COLTON, CA 923240449
Gen County:	Not reported
TSD EPA ID:	UTC093012201
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	29.498
Facility County:	San Bernardino

Year:	2011
Gepaid:	CAD982444481
Contact:	WADE RIDDERING/TRANSPORTATION
Telephone:	9098734141
Mailing Name:	Not reported
Mailing Address:	PO BOX 449
Mailing City,St,Zip:	COLTON, CA 923240449
Gen County:	Not reported
TSD EPA ID:	UTC093012201
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	29.498
Facility County:	San Bernardino

Year:	2011
Gepaid:	CAD982444481
Contact:	WADE RIDDERING/TRANSPORTATION
Telephone:	9098734141
Mailing Name:	Not reported
Mailing Address:	PO BOX 449
Mailing City,St,Zip:	COLTON, CA 923240449
Gen County:	Not reported
TSD EPA ID:	CAL000330365
TSD County:	Not reported
Waste Category:	Oil/water separation sludge
Disposal Method:	Not reported
Tons:	0.417
Facility County:	San Bernardino

Click this hyperlink while viewing on your computer to access
1594 additional CA_HAZNET: record(s) in the EDR Site Report.

ENVIROSTOR:

Site Type:	Corrective Action
Site Type Detailed:	Corrective Action
Acres:	0
NPL:	NO
Regulatory Agencies:	NONE SPECIFIED
Lead Agency:	NONE SPECIFIED

FILTERRECYCLING SERVICES, INC. (Continued) **1000473043**

Program Manager: Not reported
Supervisor: * Unknown
Division Branch: Cleanup Cypress
Facility ID: 80001495
Site Code: 400463
Assembly: 47
Senate: 20
Special Program: Not reported
Status: Inactive - Needs Evaluation
Status Date: 11/09/2010
Restricted Use: NO
Site Mgmt. Req.: NONE SPECIFIED
Funding: Not reported
Latitude: 34.06109
Longitude: -117.3706
APN: NONE SPECIFIED
Past Use: NONE SPECIFIED
Potential COC: NONE SPECIFIED
Confirmed COC: NONE SPECIFIED
Potential Description: NONE SPECIFIED
Alias Name: CAD982444481
Alias Type: EPA Identification Number
Alias Name: 400463
Alias Type: Project Code (Site Code)
Alias Name: 80001495
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Assessment Report
Completed Date: 12/20/1991
Comments: This information may require further review.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Other Instrument
Completed Date: 01/01/1990
Comments: Not reported

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

US FIN ASSUR:
EPA ID: CAD982444481
Provider: UNION BANK OF CALIFORNIA
EPA region: 9
County: SAN BERNARDINO
Mechanism type: TRUST FUND (FULLY FUNDED)
Mechanism ID: Not reported

FILTERRECYCLING SERVICES, INC. (Continued) **1000473043**

Cost estimate: 345988.25
Face value: 345988.25
Effective date: 3/31/2011

EPA ID: CAD982444481
Provider: CHARTIS SPECIALTY INS. COMP.
EPA region: 9
County: SAN BERNARDINO
Mechanism type: INSURANCE
Mechanism ID: EG14852637
Cost estimate: 2000000
Face value: 2000000
Effective date: 1/15/2011

HWP:
EPA Id: CAD982444481
Latitude: 34.06109
Longitude: -117.3706
Facility Type: Permitted - Operating
Cleanup Status: OPERATING PERMIT
Supervisor: WAQAR AHMAD
Site Code: 400463
Assembly District: 47
Senate District: 20
Public Information Officer: CHARLOTTE FADIPE

Activities:
EPA Id: CAD982444481
Facility Type: Permitted - Operating
Unit Names: AEROSOL CAN PUNCTURING - OIL (T5), AEROSOL CAN PUNCTURING - PAINTS (T4), CONTAINER DECONTAMINATIOn (T7), DRUM CRUSHER/BAILER (T3), OILY WATER STORAGE (T6), Unit #1 - SHREDDER/SEPARATOR- OIL WASTE (T1), Unit #10 - Waste Storage (Interior Area 10)(S3), Unit #11 - Waste Storage Exterior Unit - South Area (S4), Unit #2 - SHREDDER/SEPARATOR - PAINT WASTE (T2), Unit #8 - Waste Storage (Interior) (S1), Unit #9 - Waste Storage (Exterior) (S2)
Event Description: Mod Class 2 - 2 or More Units - PUBLIC COMMENT (PUBLIC HEARING)
Actual Date: 03/19/2013

EPA Id: CAD982444481
Facility Type: Permitted - Operating
Unit Names: AEROSOL CAN PUNCTURING - OIL (T5), AEROSOL CAN PUNCTURING - PAINTS (T4), CONTAINER DECONTAMINATIOn (T7), DRUM CRUSHER/BAILER (T3), OILY WATER STORAGE (T6), Unit #1 - SHREDDER/SEPARATOR- OIL WASTE (T1), Unit #10 - Waste Storage (Interior Area 10)(S3), Unit #11 - Waste Storage Exterior Unit - South Area (S4), Unit #2 - SHREDDER/SEPARATOR - PAINT WASTE (T2), Unit #8 - Waste Storage (Interior) (S1), Unit #9 - Waste Storage (Exterior) (S2)
Event Description: Mod Class 2 - 2 or More Units - CEQA
Actual Date: 02/13/2013

EPA Id: CAD982444481
Facility Type: Permitted - Operating
Unit Names: AEROSOL CAN PUNCTURING - OIL (T5), AEROSOL CAN PUNCTURING - PAINTS (T4), CONTAINER DECONTAMINATIOn (T7), DRUM CRUSHER/BAILER (T3), OILY WATER STORAGE (T6), Unit #1 - SHREDDER/SEPARATOR- OIL WASTE (T1), Unit #10 - Waste Storage (Interior Area 10)(S3), Unit #11 - Waste Storage

FILTERRECYCLING SERVICES, INC. (Continued) **1000473043**

Exterior Unit - South Area (S4), Unit #2 - SHREDDER/SEPARATOR - PAINT WASTE (T2), Unit #8 - Waste Storage (Interior) (S1), Unit #9 - Waste Storage (Exterior) (S2)
Event Description: New Operating Permit - 2ND NOTICE OF DEFICIENCY ISSUED
Actual Date: 07/31/1997

EPA Id: CAD982444481
Facility Type: Permitted - Operating
Unit Names: AEROSOL CAN PUNCTURING - OIL (T5), AEROSOL CAN PUNCTURING - PAINTS (T4), CONTAINER DECONTAMINATIOn (T7), DRUM CRUSHER/BAILER (T3), OILY WATER STORAGE (T6), Unit #1 - SHREDDER/SEPARATOR- OIL WASTE (T1), Unit #10 - Waste Storage (Interior Area 10)(S3), Unit #11 - Waste Storage Exterior Unit - South Area (S4), Unit #2 - SHREDDER/SEPARATOR - PAINT WASTE (T2), Unit #8 - Waste Storage (Interior) (S1), Unit #9 - Waste Storage (Exterior) (S2)
Event Description: New Operating Permit - FINAL PART A & PART B RECEIVED
Actual Date: 01/02/1998

EPA Id: CAD982444481
Facility Type: Permitted - Operating
Unit Names: AEROSOL CAN PUNCTURING - OIL (T5), AEROSOL CAN PUNCTURING - PAINTS (T4), CONTAINER DECONTAMINATIOn (T7), DRUM CRUSHER/BAILER (T3), OILY WATER STORAGE (T6), Unit #1 - SHREDDER/SEPARATOR- OIL WASTE (T1), Unit #10 - Waste Storage (Interior Area 10)(S3), Unit #11 - Waste Storage Exterior Unit - South Area (S4), Unit #2 - SHREDDER/SEPARATOR - PAINT WASTE (T2), Unit #8 - Waste Storage (Interior) (S1), Unit #9 - Waste Storage (Exterior) (S2)
Event Description: New Operating Permit - DRAFT PERMIT
Actual Date: 12/31/1997

EPA Id: CAD982444481
Facility Type: Permitted - Operating
Unit Names: AEROSOL CAN PUNCTURING - OIL (T5), AEROSOL CAN PUNCTURING - PAINTS (T4), CONTAINER DECONTAMINATIOn (T7), DRUM CRUSHER/BAILER (T3), OILY WATER STORAGE (T6), Unit #1 - SHREDDER/SEPARATOR- OIL WASTE (T1), Unit #10 - Waste Storage (Interior Area 10)(S3), Unit #11 - Waste Storage Exterior Unit - South Area (S4), Unit #2 - SHREDDER/SEPARATOR - PAINT WASTE (T2), Unit #8 - Waste Storage (Interior) (S1), Unit #9 - Waste Storage (Exterior) (S2)
Event Description: New Operating Permit - 1ST NOTICE OF DEFICIENCY ISSUED
Actual Date: 04/09/1997

EPA Id: CAD982444481
Facility Type: Permitted - Operating
Unit Names: AEROSOL CAN PUNCTURING - OIL (T5), AEROSOL CAN PUNCTURING - PAINTS (T4), CONTAINER DECONTAMINATIOn (T7), DRUM CRUSHER/BAILER (T3), OILY WATER STORAGE (T6), Unit #1 - SHREDDER/SEPARATOR- OIL WASTE (T1), Unit #10 - Waste Storage (Interior Area 10)(S3), Unit #11 - Waste Storage Exterior Unit - South Area (S4), Unit #2 - SHREDDER/SEPARATOR - PAINT WASTE (T2), Unit #8 - Waste Storage (Interior) (S1), Unit #9 - Waste Storage (Exterior) (S2)
Event Description: New Operating Permit - PUBLIC COMMENT (BEGIN)
Actual Date: 12/31/1997

EPA Id: CAD982444481
Facility Type: Permitted - Operating
Unit Names: AEROSOL CAN PUNCTURING - OIL (T5), AEROSOL CAN PUNCTURING - PAINTS

FILTERRECYCLING SERVICES, INC. (Continued) **1000473043**

(T4), CONTAINER DECONTAMINATIOn (T7), DRUM CRUSHER/BAILER (T3), OILY WATER STORAGE (T6), Unit #1 - SHREDDER/SEPARATOR- OIL WASTE (T1), Unit #10 - Waste Storage (Interior Area 10)(S3), Unit #11 - Waste Storage Exterior Unit - South Area (S4), Unit #2 - SHREDDER/SEPARATOR - PAINT WASTE (T2), Unit #8 - Waste Storage (Interior) (S1), Unit #9 - Waste Storage (Exterior) (S2)
Event Description: Mod Class 2 - 2 or More Units - DRAFT PERMIT MODIFICATION
Actual Date: 02/15/2013

EPA Id: CAD982444481
Facility Type: Permitted - Operating
Unit Names: AEROSOL CAN PUNCTURING - OIL (T5), AEROSOL CAN PUNCTURING - PAINTS (T4), CONTAINER DECONTAMINATIOn (T7), DRUM CRUSHER/BAILER (T3), OILY WATER STORAGE (T6), Unit #1 - SHREDDER/SEPARATOR- OIL WASTE (T1), Unit #10 - Waste Storage (Interior Area 10)(S3), Unit #11 - Waste Storage Exterior Unit - South Area (S4), Unit #2 - SHREDDER/SEPARATOR - PAINT WASTE (T2), Unit #8 - Waste Storage (Interior) (S1), Unit #9 - Waste Storage (Exterior) (S2)
Event Description: Mod Class 2 - 2 or More Units - PUBLIC COMMENT (END)
Actual Date: 04/02/2013

EPA Id: CAD982444481
Facility Type: Permitted - Operating
Unit Names: AEROSOL CAN PUNCTURING - OIL (T5), AEROSOL CAN PUNCTURING - PAINTS (T4), CONTAINER DECONTAMINATIOn (T7), DRUM CRUSHER/BAILER (T3), OILY WATER STORAGE (T6), Unit #1 - SHREDDER/SEPARATOR- OIL WASTE (T1), Unit #10 - Waste Storage (Interior Area 10)(S3), Unit #11 - Waste Storage Exterior Unit - South Area (S4), Unit #2 - SHREDDER/SEPARATOR - PAINT WASTE (T2), Unit #8 - Waste Storage (Interior) (S1), Unit #9 - Waste Storage (Exterior) (S2)
Event Description: Mod Class 2 - 2 or More Units - TECHNICAL COMPLETE LETTER
Actual Date: 02/12/2013

EPA Id: CAD982444481
Facility Type: Permitted - Operating
Unit Names: AEROSOL CAN PUNCTURING - OIL (T5), AEROSOL CAN PUNCTURING - PAINTS (T4), CONTAINER DECONTAMINATIOn (T7), DRUM CRUSHER/BAILER (T3), OILY WATER STORAGE (T6), Unit #1 - SHREDDER/SEPARATOR- OIL WASTE (T1), Unit #10 - Waste Storage (Interior Area 10)(S3), Unit #11 - Waste Storage Exterior Unit - South Area (S4), Unit #2 - SHREDDER/SEPARATOR - PAINT WASTE (T2), Unit #8 - Waste Storage (Interior) (S1), Unit #9 - Waste Storage (Exterior) (S2)
Event Description: New Operating Permit - PERMIT APPEALED - APPEAL RECEIVED
Actual Date: 01/22/2002

EPA Id: CAD982444481
Facility Type: Permitted - Operating
Unit Names: AEROSOL CAN PUNCTURING - OIL (T5), AEROSOL CAN PUNCTURING - PAINTS (T4), CONTAINER DECONTAMINATIOn (T7), DRUM CRUSHER/BAILER (T3), OILY WATER STORAGE (T6), Unit #1 - SHREDDER/SEPARATOR- OIL WASTE (T1), Unit #10 - Waste Storage (Interior Area 10)(S3), Unit #11 - Waste Storage Exterior Unit - South Area (S4), Unit #2 - SHREDDER/SEPARATOR - PAINT WASTE (T2), Unit #8 - Waste Storage (Interior) (S1), Unit #9 - Waste Storage (Exterior) (S2)
Event Description: Mod Class 2 - 2 or More Units - APPLICATION PART B RECEIVED
Actual Date: 02/24/2008

FILTERRECYCLING SERVICES, INC. (Continued) **1000473043**

EPA Id: CAD982444481
Facility Type: Permitted - Operating
Unit Names: AEROSOL CAN PUNCTURING - OIL (T5), AEROSOL CAN PUNCTURING - PAINTS (T4), CONTAINER DECONTAMINATIOn (T7), DRUM CRUSHER/BAILER (T3), OILY WATER STORAGE (T6), Unit #1 - SHREDDER/SEPARATOR- OIL WASTE (T1), Unit #10 - Waste Storage (Interior Area 10)(S3), Unit #11 - Waste Storage Exterior Unit - South Area (S4), Unit #2 - SHREDDER/SEPARATOR - PAINT WASTE (T2), Unit #8 - Waste Storage (Interior) (S1), Unit #9 - Waste Storage (Exterior) (S2)
Event Description: Renewal - With Changes - APPLICATION PART B RECEIVED
Actual Date: 07/14/2011

EPA Id: CAD982444481
Facility Type: Permitted - Operating
Unit Names: AEROSOL CAN PUNCTURING - OIL (T5), AEROSOL CAN PUNCTURING - PAINTS (T4), CONTAINER DECONTAMINATIOn (T7), DRUM CRUSHER/BAILER (T3), OILY WATER STORAGE (T6), Unit #1 - SHREDDER/SEPARATOR- OIL WASTE (T1), Unit #10 - Waste Storage (Interior Area 10)(S3), Unit #11 - Waste Storage Exterior Unit - South Area (S4), Unit #2 - SHREDDER/SEPARATOR - PAINT WASTE (T2), Unit #8 - Waste Storage (Interior) (S1), Unit #9 - Waste Storage (Exterior) (S2)
Event Description: New Operating Permit - APPLICATION PART A RECEIVED
Actual Date: 09/24/1993

EPA Id: CAD982444481
Facility Type: Permitted - Operating
Unit Names: AEROSOL CAN PUNCTURING - OIL (T5), AEROSOL CAN PUNCTURING - PAINTS (T4), CONTAINER DECONTAMINATIOn (T7), DRUM CRUSHER/BAILER (T3), OILY WATER STORAGE (T6), Unit #1 - SHREDDER/SEPARATOR- OIL WASTE (T1), Unit #10 - Waste Storage (Interior Area 10)(S3), Unit #11 - Waste Storage Exterior Unit - South Area (S4), Unit #2 - SHREDDER/SEPARATOR - PAINT WASTE (T2), Unit #8 - Waste Storage (Interior) (S1), Unit #9 - Waste Storage (Exterior) (S2)
Event Description: New Operating Permit - PERMIT APPEALED - FINAL DECISION
Actual Date: 10/23/2006

EPA Id: CAD982444481
Facility Type: Permitted - Operating
Unit Names: AEROSOL CAN PUNCTURING - OIL (T5), AEROSOL CAN PUNCTURING - PAINTS (T4), CONTAINER DECONTAMINATIOn (T7), DRUM CRUSHER/BAILER (T3), OILY WATER STORAGE (T6), Unit #1 - SHREDDER/SEPARATOR- OIL WASTE (T1), Unit #10 - Waste Storage (Interior Area 10)(S3), Unit #11 - Waste Storage Exterior Unit - South Area (S4), Unit #2 - SHREDDER/SEPARATOR - PAINT WASTE (T2), Unit #8 - Waste Storage (Interior) (S1), Unit #9 - Waste Storage (Exterior) (S2)
Event Description: New Operating Permit - CALL-IN LETTER ISSUED
Actual Date: 03/31/1994

EPA Id: CAD982444481
Facility Type: Permitted - Operating
Unit Names: AEROSOL CAN PUNCTURING - OIL (T5), AEROSOL CAN PUNCTURING - PAINTS (T4), CONTAINER DECONTAMINATIOn (T7), DRUM CRUSHER/BAILER (T3), OILY WATER STORAGE (T6), Unit #1 - SHREDDER/SEPARATOR- OIL WASTE (T1), Unit #10 - Waste Storage (Interior Area 10)(S3), Unit #11 - Waste Storage Exterior Unit - South Area (S4), Unit #2 - SHREDDER/SEPARATOR - PAINT WASTE (T2), Unit #8 - Waste Storage (Interior) (S1), Unit #9 - Waste Storage (Exterior) (S2)

FILTERRECYCLING SERVICES, INC. (Continued) **1000473043**

Event Description: Mod Class 2 - 2 or More Units - PUBLIC COMMENT (PUBLIC MEETING)
Actual Date: 03/19/2013

EPA Id: CAD982444481
Facility Type: Permitted - Operating
Unit Names: AEROSOL CAN PUNCTURING - OIL (T5), AEROSOL CAN PUNCTURING - PAINTS (T4), CONTAINER DECONTAMINATIOn (T7), DRUM CRUSHER/BAILER (T3), OILY WATER STORAGE (T6), Unit #1 - SHREDDER/SEPARATOR- OIL WASTE (T1), Unit #10 - Waste Storage (Interior Area 10)(S3), Unit #11 - Waste Storage Exterior Unit - South Area (S4), Unit #2 - SHREDDER/SEPARATOR - PAINT WASTE (T2), Unit #8 - Waste Storage (Interior) (S1), Unit #9 - Waste Storage (Exterior) (S2)
Event Description: New Operating Permit - APPLICATION PART B RECEIVED
Actual Date: 04/01/1994

EPA Id: CAD982444481
Facility Type: Permitted - Operating
Unit Names: AEROSOL CAN PUNCTURING - OIL (T5), AEROSOL CAN PUNCTURING - PAINTS (T4), CONTAINER DECONTAMINATIOn (T7), DRUM CRUSHER/BAILER (T3), OILY WATER STORAGE (T6), Unit #1 - SHREDDER/SEPARATOR- OIL WASTE (T1), Unit #10 - Waste Storage (Interior Area 10)(S3), Unit #11 - Waste Storage Exterior Unit - South Area (S4), Unit #2 - SHREDDER/SEPARATOR - PAINT WASTE (T2), Unit #8 - Waste Storage (Interior) (S1), Unit #9 - Waste Storage (Exterior) (S2)
Event Description: New Operating Permit - FINAL PERMIT (EFFECTIVE)
Actual Date: 01/21/2002

EPA Id: CAD982444481
Facility Type: Permitted - Operating
Unit Names: AEROSOL CAN PUNCTURING - OIL (T5), AEROSOL CAN PUNCTURING - PAINTS (T4), CONTAINER DECONTAMINATIOn (T7), DRUM CRUSHER/BAILER (T3), OILY WATER STORAGE (T6), Unit #1 - SHREDDER/SEPARATOR- OIL WASTE (T1), Unit #10 - Waste Storage (Interior Area 10)(S3), Unit #11 - Waste Storage Exterior Unit - South Area (S4), Unit #2 - SHREDDER/SEPARATOR - PAINT WASTE (T2), Unit #8 - Waste Storage (Interior) (S1), Unit #9 - Waste Storage (Exterior) (S2)
Event Description: New Operating Permit - PUBLIC COMMENT (PUBLIC MEETING)
Actual Date: 03/26/1998

EPA Id: CAD982444481
Facility Type: Permitted - Operating
Unit Names: AEROSOL CAN PUNCTURING - OIL (T5), AEROSOL CAN PUNCTURING - PAINTS (T4), CONTAINER DECONTAMINATIOn (T7), DRUM CRUSHER/BAILER (T3), OILY WATER STORAGE (T6), Unit #1 - SHREDDER/SEPARATOR- OIL WASTE (T1), Unit #10 - Waste Storage (Interior Area 10)(S3), Unit #11 - Waste Storage Exterior Unit - South Area (S4), Unit #2 - SHREDDER/SEPARATOR - PAINT WASTE (T2), Unit #8 - Waste Storage (Interior) (S1), Unit #9 - Waste Storage (Exterior) (S2)
Event Description: New Operating Permit - PUBLIC COMMENT (END)
Actual Date: 02/14/1998

EPA Id: CAD982444481
Facility Type: Permitted - Operating
Unit Names: AEROSOL CAN PUNCTURING - OIL (T5), AEROSOL CAN PUNCTURING - PAINTS (T4), CONTAINER DECONTAMINATIOn (T7), DRUM CRUSHER/BAILER (T3), OILY WATER STORAGE (T6), Unit #1 - SHREDDER/SEPARATOR- OIL WASTE (T1), Unit #10 - Waste Storage (Interior Area 10)(S3), Unit #11 - Waste Storage

FILTERRECYCLING SERVICES, INC. (Continued) **1000473043**

Exterior Unit - South Area (S4), Unit #2 - SHREDDER/SEPARATOR - PAINT WASTE (T2), Unit #8 - Waste Storage (Interior) (S1), Unit #9 - Waste Storage (Exterior) (S2)
Event Description: New Operating Permit - 3RD NOTICE OF DEFICIENCY ISSUED
Actual Date: 08/26/1997

EPA Id: CAD982444481
Facility Type: Permitted - Operating
Unit Names: AEROSOL CAN PUNCTURING - OIL (T5), AEROSOL CAN PUNCTURING - PAINTS (T4), CONTAINER DECONTAMINATIOn (T7), DRUM CRUSHER/BAILER (T3), OILY WATER STORAGE (T6), Unit #1 - SHREDDER/SEPARATOR- OIL WASTE (T1), Unit #10 - Waste Storage (Interior Area 10)(S3), Unit #11 - Waste Storage Exterior Unit - South Area (S4), Unit #2 - SHREDDER/SEPARATOR - PAINT WASTE (T2), Unit #8 - Waste Storage (Interior) (S1), Unit #9 - Waste Storage (Exterior) (S2)
Event Description: Mod Class 2 - 2 or More Units - PUBLIC COMMENT (BEGIN)
Actual Date: 02/15/2013

EPA Id: CAD982444481
Facility Type: Permitted - Operating
Unit Names: AEROSOL CAN PUNCTURING - OIL (T5), AEROSOL CAN PUNCTURING - PAINTS (T4), CONTAINER DECONTAMINATIOn (T7), DRUM CRUSHER/BAILER (T3), OILY WATER STORAGE (T6), Unit #1 - SHREDDER/SEPARATOR- OIL WASTE (T1), Unit #10 - Waste Storage (Interior Area 10)(S3), Unit #11 - Waste Storage Exterior Unit - South Area (S4), Unit #2 - SHREDDER/SEPARATOR - PAINT WASTE (T2), Unit #8 - Waste Storage (Interior) (S1), Unit #9 - Waste Storage (Exterior) (S2)
Event Description: Mod Class 2 - 2 or More Units - FINAL PART A & PART B RECEIVED
Actual Date: 04/13/2011

EPA Id: CAD982444481
Facility Type: Permitted - Operating
Unit Names: AEROSOL CAN PUNCTURING - OIL (T5), AEROSOL CAN PUNCTURING - PAINTS (T4), CONTAINER DECONTAMINATIOn (T7), DRUM CRUSHER/BAILER (T3), OILY WATER STORAGE (T6), Unit #1 - SHREDDER/SEPARATOR- OIL WASTE (T1), Unit #10 - Waste Storage (Interior Area 10)(S3), Unit #11 - Waste Storage Exterior Unit - South Area (S4), Unit #2 - SHREDDER/SEPARATOR - PAINT WASTE (T2), Unit #8 - Waste Storage (Interior) (S1), Unit #9 - Waste Storage (Exterior) (S2)
Event Description: New Operating Permit - FINAL PERMIT
Actual Date: 12/17/2001

Alias:
EPA Id: CAD982444481
Facility Type: Permitted - Operating
Alias Type: Project Code (Site Code)
Alias: 400463

CA Financial Assurance 1:
EPA ID Number: CAD982444481
Closure Mechanism: Trust
Closure Amount: 309,879
Post Clousure Mechanism: Not reported
Post Clousure Amount: Not reported
Corrective Action Mechanism: Not reported

FILTERRECYCLING SERVICES, INC. (Continued) **1000473043**

Corrective Action Amount: Not reported
Sudden Mecahanism Type: Ins
Sudden Mecahanism Amount: 2,000,000
Non Sudden Mecahanism Type: Not reported
Non Sudden Mecahanism Amount: Not reported

CA WDS:
Facility ID: Santa Ana River 36I012307
Facility Type: Industrial - Facility that treats and/or disposes of liquid or semisolid wastes from any servicing, producing, manufacturing or processing operation of whatever nature, including mining, gravel washing, geothermal operations, air conditioning, ship building and repairing, oil production, storage and disposal operations, water pumping.
Facility Status: Active - Any facility with a continuous or seasonal discharge that is under Waste Discharge Requirements.
NPDES Number: CAS000001 The 1st 2 characters designate the state. The remaining 7 are assigned by the Regional Board
Subregion: 8
Facility Telephone: 9094212012
Facility Contact: WADE RIDDERING
Agency Name: FILTER RECYCLING SERVICE
Agency Address: 2230 RIVERSIDE AVE.
Agency City,St,Zip: RIALTO 92317
Agency Contact: JOHN BENNETT JR.
Agency Telephone: 9094211630
Agency Type: Private
SIC Code: 0
SIC Code 2: Not reported
Primary Waste: Not reported
Primary Waste Type: Not reported
Secondary Waste: Not reported
Secondary Waste Type: Not reported
Design Flow: 0
Baseline Flow: 0
Reclamation: Not reported
POTW: Not reported
Treat To Water: Minor Threat to Water Quality. A violation of a regional board order should cause a relatively minor impairment of beneficial uses compared to a major or minor threat. Not: All nurds without a TTWQ will be considered a minor threat to water quality unless coded at a higher Level. A Zero (0) may be used to code those NURDS that are found to represent no threat to water quality.
Complexity: Category C - Facilities having no waste treatment systems, such as cooling water dischargers or thosewho must comply through best management practices, facilities with passive waste treatment and disposal systems, such as septic systems with subsurface disposal, or dischargers having waste storage systems with land disposal such as dairy waste ponds.

AX417 **FILTER RECYCLING SERVICES, INC.** **SWF/LF** **S106800136**
SW **180 WEST MONTE AVENUE** **N/A**
1/2-1 **BLOOMINGTON, CA**
0.613 mi.
3235 ft. **Site 15 of 30 in cluster AX**

Relative:
Lower

Actual:
1007 ft.

SWF/LF (SWIS):

Region:	STATE
Facility ID:	36-AA-0424
Lat/Long:	34.0621599 / -117.37245
Owner Name:	Filter Recycling Services, Inc.
Owner Telephone:	9098734141
Owner Address:	Not reported
Owner Address2:	2230 South Riverside Avenue
Owner City,St,Zip:	Rialto, CA 92316
Operational Status:	Active
Operator:	Filter Recycling Services, Inc.
Operator Phone:	9094241630
Operator Address:	Jon L. Bennett Jr.
Operator Address2:	P.O. Box 449
Operator City,St,Zip:	Colton, CA 92324-0449
Permit Date:	04/12/2012
Permit Status:	Notification
Permitted Acreage:	1
Activity:	Contaminated Soil Operation, Xfer
Regulation Status:	Notification
Landuse Name:	Not reported
GIS Source:	Map
Category:	Transfer/Processing
Unit Number:	01
Inspection Frequency:	Quarterly
Accepted Waste:	Contaminated soil
Closure Date:	Not reported
Closure Type:	Not reported
Disposal Acreage:	Not reported
SWIS Num:	36-AA-0424
Waste Discharge Requirement Num:	Not reported
Program Type:	Not reported
Permitted Throughput with Units:	250
Actual Throughput with Units:	Tons/day
Permitted Capacity with Units:	48000
Remaining Capacity:	Not reported
Remaining Capacity with Units:	Tons/year

AX418 **FILTER RECYCLING SERVICES, INC.** **HWT** **S108487245**
SW **180 WEST MONTE AVENUE** **N/A**
1/2-1 **RIALTO, CA 92316**
0.613 mi.
3235 ft. **Site 16 of 30 in cluster AX**

Relative:
Lower

Actual:
1007 ft.

HWT:

Reg Num:	2950
Expiration Date:	04/30/2013

AX419 **TOSCO COLTON TERMINAL** **UST** **U003784683**
SW **2301 S RIVERSIDE AVE** **N/A**
1/2-1 **RIALTO, CA 92376**
0.618 mi.
3264 ft. **Site 17 of 30 in cluster AX**

Relative:
Lower

Actual:
1006 ft.

UST:
Facility ID: 86008629
Latitude: 34.10923
Longitude: -117.37651

AY420 **RESIDENCE** **San Bern. Co. Permit** **S108202595**
West **515 W VALLEY BLVD** **N/A**
1/2-1 **RIALTO, CA 92376**
0.620 mi.
3272 ft. **Site 8 of 12 in cluster AY**

Relative:
Higher

Actual:
1081 ft.

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0008305
Owner: C.E. BAILEY
Permit Number: PT0014523
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: INACTIVE
Expiration Date: 04/30/2004

BB421 **EDR US Hist Auto Stat** **1015255097**
West **1611 S LILAC AVE** **N/A**
1/2-1 **BLOOMINGTON, CA 92316**
0.625 mi.
3298 ft. **Site 1 of 4 in cluster BB**

Relative:
Higher

Actual:
1089 ft.

EDR Historical Auto Stations:
Name: AGENCY AUTOMOTIVE SERVICE
Year: 1999
Address: 1611 S LILAC AVE

Name: AGENCY AUTOMOTIVE SERVICE
Year: 2005
Address: 1611 S LILAC AVE

Name: AGENCY AUTOMOTIVE SERVICE
Year: 2006
Address: 1611 S LILAC AVE

Name: AGENCY AUTOMOTIVE SERVICE
Year: 2007
Address: 1611 S LILAC AVE

Name: AGENCY AUTOMOTIVE
Year: 2010
Address: 1611 S LILAC AVE

Name: AGENCY AUTOMOTIVE
Year: 2011
Address: 1611 S LILAC AVE

Name: AGENCY AUTOMOTIVE

(Continued) **1015255097**

Year: 2012
Address: 1611 S LILAC AVE

BB422 **AGENCY AUTOMOTIVE, INC.** **San Bern. Co. Permit** **S104763345**
West **1611 S LILAC AVE** **HAULERS** **N/A**
1/2-1 **BLOOMINGTON, CA 92323**
0.625 mi.
3298 ft. **Site 2 of 4 in cluster BB**

Relative:
Higher

Actual:
1089 ft.

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0000713
Owner: MAINUDDIN CHOWDHURY
Permit Number: PT0000561
Permit Category: SPECIAL HANDLER
Facility Status: ACTIVE
Expiration Date: 08/31/2013

Region: SAN BERNARDINO
Facility ID: FA0000713
Owner: MAINUDDIN CHOWDHURY
Permit Number: PT0000562
Permit Category: SPECIAL GENERATOR
Facility Status: ACTIVE
Expiration Date: 08/31/2013

HAULERS:
Facility ID: 1425459
Facility Phone: (909) 820-7090

BB423 **PACIFIC ORNAMENTAL IRON** **San Bern. Co. Permit** **S106911022**
West **1625 S LILAC AVE** **N/A**
1/2-1 **RIALTO, CA 92376**
0.626 mi.
3304 ft. **Site 3 of 4 in cluster BB**

Relative:
Higher

Actual:
1089 ft.

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0005193
Owner: IBARRA, TEOFILO
Permit Number: PT0009343
Permit Category: SPECIAL HANDLER
Facility Status: INACTIVE
Expiration Date: 11/30/2001

Region: SAN BERNARDINO
Facility ID: FA0005193
Owner: IBARRA, TEOFILO
Permit Number: PT0009344
Permit Category: SPECIAL GENERATOR
Facility Status: INACTIVE
Expiration Date: 11/30/2001

BB424 **DOOR COMPANY OF SAN BERNARDINO** **HIST UST** **U001574571**
West **1591 S LILAC AVE** **SWEEPS UST** **N/A**
1/2-1 **BLOOMINGTON, CA 92316**
0.626 mi.
3305 ft. **Site 4 of 4 in cluster BB**

Relative:
Higher

Actual:
1090 ft.

HIST UST:

Region:	STATE
Facility ID:	00000009399
Facility Type:	Other
Other Type:	DOOR BUSINESS
Total Tanks:	0001
Contact Name:	Not reported
Telephone:	7148770610
Owner Name:	DOOR COMPANY OF SAN BERNARDINO
Owner Address:	1591 S. LILAC AVENUE
Owner City,St,Zip:	BLOOMINGTON, CA 92316
Tank Num:	001
Container Num:	1
Year Installed:	Not reported
Tank Capacity:	00000000
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Tank Construction:	Not reported
Leak Detection:	None

SWEEPS UST:

Status:	Not reported
Comp Number:	9399
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	36-000-009399-000001
Actv Date:	Not reported
Capacity:	1
Tank Use:	M.V. FUEL
Stg:	PRODUCT
Content:	REG UNLEADED
Number Of Tanks:	1

AY425 **EL TORO SPICES** **SWEEPS UST** **S106925780**
West **1730 S LILAC** **N/A**
1/2-1 **BLOOMINGTON, CA 92316**
0.627 mi.
3313 ft. **Site 9 of 12 in cluster AY**

Relative:
Lower

Actual:
1078 ft.

SWEEPS UST:

Status:	Active
Comp Number:	11741
Number:	9
Board Of Equalization:	44-020362
Referral Date:	03-19-92
Action Date:	03-19-92
Created Date:	09-23-88

EL TORO SPICES (Continued) **S106925780**

Tank Status:	A
Owner Tank Id:	Not reported
Swrcb Tank Id:	36-000-011741-000001
Actv Date:	09-23-88
Capacity:	1
Tank Use:	UNKNOWN
Stg:	P
Content:	UNKNOWN
Number Of Tanks:	1

AX426 **ENVIRONMENTAL LOGISTICS INC** **RCRA NonGen / NLR** **1009398261**
SW **140 W MONTE AVE** **PADS** **CAR000172460**
1/2-1 **BLOOMINGTON, CA 92316** **HAZNET**
0.628 mi. **HWT**
3317 ft. **Site 18 of 30 in cluster AX** **MWMP**

Relative:
Lower

Actual:
1009 ft.

RCRA NonGen / NLR:

Date form received by agency:	03/29/2006
Facility name:	ENVIRONMENTAL LOGISTICS INC
Facility address:	140 W MONTE AVE BLOOMINGTON, CA 92316
EPA ID:	CAR000172460
Contact:	WADE RIDDERING
Contact address:	140 W MONTE AVE BLOOMINGTON, CA 92316
Contact country:	US
Contact telephone:	909-873-4141
Contact email:	WADE_RIDDERING@FILTERRECYCLING.COM
EPA Region:	09
Land type:	Private
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	JON AND TRACY BENNETT
Owner/operator address:	140 W MONTE AVE BLOOMINGTON, CA 92316
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	08/01/2004
Owner/Op end date:	Not reported

Owner/operator name:	ENVIRONMENTAL LOGISTICS INC
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	03/01/2006
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No

ENVIRONMENTAL LOGISTICS INC (Continued) **1009398261**

Recycler of hazardous waste:	No
Transporter of hazardous waste:	Yes
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	Yes

Hazardous Waste Summary:

Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002
Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Waste code: D003
Waste name: A MATERIAL IS CONSIDERED TO BE A REACTIVE HAZARDOUS WASTE IF IT IS NORMALLY UNSTABLE, REACTS VIOLENTLY WITH WATER, GENERATES TOXIC GASES WHEN EXPOSED TO WATER OR CORROSIVE MATERIALS, OR IF IT IS CAPABLE OF DETONATION OR EXPLOSION WHEN EXPOSED TO HEAT OR A FLAME. ONE EXAMPLE OF SUCH WASTE WOULD BY WASTE GUNPOWDER.

Waste code: D004
Waste name: ARSENIC

Waste code: D005
Waste name: BARIUM

Waste code: D006
Waste name: CADMIUM

Waste code: D007
Waste name: CHROMIUM

Waste code: D008
Waste name: LEAD

Waste code: D009
Waste name: MERCURY

ENVIRONMENTAL LOGISTICS INC (Continued) **1009398261**

Waste code: D010
Waste name: SELENIUM

Waste code: D011
Waste name: SILVER

Waste code: D018
Waste name: BENZENE

Waste code: D019
Waste name: CARBON TETRACHLORIDE

Waste code: D035
Waste name: METHYL ETHYL KETONE

Waste code: D039
Waste name: TETRACHLOROETHYLENE

Waste code: D040
Waste name: TRICHLOROETHYLENE

Waste code: D043
Waste name: VINYL CHLORIDE

Waste code: F001
Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLOROETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE, AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste code: F002
Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste code: F003
Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

ENVIRONMENTAL LOGISTICS INC (Continued) **1009398261**

Waste code: F004
Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: CRESOLS AND CRESYLIC ACID, AND NITROBENZENE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste code: F005
Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste code: F006
Waste name: WASTEWATER TREATMENT SLUDGES FROM ELECTROPLATING OPERATIONS EXCEPT FROM THE FOLLOWING PROCESSES: (1) SULFURIC ACID ANODIZING OF ALUMINUM; (2) TIN PLATING ON CARBON STEEL; (3) ZINC PLATING (SEGREGATED BASIS) ON CARBON STEEL; (4) ALUMINUM OR ZINC-ALUMINUM PLATING ON CARBON STEEL; (5) CLEANING/STRIPPING ASSOCIATED WITH TIN, ZINC AND ALUMINUM PLATING ON CARBON STEEL; AND (6) CHEMICAL ETCHING AND MILLING OF ALUMINUM.

Waste code: F007
Waste name: SPENT CYANIDE PLATING BATH SOLUTIONS FROM ELECTROPLATING OPERATIONS

Waste code: F008
Waste name: PLATING BATH RESIDUES FROM THE BOTTOM OF PLATING BATHS FROM ELECTROPLATING OPERATIONS WHERE CYANIDES ARE USED IN THE PROCESS.

Waste code: F009
Waste name: SPENT STRIPPING AND CLEANING BATH SOLUTIONS FROM ELECTROPLATING OPERATIONS WHERE CYANIDES ARE USED IN THE PROCESS.

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Transporters - General
Date violation determined: 08/26/2009
Date achieved compliance: 08/27/2009
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 08/27/2009
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: State Statute or Regulation
Date violation determined: 08/26/2009
Date achieved compliance: 08/27/2009
Violation lead agency: State

ENVIRONMENTAL LOGISTICS INC (Continued) **1009398261**

Enforcement action: WRITTEN INFORMAL
Enforcement action date: 08/27/2009
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 08/26/2009
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Transporters - General
Date achieved compliance: 08/27/2009
Evaluation lead agency: State

Evaluation date: 08/26/2009
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: State Statute or Regulation
Date achieved compliance: 08/27/2009
Evaluation lead agency: State

PADS:
EPAID: CAR000172460
Facility name: ENVIRONMENTAL LOGISTICS, INC.
Facility Address: 140 W. MONTE AVE.
BLOOMINGTON, CA 92316
Facility country: US
Generator: No
Storer: No
Transporter: Yes
Disposer: No
Research facility: No
Smelter: No
Facility owner name: ENVIRONMENTAL LOGISTICS, INC.
Contact title: Not reported
Contact name: WADE RIDDERING
Contact tel: (909)873-4141
Contact extension: Not reported
Mailing address: 140 W. MONTE AVE.
BLOOMINGTON, CA 92316
Mailing country: US
Cert. title: Not reported
Cert. name: Not reported
Cert. date: 3/22/2006
Date received: 7/13/2006

HAZNET:
Year: 2011
Gepaid: CAR000172460
Contact: WADE RIDDERING
Telephone: 9095461354
Mailing Name: Not reported
Mailing Address: 140 W MONTE AVE
Mailing City,St,Zip: BLOOMINGTON, CA 923160000
Gen County: Not reported
TSD EPA ID: CAD982444481

ENVIRONMENTAL LOGISTICS INC (Continued) **1009398261**

TSD County: Not reported
Waste Category: Aqueous solution with total organic residues less than 10 percent
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.231
Facility County: San Bernardino

Year: 2011
Gepaid: CAR000172460
Contact: WADE RIDDERING
Telephone: 9095461354
Mailing Name: Not reported
Mailing Address: 140 W MONTE AVE
Mailing City,St,Zip: BLOOMINGTON, CA 923160000
Gen County: Not reported
TSD EPA ID: CAD982444481
TSD County: Not reported
Waste Category: Waste oil and mixed oil
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 9.405
Facility County: San Bernardino

Year: 2010
Gepaid: CAR000172460
Contact: WADE RIDDERING
Telephone: 9095461354
Mailing Name: Not reported
Mailing Address: 140 W MONTE AVE
Mailing City,St,Zip: BLOOMINGTON, CA 923160000
Gen County: Not reported
TSD EPA ID: CAD982444481
TSD County: Not reported
Waste Category: Waste oil and mixed oil
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 10.089
Facility County: San Bernardino

Year: 2010
Gepaid: CAR000172460
Contact: WADE RIDDERING
Telephone: 9095461354
Mailing Name: Not reported
Mailing Address: 140 W MONTE AVE
Mailing City,St,Zip: BLOOMINGTON, CA 923160000
Gen County: Not reported
TSD EPA ID: CAD982444481
TSD County: Not reported
Waste Category: Aqueous solution with total organic residues less than 10 percent
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.462
Facility County: San Bernardino

Year: 2010
Gepaid: CAR000172460

ENVIRONMENTAL LOGISTICS INC (Continued) **1009398261**

Contact: WADE RIDDERING
Telephone: 9095461354
Mailing Name: Not reported
Mailing Address: 140 W MONTE AVE
Mailing City,St,Zip: BLOOMINGTON, CA 923160000
Gen County: Not reported
TSD EPA ID: CAD982444481
TSD County: Not reported
Waste Category: Aqueous solution with total organic residues less than 10 percent
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.987
Facility County: San Bernardino

Click this hyperlink while viewing on your computer to access
7 additional CA_HAZNET: record(s) in the EDR Site Report.

HWT:
Reg Num: 5508
Expiration Date: 12/31/2012

MWMP:
Facility Type: MEDICAL WASTE TRANSPORTERS - March 6, 2013
Sr No: 41
Contact Name: Not reported
Contact Phone: 909-546-1354
Method: Not reported
Registration Number: 5508

AY427 **EDR US Hist Auto Stat** **1015273093**
West **1750 S LILAC AVE** **N/A**
1/2-1 **BLOOMINGTON, CA 92316**
0.629 mi.
3322 ft. **Site 10 of 12 in cluster AY**

Relative:
Lower

Actual:
1076 ft.

EDR Historical Auto Stations:
Name: J & J AUTOMOTIVE
Year: 2005
Address: 1750 S LILAC AVE

Name: J & J AUTOMOTIVE
Year: 2006
Address: 1750 S LILAC AVE

Name: J & J AUTOMOTIVE
Year: 2007
Address: 1750 S LILAC AVE

Name: J & J AUTOMOTIVE
Year: 2008
Address: 1750 S LILAC AVE

Name: J & J AUTOMOTIVE
Year: 2009
Address: 1750 S LILAC AVE

Name: J & J AUTOMOTIVE

(Continued) **1015273093**

Year: 2010
Address: 1750 S LILAC AVE

AY428 **MORENO VALLEY SEPTIC SVC** **SWEEPS UST** **S106929618**
West **1770 S LILAC** **N/A**
1/2-1 **BLOOMINGTON, CA 92316**
0.632 mi.
3336 ft. **Site 11 of 12 in cluster AY**

Relative:
Lower

Actual:
1074 ft.

SWEEPS UST:
Status: Active
Comp Number: 11740
Number: 1
Board Of Equalization: 44-020361
Referral Date: 03-19-92
Action Date: 03-19-92
Created Date: 09-13-88
Tank Status: A
Owner Tank Id: Not reported
Swrcb Tank Id: 36-000-011740-000001
Actv Date: 09-13-88
Capacity: 1
Tank Use: UNKNOWN
Stg: P
Content: UNKNOWN
Number Of Tanks: 3

Status: Active
Comp Number: 11740
Number: 1
Board Of Equalization: 44-020361
Referral Date: 03-19-92
Action Date: 03-19-92
Created Date: 09-13-88
Tank Status: A
Owner Tank Id: Not reported
Swrcb Tank Id: 36-000-011740-000002
Actv Date: 09-13-88
Capacity: 1
Tank Use: UNKNOWN
Stg: P
Content: UNKNOWN
Number Of Tanks: Not reported

Status: Active
Comp Number: 11740
Number: 1
Board Of Equalization: 44-020361
Referral Date: 03-19-92
Action Date: 03-19-92
Created Date: 09-13-88
Tank Status: A
Owner Tank Id: Not reported
Swrcb Tank Id: 36-000-011740-000003
Actv Date: 09-13-88
Capacity: 1
Tank Use: UNKNOWN
Stg: P

MORENO VALLEY SEPTIC SVC (Continued) **S106929618**

Content: UNKNOWN
Number Of Tanks: Not reported

AY429 **EDR US Hist Auto Stat** **1015274735**
West **1770 S LILAC AVE** **N/A**
1/2-1 **BLOOMINGTON, CA 92316**
0.632 mi.
3336 ft. **Site 12 of 12 in cluster AY**

Relative:
Lower

EDR Historical Auto Stations:
Name: J & J AUTO REPAIR
Year: 2004
Actual: Address: 1770 S LILAC AVE
1074 ft.

AX430 **UNOCAL CORP** **HIST UST** **U001574568**
SW **2301 S RIVERSIDE AVE** **SWEEPS UST** **N/A**
1/2-1 **BLOOMINGTON, CA 92316** **San Bern. Co. Permit**
0.633 mi. **EMI**
3340 ft. **Site 19 of 30 in cluster AX**

Relative:
Lower

HIST UST:
Region: STATE
Facility ID: 00000001338
Actual: Facility Type: Other
1005 ft. Other Type: DISTRIBUTOR
Total Tanks: 0006
Contact Name: R. D. VILLA
Telephone: 7148772700
Owner Name: UNION OIL CO. OF CALIFORNIA
Owner Address: 461 S. BOYLSTON ST.
Owner City,St,Zip: LOS ANGELES, CA 90017

Tank Num: 001
Container Num: 1
Year Installed: 1971
Tank Capacity: 00010000
Tank Used for: PRODUCT
Type of Fuel: Not reported
Tank Construction: Not reported
Leak Detection: Visual

Tank Num: 001
Container Num: 6
Year Installed: Not reported
Tank Capacity: 00000000
Tank Used for: WASTE
Type of Fuel: Not reported
Tank Construction: Not reported
Leak Detection: Visual

Tank Num: 002
Container Num: 2
Year Installed: 1978
Tank Capacity: 00012000
Tank Used for: WASTE
Type of Fuel: Not reported

UNOCAL CORP (Continued) **U001574568**

Tank Construction: 1/4 inches
Leak Detection: Visual

Tank Num: 003
Container Num: 3
Year Installed: Not reported
Tank Capacity: 00005000
Tank Used for: WASTE
Type of Fuel: Not reported
Tank Construction: Not reported
Leak Detection: Visual

Tank Num: 004
Container Num: 4
Year Installed: 1974
Tank Capacity: 00012000
Tank Used for: PRODUCT
Type of Fuel: DIESEL
Tank Construction: Not reported
Leak Detection: Visual

Tank Num: 005
Container Num: 5
Year Installed: 1982
Tank Capacity: 00001000
Tank Used for: WASTE
Type of Fuel: WASTE OIL
Tank Construction: Not reported
Leak Detection: Visual

Tank Num: 006
Container Num: 7
Year Installed: Not reported
Tank Capacity: 00000000
Tank Used for: Not reported
Type of Fuel: Not reported
Tank Construction: Not reported
Leak Detection: Visual

SWEEPS UST:
Status: Active
Comp Number: 1338
Number: 9
Board Of Equalization: 44-019801
Referral Date: 03-19-92
Action Date: 03-19-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 1
Swrcb Tank Id: 36-000-001338-000001
Actv Date: 08-23-88
Capacity: 10000
Tank Use: M.V. FUEL
Stg: P
Content: Not reported
Number Of Tanks: 3

UNOCAL CORP (Continued) **U001574568**

Status: Active
Comp Number: 1338
Number: 9
Board Of Equalization: 44-019801
Referral Date: 03-19-92
Action Date: 03-19-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 2
Swrcb Tank Id: 36-000-001338-000002
Actv Date: 08-23-88
Capacity: 12000
Tank Use: UNKNOWN
Stg: W
Content: Not reported
Number Of Tanks: Not reported

Status: Active
Comp Number: 1338
Number: 9
Board Of Equalization: 44-019801
Referral Date: 03-19-92
Action Date: 03-19-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 4
Swrcb Tank Id: 36-000-001338-000004
Actv Date: 08-23-88
Capacity: 12000
Tank Use: M.V. FUEL
Stg: P
Content: DIESEL
Number Of Tanks: Not reported

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0006727
Owner: PHILLIPS 66 REFINING CO
Permit Number: PT0025491
Permit Category: EPCRA FACILITY
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0006727
Owner: PHILLIPS 66 REFINING CO
Permit Number: PT0002104
Permit Category: APSA 1,000,001-10,000,000 GAL FAC CAPACITY
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0006727
Owner: PHILLIPS 66 REFINING CO
Permit Number: PT0002108
Permit Category: HAZARDOUS WASTE GENERATOR - 0-10 EMPLOYEES
Facility Status: ACTIVE

UNOCAL CORP (Continued) **U001574568**

Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0006727
Owner: PHILLIPS 66 REFINING CO
Permit Number: PT0002102
Permit Category: HAZMAT HANDLER 0-10 EMPLOYEES (W/GEN PRMT)
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0006727
Owner: PHILLIPS 66 REFINING CO
Permit Number: PT0012330
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0006727
Owner: PHILLIPS 66 REFINING CO
Permit Number: PT0012331
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 10/31/2013

EMI:

Year:	2002
County Code:	36
Air Basin:	SC
Facility ID:	800364
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	7
Reactive Organic Gases Tons/Yr:	7
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	2003
County Code:	36
Air Basin:	SC
Facility ID:	800364
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	7
Reactive Organic Gases Tons/Yr:	7
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0

UNOCAL CORP (Continued) **U001574568**

SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0
Year:	2004
County Code:	36
Air Basin:	SC
Facility ID:	800364
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Y
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	6.90074
Reactive Organic Gases Tons/Yr:	6.87
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0
Year:	2005
County Code:	36
Air Basin:	SC
Facility ID:	800364
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	5.89619
Reactive Organic Gases Tons/Yr:	5.76340158
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0
Year:	2006
County Code:	36
Air Basin:	SC
Facility ID:	800364
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	7.322085733189595710
Reactive Organic Gases Tons/Yr:	6.133
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0
Year:	2007
County Code:	36

UNOCAL CORP (Continued) **U001574568**

Air Basin:	SC
Facility ID:	800364
Air District Name:	SC
SIC Code:	5541
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	4.497148205291537294
Reactive Organic Gases Tons/Yr:	4.4223713087725
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	2007
County Code:	36
Air Basin:	SC
Facility ID:	800364
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	6.290423751334544790
Reactive Organic Gases Tons/Yr:	6.133
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

AX431 **GW CLEANUP-COLTON TERMINA** **Cortese** **S105022790**
SW **2301 RIVERSIDE** **HIST CORTESE** **N/A**
1/2-1 **BLOOMINGTON, CA 92316** **ENF**
0.633 mi.
3340 ft. **Site 20 of 30 in cluster AX**

Relative:
Lower

Actual:
1005 ft.

CORTESE:

Region:	CORTESE
Envirostor Id:	Not reported
Site/Facility Type:	Not reported
Cleanup Status:	Not reported
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	CORTESE
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	8
WID Id:	8 362310N01
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported

GW CLEANUP-COLTON TERMINA (Continued) **S105022790**

Region:	CORTESE
Envirostor Id:	Not reported
Site/Facility Type:	Not reported
Cleanup Status:	Not reported
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	CORTESE
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	8
WID Id:	8 362310N01
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported

CORTESE:

Region:	CORTESE
Facility County Code:	36
Reg By:	WBC&D
Reg Id:	8 362310N01

ENF:

Region:	8
Facility Id:	228236
Agency Name:	Kinder Morgan Energy Partners LP
Place Type:	Manufacturing
Place Subtype:	Manufacturing NEC
Facility Type:	Industrial
Agency Type:	Privately-Owned Business
# Of Agencies:	1
Place Latitude:	Not reported
Place Longitude:	Not reported
SIC Code 1:	4959
SIC Desc 1:	Sanitary Services, NEC
SIC Code 2:	Not reported
SIC Desc 2:	Not reported
SIC Code 3:	Not reported
SIC Desc 3:	Not reported
NAICS Code 1:	Not reported
NAICS Desc 1:	Not reported
NAICS Code 2:	Not reported
NAICS Desc 2:	Not reported
NAICS Code 3:	Not reported
NAICS Desc 3:	Not reported
# Of Places:	1
Source Of Facility:	Reg Meas
Design Flow:	Not reported
Threat To Water Quality:	Not reported
Complexity:	Not reported
Pretreatment:	Not reported
Facility Waste Type:	Not reported

GW CLEANUP-COLTON TERMINA (Continued) **S105022790**

Facility Waste Type 2:	Not reported
Facility Waste Type 3:	Not reported
Facility Waste Type 4:	Not reported
Program:	UNREGS
# Of Programs:	1
WDID:	8 362310N01
Reg Measure Id:	158780
Reg Measure Type:	Unregulated
Region:	8
Order #:	Not reported
Npdes# CA#:	Not reported
Major-Minor:	Not reported
Npdes Type:	Not reported
Reclamation:	Not reported
Dredge Fill Fee:	Not reported
301H:	Not reported
Application Fee Amt Received:	Not reported
Status:	Never Active
Status Date:	02/21/2013
Effective Date:	Not reported
Expiration/Review Date:	Not reported
Termination Date:	Not reported
WDR Review - Amend:	Not reported
WDR Review - Revise/Renew:	Not reported
WDR Review - Rescind:	Not reported
WDR Review - No Action Required:	Not reported
WDR Review - Pending:	Not reported
WDR Review - Planned:	Not reported
Status Enrollee:	N
Individual/General:	I
Fee Code:	Not reported
Direction/Voice:	Passive
Enforcement Id(EID):	224899
Region:	8
Order / Resolution Number:	87-151
Enforcement Action Type:	Clean-up and Abatement Order
Effective Date:	12/23/1987
Adoption/Issuance Date:	Not reported
Achieve Date:	Not reported
Termination Date:	Not reported
ACL Issuance Date:	Not reported
EPL Issuance Date:	Not reported
Status:	Active
Title:	Enforcement - 8 362310N01
Description:	GW INVESTIGATION
Program:	UNREGS
Latest Milestone Completion Date:	Not reported
# Of Programs1:	1
Total Assessment Amount:	0
Initial Assessed Amount:	0
Liability $ Amount:	0
Project $ Amount:	0
Liability $ Paid:	0
Project $ Completed:	0
Total $ Paid/Completed Amount:	0
Region:	8

GW CLEANUP-COLTON TERMINA (Continued) **S105022790**

Facility Id:	228236
Agency Name:	Kinder Morgan Energy Partners LP
Place Type:	Manufacturing
Place Subtype:	Manufacturing NEC
Facility Type:	Industrial
Agency Type:	Privately-Owned Business
# Of Agencies:	1
Place Latitude:	Not reported
Place Longitude:	Not reported
SIC Code 1:	4959
SIC Desc 1:	Sanitary Services, NEC
SIC Code 2:	Not reported
SIC Desc 2:	Not reported
SIC Code 3:	Not reported
SIC Desc 3:	Not reported
NAICS Code 1:	Not reported
NAICS Desc 1:	Not reported
NAICS Code 2:	Not reported
NAICS Desc 2:	Not reported
NAICS Code 3:	Not reported
NAICS Desc 3:	Not reported
# Of Places:	1
Source Of Facility:	Reg Meas
Design Flow:	Not reported
Threat To Water Quality:	Not reported
Complexity:	Not reported
Pretreatment:	Not reported
Facility Waste Type:	Not reported
Facility Waste Type 2:	Not reported
Facility Waste Type 3:	Not reported
Facility Waste Type 4:	Not reported
Program:	UNREGS
# Of Programs:	1
WDID:	8 362310N01
Reg Measure Id:	158780
Reg Measure Type:	Unregulated
Region:	8
Order #:	Not reported
Npdes# CA#:	Not reported
Major-Minor:	Not reported
Npdes Type:	Not reported
Reclamation:	Not reported
Dredge Fill Fee:	Not reported
301H:	Not reported
Application Fee Amt Received:	Not reported
Status:	Never Active
Status Date:	02/21/2013
Effective Date:	Not reported
Expiration/Review Date:	Not reported
Termination Date:	Not reported
WDR Review - Amend:	Not reported
WDR Review - Revise/Renew:	Not reported
WDR Review - Rescind:	Not reported
WDR Review - No Action Required:	Not reported
WDR Review - Pending:	Not reported
WDR Review - Planned:	Not reported
Status Enrollee:	N

GW CLEANUP-COLTON TERMINA (Continued) **S105022790**

Individual/General:	I
Fee Code:	Not reported
Direction/Voice:	Passive
Enforcement Id(EID):	224978
Region:	8
Order / Resolution Number:	88-114
Enforcement Action Type:	Clean-up and Abatement Order
Effective Date:	10/14/1988
Adoption/Issuance Date:	Not reported
Achieve Date:	Not reported
Termination Date:	Not reported
ACL Issuance Date:	Not reported
EPL Issuance Date:	Not reported
Status:	Active
Title:	Enforcement - 8 362310N01
Description:	GROUNDWATER CLEANUP
Program:	UNREGS
Latest Milestone Completion Date:	Not reported
# Of Programs1:	1
Total Assessment Amount:	0
Initial Assessed Amount:	0
Liability $ Amount:	0
Project $ Amount:	0
Liability $ Paid:	0
Project $ Completed:	0
Total $ Paid/Completed Amount:	0

Region:	8
Facility Id:	228236
Agency Name:	Kinder Morgan Energy Partners LP
Place Type:	Manufacturing
Place Subtype:	Manufacturing NEC
Facility Type:	Industrial
Agency Type:	Privately-Owned Business
# Of Agencies:	1
Place Latitude:	Not reported
Place Longitude:	Not reported
SIC Code 1:	4959
SIC Desc 1:	Sanitary Services, NEC
SIC Code 2:	Not reported
SIC Desc 2:	Not reported
SIC Code 3:	Not reported
SIC Desc 3:	Not reported
NAICS Code 1:	Not reported
NAICS Desc 1:	Not reported
NAICS Code 2:	Not reported
NAICS Desc 2:	Not reported
NAICS Code 3:	Not reported
NAICS Desc 3:	Not reported
# Of Places:	1
Source Of Facility:	Reg Meas
Design Flow:	Not reported
Threat To Water Quality:	Not reported
Complexity:	Not reported
Pretreatment:	Not reported
Facility Waste Type:	Not reported
Facility Waste Type 2:	Not reported

GW CLEANUP-COLTON TERMINA (Continued) **S105022790**

Facility Waste Type 3:	Not reported
Facility Waste Type 4:	Not reported
Program:	UNREGS
# Of Programs:	1
WDID:	8 362310N01
Reg Measure Id:	158780
Reg Measure Type:	Unregulated
Region:	8
Order #:	Not reported
Npdes# CA#:	Not reported
Major-Minor:	Not reported
Npdes Type:	Not reported
Reclamation:	Not reported
Dredge Fill Fee:	Not reported
301H:	Not reported
Application Fee Amt Received:	Not reported
Status:	Never Active
Status Date:	02/21/2013
Effective Date:	Not reported
Expiration/Review Date:	Not reported
Termination Date:	Not reported
WDR Review - Amend:	Not reported
WDR Review - Revise/Renew:	Not reported
WDR Review - Rescind:	Not reported
WDR Review - No Action Required:	Not reported
WDR Review - Pending:	Not reported
WDR Review - Planned:	Not reported
Status Enrollee:	N
Individual/General:	I
Fee Code:	Not reported
Direction/Voice:	Passive
Enforcement Id(EID):	233230
Region:	8
Order / Resolution Number:	UNKNOWN
Enforcement Action Type:	Referral to District Attorney
Effective Date:	08/01/2000
Adoption/Issuance Date:	Not reported
Achieve Date:	Not reported
Termination Date:	Not reported
ACL Issuance Date:	Not reported
EPL Issuance Date:	Not reported
Status:	Active
Title:	Enforcement - 8 362310N01
Description:	San Bernardino DA settled for a civil penalty in which all agencies that responded received equipment. Our agency received both equipment and a cash payment to the clean up and abatement fund. KM is also on probation for 3 years.
Program:	UNREGS
Latest Milestone Completion Date:	Not reported
# Of Programs1:	1
Total Assessment Amount:	0
Initial Assessed Amount:	0
Liability $ Amount:	0
Project $ Amount:	0
Liability $ Paid:	0
Project $ Completed:	0
Total $ Paid/Completed Amount:	0

AX432 **TOSCO COLTON TERMINAL** **RCRA-LQG** **1007198651**
SW **2301 S. RIVERSIDE AVE** **CAD000626917**
1/2-1 **BLOOMINGTON, CA 92316**
0.633 mi.
3340 ft. **Site 21 of 30 in cluster AX**

Relative:
Lower

Actual:
1005 ft.

RCRA-LQG:

Date form received by agency:	02/27/2002
Facility name:	TOSCO COLTON TERMINAL
Facility address:	2301 S. RIVERSIDE AVE BLOOMINGTON, CA 92316
EPA ID:	CAD000626917
Contact:	ROLAND PARKER
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(909) 877-6500
Telephone ext.:	1
Contact email:	Not reported
EPA Region:	09
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Violation Status: No violations found

AX433 **CONOCO PHILLIPS COLTON TERMINAL WES** **AST** **A100345663**
SW **2301 S. RIVERSIDE AVE.** **N/A**
1/2-1 **RIALTO, CA 92316**
0.633 mi.
3340 ft. **Site 22 of 30 in cluster AX**

Relative:
Lower

Actual:
1005 ft.

AST:
Owner: CONOCO PHILLIPS REFINING CO
Total Gallons: 3,160,500
Certified Unified Program Agencies: San Bernardino

AX434 **PHILLIPS 66 PIPELINE LLC** **RCRA-LQG** **1000337292**
SW **2301 S RIVERSIDE AVE** **FINDS** **CAD000633131**
1/2-1 **BLOOMINGTON, CA 92316** **US AIRS**
0.633 mi.
3340 ft. **Site 23 of 30 in cluster AX**

Relative:
Lower

Actual:
1005 ft.

RCRA-LQG:
Date form received by agency: 04/25/2012
Facility name: PHILLIPS 66 COLTON TERMINAL WEST
Facility address: 2301 S RIVERSIDE AVE
BLOOMINGTON, CA 92316
EPA ID: CAD000633131
Mailing address: 3900 KILROY AVE
STE 210
LONG BEACH, CA 90806
Contact: JIM A ADAMS
Contact address: 3900 KILROY AVE STE 210
LONG BEACH, CA 90806
Contact country: US
Contact telephone: 562-290-1516
Contact email: JADAMS3@P66.COM
EPA Region: 09
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:
Owner/operator name: PHILLIPS 66
Owner/operator address: 3900 KILROY AIRPORT WAY STE 210
LONG BEACH, CA 90806
Owner/operator country: US
Owner/operator telephone: 562-290-1500
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 05/01/2012
Owner/Op end date: Not reported

Owner/operator name: PHILLIPS 66

PHILLIPS 66 PIPELINE LLC (Continued) **1000337292**

Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 05/01/2012
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/28/2004
Facility name: PHILLIPS 66 COLTON TERMINAL WEST
Site name: CONOCOPHILLIPS COLTON TERMINAL-WEST
Classification: Small Quantity Generator

Date form received by agency: 02/28/2004
Facility name: PHILLIPS 66 COLTON TERMINAL WEST
Site name: CONOCOPHILLIPS COLTON TERMINAL-WEST
Classification: Large Quantity Generator

Date form received by agency: 01/15/2003
Facility name: PHILLIPS 66 COLTON TERMINAL WEST
Site name: CONOCOPHILLIPS COLTON TERMINAL WEST
Classification: Large Quantity Generator

Date form received by agency: 03/07/1997
Facility name: PHILLIPS 66 COLTON TERMINAL WEST
Site name: TOSCO COLTON TERMINAL
Classification: Large Quantity Generator

Date form received by agency: 09/01/1996
Facility name: PHILLIPS 66 COLTON TERMINAL WEST
Site name: TOSCO COLTON TERMINAL
Classification: Small Quantity Generator

Hazardous Waste Summary:
Waste code: 133
Waste name: 133

PHILLIPS 66 PIPELINE LLC (Continued) **1000337292**

Waste code: 352
Waste name: 352

Waste code: 611
Waste name: 611

Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D007
Waste name: CHROMIUM

Waste code: D008
Waste name: LEAD

Waste code: D009
Waste name: MERCURY

Waste code: D018
Waste name: BENZENE

Violation Status: No violations found

FINDS:

Registry ID: 110009527896

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

California Hazardous Waste Tracking System - Datamart (HWTS-DATAMART) provides California with information on hazardous waste shipments for generators, transporters, and treatment, storage, and disposal facilities.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport,

PHILLIPS 66 PIPELINE LLC (Continued) **1000337292**

and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

CRITERIA AND HAZARDOUS AIR POLLUTANT INVENTORY

US Facility Response Plan (FRP) contains plans for responding, to the maximum extent practical, to worst case discharges of oil.

AIRS (AFS):

Compliance and Violation Data Major Sources:

EPA plant ID:	110009527896
Plant name:	PHILLIPS 66 PIPELINE LLC
Plant address:	2301 S RIVERSIDE AVE BLOOMINGTON, CA 923160000
County:	SAN BERNARDINO
Region code:	09
Dunn & Bradst #:	025418112
Air quality cntrl region:	024
Sic code:	5171
Sic code desc:	PETROLEUM BULK STATIONS AND TERMINALS
North Am. industrial classf:	454312
NAIC code description:	Liquefied Petroleum Gas (Bottled Gas) Dealers
Default compliance status:	IN COMPLIANCE - INSPECTION
Default classification:	ACTUAL OR POTENTIAL EMISSIONS ARE ABOVE THE APPLICABLE MAJOR SOURCE THRESHOLDS
Govt facility:	ALL OTHER FACILITIES NOT OWNED OR OPERATED BY A FEDERAL, STATE, OR LOCAL GOVERNMENT
Current HPV:	Not reported

Compliance and Enforcement Major Issues:

Air program:	TITLE V PERMITS
National action type:	MULTI MEDIA INSPECTION - LEVEL 2 OR GREATER
Date achieved:	000614
Penalty amount:	Not reported
Air program:	TITLE V PERMITS
National action type:	MULTI MEDIA INSPECTION - LEVEL 2 OR GREATER
Date achieved:	010913
Penalty amount:	Not reported
Air program:	TITLE V PERMITS
National action type:	COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved:	030828
Penalty amount:	Not reported
Air program:	TITLE V PERMITS
National action type:	COMPLIANCE CERTIFICATION EPA REVIEW
Date achieved:	031007
Penalty amount:	Not reported
Air program:	TITLE V PERMITS

PHILLIPS 66 PIPELINE LLC (Continued) **1000337292**

National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 040212
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 040227
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 040301
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 040301
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 040916
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 050224
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 060227
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 060914
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V COMPLIANCE CERT DUE/RECEIVED BY
Date achieved: 090301
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V COMPLIANCE CERT DUE/RECEIVED BY
Date achieved: 100226
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: S/L REQ (O/O COND) STACK TEST/NOT OBSV BUT REVWD
Date achieved: 101202
Penalty amount: Not reported

Air program: NSPS
National action type: S/L REQ (O/O COND) STACK TEST/NOT OBSV BUT REVWD
Date achieved: 101202

PHILLIPS 66 PIPELINE LLC (Continued) **1000337292**

Penalty amount: Not reported

Air program: SIP SOURCE
National action type: S/L REQ (O/O COND) STACK TEST/NOT OBSV BUT REVWD
Date achieved: 101202
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 110222
Penalty amount: Not reported

Air program: NSPS
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 110222
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 110222
Penalty amount: Not reported

Air program: NSPS
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 110608
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 110608
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 110608
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 110629
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 110629
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 110629
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 110629
Penalty amount: Not reported

PHILLIPS 66 PIPELINE LLC (Continued) **1000337292**

Air program: NSPS
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 110629
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: S/L REQ (O/O COND) STACK TEST/NOT OBSV BUT REVWD
Date achieved: 111216
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: S/L REQ (O/O COND) STACK TEST/NOT OBSV BUT REVWD
Date achieved: 111216
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 120125
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 120125
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 120827
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 120827
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 120927
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 120927
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 120927
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 120927
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: MULTI MEDIA INSPECTION - LEVEL 2 OR GREATER

PHILLIPS 66 PIPELINE LLC (Continued) **1000337292**

Date achieved: 990924
Penalty amount: Not reported

Historical Compliance Minor Sources:
State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1001
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1001
Air prog code hist file: 9

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1001
Air prog code hist file: M

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1001
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1002
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1002
Air prog code hist file: 9

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1002
Air prog code hist file: M

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1002
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1003
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1003
Air prog code hist file: 9

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1003
Air prog code hist file: M

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1003
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1004
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION

PHILLIPS 66 PIPELINE LLC (Continued) **1000337292**

Hist compliance date: 1004
Air prog code hist file: 9

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1004
Air prog code hist file: M

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1004
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1101
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1101
Air prog code hist file: 9

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1101
Air prog code hist file: M

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1101
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1102
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1102
Air prog code hist file: 9

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1102
Air prog code hist file: M

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1102
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1103
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1103
Air prog code hist file: 9

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1103
Air prog code hist file: M

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1103

PHILLIPS 66 PIPELINE LLC (Continued) **1000337292**

Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1104
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1104
Air prog code hist file: 9

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1104
Air prog code hist file: M

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1104
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1201
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1201
Air prog code hist file: 9

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1201
Air prog code hist file: M

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1201
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1202
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1202
Air prog code hist file: 9

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1202
Air prog code hist file: M

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1202
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1203
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1203
Air prog code hist file: 9

PHILLIPS 66 PIPELINE LLC (Continued) **1000337292**

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1203
Air prog code hist file: M

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1203
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1204
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1204
Air prog code hist file: 9

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1204
Air prog code hist file: M

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1204
Air prog code hist file: V

BC435 **UNOCAL TANK FARM - CONOCO WEST YARD COLTON TERMINAL** **SLIC** **S106487016**
SW **2301 RIVERSIDE AVENUE S** **N/A**
1/2-1 **RIALTO, CA**
0.635 mi.
3353 ft. **Site 1 of 16 in cluster BC**

Relative:
Lower

Actual:
1000 ft.

SLIC:
Region: STATE
Facility Status: **Open - Assessment & Interim Remedial Action**
Status Date: 03/14/2011
Global Id: SLT8R2634093
Lead Agency: SANTA ANA RWQCB (REGION 8)
Lead Agency Case Number: Not reported
Latitude: 34.0597703954576
Longitude: -117.369003295898
Case Type: Cleanup Program Site
Case Worker: RS
Local Agency: Not reported
RB Case Number: SLT8R263
File Location: Not reported
Potential Media Affected: Not reported
Potential Contaminants of Concern: Diesel, MTBE / TBA / Other Fuel Oxygenates, Gasoline
Site History: COLTON REFINED FUELS TERMINAL FACT SHEET Site Description The Colton Terminal occupies approximately 130 acres of land. It is located in the Colton/Rialto/Bloomington Area, south of I-10, west of I-215 and the Santa Ana River. The surrounding area is primarily Industrial, Agricultural and Protected Reserve for the endangered species (Delhi Sands Flower-Loving Fly). 47 above ground tanks store ~63 million gallons of fuel (gasoline, diesel fuel, jet fuel). Fuel is piped from Watson Station (North Long Beach) to the terminal, stored on site and then either piped to other areas or transported off site by truck. Independent operators of separate facilities at the terminal include BP (Atlantic Richfield), Chevron, Shell, ExxonMobil, Kinder Morgan,

UNOCAL TANK FARM - CONOCO WEST YARD COLTON TERMINAL (Continued) **S106487016**

and Phillips. Previous operators included ARCO, Golden West Refining, Tesoro, Texaco, Tosco and Unocal. Spills and Leaks The site has a history of spills of gasoline, jet fuel and diesel fuel. Little is known of the spill history at the site prior to 1974. There have been 14 spills reported totaling approximately 268,000 gallons and other numerous reported spills of unspecified minor quantities since 1974. The first large spill reported to the Regional Board was in 1987. Hydrogeology Perched groundwater is at an average elevation of 888 feet above mean sea level (a depth of 93 to 152 feet below ground surface). Water in the perched zone is found on top of a low permeability silt layer. The perched zone gently slopes from northeast to southwest and is not present at the northwest and southern portions of the site. The movement of groundwater on the perched zone is generally to the south-southwest but may range to the southeast through various portions of the site. The perched water is not used for water production. The top of the regional aquifer is an average elevation of 847 feet (a depth of 122 to 194 feet below ground surface). The groundwater in the regional aquifer flows to the south-southwest at a rate of approximately 2 feet per day. Water Supply Wells There are two water supply wells approximately 4,600 feet south of the site, both completed in a deep aquifer. Well 41 was drilled in 1992 and began active pumping at over 2,000 gpm daily, in 1997. The well seal extends to 290 feet below ground surface. Weekly monitoring for methyl tertiary butyl ether (MTBE) and benzene is conducted at this well. MTBE and benzene have not been detected. Well 40 was drilled in 1999, but there are no current plans to equip this well until the potential impact from the MTBE plume is better understood. Enforcement Actions Cleanup and Abatement Order (CAO) No. 87-151 was issued to Southern Pacific Pipelines (SPP, Currently Kinder Morgan) and Unocal. CAO No. 88-114 was issued to ARCO, Chevron, Golden West Refining, Mobil, SPP, Shell, Tesoro, Texaco, Tosco and Unocal. Order No. 89-121 amended CAO No. 88-114 to remove ARCO, because ARCO agreed to complete an independent investigation under the direction of the Regional Board. Investigation and Cleanup Activities From 1989 to 1993, 21 wells were installed to define the plume. In 1993, soil remediation began using a 200 cfm vapor extraction unit. Later, additional wells were installed and the vapor extraction system was expanded and upgraded. Soil from various spills has been excavated, treated onsite and re-used or transported offsite for proper disposal. In 1996, offsite access negotiations began, and in 1998 an offsite monitoring well was installed. In 1998, oil skimmers were installed in certain down gradient wells and removed free product of approximately 165 gallons of fuel. In 1999, the vapor extraction system was replaced with a 6,000 cfm unit to assist in free product removal. In December 1998, Atlantic Richfield began operation of a separate 1,000 cfm vapor extraction unit on their portion of the facility.

Click here to access the California GeoTracker records for this facility:

AW436 **RUSSELL L C GAS** **EDR US Hist Auto Stat** **1014168491**
ESE **690 W I ST** **N/A**
1/2-1 **COLTON, CA 91737**
0.637 mi.
3361 ft. **Site 4 of 4 in cluster AW**

Relative: **Lower**

Actual: **1000 ft.**

EDR Historical Auto Stations:

Name:	RUSSELL L C GAS
Year:	1936
Type:	GASOLINE AND OIL SERVICE STATIONS

---

437 **EDR US Hist Auto Stat** **1015480773**
WNW **412 W SAN BERNARDINO AVE** **N/A**
1/2-1 **RIALTO, CA 92376**
0.640 mi.
3378 ft.

Relative: **Higher**

Actual: **1104 ft.**

EDR Historical Auto Stations:

Name:	DANIEL AUTOMOTIVE TOWING
Year:	2001
Address:	412 W SAN BERNARDINO AVE
Name:	DANIEL AUTOMOTIVE TOWING
Year:	2002
Address:	412 W SAN BERNARDINO AVE
Name:	DANIEL AUTOMOTIVE TOWING
Year:	2003
Address:	412 W SAN BERNARDINO AVE

BD438 **COLTON PIPE TRADES TRAINING CENTER** **San Bern. Co. Permit** **S104771316**
ESE **225 S RANCHO AVE** **N/A**
1/2-1 **COLTON, CA 92324**
0.641 mi.
3384 ft. **Site 1 of 2 in cluster BD**

Relative: **Lower**

Actual: **994 ft.**

San Bern. Co. Permit:

Region:	SAN BERNARDINO
Facility ID:	FA0006771
Owner:	COLTON PIPE TRADE TRAINING CTR
Permit Number:	PT0007919
Permit Category:	HAZMAT HANDLER 0-10 EMPLOYEES
Facility Status:	ACTIVE
Expiration Date:	05/31/2013

---

439 **EDR US Hist Auto Stat** **1015483467**
WNW **416 W GRANADA ST** **N/A**
1/2-1 **RIALTO, CA 92376**
0.659 mi.
3481 ft.

Relative: **Higher**

Actual: **1116 ft.**

EDR Historical Auto Stations:

Name:	CLASSIC AUTO UPHOLSTERY
Year:	2003
Address:	416 W GRANADA ST
Name:	CLASSIC AUTO UPHOLSTERY

(Continued) **1015483467**

Year: 2006
Address: 416 W GRANADA ST

Name: CLASSIC AUTO UPHOLSTERY
Year: 2007
Address: 416 W GRANADA ST

Name: CLASSIC AUTO UPHOLSTERY
Year: 2008
Address: 416 W GRANADA ST

AX440 **CHEVRON COLTON TERMINAL** **SLIC** **S109286046**
SW **2297 RIVERSIDE AVE S** **N/A**
1/2-1 **BLOOMINGTON, CA**
0.660 mi.
3486 ft. **Site 24 of 30 in cluster AX**

Relative:
Lower

Actual:
1001 ft.

SLIC:

Region:	STATE
Facility Status:	**Open - Assessment & Interim Remedial Action**
Status Date:	09/23/2011
Global Id:	SL0607119456
Lead Agency:	SANTA ANA RWQCB (REGION 8)
Lead Agency Case Number:	Not reported
Latitude:	34.060186
Longitude:	-117.370264
Case Type:	Cleanup Program Site
Case Worker:	RS
Local Agency:	Not reported
RB Case Number:	Not reported
File Location:	Not reported
Potential Media Affected:	Aquifer used for drinking water supply
Potential Contaminants of Concern:	Diesel, Gasoline
Site History:	COLTON REFINED FUELS TERMINAL FACT SHEET Site Description The Colton Terminal occupies approximately 130 acres of land. It is located in the Colton/Rialto/Bloomington Area, south of I-10, west of I-215 and the Santa Ana River. The surrounding area is primarily Industrial, Agricultural and Protected Reserve for the endangered species (Delhi Sands Flower-Loving Fly). 47 above ground tanks store ~63 million gallons of fuel (gasoline, diesel fuel, jet fuel). Fuel is piped from Watson Station (North Long Beach) to the terminal, stored on site and then either piped to other areas or transported off site by truck. Independent operators of separate facilities at the terminal include BP (Atlantic Richfield), Chevron, Shell, ExxonMobil, Kinder Morgan, and Phillips. Previous operators included ARCO, Golden West Refining, Tesoro, Texaco, Tosco and Unocal. Spills and Leaks The site has a history of spills of gasoline, jet fuel and diesel fuel. Little is known of the spill history at the site prior to 1974. There have been 14 spills reported totaling approximately 268,000 gallons and other numerous reported spills of unspecified minor quantities since 1974. The first large spill reported to the Regional Board was in 1987. Hydrogeology Perched groundwater is at an average elevation of 888 feet above mean sea level (a depth of 93 to 152 feet below ground surface). Water in the perched zone is found on top of a low permeability silt layer. The perched zone gently slopes from northeast to southwest and is not present at the northwest and southern portions of the site. The movement of groundwater on the perched zone is generally to the south-southwest but may range to the

CHEVRON COLTON TERMINAL (Continued) **S109286046**

southeast through various portions of the site. The perched water is not used for water production. The top of the regional aquifer is an average elevation of 847 feet (a depth of 122 to 194 feet below ground surface). The groundwater in the regional aquifer flows to the south-southwest at a rate of approximately 2 feet per day. Water Supply Wells There are two water supply wells approximately 4,600 feet south of the site, both completed in a deep aquifer. Well 41 was drilled in 1992 and began active pumping at over 2,000 gpm daily, in 1997. The well seal extends to 290 feet below ground surface. Weekly monitoring for methyl tertiary butyl ether (MTBE) and benzene is conducted at this well. MTBE and benzene have not been detected. Well 40 was drilled in 1999, but there are no current plans to equip this well until the potential impact from the MTBE plume is better understood. Enforcement Actions Cleanup and Abatement Order (CAO) No. 87-151 was issued to Southern Pacific Pipelines (SPP, Currently Kinder Morgan) and Unocal. CAO No. 88-114 was issued to ARCO, Chevron, Golden West Refining, Mobil, SPP, Shell, Tesoro, Texaco, Tosco and Unocal. Order No. 89-121 amended CAO No. 88-114 to remove ARCO, because ARCO agreed to complete an independent investigation under the direction of the Regional Board. Investigation and Cleanup Activities From 1989 to 1993, 21 wells were installed to define the plume. In 1993, soil remediation began using a 200 cfm vapor extraction unit. Later, additional wells were installed and the vapor extraction system was expanded and upgraded. Soil from various spills has been excavated, treated onsite and re-used or transported offsite for proper disposal. In 1996, offsite access negotiations began, and in 1998 an offsite monitoring well was installed. In 1998, oil skimmers were installed in certain down gradient wells and removed free product of approximately 165 gallons of fuel. In 1999, the vapor extraction system was replaced with a 6,000 cfm unit to assist in free product removal. In December 1998, Atlantic Richfield began operation of a separate 1,000 cfm vapor extraction unit on their portion of the facility.

Click here to access the California GeoTracker records for this facility:

AX441 **KINDER MORGAN** **San Bern. Co. Permit** **S106910950**
SW **2297 S RIVERSIDE AVE** **N/A**
1/2-1 **RIALTO, CA 92376**
0.660 mi.
3486 ft. **Site 25 of 30 in cluster AX**

Relative:
Lower

Actual:
1001 ft.

San Bern. Co. Permit:

Region:	SAN BERNARDINO
Facility ID:	FA0004260
Owner:	SFPP, L.P.
Permit Number:	PT0012328
Permit Category:	UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status:	INACTIVE
Expiration Date:	07/31/2005

Region:	SAN BERNARDINO
Facility ID:	FA0004260
Owner:	SFPP, L.P.
Permit Number:	PT0012329
Permit Category:	UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status:	INACTIVE
Expiration Date:	07/31/2005

KINDER MORGAN (Continued) **S106910950**

Region: SAN BERNARDINO
Facility ID: FA0004260
Owner: SFPP, L.P.
Permit Number: PT0002100
Permit Category: HAZMAT HANDLER 11-25 EMPLOYEES (W/GEN PRMT)
Facility Status: INACTIVE
Expiration Date: 07/31/2004

Region: SAN BERNARDINO
Facility ID: FA0004260
Owner: SFPP, L.P.
Permit Number: PT0002101
Permit Category: HAZARDOUS WASTE GENERATOR - 11-25 EMPLOYEES
Facility Status: INACTIVE
Expiration Date: 07/31/2004

Region: SAN BERNARDINO
Facility ID: FA0004260
Owner: SFPP, L.P.
Permit Number: PT0002099
Permit Category: ABOVEGROUND PETROLEUM STORAGE (AST) (SPCC)
Facility Status: INACTIVE
Expiration Date: 07/31/2004

AX442 **KINDER/MORGAN.** **UST** **U003784682**
SW **2297 S RIVERSIDE AVE** **N/A**
1/2-1 **RIALTO, CA 92376**
0.660 mi.
3486 ft. **Site 26 of 30 in cluster AX**

Relative:
Lower

Actual:
1001 ft.

UST:
Facility ID: 86008628
Latitude: 34.10923
Longitude: -117.37651

AX443 **MOBIL OIL CORP COLTON TERM** **RCRA-SQG** **1000253693**
SW **2305 S RIVERSIDE AVE** **FINDS** **CAT000623512**
1/2-1 **BLOOMINGTON, CA 92316**
0.660 mi.
3486 ft. **Site 27 of 30 in cluster AX**

Relative:
Lower

Actual:
1001 ft.

RCRA-SQG:
Date form received by agency: 09/01/1996
Facility name: MOBIL OIL CORP COLTON TERM
Facility address: 2305 S RIVERSIDE AVE
BLOOMINGTON, CA 92316
EPA ID: CAT000623512
Mailing address: PO BOX 5887
SAN BERNARDINO, CA 92412
Contact: Not reported
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 09

MOBIL OIL CORP COLTON TERM (Continued) **1000253693**

Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: MOBIL OIL CORPORATION
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 09/01/1996
Facility name: MOBIL OIL CORP COLTON TERM
Classification: Small Quantity Generator

Date form received by agency: 04/16/1990
Facility name: MOBIL OIL CORP COLTON TERM
Site name: MOBIL OIL CORP
Classification: Large Quantity Generator

Date form received by agency: 08/18/1980

MOBIL OIL CORP COLTON TERM (Continued) **1000253693**

Facility name: MOBIL OIL CORP COLTON TERM
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110002944262

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

US Facility Response Plan (FRP) contains plans for responding, to the maximum extent practical, to worst case discharges of oil.

AX444 **MOBIL FAC. #04-086 /COLTON TER** **LUST** **S102433686**
SW **2305 RIVERSIDE AVE** **N/A**
1/2-1 **BLOOMINGTON, CA 92316**
0.660 mi.
3486 ft. **Site 28 of 30 in cluster AX**

Relative:
Lower

Actual:
1001 ft.

LUST REG 8:

Region:	8
County:	San Bernardino
Regional Board:	Santa Ana Region
Facility Status:	Remedial action (cleanup) Underway
Case Number:	083602777T
Local Case Num:	Not reported
Case Type:	Aquifer affected
Substance:	Gasoline
Qty Leaked:	Not reported
Abate Method:	Remove Free Product - remove floating product from water table
Cross Street:	Not reported
Enf Type:	VER
Funding:	Not reported
How Discovered:	Not reported
How Stopped:	Not reported
Leak Cause:	Not reported
Leak Source:	Not reported
Global ID:	T0607100402
How Stopped Date:	Not reported
Enter Date:	12/20/1995
Review Date:	Not reported
Prelim Assess:	Not reported
Discover Date:	Not reported
Enforcement Date:	Not reported
Close Date:	Not reported
Workplan:	3/1/1993
Pollution Char:	12/1/1995
Remed Plan:	7/15/1996
Remed Action:	6/1/2000
Monitoring:	Not reported

MOBIL FAC. #04-086 /COLTON TER (Continued) **S102433686**

Enter Date:	12/20/1995
GW Qualifies:	=
Soil Qualifies:	Not reported
Operator:	Not reported
Facility Contact:	Not reported
Interim:	Not reported
Oversite Program:	LUST
Latitude:	34.0594498
Longitude:	-117.3700118
MTBE Date:	2/25/1998
Max MTBE GW:	10000
MTBE Concentration:	1
Max MTBE Soil:	Not reported
MTBE Fuel:	1
MTBE Tested:	MTBE Detected. Site tested for MTBE & MTBE detected
MTBE Class:	B
Staff:	RS
Staff Initials:	CR2
Lead Agency:	Regional Board
Local Agency:	36000L
Hydr Basin #:	UPPER SANTA ANA VALL
Beneficial:	Not reported
Priority:	Not reported
Cleanup Fund Id:	Not reported
Work Suspended:	Not reported
Summary:	SUBMITTED NUMEROUS LETTERS TO CONDUCT INTERIM REMEDIATION. WORKING W/SWPPP TO OBTAIN ACCESS FOR VES, HIGH BTEX AND MTBE LEVELS IN GW.

AX445 **MOBIL FAC. #04-086 /COLTON TER** **LUST** **S100940232**
SW **2305 S RIVERSIDE AVE** **SWEEPS UST** **N/A**
1/2-1 **BLOOMINGTON, CA 92316** **EMI**
0.660 mi.
3486 ft. **Site 29 of 30 in cluster AX**

Relative:
Lower

Actual:
1001 ft.

LUST:

Region:	STATE
Global Id:	T0607100402
Latitude:	34.0594498
Longitude:	-117.3700118
Case Type:	LUST Cleanup Site
Status:	Open - Remediation
Status Date:	10/13/2006
Lead Agency:	SANTA ANA RWQCB (REGION 8)
Case Worker:	RS
Local Agency:	SAN BERNARDINO COUNTY
RB Case Number:	083602777T
LOC Case Number:	Not reported
File Location:	Regional Board
Potential Media Affect:	Aquifer used for drinking water supply
Potential Contaminants of Concern:	Gasoline
Site History:	COLTON REFINED FUELS TERMINAL FACT SHEET Site Description The Colton Terminal occupies approximately 130 acres of land. It is located in the Colton/Rialto/Bloomington Area, south of I-10, west of I-215 and the Santa Ana River. The surrounding area is primarily Industrial, Agricultural and Protected Reserve for the endangered species (Delhi Sands Flower-Loving Fly). 47 above ground tanks store ~63 million gallons of fuel (gasoline, diesel fuel, jet fuel). Fuel is piped from Watson Station (North Long Beach) to the terminal, stored on site and

MOBIL FAC. #04-086 /COLTON TER (Continued) **S100940232**

then either piped to other areas or transported off site by truck. Independent operators of separate facilities at the terminal include BP (Atlantic Richfield), Chevron, Shell, ExxonMobil, Kinder Morgan, and Phillips. Previous operators included ARCO, Golden West Refining, Tesoro, Texaco, Tosco and Unocal. Spills and Leaks The site has a history of spills of gasoline, jet fuel and diesel fuel. Little is known of the spill history at the site prior to 1974. There have been 14 spills reported totaling approximately 268,000 gallons and other numerous reported spills of unspecified minor quantities since 1974. The first large spill reported to the Regional Board was in 1987. Hydrogeology Perched groundwater is at an average elevation of 888 feet above mean sea level (a depth of 93 to 152 feet below ground surface). Water in the perched zone is found on top of a low permeability silt layer. The perched zone gently slopes from northeast to southwest and is not present at the northwest and southern portions of the site. The movement of groundwater on the perched zone is generally to the south-southwest but may range to the southeast through various portions of the site. The perched water is not used for water production. The top of the regional aquifer is an average elevation of 847 feet (a depth of 122 to 194 feet below ground surface). The groundwater in the regional aquifer flows to the south-southwest at a rate of approximately 2 feet per day. Water Supply Wells There are two water supply wells approximately 4,600 feet south of the site, both completed in a deep aquifer. Well 41 was drilled in 1992 and began active pumping at over 2,000 gpm daily, in 1997. The well seal extends to 290 feet below ground surface. Weekly monitoring for methyl tertiary butyl ether (MTBE) and benzene is conducted at this well. MTBE and benzene have not been detected. Well 40 was drilled in 1999, but there are no current plans to equip this well until the potential impact from the MTBE plume is better understood. Enforcement Actions Cleanup and Abatement Order (CAO) No. 87-151 was issued to Southern Pacific Pipelines (SPP, Currently Kinder Morgan) and Unocal. CAO No. 88-114 was issued to ARCO, Chevron, Golden West Refining, Mobil, SPP, Shell, Tesoro, Texaco, Tosco and Unocal. Order No. 89-121 amended CAO No. 88-114 to remove ARCO, because ARCO agreed to complete an independent investigation under the direction of the Regional Board. Investigation and Cleanup Activities From 1989 to 1993, 21 wells were installed to define the plume. In 1993, soil remediation began using a 200 cfm vapor extraction unit. Later, additional wells were installed and the vapor extraction system was expanded and upgraded. Soil from various spills has been excavated, treated onsite and re-used or transported offsite for proper disposal. In 1996, offsite access negotiations began, and in 1998 an offsite monitoring well was installed. In 1998, oil skimmers were installed in certain down gradient wells and removed free product of approximately 165 gallons of fuel. In 1999, the vapor extraction system was replaced with a 6,000 cfm unit to assist in free product removal. In December 1998, Atlantic Richfield began operation of a separate 1,000 cfm vapor extraction unit on their portion of the facility.

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607100402
Contact Type:	Local Agency Caseworker
Contact Name:	CATHERINE RICHARDS
Organization Name:	SAN BERNARDINO COUNTY

MOBIL FAC. #04-086 /COLTON TER (Continued) **S100940232**

Address: 620 SOUTH E STREET
City: SAN BERNARDINO
Email: crichards@sbcfire.org
Phone Number: 9093868419

Global Id: T0607100402
Contact Type: Regional Board Caseworker
Contact Name: ROSE SCOTT
Organization Name: SANTA ANA RWQCB (REGION 8)
Address: 3737 MAIN STREET, SUITE 500
City: RIVERSIDE
Email: rscott@waterboards.ca.gov
Phone Number: 9513206375

Regulatory Activities:

Global Id: T0607100402
Action Type: ENFORCEMENT
Date: 04/14/2009
Action: Verbal Enforcement

Global Id: T0607100402
Action Type: ENFORCEMENT
Date: 07/30/2002
Action: * Verbal Communication

Global Id: T0607100402
Action Type: ENFORCEMENT
Date: 11/07/2002
Action: * Verbal Communication

Global Id: T0607100402
Action Type: ENFORCEMENT
Date: 03/25/2003
Action: * Verbal Communication

Global Id: T0607100402
Action Type: RESPONSE
Date: 10/31/2006
Action: CAP/RAP - Other Report

Global Id: T0607100402
Action Type: RESPONSE
Date: 07/30/2006
Action: CAP/RAP - Other Report

Global Id: T0607100402
Action Type: RESPONSE
Date: 07/30/2006
Action: Other Report / Document

Global Id: T0607100402
Action Type: ENFORCEMENT
Date: 07/26/2005
Action: * No Action

Global Id: T0607100402
Action Type: ENFORCEMENT

MOBIL FAC. #04-086 /COLTON TER (Continued) **S100940232**

Date:	10/14/1988
Action:	Clean-up and Abatement Order
Global Id:	T0607100402
Action Type:	ENFORCEMENT
Date:	01/26/2012
Action:	Staff Letter
Global Id:	T0607100402
Action Type:	ENFORCEMENT
Date:	02/18/2010
Action:	Technical Correspondence / Assistance / Other
Global Id:	T0607100402
Action Type:	ENFORCEMENT
Date:	11/18/2009
Action:	Technical Correspondence / Assistance / Other
Global Id:	T0607100402
Action Type:	ENFORCEMENT
Date:	01/21/2010
Action:	Technical Correspondence / Assistance / Other
Global Id:	T0607100402
Action Type:	ENFORCEMENT
Date:	12/17/2009
Action:	Technical Correspondence / Assistance / Other
Global Id:	T0607100402
Action Type:	ENFORCEMENT
Date:	06/10/2005
Action:	* No Action
Global Id:	T0607100402
Action Type:	ENFORCEMENT
Date:	10/15/2004
Action:	* No Action
Global Id:	T0607100402
Action Type:	RESPONSE
Date:	10/30/2004
Action:	Monitoring Report - Quarterly
Global Id:	T0607100402
Action Type:	ENFORCEMENT
Date:	07/07/1989
Action:	Clean-up and Abatement Order
Global Id:	T0607100402
Action Type:	ENFORCEMENT
Date:	09/27/2002
Action:	* Historical Enforcement
Global Id:	T0607100402
Action Type:	RESPONSE
Date:	01/30/2005
Action:	Remedial Progress Report

MOBIL FAC. #04-086 /COLTON TER (Continued) **S100940232**

Global Id: T0607100402
Action Type: RESPONSE
Date: 10/30/2002
Action: Interim Remedial Action Report

Global Id: T0607100402
Action Type: RESPONSE
Date: 04/30/2003
Action: Remedial Progress Report

Global Id: T0607100402
Action Type: RESPONSE
Date: 10/30/2002
Action: Remedial Progress Report

Global Id: T0607100402
Action Type: RESPONSE
Date: 01/30/2003
Action: Interim Remedial Action Report

Global Id: T0607100402
Action Type: RESPONSE
Date: 04/30/2003
Action: Interim Remedial Action Report

Global Id: T0607100402
Action Type: RESPONSE
Date: 01/30/2003
Action: Monitoring Report - Quarterly

Global Id: T0607100402
Action Type: RESPONSE
Date: 07/30/2002
Action: Monitoring Report - Quarterly

Global Id: T0607100402
Action Type: ENFORCEMENT
Date: 06/10/2010
Action: Staff Letter

Global Id: T0607100402
Action Type: RESPONSE
Date: 07/15/2005
Action: Other Report / Document

Global Id: T0607100402
Action Type: RESPONSE
Date: 01/30/2003
Action: Remedial Progress Report

Global Id: T0607100402
Action Type: RESPONSE
Date: 10/30/2002
Action: Monitoring Report - Quarterly

Global Id: T0607100402
Action Type: RESPONSE

MOBIL FAC. #04-086 /COLTON TER (Continued) **S100940232**

Date: 04/30/2011
Action: Monitoring Report - Quarterly

Global Id: T0607100402
Action Type: RESPONSE
Date: 04/30/2011
Action: Remedial Progress Report

Global Id: T0607100402
Action Type: RESPONSE
Date: 12/30/2011
Action: Soil and Water Investigation Workplan

Global Id: T0607100402
Action Type: ENFORCEMENT
Date: 03/24/2010
Action: Meeting

Global Id: T0607100402
Action Type: ENFORCEMENT
Date: 09/15/2006
Action: Site Visit / Inspection / Sampling

Global Id: T0607100402
Action Type: ENFORCEMENT
Date: 07/29/2009
Action: Staff Letter

Global Id: T0607100402
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

Global Id: T0607100402
Action Type: REMEDIATION
Date: 01/01/1950
Action: Soil Vapor Extraction (SVE)

Global Id: T0607100402
Action Type: RESPONSE
Date: 05/30/2005
Action: Remedial Progress Report

Global Id: T0607100402
Action Type: ENFORCEMENT
Date: 09/23/2008
Action: Technical Correspondence / Assistance / Other

SWEEPS UST:
Status: Active
Comp Number: 58939
Number: 9
Board Of Equalization: 44-021274
Referral Date: 03-19-92
Action Date: 03-19-92
Created Date: 02-29-88

MOBIL FAC. #04-086 /COLTON TER (Continued) **S100940232**

Tank Status:	A
Owner Tank Id:	1
Swrcb Tank Id:	36-000-058939-000001
Actv Date:	08-26-88
Capacity:	4000
Tank Use:	M.V. FUEL
Stg:	W
Content:	LEADED
Number Of Tanks:	1

EMI:

Year:	1987
County Code:	36
Air Basin:	SC
Facility ID:	25133
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	14
Reactive Organic Gases Tons/Yr:	14
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

AX446 **EDR US Hist Auto Stat** **1015345215**
SW **2305 S RIVERSIDE AVE** **N/A**
1/2-1 **BLOOMINGTON, CA 92316**
0.660 mi.
3486 ft. **Site 30 of 30 in cluster AX**

Relative:
Lower

Actual:
1001 ft.

EDR Historical Auto Stations:

Name:	EXXONMOBIL OIL CORP
Year:	2007
Address:	2305 S RIVERSIDE AVE
Name:	EXXONMOBIL OIL CORP
Year:	2008
Address:	2305 S RIVERSIDE AVE
Name:	EXXONMOBIL OIL CORP
Year:	2009
Address:	2305 S RIVERSIDE AVE

BC447 **EQUILON ETERPISES LLC/COLTON TERM** **RCRA-LQG** **1007199813**
SW **2307 S. RIVERSIDE AVE** **CAD982327744**
1/2-1 **BLOOMINGTON, CA 92316**
0.670 mi.
3537 ft. **Site 2 of 16 in cluster BC**

Relative:
Lower

Actual:
1000 ft.

RCRA-LQG:

Date form received by agency:	10/12/2000
Facility name:	EQUILON ETERPISES LLC/COLTON TERM
Facility address:	2307 S. RIVERSIDE AVE BLOOMINGTON, CA 92316
EPA ID:	CAD982327744
Mailing address:	PO BOX 2099 HOUSTON, TX 772522099
Contact:	SONDRA BIENVENU
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(713) 241-2258
Contact email:	Not reported
EPA Region:	09
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	02/07/1996
Facility name:	EQUILON ETERPISES LLC/COLTON TERM
Site name:	SHELL OIL COMPANY
Classification:	Large Quantity Generator

EQUILON ETERPISES LLC/COLTON TERM (Continued) **1007199813**

Date form received by agency: 02/24/1992
Facility name: EQUILON ETERPISES LLC/COLTON TERM
Site name: SHELL - COLTON PLANT
Classification: Large Quantity Generator

Date form received by agency: 04/13/1990
Facility name: EQUILON ETERPISES LLC/COLTON TERM
Site name: SHELL OIL CO COLTON PLANT
Classification: Large Quantity Generator

Violation Status: No violations found

BC448 **SHELL OIL CO** **SWEEPS UST** **S105939568**
SW **2307 RIVERSIDE AVE** **EMI** **N/A**
1/2-1 **BLOOMINGTON, CA 92316**
0.670 mi.
3537 ft. **Site 3 of 16 in cluster BC**

Relative:
Lower

Actual:
1000 ft.

SWEEPS UST:
Status: Active
Comp Number: 20078
Number: 1
Board Of Equalization: 44-000074
Referral Date: 03-19-92
Action Date: 03-19-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 1
Swrcb Tank Id: 36-000-020078-000002
Actv Date: 08-23-88
Capacity: 12000
Tank Use: UNKNOWN
Stg: P
Content: Not reported
Number Of Tanks: 2

Status: Active
Comp Number: 20078
Number: 1
Board Of Equalization: 44-000074
Referral Date: 03-19-92
Action Date: 03-19-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 2
Swrcb Tank Id: 36-000-020078-000003
Actv Date: 08-23-88
Capacity: 12000
Tank Use: UNKNOWN
Stg: P
Content: Not reported
Number Of Tanks: Not reported

EMI:
Year: 1987
County Code: 36
Air Basin: SC
Facility ID: 10507

SHELL OIL CO (Continued) **S105939568**

Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	8
Reactive Organic Gases Tons/Yr:	8
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1990
County Code:	36
Air Basin:	SC
Facility ID:	30182
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	15
Reactive Organic Gases Tons/Yr:	12
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1990
County Code:	36
Air Basin:	SC
Facility ID:	10507
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2
Reactive Organic Gases Tons/Yr:	2
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1995
County Code:	36
Air Basin:	SC
Facility ID:	30182
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	26

SHELL OIL CO (Continued) **S105939568**

Reactive Organic Gases Tons/Yr:	21
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1996
County Code:	36
Air Basin:	SC
Facility ID:	30182
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	87
Reactive Organic Gases Tons/Yr:	84
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1997
County Code:	36
Air Basin:	SC
Facility ID:	30182
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1998
County Code:	36
Air Basin:	SC
Facility ID:	30182
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

SHELL OIL CO (Continued) **S105939568**

Year:	1999
County Code:	36
Air Basin:	SC
Facility ID:	30182
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	2000
County Code:	36
Air Basin:	SC
Facility ID:	30182
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	2001
County Code:	36
Air Basin:	SC
Facility ID:	30182
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	2002
County Code:	36
Air Basin:	SC
Facility ID:	117225
Air District Name:	SC
SIC Code:	5171

SHELL OIL CO (Continued) **S105939568**

Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	15
Reactive Organic Gases Tons/Yr:	13
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	2003
County Code:	36
Air Basin:	SC
Facility ID:	117225
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	15
Reactive Organic Gases Tons/Yr:	13
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	2004
County Code:	36
Air Basin:	SC
Facility ID:	117225
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	15.34143
Reactive Organic Gases Tons/Yr:	14.31
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	2005
County Code:	36
Air Basin:	SC
Facility ID:	117225
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	7.35379
Reactive Organic Gases Tons/Yr:	7.21455332
Carbon Monoxide Emissions Tons/Yr:	0

SHELL OIL CO (Continued) **S105939568**

NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0
Year:	2006
County Code:	36
Air Basin:	SC
Facility ID:	117225
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	7.791054629416345269
Reactive Organic Gases Tons/Yr:	7.536
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0
Year:	2007
County Code:	36
Air Basin:	SC
Facility ID:	117225
Air District Name:	SC
SIC Code:	5541
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	11.11676286081204769
Reactive Organic Gases Tons/Yr:	10.9407267626425
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0
Year:	2007
County Code:	36
Air Basin:	SC
Facility ID:	117225
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	7.722191619848076944
Reactive Organic Gases Tons/Yr:	7.536
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

BC449 **EQUILON ENT LLC** **UST** **U003784680**
SW **2307 S RIVERSIDE AVE** **N/A**
1/2-1 **BLOOMINGTON, CA 92316**
0.670 mi.
3537 ft. **Site 4 of 16 in cluster BC**

Relative:
Lower

Actual:
1000 ft.

UST:
Facility ID: 86008623
Latitude: 34.05961
Longitude: -117.37024

BC450 **SHELL OIL PROD US COLTON TERMI** **NPDES** **S108755000**
SW **2307 S RIVERSIDE AVE** **SLIC** **N/A**
1/2-1 **BLOOMINGTON, CA 92316**
0.670 mi.
3537 ft. **Site 5 of 16 in cluster BC**

Relative:
Lower

Actual:
1000 ft.

NPDES:

Npdes Number:	CAS000001
Facility Status:	Active
Agency Id:	0
Region:	8
Regulatory Measure Id:	213513
Order No:	97-03-DWQ
Regulatory Measure Type:	Enrollee
Place Id:	Not reported
WDID:	8 36I015595
Program Type:	Industrial
Adoption Date Of Regulatory Measure:	Not reported
Effective Date Of Regulatory Measure:	01/19/2000
Expiration Date Of Regulatory Measure:	Not reported
Termination Date Of Regulatory Measure:	Not reported
Discharge Name:	Shell Oil Product US
Discharge Address:	20945 S Wilmington Ave
Discharge City:	Carson
Discharge State:	California
Discharge Zip:	90810

SLIC:

Region:	STATE
Facility Status:	**Open - Site Assessment**
Status Date:	06/10/2010
Global Id:	T10000002074
Lead Agency:	SANTA ANA RWQCB (REGION 8)
Lead Agency Case Number:	Not reported
Latitude:	34.059189
Longitude:	-117.368328
Case Type:	Cleanup Program Site
Case Worker:	RS
Local Agency:	Not reported
RB Case Number:	Not reported
File Location:	Regional Board
Potential Media Affected:	Aquifer used for drinking water supply
Potential Contaminants of Concern:	Diesel, MTBE / TBA / Other Fuel Oxygenates, Gasoline, Other Petroleum
Site History:	The Shell terminal is part of the larger Colton Terminal facility that has been under cleanup and abatement orders since the 1980s.

Click here to access the California GeoTracker records for this facility:

BC451 **SHELL OIL PRODUCTS - COLTON TERMINAL** **AST** **A100346146**
SW **2307 S. RIVERSIDE AVE.** **N/A**
1/2-1 **RIALTO, CA 92316**
0.670 mi.
3537 ft. **Site 6 of 16 in cluster BC**

Relative:
Lower

Actual:
1000 ft.

AST:
Owner: SHELL OIL PRODUCTS US
Total Gallons: 5,767,906
Certified Unified Program Agencies: San Bernardino

BC452 **EQUILON ENTERPRISES,SHELL OIL PRODUCTS** **RCRA-LQG** **1004676329**
SW **2307 RIVERSIDE AVE** **FINDS** **CAR000083923**
1/2-1 **BLOOMINGTON, CA 92316** **US AIRS**
0.670 mi.
3537 ft. **Site 7 of 16 in cluster BC**

Relative:
Lower

Actual:
1000 ft.

RCRA-LQG:
Date form received by agency: 02/24/2012
Facility name: COLTON TERMINAL
Facility address: 2307 SOUTH RIVERSIDE AVENUE
BLOOMINTON, CA 92316
EPA ID: CAR000083923
Mailing address: PO BOX 2648
HOUSTON, TX 77252
Contact: RAY E WALDING
Contact address: PO BOX 2648
HOUSTON, TX 77252
Contact country: Not reported
Contact telephone: (713) 241-7008
Contact email: RAY .WALDING@SHELL.COM
EPA Region: 09
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:
Owner/operator name: WQUILON ENTERPRISES LLC
Owner/operator address: PO BOX 2648
HOUSTON, TX 77252
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 07/01/1998
Owner/Op end date: Not reported

Owner/operator name: SHELL OIL PRODUCTS US
Owner/operator address: PO BOX 2648

EQUILON ENTERPRISES,SHELL OIL PRODUCTS (Continued) **1004676329**

HOUSTON, TX 77252
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 07/01/1998
Owner/Op end date: Not reported

Owner/operator name: EQUILON ENTERPRISES LLC DBA SOP US
Owner/operator address: P O BOX 2648
HOUSTON, TX 77252
Owner/operator country: US
Owner/operator telephone: (713) 241-5036
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 07/01/1998
Owner/Op end date: Not reported

Owner/operator name: EQUILON ENTERPRISES LLC DBA SOP US
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 07/01/1998
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 04/11/2011
Facility name: COLTON TERMINAL
Site name: SHELL OIL PRODUCTS US COLTON TERMINAL
Classification: Large Quantity Generator

Date form received by agency: 07/20/2010
Facility name: COLTON TERMINAL
Site name: SHELL OIL PRODUCTS US COLTON TERMINAL
Classification: Large Quantity Generator

EQUILON ENTERPRISES,SHELL OIL PRODUCTS (Continued) **1004676329**

Date form received by agency: 11/17/2009
Facility name: COLTON TERMINAL
Site name: SHELL OIL PRODUCTS US COLTON TERMINAL
Classification: Small Quantity Generator

Date form received by agency: 02/27/2006
Facility name: COLTON TERMINAL
Classification: Small Quantity Generator

Date form received by agency: 02/19/2004
Facility name: COLTON TERMINAL
Site name: SHELL OIL PRODUCTS US-COLTON TERMINAL
Classification: Large Quantity Generator

Date form received by agency: 01/14/2004
Facility name: COLTON TERMINAL
Classification: Large Quantity Generator

Date form received by agency: 12/30/2002
Facility name: COLTON TERMINAL
Site name: SHELL COLTON TERMINAL
Classification: Small Quantity Generator

Date form received by agency: 10/03/2000
Facility name: COLTON TERMINAL
Site name: EQUILON ENTERPRISES L L C
Classification: Large Quantity Generator

Hazardous Waste Summary:
Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D018
Waste name: BENZENE

Waste code: F005
Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT

EQUILON ENTERPRISES,SHELL OIL PRODUCTS (Continued) **1004676329**

WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D018
Waste name: BENZENE

Biennial Reports:

Last Biennial Reporting Year: 2013

Annual Waste Handled:
Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.
Amount (Lbs): 38648.8

Waste code: D018
Waste name: BENZENE
Amount (Lbs): 38648.8

Waste code: F005
Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Amount (Lbs): 8.3

Violation Status: No violations found

FINDS:

Registry ID: 110017210980

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

EQUILON ENTERPRISES,SHELL OIL PRODUCTS (Continued) **1004676329**

US EPA TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

US Facility Response Plan (FRP) contains plans for responding, to the maximum extent practical, to worst case discharges of oil.

AIRS (AFS):

Compliance and Violation Data Major Sources:

EPA plant ID:	110038615077
Plant name:	EQUILON ENTERPRISES,SHELL OIL PRODUCTS
Plant address:	2307 RIVERSIDE AVE BLOOMINGTON, CA 92316
County:	SAN BERNARDINO
Region code:	09
Dunn & Bradst #:	Not reported
Air quality cntrl region:	024
Sic code:	5171
Sic code desc:	PETROLEUM BULK STATIONS AND TERMINALS
North Am. industrial classf:	424710
NAIC code description:	Petroleum Bulk Stations and Terminals
Default compliance status:	IN COMPLIANCE - INSPECTION
Default classification:	ACTUAL OR POTENTIAL EMISSIONS ARE ABOVE THE APPLICABLE MAJOR SOURCE THRESHOLDS
Govt facility:	ALL OTHER FACILITIES NOT OWNED OR OPERATED BY A FEDERAL, STATE, OR LOCAL GOVERNMENT
Current HPV:	Not reported

Compliance and Enforcement Major Issues:

Air program:	TITLE V PERMITS
National action type:	MULTI MEDIA INSPECTION - LEVEL 2 OR GREATER
Date achieved:	010509
Penalty amount:	000000000
Air program:	SIP SOURCE
National action type:	TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved:	100222
Penalty amount:	Not reported
Air program:	TITLE V PERMITS
National action type:	TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved:	100222
Penalty amount:	Not reported

EQUILON ENTERPRISES,SHELL OIL PRODUCTS (Continued) **1004676329**

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 100225
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 100225
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V COMPLIANCE CERT DUE/RECEIVED BY
Date achieved: 100302
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 100310
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 100310
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 100310
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 100310
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 110215
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 110215
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 110914
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 110914
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED FCE / ON-SITE

EQUILON ENTERPRISES,SHELL OIL PRODUCTS (Continued) **1004676329**

Date achieved: 110921
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 110921
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 110921
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 110921
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 120125
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: TITLE V ANN COMPL CERT DUE/RCV BY PERMIT AUTHORITY
Date achieved: 120125
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 120827
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 120827
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 120918
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: COMPLIANCE CERTIFICATION STATE REVIEW
Date achieved: 120918
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 120918
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 120918
Penalty amount: Not reported

EQUILON ENTERPRISES,SHELL OIL PRODUCTS (Continued) **1004676329**

Historical Compliance Minor Sources:

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1001
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1002
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1002
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1003
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1004
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1101
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1101
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1102
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1103
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1104
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1104
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1201
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1202
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1203
Air prog code hist file: 0

EQUILON ENTERPRISES,SHELL OIL PRODUCTS (Continued) **1004676329**

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1204
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1204
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1001
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1003
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1004
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1102
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1103
Air prog code hist file: V

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1201
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1202
Air prog code hist file: 0

State compliance status: IN COMPLIANCE - INSPECTION
Hist compliance date: 1203
Air prog code hist file: V

Permit Information:
Compliance plant ID: CA165
Permit number: 117225
Permit category: V
Permit category desc: TITLE V PERMIT - PLANT SP

Permit Source:
Compliance plant ID: CA165
Plant name: EQUILON ENTERPRISES,SHELL OIL PRODUCTS
Plant address: 2307 RIVERSIDE AVE
BLOOMINGTON, CA 92316

Event Information:
Compliance permit ID: CA165
Permit number: 117225
Event action type: IF

EQUILON ENTERPRISES,SHELL OIL PRODUCTS (Continued) **1004676329**

Event description: *PERMIT AUTHORITY ISSUES FINAL PERMIT
Event action #: 001
Event date: 20090518

BC453 **SHELL OIL PRODUCTS-COLTON TERMINAL** **San Bern. Co. Permit** **S105126508**
SW **2307 S RIVERSIDE AVE** **N/A**
1/2-1 **RIALTO, CA 92316**
0.670 mi.
3537 ft. **Site 8 of 16 in cluster BC**

Relative:
Lower

Actual:
1000 ft.

San Bern. Co. Permit:

Region: SAN BERNARDINO
Facility ID: FA0002930
Owner: SHELL OIL PRODUCTS, US.
Permit Number: PT0025612
Permit Category: EPCRA FACILITY
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0002930
Owner: SHELL OIL PRODUCTS, US.
Permit Number: PT0002095
Permit Category: HAZARDOUS WASTE GENERATOR - 0-10 EMPLOYEES
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0002930
Owner: SHELL OIL PRODUCTS, US.
Permit Number: PT0020779
Permit Category: APSA 1,000,001-10,000,000 GAL FAC CAPACITY
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0002930
Owner: SHELL OIL PRODUCTS, US.
Permit Number: PT0002094
Permit Category: HAZMAT HANDLER 0-10 EMPLOYEES (W/GEN PRMT)
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0002930
Owner: SHELL OIL PRODUCTS, US.
Permit Number: PT0012323
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0002930
Owner: SHELL OIL PRODUCTS, US.
Permit Number: PT0012322
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE

SHELL OIL PRODUCTS-COLTON TERMINAL (Continued) **S105126508**

Expiration Date: 10/31/2013

BC454 **STATE OF CALIF RIALTO SHOP** **RCRA NonGen / NLR** **1004676832**
SW **170 W MINDANAO ST** **FINDS** **CAR000090076**
1/2-1 **BLOOMINGTON, CA 92316** **HAZNET**
0.672 mi.
3550 ft. **Site 9 of 16 in cluster BC**

Relative:
Lower

Actual:
1002 ft.

RCRA NonGen / NLR:

Date form received by agency:	10/12/2008
Facility name:	STATE OF CALIF RIALTO SHOP
Facility address:	170 W MINDANAO ST BLOOMINGTON, CA 92316
EPA ID:	CAR000090076
Mailing address:	10240 SYSTEMS PKWY SACRAMENTO, CA 95827
Contact:	ROBERT BREISACHER
Contact address:	10240 SYSTEMS PKWY SACRAMENTO, CA 95827
Contact country:	US
Contact telephone:	916-255-3491
Contact email:	Not reported
EPA Region:	09
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	DAVID KUYKENDALL
Owner/operator address:	4045 GUASTI RD STE 206 ONTARIO, CA 91761
Owner/operator country:	Not reported
Owner/operator telephone:	(909) 272-8996
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/12/2001

STATE OF CALIF RIALTO SHOP (Continued) **1004676832**

Facility name: STATE OF CALIF RIALTO SHOP
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110012226787

Environmental Interest/Information System
California Hazardous Waste Tracking System - Datamart (HWTS-DATAMART) provides California with information on hazardous waste shipments for generators, transporters, and treatment, storage, and disposal facilities.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZNET:

Year:	2008
Gepaid:	CAR000090076
Contact:	ROBERT BREISACHER
Telephone:	9162553487
Mailing Name:	Not reported
Mailing Address:	7627 CHERRY AVE
Mailing City,St,Zip:	FONTANA, CA 923361661
Gen County:	Not reported
TSD EPA ID:	NVT330010000
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.025
Facility County:	San Bernardino

Year:	2007
Gepaid:	CAR000090076
Contact:	ROBERT BREISACHER
Telephone:	9162553487
Mailing Name:	Not reported
Mailing Address:	7627 CHERRY AVE
Mailing City,St,Zip:	FONTANA, CA 923361661
Gen County:	Not reported
TSD EPA ID:	NVT330010000
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.03
Facility County:	San Bernardino

Year: 2007

STATE OF CALIF RIALTO SHOP (Continued) **1004676832**

Gepaid:	CAR000090076
Contact:	ROBERT BREISACHER
Telephone:	9162553487
Mailing Name:	Not reported
Mailing Address:	7627 CHERRY AVE
Mailing City,St,Zip:	FONTANA, CA 923361661
Gen County:	Not reported
TSD EPA ID:	TXD077603371
TSD County:	Not reported
Waste Category:	Waste oil and mixed oil
Disposal Method:	Fuel Blending Prior To Energy Recovery At Another Site
Tons:	0.02
Facility County:	San Bernardino

Year:	2006
Gepaid:	CAR000090076
Contact:	PAT NEELEY
Telephone:	9162553483
Mailing Name:	Not reported
Mailing Address:	10240 SYSTEMS PKWY
Mailing City,St,Zip:	SACRAMENTO, CA 958273006
Gen County:	Not reported
TSD EPA ID:	TXD077603371
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.03
Facility County:	San Bernardino

Year:	2005
Gepaid:	CAR000090076
Contact:	PAT NEELEY
Telephone:	9162553483
Mailing Name:	Not reported
Mailing Address:	10240 SYSTEMS PKWY
Mailing City,St,Zip:	SACRAMENTO, CA 958273006
Gen County:	Not reported
TSD EPA ID:	CAT000613893
TSD County:	Not reported
Waste Category:	Unspecified organic liquid mixture
Disposal Method:	Transfer Station
Tons:	0.11
Facility County:	San Bernardino

Click this hyperlink while viewing on your computer to access
5 additional CA_HAZNET: record(s) in the EDR Site Report.

BC455 **BUREAU OF AUTOMOTIVE REPAIRS** **San Bern. Co. Permit** **S106911454**
SW **170 W MINDANAO ST** **N/A**
1/2-1 **RIALTO, CA 92316**
0.672 mi.
3550 ft. **Site 10 of 16 in cluster BC**

Relative:
Lower

Actual:
1002 ft.

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0009828
Owner: CALIFORNIA DEPT. OF CONSUMER
Permit Number: PT0016711
Permit Category: SPECIAL GENERATOR
Facility Status: INACTIVE
Expiration Date: 05/31/2009

Region: SAN BERNARDINO
Facility ID: FA0009828
Owner: CALIFORNIA DEPT. OF CONSUMER
Permit Number: PT0016712
Permit Category: SPECIAL HANDLER
Facility Status: INACTIVE
Expiration Date: 05/31/2009

BC456 **FOA BLOCKBUSTER FIREWORKS** **San Bern. Co. Permit** **S105697251**
SW **169 W MINDANAO ST** **N/A**
1/2-1 **RIALTO, CA 92376**
0.673 mi.
3556 ft. **Site 11 of 16 in cluster BC**

Relative:
Lower

Actual:
1002 ft.

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0001502
Owner: MIKE INGRAM
Permit Number: PT0008569
Permit Category: HAZMAT HANDLER 0-10 EMPLOYEES
Facility Status: INACTIVE
Expiration Date: 08/31/2006

Region: SAN BERNARDINO
Facility ID: FA0001502
Owner: MIKE INGRAM
Permit Number: PT0013694
Permit Category: EPCRA FACILITY
Facility Status: INACTIVE
Expiration Date: 08/31/2005

Region: SAN BERNARDINO
Facility ID: FA0001502
Owner: MIKE INGRAM
Permit Number: PT0008568
Permit Category: SPECIAL HANDLER
Facility Status: INACTIVE
Expiration Date: 08/31/2003

BE457
SW
1/2-1
0.681 mi.
3597 ft.

149 W MINDANAO ST
BLOOMINGTON, CA 92316

Site 1 of 4 in cluster BE

EDR US Hist Auto Stat **1015234783**
N/A

Relative:
Lower

Actual:
1002 ft.

EDR Historical Auto Stations:

Name:	CONDOR MOTORSPORTS
Year:	2003
Address:	149 W MINDANAO ST
Name:	CONDOR MOTORSPORTS
Year:	2004
Address:	149 W MINDANAO ST
Name:	CONDOR MOTORSPORT
Year:	2005
Address:	149 W MINDANAO ST
Name:	CONDOR MOTORSPORT
Year:	2006
Address:	149 W MINDANAO ST
Name:	CONDOR MOTORSPORT
Year:	2007
Address:	149 W MINDANAO ST
Name:	CONDOR MOTORSPORT
Year:	2008
Address:	149 W MINDANAO ST
Name:	CONDOR MOTORSPORTS
Year:	2010
Address:	149 W MINDANAO ST
Name:	CONDOR MOTORSPORTS
Year:	2011
Address:	149 W MINDANAO ST
Name:	CONDOR MOTORSPORTS
Year:	2012
Address:	149 W MINDANAO ST

458
NW
1/2-1
0.684 mi.
3612 ft.

RIALTO UNIFIED SCHOOL DISTRICT - MILOR
266 W RANDALL
RIALTO, CA 92376

RCRA-SQG **1000292653**
FINDS **CAD981161268**

Relative:
Higher

Actual:
1146 ft.

RCRA-SQG:

Date form received by agency:	09/01/1996
Facility name:	RIALTO UNIFIED SCHOOL DISTRICT - MILOR
Facility address:	266 W RANDALL RIALTO, CA 92376
EPA ID:	CAD981161268
Mailing address:	182 E WALNUT AVE RIALTO, CA 92376
Contact:	Not reported
Contact address:	Not reported Not reported

RIALTO UNIFIED SCHOOL DISTRICT - MILOR (Continued) **1000292653**

Contact country: Not reported
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 09
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: STATE OF CALIFORNIA
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: State
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: State
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 10/30/1985
Facility name: RIALTO UNIFIED SCHOOL DISTRICT - MILOR
Classification: Large Quantity Generator

Violation Status: No violations found

RIALTO UNIFIED SCHOOL DISTRICT - MILOR (Continued) **1000292653**

FINDS:

Registry ID: 110002678594

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

BE459 **FONTANA POLISHING AND PLATING** **RCRA-LQG** **1007569187**
SW **130 W MINDANAO ST** **CAR000156927**
1/2-1 **BLOOMINGTON, CA 92316**
0.686 mi.
3620 ft. **Site 2 of 4 in cluster BE**

Relative:
Lower

Actual:
1004 ft.

RCRA-LQG:

Date form received by agency:	08/09/2010
Facility name:	FONTANA POLISHING AND PLATING
Facility address:	130 W MINDANAO ST BLOOMINGTON, CA 92316
EPA ID:	CAR000156927
Mailing address:	W MINDANAO ST BLOOMINGTON, CA 92316
Contact:	RICK MARTINEZ
Contact address:	W MINDANAO ST BLOOMINGTON, CA 92316
Contact country:	Not reported
Contact telephone:	(909) 820-7415
Contact email:	Not reported
EPA Region:	09
Land type:	Private
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	RICK MARTINEZ
Owner/operator address:	W MINDANAO ST BLOOMINGTON, CA 92316
Owner/operator country:	Not reported
Owner/operator telephone:	(909) 820-7415
Legal status:	Private
Owner/Operator Type:	Owner

FONTANA POLISHING AND PLATING (Continued) **1007569187**

Owner/Op start date: 04/01/2003
Owner/Op end date: Not reported

Owner/operator name: FONTANA POLISHING AND PLATING
Owner/operator address: Not reported
92316
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 04/01/2003
Owner/Op end date: Not reported

Owner/operator name: JOSE J LUCIO
Owner/operator address: 12171 WILKEN WAY
GARDEN GROVE, CA 92840
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 02/19/2002
Owner/Op end date: Not reported

Owner/operator name: WILLIAN LOPEZ
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 02/02/2003
Owner/Op end date: Not reported

Owner/operator name: ALLEN SNYDER
Owner/operator address: 16852 CALLE BELLEVISTA
PACIFIC PALESADES, CA 90272
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/01/1997
Owner/Op end date: Not reported

Owner/operator name: JOSE J LUCIO
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 02/19/2002
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No

FONTANA POLISHING AND PLATING (Continued) **1007569187**

Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/08/2005
Facility name: FONTANA POLISHING AND PLATING
Classification: Large Quantity Generator

Date form received by agency: 09/29/2004
Facility name: FONTANA POLISHING AND PLATING
Site name: FONTANA POLISHING AND PLATING INC
Classification: Small Quantity Generator

Hazardous Waste Summary:
Waste code: D002
Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Waste code: D004
Waste name: ARSENIC

Waste code: D007
Waste name: CHROMIUM

Waste code: D008
Waste name: LEAD

Waste code: F006
Waste name: WASTEWATER TREATMENT SLUDGES FROM ELECTROPLATING OPERATIONS EXCEPT FROM THE FOLLOWING PROCESSES: (1) SULFURIC ACID ANODIZING OF ALUMINUM; (2) TIN PLATING ON CARBON STEEL; (3) ZINC PLATING (SEGREGATED BASIS) ON CARBON STEEL; (4) ALUMINUM OR ZINC-ALUMINUM PLATING ON CARBON STEEL; (5) CLEANING/STRIPPING ASSOCIATED WITH TIN, ZINC AND ALUMINUM PLATING ON CARBON STEEL; AND (6) CHEMICAL ETCHING AND MILLING OF ALUMINUM.

Waste code: D002
Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS

FONTANA POLISHING AND PLATING (Continued) **1007569187**

USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Waste code: D007
Waste name: CHROMIUM

Waste code: F006
Waste name: WASTEWATER TREATMENT SLUDGES FROM ELECTROPLATING OPERATIONS EXCEPT FROM THE FOLLOWING PROCESSES: (1) SULFURIC ACID ANODIZING OF ALUMINUM; (2) TIN PLATING ON CARBON STEEL; (3) ZINC PLATING (SEGREGATED BASIS) ON CARBON STEEL; (4) ALUMINUM OR ZINC-ALUMINUM PLATING ON CARBON STEEL; (5) CLEANING/STRIPPING ASSOCIATED WITH TIN, ZINC AND ALUMINUM PLATING ON CARBON STEEL; AND (6) CHEMICAL ETCHING AND MILLING OF ALUMINUM.

Waste code: D007
Waste name: CHROMIUM

Waste code: D008
Waste name: LEAD

Waste code: F006
Waste name: WASTEWATER TREATMENT SLUDGES FROM ELECTROPLATING OPERATIONS EXCEPT FROM THE FOLLOWING PROCESSES: (1) SULFURIC ACID ANODIZING OF ALUMINUM; (2) TIN PLATING ON CARBON STEEL; (3) ZINC PLATING (SEGREGATED BASIS) ON CARBON STEEL; (4) ALUMINUM OR ZINC-ALUMINUM PLATING ON CARBON STEEL; (5) CLEANING/STRIPPING ASSOCIATED WITH TIN, ZINC AND ALUMINUM PLATING ON CARBON STEEL; AND (6) CHEMICAL ETCHING AND MILLING OF ALUMINUM.

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 05/20/2009
Date achieved compliance: 07/29/2009
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 12/09/2005
Date achieved compliance: Not reported
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported

FONTANA POLISHING AND PLATING (Continued) **1007569187**

Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 07/29/2009
Evaluation: NOT A SIGNIFICANT NON-COMPLIER
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 05/20/2009
Evaluation: SIGNIFICANT NON-COMPLIER
Area of violation: Generators - General
Date achieved compliance: 07/29/2009
Evaluation lead agency: State

Evaluation date: 12/09/2005
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: Not reported
Evaluation lead agency: State Contractor/Grantee

BE460 **EDR US Hist Auto Stat** **1015201029**
SW **130 W MINDANAO ST** **N/A**
1/2-1 **BLOOMINGTON, CA 92316**
0.686 mi.
3620 ft. **Site 3 of 4 in cluster BE**

Relative: Lower
Actual: 1004 ft.

EDR Historical Auto Stations:
Name: A ONE AUTO CENTER SAN BERNARDINO INC
Year: 2006
Address: 130 W MINDANAO ST

Name: A ONE AUTO CENTER SAN BERNARDINO INC
Year: 2007
Address: 130 W MINDANAO ST

BE461 **FONTANA POLISHING & PLATING** **San Bern. Co. Permit** **S105790495**
SW **130 W MINDANAO ST** **N/A**
1/2-1 **RIALTO, CA 92377**
0.687 mi.
3627 ft. **Site 4 of 4 in cluster BE**

Relative: Lower
Actual: 1004 ft.

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0007714
Owner: MARTINEZ, RICK & LOPEZ, WILLIAM
Permit Number: PT0017274
Permit Category: HAZARDOUS WASTE GENERATOR RCRA LQG
Facility Status: ACTIVE
Expiration Date: 11/30/2008

Region: SAN BERNARDINO
Facility ID: FA0007714
Owner: MARTINEZ, RICK & LOPEZ, WILLIAM
Permit Number: PT0018587
Permit Category: CA ANNUAL FEE

FONTANA POLISHING & PLATING (Continued) **S105790495**

Facility Status: ACTIVE
Expiration Date: 11/30/2008

Region: SAN BERNARDINO
Facility ID: FA0007714
Owner: MARTINEZ, RICK & LOPEZ, WILLIAM
Permit Number: PT0013284
Permit Category: HAZMAT HANDLER 0-10 EMPLOYEES (W/GEN PRMT)
Facility Status: ACTIVE
Expiration Date: 11/30/2007

Region: SAN BERNARDINO
Facility ID: FA0007714
Owner: MARTINEZ, RICK & LOPEZ, WILLIAM
Permit Number: PT0013285
Permit Category: PBR ANNUAL FEE
Facility Status: ACTIVE
Expiration Date: 11/30/2007

Region: SAN BERNARDINO
Facility ID: FA0007714
Owner: MARTINEZ, RICK & LOPEZ, WILLIAM
Permit Number: PT0013283
Permit Category: HAZARDOUS WASTE GENERATOR - 0-10 EMPLOYEES
Facility Status: ACTIVE
Expiration Date: 11/30/2007

BF462 **EDR US Hist Cleaners** **1015083259**
ESE **632 W VALLEY BLVD** **N/A**
1/2-1 **COLTON, CA 92324**
0.687 mi.
3628 ft. **Site 1 of 5 in cluster BF**

Relative:
Lower

Actual:
996 ft.

EDR Historical Cleaners:

Name: CLEANERS & ALTERATIONS
Year: 2002
Address: 632 W VALLEY BLVD

Name: DORISS CLEANERS & ALTRTN
Year: 2003
Address: 632 W VALLEY BLVD

Name: DORIS CLEANERS & ALTERATIONS
Year: 2004
Address: 632 W VALLEY BLVD

Name: DORIS CLEANERS & ALTERATIONS
Year: 2005
Address: 632 W VALLEY BLVD

BF463 **TUTTLE JOHN** **EDR US Hist Auto Stat** **1014182946**
ESE **632 W I ST** **N/A**
1/2-1 **COLTON, CA 91737**
0.687 mi.
3628 ft. **Site 2 of 5 in cluster BF**

Relative:
Lower

Actual:
996 ft.

EDR Historical Auto Stations:
Name: TUTTLE JOHN
Year: 1936
Type: GASOLINE AND OIL SERVICE STATIONS

BG464 **DON BONANNO-CITRUS CO.** **HIST UST** **U001574570**
West **585 W VALLEY BLVD** **SWEEPS UST** **N/A**
1/2-1 **BLOOMINGTON, CA 92316** **EMI**
0.699 mi.
3690 ft. **Site 1 of 2 in cluster BG**

Relative:
Higher

Actual:
1084 ft.

HIST UST:
Region: STATE
Facility ID: 00000068708
Facility Type: Other
Other Type: PRODUCE CO.
Total Tanks: 0001
Contact Name: JOHN LEDBETTER
Telephone: 7148772552
Owner Name: DON BONANNO
Owner Address: 585 WEST VALLEY BOULEVARD
Owner City,St,Zip: BLOOMINGTON, CA 92316

Tank Num: 001
Container Num: 1
Year Installed: Not reported
Tank Capacity: 00001000
Tank Used for: WASTE
Type of Fuel: 1
Tank Construction: Unkown centimeters
Leak Detection: Visual

SWEEPS UST:
Status: Active
Comp Number: 68708
Number: 9
Board Of Equalization: 44-021508
Referral Date: 03-19-92
Action Date: 03-19-92
Created Date: 02-29-88
Tank Status: A
Owner Tank Id: 1
Swrcb Tank Id: 36-000-068708-000001
Actv Date: 08-23-88
Capacity: 1000
Tank Use: M.V. FUEL
Stg: P
Content: REG UNLEADED
Number Of Tanks: 1

EMI:
Year: 1990
County Code: 36

DON BONANNO-CITRUS CO. (Continued) **U001574570**

Air Basin:	SC
Facility ID:	68161
Air District Name:	SC
SIC Code:	1381
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	1
NOX - Oxides of Nitrogen Tons/Yr:	3
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1995
County Code:	36
Air Basin:	SC
Facility ID:	68161
Air District Name:	SC
SIC Code:	1381
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	1
NOX - Oxides of Nitrogen Tons/Yr:	3
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

BH465 **NORTON BATTERY MFG CO** **RCRA-SQG 1001023037**
SW **2175 S WILLOW AVE** **FINDS CAR000003889**
1/2-1 **RIALTO, CA 92376** **HAZNET**
0.701 mi. **EMI**
3700 ft. **Site 1 of 3 in cluster BH**

Relative: Lower

Actual: 1030 ft.

RCRA-SQG:

Date form received by agency:	06/27/1995
Facility name:	NORTON BATTERY MFG CO
Facility address:	2175 S WILLOW AVE RIALTO, CA 92376
EPA ID:	CAR000003889
Mailing address:	P O BOX 2440 RIALTO, CA 92377
Contact:	CAROL JOHNSON
Contact address:	P O BOX 2440 RIALTO, CA 92377
Contact country:	US
Contact telephone:	(909) 877-2161
Contact email:	Not reported
EPA Region:	09
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of

NORTON BATTERY MFG CO (Continued) **1001023037**

hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: BRAD STREELMAN
Owner/operator address: P O BOX 2440
RIALTO, CA 92377
Owner/operator country: Not reported
Owner/operator telephone: (909) 877-2161
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110002906776

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZNET:
Year: 1997
Gepaid: CAR000003889
Contact: BRAD STREELMAN
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 2175 S WILLOW AVE
Mailing City,St,Zip: RIALTO, CA 923760000
Gen County: Not reported
TSD EPA ID: NVT330010000
TSD County: Not reported

NORTON BATTERY MFG CO (Continued) **1001023037**

Waste Category: Other organic solids
Disposal Method: Not reported
Tons: .4000
Facility County: San Bernardino

Year: 1997
Gepaid: CAR000003889
Contact: BRAD STREELMAN
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 2175 S WILLOW AVE
Mailing City,St,Zip: RIALTO, CA 923760000
Gen County: Not reported
TSD EPA ID: CAD008488025
TSD County: Not reported
Waste Category: Liquids with pH <= 2 with metals
Disposal Method: Treatment, Tank
Tons: 10.4250
Facility County: San Bernardino

Year: 1995
Gepaid: CAR000003889
Contact: BRAD STREELMAN
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 2175 S WILLOW AVE
Mailing City,St,Zip: RIALTO, CA 923760000
Gen County: Not reported
TSD EPA ID: NVT330010000
TSD County: Not reported
Waste Category: Other inorganic solid waste
Disposal Method: Not reported
Tons: .4500
Facility County: San Bernardino

EMI:
Year: 1990
County Code: 36
Air Basin: SC
Facility ID: 45869
Air District Name: SC
SIC Code: 3692
Air District Name: SOUTH COAST AQMD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported
Total Organic Hydrocarbon Gases Tons/Yr: 0
Reactive Organic Gases Tons/Yr: 0
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers & Smllr Tons/Yr: 0

466
ENE
1/2-1
0.706 mi.
3726 ft.

1101 LYNDON DR
COLTON, CA 92324

EDR US Hist Auto Stat **1015153444**
N/A

Relative:
Lower

Actual:
1040 ft.

EDR Historical Auto Stations:
Name: CALI AUTO ACCESSORIES
Year: 2009
Address: 1101 LYNDON DR

BD467
ESE
1/2-1
0.710 mi.
3747 ft.

C & R MANUFACTURING, INC.
275 S RANCHO AVE
COLTON, CA 92324

Site 2 of 2 in cluster BD

NPDES **S102038734**
San Bern. Co. Permit **N/A**

Relative:
Lower

Actual:
989 ft.

NPDES:

Npdes Number:	CAS000001
Facility Status:	Terminated
Agency Id:	0
Region:	8
Regulatory Measure Id:	334072
Order No:	97-03-DWQ
Regulatory Measure Type:	Enrollee
Place Id:	Not reported
WDID:	8 36I021235
Program Type:	Industrial
Adoption Date Of Regulatory Measure:	Not reported
Effective Date Of Regulatory Measure:	10/26/2007
Expiration Date Of Regulatory Measure:	Not reported
Termination Date Of Regulatory Measure:	08/20/2012
Discharge Name:	C&R Pier Mfg
Discharge Address:	275 S Ranaho Ave
Discharge City:	Colton
Discharge State:	California
Discharge Zip:	92324

San Bern. Co. Permit:

Region:	SAN BERNARDINO
Facility ID:	FA0001643
Owner:	C & R PIER MFG INC
Permit Number:	PT0003995
Permit Category:	HAZMAT HANDLER 0-10 EMPLOYEES
Facility Status:	INACTIVE
Expiration Date:	08/31/2012

Region:	SAN BERNARDINO
Facility ID:	FA0001643
Owner:	C & R PIER MFG INC
Permit Number:	PT0003996
Permit Category:	CONDITIONALLY EXEMPT SMALL QUANTITY GENERATOR
Facility Status:	INACTIVE
Expiration Date:	08/31/2012

BF468 **SOUTHERN GASOLINE STATIONS** **EDR US Hist Auto Stat** **1014192248**
ESE **606 W I ST** **N/A**
1/2-1 **COLTON, CA 91737**
0.710 mi.
3749 ft. **Site 3 of 5 in cluster BF**

Relative:
Lower

Actual:
995 ft.

EDR Historical Auto Stations:

Name:	SOUTHERN GASOLINE STATIONS
Year:	1930
Type:	GASOLINE AND OIL SERVICE STATIONS

BH469 **OLD DOMINION FREIGHT LINES** **NPDES** **S105698179**
SW **2180 S WILLOW AVE** **San Bern. Co. Permit** **N/A**
1/2-1 **BLOOMINGTON, CA 92316**
0.714 mi.
3768 ft. **Site 2 of 3 in cluster BH**

Relative:
Lower

Actual:
1029 ft.

NPDES:

Npdes Number:	CAS000002
Facility Status:	Terminated
Agency Id:	0
Region:	8
Regulatory Measure Id:	400919
Order No:	2009-0009-DWQ
Regulatory Measure Type:	Enrollee
Place Id:	Not reported
WDID:	8 36C356866
Program Type:	Construction
Adoption Date Of Regulatory Measure:	Not reported
Effective Date Of Regulatory Measure:	12/08/2009
Expiration Date Of Regulatory Measure:	Not reported
Termination Date Of Regulatory Measure:	09/02/2010
Discharge Name:	Old Dominion Freight Line Inc
Discharge Address:	500 Old Dominion Wy
Discharge City:	Thomasville
Discharge State:	California
Discharge Zip:	27360

Npdes Number:	CAS000001
Facility Status:	Active
Agency Id:	0
Region:	8
Regulatory Measure Id:	213766
Order No:	97-03-DWQ
Regulatory Measure Type:	Enrollee
Place Id:	Not reported
WDID:	8 36I018906
Program Type:	Industrial
Adoption Date Of Regulatory Measure:	Not reported
Effective Date Of Regulatory Measure:	07/21/2004
Expiration Date Of Regulatory Measure:	Not reported
Termination Date Of Regulatory Measure:	Not reported
Discharge Name:	Old Dominion Freight Lines
Discharge Address:	2180 S Willow Ave
Discharge City:	Bloomington
Discharge State:	California
Discharge Zip:	92316

San Bern. Co. Permit:

OLD DOMINION FREIGHT LINES (Continued) **S105698179**

Region: SAN BERNARDINO
Facility ID: FA0007594
Owner: OLD DOMINION FREIGHT LINE
Permit Number: PT0022504
Permit Category: HAZARDOUS WASTE GENERATOR - 51-100 EMPLOYEES
Facility Status: ACTIVE
Expiration Date: 01/31/2014

Region: SAN BERNARDINO
Facility ID: FA0007594
Owner: OLD DOMINION FREIGHT LINE
Permit Number: PT0013047
Permit Category: HAZMAT HANDLER 51-100 EMPLOYEES (W/GEN PRMT)
Facility Status: ACTIVE
Expiration Date: 01/31/2014

BF470 **GILBERT & JENKINS GAS STA** **EDR US Hist Auto Stat** **1014190165**
ESE **588 W I ST** **N/A**
1/2-1 **COLTON, CA 91737**
0.729 mi.
3851 ft. **Site 4 of 5 in cluster BF**

Relative:
Lower

Actual:
993 ft.

EDR Historical Auto Stations:

Name: SPRAGUE E W AUTO REPR
Year: 1930
Type: AUTOMOBILE REPAIRING

Name: GILBERT & JENKINS GAS STA
Year: 1930
Type: GASOLINE AND OIL SERVICE STATIONS

Name: GILBERT E E GAS
Year: 1936
Type: GASOLINE AND OIL SERVICE STATIONS

Name: GRAHAM L A AUTO
Year: 1936
Type: AUTOMOBILE REPAIRING

BH471 **OLD DOMINION FREIGHT LINE** **UST** **U003775830**
SW **2209 S WILLOW AVE** **N/A**
1/2-1 **RIALTO, CA 92376**
0.732 mi.
3863 ft. **Site 3 of 3 in cluster BH**

Relative:
Lower

Actual:
1028 ft.

UST:

Facility ID: 49180
Latitude: 34.10923
Longitude: -117.37651

BF472 **EDR US Hist Auto Stat** **1015561108**
ESE **582 W VALLEY BLVD** **N/A**
1/2-1 **COLTON, CA 92324**
0.735 mi.
3879 ft. **Site 5 of 5 in cluster BF**

Relative:
Lower

Actual:
993 ft.

EDR Historical Auto Stations:

Name:	EAST VALLEY AUTO SALES
Year:	2005
Address:	582 W VALLEY BLVD
Name:	EAST VALLEY AUTO
Year:	2007
Address:	582 W VALLEY BLVD

BG473 **FRITO-LAY SALES, LP** **San Bern. Co. Permit** **S108754134**
West **635 W VALLEY BLVD** **N/A**
1/2-1 **RIALTO, CA 92316**
0.738 mi.
3898 ft. **Site 2 of 2 in cluster BG**

Relative:
Higher

Actual:
1084 ft.

San Bern. Co. Permit:

Region:	SAN BERNARDINO
Facility ID:	FA0003348
Owner:	FRITO-LAY SALES, LP
Permit Number:	PT0005233
Permit Category:	SPECIAL HANDLER
Facility Status:	ACTIVE
Expiration Date:	10/31/2013
Region:	SAN BERNARDINO
Facility ID:	FA0003348
Owner:	FRITO-LAY SALES, LP
Permit Number:	PT0005231
Permit Category:	SPECIAL GENERATOR
Facility Status:	ACTIVE
Expiration Date:	10/31/2013

BC474 **SFPP, L.P.** **AST** **A100346110**
SW **2359 S. RIVERSIDE AVE.** **N/A**
1/2-1 **RIALTO, CA 92316**
0.738 mi.
3899 ft. **Site 12 of 16 in cluster BC**

Relative:
Lower

Actual:
998 ft.

AST:

Owner:	SFPP, LP
Total Gallons:	63,849,890
Certified Unified Program Agencies:	San Bernardino

BC475
SW
1/2-1
0.738 mi.
3899 ft.

COLTON TRUCK RACK
2359 SOUTH RIVERSIDE AVE
BLOOMINGTON, CA 92316

Site 13 of 16 in cluster BC

RCRA-SQG | **1000417303** | **CAD981433097**

Relative:
Lower

Actual:
998 ft.

RCRA-SQG:

Date form received by agency:	08/01/1986
Facility name:	COLTON TRUCK RACK
Facility address:	2359 SOUTH RIVERSIDE AVE BLOOMINGTON, CA 92316
EPA ID:	CAD981433097
Mailing address:	2 INVERNESS DR EAST STE 202 ENGLEWOOD, CO 80112
Contact:	ENVIRONMENTAL MANAGER
Contact address:	2359 SOUTH RIVERSIDE AVE BLOOMINGTON, CA 92404
Contact country:	US
Contact telephone:	(303) 649-4012
Contact email:	Not reported
EPA Region:	09
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	CONOCO INC
Owner/operator address:	NOT REQUIRED NOT REQUIRED, ME 99999
Owner/operator country:	Not reported
Owner/operator telephone:	(415) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	NOT REQUIRED
Owner/operator address:	NOT REQUIRED NOT REQUIRED, ME 99999
Owner/operator country:	Not reported
Owner/operator telephone:	(415) 555-1212
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No

COLTON TRUCK RACK (Continued) **1000417303**

Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

BC476 **SFPP, L.P.** **NPDES U003784561**
SW **2359 S RIVERSIDE AVE** **UST N/A**
1/2-1 **RIALTO, CA 92376** **SWEEPS UST**
0.738 mi. **San Bern. Co. Permit**
3899 ft. **Site 14 of 16 in cluster BC** **EMI**
ENVIROSTOR

Relative:
Lower

Actual:
998 ft.

NPDES:

Npdes Number:	CAS000002
Facility Status:	Terminated
Agency Id:	0
Region:	8
Regulatory Measure Id:	344609
Order No:	2009-0009-DWQ
Regulatory Measure Type:	Enrollee
Place Id:	Not reported
WDID:	8 36C351740
Program Type:	Construction
Adoption Date Of Regulatory Measure:	Not reported
Effective Date Of Regulatory Measure:	05/08/2008
Expiration Date Of Regulatory Measure:	Not reported
Termination Date Of Regulatory Measure:	10/05/2010
Discharge Name:	Kinder Morgan Energy Partners
Discharge Address:	1100 Town and Country Road
Discharge City:	Orange
Discharge State:	California
Discharge Zip:	92868

UST:

Facility ID:	85004392
Latitude:	34.10923
Longitude:	-117.37651

SWEEPS UST:

Status:	Active
Comp Number:	7817
Number:	3
Board Of Equalization:	Not reported
Referral Date:	06-21-94
Action Date:	06-21-94
Created Date:	06-21-94
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	Not reported
Actv Date:	Not reported
Capacity:	Not reported
Tank Use:	Not reported
Stg:	Not reported

SFPP, L.P. (Continued) **U003784561**

Content: Not reported
Number Of Tanks: Not reported

Status: Not reported
Comp Number: 7817
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 36-000-007817-000001
Actv Date: Not reported
Capacity: 1500
Tank Use: M.V. FUEL
Stg: PRODUCT
Content: DIESEL
Number Of Tanks: 1

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0006133
Owner: SFPP, L.P.
Permit Number: PT0001602
Permit Category: CA ANNUAL FEE
Facility Status: INACTIVE
Expiration Date: 10/31/2009

Region: SAN BERNARDINO
Facility ID: FA0006133
Owner: SFPP, L.P.
Permit Number: PT0001603
Permit Category: HAZMAT HANDLER 11-25 EMPLOYEES (W/GEN PRMT)
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0006133
Owner: SFPP, L.P.
Permit Number: PT0016025
Permit Category: EPCRA FACILITY
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0006133
Owner: SFPP, L.P.
Permit Number: PT0020494
Permit Category: WASTE-GENERATING RECYCLER (ONSITE)
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0006133
Owner: SFPP, L.P.
Permit Number: PT0001604

SFPP, L.P. (Continued) **U003784561**

Permit Category: HAZARDOUS WASTE GENERATOR - 11-25 EMPLOYEES
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0006133
Owner: SFPP, L.P.
Permit Number: PT0001605
Permit Category: APSA 10,000,001-100,000,000 GAL FAC CAPACITY
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0006133
Owner: SFPP, L.P.
Permit Number: PT0020493
Permit Category: HAZARDOUS WASTE GENERATOR RCRA LQG
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0006133
Owner: SFPP, L.P.
Permit Number: PT0012474
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0006133
Owner: SFPP, L.P.
Permit Number: PT0012475
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0006133
Owner: SFPP, L.P.
Permit Number: PT0012476
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0006133
Owner: SFPP, L.P.
Permit Number: PT0016149
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0006133
Owner: SFPP, L.P.
Permit Number: PT0016150
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)

SFPP, L.P. (Continued) **U003784561**

Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0006133
Owner: SFPP, L.P.
Permit Number: PT0016151
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 10/31/2013

EMI:

Year:	2001
County Code:	36
Air Basin:	SC
Facility ID:	800129
Air District Name:	SC
SIC Code:	4226
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Y
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	97
Reactive Organic Gases Tons/Yr:	68
Carbon Monoxide Emissions Tons/Yr:	1
NOX - Oxides of Nitrogen Tons/Yr:	1
SOX - Oxides of Sulphur Tons/Yr:	5
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

ENVIROSTOR:

Site Type:	Tiered Permit
Site Type Detailed:	Tiered Permit
Acres:	Not reported
NPL:	NO
Regulatory Agencies:	NONE SPECIFIED
Lead Agency:	NONE SPECIFIED
Program Manager:	Not reported
Supervisor:	Not reported
Division Branch:	Cleanup Cypress
Facility ID:	71002535
Site Code:	Not reported
Assembly:	47
Senate:	20
Special Program:	Not reported
Status:	Inactive - Needs Evaluation
Status Date:	Not reported
Restricted Use:	NO
Site Mgmt. Req.:	NONE SPECIFIED
Funding:	Not reported
Latitude:	34.03076
Longitude:	-117.3649
APN:	NONE SPECIFIED
Past Use:	NONE SPECIFIED
Potential COC:	NONE SPECIFIED
Confirmed COC:	NONE SPECIFIED
Potential Description:	NONE SPECIFIED

SFPP, L.P. (Continued) **U003784561**

Alias Name: CAD067618389
Alias Type: EPA Identification Number
Alias Name: 110021273600
Alias Type: EPA (FRS #)
Alias Name: 71002535
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: Not reported
Completed Sub Area Name: Not reported
Completed Document Type: Not reported
Completed Date: Not reported
Comments: Not reported

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

BC477 **COLTON TERMINAL** **SLIC** **U001575309**
SW **2359 RIVERSIDE AVE** **HIST UST** **N/A**
1/2-1 **RIALTO, CA 9237** **CHMIRS**
0.738 mi. **ENF**
3899 ft. **Site 15 of 16 in cluster BC**

Relative:
Lower

Actual:
998 ft.

SLIC:
Region: STATE
Facility Status: **Open - Remediation**
Status Date: 03/01/2002
Global Id: SL208023857
Lead Agency: SANTA ANA RWQCB (REGION 8)
Lead Agency Case Number: Not reported
Latitude: 34.0594
Longitude: -117.369266
Case Type: Cleanup Program Site
Case Worker: RS
Local Agency: Not reported
RB Case Number: SL208023857
File Location: Regional Board
Potential Media Affected: Aquifer used for drinking water supply
Potential Contaminants of Concern: * Petroleum - Automotive gasolines, * Petroleum - Diesel fuels, * Petroleum - Jet Fuel / Aviation
Site History: This is a bulk petrochemical storage and transfer facility with a large plume of gasoline on the groundwater and dissolved gasoline constituents in the groundwater.

Click here to access the California GeoTracker records for this facility:

HIST UST:
Region: STATE
Facility ID: 00000040276
Facility Type: Other
Other Type: COMMON CARRIER PIPEL

COLTON TERMINAL (Continued) **U001575309**

Total Tanks: 0003
Contact Name: L. O. LUTHER
Telephone: 7148772141
Owner Name: SOUTHERN PACIFIC PIPE LINES, I
Owner Address: 610 SOUTH MAIN STREET
Owner City,St,Zip: LOS ANGELES, CA 90014

Tank Num: 001
Container Num: #1
Year Installed: 1956
Tank Capacity: 00005880
Tank Used for: PRODUCT
Type of Fuel: UNLEADED
Tank Construction: 1/8 inches
Leak Detection: Visual

Tank Num: 002
Container Num: #2
Year Installed: 1979
Tank Capacity: 00005880
Tank Used for: WASTE
Type of Fuel: UNLEADED
Tank Construction: 1/8 inches
Leak Detection: Visual

Tank Num: 003
Container Num: #3
Year Installed: 1956
Tank Capacity: 00000420
Tank Used for: PRODUCT
Type of Fuel: 06
Tank Construction: 1/8 inches
Leak Detection: Visual

CHMIRS:
OES Incident Number: '10-7527
OES notification: 12/15/2010
OES Date: Not reported
OES Time: Not reported
Incident Date: Not reported
Date Completed: Not reported
Property Use: Not reported
Agency Id Number: Not reported
Agency Incident Number: Not reported
Time Notified: Not reported
Time Completed: Not reported
Surrounding Area: Not reported
Estimated Temperature: Not reported
Property Management: Not reported
Special Studies 1: Not reported
Special Studies 2: Not reported
Special Studies 3: Not reported
Special Studies 4: Not reported
Special Studies 5: Not reported
Special Studies 6: Not reported
More Than Two Substances Involved?: Not reported
Resp Agncy Personel # Of Decontaminated: Not reported

COLTON TERMINAL (Continued) **U001575309**

Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	No
Waterway:	Not reported
Spill Site:	Other
Cleanup By:	None
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	N/A
Other:	Not reported
Date/Time:	1530
Year:	2010
Agency:	City of Rialto FD
Incident Date:	12/14/2010
Admin Agency:	San Bernardino County Health Department
Amount:	Not reported
Contained:	Yes
Site Type:	Not reported
E Date:	Not reported
Substance:	Unleaded Fuel - non release
Quantity Released:	Not reported
BBLS:	Not reported
Cups:	Not reported
CUFT:	Not reported
Gallons:	Not reported
Grams:	Not reported
Pounds:	Not reported
Liters:	Not reported
Ounces:	Not reported
Pints:	Not reported
Quarts:	Not reported
Sheen:	Not reported
Tons:	Not reported
Unknown:	Not reported
Evacuations:	Not reported
Number of Injuries:	Not reported
Number of Fatalities:	Not reported
Description:	RP states that a storage tank cover sank to the bottom of the tank. Currently in the process of transferring fuel from one tank to another.

ENF:
Region: 8

COLTON TERMINAL (Continued) **U001575309**

Facility Id:	228202
Agency Name:	Not reported
Place Type:	Service/Commercial
Place Subtype:	Service/Commercial Site, NEC
Facility Type:	Industrial
Agency Type:	Not reported
# Of Agencies:	Not reported
Place Latitude:	34.0588550
Place Longitude:	-117.37025
SIC Code 1:	4959
SIC Desc 1:	Sanitary Services, NEC
SIC Code 2:	Not reported
SIC Desc 2:	Not reported
SIC Code 3:	Not reported
SIC Desc 3:	Not reported
NAICS Code 1:	Not reported
NAICS Desc 1:	Not reported
NAICS Code 2:	Not reported
NAICS Desc 2:	Not reported
NAICS Code 3:	Not reported
NAICS Desc 3:	Not reported
# Of Places:	1
Source Of Facility:	Enf Action
Design Flow:	Not reported
Threat To Water Quality:	Not reported
Complexity:	Not reported
Pretreatment:	Not reported
Facility Waste Type:	Not reported
Facility Waste Type 2:	Not reported
Facility Waste Type 3:	Not reported
Facility Waste Type 4:	Not reported
Program:	NPDES
# Of Programs:	1
WDID:	Not reported
Reg Measure Id:	131332
Reg Measure Type:	NPDES Permits
Region:	8
Order #:	R8-2002-0007
Npdes# CA#:	CAG918001
Major-Minor:	Minor
Npdes Type:	Not reported
Reclamation:	Not reported
Dredge Fill Fee:	Not reported
301H:	N
Application Fee Amt Received:	5688
Status:	Historical
Status Date:	02/02/2007
Effective Date:	02/02/2002
Expiration/Review Date:	01/01/2007
Termination Date:	02/01/2007
WDR Review - Amend:	Not reported
WDR Review - Revise/Renew:	Not reported
WDR Review - Rescind:	Not reported
WDR Review - No Action Required:	Not reported
WDR Review - Pending:	Not reported
WDR Review - Planned:	Not reported
Status Enrollee:	N

COLTON TERMINAL (Continued) **U001575309**

Individual/General:	G
Fee Code:	Not reported
Direction/Voice:	Passive
Enforcement Id(EID):	244976
Region:	8
Order / Resolution Number:	R8-2003-0040
Enforcement Action Type:	Admin Civil Liability
Effective Date:	02/14/2003
Adoption/Issuance Date:	Not reported
Achieve Date:	Not reported
Termination Date:	Not reported
ACL Issuance Date:	Not reported
EPL Issuance Date:	Not reported
Status:	Historical
Title:	ACLC R8-2003-0040 for SFPP, LP
Description:	VIOLATED TBA LIMITS. WILL ISSUE ACL.
Program:	NPDES
Latest Milestone Completion Date:	5/20/2003
# Of Programs1:	1
Total Assessment Amount:	48000
Initial Assessed Amount:	0
Liability $ Amount:	24000
Project $ Amount:	0
Liability $ Paid:	24000
Project $ Completed:	0
Total $ Paid/Completed Amount:	48000

BC478 **SFPP, L.P. - COLTON SOUTH** **RCRA-LQG** **1000409079**
SW **2359 S. RIVERSIDE AVE** **CAD067618389**
1/2-1 **BLOOMINGTON, CA 92316**
0.738 mi.
3899 ft. **Site 16 of 16 in cluster BC**

Relative:
Lower

Actual:
998 ft.

RCRA-LQG:

Date form received by agency:	04/27/2012
Facility name:	SFPP, L.P. - COLTON SOUTH
Facility address:	2359 S. RIVERSIDE AVE BLOOMINGTON, CA 92316
EPA ID:	CAD067618389
Mailing address:	TOWN AND COUNTRY ROAD BLOOMINGTON, CA 92316
Contact:	RICH BRITO
Contact address:	TOWN AND COUNTRY ROAD BLOOMINGTON, CA 92316
Contact country:	Not reported
Contact telephone:	(714) 560-4875
Contact email:	RICH_BRITO@KINDERMORGAN.COM
EPA Region:	09
Land type:	Private
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less

SFPP, L.P. - COLTON SOUTH (Continued) **1000409079**

of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	SFPP, L.P.
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	02/08/1990
Owner/Op end date:	Not reported

Owner/operator name:	SFPP, L.P.
Owner/operator address:	TOWN AND COUNTRY ROAD
	BLOOMINGTON, CA 92316
Owner/operator country:	Not reported
Owner/operator telephone:	(714) 560-4875
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	02/08/1990
Owner/Op end date:	Not reported

Owner/operator name:	SFPP LP
Owner/operator address:	1100 TOWN AND COUNTRY RD
	ORANGE, CA 92868
Owner/operator country:	Not reported
Owner/operator telephone:	(714) 560-4873
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	08/03/2010
Facility name:	SFPP, L.P. - COLTON SOUTH

SFPP, L.P. - COLTON SOUTH (Continued) **1000409079**

Site name: SFPP, L.P. - COLTON
Classification: Large Quantity Generator

Date form received by agency: 02/29/2008
Facility name: SFPP, L.P. - COLTON SOUTH
Site name: SFPP, L.P. COLTON TERMINAL
Classification: Large Quantity Generator

Date form received by agency: 02/28/2006
Facility name: SFPP, L.P. - COLTON SOUTH
Site name: SFPP, L.P. COLTON TERMINAL
Classification: Large Quantity Generator

Date form received by agency: 02/27/2004
Facility name: SFPP, L.P. - COLTON SOUTH
Site name: SFPP, L.P. COLTON TERMINAL
Classification: Large Quantity Generator

Date form received by agency: 02/28/2002
Facility name: SFPP, L.P. - COLTON SOUTH
Site name: SFPP, L.P. COLTON TERMINAL
Classification: Large Quantity Generator

Date form received by agency: 10/12/2000
Facility name: SFPP, L.P. - COLTON SOUTH
Site name: SFPP, L.P./ COLTON
Classification: Large Quantity Generator

Date form received by agency: 03/04/1999
Facility name: SFPP, L.P. - COLTON SOUTH
Site name: SFPP, L.P.
Classification: Large Quantity Generator

Date form received by agency: 01/26/1998
Facility name: SFPP, L.P. - COLTON SOUTH
Site name: SFPP LP COLTON TERMINAL
Classification: Large Quantity Generator

Date form received by agency: 09/01/1996
Facility name: SFPP, L.P. - COLTON SOUTH
Site name: SFPP LP COLTON TERMINAL
Classification: Large Quantity Generator

Date form received by agency: 02/29/1996
Facility name: SFPP, L.P. - COLTON SOUTH
Site name: SFPP, LP COLTON TERMINAL
Classification: Large Quantity Generator

Date form received by agency: 03/30/1994
Facility name: SFPP, L.P. - COLTON SOUTH
Site name: S.F.P.P. L.P. COLTON TERMINAL
Classification: Large Quantity Generator

Date form received by agency: 07/16/1990
Facility name: SFPP, L.P. - COLTON SOUTH
Site name: SANTA FE PACIFIC PIPE LINES INC
Classification: Large Quantity Generator

SFPP, L.P. - COLTON SOUTH (Continued) **1000409079**

Date form received by agency: 07/27/1989
Facility name: SFPP, L.P. - COLTON SOUTH
Site name: SFPP LP COLTON TERMINAL
Classification: Large Quantity Generator

Hazardous Waste Summary:
Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D018
Waste name: BENZENE

Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D018
Waste name: BENZENE

Biennial Reports:

Last Biennial Reporting Year: 2013

Annual Waste Handled:
Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.
Amount (Lbs): 317233.8

Waste code: D018
Waste name: BENZENE
Amount (Lbs): 1233297.6

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 06/28/2008
Date achieved compliance: Not reported
Violation lead agency: State
Enforcement action: Not reported

SFPP, L.P. - COLTON SOUTH (Continued) **1000409079**

Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 06/28/2008
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: Not reported
Evaluation lead agency: State

---

479 **WEST VALLEY WATER DIST ZONE 2-3** **San Bern. Co. Permit** **S109254401**
North **691 S EUCALYPTUS** **N/A**
1/2-1 **SAN BERNARDINO, CA 92376**
0.744 mi.
3926 ft.

Relative:
Higher

Actual:
1164 ft.

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0011758
Owner: WEST VALLEY WATER DISTRICT
Permit Number: PT0020637
Permit Category: HAZMAT HANDLER 0-10 EMPLOYEES
Facility Status: ACTIVE
Expiration Date: 08/31/2013

---

480 **TRANS** **NPDES** **S106105372**
East **451 N 3RD ST** **San Bern. Co. Permit** **N/A**
1/2-1 **COLTON, CA 92324** **WDS**
0.744 mi.
3926 ft.

Relative:
Lower

Actual:
1020 ft.

NPDES:
Npdes Number: CAS000001
Facility Status: Active
Agency Id: 0
Region: 8
Regulatory Measure Id: 213694
Order No: 97-03-DWQ
Regulatory Measure Type: Enrollee
Place Id: Not reported
WDID: 8 36I017877
Program Type: Industrial
Adoption Date Of Regulatory Measure: Not reported
Effective Date Of Regulatory Measure: 03/11/2003
Expiration Date Of Regulatory Measure: Not reported
Termination Date Of Regulatory Measure: Not reported
Discharge Name: Colton Joint Unified School District
Discharge Address: 451 N 3rd St
Discharge City: Colton
Discharge State: California
Discharge Zip: 92324

TRANS (Continued) **S106105372**

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0005967
Owner: COLTON JOINT USD
Permit Number: PT0023726
Permit Category: APSA 1,320-10,000 GAL FAC CAPACITY
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0005967
Owner: COLTON JOINT USD
Permit Number: PT0010930
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0005967
Owner: COLTON JOINT USD
Permit Number: PT0010931
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0005967
Owner: COLTON JOINT USD
Permit Number: PT0010932
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0005967
Owner: COLTON JOINT USD
Permit Number: PT0023724
Permit Category: UW HANDLER W/ ANOTHER HAZ WASTE GENERATOR FEE
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0005967
Owner: COLTON JOINT USD
Permit Number: PT0023725
Permit Category: EPCRA FACILITY
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0005967
Owner: COLTON JOINT USD
Permit Number: PT0015254
Permit Category: HAZMAT HANDLER 11-25 EMPLOYEES (W/GEN PRMT)
Facility Status: ACTIVE
Expiration Date: 10/31/2013

TRANS (Continued) **S106105372**

Region: SAN BERNARDINO
Facility ID: FA0005967
Owner: COLTON JOINT USD
Permit Number: PT0023723
Permit Category: HAZARDOUS WASTE GENERATOR - 11-25 EMPLOYEES
Facility Status: ACTIVE
Expiration Date: 10/31/2013

CA WDS:
Facility ID: Santa Ana River 36I017877
Facility Type: Industrial - Facility that treats and/or disposes of liquid or semisolid wastes from any servicing, producing, manufacturing or processing operation of whatever nature, including mining, gravel washing, geothermal operations, air conditioning, ship building and repairing, oil production, storage and disposal operations, water pumping.
Facility Status: Active - Any facility with a continuous or seasonal discharge that is under Waste Discharge Requirements.
NPDES Number: CAS000001 The 1st 2 characters designate the state. The remaining 7 are assigned by the Regional Board
Subregion: 8
Facility Telephone: 9098764110
Facility Contact: MARECEK BILL
Agency Name: COLTON JOINT UNIFIED SCH DIST
Agency Address: 451 N 3rd St
Agency City,St,Zip: Colton 923242253
Agency Contact: MARECEK BILL
Agency Telephone: 9098764110
Agency Type: County
SIC Code: 0
SIC Code 2: Not reported
Primary Waste: Not reported
Primary Waste Type: Not reported
Secondary Waste: Not reported
Secondary Waste Type: Not reported
Design Flow: 0
Baseline Flow: 0
Reclamation: Not reported
POTW: Not reported
Treat To Water: Minor Threat to Water Quality. A violation of a regional board order should cause a relatively minor impairment of beneficial uses compared to a major or minor threat. Not: All nurds without a TTWQ will be considered a minor threat to water quality unless coded at a higher Level. A Zero (0) may be used to code those NURDS that are found to represent no threat to water quality.
Complexity: Category C - Facilities having no waste treatment systems, such as cooling water dischargers or thosewho must comply through best management practices, facilities with passive waste treatment and disposal systems, such as septic systems with subsurface disposal, or dischargers having waste storage systems with land disposal such as dairy waste ponds.

481
West
1/2-1
0.875 mi.
4619 ft.

CACTUS MIDDLE SCHOOL
VALLEY BOULEVARD/CACTUS AVENUE
RIALTO, CA 92316

SCH **S105628851**
ENVIROSTOR **N/A**

Relative:
Higher

Actual:
1086 ft.

SCH:

Facility ID:	36010034
Site Type:	School Investigation
Site Type Detail:	School
Site Mgmt. Req.:	NONE SPECIFIED
Acres:	17
National Priorities List:	NO
Cleanup Oversight Agencies:	DTSC
Lead Agency:	DTSC
Lead Agency Description:	* DTSC
Project Manager:	Not reported
Supervisor:	Javier Hinojosa
Division Branch:	Southern California Schools & Brownfields Outreach
Site Code:	404329
Assembly:	47
Senate:	20
Special Program Status:	Not reported
Status:	No Further Action
Status Date:	08/29/2002
Restricted Use:	NO
Funding:	School District
Latitude:	34.07078
Longitude:	-117.3822
APN:	NONE SPECIFIED
Past Use:	AGRICULTURAL - ROW CROPS
Potential COC:	NONE SPECIFIED,31000
Confirmed COC:	NONE SPECIFIED
Potential Description:	NONE SPECIFIED
Alias Name:	CACTUS MIDDLE SCHOOL
Alias Type:	Alternate Name
Alias Name:	COLTON JOINT UNIFIED SCHOOL DISTRICT
Alias Type:	Alternate Name
Alias Name:	COLTON JOINT USD-PRPSD MID SCL VLLEY BLV
Alias Type:	Alternate Name
Alias Name:	404329
Alias Type:	Project Code (Site Code)
Alias Name:	36010034
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Preliminary Endangerment Assessment Report
Completed Date:	03/16/2005
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Preliminary Endangerment Assessment Workplan
Completed Date:	08/04/2004
Comments:	Not reported
Completed Area Name:	PROJECT WIDE

CACTUS MIDDLE SCHOOL (Continued) **S105628851**

Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 04/26/2002
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 04/24/2002
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Cost Recovery Closeout Memo
Completed Date: 06/07/2005
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Environmental Oversight Agreement
Completed Date: 08/29/2002
Comments: Not reported

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

ENVIROSTOR:
Site Type: School Investigation
Site Type Detailed: School
Acres: 17
NPL: NO
Regulatory Agencies: DTSC
Lead Agency: DTSC
Program Manager: Not reported
Supervisor: Javier Hinojosa
Division Branch: Southern California Schools & Brownfields Outreach
Facility ID: 36010034
Site Code: 404329
Assembly: 47
Senate: 20
Special Program: Not reported
Status: No Further Action
Status Date: 08/29/2002
Restricted Use: NO
Site Mgmt. Req.: NONE SPECIFIED
Funding: School District
Latitude: 34.07078
Longitude: -117.3822
APN: NONE SPECIFIED
Past Use: AGRICULTURAL - ROW CROPS

CACTUS MIDDLE SCHOOL (Continued) **S105628851**

Potential COC: NONE SPECIFIED,31000
Confirmed COC: NONE SPECIFIED
Potential Description: NONE SPECIFIED
Alias Name: CACTUS MIDDLE SCHOOL
Alias Type: Alternate Name
Alias Name: COLTON JOINT UNIFIED SCHOOL DISTRICT
Alias Type: Alternate Name
Alias Name: COLTON JOINT USD-PRPSD MID SCL VLLEY BLV
Alias Type: Alternate Name
Alias Name: 404329
Alias Type: Project Code (Site Code)
Alias Name: 36010034
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Report
Completed Date: 03/16/2005
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Workplan
Completed Date: 08/04/2004
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 04/26/2002
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 04/24/2002
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Cost Recovery Closeout Memo
Completed Date: 06/07/2005
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Environmental Oversight Agreement
Completed Date: 08/29/2002
Comments: Not reported

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported

CACTUS MIDDLE SCHOOL (Continued) **S105628851**

Schedule Due Date: Not reported
Schedule Revised Date: Not reported

BI482 **HOLLIDAY SANITARY LANDFILL** **WMUDS/SWAT** **S103320775**
SSW **SANTA ANA AVE** **N/A**
1/2-1 **RIALTO ,CA, CA 92376**
0.900 mi.
4753 ft. **Site 1 of 3 in cluster BI**

Relative:
Lower

Actual:
974 ft.

WMUDS/SWAT:

Edit Date:	Not reported
Complexity:	Not reported
Primary Waste:	Not reported
Primary Waste Type:	Not reported
Secondary Waste:	Not reported
Secondary Waste Type:	Not reported
Base Meridian:	SB
NPID:	Not reported
Tonnage:	1
Regional Board ID:	Not reported
Municipal Solid Waste:	False
Superorder:	False
Open To Public:	False
Waste List:	False
Agency Type:	Not reported
Agency Name:	FREDRICK HOLLIDAY
Agency Department:	Not reported
Agency Address:	2193 W. FOOTHILL BLVD.
Agency City,St,Zip:	UPLAND 91786
Agency Contact:	Not reported
Agency Telephone:	7149821553
Land Owner Name:	FREDRICK HOLLIDAY, ET AL
Land Owner Address:	2303 SIENA COURT
Land Owner City,St,Zip:	CLAREMONT, CA 91711
Land Owner Contact:	Not reported
Land Owner Phone:	7146212080
Region:	8
Facility Type:	Not reported
Facility Description:	Not reported
Facility Telephone:	Not reported
SWAT Facility Name:	HOLLIDAY SANITARY LANDFILL
Primary SIC:	Not reported
Secondary SIC:	Not reported
Comments:	Not reported
Last Facility Editors:	Not reported
Waste Discharge System:	False
Solid Waste Assessment Test Program:	True
Toxic Pits Cleanup Act Program:	False
Resource Conservation Recovery Act:	False
Department of Defence:	False
Solid Waste Assessment Test Program:	FREDRICK HOLLIDAY
Threat to Water Quality:	Not reported
Sub Chapter 15:	False
Regional Board Project Officer:	MA
Number of WMUDS at Facility:	1
Section Range:	01S05W25
RCRA Facility:	Not reported
Waste Discharge Requirements:	Not reported

HOLLIDAY SANITARY LANDFILL (Continued) **S103320775**

Self-Monitoring Rept. Frequency: Not reported
Waste Discharge System ID: 8 360308001
Solid Waste Information ID: 36-AA-0064

BI483 **HOLLIDAY INERTWASTE SITE** **SWF/LF** **S102361949**
SSW **249 EAST SANTA ANA AVENUE** **N/A**
1/2-1 **RIALTO, CA**
0.902 mi.
4762 ft. **Site 2 of 3 in cluster BI**

Relative:
Lower

Actual:
975 ft.

SWF/LF (SWIS):

Region:	STATE
Facility ID:	36-AA-0064
Lat/Long:	34.05583 / -117.37361
Owner Name:	Holliday Trucking
Owner Telephone:	9099821553
Owner Address:	Mr. Holliday
Owner Address2:	2193 West Foothill Blvd
Owner City,St,Zip:	Upland, CA 91786
Operational Status:	Active
Operator:	Holliday Trucking
Operator Phone:	9099821553
Operator Address:	Mr. Holliday
Operator Address2:	2193 West Foothill Blvd
Operator City,St,Zip:	Upland, CA 91786
Permit Date:	07/02/2004
Permit Status:	Notification
Permitted Acreage:	40
Activity:	Inert Debris ENG Fill Operation
Regulation Status:	Notification
Landuse Name:	Industrial,Commercial
GIS Source:	Map
Category:	Disposal
Unit Number:	01
Inspection Frequency:	Quarterly
Accepted Waste:	Construction/demolition,Inert
Closure Date:	Not reported
Closure Type:	Not reported
Disposal Acreage:	5
SWIS Num:	36-AA-0064
Waste Discharge Requirement Num:	III
Program Type:	Not reported
Permitted Throughput with Units:	500
Actual Throughput with Units:	Cu Yards/day
Permitted Capacity with Units:	2000000
Remaining Capacity:	2000000
Remaining Capacity with Units:	Cubic Yards

BJ484 **LANDFILLRIALTO** **WMUDS/SWAT** **S103442702**
SSW **SANTA ANA AVE** **WDS** **N/A**
1/2-1 **RIALTO, CA 0**
0.902 mi.
4764 ft. **Site 1 of 2 in cluster BJ**

Relative:
Lower

Actual:
963 ft.

WMUDS/SWAT:

Edit Date:	Not reported
Complexity:	Category B - Any facility having a physical, chemical, or biological waste treatment system (except for septic systems with subsurface disposal), or any Class II or III disposal site, or facilities without treatment systems that are complex, such as marinas with petroleum products, solid wastes, and sewage pump out facilities.
Primary Waste:	Solid Wastes
Primary Waste Type:	Nonhazardous Solid Wastes/Influent or Solid Wastes that contain nonhazardous putrescible and non putrescible solid, semisolid, and liquid wastes (E.G., garbage, trash, refuse, paper, demolition and construction wastes, manure, vegetable or animal solid and semisolid waste).
Secondary Waste:	Not reported
Secondary Waste Type:	Not reported
Base Meridian:	SB
NPID:	Not reported
Tonnage:	17
Regional Board ID:	Not reported
Municipal Solid Waste:	True
Superorder:	True
Open To Public:	False
Waste List:	False
Agency Type:	City
Agency Name:	RIALTO, CITY OF
Agency Department:	DIRECTOR, COMMUNITY SERVICES
Agency Address:	150 SOUTH PALM AVENUE
Agency City,St,Zip:	RIALTO CA 92376
Agency Contact:	JOE GUZZETTA
Agency Telephone:	9098202689
Land Owner Name:	CITY OF RIALTO
Land Owner Address:	150 SOUTH PALM STREET
Land Owner City,St,Zip:	RIALTO, CA 92376
Land Owner Contact:	RICHARD POLEN,
Land Owner Phone:	7148202533
Region:	8
Facility Type:	Solid Waste Site-Class III - Landfills for non hazardous solid wastes.
Facility Description:	Not reported
Facility Telephone:	Not reported
SWAT Facility Name:	CITY OF RIALTO DISPOSAL SITE
Primary SIC:	4953
Secondary SIC:	Not reported
Comments:	Not reported
Last Facility Editors:	Not reported
Waste Discharge System:	True
Solid Waste Assessment Test Program:	True
Toxic Pits Cleanup Act Program:	False
Resource Conservation Recovery Act:	False
Department of Defence:	False
Solid Waste Assessment Test Program:	CITY OF RIALTO
Threat to Water Quality:	Major Threat to Water Quality. A violation could render unusable a ground water or surface water resource used as a significant drink water supply, require closure of an area used for contact recreation,

LANDFILLRIALTO (Continued) **S103442702**

result in long-term deleterious effects on shell fish spawning or growth areas of aquatic resources, or directly expose the public to toxic substances.

Sub Chapter 15: True
Regional Board Project Officer: RA
Number of WMUDS at Facility: 1
Section Range: 01S05W25
RCRA Facility: No
Waste Discharge Requirements: A
Self-Monitoring Rept. Frequency: Quarterly Submittal
Waste Discharge System ID: 8 360112002
Solid Waste Information ID: 36-AA-0250

CA WDS:

Facility ID: Santa Ana River 360112002
Facility Type: Solid Waste Site-Class III - Landfills for non hazardous solid wastes.
Facility Status: Active - Any facility with a continuous or seasonal discharge that is under Waste Discharge Requirements.
NPDES Number: Not reported
Subregion: 8
Facility Telephone: Not reported
Facility Contact: Not reported
Agency Name: RIALTO CITY OF
Agency Address: 150 SOUTH PALM AVENUE
Agency City,St,Zip: RIALTO 92376
Agency Contact: BRADLEY L. BAXTER
Agency Telephone: 9094217229
Agency Type: City
SIC Code: 4953
SIC Code 2: Not reported
Primary Waste: Solid Wastes
Primary Waste Type: Nonhazardous Solid Wastes/Influent or Solid Wastes that contain nonhazardous putrescible and non putrescible solid, semisolid, and liquid wastes (E.G., garbage, trash, refuse, paper, demolition and construction wastes, manure, vegetable or animal solid and semisolid waste).
Secondary Waste: Not reported
Secondary Waste Type: Not reported
Design Flow: 0
Baseline Flow: 0
Reclamation: No reclamation requirements associated with this facility.
POTW: The facility is not a POTW.
Treat To Water: Major Threat to Water Quality. A violation could render unusable a ground water or surface water resource used as a significant drink water supply, require closure of an area used for contact recreation, result in long-term deleterious effects on shell fish spawning or growth areas of aquatic resources, or directly expose the public to toxic substances.
Complexity: Category B - Any facility having a physical, chemical, or biological waste treatment system (except for septic systems with subsurface disposal), or any Class II or III disposal site, or facilities without treatment systems that are complex, such as marinas with petroleum products, solid wastes, and sewage pump out facilities.

BJ485 **RIALTO SEWER PLANT** **SWF/LF** **U001575558**
SSW **501 E SANTA ANA** **HIST UST** **N/A**
1/2-1 **RIALTO, CA 92376** **San Bern. Co. Permit**
0.904 mi.
4775 ft. **Site 2 of 2 in cluster BJ**

Relative:
Lower

Actual:
961 ft.

SWF/LF (SWIS):

Region:	STATE
Facility ID:	36-AA-0446
Lat/Long:	34.0531500 / -117.35999
Owner Name:	City Of Rialto
Owner Telephone:	9098791140
Owner Address:	Economic Development attn. Rob Steel
Owner Address2:	150 South Palm Street
Owner City,St,Zip:	Rialto, CA 92376
Operational Status:	Active
Operator:	Ener Tech Environmental California LLC
Operator Phone:	9492358677
Operator Address:	Rus Miller-VP Engineering Energy Project
Operator Address2:	657 Seminole Avenue, Suite 207
Operator City,St,Zip:	Alanta, GA 30307-1479
Permit Date:	06/08/2009
Permit Status:	Permitted
Permitted Acreage:	6.4
Activity:	Large Volume Transfer/Proc Facility
Regulation Status:	Permitted
Landuse Name:	Industrial,Commercial
GIS Source:	Map
Category:	Transfer/Processing
Unit Number:	01
Inspection Frequency:	Monthly
Accepted Waste:	Sludge (BioSolids)
Closure Date:	Not reported
Closure Type:	Not reported
Disposal Acreage:	Not reported
SWIS Num:	36-AA-0446
Waste Discharge Requirement Num:	Not reported
Program Type:	Not reported
Permitted Throughput with Units:	1080
Actual Throughput with Units:	Tons/day
Permitted Capacity with Units:	1650
Remaining Capacity:	Not reported
Remaining Capacity with Units:	Tons/day

HIST UST:

Region:	STATE
Facility ID:	00000057507
Facility Type:	Other
Other Type:	SEWER PLANT
Total Tanks:	0001
Contact Name:	Not reported
Telephone:	7148202610
Owner Name:	CITY OF RIALTO
Owner Address:	150 S PALM
Owner City,St,Zip:	RIALTO, CA 92376
Tank Num:	001
Container Num:	1
Year Installed:	1980

RIALTO SEWER PLANT (Continued) **U001575558**

Tank Capacity: 00002000
Tank Used for: PRODUCT
Type of Fuel: DIESEL
Tank Construction: Not reported
Leak Detection: Stock Inventor

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0002076
Owner: CITY OF RIALTO
Permit Number: PT0003560
Permit Category: CALARP FACILITY PERMIT
Facility Status: INACTIVE
Expiration Date: 10/31/2004

Region: SAN BERNARDINO
Facility ID: FA0002076
Owner: CITY OF RIALTO
Permit Number: PT0003555
Permit Category: RISK MANAGEMENT PLAN - LEVEL III
Facility Status: INACTIVE
Expiration Date: 10/31/2004

Region: SAN BERNARDINO
Facility ID: FA0002076
Owner: CITY OF RIALTO
Permit Number: PT0003561
Permit Category: HAZARDOUS WASTE GENERATOR - 11-25 EMPLOYEES
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0002076
Owner: CITY OF RIALTO
Permit Number: PT0003554
Permit Category: EPCRA FACILITY
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0002076
Owner: CITY OF RIALTO
Permit Number: PT0003559
Permit Category: HAZMAT HANDLER 11-25 EMPLOYEES (W/GEN PRMT)
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0002076
Owner: CITY OF RIALTO
Permit Number: PT0011184
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 10/31/2013

Region: SAN BERNARDINO
Facility ID: FA0002076

RIALTO SEWER PLANT (Continued) **U001575558**

Owner: CITY OF RIALTO
Permit Number: PT0011185
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: ACTIVE
Expiration Date: 10/31/2013

BI486 **ECOLOGY AUTO WRECKING** **SWF/LF S108087010**
SSW **221 SANTA ANA AVENUE EAST** **LUST N/A**
1/2-1 **RIALTO, CA 92376**
0.907 mi.
4790 ft. **Site 3 of 3 in cluster BI**

Relative:
Lower

Actual:
977 ft.

SWF/LF (SWIS):
Region: STATE
Facility ID: 36-AA-0457
Lat/Long: 34.05592 / -117.36823
Owner Name: Rialto Properties
Owner Telephone: 5629219947
Owner Address: Not reported
Owner Address2: 14150 Vine Place
Owner City,St,Zip: Cerritos, CA 90703
Operational Status: Inactive
Operator: Ecology Auto Parts
Operator Phone: 5629219974
Operator Address: Not reported
Operator Address2: 14150 Vine Place
Operator City,St,Zip: Cerritos, CA 90703
Permit Date: 09/07/2011
Permit Status: Notification
Permitted Acreage: 3
Activity: Chipping and Grinding Activity Fac./ Op.
Regulation Status: Notification
Landuse Name: Industrial
GIS Source: Map
Category: Composting
Unit Number: 01
Inspection Frequency: Quarterly
Accepted Waste: Green Materials,Wood waste
Closure Date: Not reported
Closure Type: Not reported
Disposal Acreage: Not reported
SWIS Num: 36-AA-0457
Waste Discharge Requirement Num: Not reported
Program Type: Not reported
Permitted Throughput with Units: 200
Actual Throughput with Units: Tons/day
Permitted Capacity with Units: 44000
Remaining Capacity: Not reported
Remaining Capacity with Units: Tons/year

LUST:
Region: STATE
Global Id: T0607133526
Latitude: 34.054993
Longitude: -117.367493
Case Type: LUST Cleanup Site
Status: Open - Site Assessment

ECOLOGY AUTO WRECKING (Continued) **S108087010**

Status Date:	03/08/2006
Lead Agency:	SANTA ANA RWQCB (REGION 8)
Case Worker:	RS
Local Agency:	SAN BERNARDINO COUNTY
RB Case Number:	Not reported
LOC Case Number:	2006001
File Location:	Local Agency
Potential Media Affect:	Aquifer used for drinking water supply
Potential Contaminants of Concern:	Gasoline
Site History:	In October 2005, petroleum hydrocarbons were detected at the site during the removal of one 10,000 gallon gasoline underground storage tank (UST) and associated piping and dispenser. Concentrations of total petroleum hydrocarbons (TPH) as gasoline in soil samples collected at 3 and 14 feet beneath the USTs remote fill were 770 and 1,500 milligrams per kilogram (mg/kg). In June 2006, one boring, B1, was drilled to groundwater, which was found at 80 feet. In October 2006, four wells were installed at the site. MW1 was installed at the location of boring B1. Methyl tertiary butyl ether (MtBE) was detected in the soil samples collected from B1 every five feet from 15 to 80 feet below ground surface. The MtBE concentrations ranged from 0.0051 to 310 mg/kg. The highest concentrations of petroleum hydrocarbons were detected in the soil sample collected from B1 at a depth of 35 feet. TPH as gasoline, benzene, toluene, ethylbenzene and xylenes (BTEX) were detected in this sample at concentrations of 15,000 mg/kg, 25 mg/kg, 470 mg/kg, 150 mg/kg and 830 mg/kg, respectively. MtBE was also detected in soil samples collected from: MW2 at depths of 30 to 70 feet below surface at concentrations from 0.0074 to 1.9 mg/kg; MW3 at depths of 15 to 70 feet at concentrations ranging from 0.0013 to 17 mg/kg; and MW3 at depths of 45 to 60 feet at concentrations ranging from 0.0056 to 0.20 mg/kg. In October 2006, groundwater samples were collected from the four wells. MtBE detected in the samples from MW1 through MW3 ranged from 7.5 to 1,300 micrograms per liter (g/l). Groundwater concentrations in MW1 have decreased with time and in May 2010, TPH, BTEX and oxygenates were not detected in groundwater from the four wells at the site. On June 21, 2010, SB County LOP requested either a meeting with RP to discuss closure criteria, a workplan for further investigation or a closure request. On July 13, 2010, Ecology Auto Parts requested closure from the County of San Bernardino Office of the Fire Marshal Hazardous Materials Division (County). On August 5, 2010, Ms. Marilyn Kraft of the County transferred this case to our office for Regional Board oversight. County staff did not agree that the case should be closed. An extended vapor extraction test was required to determine the mass and availability of MtBE in soil. Also, an additional downgradient well was required to verify that the plume did not migrate downgradient of well MW1.

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607133526
Contact Type:	Regional Board Caseworker
Contact Name:	ROSE SCOTT
Organization Name:	SANTA ANA RWQCB (REGION 8)
Address:	3737 MAIN STREET, SUITE 500
City:	RIVERSIDE
Email:	rscott@waterboards.ca.gov
Phone Number:	9513206375

ECOLOGY AUTO WRECKING (Continued) **S108087010**

Global Id: T0607133526
Contact Type: Local Agency Caseworker
Contact Name: JACKSON CRUTSINGER
Organization Name: SAN BERNARDINO COUNTY
Address: 620 SOUTH E STREET
City: SAN BERNARDINO
Email: jcrutsinger@sbcfire.org
Phone Number: Not reported

Regulatory Activities:

Global Id: T0607133526
Action Type: ENFORCEMENT
Date: 11/18/2010
Action: Staff Letter

Global Id: T0607133526
Action Type: Other
Date: 01/01/1950
Action: Leak Began

Global Id: T0607133526
Action Type: ENFORCEMENT
Date: 11/18/2010
Action: Staff Letter

Global Id: T0607133526
Action Type: ENFORCEMENT
Date: 10/01/2009
Action: 13267 Monitoring Program

Global Id: T0607133526
Action Type: Other
Date: 01/01/1950
Action: Leak Stopped

Global Id: T0607133526
Action Type: ENFORCEMENT
Date: 01/04/2011
Action: Technical Correspondence / Assistance / Other

Global Id: T0607133526
Action Type: ENFORCEMENT
Date: 06/21/2010
Action: Staff Letter

Global Id: T0607133526
Action Type: ENFORCEMENT
Date: 08/05/2010
Action: Referral to Regional Board

Global Id: T0607133526
Action Type: ENFORCEMENT
Date: 08/06/2010
Action: Technical Correspondence / Assistance / Other

Global Id: T0607133526
Action Type: ENFORCEMENT

ECOLOGY AUTO WRECKING (Continued) **S108087010**

Date: 05/28/2009
Action: Staff Letter

Global Id: T0607133526
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

Global Id: T0607133526
Action Type: RESPONSE
Date: 11/15/2011
Action: Pilot Study/ Treatability Report

Global Id: T0607133526
Action Type: RESPONSE
Date: 11/15/2011
Action: Well Installation Report

Global Id: T0607133526
Action Type: ENFORCEMENT
Date: 02/13/2013
Action: Staff Letter

Global Id: T0607133526
Action Type: ENFORCEMENT
Date: 08/05/2010
Action: Referral to Regional Board

Global Id: T0607133526
Action Type: ENFORCEMENT
Date: 07/09/2009
Action: 13267 Monitoring Program

Global Id: T0607133526
Action Type: ENFORCEMENT
Date: 12/15/2011
Action: Staff Letter

Global Id: T0607133526
Action Type: RESPONSE
Date: 07/13/2010
Action: Request for Closure

Global Id: T0607133526
Action Type: RESPONSE
Date: 07/20/2010
Action: Request for Closure

Global Id: T0607133526
Action Type: RESPONSE
Date: 07/20/2010
Action: Request for Closure

Global Id: T0607133526
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

ECOLOGY AUTO WRECKING (Continued) **S108087010**

Global Id: T0607133526
Action Type: ENFORCEMENT
Date: 02/23/2011
Action: Staff Letter

BK487 **CA PORTLAND CEMENT CO** **NPDES** **U001574647**
SE **695 S RANCHO AVE** **LUST** **N/A**
1/2-1 **COLTON, CA 92324** **HIST UST**
0.970 mi. **San Bern. Co. Permit**
5122 ft. **Site 1 of 4 in cluster BK** **EMI**

Relative: Lower

Actual: 965 ft.

NPDES:

Npdes Number:	CAS000001
Facility Status:	Active
Agency Id:	0
Region:	8
Regulatory Measure Id:	213232
Order No:	97-03-DWQ
Regulatory Measure Type:	Enrollee
Place Id:	Not reported
WDID:	8 36I006256
Program Type:	Industrial
Adoption Date Of Regulatory Measure:	Not reported
Effective Date Of Regulatory Measure:	04/22/1992
Expiration Date Of Regulatory Measure:	Not reported
Termination Date Of Regulatory Measure:	Not reported
Discharge Name:	California Portland Cement Co
Discharge Address:	PO BOX 947
Discharge City:	COLTON
Discharge State:	California
Discharge Zip:	92324

Npdes Number:	CAS000001
Facility Status:	Active
Agency Id:	0
Region:	8
Regulatory Measure Id:	436101
Order No:	97-03-DWQ
Regulatory Measure Type:	Enrollee
Place Id:	Not reported
WDID:	8 36I024148
Program Type:	Industrial
Adoption Date Of Regulatory Measure:	Not reported
Effective Date Of Regulatory Measure:	03/22/2013
Expiration Date Of Regulatory Measure:	Not reported
Termination Date Of Regulatory Measure:	Not reported
Discharge Name:	Skanska
Discharge Address:	1995 Agua Mansa Rd
Discharge City:	Riverside
Discharge State:	California
Discharge Zip:	92509

LUST:

Region:	STATE
Global Id:	T0607100069
Latitude:	34.0578111

CA PORTLAND CEMENT CO (Continued) **U001574647**

Longitude:	-117.3343618
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	01/30/1989
Lead Agency:	SAN BERNARDINO COUNTY
Case Worker:	CR2
Local Agency:	SAN BERNARDINO COUNTY
RB Case Number:	083600677T
LOC Case Number:	87009
File Location:	Local Agency
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Diesel
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607100069
Contact Type:	Local Agency Caseworker
Contact Name:	CATHERINE RICHARDS
Organization Name:	SAN BERNARDINO COUNTY
Address:	620 SOUTH E STREET
City:	SAN BERNARDINO
Email:	crichards@sbcfire.org
Phone Number:	9093868419

Global Id:	T0607100069
Contact Type:	Regional Board Caseworker
Contact Name:	TOM E. MBEKE-EKANEM
Organization Name:	SANTA ANA RWQCB (REGION 8)
Address:	3737 MAIN STREET, SUITE 500
City:	RIVERSIDE
Email:	tmbeke-ekanem@waterboards.ca.gov
Phone Number:	9513202007

Regulatory Activities:

Global Id:	T0607100069
Action Type:	ENFORCEMENT
Date:	01/30/1989
Action:	Closure/No Further Action Letter

Global Id:	T0607100069
Action Type:	Other
Date:	01/01/1950
Action:	Leak Reported

Global Id:	T0607100069
Action Type:	REMEDIATION
Date:	01/01/1950
Action:	Excavation

HIST UST:

Region:	STATE
Facility ID:	00000013292
Facility Type:	Other
Other Type:	CEMENT MANUFACTURE

CA PORTLAND CEMENT CO (Continued) **U001574647**

Total Tanks: 0003
Contact Name: G.E. THORNBERRY
Telephone: 7148254260
Owner Name: CALIFORNIA PORTLAND CEMENT COM
Owner Address: 800 WILSHIRE BLVD.
Owner City,St,Zip: LOS ANGELES, CA 90017

Tank Num: 001
Container Num: R6-TFS 3
Year Installed: 1977
Tank Capacity: 00005000
Tank Used for: PRODUCT
Type of Fuel: UNLEADED
Tank Construction: 1/4 inches
Leak Detection: Stock Inventor

Tank Num: 002
Container Num: T4-TOS 1
Year Installed: Not reported
Tank Capacity: 00001600
Tank Used for: WASTE
Type of Fuel: WASTE OIL
Tank Construction: Not reported
Leak Detection: None

Tank Num: 003
Container Num: R6-TFS 1
Year Installed: 1955
Tank Capacity: 00012000
Tank Used for: PRODUCT
Type of Fuel: REGULAR
Tank Construction: 1/4 inches
Leak Detection: Stock Inventor

San Bern. Co. Permit:
Region: SAN BERNARDINO
Facility ID: FA0001681
Owner: CALPORTLAND CEMENT CO
Permit Number: PT0016905
Permit Category: CALARP FACILITY PERMIT
Facility Status: INACTIVE
Expiration Date: 09/30/2011

Region: SAN BERNARDINO
Facility ID: FA0001681
Owner: CALPORTLAND CEMENT CO
Permit Number: PT0016906
Permit Category: RISK MANAGEMENT PLAN - LEVEL I
Facility Status: INACTIVE
Expiration Date: 09/30/2011

Region: SAN BERNARDINO
Facility ID: FA0001681
Owner: CALPORTLAND CEMENT CO
Permit Number: PT0011771
Permit Category: UST OWNERSHIP/OPERATING PERMIT (PER UST)
Facility Status: INACTIVE

CA PORTLAND CEMENT CO (Continued) **U001574647**

Expiration Date: 09/30/2003

Region: SAN BERNARDINO
Facility ID: FA0001681
Owner: CALPORTLAND CEMENT CO
Permit Number: PT0002544
Permit Category: HAZARDOUS WASTE GENERATOR - 11-25 EMPLOYEES
Facility Status: ACTIVE
Expiration Date: 09/30/2013

Region: SAN BERNARDINO
Facility ID: FA0001681
Owner: CALPORTLAND CEMENT CO
Permit Number: PT0020775
Permit Category: APSA 10,001-100,000 GAL FAC CAPACITY
Facility Status: ACTIVE
Expiration Date: 09/30/2013

Region: SAN BERNARDINO
Facility ID: FA0001681
Owner: CALPORTLAND CEMENT CO
Permit Number: PT0002543
Permit Category: HAZMAT HANDLER 11-25 EMPLOYEES (W/GEN PRMT)
Facility Status: ACTIVE
Expiration Date: 09/30/2013

Region: SAN BERNARDINO
Facility ID: FA0001681
Owner: CALPORTLAND CEMENT CO
Permit Number: PT0016907
Permit Category: EPCRA FACILITY
Facility Status: ACTIVE
Expiration Date: 09/30/2013

Region: SAN BERNARDINO
Facility ID: FA0001681
Owner: CALPORTLAND CEMENT CO
Permit Number: PT0020181
Permit Category: WASTE-GENERATING RECYCLER (ONSITE)
Facility Status: ACTIVE
Expiration Date: 09/30/2013

Region: SAN BERNARDINO
Facility ID: FA0001681
Owner: CALPORTLAND CEMENT CO
Permit Number: PT0020182
Permit Category: UW HANDLER W/ ANOTHER HAZ WASTE GENERATOR FEE
Facility Status: ACTIVE
Expiration Date: 09/30/2013

Region: SAN BERNARDINO
Facility ID: FA0014581
Owner: BUBALO, NICK
Permit Number: PT0025482
Permit Category: HAZMAT HANDLER 0-10 EMPLOYEES
Facility Status: ACTIVE
Expiration Date: 05/31/2013

CA PORTLAND CEMENT CO (Continued) **U001574647**

Region: SAN BERNARDINO
Facility ID: FA0014355
Owner: PAREDES, ANTONIO T
Permit Number: PT0025273
Permit Category: HAZARDOUS WASTE GENERATOR - 0-10 EMPLOYEES
Facility Status: ACTIVE
Expiration Date: 04/30/2013

Region: SAN BERNARDINO
Facility ID: FA0014355
Owner: PAREDES, ANTONIO T
Permit Number: PT0025272
Permit Category: HAZMAT HANDLER 0-10 EMPLOYEES (W/GEN PRMT)
Facility Status: ACTIVE
Expiration Date: 04/30/2013

Region: SAN BERNARDINO
Facility ID: FA0014355
Owner: PAREDES, ANTONIO T
Permit Number: PT0025274
Permit Category: APSA 1,320-10,000 GAL FAC CAPACITY
Facility Status: ACTIVE
Expiration Date: 04/30/2013

EMI:

Year:	1987
County Code:	36
Air Basin:	SC
Facility ID:	800181
Air District Name:	SC
SIC Code:	3273
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	11
Reactive Organic Gases Tons/Yr:	7
Carbon Monoxide Emissions Tons/Yr:	287
NOX - Oxides of Nitrogen Tons/Yr:	2639
SOX - Oxides of Sulphur Tons/Yr:	121
Particulate Matter Tons/Yr:	145
Part. Matter 10 Micrometers & Smllr Tons/Yr:	107

Year:	1990
County Code:	36
Air Basin:	SC
Facility ID:	800181
Air District Name:	SC
SIC Code:	3273
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	5
Reactive Organic Gases Tons/Yr:	2
Carbon Monoxide Emissions Tons/Yr:	318
NOX - Oxides of Nitrogen Tons/Yr:	1818
SOX - Oxides of Sulphur Tons/Yr:	112
Particulate Matter Tons/Yr:	161

CA PORTLAND CEMENT CO (Continued) **U001574647**

Part. Matter 10 Micrometers & Smllr Tons/Yr:	121
Year:	1993
County Code:	36
Air Basin:	SC
Facility ID:	800181
Air District Name:	SC
SIC Code:	3273
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	3
Reactive Organic Gases Tons/Yr:	2
Carbon Monoxide Emissions Tons/Yr:	163
NOX - Oxides of Nitrogen Tons/Yr:	866
SOX - Oxides of Sulphur Tons/Yr:	9
Particulate Matter Tons/Yr:	63
Part. Matter 10 Micrometers & Smllr Tons/Yr:	58
Year:	1995
County Code:	36
Air Basin:	SC
Facility ID:	800181
Air District Name:	SC
SIC Code:	3273
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	3
Reactive Organic Gases Tons/Yr:	2
Carbon Monoxide Emissions Tons/Yr:	163
NOX - Oxides of Nitrogen Tons/Yr:	866
SOX - Oxides of Sulphur Tons/Yr:	9
Particulate Matter Tons/Yr:	63
Part. Matter 10 Micrometers & Smllr Tons/Yr:	58
Year:	1996
County Code:	36
Air Basin:	SC
Facility ID:	800181
Air District Name:	SC
SIC Code:	3273
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	343
NOX - Oxides of Nitrogen Tons/Yr:	2294
SOX - Oxides of Sulphur Tons/Yr:	53
Particulate Matter Tons/Yr:	162
Part. Matter 10 Micrometers & Smllr Tons/Yr:	150
Year:	1997
County Code:	36
Air Basin:	SC
Facility ID:	800181

CA PORTLAND CEMENT CO (Continued) **U001574647**

Air District Name:	SC
SIC Code:	3241
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	12
Reactive Organic Gases Tons/Yr:	10
Carbon Monoxide Emissions Tons/Yr:	293
NOX - Oxides of Nitrogen Tons/Yr:	1847
SOX - Oxides of Sulphur Tons/Yr:	12
Particulate Matter Tons/Yr:	138
Part. Matter 10 Micrometers & Smllr Tons/Yr:	121

Year:	1998
County Code:	36
Air Basin:	SC
Facility ID:	800181
Air District Name:	SC
SIC Code:	3241
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	12
Reactive Organic Gases Tons/Yr:	10
Carbon Monoxide Emissions Tons/Yr:	293
NOX - Oxides of Nitrogen Tons/Yr:	1847
SOX - Oxides of Sulphur Tons/Yr:	12
Particulate Matter Tons/Yr:	138
Part. Matter 10 Micrometers & Smllr Tons/Yr:	121

Year:	1999
County Code:	36
Air Basin:	SC
Facility ID:	800181
Air District Name:	SC
SIC Code:	3241
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	12
Reactive Organic Gases Tons/Yr:	10
Carbon Monoxide Emissions Tons/Yr:	293
NOX - Oxides of Nitrogen Tons/Yr:	1847
SOX - Oxides of Sulphur Tons/Yr:	12
Particulate Matter Tons/Yr:	138
Part. Matter 10 Micrometers & Smllr Tons/Yr:	121

Year:	2000
County Code:	36
Air Basin:	SC
Facility ID:	800181
Air District Name:	SC
SIC Code:	3241
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	12

CA PORTLAND CEMENT CO (Continued) **U001574647**

Reactive Organic Gases Tons/Yr:	10
Carbon Monoxide Emissions Tons/Yr:	293
NOX - Oxides of Nitrogen Tons/Yr:	1847
SOX - Oxides of Sulphur Tons/Yr:	12
Particulate Matter Tons/Yr:	138
Part. Matter 10 Micrometers & Smllr Tons/Yr:	121

Year:	2002
County Code:	36
Air Basin:	SC
Facility ID:	800181
Air District Name:	SC
SIC Code:	3241
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	14
Reactive Organic Gases Tons/Yr:	6
Carbon Monoxide Emissions Tons/Yr:	160
NOX - Oxides of Nitrogen Tons/Yr:	974
SOX - Oxides of Sulphur Tons/Yr:	56
Particulate Matter Tons/Yr:	96
Part. Matter 10 Micrometers & Smllr Tons/Yr:	73

Year:	2003
County Code:	36
Air Basin:	SC
Facility ID:	800181
Air District Name:	SC
SIC Code:	3241
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	14
Reactive Organic Gases Tons/Yr:	6
Carbon Monoxide Emissions Tons/Yr:	160
NOX - Oxides of Nitrogen Tons/Yr:	974
SOX - Oxides of Sulphur Tons/Yr:	56
Particulate Matter Tons/Yr:	96
Part. Matter 10 Micrometers & Smllr Tons/Yr:	73

Year:	2004
County Code:	36
Air Basin:	SC
Facility ID:	800181
Air District Name:	SC
SIC Code:	3241
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Y
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	13.580592
Reactive Organic Gases Tons/Yr:	6.39
Carbon Monoxide Emissions Tons/Yr:	159.67025
NOX - Oxides of Nitrogen Tons/Yr:	974.0801
SOX - Oxides of Sulphur Tons/Yr:	55.591649
Particulate Matter Tons/Yr:	96.31023
Part. Matter 10 Micrometers & Smllr Tons/Yr:	73.19

CA PORTLAND CEMENT CO (Continued) **U001574647**

Year:	2005
County Code:	36
Air Basin:	SC
Facility ID:	800181
Air District Name:	SC
SIC Code:	3241
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	5.554685
Reactive Organic Gases Tons/Yr:	2.70069394
Carbon Monoxide Emissions Tons/Yr:	156.2218
NOX - Oxides of Nitrogen Tons/Yr:	937.496
SOX - Oxides of Sulphur Tons/Yr:	87.0118
Particulate Matter Tons/Yr:	112.96131
Part. Matter 10 Micrometers & Smllr Tons/Yr:	89.5607755

Year:	2006
County Code:	36
Air Basin:	SC
Facility ID:	800181
Air District Name:	SC
SIC Code:	3241
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	11.42005235483244631
Reactive Organic Gases Tons/Yr:	8.751
Carbon Monoxide Emissions Tons/Yr:	73.32
NOX - Oxides of Nitrogen Tons/Yr:	794.26
SOX - Oxides of Sulphur Tons/Yr:	108.76
Particulate Matter Tons/Yr:	117.207
Part. Matter 10 Micrometers & Smllr Tons/Yr:	98.61353

Year:	2007
County Code:	36
Air Basin:	SC
Facility ID:	800181
Air District Name:	SC
SIC Code:	3241
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	11.41705831093817378
Reactive Organic Gases Tons/Yr:	8.751
Carbon Monoxide Emissions Tons/Yr:	73.32
NOX - Oxides of Nitrogen Tons/Yr:	794.26
SOX - Oxides of Sulphur Tons/Yr:	108.76
Particulate Matter Tons/Yr:	117.207
Part. Matter 10 Micrometers & Smllr Tons/Yr:	98.61353

Year:	2007
County Code:	36
Air Basin:	SC
Facility ID:	800181
Air District Name:	SC
SIC Code:	3241

CA PORTLAND CEMENT CO (Continued) **U001574647**

Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	8.510901511148677686
Reactive Organic Gases Tons/Yr:	6.5738160511353527
Carbon Monoxide Emissions Tons/Yr:	71.05
NOX - Oxides of Nitrogen Tons/Yr:	607.08
SOX - Oxides of Sulphur Tons/Yr:	46.83
Particulate Matter Tons/Yr:	104.7914545
Part. Matter 10 Micrometers & Smllr Tons/Yr:	89.735392883

BK488 **CALIFORNIA PORTLAND CEMENT CO** **CERC-NFRAP 1015732630**
SE **695 SOUTH RANCHO AVE.** **RCRA-SQG CAD008256315**
1/2-1 **COLTON, CA 92324**
0.970 mi.
5122 ft. **Site 2 of 4 in cluster BK**

Relative:
Lower

Actual:
965 ft.

CERC-NFRAP:

Site ID:	0904614
Federal Facility:	Not a Federal Facility
NPL Status:	Not on the NPL
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information

CERCLIS-NFRAP Site Contact Details:

Contact Sequence ID:	13055567.00000
Person ID:	9271184.00000
Contact Sequence ID:	13287457.00000
Person ID:	13003854.00000
Contact Sequence ID:	13293052.00000
Person ID:	13003858.00000
Contact Sequence ID:	13298910.00000
Person ID:	13004003.00000

CERCLIS-NFRAP Assessment History:

Action:	ARCHIVE SITE
Date Started:	/ /
Date Completed:	01/23/96
Priority Level:	Not reported
Action:	PRELIMINARY ASSESSMENT
Date Started:	/ /
Date Completed:	03/16/94
Priority Level:	Low priority for further assessment
Action:	SITE INSPECTION
Date Started:	03/24/94
Date Completed:	05/04/95
Priority Level:	NFRAP-Site does not qualify for the NPL based on existing information
Action:	DISCOVERY
Date Started:	/ /
Date Completed:	10/16/92
Priority Level:	Not reported

CALIFORNIA PORTLAND CEMENT CO (Continued) **1015732630**

RCRA-SQG:
Date form received by agency: 03/04/1999
Facility name: CALIFORNIA PORTLAND CEMENT CO
Site name: CALIFORNIA PORTLAND CEMENT- COLTON PLANT
Facility address: 695 SOUTH RANCHO AVE.
COLTON, CA 92324
EPA ID: CAD008256315
Mailing address: 2025 E. FINANCIAL WAY
GLENDORA, CA 91741
Contact: TINA SENTNER
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (626) 852-6200
Telephone ext.: 6264
Contact email: Not reported
EPA Region: 09
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 09/01/1996
Facility name: CALIFORNIA PORTLAND CEMENT CO
Classification: Small Quantity Generator

Date form received by agency: 03/20/1996
Facility name: CALIFORNIA PORTLAND CEMENT CO
Site name: CPCC MOJAVE PLANT
Classification: Large Quantity Generator

Date form received by agency: 02/28/1992
Facility name: CALIFORNIA PORTLAND CEMENT CO
Site name: CALIFORNIA PORTLAND CEMENT COM
Classification: Large Quantity Generator

CALIFORNIA PORTLAND CEMENT CO (Continued) **1015732630**

Date form received by agency: 08/08/1980
Facility name: CALIFORNIA PORTLAND CEMENT CO
Classification: Large Quantity Generator

Violation Status: No violations found

BK489 **HIST CORTESE** **S104890721**
SE **695 SOUTH RANCHO AVE** **LUST** **N/A**
1/2-1 **COLTON, CA 92324** **CHMIRS**
0.970 mi.
5122 ft. **Site 3 of 4 in cluster BK**

Relative:
Lower

Actual:
965 ft.

CORTESE:
Region: CORTESE
Facility County Code: 36
Reg By: LTNKA
Reg Id: 083600677T

LUST REG 8:
Region: 8
County: San Bernardino
Regional Board: Santa Ana Region
Facility Status: Case Closed
Case Number: 083600677T
Local Case Num: 87009
Case Type: Soil only
Substance: Diesel
Qty Leaked: Not reported
Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site
Cross Street: AGUA MANSA
Enf Type: CLOS
Funding: Not reported
How Discovered: Tank Closure
How Stopped: Not reported
Leak Cause: UNK
Leak Source: UNK
Global ID: T0607100069
How Stopped Date: Not reported
Enter Date: 10/29/1987
Review Date: Not reported
Prelim Assess: Not reported
Discover Date: Not reported
Enforcement Date: Not reported
Close Date: 1/30/1989
Workplan: Not reported
Pollution Char: 10/29/1987
Remed Plan: Not reported
Remed Action: 1/30/1989
Monitoring: Not reported
Enter Date: 10/29/1987
GW Qualifies: Not reported
Soil Qualifies: Not reported
Operator: Not reported
Facility Contact: Not reported
Interim: Yes
Oversite Program: LUST
Latitude: 34.0576231

(Continued) **S104890721**

Longitude:	-117.3344685
MTBE Date:	Not reported
Max MTBE GW:	Not reported
MTBE Concentration:	0
Max MTBE Soil:	Not reported
MTBE Fuel:	0
MTBE Tested:	Not Required to be Tested.
MTBE Class:	*
Staff:	TME
Staff Initials:	CR2
Lead Agency:	Local Agency
Local Agency:	36000L
Hydr Basin #:	UPPER SANTA ANA VALL
Beneficial:	Not reported
Priority:	Not reported
Cleanup Fund Id:	Not reported
Work Suspended:	Not reported
Summary:	CONTAMINATION COMING FROM DIRECTION OF DISPENSERS (APPROXIMATELY 50 YEARS OLD).

CHMIRS:

OES Incident Number:	'10-7180
OES notification:	11/30/2010
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported

(Continued) **S104890721**

Waterway Involved:	No
Waterway:	Not reported
Spill Site:	Merchant/Business
Cleanup By:	Reporting Party
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Gal(s)
Other:	Not reported
Date/Time:	1200
Year:	2010
Agency:	Cal Portland Co
Incident Date:	11/30/2010
Admin Agency:	Not reported
Amount:	Not reported
Contained:	Yes
Site Type:	Not reported
E Date:	Not reported
Substance:	Hydraulic Fluid
Quantity Released:	120
BBLS:	Not reported
Cups:	Not reported
CUFT:	Not reported
Gallons:	Not reported
Grams:	Not reported
Pounds:	Not reported
Liters:	Not reported
Ounces:	Not reported
Pints:	Not reported
Quarts:	Not reported
Sheen:	Not reported
Tons:	Not reported
Unknown:	Not reported
Evacuations:	Not reported
Number of Injuries:	Not reported
Number of Fatalities:	Not reported
Description:	Front end loader struck barrels causing this release to the soil

---

BK490 **WMUDS/SWAT** **S104156510**
SE **695 SOUTH RANCHO AVE** **CHMIRS** **N/A**
1/2-1 **COLTON, CA 92324** **EMI**
0.970 mi.
5122 ft. **Site 4 of 4 in cluster BK**

Relative:
Lower

Actual:
965 ft.

WMUDS/SWAT:

Edit Date:	Not reported
Complexity:	Not reported
Primary Waste:	Not reported
Primary Waste Type:	Not reported
Secondary Waste:	Not reported
Secondary Waste Type:	Not reported
Base Meridian:	SB
NPID:	Not reported
Tonnage:	0
Regional Board ID:	Not reported
Municipal Solid Waste:	False
Superorder:	False
Open To Public:	False

(Continued) **S104156510**

Waste List:	False
Agency Type:	Not reported
Agency Name:	CALIFORNIA PORTLAND CEMENT
Agency Department:	Not reported
Agency Address:	Not reported
Agency City,St,Zip:	GLENDORA 90017
Agency Contact:	JOHN BENNETT
Agency Telephone:	7148254260
Land Owner Name:	CALIFORNIA PORTLAND CEMENT
Land Owner Address:	Not reported
Land Owner City,St,Zip:	Not reported
Land Owner Contact:	Not reported
Land Owner Phone:	7148254260
Region:	8
Facility Type:	Not reported
Facility Description:	Not reported
Facility Telephone:	Not reported
SWAT Facility Name:	CALIFORNIA PORTLAND CEMENT - COLTON D.
Primary SIC:	Not reported
Secondary SIC:	Not reported
Comments:	Not reported
Last Facility Editors:	Not reported
Waste Discharge System:	False
Solid Waste Assessment Test Program:	True
Toxic Pits Cleanup Act Program:	False
Resource Conservation Recovery Act:	False
Department of Defence:	False
Solid Waste Assessment Test Program:	CALIFORNIA PORTLAND CEMENT
Threat to Water Quality:	Not reported
Sub Chapter 15:	False
Regional Board Project Officer:	GSR
Number of WMUDS at Facility:	1
Section Range:	01S04W30
RCRA Facility:	Not reported
Waste Discharge Requirements:	Not reported
Self-Monitoring Rept. Frequency:	Not reported
Waste Discharge System ID:	8 360008NUR
Solid Waste Information ID:	36-AA-0015

CHMIRS:

OES Incident Number:	00-2143
OES notification:	05/15/2000
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported

(Continued) **S104156510**

Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	No
Waterway:	Not reported
Spill Site:	Not reported
Cleanup By:	Reporting Party
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	2000
Agency:	California Portland Cement Co
Incident Date:	5/15/200012:00:00 AM
Admin Agency:	San Bernardino County Health Department
Amount:	Not reported
Contained:	Yes
Site Type:	Industrial Plant
E Date:	Not reported
Substance:	Diesel
Quantity Released:	Not reported
BBLS:	0
Cups:	0
CUFT:	0
Gallons:	500
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	Valve not completely shut which caused the fuel to spill out of the

(Continued) **S104156510**

tank upon filling

EMI:

Year:	2001
County Code:	36
Air Basin:	SC
Facility ID:	800181
Air District Name:	SC
SIC Code:	3241
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Y
Consolidated Emission Reporting Rule:	B
Total Organic Hydrocarbon Gases Tons/Yr:	2
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	137
NOX - Oxides of Nitrogen Tons/Yr:	925
SOX - Oxides of Sulphur Tons/Yr:	90
Particulate Matter Tons/Yr:	109
Part. Matter 10 Micrometers & Smllr Tons/Yr:	96

491
ESE
1/2-1
0.970 mi.
5123 ft.

AMKO RECYCLING LLC **NPDES** **S109691699**
340 W VALLEY BLVD **SWRCY** **N/A**
COLTON, CA 92324

Relative:
Lower

Actual:
979 ft.

NPDES:

Npdes Number:	CAS000001
Facility Status:	Active
Agency Id:	0
Region:	8
Regulatory Measure Id:	330978
Order No:	97-03-DWQ
Regulatory Measure Type:	Enrollee
Place Id:	Not reported
WDID:	8 36I021093
Program Type:	Industrial
Adoption Date Of Regulatory Measure:	Not reported
Effective Date Of Regulatory Measure:	08/30/2007
Expiration Date Of Regulatory Measure:	Not reported
Termination Date Of Regulatory Measure:	Not reported
Discharge Name:	AMKO Recycling
Discharge Address:	340 W Valley Blvd
Discharge City:	Colton
Discharge State:	California
Discharge Zip:	92324

SWRCY:

Reg Id:	18642
Cert Id:	RC10621
Org Or Agency Reg Id:	18642
Organization Or Agency Name:	Amko Recycling LLC
Mailing Address:	340 W Valley Blvd
Mailing City:	Colton
Mailing State:	CA
Mailing Zip Code:	92324
Website:	Not reported

AMKO RECYCLING LLC (Continued) **S109691699**

Email:	Not reported
Phone Number:	(909) 370-2656
Grand Father:	N
Rural:	N
Operation Begin Date:	01/08/2001
Aluminium:	Y
Glass:	Y
Plastic:	Y
Bimetal:	Y
Agency:	N/A
Monday Hours Of Operation:	8:00 am - 4:30 pm
Tuesday Hours Of Operation:	8:00 am - 4:30 pm
Wednesday Hours Of Operation:	8:00 am - 4:30 pm
Thursday Hours Of Operation:	8:00 am - 4:30 pm
Friday Hours Of Operation:	8:00 am - 4:30 pm
Saturday Hours Of Operation:	8:00 am - 2:00 pm
Sunday Hours Of Operation:	CLOSED

492
NNW
1/2-1
0.973 mi.
5139 ft.

RIALTO RECYCLING CENTER 2 **SWRCY** **S110326834**
515 S RIVERSIDE AVE **N/A**
RIALTO, CA 92376

Relative:
Higher

Actual:
1172 ft.

SWRCY:

Reg Id:	54135
Cert Id:	RC14780
Org Or Agency Reg Id:	19577
Organization Or Agency Name:	CA Recycling Inc
Mailing Address:	3249 W El Segundo Blvd
Mailing City:	Hawthorne
Mailing State:	CA
Mailing Zip Code:	90250
Website:	Not reported
Email:	Not reported
Phone Number:	(310) 978-9900
Grand Father:	N
Rural:	N
Operation Begin Date:	05/01/2010
Aluminium:	Y
Glass:	Y
Plastic:	Y
Bimetal:	Y
Agency:	N/A
Monday Hours Of Operation:	9:00 am - 4:30 pm; Closed 1:00 pm - 1:30 pm
Tuesday Hours Of Operation:	9:00 am - 4:30 pm; Closed 1:00 pm - 1:30 pm
Wednesday Hours Of Operation:	9:00 am - 4:30 pm; Closed 1:00 pm - 1:30 pm
Thursday Hours Of Operation:	CLOSED
Friday Hours Of Operation:	9:00 am - 4:30 pm; Closed 1:00 pm - 1:30 pm
Saturday Hours Of Operation:	9:00 am - 4:30 pm; Closed 1:00 pm - 1:30 pm
Sunday Hours Of Operation:	9:00 am - 1:30 pm; Closed 1:00 pm - 1:30 pm

BL493 **DOMECQ RESERVOIR** **HIST CORTESE** **S104747773**
NE **1011** **LUST** **N/A**
1/2-1 **COLTON, CA 92324**
0.991 mi.
5230 ft. **Site 1 of 2 in cluster BL**

Relative:
Higher

Actual:
1106 ft.

CORTESE:

Region:	CORTESE
Facility County Code:	36
Reg By:	LTNKA
Reg Id:	083603563T

LUST REG 8:

Region:	8
County:	San Bernardino
Regional Board:	Santa Ana Region
Facility Status:	Case Closed
Case Number:	083603563T
Local Case Num:	99091
Case Type:	Soil only
Substance:	Diesel
Qty Leaked:	Not reported
Abate Method:	Not reported
Cross Street:	WATWOOD
Enf Type:	Not reported
Funding:	Not reported
How Discovered:	Tank Closure
How Stopped:	Not reported
Leak Cause:	UNK
Leak Source:	UNK
Global ID:	T0607100604
How Stopped Date:	5/20/1999
Enter Date:	9/17/1999
Review Date:	Not reported
Prelim Assess:	Not reported
Discover Date:	5/20/1999
Enforcement Date:	Not reported
Close Date:	1/17/2001
Workplan:	6/1/1999
Pollution Char:	Not reported
Remed Plan:	Not reported
Remed Action:	Not reported
Monitoring:	Not reported
Enter Date:	9/17/1999
GW Qualifies:	Not reported
Soil Qualifies:	Not reported
Operator:	Not reported
Facility Contact:	Not reported
Interim:	Not reported
Oversite Program:	LUST
Latitude:	34.089502
Longitude:	-117.3384929
MTBE Date:	Not reported
Max MTBE GW:	Not reported
MTBE Concentration:	0
Max MTBE Soil:	Not reported
MTBE Fuel:	0
MTBE Tested:	Not Required to be Tested.
MTBE Class:	*

DOMECQ RESERVOIR (Continued) **S104747773**

Staff: NOM
Staff Initials: LH6
Lead Agency: Local Agency
Local Agency: 36000L
Hydr Basin #: UPPER SANTA ANA VALL
Beneficial: Not reported
Priority: Not reported
Cleanup Fund Id: Not reported
Work Suspended: No
Summary: Not reported

BL494 **DOMECQ RESERVOIR** **LUST** **S109285109**
NE **1011 W ELLEN ST** **N/A**
1/2-1 **COLTON, CA 92324**
0.991 mi.
5230 ft. **Site 2 of 2 in cluster BL**

Relative:
Higher

Actual:
1106 ft.

LUST:
Region: STATE
Global Id: T0607100604
Latitude: 34.0892525
Longitude: -117.339514
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 01/17/2001
Lead Agency: SAN BERNARDINO COUNTY
Case Worker: LH6
Local Agency: Not reported
RB Case Number: 083603563T
LOC Case Number: 99091
File Location: Local Agency
Potential Media Affect: Soil
Potential Contaminants of Concern: Diesel
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0607100604
Contact Type: Regional Board Caseworker
Contact Name: NANCY OLSON-MARTIN
Organization Name: SANTA ANA RWQCB (REGION 8)
Address: 3737 MAIN STREET, SUITE 500
City: RIVERSIDE
Email: nolson-martin@waterboards.ca.gov
Phone Number: Not reported

Regulatory Activities:
Global Id: T0607100604
Action Type: Other
Date: 01/01/1950
Action: Leak Stopped

Global Id: T0607100604
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

DOMECQ RESERVOIR (Continued) **S109285109**

Global Id: T0607100604
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

495
WSW
> 1
1.226 mi.
6472 ft.

UNION PACIFIC RAILROAD CO **CHMIRS** **S105640256**
19100 SLOVER AVE **San Bern. Co. Permit** **N/A**
BLOOMINGTON, CA 92316 **ENVIROSTOR**

Relative:
Lower

Actual:
1051 ft.

CHMIRS:

OES Incident Number:	'10-7689	
OES notification:	12/20/2010	
OES Date:	Not reported	
OES Time:	Not reported	
Incident Date:	Not reported	
Date Completed:	**Not reported**	
Property Use:	Not reported	
Agency Id Number:	Not reported	
Agency Incident Number:	Not reported	
Time Notified:	Not reported	
Time Completed:	Not reported	
Surrounding Area:	Not reported	
Estimated Temperature:	Not reported	
Property Management:	Not reported	
Special Studies 1:	Not reported	
Special Studies 2:	Not reported	
Special Studies 3:	Not reported	
Special Studies 4:	Not reported	
Special Studies 5:	Not reported	
Special Studies 6:	Not reported	
More Than Two Substances Involved?:		Not reported
Resp Agncy Personel # Of Decontaminated:		Not reported
Responding Agency Personel # Of Injuries:		Not reported
Responding Agency Personel # Of Fatalities:		Not reported
Others Number Of Decontaminated:		Not reported
Others Number Of Injuries:		Not reported
Others Number Of Fatalities:		Not reported
Vehicle Make/year:	Not reported	
Vehicle License Number:	Not reported	
Vehicle State:	Not reported	
Vehicle Id Number:	Not reported	
CA/DOT/PUC/ICC Number:	Not reported	
Company Name:	Not reported	
Reporting Officer Name/ID:	Not reported	
Report Date:	Not reported	
Comments:	Not reported	
Facility Telephone:	Not reported	
Waterway Involved:	Yes	
Waterway:	Storm Drain	
Spill Site:	Rail Road	
Cleanup By:	Contractor	
Containment:	Not reported	
What Happened:	Not reported	
Type:	Not reported	
Measure:	Gal(s)	

UNION PACIFIC RAILROAD CO (Continued) **S105640256**

Other:	Not reported
Date/Time:	2212
Year:	2010
Agency:	UPRR
Incident Date:	12/20/2010
Admin Agency:	San Bernardino County Health Department
Amount:	Not reported
Contained:	Yes
Site Type:	Storm Drain
E Date:	Not reported
Substance:	Rain Water
Quantity Released:	Not reported
BBLS:	Not reported
Cups:	Not reported
CUFT:	Not reported
Gallons:	Not reported
Grams:	Not reported
Pounds:	Not reported
Liters:	Not reported
Ounces:	Not reported
Pints:	Not reported
Quarts:	Not reported
Sheen:	Not reported
Tons:	Not reported
Unknown:	Not reported
Evacuations:	Not reported
Number of Injuries:	Not reported
Number of Fatalities:	Not reported
Description:	Caller states that at a rail yard the oil water separator is overflowing with water and rain water. No petroleum product in the water. Caller states that vacuum crews are onscene trying to capture the release.
OES Incident Number:	008506
OES notification:	Not reported
OES Date:	6/1/1995
OES Time:	04:49:17 AM
Incident Date:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported

UNION PACIFIC RAILROAD CO (Continued) **S105640256**

Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	YES
Waterway:	Not reported
Spill Site:	Not reported
Cleanup By:	Not reported
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	1995
Agency:	southern pacific
Incident Date:	6/1/95 0320
Admin Agency:	Not reported
Amount:	Not reported
Contained:	NO
Site Type:	R/R
E Date:	Not reported
Substance:	train car derailment no release
Quantity Released:	Not reported
BBLS:	Not reported
Cups:	Not reported
CUFT:	Not reported
Gallons:	Not reported
Grams:	Not reported
Pounds:	Not reported
Liters:	Not reported
Ounces:	Not reported
Pints:	Not reported
Quarts:	Not reported
Sheen:	Not reported
Tons:	Not reported
Unknown:	Not reported
Evacuations:	NO
Number of Injuries:	NO
Number of Fatalities:	NO
Description:	train car derailment, no leakage. one set of wheels off track, upright.
OES Incident Number:	11-6945
OES notification:	11/22/2011
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported

UNION PACIFIC RAILROAD CO (Continued) **S105640256**

Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	No
Waterway:	Not reported
Spill Site:	Rail Road
Cleanup By:	Reporting Party
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Oz.
Other:	Not reported
Date/Time:	1130
Year:	2011
Agency:	UPRR
Incident Date:	11/22/2011
Admin Agency:	San Bernardino County Health Department
Amount:	Not reported
Contained:	Yes
Site Type:	Not reported
E Date:	Not reported
Substance:	Dicyclopentadidne
Quantity Released:	6
BBLS:	Not reported
Cups:	Not reported
CUFT:	Not reported
Gallons:	Not reported
Grams:	Not reported

UNION PACIFIC RAILROAD CO (Continued) **S105640256**

Pounds:	Not reported
Liters:	Not reported
Ounces:	Not reported
Pints:	Not reported
Quarts:	Not reported
Sheen:	Not reported
Tons:	Not reported
Unknown:	Not reported
Evacuations:	Not reported
Number of Injuries:	Not reported
Number of Fatalities:	Not reported
Description:	RP states that six ounces of the product was found on top of a tank car. No waterways were impacted.
OES Incident Number:	'12-0446
OES notification:	01/23/2012
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	No
Waterway:	Not reported
Spill Site:	Rail Road
Cleanup By:	Unknown
Containment:	Not reported
What Happened:	Not reported

UNION PACIFIC RAILROAD CO (Continued) **S105640256**

Type:	Not reported
Measure:	Gal(s)
Other:	Not reported
Date/Time:	116
Year:	2012
Agency:	UPRR
Incident Date:	1/23/2012
Admin Agency:	San Bernardino County Health Department
Amount:	Not reported
Contained:	Yes
Site Type:	Not reported
E Date:	Not reported
Substance:	Oil - Crude
Quantity Released:	Unknown
BBLS:	Not reported
Cups:	Not reported
CUFT:	Not reported
Gallons:	Not reported
Grams:	Not reported
Pounds:	Not reported
Liters:	Not reported
Ounces:	Not reported
Pints:	Not reported
Quarts:	Not reported
Sheen:	Not reported
Tons:	Not reported
Unknown:	Not reported
Evacuations:	Not reported
Number of Injuries:	Not reported
Number of Fatalities:	Not reported
Description:	RP states that a release of crude oil from the top of a tank car due to unknown circumstances. HazMat manager is enroute to scene. Flow of crude oil has been contained. Tank car ID: CTCX734728.
OES Incident Number:	'12-0447
OES notification:	01/23/2012
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported

UNION PACIFIC RAILROAD CO (Continued) **S105640256**

Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	No
Waterway:	Not reported
Spill Site:	Rail Road
Cleanup By:	Reporting Party
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	N/A
Other:	Not reported
Date/Time:	2340
Year:	2012
Agency:	UPRR
Incident Date:	1/22/2012
Admin Agency:	San Bernardino County Health Department
Amount:	Not reported
Contained:	Yes
Site Type:	Not reported
E Date:	Not reported
Substance:	Derailment
Quantity Released:	1
BBLS:	Not reported
Cups:	Not reported
CUFT:	Not reported
Gallons:	Not reported
Grams:	Not reported
Pounds:	Not reported
Liters:	Not reported
Ounces:	Not reported
Pints:	Not reported
Quarts:	Not reported
Sheen:	Not reported
Tons:	Not reported
Unknown:	Not reported
Evacuations:	Not reported
Number of Injuries:	Not reported
Number of Fatalities:	Not reported
Description:	RP states that the manager of rail yard reported that a flat car: Car ID TTYX353194 derailed upright with one wheel on the ground. Personnel on scene will re-rail car.
OES Incident Number:	'12-2185
OES notification:	04/13/2012
OES Date:	Not reported

UNION PACIFIC RAILROAD CO (Continued) **S105640256**

OES Time:	Not reported
Incident Date:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	No
Waterway:	Not reported
Spill Site:	Rail Road
Cleanup By:	Contractor
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Gal(s)
Other:	Not reported
Date/Time:	802
Year:	2012
Agency:	UPRR
Incident Date:	4/13/2012
Admin Agency:	San Bernardino County Health Department
Amount:	Not reported
Contained:	Yes
Site Type:	Not reported
E Date:	Not reported
Substance:	Transmission Fluid
Quantity Released:	5
BBLS:	Not reported
Cups:	Not reported
CUFT:	Not reported

UNION PACIFIC RAILROAD CO (Continued) **S105640256**

Gallons:	Not reported
Grams:	Not reported
Pounds:	Not reported
Liters:	Not reported
Ounces:	Not reported
Pints:	Not reported
Quarts:	Not reported
Sheen:	Not reported
Tons:	Not reported
Unknown:	Not reported
Evacuations:	Not reported
Number of Injuries:	Not reported
Number of Fatalities:	Not reported
Description:	Caller states a contractor welder truck released five gallons of transmission fluid to ground due to unknown causes.

San Bern. Co. Permit:

Region:	SAN BERNARDINO
Facility ID:	FA0006899
Owner:	UNION PACIFIC RAILROAD
Permit Number:	PT0001676
Permit Category:	HAZARDOUS WASTE GENERATOR - 51-100 EMPLOYEES
Facility Status:	ACTIVE
Expiration Date:	09/30/2013

Region:	SAN BERNARDINO
Facility ID:	FA0006899
Owner:	UNION PACIFIC RAILROAD
Permit Number:	PT0001675
Permit Category:	HAZMAT HANDLER 51-100 EMPLOYEES (W/GEN PRMT)
Facility Status:	ACTIVE
Expiration Date:	09/30/2013

Region:	SAN BERNARDINO
Facility ID:	FA0006899
Owner:	UNION PACIFIC RAILROAD
Permit Number:	PT0020793
Permit Category:	APSA 100,001-1,000,000 GAL FAC CAPACITY
Facility Status:	ACTIVE
Expiration Date:	09/30/2012

ENVIROSTOR:

Site Type:	Evaluation
Site Type Detailed:	Evaluation
Acres:	0.01
NPL:	NO
Regulatory Agencies:	NONE SPECIFIED
Lead Agency:	NONE SPECIFIED
Program Manager:	Not reported
Supervisor:	* Greg Holmes
Division Branch:	Cleanup Cypress
Facility ID:	36370027
Site Code:	540014
Assembly:	47
Senate:	20
Special Program:	EPA - PASI

UNION PACIFIC RAILROAD CO (Continued) **S105640256**

Status: No Further Action
Status Date: 04/14/1995
Restricted Use: NO
Site Mgmt. Req.: NONE SPECIFIED
Funding: EPA Grant
Latitude: 34.06305
Longitude: -117.3933
APN: NONE SPECIFIED
Past Use: RAIL ROAD MAINTENANCE SHOP
Potential COC: 30024, 30025, 3002502
Confirmed COC: 30024-NO,30025-NO,3002502-NO
Potential Description: SOIL
Alias Name: CAD000627950
Alias Type: EPA Identification Number
Alias Name: 110018981592
Alias Type: EPA (FRS #)
Alias Name: 540014
Alias Type: Project Code (Site Code)
Alias Name: 36370027
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Assessment Report
Completed Date: 04/01/1985
Comments: T/C W/ W.KEENEY,SO PACIFIC,714-877-4371, 6/28/84-1)SOURCE ACT: CLEAN DIRT,OIL,& GREASE FROM LOCOMOTIVES. 2)YR OF OPER: 1972-PRESENT SUBMIT TO EPA PRELIM ASSESS DONE CERCLA 104

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Discovery
Completed Date: 10/12/1983
Comments: FACILITY IDENTIFIED ID FROM ERRIS

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Discovery
Completed Date: 04/18/1983
Comments: FACILITY IDENTIFIED ID FROM EPA GEN.LIST

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

496
ENE
> 1
1.289 mi.
6805 ft.

CRANE COMPANY
330 WEST CITRUS STREET
COLTON, CA 92324

ENVIROSTOR **S108200725**
N/A

Relative:
Lower

Actual:
1052 ft.

ENVIROSTOR:

Site Type:	Evaluation
Site Type Detailed:	Evaluation
Acres:	0
NPL:	NO
Regulatory Agencies:	US EPA
Lead Agency:	US EPA
Program Manager:	Rania Zabaneh
Supervisor:	Douglas Bautista
Division Branch:	Cleanup Cypress
Facility ID:	36360025
Site Code:	400974
Assembly:	47
Senate:	20
Special Program:	EPA - PASI
Status:	Refer: RWQCB
Status Date:	06/01/1995
Restricted Use:	NO
Site Mgmt. Req.:	NONE SPECIFIED
Funding:	EPA Grant
Latitude:	34.08333
Longitude:	-117.3263
APN:	NONE SPECIFIED
Past Use:	NONE SPECIFIED
Potential COC:	10002, 10099, 10193, 10195, 10197, 20011, 30153, 30542
Confirmed COC:	NONE SPECIFIED
Potential Description:	NONE SPECIFIED
Alias Name:	COLTON MANUFACTURING
Alias Type:	Alternate Name
Alias Name:	COLTON-WARTSILA (SUB OF O.Y. WARTSILA)
Alias Type:	Alternate Name
Alias Name:	CAD066135690
Alias Type:	EPA Identification Number
Alias Name:	L10002088354
Alias Type:	GeoTracker Global ID
Alias Name:	CAD066135690
Alias Type:	HWTS Identification Code
Alias Name:	400974
Alias Type:	Project Code (Site Code)
Alias Name:	36360025
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Site Screening
Completed Date:	09/26/1988
Comments:	A Preliminary Assessment prepared by EPA recommending Screen ing Site Inspection was received and reviewed by Region 4 staff.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	* Discovery
Completed Date:	02/04/1983

CRANE COMPANY (Continued) **S108200725**

Comments: FACILITY IDENTIFIED ID VIA RWQCB INACTIVE FILES CO. DID STEEL GLAZING AND PICKLING 5 MGD TO EVAPORATION PONDS

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

BM497 **EDISON/COLTON 2 (10TH ST) MGP** **DEED S101481942**
ESE **EAST OF 10TH STREET, SOUTH OF L STREET** **VCP N/A**
> 1 **COLTON, CA 92324** **ENVIROSTOR**
1.334 mi.
7044 ft. **Site 1 of 2 in cluster BM**

Relative:
Lower

Actual:
966 ft.

DEED:
Area: PROJECT WIDE
Sub Area: Not reported
Site Type: VOLUNTARY CLEANUP
Status: CERTIFIED / OPERATION & MAINTENANCE
Deed Date(s): 05/02/2005

VCP:
Facility ID: 36490108
Site Type: Voluntary Cleanup
Site Type Detail: Voluntary Cleanup
Site Mgmt. Req.: FOUN, COV
Acres: 2.5
National Priorities List: NO
Cleanup Oversight Agencies: SMBRP
Lead Agency: SMBRP
Lead Agency Description: DTSC - Site Cleanup Program
Project Manager: Lori Parnass
Supervisor: Juli Propes
Division Branch: Cleanup Chatsworth
Site Code: 400296
Assembly: 47
Senate: 20
Special Programs Code: Voluntary Cleanup Program
Status: Certified / Operation & Maintenance
Status Date: 06/16/2005
Restricted Use: YES
Funding: Responsible Party
Lat/Long: 34.0625 / -117.3208
APN: 163-041-0318
Past Use: MANUFACTURED GAS PLANT
Potential COC: 10009, 30019
Confirmed COC: 30019
Potential Description: SOIL
Alias Name: EDISON/COLTON
Alias Type: Alternate Name
Alias Name: TOWN GAS PLANT COLTON NUMBER 2
Alias Type: Alternate Name

EDISON/COLTON 2 (10TH ST) MGP (Continued) **S101481942**

Alias Name: 163-041-0318
Alias Type: APN
Alias Name: 110033618798
Alias Type: EPA (FRS #)
Alias Name: 400296
Alias Type: Project Code (Site Code)
Alias Name: 36490108
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Completion Report
Completed Date: 08/28/2002
Comments: DTSC approved "Soil Remediation Report" dated August 7, 2002. DTSC conducted oversight for site characterization and removal activity for this two acre property. Approximately 2000 tons of PAH-impacted soil was removed.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Workplan
Completed Date: 10/19/1999
Comments: Removal Action Workplan is approved. PAH contaminated soil will be removed to background study number, 0.9 mg/kg.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Report
Completed Date: 02/26/1999
Comments: The Final Supplemental PEA report, prepared by Fluor Daniel, was approved on February 26, 1999. DTSC concluded that elevated levels of polycyclic hydrocarbons and lead exist in the soil at the subject site and require further action. Removal action workplan is required. Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Report
Completed Date: 01/27/1995
Comments: PEA complete. Further investigation required.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Screening
Completed Date: 06/06/1991
Comments: No information available for Southern CA Edison site. Recommend future follow-up.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Certification
Completed Date: 06/16/2005
Comments: A Remedial Action Certification was finalized on June 6,2005 for the new MGP Site at 160 South Tenth Street in the City of Colton. Approximately 2000 tons of polycyclic aromatic hydrocarbon and lead contaminated soil was removed from the property. The clean up goal for lead in soil was 97.1 mg/kg. The cleanup goal was met. The

EDISON/COLTON 2 (10TH ST) MGP (Continued) **S101481942**

cleanup goal for PAHs was established as B (a) P equivalent of upper confidence level of 0.9 mg/kg. The cleanup goal for PAHs was not met at four inaccessible areas. A deed restriction is in place for the specified inaccessible areas.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction
Completed Date: 05/02/2005
Comments: A deed restriction was filed on May 2, 2005 for four inaccessible parcels located on the former MGP site at 160 South Tenth Street in the City of Colton. An Operation and Maintenance agreement requires the owners, the City of Colton to conduct annual investigations of the parcels and submit a report of findings to DTSC.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 04/26/2008
Comments: site in compliance with LUC

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 06/28/2011
Comments: in compliance

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operation & Maintenance Order/Agreement
Completed Date: 06/16/2005
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Voluntary Cleanup Agreement
Completed Date: 12/21/1998
Comments: Transition to Chapter 6.5 - Amendment to the existing Voluntary Cleanup Agreement No. HSA 98/99-001, signed by the RP.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Voluntary Cleanup Agreement
Completed Date: 07/10/2001
Comments: A Voluntary Cleanup Agreement was signed for RAW.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: CEQA - Notice of Exemption
Completed Date: 10/19/1999
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Voluntary Cleanup Agreement
Completed Date: 08/04/1998
Comments: Edison and DTSC entered into a second Voluntary Cleanup Agreement for

EDISON/COLTON 2 (10TH ST) MGP (Continued) **S101481942**

the site - conduct a supplement to the Preliminary Endangerment Assessment, to determine whether further action is required.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Voluntary Cleanup Agreement
Completed Date: 05/10/1994
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 08/25/2012
Comments: Not reported

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

ENVIROSTOR:
Site Type: Voluntary Cleanup
Site Type Detailed: Voluntary Cleanup
Acres: 2.5
NPL: NO
Regulatory Agencies: SMBRP
Lead Agency: SMBRP
Program Manager: Lori Parnass
Supervisor: Juli Propes
Division Branch: Cleanup Chatsworth
Facility ID: 36490108
Site Code: 400296
Assembly: 47
Senate: 20
Special Program: Voluntary Cleanup Program
Status: Certified / Operation & Maintenance
Status Date: 06/16/2005
Restricted Use: YES
Site Mgmt. Req.: FOUN, COV
Funding: Responsible Party
Latitude: 34.0625
Longitude: -117.3208
APN: 163-041-0318
Past Use: MANUFACTURED GAS PLANT
Potential COC: 10009, 30019
Confirmed COC: 30019
Potential Description: SOIL
Alias Name: EDISON/COLTON
Alias Type: Alternate Name
Alias Name: TOWN GAS PLANT COLTON NUMBER 2
Alias Type: Alternate Name
Alias Name: 163-041-0318

EDISON/COLTON 2 (10TH ST) MGP (Continued) **S101481942**

Alias Type: APN
Alias Name: 110033618798
Alias Type: EPA (FRS #)
Alias Name: 400296
Alias Type: Project Code (Site Code)
Alias Name: 36490108
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Completion Report
Completed Date: 08/28/2002
Comments: DTSC approved "Soil Remediation Report" dated August 7, 2002. DTSC conducted oversight for site characterization and removal activity for this two acre property. Approximately 2000 tons of PAH-impacted soil was removed.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Workplan
Completed Date: 10/19/1999
Comments: Removal Action Workplan is approved. PAH contaminated soil will be removed to background study number, 0.9 mg/kg.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Report
Completed Date: 02/26/1999
Comments: The Final Supplemental PEA report, prepared by Fluor Daniel, was approved on February 26, 1999. DTSC concluded that elevated levels of polycyclic hydrocarbons and lead exist in the soil at the subject site and require further action. Removal action workplan is required. Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Report
Completed Date: 01/27/1995
Comments: PEA complete. Further investigation required.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Screening
Completed Date: 06/06/1991
Comments: No information available for Southern CA Edison site. Recommend future follow-up.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Certification
Completed Date: 06/16/2005
Comments: A Remedial Action Certification was finalized on June 6,2005 for the new MGP Site at 160 South Tenth Street in the City of Colton. Approximately 2000 tons of polycyclic aromatic hydrocarbon and lead contaminated soil was removed from the property. The clean up goal for lead in soil was 97.1 mg/kg. The cleanup goal was met. The cleanup goal for PAHs was established as B (a) P equivalent of upper

EDISON/COLTON 2 (10TH ST) MGP (Continued) **S101481942**

confidence level of 0.9 mg/kg. The cleanup goal for PAHs was not met at four inaccessible areas. A deed restriction is in place for the specified inaccessible areas.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction
Completed Date: 05/02/2005
Comments: A deed restriction was filed on May 2, 2005 for four inaccessible parcels located on the former MGP site at 160 South Tenth Street in the City of Colton. An Operation and Maintenance agreement requires the owners, the City of Colton to conduct annual investigations of the parcels and submit a report of findings to DTSC.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 04/26/2008
Comments: site in compliance with LUC

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 06/28/2011
Comments: in compliance

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operation & Maintenance Order/Agreement
Completed Date: 06/16/2005
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Voluntary Cleanup Agreement
Completed Date: 12/21/1998
Comments: Transition to Chapter 6.5 - Amendment to the existing Voluntary Cleanup Agreement No. HSA 98/99-001, signed by the RP.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Voluntary Cleanup Agreement
Completed Date: 07/10/2001
Comments: A Voluntary Cleanup Agreement was signed for RAW.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: CEQA - Notice of Exemption
Completed Date: 10/19/1999
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Voluntary Cleanup Agreement
Completed Date: 08/04/1998
Comments: Edison and DTSC entered into a second Voluntary Cleanup Agreement for the site - conduct a supplement to the Preliminary Endangerment

EDISON/COLTON 2 (10TH ST) MGP (Continued) **S101481942**

Assessment, to determine whether further action is required.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Voluntary Cleanup Agreement
Completed Date: 05/10/1994
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 08/25/2012
Comments: Not reported

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

BM498 **EDISON/COLTON 2 (10TH ST) MGP** **EDR MGP** **1008407664**
ESE **EAST OF 10TH STREET, SOUTH OF L STREET** **N/A**
> 1 **COLTON, CA 92324**
1.389 mi.
7335 ft. **Site 2 of 2 in cluster BM**

Relative: **Lower**

Actual: **965 ft.**

Manufactured Gas Plants:
Alternate Name:COLTON GAS CO PLANT. This site was formerly used as a manufactured gas plant, and is contaminated with the associated chemicals; polycyclic aromatic hydrocarbons (PAHs) and metals. The site has an asphalt cap and is currently in use as part of the City of Colton Maintennance Yard.

---

499 **SO CAL GAS/COLTON** **EDR MGP** **1008407665**
SE **NEC OF 6TH STREET AND FOGG STREET** **N/A**
> 1 **COLTON, CA 92324**
1.419 mi.
7490 ft.

Relative: **Lower**

Actual: **920 ft.**

Manufactured Gas Plants:
Alternate Name:COLTON 1 (FOGG ST) MGP. No additional information available

500 ENE > 1 1.495 mi. 7896 ft. **SOLVEX INC**
1475 MILLER DR
COLTON, CA 92324

HIST CORTESE ENVIROSTOR **1000432088 N/A**

Relative: Lower

Actual: 1044 ft.

CORTESE:
Region: CORTESE
Facility County Code: 36
Reg By: CALSI
Reg Id: 36280086

ENVIROSTOR:
Site Type: Historical
Site Type Detailed: * Historical
Acres: Not reported
NPL: NO
Regulatory Agencies: NONE SPECIFIED
Lead Agency: NONE SPECIFIED
Program Manager: Not reported
Supervisor: * Mmonroy
Division Branch: Cleanup Cypress
Facility ID: 36280086
Site Code: Not reported
Assembly: 47
Senate: 20
Special Program: * CERC2
Status: No Further Action
Status Date: 05/16/1995
Restricted Use: NO
Site Mgmt. Req.: NONE SPECIFIED
Funding: Not reported
Latitude: 34.08444
Longitude: -117.3208
APN: NONE SPECIFIED
Past Use: NONE
Potential COC: NONE SPECIFIED,31000
Confirmed COC: 31000-NO
Potential Description: NMA
Alias Name: 36280086
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Screening
Completed Date: 10/27/1994
Comments: DATABASE VALIDATION PROGRAM CONFIRMS NFA FOR DTSC.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Assessment Report
Completed Date: 03/31/1989
Comments: GROUND PHOTOS PHOTOGRAPHS OF FACILITY WITH EMPTY DRUMS ON-SITE; BELIEVED TO HAVE CONTAIN- ED HONEY PRELIM ASSESS DONE SOLVEX, INC WAS A BEESWAX EXTRACTION OPERATION WHICH OPERATED SEASONALLY. THE EXTRACTION PROCESS WAS A CLOSED SYSTEM WHICH REQUIRED THE DISTILLATION OF A HEXANE-BEESWAX SOLUTION. THE HEXANE WAS RECYCLED AND STORED FOR USE ON THE NEXT BATCH OF BEESWAX. ONLY 2-3% OF THE

SOLVEX INC (Continued) **1000432088**

HEXANE REMAINED IN THE BEESWAX.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Screening
Completed Date: 03/20/1987
Comments: SITE SCREENING DONE FURTHER RECORD SEARCH NEEDED.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Discovery
Completed Date: 02/09/1983
Comments: FACILITY IDENTIFIED PHONE DIRECTORY (1969) CHEM MFG

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

Count: 43 records.

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
RIALTO	S107540006		ON PEPPER AVENUE, 100 YARDS NO	92376	CDL
	S107540087		ON STATE HIGHWAY 173, ~2 MILES		CDL
	S107540506		ROAD INO9, 3/2 MI E OF HWY 330		CDL
REDLANDS	S107592131	REDLANDS PROPERTY/ORANGE GROVE	SE CALIFORNIA & PIONEERTO NEVA	92410	PERMITS SAN BERNARDINO
BLOOMINGTON	S108419379	MARCO AUTO REPAIR	17770 VALLEY BLVD A	92316	PERMITS SAN BERNARDINO
BLOOMINGTON	S109254312	IMPORT & DOMESTIC CONVERT	17781 VALLEY BLVD J	92316	PERMITS SAN BERNARDINO
SAN BERNARDINO	S110655011	CALTRANS PANARAMA PT.MAINT.ST.	HWY 18, MILEPOST 15.84	92410	LUST
COLTON	S111291337	COLTON CROSSING GRADE SEPARATION	SOUTH OF I10 BTWN MT VERNON AV	92324	NPDES
RIALTO	S111413514	ELITE ROAD SERVICE & TIRE, INC.	993 W VALLEY BLVD STE 510	CA923	HAULERS
SAN BERNARDINO	S112274060	FOREST RIVER, INC-PLANT #19	255 S PEPPER AVE	92410	PERMITS SAN BERNARDINO
COLTON	S112855442	B & D SPECIALTY	2048 VALLEY BLVD	92376	HAZNET
HIGHLAND	S112865494	INTOWN PROPERTIES, INC/HUD	26978 CYPRESS AVE	92410	HAZNET
COLTON	S112884926	HUD INTOWN PROPERTIES	710 VALLEY BLVD W & 712	92324	HAZNET
RIALTO	S112889100	EDCO DISPOSAL	210 E CAMERON WAY	92376	HAZNET
COLTON	S112889256	CHAROLETTE GUYAUX	105 1/2 CYPRESS AVE	92324	HAZNET
COLTON	S112902216	E YEARA TRUCKING	I 215 OFF RAMP LA CADENA DR	92324	HAZNET
RIALTO	S112924416	ROADWAY EXPRESS	INTERSECTION OF VALLEY BLVD	92316	HAZNET
COLTON	S112930688	J.B. HUNT TRANSPORT SERVICES INC	SAN BERNADINO & PEPPER AVE	92324	HAZNET
COLTON	S112932514	CALTRANS DIST 8/CONSTR EA 08-45760	I 10 RTE 215 CONNECTOR	92324	HAZNET
BLOOMINGTON	S112941368	UNION PACIFIC RAILROAD	300 S PEPPER AVE	92324	HAZNET
RIALTO	S112957711	THE WALTON CONSTRUCTION	NW CORNER OF N PEPPER AVE	92376	HAZNET
BLOOMINGTON	S112994236	TYSON FRESH MEATS INC	19544 E SLOVER AVE	92316	HAZNET
RIALTO	S112998760	CONOCO PHILLIPS COLTON TERMINAL-EA	271 E SLOVER AVE	92376	HAZNET
RIALTO	S113003296	1X RIALTO UNIFIED SCHOOL DISTRICT(	1442 N EUCALYPTUS AVE	92376	HAZNET
COLTON	S113010044	CIRCLE K STORES INC.#627	990 VALLEY BLVD	92324	HAZNET
RIALTO	S113014650	RIALTO USD/FRISBIE MIDDLE SCHOOL	1442 N EUCALYPTUS AVE	92376	HAZNET
RIALTO	S113036696	BESTFOODS BAKING COMPANY	2036 W VALLEY BLVD	92376	HAZNET
SAN BERNARDINO	S113040600	UNOCAL SERVICE STATION #5961	I-15/HWY 138	92410	HAZNET
BLOOMINGTON	S113061418	PALOMERA'S AUTO BODY SHOP	17866 3A VALLEY BLVD	92316	HAZNET
COLTON	S113069095	SHELL	1600 W VALLEY BLVD/PEPPER	92324	HAZNET
COLTON	S113069988	COLTON BISHOP STORE HOUSE	791 NORTH_PEPPER AVENUE	92324	HAZNET
SAN BERNARDINO	S113088721	CIRCLE K STORES INC STATION #5700	I-5/HWY 138	92410	HAZNET
COLTON	S113102654	COLTON VALLEY DENTAL	552 VALLEY BLVD	92324	HAZNET
RIALTO	S113113555	PICK YOUR PART	2084 VALLEY BLVD	92376	HAZNET
RIALTO	S113121290	BIMBO BAKERIES USA INC	2036 W VALLEY BLVD	92376	HAZNET
BLOOMINGTON	S113126377	JG COLLISION CENTER	17763 VALLEY BLVD BLDG C	92316	HAZNET
RIALTO	S113155156	BISCOMERICA CORP	565 W SLOVER AVE	92376	HAZNET
COLTON	S113170421	CALTRANS	STATE RTE 10 AT MT VERNON OVER	92324	HAZNET
COLTON	S113170443	CALTRANS DIST 8	STATE RTE 10 AT 215 COLTON LOM	92324	HAZNET
RIALTO	S113177027	CONOCO PHILLIPS COLTON TERMINAL EA	271 E SLOVER AVE	92376	HAZNET
RIALTO	S113182830	LAURENCE MCGUIRE	838 W VALLEY BLVD	92376	HAZNET
COLTON	S113182861	HENRY RAY CARTER	762 1/2 W VALLEY BLVD	92324	HAZNET
RIALTO	S113450206	I 10 RIVERSIDE AVE LANDSCAPE PROJE	INTERSTATE 10 AND RIVERSIDE AV	92410	NPDES

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 02/01/2013
Date Data Arrived at EDR: 03/01/2013
Date Made Active in Reports: 03/13/2013
Number of Days to Update: 12

Source: EPA
Telephone: N/A
Last EDR Contact: 05/09/2013
Next Scheduled EDR Contact: 07/22/2013
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 3
Telephone 215-814-5418

EPA Region 4
Telephone 404-562-8033

EPA Region 5
Telephone 312-886-6686

EPA Region 6
Telephone: 214-655-6659

EPA Region 7
Telephone: 913-551-7247

EPA Region 8
Telephone: 303-312-6774

EPA Region 9
Telephone: 415-947-4246

EPA Region 10
Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 02/01/2013
Date Data Arrived at EDR: 03/01/2013
Date Made Active in Reports: 03/13/2013
Number of Days to Update: 12

Source: EPA
Telephone: N/A
Last EDR Contact: 05/09/2013
Next Scheduled EDR Contact: 07/22/2013
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Federal Delisted NPL site list

DELISTED NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 02/01/2013
Date Data Arrived at EDR: 03/01/2013
Date Made Active in Reports: 03/13/2013
Number of Days to Update: 12

Source: EPA
Telephone: N/A
Last EDR Contact: 05/09/2013
Next Scheduled EDR Contact: 07/22/2013
Data Release Frequency: Quarterly

Federal CERCLIS list

CERCLIS: Comprehensive Environmental Response, Compensation, and Liability Information System

CERCLIS contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). CERCLIS contains sites which are either proposed to or on the National Priorities List (NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 02/04/2013
Date Data Arrived at EDR: 03/01/2013
Date Made Active in Reports: 03/13/2013
Number of Days to Update: 12

Source: EPA
Telephone: 703-412-9810
Last EDR Contact: 05/29/2013
Next Scheduled EDR Contact: 09/09/2013
Data Release Frequency: Quarterly

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 07/31/2012
Date Data Arrived at EDR: 10/09/2012
Date Made Active in Reports: 12/20/2012
Number of Days to Update: 72

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 04/10/2013
Next Scheduled EDR Contact: 07/22/2013
Data Release Frequency: Varies

Federal CERCLIS NFRAP site List

CERCLIS-NFRAP: CERCLIS No Further Remedial Action Planned

Archived sites are sites that have been removed and archived from the inventory of CERCLIS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

Date of Government Version: 02/05/2013
Date Data Arrived at EDR: 03/01/2013
Date Made Active in Reports: 03/13/2013
Number of Days to Update: 12

Source: EPA
Telephone: 703-412-9810
Last EDR Contact: 05/29/2013
Next Scheduled EDR Contact: 05/09/2013
Data Release Frequency: Quarterly

Federal RCRA CORRACTS facilities list

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 02/12/2013
Date Data Arrived at EDR: 02/21/2013
Date Made Active in Reports: 02/27/2013
Number of Days to Update: 6

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 05/02/2013
Next Scheduled EDR Contact: 07/15/2013
Data Release Frequency: Quarterly

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 02/12/2013
Date Data Arrived at EDR: 02/15/2013
Date Made Active in Reports: 02/27/2013
Number of Days to Update: 12

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 05/02/2013
Next Scheduled EDR Contact: 07/15/2013
Data Release Frequency: Quarterly

Federal RCRA generators list

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 02/12/2013
Date Data Arrived at EDR: 02/15/2013
Date Made Active in Reports: 02/27/2013
Number of Days to Update: 12

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 05/02/2013
Next Scheduled EDR Contact: 07/15/2013
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 02/12/2013
Date Data Arrived at EDR: 02/15/2013
Date Made Active in Reports: 02/27/2013
Number of Days to Update: 12

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 05/02/2013
Next Scheduled EDR Contact: 07/15/2013
Data Release Frequency: Quarterly

RCRA-CESQG: RCRA - Conditionally Exempt Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 02/12/2013
Date Data Arrived at EDR: 02/15/2013
Date Made Active in Reports: 02/27/2013
Number of Days to Update: 12

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 05/02/2013
Next Scheduled EDR Contact: 07/15/2013
Data Release Frequency: Varies

Federal institutional controls / engineering controls registries

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 03/14/2013
Date Data Arrived at EDR: 03/29/2013
Date Made Active in Reports: 05/10/2013
Number of Days to Update: 42

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 06/10/2013
Next Scheduled EDR Contact: 09/23/2013
Data Release Frequency: Varies

US INST CONTROL: Sites with Institutional Controls

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 03/14/2013
Date Data Arrived at EDR: 03/29/2013
Date Made Active in Reports: 05/10/2013
Number of Days to Update: 42

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 06/10/2013
Next Scheduled EDR Contact: 09/23/2013
Data Release Frequency: Varies

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 12/09/2005
Date Data Arrived at EDR: 12/11/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 31

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 05/20/2013
Next Scheduled EDR Contact: 09/02/2013
Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 12/31/2012
Date Data Arrived at EDR: 01/17/2013
Date Made Active in Reports: 02/15/2013
Number of Days to Update: 29

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 04/02/2013
Next Scheduled EDR Contact: 07/15/2013
Data Release Frequency: Annually

State- and tribal - equivalent NPL

RESPONSE: State Response Sites

Identifies confirmed release sites where DTSC is involved in remediation, either in a lead or oversight capacity. These confirmed release sites are generally high-priority and high potential risk.

Date of Government Version: 03/13/2013
Date Data Arrived at EDR: 03/14/2013
Date Made Active in Reports: 03/27/2013
Number of Days to Update: 13

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 05/07/2013
Next Scheduled EDR Contact: 08/19/2013
Data Release Frequency: Quarterly

State- and tribal - equivalent CERCLIS

ENVIROSTOR: EnviroStor Database

The Department of Toxic Substances Control's (DTSC's) Site Mitigation and Brownfields Reuse Program's (SMBRP's) EnviroStor database identifes sites that have known contamination or sites for which there may be reasons to investigate further. The database includes the following site types: Federal Superfund sites (National Priorities List (NPL)); State Response, including Military Facilities and State Superfund; Voluntary Cleanup; and School sites. EnviroStor provides similar information to the information that was available in CalSites, and provides additional site information, including, but not limited to, identification of formerly-contaminated properties that have been released for reuse, properties where environmental deed restrictions have been recorded to prevent inappropriate land uses, and risk characterization information that is used to assess potential impacts to public health and the environment at contaminated sites.

Date of Government Version: 03/13/2013
Date Data Arrived at EDR: 03/14/2013
Date Made Active in Reports: 03/27/2013
Number of Days to Update: 13

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 05/07/2013
Next Scheduled EDR Contact: 08/19/2013
Data Release Frequency: Quarterly

State and tribal landfill and/or solid waste disposal site lists

SWF/LF (SWIS): Solid Waste Information System

Active, Closed and Inactive Landfills. SWF/LF records typically contain an inve ntory of solid waste disposal facilities or landfills. These may be active or i nactive facilities or open dumps that failed to meet RCRA Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 02/18/2013
Date Data Arrived at EDR: 02/18/2013
Date Made Active in Reports: 03/20/2013
Number of Days to Update: 30

Source: Department of Resources Recycling and Recovery
Telephone: 916-341-6320
Last EDR Contact: 05/21/2013
Next Scheduled EDR Contact: 09/02/2013
Data Release Frequency: Quarterly

State and tribal leaking storage tank lists

LUST REG 8: Leaking Underground Storage Tanks

California Regional Water Quality Control Board Santa Ana Region (8). For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 02/14/2005
Date Data Arrived at EDR: 02/15/2005
Date Made Active in Reports: 03/28/2005
Number of Days to Update: 41

Source: California Regional Water Quality Control Board Santa Ana Region (8)
Telephone: 909-782-4496
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: Varies

LUST REG 7: Leaking Underground Storage Tank Case Listing

Leaking Underground Storage Tank locations. Imperial, Riverside, San Diego, Santa Barbara counties.

Date of Government Version: 02/26/2004
Date Data Arrived at EDR: 02/26/2004
Date Made Active in Reports: 03/24/2004
Number of Days to Update: 27

Source: California Regional Water Quality Control Board Colorado River Basin Region (7)
Telephone: 760-776-8943
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: No Update Planned

LUST REG 6V: Leaking Underground Storage Tank Case Listing

Leaking Underground Storage Tank locations. Inyo, Kern, Los Angeles, Mono, San Bernardino counties.

Date of Government Version: 06/07/2005
Date Data Arrived at EDR: 06/07/2005
Date Made Active in Reports: 06/29/2005
Number of Days to Update: 22

Source: California Regional Water Quality Control Board Victorville Branch Office (6)
Telephone: 760-241-7365
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: No Update Planned

LUST REG 6L: Leaking Underground Storage Tank Case Listing
For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 09/09/2003
Date Data Arrived at EDR: 09/10/2003
Date Made Active in Reports: 10/07/2003
Number of Days to Update: 27

Source: California Regional Water Quality Control Board Lahontan Region (6)
Telephone: 530-542-5572
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: No Update Planned

LUST REG 5: Leaking Underground Storage Tank Database
Leaking Underground Storage Tank locations. Alameda, Alpine, Amador, Butte, Colusa, Contra Costa, Calveras, El Dorado, Fresno, Glenn, Kern, Kings, Lake, Lassen, Madera, Mariposa, Merced, Modoc, Napa, Nevada, Placer, Plumas, Sacramento, San Joaquin, Shasta, Solano, Stanislaus, Sutter, Tehama, Tulare, Tuolumne, Yolo, Yuba counties.

Date of Government Version: 07/01/2008
Date Data Arrived at EDR: 07/22/2008
Date Made Active in Reports: 07/31/2008
Number of Days to Update: 9

Source: California Regional Water Quality Control Board Central Valley Region (5)
Telephone: 916-464-4834
Last EDR Contact: 07/01/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: No Update Planned

LUST REG 4: Underground Storage Tank Leak List
Los Angeles, Ventura counties. For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 09/07/2004
Date Data Arrived at EDR: 09/07/2004
Date Made Active in Reports: 10/12/2004
Number of Days to Update: 35

Source: California Regional Water Quality Control Board Los Angeles Region (4)
Telephone: 213-576-6710
Last EDR Contact: 09/06/2011
Next Scheduled EDR Contact: 12/19/2011
Data Release Frequency: No Update Planned

LUST REG 3: Leaking Underground Storage Tank Database
Leaking Underground Storage Tank locations. Monterey, San Benito, San Luis Obispo, Santa Barbara, Santa Cruz counties.

Date of Government Version: 05/19/2003
Date Data Arrived at EDR: 05/19/2003
Date Made Active in Reports: 06/02/2003
Number of Days to Update: 14

Source: California Regional Water Quality Control Board Central Coast Region (3)
Telephone: 805-542-4786
Last EDR Contact: 07/18/2011
Next Scheduled EDR Contact: 10/31/2011
Data Release Frequency: No Update Planned

LUST REG 2: Fuel Leak List
Leaking Underground Storage Tank locations. Alameda, Contra Costa, Marin, Napa, San Francisco, San Mateo, Santa Clara, Solano, Sonoma counties.

Date of Government Version: 09/30/2004
Date Data Arrived at EDR: 10/20/2004
Date Made Active in Reports: 11/19/2004
Number of Days to Update: 30

Source: California Regional Water Quality Control Board San Francisco Bay Region (2)
Telephone: 510-622-2433
Last EDR Contact: 09/19/2011
Next Scheduled EDR Contact: 01/02/2012
Data Release Frequency: Quarterly

LUST REG 1: Active Toxic Site Investigation
Del Norte, Humboldt, Lake, Mendocino, Modoc, Siskiyou, Sonoma, Trinity counties. For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 02/01/2001
Date Data Arrived at EDR: 02/28/2001
Date Made Active in Reports: 03/29/2001
Number of Days to Update: 29

Source: California Regional Water Quality Control Board North Coast (1)
Telephone: 707-570-3769
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: No Update Planned

LUST: Geotracker's Leaking Underground Fuel Tank Report

Leaking Underground Storage Tank Incident Reports. LUST records contain an inventory of reported leaking underground storage tank incidents. Not all states maintain these records, and the information stored varies by state. For more information on a particular leaking underground storage tank sites, please contact the appropriate regulatory agency.

Date of Government Version: 03/18/2013
Date Data Arrived at EDR: 03/19/2013
Date Made Active in Reports: 03/27/2013
Number of Days to Update: 8

Source: State Water Resources Control Board
Telephone: see region list
Last EDR Contact: 06/17/2013
Next Scheduled EDR Contact: 09/30/2013
Data Release Frequency: Quarterly

LUST REG 9: Leaking Underground Storage Tank Report

Orange, Riverside, San Diego counties. For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 03/01/2001
Date Data Arrived at EDR: 04/23/2001
Date Made Active in Reports: 05/21/2001
Number of Days to Update: 28

Source: California Regional Water Quality Control Board San Diego Region (9)
Telephone: 858-637-5595
Last EDR Contact: 09/26/2011
Next Scheduled EDR Contact: 01/09/2012
Data Release Frequency: No Update Planned

SLIC: Statewide SLIC Cases

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 03/18/2013
Date Data Arrived at EDR: 03/19/2013
Date Made Active in Reports: 03/27/2013
Number of Days to Update: 8

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 06/17/2013
Next Scheduled EDR Contact: 09/30/2013
Data Release Frequency: Varies

SLIC REG 1: Active Toxic Site Investigations

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 04/03/2003
Date Data Arrived at EDR: 04/07/2003
Date Made Active in Reports: 04/25/2003
Number of Days to Update: 18

Source: California Regional Water Quality Control Board, North Coast Region (1)
Telephone: 707-576-2220
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: No Update Planned

SLIC REG 2: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 09/30/2004
Date Data Arrived at EDR: 10/20/2004
Date Made Active in Reports: 11/19/2004
Number of Days to Update: 30

Source: Regional Water Quality Control Board San Francisco Bay Region (2)
Telephone: 510-286-0457
Last EDR Contact: 09/19/2011
Next Scheduled EDR Contact: 01/02/2012
Data Release Frequency: Quarterly

SLIC REG 3: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 05/18/2006
Date Data Arrived at EDR: 05/18/2006
Date Made Active in Reports: 06/15/2006
Number of Days to Update: 28

Source: California Regional Water Quality Control Board Central Coast Region (3)
Telephone: 805-549-3147
Last EDR Contact: 07/18/2011
Next Scheduled EDR Contact: 10/31/2011
Data Release Frequency: Semi-Annually

SLIC REG 4: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 11/17/2004
Date Data Arrived at EDR: 11/18/2004
Date Made Active in Reports: 01/04/2005
Number of Days to Update: 47

Source: Region Water Quality Control Board Los Angeles Region (4)
Telephone: 213-576-6600
Last EDR Contact: 07/01/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: Varies

SLIC REG 5: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 04/01/2005
Date Data Arrived at EDR: 04/05/2005
Date Made Active in Reports: 04/21/2005
Number of Days to Update: 16

Source: Regional Water Quality Control Board Central Valley Region (5)
Telephone: 916-464-3291
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: Semi-Annually

SLIC REG 6V: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 05/24/2005
Date Data Arrived at EDR: 05/25/2005
Date Made Active in Reports: 06/16/2005
Number of Days to Update: 22

Source: Regional Water Quality Control Board, Victorville Branch
Telephone: 619-241-6583
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: Semi-Annually

SLIC REG 6L: SLIC Sites
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 09/07/2004
Date Data Arrived at EDR: 09/07/2004
Date Made Active in Reports: 10/12/2004
Number of Days to Update: 35

Source: California Regional Water Quality Control Board, Lahontan Region
Telephone: 530-542-5574
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

SLIC REG 7: SLIC List
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 11/24/2004
Date Data Arrived at EDR: 11/29/2004
Date Made Active in Reports: 01/04/2005
Number of Days to Update: 36

Source: California Regional Quality Control Board, Colorado River Basin Region
Telephone: 760-346-7491
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: No Update Planned

SLIC REG 8: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 04/03/2008
Date Data Arrived at EDR: 04/03/2008
Date Made Active in Reports: 04/14/2008
Number of Days to Update: 11

Source: California Region Water Quality Control Board Santa Ana Region (8)
Telephone: 951-782-3298
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: Semi-Annually

SLIC REG 9: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 09/10/2007
Date Data Arrived at EDR: 09/11/2007
Date Made Active in Reports: 09/28/2007
Number of Days to Update: 17

Source: California Regional Water Quality Control Board San Diego Region (9)
Telephone: 858-467-2980
Last EDR Contact: 08/08/2011
Next Scheduled EDR Contact: 11/21/2011
Data Release Frequency: Annually

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 02/05/2013
Date Data Arrived at EDR: 02/06/2013
Date Made Active in Reports: 04/12/2013
Number of Days to Update: 65

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 04/29/2013
Next Scheduled EDR Contact: 08/12/2013
Data Release Frequency: Quarterly

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 09/28/2012
Date Data Arrived at EDR: 11/01/2012
Date Made Active in Reports: 04/12/2013
Number of Days to Update: 162

Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 05/01/2013
Next Scheduled EDR Contact: 08/12/2013
Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 08/27/2012
Date Data Arrived at EDR: 08/28/2012
Date Made Active in Reports: 10/16/2012
Number of Days to Update: 49

Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 04/29/2013
Next Scheduled EDR Contact: 08/12/2013
Data Release Frequency: Quarterly

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 09/12/2011
Date Data Arrived at EDR: 09/13/2011
Date Made Active in Reports: 11/11/2011
Number of Days to Update: 59

Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 04/29/2013
Next Scheduled EDR Contact: 08/12/2013
Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 02/06/2013
Date Data Arrived at EDR: 02/08/2013
Date Made Active in Reports: 04/12/2013
Number of Days to Update: 63

Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 04/29/2013
Next Scheduled EDR Contact: 08/12/2013
Data Release Frequency: Semi-Annually

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 12/31/2012
Date Data Arrived at EDR: 02/28/2013
Date Made Active in Reports: 04/12/2013
Number of Days to Update: 43

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 04/29/2013
Next Scheduled EDR Contact: 08/12/2013
Data Release Frequency: Varies

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 03/01/2013
Date Data Arrived at EDR: 03/01/2013
Date Made Active in Reports: 04/12/2013
Number of Days to Update: 42

Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 04/29/2013
Next Scheduled EDR Contact: 08/12/2013
Data Release Frequency: Quarterly

State and tribal registered storage tank lists

UST: Active UST Facilities
Active UST facilities gathered from the local regulatory agencies

Date of Government Version: 03/18/2013
Date Data Arrived at EDR: 03/19/2013
Date Made Active in Reports: 04/18/2013
Number of Days to Update: 30

Source: SWRCB
Telephone: 916-341-5851
Last EDR Contact: 06/17/2013
Next Scheduled EDR Contact: 09/30/2013
Data Release Frequency: Semi-Annually

AST: Aboveground Petroleum Storage Tank Facilities
Registered Aboveground Storage Tanks.

Date of Government Version: 08/01/2009
Date Data Arrived at EDR: 09/10/2009
Date Made Active in Reports: 10/01/2009
Number of Days to Update: 21

Source: State Water Resources Control Board
Telephone: 916-327-5092
Last EDR Contact: 04/08/2013
Next Scheduled EDR Contact: 07/22/2013
Data Release Frequency: Quarterly

INDIAN UST R10: Underground Storage Tanks on Indian Land
The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 02/05/2013
Date Data Arrived at EDR: 02/06/2013
Date Made Active in Reports: 04/12/2013
Number of Days to Update: 65

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 04/29/2013
Next Scheduled EDR Contact: 08/12/2013
Data Release Frequency: Quarterly

INDIAN UST R9: Underground Storage Tanks on Indian Land
The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 02/21/2013
Date Data Arrived at EDR: 02/26/2013
Date Made Active in Reports: 04/12/2013
Number of Days to Update: 45

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 04/29/2013
Next Scheduled EDR Contact: 08/12/2013
Data Release Frequency: Quarterly

INDIAN UST R8: Underground Storage Tanks on Indian Land
The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 08/27/2012
Date Data Arrived at EDR: 08/28/2012
Date Made Active in Reports: 10/16/2012
Number of Days to Update: 49

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 04/29/2013
Next Scheduled EDR Contact: 08/12/2013
Data Release Frequency: Quarterly

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 12/31/2012
Date Data Arrived at EDR: 02/28/2013
Date Made Active in Reports: 04/12/2013
Number of Days to Update: 43

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 04/29/2013
Next Scheduled EDR Contact: 08/12/2013
Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 05/10/2011
Date Data Arrived at EDR: 05/11/2011
Date Made Active in Reports: 06/14/2011
Number of Days to Update: 34

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 04/29/2013
Next Scheduled EDR Contact: 08/12/2013
Data Release Frequency: Semi-Annually

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 08/02/2012
Date Data Arrived at EDR: 08/03/2012
Date Made Active in Reports: 11/05/2012
Number of Days to Update: 94

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 04/29/2013
Next Scheduled EDR Contact: 08/12/2013
Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 02/06/2013
Date Data Arrived at EDR: 02/08/2013
Date Made Active in Reports: 04/12/2013
Number of Days to Update: 63

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 04/29/2013
Next Scheduled EDR Contact: 08/12/2013
Data Release Frequency: Semi-Annually

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 09/28/2012
Date Data Arrived at EDR: 11/07/2012
Date Made Active in Reports: 04/12/2013
Number of Days to Update: 156

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 04/29/2013
Next Scheduled EDR Contact: 08/12/2013
Data Release Frequency: Varies

FEMA UST: Underground Storage Tank Listing

A listing of all FEMA owned underground storage tanks.

Date of Government Version: 01/01/2010
Date Data Arrived at EDR: 02/16/2010
Date Made Active in Reports: 04/12/2010
Number of Days to Update: 55

Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 04/18/2013
Next Scheduled EDR Contact: 07/29/2013
Data Release Frequency: Varies

State and tribal voluntary cleanup sites

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng
A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27
Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 04/20/2009
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

VCP: Voluntary Cleanup Program Properties
Contains low threat level properties with either confirmed or unconfirmed releases and the project proponents have request that DTSC oversee investigation and/or cleanup activities and have agreed to provide coverage for DTSC's costs.

Date of Government Version: 03/13/2013
Date Data Arrived at EDR: 03/14/2013
Date Made Active in Reports: 03/27/2013
Number of Days to Update: 13
Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 05/07/2013
Next Scheduled EDR Contact: 08/19/2013
Data Release Frequency: Quarterly

INDIAN VCP R1: Voluntary Cleanup Priority Listing
A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 09/28/2012
Date Data Arrived at EDR: 10/02/2012
Date Made Active in Reports: 10/16/2012
Number of Days to Update: 14
Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 04/05/2013
Next Scheduled EDR Contact: 07/15/2013
Data Release Frequency: Varies

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites
Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 12/10/2012
Date Data Arrived at EDR: 12/11/2012
Date Made Active in Reports: 12/20/2012
Number of Days to Update: 9
Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 03/26/2013
Next Scheduled EDR Contact: 07/08/2013
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

ODI: Open Dump Inventory
An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39
Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations
A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137
Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 04/29/2013
Next Scheduled EDR Contact: 08/12/2013
Data Release Frequency: No Update Planned

WMUDS/SWAT: Waste Management Unit Database
Waste Management Unit Database System. WMUDS is used by the State Water Resources Control Board staff and the Regional Water Quality Control Boards for program tracking and inventory of waste management units. WMUDS is composed of the following databases: Facility Information, Scheduled Inspections Information, Waste Management Unit Information, SWAT Program Information, SWAT Report Summary Information, SWAT Report Summary Data, Chapter 15 (formerly Subchapter 15) Information, Chapter 15 Monitoring Parameters, TPCA Program Information, RCRA Program Information, Closure Information, and Interested Parties Information.

Date of Government Version: 04/01/2000
Date Data Arrived at EDR: 04/10/2000
Date Made Active in Reports: 05/10/2000
Number of Days to Update: 30
Source: State Water Resources Control Board
Telephone: 916-227-4448
Last EDR Contact: 05/10/2013
Next Scheduled EDR Contact: 08/26/2013
Data Release Frequency: No Update Planned

SWRCY: Recycler Database
A listing of recycling facilities in California.

Date of Government Version: 03/18/2013
Date Data Arrived at EDR: 03/19/2013
Date Made Active in Reports: 03/27/2013
Number of Days to Update: 8
Source: Department of Conservation
Telephone: 916-323-3836
Last EDR Contact: 06/17/2013
Next Scheduled EDR Contact: 09/30/2013
Data Release Frequency: Quarterly

HAULERS: Registered Waste Tire Haulers Listing
A listing of registered waste tire haulers.

Date of Government Version: 04/26/2013
Date Data Arrived at EDR: 04/26/2013
Date Made Active in Reports: 05/16/2013
Number of Days to Update: 20
Source: Integrated Waste Management Board
Telephone: 916-341-6422
Last EDR Contact: 06/10/2013
Next Scheduled EDR Contact: 09/02/2013
Data Release Frequency: Varies

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands
Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52
Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 05/03/2013
Next Scheduled EDR Contact: 08/19/2013
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US CDL: Clandestine Drug Labs
A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 03/04/2013
Date Data Arrived at EDR: 03/12/2013
Date Made Active in Reports: 05/10/2013
Number of Days to Update: 59

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 06/03/2013
Next Scheduled EDR Contact: 09/16/2013
Data Release Frequency: Quarterly

HIST CAL-SITES: Calsites Database

The Calsites database contains potential or confirmed hazardous substance release properties. In 1996, California EPA reevaluated and significantly reduced the number of sites in the Calsites database. No longer updated by the state agency. It has been replaced by ENVIROSTOR.

Date of Government Version: 08/08/2005
Date Data Arrived at EDR: 08/03/2006
Date Made Active in Reports: 08/24/2006
Number of Days to Update: 21

Source: Department of Toxic Substance Control
Telephone: 916-323-3400
Last EDR Contact: 02/23/2009
Next Scheduled EDR Contact: 05/25/2009
Data Release Frequency: No Update Planned

SCH: School Property Evaluation Program

This category contains proposed and existing school sites that are being evaluated by DTSC for possible hazardous materials contamination. In some cases, these properties may be listed in the CalSites category depending on the level of threat to public health and safety or the environment they pose.

Date of Government Version: 03/13/2013
Date Data Arrived at EDR: 03/14/2013
Date Made Active in Reports: 03/27/2013
Number of Days to Update: 13

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 05/07/2013
Next Scheduled EDR Contact: 08/19/2013
Data Release Frequency: Quarterly

TOXIC PITS: Toxic Pits Cleanup Act Sites

Toxic PITS Cleanup Act Sites. TOXIC PITS identifies sites suspected of containing hazardous substances where cleanup has not yet been completed.

Date of Government Version: 07/01/1995
Date Data Arrived at EDR: 08/30/1995
Date Made Active in Reports: 09/26/1995
Number of Days to Update: 27

Source: State Water Resources Control Board
Telephone: 916-227-4364
Last EDR Contact: 01/26/2009
Next Scheduled EDR Contact: 04/27/2009
Data Release Frequency: No Update Planned

CDL: Clandestine Drug Labs

A listing of drug lab locations. Listing of a location in this database does not indicate that any illegal drug lab materials were or were not present there, and does not constitute a determination that the location either requires or does not require additional cleanup work.

Date of Government Version: 12/31/2012
Date Data Arrived at EDR: 04/03/2013
Date Made Active in Reports: 05/14/2013
Number of Days to Update: 41

Source: Department of Toxic Substances Control
Telephone: 916-255-6504
Last EDR Contact: 04/01/2013
Next Scheduled EDR Contact: 07/15/2013
Data Release Frequency: Varies

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 09/01/2007
Date Data Arrived at EDR: 11/19/2008
Date Made Active in Reports: 03/30/2009
Number of Days to Update: 131

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 03/23/2009
Next Scheduled EDR Contact: 06/22/2009
Data Release Frequency: No Update Planned

Local Lists of Registered Storage Tanks

CA FID UST: Facility Inventory Database

The Facility Inventory Database (FID) contains a historical listing of active and inactive underground storage tank locations from the State Water Resource Control Board. Refer to local/county source for current data.

Date of Government Version: 10/31/1994
Date Data Arrived at EDR: 09/05/1995
Date Made Active in Reports: 09/29/1995
Number of Days to Update: 24

Source: California Environmental Protection Agency
Telephone: 916-341-5851
Last EDR Contact: 12/28/1998
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

UST MENDOCINO: Mendocino County UST Database

A listing of underground storage tank locations in Mendocino County.

Date of Government Version: 09/23/2009
Date Data Arrived at EDR: 09/23/2009
Date Made Active in Reports: 10/01/2009
Number of Days to Update: 8

Source: Department of Public Health
Telephone: 707-463-4466
Last EDR Contact: 06/03/2013
Next Scheduled EDR Contact: 09/16/2013
Data Release Frequency: Annually

HIST UST: Hazardous Substance Storage Container Database

The Hazardous Substance Storage Container Database is a historical listing of UST sites. Refer to local/county source for current data.

Date of Government Version: 10/15/1990
Date Data Arrived at EDR: 01/25/1991
Date Made Active in Reports: 02/12/1991
Number of Days to Update: 18

Source: State Water Resources Control Board
Telephone: 916-341-5851
Last EDR Contact: 07/26/2001
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SWEEPS UST: SWEEPS UST Listing

Statewide Environmental Evaluation and Planning System. This underground storage tank listing was updated and maintained by a company contacted by the SWRCB in the early 1990's. The listing is no longer updated or maintained. The local agency is the contact for more information on a site on the SWEEPS list.

Date of Government Version: 06/01/1994
Date Data Arrived at EDR: 07/07/2005
Date Made Active in Reports: 08/11/2005
Number of Days to Update: 35

Source: State Water Resources Control Board
Telephone: N/A
Last EDR Contact: 06/03/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Local Land Records

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 02/06/2013
Date Data Arrived at EDR: 04/25/2013
Date Made Active in Reports: 05/10/2013
Number of Days to Update: 15

Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 04/29/2013
Next Scheduled EDR Contact: 08/12/2013
Data Release Frequency: Varies

LIENS: Environmental Liens Listing

A listing of property locations with environmental liens for California where DTSC is a lien holder.

Date of Government Version: 03/15/2013
Date Data Arrived at EDR: 03/15/2013
Date Made Active in Reports: 03/27/2013
Number of Days to Update: 12

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 06/10/2013
Next Scheduled EDR Contact: 09/23/2013
Data Release Frequency: Varies

DEED: Deed Restriction Listing

Site Mitigation and Brownfields Reuse Program Facility Sites with Deed Restrictions & Hazardous Waste Management Program Facility Sites with Deed / Land Use Restriction. The DTSC Site Mitigation and Brownfields Reuse Program (SMBRP) list includes sites cleaned up under the program's oversight and generally does not include current or former hazardous waste facilities that required a hazardous waste facility permit. The list represents deed restrictions that are active. Some sites have multiple deed restrictions. The DTSC Hazardous Waste Management Program (HWMP) has developed a list of current or former hazardous waste facilities that have a recorded land use restriction at the local county recorder's office. The land use restrictions on this list were required by the DTSC HWMP as a result of the presence of hazardous substances that remain on site after the facility (or part of the facility) has been closed or cleaned up. The types of land use restriction include deed notice, deed restriction, or a land use restriction that binds current and future owners.

Date of Government Version: 03/11/2013
Date Data Arrived at EDR: 03/12/2013
Date Made Active in Reports: 03/25/2013
Number of Days to Update: 13

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 06/11/2013
Next Scheduled EDR Contact: 09/23/2013
Data Release Frequency: Semi-Annually

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 12/31/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/27/2013
Number of Days to Update: 55

Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 04/02/2013
Next Scheduled EDR Contact: 07/15/2013
Data Release Frequency: Annually

CHMIRS: California Hazardous Material Incident Report System

California Hazardous Material Incident Reporting System. CHMIRS contains information on reported hazardous material incidents (accidental releases or spills).

Date of Government Version: 12/06/2012
Date Data Arrived at EDR: 01/29/2013
Date Made Active in Reports: 03/19/2013
Number of Days to Update: 49

Source: Office of Emergency Services
Telephone: 916-845-8400
Last EDR Contact: 05/01/2013
Next Scheduled EDR Contact: 08/12/2013
Data Release Frequency: Varies

LDS: Land Disposal Sites Listing

The Land Disposal program regulates of waste discharge to land for treatment, storage and disposal in waste management units.

Date of Government Version: 03/18/2013
Date Data Arrived at EDR: 03/19/2013
Date Made Active in Reports: 03/27/2013
Number of Days to Update: 8

Source: State Water Qualilty Control Board
Telephone: 866-480-1028
Last EDR Contact: 06/17/2013
Next Scheduled EDR Contact: 09/30/2013
Data Release Frequency: Quarterly

MCS: Military Cleanup Sites Listing

The State Water Resources Control Board and nine Regional Water Quality Control Boards partner with the Department of Defense (DoD) through the Defense and State Memorandum of Agreement (DSMOA) to oversee the investigation and remediation of water quality issues at military facilities.

Date of Government Version: 03/18/2013
Date Data Arrived at EDR: 03/19/2013
Date Made Active in Reports: 03/27/2013
Number of Days to Update: 8

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 06/17/2013
Next Scheduled EDR Contact: 09/30/2013
Data Release Frequency: Quarterly

SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 06/06/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/22/2013
Number of Days to Update: 50

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 02/12/2013
Date Data Arrived at EDR: 02/15/2013
Date Made Active in Reports: 02/27/2013
Number of Days to Update: 12

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 05/02/2013
Next Scheduled EDR Contact: 07/15/2013
Data Release Frequency: Varies

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 07/31/2012
Date Data Arrived at EDR: 08/07/2012
Date Made Active in Reports: 09/18/2012
Number of Days to Update: 42

Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 05/07/2013
Next Scheduled EDR Contact: 08/19/2013
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 11/10/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 62

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 04/19/2013
Next Scheduled EDR Contact: 07/29/2013
Data Release Frequency: Semi-Annually

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 12/31/2011
Date Data Arrived at EDR: 02/26/2013
Date Made Active in Reports: 03/13/2013
Number of Days to Update: 15

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 06/10/2013
Next Scheduled EDR Contact: 09/23/2013
Data Release Frequency: Varies

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 12/31/2011
Date Data Arrived at EDR: 01/15/2013
Date Made Active in Reports: 03/13/2013
Number of Days to Update: 57

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 04/01/2013
Next Scheduled EDR Contact: 07/15/2013
Data Release Frequency: Varies

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 12/18/2012
Date Data Arrived at EDR: 03/13/2013
Date Made Active in Reports: 04/12/2013
Number of Days to Update: 30

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 06/11/2013
Next Scheduled EDR Contact: 09/23/2013
Data Release Frequency: Annually

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 09/14/2010
Date Data Arrived at EDR: 10/07/2011
Date Made Active in Reports: 03/01/2012
Number of Days to Update: 146

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 05/28/2013
Next Scheduled EDR Contact: 09/09/2013
Data Release Frequency: Varies

US MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 02/05/2013
Date Data Arrived at EDR: 04/18/2013
Date Made Active in Reports: 05/10/2013
Number of Days to Update: 22

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 06/04/2013
Next Scheduled EDR Contact: 09/16/2013
Data Release Frequency: Semi-Annually

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2009
Date Data Arrived at EDR: 09/01/2011
Date Made Active in Reports: 01/10/2012
Number of Days to Update: 131

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 05/29/2013
Next Scheduled EDR Contact: 09/09/2013
Data Release Frequency: Annually

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2006
Date Data Arrived at EDR: 09/29/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 64

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 03/28/2013
Next Scheduled EDR Contact: 07/08/2013
Data Release Frequency: Every 4 Years

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 05/28/2013
Next Scheduled EDR Contact: 09/09/2013
Data Release Frequency: Quarterly

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 05/28/2013
Next Scheduled EDR Contact: 09/09/2013
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing
A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing
A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

SSTS: Section 7 Tracking Systems
Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 12/31/2009
Date Data Arrived at EDR: 12/10/2010
Date Made Active in Reports: 02/25/2011
Number of Days to Update: 77
Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 04/29/2013
Next Scheduled EDR Contact: 08/12/2013
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 07/20/2011
Date Data Arrived at EDR: 11/10/2011
Date Made Active in Reports: 01/10/2012
Number of Days to Update: 61

Source: Environmental Protection Agency
Telephone: 202-564-5088
Last EDR Contact: 04/15/2013
Next Scheduled EDR Contact: 07/29/2013
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 11/01/2012
Date Data Arrived at EDR: 01/16/2013
Date Made Active in Reports: 05/10/2013
Number of Days to Update: 114

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 04/19/2013
Next Scheduled EDR Contact: 07/29/2013
Data Release Frequency: Annually

MLTS: Material Licensing Tracking System

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 06/21/2011
Date Data Arrived at EDR: 07/15/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 60

Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
Last EDR Contact: 06/10/2013
Next Scheduled EDR Contact: 09/23/2013
Data Release Frequency: Quarterly

RADINFO: Radiation Information Database

The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 04/09/2013
Date Data Arrived at EDR: 04/11/2013
Date Made Active in Reports: 05/10/2013
Number of Days to Update: 29

Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 04/11/2013
Next Scheduled EDR Contact: 07/22/2013
Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 10/23/2011
Date Data Arrived at EDR: 12/13/2011
Date Made Active in Reports: 03/01/2012
Number of Days to Update: 79

Source: EPA
Telephone: (415) 947-8000
Last EDR Contact: 06/13/2013
Next Scheduled EDR Contact: 09/23/2013
Data Release Frequency: Quarterly

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 05/08/2012
Date Data Arrived at EDR: 05/25/2012
Date Made Active in Reports: 07/10/2012
Number of Days to Update: 46

Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 04/29/2013
Next Scheduled EDR Contact: 08/12/2013
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2011
Date Data Arrived at EDR: 02/26/2013
Date Made Active in Reports: 04/19/2013
Number of Days to Update: 52

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 05/30/2013
Next Scheduled EDR Contact: 09/09/2013
Data Release Frequency: Biennially

CA BOND EXP. PLAN: Bond Expenditure Plan

Department of Health Services developed a site-specific expenditure plan as the basis for an appropriation of Hazardous Substance Cleanup Bond Act funds. It is not updated.

Date of Government Version: 01/01/1989
Date Data Arrived at EDR: 07/27/1994
Date Made Active in Reports: 08/02/1994
Number of Days to Update: 6

Source: Department of Health Services
Telephone: 916-255-2118
Last EDR Contact: 05/31/1994
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

NPDES: NPDES Permits Listing

A listing of NPDES permits, including stormwater.

Date of Government Version: 05/20/2013
Date Data Arrived at EDR: 05/21/2013
Date Made Active in Reports: 06/12/2013
Number of Days to Update: 22

Source: State Water Resources Control Board
Telephone: 916-445-9379
Last EDR Contact: 05/21/2013
Next Scheduled EDR Contact: 09/02/2013
Data Release Frequency: Quarterly

UIC: UIC Listing

A listing of underground control injection wells.

Date of Government Version: 03/05/2013
Date Data Arrived at EDR: 03/19/2013
Date Made Active in Reports: 03/27/2013
Number of Days to Update: 8

Source: Deaprtment of Conservation
Telephone: 916-445-2408
Last EDR Contact: 03/19/2013
Next Scheduled EDR Contact: 12/31/2012
Data Release Frequency: Varies

CORTESE: "Cortese" Hazardous Waste & Substances Sites List
The sites for the list are designated by the State Water Resource Control Board (LUST), the Integrated Waste Board (SWF/LS), and the Department of Toxic Substances Control (Cal-Sites).

Date of Government Version: 04/01/2013
Date Data Arrived at EDR: 04/02/2013
Date Made Active in Reports: 05/14/2013
Number of Days to Update: 42
Source: CAL EPA/Office of Emergency Information
Telephone: 916-323-3400
Last EDR Contact: 04/02/2013
Next Scheduled EDR Contact: 07/15/2013
Data Release Frequency: Quarterly

HIST CORTESE: Hazardous Waste & Substance Site List
The sites for the list are designated by the State Water Resource Control Board [LUST], the Integrated Waste Board [SWF/LS], and the Department of Toxic Substances Control [CALSITES]. This listing is no longer updated by the state agency.

Date of Government Version: 04/01/2001
Date Data Arrived at EDR: 01/22/2009
Date Made Active in Reports: 04/08/2009
Number of Days to Update: 76
Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 01/22/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

NOTIFY 65: Proposition 65 Records
Listings of all Proposition 65 incidents reported to counties by the State Water Resources Control Board and the Regional Water Quality Control Board. This database is no longer updated by the reporting agency.

Date of Government Version: 10/21/1993
Date Data Arrived at EDR: 11/01/1993
Date Made Active in Reports: 11/19/1993
Number of Days to Update: 18
Source: State Water Resources Control Board
Telephone: 916-445-3846
Last EDR Contact: 03/25/2013
Next Scheduled EDR Contact: 07/08/2013
Data Release Frequency: No Update Planned

DRYCLEANERS: Cleaner Facilities
A list of drycleaner related facilities that have EPA ID numbers. These are facilities with certain SIC codes: power laundries, family and commercial; garment pressing and cleaner's agents; linen supply; coin-operated laundries and cleaning; drycleaning plants, except rugs; carpet and upholster cleaning; industrial launderers; laundry and garment services.

Date of Government Version: 12/11/2012
Date Data Arrived at EDR: 12/12/2012
Date Made Active in Reports: 01/04/2013
Number of Days to Update: 23
Source: Department of Toxic Substance Control
Telephone: 916-327-4498
Last EDR Contact: 06/10/2013
Next Scheduled EDR Contact: 12/24/2012
Data Release Frequency: Annually

WIP: Well Investigation Program Case List
Well Investigation Program case in the San Gabriel and San Fernando Valley area.

Date of Government Version: 07/03/2009
Date Data Arrived at EDR: 07/21/2009
Date Made Active in Reports: 08/03/2009
Number of Days to Update: 13
Source: Los Angeles Water Quality Control Board
Telephone: 213-576-6726
Last EDR Contact: 04/01/2013
Next Scheduled EDR Contact: 07/15/2013
Data Release Frequency: Varies

ENF: Enforcement Action Listing
A listing of Water Board Enforcement Actions. Formal is everything except Oral/Verbal Communication, Notice of Violation, Expedited Payment Letter, and Staff Enforcement Letter.

Date of Government Version: 04/26/2013
Date Data Arrived at EDR: 04/29/2013
Date Made Active in Reports: 05/16/2013
Number of Days to Update: 17
Source: State Water Resoruces Control Board
Telephone: 916-445-9379
Last EDR Contact: 04/26/2013
Next Scheduled EDR Contact: 08/12/2013
Data Release Frequency: Varies

HAZNET: Facility and Manifest Data

Facility and Manifest Data. The data is extracted from the copies of hazardous waste manifests received each year by the DTSC. The annual volume of manifests is typically 700,000 - 1,000,000 annually, representing approximately 350,000 - 500,000 shipments. Data are from the manifests submitted without correction, and therefore many contain some invalid values for data elements such as generator ID, TSD ID, waste category, and disposal method.

Date of Government Version: 12/31/2011
Date Data Arrived at EDR: 06/22/2012
Date Made Active in Reports: 07/06/2012
Number of Days to Update: 14

Source: California Environmental Protection Agency
Telephone: 916-255-1136
Last EDR Contact: 04/19/2013
Next Scheduled EDR Contact: 07/29/2013
Data Release Frequency: Annually

EMI: Emissions Inventory Data

Toxics and criteria pollutant emissions data collected by the ARB and local air pollution agencies.

Date of Government Version: 12/31/2008
Date Data Arrived at EDR: 09/29/2010
Date Made Active in Reports: 10/18/2010
Number of Days to Update: 19

Source: California Air Resources Board
Telephone: 916-322-2990
Last EDR Contact: 03/29/2013
Next Scheduled EDR Contact: 07/08/2013
Data Release Frequency: Varies

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 12/08/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 34

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 04/19/2013
Next Scheduled EDR Contact: 07/29/2013
Data Release Frequency: Semi-Annually

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 03/07/2011
Date Data Arrived at EDR: 03/09/2011
Date Made Active in Reports: 05/02/2011
Number of Days to Update: 54

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 05/06/2013
Next Scheduled EDR Contact: 08/05/2013
Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 03/04/2013
Date Data Arrived at EDR: 03/15/2013
Date Made Active in Reports: 05/10/2013
Number of Days to Update: 56

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 05/20/2013
Next Scheduled EDR Contact: 09/02/2013
Data Release Frequency: Quarterly

PCB TRANSFORMER: PCB Transformer Registration Database

The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 02/01/2011
Date Data Arrived at EDR: 10/19/2011
Date Made Active in Reports: 01/10/2012
Number of Days to Update: 83

Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 05/03/2013
Next Scheduled EDR Contact: 08/12/2013
Data Release Frequency: Varies

PROC: Certified Processors Database
A listing of certified processors.

Date of Government Version: 03/18/2013
Date Data Arrived at EDR: 03/19/2013
Date Made Active in Reports: 03/27/2013
Number of Days to Update: 8
Source: Department of Conservation
Telephone: 916-323-3836
Last EDR Contact: 06/17/2013
Next Scheduled EDR Contact: 09/30/2013
Data Release Frequency: Quarterly

MWMP: Medical Waste Management Program Listing
The Medical Waste Management Program (MWMP) ensures the proper handling and disposal of medical waste by permitting and inspecting medical waste Offsite Treatment Facilities (PDF) and Transfer Stations (PDF) throughout the state. MWMP also oversees all Medical Waste Transporters.

Date of Government Version: 03/06/2013
Date Data Arrived at EDR: 03/12/2013
Date Made Active in Reports: 03/25/2013
Number of Days to Update: 13
Source: Department of Public Health
Telephone: 916-558-1784
Last EDR Contact: 06/10/2013
Next Scheduled EDR Contact: 09/23/2013
Data Release Frequency: Varies

COAL ASH DOE: Sleam-Electric Plan Operation Data
A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 08/07/2009
Date Made Active in Reports: 10/22/2009
Number of Days to Update: 76
Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 04/18/2013
Next Scheduled EDR Contact: 07/29/2013
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List
A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 08/17/2010
Date Data Arrived at EDR: 01/03/2011
Date Made Active in Reports: 03/21/2011
Number of Days to Update: 77
Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 06/14/2013
Next Scheduled EDR Contact: 09/23/2013
Data Release Frequency: Varies

HWT: Registered Hazardous Waste Transporter Database
A listing of hazardous waste transporters. In California, unless specifically exempted, it is unlawful for any person to transport hazardous wastes unless the person holds a valid registration issued by DTSC. A hazardous waste transporter registration is valid for one year and is assigned a unique registration number.

Date of Government Version: 04/15/2013
Date Data Arrived at EDR: 04/16/2013
Date Made Active in Reports: 05/17/2013
Number of Days to Update: 31
Source: Department of Toxic Substances Control
Telephone: 916-440-7145
Last EDR Contact: 04/16/2013
Next Scheduled EDR Contact: 07/29/2013
Data Release Frequency: Quarterly

HWP: EnviroStor Permitted Facilities Listing
Detailed information on permitted hazardous waste facilities and corrective action ("cleanups") tracked in EnviroStor.

Date of Government Version: 02/25/2013
Date Data Arrived at EDR: 02/26/2013
Date Made Active in Reports: 03/25/2013
Number of Days to Update: 27
Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 05/29/2013
Next Scheduled EDR Contact: 09/09/2013
Data Release Frequency: Quarterly

Financial Assurance 2: Financial Assurance Information Listing
A listing of financial assurance information for solid waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 02/19/2013
Date Data Arrived at EDR: 02/20/2013
Date Made Active in Reports: 03/20/2013
Number of Days to Update: 28

Source: California Integrated Waste Management Board
Telephone: 916-341-6066
Last EDR Contact: 05/20/2013
Next Scheduled EDR Contact: 09/02/2013
Data Release Frequency: Varies

Financial Assurance 1: Financial Assurance Information Listing
Financial Assurance information

Date of Government Version: 03/01/2007
Date Data Arrived at EDR: 06/01/2007
Date Made Active in Reports: 06/29/2007
Number of Days to Update: 28

Source: Department of Toxic Substances Control
Telephone: 916-255-3628
Last EDR Contact: 05/03/2013
Next Scheduled EDR Contact: 08/12/2013
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites
A listing of former lead smelter site locations.

Date of Government Version: 01/29/2013
Date Data Arrived at EDR: 02/14/2013
Date Made Active in Reports: 02/27/2013
Number of Days to Update: 13

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 04/08/2013
Next Scheduled EDR Contact: 07/22/2013
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites
A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

2020 COR ACTION: 2020 Corrective Action Program List
The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 11/11/2011
Date Data Arrived at EDR: 05/18/2012
Date Made Active in Reports: 05/25/2012
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 05/17/2013
Next Scheduled EDR Contact: 08/26/2013
Data Release Frequency: Varies

FEDLAND: Federal and Indian Lands
Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 02/06/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 339

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 04/19/2013
Next Scheduled EDR Contact: 07/29/2013
Data Release Frequency: N/A

PRP: Potentially Responsible Parties
A listing of verified Potentially Responsible Parties

Date of Government Version: 12/02/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 03/13/2013
Number of Days to Update: 69

Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 04/04/2013
Next Scheduled EDR Contact: 07/15/2013
Data Release Frequency: Quarterly

WDS: Waste Discharge System
Sites which have been issued waste discharge requirements.

Date of Government Version: 06/19/2007
Date Data Arrived at EDR: 06/20/2007
Date Made Active in Reports: 06/29/2007
Number of Days to Update: 9

Source: State Water Resources Control Board
Telephone: 916-341-5227
Last EDR Contact: 05/28/2013
Next Scheduled EDR Contact: 09/09/2013
Data Release Frequency: Quarterly

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)
The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 01/23/2013
Date Data Arrived at EDR: 01/30/2013
Date Made Active in Reports: 05/10/2013
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-5962
Last EDR Contact: 04/01/2013
Next Scheduled EDR Contact: 07/15/2013
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data
A listing of minor source facilities.

Date of Government Version: 01/23/2013
Date Data Arrived at EDR: 01/30/2013
Date Made Active in Reports: 05/10/2013
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-5962
Last EDR Contact: 04/01/2013
Next Scheduled EDR Contact: 07/15/2013
Data Release Frequency: Annually

EPA WATCH LIST: EPA WATCH LIST
EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 12/31/2012
Date Data Arrived at EDR: 02/18/2013
Date Made Active in Reports: 05/10/2013
Number of Days to Update: 81

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 05/10/2013
Next Scheduled EDR Contact: 08/26/2013
Data Release Frequency: Quarterly

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

EDR MGP: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR US Hist Auto Stat: EDR Exclusive Historic Gas Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR US Hist Cleaners: EDR Exclusive Historic Dry Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR US Hist Cleaners: EDR Proprietary Historic Dry Cleaners - Cole

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: N/A
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR US Hist Auto Stat: EDR Proprietary Historic Gas Stations - Cole

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: N/A
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

COUNTY RECORDS

ALAMEDA COUNTY:

Contaminated Sites

A listing of contaminated sites overseen by the Toxic Release Program (oil and groundwater contamination from chemical releases and spills) and the Leaking Underground Storage Tank Program (soil and ground water contamination from leaking petroleum USTs).

Date of Government Version: 04/15/2013
Date Data Arrived at EDR: 04/16/2013
Date Made Active in Reports: 05/16/2013
Number of Days to Update: 30

Source: Alameda County Environmental Health Services
Telephone: 510-567-6700
Last EDR Contact: 04/01/2013
Next Scheduled EDR Contact: 07/15/2013
Data Release Frequency: Semi-Annually

Underground Tanks

Underground storage tank sites located in Alameda county.

Date of Government Version: 04/15/2013
Date Data Arrived at EDR: 04/16/2013
Date Made Active in Reports: 05/16/2013
Number of Days to Update: 30

Source: Alameda County Environmental Health Services
Telephone: 510-567-6700
Last EDR Contact: 04/01/2013
Next Scheduled EDR Contact: 07/15/2013
Data Release Frequency: Semi-Annually

AMADOR COUNTY:

CUPA Facility List

Cupa Facility List

Date of Government Version: 03/13/2013
Date Data Arrived at EDR: 03/14/2013
Date Made Active in Reports: 04/04/2013
Number of Days to Update: 21

Source: Amador County Environmental Health
Telephone: 209-223-6439
Last EDR Contact: 06/10/2013
Next Scheduled EDR Contact: 09/23/2013
Data Release Frequency: Varies

BUTTE COUNTY:

CUPA Facility Listing

Cupa facility list.

Date of Government Version: 10/16/2012
Date Data Arrived at EDR: 10/17/2012
Date Made Active in Reports: 11/13/2012
Number of Days to Update: 27

Source: Public Health Department
Telephone: 530-538-7149
Last EDR Contact: 04/26/2013
Next Scheduled EDR Contact: 04/29/2013
Data Release Frequency: Varies

CALVERAS COUNTY:

CUPA Facility Listing

Cupa Facility Listing

Date of Government Version: 04/16/2013
Date Data Arrived at EDR: 04/17/2013
Date Made Active in Reports: 05/16/2013
Number of Days to Update: 29

Source: Calveras County Environmental Health
Telephone: 209-754-6399
Last EDR Contact: 04/15/2013
Next Scheduled EDR Contact: 07/15/2013
Data Release Frequency: Quarterly

COLUSA COUNTY:

CUPA Facility List
Cupa facility list.

Date of Government Version: 01/04/2013
Date Data Arrived at EDR: 01/14/2013
Date Made Active in Reports: 03/01/2013
Number of Days to Update: 46

Source: Health & Human Services
Telephone: 530-458-0396
Last EDR Contact: 06/13/2013
Next Scheduled EDR Contact: 08/26/2013
Data Release Frequency: Varies

CONTRA COSTA COUNTY:

Site List
List includes sites from the underground tank, hazardous waste generator and business plan/2185 programs.

Date of Government Version: 04/09/2013
Date Data Arrived at EDR: 04/10/2013
Date Made Active in Reports: 05/14/2013
Number of Days to Update: 34

Source: Contra Costa Health Services Department
Telephone: 925-646-2286
Last EDR Contact: 05/06/2013
Next Scheduled EDR Contact: 08/19/2013
Data Release Frequency: Semi-Annually

DEL NORTE COUNTY:

CUPA Facility List
Cupa Facility list

Date of Government Version: 01/09/2013
Date Data Arrived at EDR: 01/10/2013
Date Made Active in Reports: 02/25/2013
Number of Days to Update: 46

Source: Del Norte County Environmental Health Division
Telephone: 707-465-0426
Last EDR Contact: 05/06/2013
Next Scheduled EDR Contact: 08/19/2013
Data Release Frequency: Varies

EL DORADO COUNTY:

CUPA Facility List
CUPA facility list.

Date of Government Version: 02/27/2013
Date Data Arrived at EDR: 02/28/2013
Date Made Active in Reports: 03/25/2013
Number of Days to Update: 25

Source: El Dorado County Environmental Management Department
Telephone: 530-621-6623
Last EDR Contact: 05/06/2013
Next Scheduled EDR Contact: 08/19/2013
Data Release Frequency: Varies

FRESNO COUNTY:

CUPA Resources List
Certified Unified Program Agency. CUPA's are responsible for implementing a unified hazardous materials and hazardous waste management regulatory program. The agency provides oversight of businesses that deal with hazardous materials, operate underground storage tanks or aboveground storage tanks.

Date of Government Version: 03/31/2013
Date Data Arrived at EDR: 04/16/2013
Date Made Active in Reports: 05/16/2013
Number of Days to Update: 30

Source: Dept. of Community Health
Telephone: 559-445-3271
Last EDR Contact: 04/15/2013
Next Scheduled EDR Contact: 07/29/2013
Data Release Frequency: Semi-Annually

HUMBOLDT COUNTY:

CUPA Facility List
CUPA facility list.

Date of Government Version: 03/15/2013
Date Data Arrived at EDR: 03/19/2013
Date Made Active in Reports: 03/27/2013
Number of Days to Update: 8

Source: Humboldt County Environmental Health
Telephone: N/A
Last EDR Contact: 05/28/2013
Next Scheduled EDR Contact: 09/09/2013
Data Release Frequency: Varies

IMPERIAL COUNTY:

CUPA Facility List
Cupa facility list.

Date of Government Version: 05/01/2012
Date Data Arrived at EDR: 05/02/2012
Date Made Active in Reports: 06/11/2012
Number of Days to Update: 40

Source: San Diego Border Field Office
Telephone: 760-339-2777
Last EDR Contact: 04/29/2013
Next Scheduled EDR Contact: 08/12/2013
Data Release Frequency: Varies

INYO COUNTY:

CUPA Facility List
Cupa facility list.

Date of Government Version: 06/26/2012
Date Data Arrived at EDR: 06/27/2012
Date Made Active in Reports: 08/17/2012
Number of Days to Update: 51

Source: Inyo County Environmental Health Services
Telephone: 760-878-0238
Last EDR Contact: 05/28/2013
Next Scheduled EDR Contact: 09/09/2013
Data Release Frequency: Varies

KERN COUNTY:

Underground Storage Tank Sites & Tank Listing
Kern County Sites and Tanks Listing.

Date of Government Version: 08/31/2010
Date Data Arrived at EDR: 09/01/2010
Date Made Active in Reports: 09/30/2010
Number of Days to Update: 29

Source: Kern County Environment Health Services Department
Telephone: 661-862-8700
Last EDR Contact: 05/10/2013
Next Scheduled EDR Contact: 08/26/2013
Data Release Frequency: Quarterly

KINGS COUNTY:

CUPA Facility List
A listing of sites included in the county?s Certified Unified Program Agency database. California?s Secretary for Environmental Protection established the unified hazardous materials and hazardous waste regulatory program as required by chapter 6.11 of the California Health and Safety Code. The Unified Program consolidates the administration, permits, inspections, and enforcement activities.

Date of Government Version: 02/12/2013
Date Data Arrived at EDR: 02/13/2013
Date Made Active in Reports: 03/21/2013
Number of Days to Update: 36

Source: Kings County Department of Public Health
Telephone: 559-584-1411
Last EDR Contact: 06/10/2013
Next Scheduled EDR Contact: 09/09/2013
Data Release Frequency: Varies

LAKE COUNTY:

CUPA Facility List
Cupa facility list

Date of Government Version: 01/23/2013
Date Data Arrived at EDR: 01/25/2013
Date Made Active in Reports: 02/27/2013
Number of Days to Update: 33

Source: Lake County Environmental Health
Telephone: 707-263-1164
Last EDR Contact: 04/19/2013
Next Scheduled EDR Contact: 08/05/2013
Data Release Frequency: Varies

LOS ANGELES COUNTY:

San Gabriel Valley Areas of Concern
San Gabriel Valley areas where VOC contamination is at or above the MCL as designated by region 9 EPA office.

Date of Government Version: 03/30/2009
Date Data Arrived at EDR: 03/31/2009
Date Made Active in Reports: 10/23/2009
Number of Days to Update: 206

Source: EPA Region 9
Telephone: 415-972-3178
Last EDR Contact: 05/10/2013
Next Scheduled EDR Contact: 07/01/2013
Data Release Frequency: No Update Planned

HMS: Street Number List
Industrial Waste and Underground Storage Tank Sites.

Date of Government Version: 10/31/2012
Date Data Arrived at EDR: 12/28/2012
Date Made Active in Reports: 01/25/2013
Number of Days to Update: 28

Source: Department of Public Works
Telephone: 626-458-3517
Last EDR Contact: 04/15/2013
Next Scheduled EDR Contact: 07/29/2013
Data Release Frequency: Semi-Annually

List of Solid Waste Facilities
Solid Waste Facilities in Los Angeles County.

Date of Government Version: 04/24/2013
Date Data Arrived at EDR: 04/24/2013
Date Made Active in Reports: 05/17/2013
Number of Days to Update: 23

Source: La County Department of Public Works
Telephone: 818-458-5185
Last EDR Contact: 04/24/2013
Next Scheduled EDR Contact: 08/05/2013
Data Release Frequency: Varies

City of Los Angeles Landfills
Landfills owned and maintained by the City of Los Angeles.

Date of Government Version: 03/05/2009
Date Data Arrived at EDR: 03/10/2009
Date Made Active in Reports: 04/08/2009
Number of Days to Update: 29

Source: Engineering & Construction Division
Telephone: 213-473-7869
Last EDR Contact: 05/20/2013
Next Scheduled EDR Contact: 09/02/2013
Data Release Frequency: Varies

Site Mitigation List
Industrial sites that have had some sort of spill or complaint.

Date of Government Version: 01/30/2013
Date Data Arrived at EDR: 02/21/2013
Date Made Active in Reports: 03/25/2013
Number of Days to Update: 32

Source: Community Health Services
Telephone: 323-890-7806
Last EDR Contact: 04/19/2013
Next Scheduled EDR Contact: 08/05/2013
Data Release Frequency: Annually

City of El Segundo Underground Storage Tank
Underground storage tank sites located in El Segundo city.

Date of Government Version: 04/22/2013
Date Data Arrived at EDR: 04/29/2013
Date Made Active in Reports: 05/17/2013
Number of Days to Update: 18

Source: City of El Segundo Fire Department
Telephone: 310-524-2236
Last EDR Contact: 04/19/2013
Next Scheduled EDR Contact: 08/05/2013
Data Release Frequency: Semi-Annually

City of Long Beach Underground Storage Tank

Underground storage tank sites located in the city of Long Beach.

Date of Government Version: 03/28/2003
Date Data Arrived at EDR: 10/23/2003
Date Made Active in Reports: 11/26/2003
Number of Days to Update: 34

Source: City of Long Beach Fire Department
Telephone: 562-570-2563
Last EDR Contact: 04/26/2013
Next Scheduled EDR Contact: 08/12/2013
Data Release Frequency: Annually

City of Torrance Underground Storage Tank

Underground storage tank sites located in the city of Torrance.

Date of Government Version: 04/15/2013
Date Data Arrived at EDR: 04/16/2013
Date Made Active in Reports: 05/17/2013
Number of Days to Update: 31

Source: City of Torrance Fire Department
Telephone: 310-618-2973
Last EDR Contact: 04/15/2013
Next Scheduled EDR Contact: 07/29/2013
Data Release Frequency: Semi-Annually

MADERA COUNTY:

CUPA Facility List

A listing of sites included in the county?s Certified Unified Program Agency database. California?s Secretary for Environmental Protection established the unified hazardous materials and hazardous waste regulatory program as required by chapter 6.11 of the California Health and Safety Code. The Unified Program consolidates the administration, permits, inspections, and enforcement activities.

Date of Government Version: 04/15/2013
Date Data Arrived at EDR: 04/16/2013
Date Made Active in Reports: 05/17/2013
Number of Days to Update: 31

Source: Madera County Environmental Health
Telephone: 559-675-7823
Last EDR Contact: 05/28/2013
Next Scheduled EDR Contact: 09/09/2013
Data Release Frequency: Varies

MARIN COUNTY:

Underground Storage Tank Sites

Currently permitted USTs in Marin County.

Date of Government Version: 11/26/2012
Date Data Arrived at EDR: 11/28/2012
Date Made Active in Reports: 01/21/2013
Number of Days to Update: 54

Source: Public Works Department Waste Management
Telephone: 415-499-6647
Last EDR Contact: 04/08/2013
Next Scheduled EDR Contact: 07/22/2013
Data Release Frequency: Semi-Annually

MERCED COUNTY:

CUPA Facility List

CUPA facility list.

Date of Government Version: 02/25/2013
Date Data Arrived at EDR: 02/26/2013
Date Made Active in Reports: 03/25/2013
Number of Days to Update: 27

Source: Merced County Environmental Health
Telephone: 209-381-1094
Last EDR Contact: 02/25/2013
Next Scheduled EDR Contact: 09/09/2013
Data Release Frequency: Varies

MONO COUNTY:

CUPA Facility List
CUPA Facility List

Date of Government Version: 03/04/2013
Date Data Arrived at EDR: 03/08/2013
Date Made Active in Reports: 03/25/2013
Number of Days to Update: 17

Source: Mono County Health Department
Telephone: 760-932-5580
Last EDR Contact: 06/03/2013
Next Scheduled EDR Contact: 09/16/2013
Data Release Frequency: Varies

MONTEREY COUNTY:

CUPA Facility Listing
CUPA Program listing from the Environmental Health Division.

Date of Government Version: 03/14/2013
Date Data Arrived at EDR: 03/15/2013
Date Made Active in Reports: 03/27/2013
Number of Days to Update: 12

Source: Monterey County Health Department
Telephone: 831-796-1297
Last EDR Contact: 05/28/2013
Next Scheduled EDR Contact: 09/09/2013
Data Release Frequency: Varies

NAPA COUNTY:

Sites With Reported Contamination
A listing of leaking underground storage tank sites located in Napa county.

Date of Government Version: 12/05/2011
Date Data Arrived at EDR: 12/06/2011
Date Made Active in Reports: 02/07/2012
Number of Days to Update: 63

Source: Napa County Department of Environmental Management
Telephone: 707-253-4269
Last EDR Contact: 06/03/2013
Next Scheduled EDR Contact: 09/16/2013
Data Release Frequency: No Update Planned

Closed and Operating Underground Storage Tank Sites
Underground storage tank sites located in Napa county.

Date of Government Version: 01/15/2008
Date Data Arrived at EDR: 01/16/2008
Date Made Active in Reports: 02/08/2008
Number of Days to Update: 23

Source: Napa County Department of Environmental Management
Telephone: 707-253-4269
Last EDR Contact: 06/03/2013
Next Scheduled EDR Contact: 09/16/2013
Data Release Frequency: No Update Planned

NEVADA COUNTY:

CUPA Facility List
CUPA facility list.

Date of Government Version: 03/08/2013
Date Data Arrived at EDR: 03/08/2013
Date Made Active in Reports: 03/25/2013
Number of Days to Update: 17

Source: Community Development Agency
Telephone: 530-265-1467
Last EDR Contact: 05/17/2013
Next Scheduled EDR Contact: 08/19/2013
Data Release Frequency: Varies

ORANGE COUNTY:

List of Industrial Site Cleanups
Petroleum and non-petroleum spills.

Date of Government Version: 05/01/2013
Date Data Arrived at EDR: 05/15/2013
Date Made Active in Reports: 06/12/2013
Number of Days to Update: 28

Source: Health Care Agency
Telephone: 714-834-3446
Last EDR Contact: 05/10/2013
Next Scheduled EDR Contact: 08/26/2013
Data Release Frequency: Annually

List of Underground Storage Tank Cleanups
Orange County Underground Storage Tank Cleanups (LUST).

Date of Government Version: 02/04/2013
Date Data Arrived at EDR: 02/19/2013
Date Made Active in Reports: 03/20/2013
Number of Days to Update: 29

Source: Health Care Agency
Telephone: 714-834-3446
Last EDR Contact: 05/10/2013
Next Scheduled EDR Contact: 08/26/2013
Data Release Frequency: Quarterly

List of Underground Storage Tank Facilities
Orange County Underground Storage Tank Facilities (UST).

Date of Government Version: 02/04/2013
Date Data Arrived at EDR: 02/18/2013
Date Made Active in Reports: 03/27/2013
Number of Days to Update: 37

Source: Health Care Agency
Telephone: 714-834-3446
Last EDR Contact: 05/10/2013
Next Scheduled EDR Contact: 08/26/2013
Data Release Frequency: Quarterly

PLACER COUNTY:

Master List of Facilities
List includes aboveground tanks, underground tanks and cleanup sites.

Date of Government Version: 03/12/2013
Date Data Arrived at EDR: 03/13/2013
Date Made Active in Reports: 03/27/2013
Number of Days to Update: 14

Source: Placer County Health and Human Services
Telephone: 530-745-2363
Last EDR Contact: 06/10/2013
Next Scheduled EDR Contact: 09/23/2013
Data Release Frequency: Semi-Annually

RIVERSIDE COUNTY:

Listing of Underground Tank Cleanup Sites
Riverside County Underground Storage Tank Cleanup Sites (LUST).

Date of Government Version: 04/23/2013
Date Data Arrived at EDR: 04/24/2013
Date Made Active in Reports: 05/17/2013
Number of Days to Update: 23

Source: Department of Environmental Health
Telephone: 951-358-5055
Last EDR Contact: 03/25/2013
Next Scheduled EDR Contact: 07/08/2013
Data Release Frequency: Quarterly

Underground Storage Tank Tank List
Underground storage tank sites located in Riverside county.

Date of Government Version: 04/23/2013
Date Data Arrived at EDR: 04/24/2013
Date Made Active in Reports: 05/16/2013
Number of Days to Update: 22

Source: Department of Environmental Health
Telephone: 951-358-5055
Last EDR Contact: 03/25/2013
Next Scheduled EDR Contact: 07/08/2013
Data Release Frequency: Quarterly

SACRAMENTO COUNTY:

Toxic Site Clean-Up List

List of sites where unauthorized releases of potentially hazardous materials have occurred.

Date of Government Version: 02/04/2013
Date Data Arrived at EDR: 04/11/2013
Date Made Active in Reports: 05/14/2013
Number of Days to Update: 33

Source: Sacramento County Environmental Management
Telephone: 916-875-8406
Last EDR Contact: 04/08/2013
Next Scheduled EDR Contact: 07/22/2013
Data Release Frequency: Quarterly

Master Hazardous Materials Facility List

Any business that has hazardous materials on site - hazardous material storage sites, underground storage tanks, waste generators.

Date of Government Version: 02/04/2013
Date Data Arrived at EDR: 04/12/2013
Date Made Active in Reports: 05/16/2013
Number of Days to Update: 34

Source: Sacramento County Environmental Management
Telephone: 916-875-8406
Last EDR Contact: 04/08/2013
Next Scheduled EDR Contact: 07/22/2013
Data Release Frequency: Quarterly

SAN BERNARDINO COUNTY:

Hazardous Material Permits

This listing includes underground storage tanks, medical waste handlers/generators, hazardous materials handlers, hazardous waste generators, and waste oil generators/handlers.

Date of Government Version: 03/04/2013
Date Data Arrived at EDR: 03/05/2013
Date Made Active in Reports: 03/25/2013
Number of Days to Update: 20

Source: San Bernardino County Fire Department Hazardous Materials Division
Telephone: 909-387-3041
Last EDR Contact: 05/13/2013
Next Scheduled EDR Contact: 08/26/2013
Data Release Frequency: Quarterly

SAN DIEGO COUNTY:

Hazardous Materials Management Division Database

The database includes: HE58 - This report contains the business name, site address, business phone number, establishment 'H' permit number, type of permit, and the business status. HE17 - In addition to providing the same information provided in the HE58 listing, HE17 provides inspection dates, violations received by the establishment, hazardous waste generated, the quantity, method of storage, treatment/disposal of waste and the hauler, and information on underground storage tanks. Unauthorized Release List - Includes a summary of environmental contamination cases in San Diego County (underground tank cases, non-tank cases, groundwater contamination, and soil contamination are included.)

Date of Government Version: 08/17/2012
Date Data Arrived at EDR: 08/20/2012
Date Made Active in Reports: 10/03/2012
Number of Days to Update: 44

Source: Hazardous Materials Management Division
Telephone: 619-338-2268
Last EDR Contact: 06/10/2013
Next Scheduled EDR Contact: 09/23/2013
Data Release Frequency: Quarterly

Solid Waste Facilities

San Diego County Solid Waste Facilities.

Date of Government Version: 10/31/2012
Date Data Arrived at EDR: 11/06/2012
Date Made Active in Reports: 11/30/2012
Number of Days to Update: 24

Source: Department of Health Services
Telephone: 619-338-2209
Last EDR Contact: 04/26/2013
Next Scheduled EDR Contact: 08/12/2013
Data Release Frequency: Varies

Environmental Case Listing
The listing contains all underground tank release cases and projects pertaining to properties contaminated with hazardous substances that are actively under review by the Site Assessment and Mitigation Program.

Date of Government Version: 03/23/2010
Date Data Arrived at EDR: 06/15/2010
Date Made Active in Reports: 07/09/2010
Number of Days to Update: 24
Source: San Diego County Department of Environmental Health
Telephone: 619-338-2371
Last EDR Contact: 06/10/2013
Next Scheduled EDR Contact: 09/23/2013
Data Release Frequency: No Update Planned

SAN FRANCISCO COUNTY:

Local Oversite Facilities
A listing of leaking underground storage tank sites located in San Francisco county.

Date of Government Version: 09/19/2008
Date Data Arrived at EDR: 09/19/2008
Date Made Active in Reports: 09/29/2008
Number of Days to Update: 10
Source: Department Of Public Health San Francisco County
Telephone: 415-252-3920
Last EDR Contact: 05/10/2013
Next Scheduled EDR Contact: 08/26/2013
Data Release Frequency: Quarterly

Underground Storage Tank Information
Underground storage tank sites located in San Francisco county.

Date of Government Version: 11/29/2010
Date Data Arrived at EDR: 03/10/2011
Date Made Active in Reports: 03/15/2011
Number of Days to Update: 5
Source: Department of Public Health
Telephone: 415-252-3920
Last EDR Contact: 05/10/2013
Next Scheduled EDR Contact: 08/26/2013
Data Release Frequency: Quarterly

SAN JOAQUIN COUNTY:

San Joaquin Co. UST
A listing of underground storage tank locations in San Joaquin county.

Date of Government Version: 03/25/2013
Date Data Arrived at EDR: 03/25/2013
Date Made Active in Reports: 04/18/2013
Number of Days to Update: 24
Source: Environmental Health Department
Telephone: N/A
Last EDR Contact: 03/25/2013
Next Scheduled EDR Contact: 07/08/2013
Data Release Frequency: Semi-Annually

SAN LUIS OBISPO COUNTY:

CUPA Facility List
Cupa Facility List.

Date of Government Version: 02/26/2013
Date Data Arrived at EDR: 02/26/2013
Date Made Active in Reports: 03/25/2013
Number of Days to Update: 27
Source: San Luis Obispo County Public Health Department
Telephone: 805-781-5596
Last EDR Contact: 05/28/2013
Next Scheduled EDR Contact: 09/09/2013
Data Release Frequency: Varies

SAN MATEO COUNTY:

Business Inventory
List includes Hazardous Materials Business Plan, hazardous waste generators, and underground storage tanks.

Date of Government Version: 04/09/2013
Date Data Arrived at EDR: 04/10/2013
Date Made Active in Reports: 05/14/2013
Number of Days to Update: 34

Source: San Mateo County Environmental Health Services Division
Telephone: 650-363-1921
Last EDR Contact: 06/13/2013
Next Scheduled EDR Contact: 09/30/2013
Data Release Frequency: Annually

Fuel Leak List

A listing of leaking underground storage tank sites located in San Mateo county.

Date of Government Version: 03/18/2013
Date Data Arrived at EDR: 03/19/2013
Date Made Active in Reports: 03/27/2013
Number of Days to Update: 8

Source: San Mateo County Environmental Health Services Division
Telephone: 650-363-1921
Last EDR Contact: 06/17/2013
Next Scheduled EDR Contact: 09/30/2013
Data Release Frequency: Semi-Annually

SANTA BARBARA COUNTY:

CUPA Facility Listing

CUPA Program Listing from the Environmental Health Services division.

Date of Government Version: 09/08/2011
Date Data Arrived at EDR: 09/09/2011
Date Made Active in Reports: 10/07/2011
Number of Days to Update: 28

Source: Santa Barbara County Public Health Department
Telephone: 805-686-8167
Last EDR Contact: 05/20/2013
Next Scheduled EDR Contact: 06/10/2013
Data Release Frequency: Varies

SANTA CLARA COUNTY:

Cupa Facility List

Cupa facility list

Date of Government Version: 03/04/2013
Date Data Arrived at EDR: 03/05/2013
Date Made Active in Reports: 03/25/2013
Number of Days to Update: 20

Source: Department of Environmental Health
Telephone: 408-918-1973
Last EDR Contact: 06/03/2013
Next Scheduled EDR Contact: 09/16/2013
Data Release Frequency: Varies

HIST LUST - Fuel Leak Site Activity Report

A listing of open and closed leaking underground storage tanks. This listing is no longer updated by the county. Leaking underground storage tanks are now handled by the Department of Environmental Health.

Date of Government Version: 03/29/2005
Date Data Arrived at EDR: 03/30/2005
Date Made Active in Reports: 04/21/2005
Number of Days to Update: 22

Source: Santa Clara Valley Water District
Telephone: 408-265-2600
Last EDR Contact: 03/23/2009
Next Scheduled EDR Contact: 06/22/2009
Data Release Frequency: No Update Planned

LOP Listing

A listing of leaking underground storage tanks located in Santa Clara county.

Date of Government Version: 03/04/2013
Date Data Arrived at EDR: 03/06/2013
Date Made Active in Reports: 03/25/2013
Number of Days to Update: 19

Source: Department of Environmental Health
Telephone: 408-918-3417
Last EDR Contact: 06/03/2013
Next Scheduled EDR Contact: 09/16/2013
Data Release Frequency: Annually

Hazardous Material Facilities

Hazardous material facilities, including underground storage tank sites.

Date of Government Version: 02/12/2013
Date Data Arrived at EDR: 02/14/2013
Date Made Active in Reports: 03/20/2013
Number of Days to Update: 34

Source: City of San Jose Fire Department
Telephone: 408-535-7694
Last EDR Contact: 05/13/2013
Next Scheduled EDR Contact: 08/26/2013
Data Release Frequency: Annually

SANTA CRUZ COUNTY:

CUPA Facility List
CUPA facility listing.

Date of Government Version: 02/26/2013
Date Data Arrived at EDR: 02/26/2013
Date Made Active in Reports: 03/20/2013
Number of Days to Update: 22

Source: Santa Cruz County Environmental Health
Telephone: 831-464-2761
Last EDR Contact: 05/28/2013
Next Scheduled EDR Contact: 09/09/2013
Data Release Frequency: Varies

SHASTA COUNTY:

CUPA Facility List
Cupa Facility List.

Date of Government Version: 03/15/2013
Date Data Arrived at EDR: 03/15/2013
Date Made Active in Reports: 03/27/2013
Number of Days to Update: 12

Source: Shasta County Department of Resource Management
Telephone: 530-225-5789
Last EDR Contact: 05/28/2013
Next Scheduled EDR Contact: 09/09/2013
Data Release Frequency: Varies

SOLANO COUNTY:

Leaking Underground Storage Tanks
A listing of leaking underground storage tank sites located in Solano county.

Date of Government Version: 03/20/2013
Date Data Arrived at EDR: 03/28/2013
Date Made Active in Reports: 05/14/2013
Number of Days to Update: 47

Source: Solano County Department of Environmental Management
Telephone: 707-784-6770
Last EDR Contact: 06/12/2013
Next Scheduled EDR Contact: 09/30/2013
Data Release Frequency: Quarterly

Underground Storage Tanks
Underground storage tank sites located in Solano county.

Date of Government Version: 03/20/2013
Date Data Arrived at EDR: 03/28/2013
Date Made Active in Reports: 05/13/2013
Number of Days to Update: 46

Source: Solano County Department of Environmental Management
Telephone: 707-784-6770
Last EDR Contact: 06/12/2013
Next Scheduled EDR Contact: 09/30/2013
Data Release Frequency: Quarterly

SONOMA COUNTY:

Cupa Facility List
Cupa Facility list

Date of Government Version: 04/01/2013
Date Data Arrived at EDR: 04/03/2013
Date Made Active in Reports: 05/14/2013
Number of Days to Update: 41

Source: County of Sonoma Fire & Emergency Services Department
Telephone: 707-565-1174
Last EDR Contact: 04/01/2013
Next Scheduled EDR Contact: 07/15/2013
Data Release Frequency: Varies

Leaking Underground Storage Tank Sites
A listing of leaking underground storage tank sites located in Sonoma county.

Date of Government Version: 04/02/2013
Date Data Arrived at EDR: 04/03/2013
Date Made Active in Reports: 05/14/2013
Number of Days to Update: 41

Source: Department of Health Services
Telephone: 707-565-6565
Last EDR Contact: 04/01/2013
Next Scheduled EDR Contact: 07/15/2013
Data Release Frequency: Quarterly

SUTTER COUNTY:

Underground Storage Tanks
Underground storage tank sites located in Sutter county.

Date of Government Version: 03/13/2013
Date Data Arrived at EDR: 03/14/2013
Date Made Active in Reports: 03/27/2013
Number of Days to Update: 13

Source: Sutter County Department of Agriculture
Telephone: 530-822-7500
Last EDR Contact: 06/10/2013
Next Scheduled EDR Contact: 09/23/2013
Data Release Frequency: Semi-Annually

TUOLUMNE COUNTY:

CUPA Facility List
Cupa facility list

Date of Government Version: 01/14/2013
Date Data Arrived at EDR: 01/16/2013
Date Made Active in Reports: 02/27/2013
Number of Days to Update: 42

Source: Divison of Environmental Health
Telephone: 209-533-5633
Last EDR Contact: 05/15/2013
Next Scheduled EDR Contact: 07/29/2013
Data Release Frequency: Varies

VENTURA COUNTY:

Business Plan, Hazardous Waste Producers, and Operating Underground Tanks
The BWT list indicates by site address whether the Environmental Health Division has Business Plan (B), Waste Producer (W), and/or Underground Tank (T) information.

Date of Government Version: 03/30/2012
Date Data Arrived at EDR: 05/25/2012
Date Made Active in Reports: 07/06/2012
Number of Days to Update: 42

Source: Ventura County Environmental Health Division
Telephone: 805-654-2813
Last EDR Contact: 05/20/2013
Next Scheduled EDR Contact: 09/02/2013
Data Release Frequency: Quarterly

Inventory of Illegal Abandoned and Inactive Sites
Ventura County Inventory of Closed, Illegal Abandoned, and Inactive Sites.

Date of Government Version: 12/01/2011
Date Data Arrived at EDR: 12/01/2011
Date Made Active in Reports: 01/19/2012
Number of Days to Update: 49

Source: Environmental Health Division
Telephone: 805-654-2813
Last EDR Contact: 04/08/2013
Next Scheduled EDR Contact: 07/22/2013
Data Release Frequency: Annually

Listing of Underground Tank Cleanup Sites
Ventura County Underground Storage Tank Cleanup Sites (LUST).

Date of Government Version: 05/29/2008
Date Data Arrived at EDR: 06/24/2008
Date Made Active in Reports: 07/31/2008
Number of Days to Update: 37

Source: Environmental Health Division
Telephone: 805-654-2813
Last EDR Contact: 02/18/2013
Next Scheduled EDR Contact: 06/03/2013
Data Release Frequency: Quarterly

Medical Waste Program List

To protect public health and safety and the environment from potential exposure to disease causing agents, the Environmental Health Division Medical Waste Program regulates the generation, handling, storage, treatment and disposal of medical waste throughout the County.

Date of Government Version: 01/28/2013
Date Data Arrived at EDR: 02/01/2013
Date Made Active in Reports: 03/20/2013
Number of Days to Update: 47

Source: Ventura County Resource Management Agency
Telephone: 805-654-2813
Last EDR Contact: 06/11/2013
Next Scheduled EDR Contact: 08/12/2013
Data Release Frequency: Quarterly

Underground Tank Closed Sites List

Ventura County Operating Underground Storage Tank Sites (UST)/Underground Tank Closed Sites List.

Date of Government Version: 03/01/2013
Date Data Arrived at EDR: 03/28/2013
Date Made Active in Reports: 05/13/2013
Number of Days to Update: 46

Source: Environmental Health Division
Telephone: 805-654-2813
Last EDR Contact: 06/12/2013
Next Scheduled EDR Contact: 09/30/2013
Data Release Frequency: Quarterly

YOLO COUNTY:

Underground Storage Tank Comprehensive Facility Report

Underground storage tank sites located in Yolo county.

Date of Government Version: 03/25/2013
Date Data Arrived at EDR: 03/29/2013
Date Made Active in Reports: 05/13/2013
Number of Days to Update: 45

Source: Yolo County Department of Health
Telephone: 530-666-8646
Last EDR Contact: 03/25/2013
Next Scheduled EDR Contact: 07/08/2013
Data Release Frequency: Annually

YUBA COUNTY:

CUPA Facility List

CUPA facility listing for Yuba County.

Date of Government Version: 03/05/2013
Date Data Arrived at EDR: 03/06/2013
Date Made Active in Reports: 03/25/2013
Number of Days to Update: 19

Source: Yuba County Environmental Health Department
Telephone: 530-749-7523
Last EDR Contact: 05/20/2013
Next Scheduled EDR Contact: 08/19/2013
Data Release Frequency: Varies

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data

Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 02/18/2013
Date Data Arrived at EDR: 02/18/2013
Date Made Active in Reports: 03/21/2013
Number of Days to Update: 31

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 05/21/2013
Next Scheduled EDR Contact: 09/02/2013
Data Release Frequency: Annually

NJ MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2011
Date Data Arrived at EDR: 07/19/2012
Date Made Active in Reports: 08/28/2012
Number of Days to Update: 40

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 04/19/2013
Next Scheduled EDR Contact: 07/29/2013
Data Release Frequency: Annually

NY MANIFEST: Facility and Manifest Data
Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 02/01/2013
Date Data Arrived at EDR: 02/07/2013
Date Made Active in Reports: 03/15/2013
Number of Days to Update: 36

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 05/09/2013
Next Scheduled EDR Contact: 08/19/2013
Data Release Frequency: Annually

PA MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2011
Date Data Arrived at EDR: 07/23/2012
Date Made Active in Reports: 09/18/2012
Number of Days to Update: 57

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 04/23/2013
Next Scheduled EDR Contact: 08/05/2013
Data Release Frequency: Annually

RI MANIFEST: Manifest information
Hazardous waste manifest information

Date of Government Version: 12/31/2011
Date Data Arrived at EDR: 06/22/2012
Date Made Active in Reports: 07/31/2012
Number of Days to Update: 39

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 05/28/2013
Next Scheduled EDR Contact: 09/09/2013
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2011
Date Data Arrived at EDR: 07/19/2012
Date Made Active in Reports: 09/27/2012
Number of Days to Update: 70

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 06/14/2013
Next Scheduled EDR Contact: 09/30/2013
Data Release Frequency: Annually

Oil/Gas Pipelines: This data was obtained by EDR from the USGS in 1994. It is referred to by USGS as GeoData Digital Line Graphs from 1:100,000-Scale Maps. It was extracted from the transportation category including some oil, but primarily gas pipelines.

Electric Power Transmission Line Data
Source: Rextag Strategies Corp.
Telephone: (281) 769-2247
U.S. Electric Transmission and Power Plants Systems Digital GIS Data

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Licensed Facilities
Source: Department of Social Services
Telephone: 916-657-4041

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 2003 & 2011 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002 and 2005 from the U.S. Fish and Wildlife Service.

Scanned Digital USGS 7.5' Topographic Map (DRG)
Source: United States Geologic Survey
A digital raster graphic (DRG) is a scanned image of a U.S. Geological Survey topographic map. The map images are made by scanning published paper maps on high-resolution scanners. The raster image is georeferenced and fit to the Universal Transverse Mercator (UTM) projection.

STREET AND ADDRESS INFORMATION

© 2010 Tele Atlas North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

COLTONS HUB CITY CENTRE
EUCALYPTUS AVENUE/VALLEY BOULEVARD
COLTON, CA 92324

TARGET PROPERTY COORDINATES

Latitude (North):	34.0724 - 34° 4' 20.64''
Longitude (West):	117.3571 - 117° 21' 25.56''
Universal Tranverse Mercator:	Zone 11
UTM X (Meters):	467049.8
UTM Y (Meters):	3770046.5
Elevation:	1081 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	34117-A3 SAN BERNARDINO SOUTH, CA
Most Recent Revision:	1980

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principal investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).

TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General South

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Target Property County	FEMA Flood Electronic Data
SAN BERNARDINO, CA	YES - refer to the Overview Map and Detail Map

Flood Plain Panel at Target Property: 06071C - FEMA DFIRM Flood data

Additional Panels in search area: Not Reported

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
NOT AVAILABLE	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius:	1.25 miles
Status:	Not found

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
11	1/2 - 1 Mile West	SE

For additional site information, refer to Physical Setting Source Map Findings.

* ©1996 Site−specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT

Era:	Cenozoic
System:	Quaternary
Series:	Quaternary
Code:	Q *(decoded above as Era, System & Series)*

GEOLOGIC AGE IDENTIFICATION

Category: Stratifed Sequence

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

SSURGO SOIL MAP - 3639401.1s



Target Property
SSURGO Soil
Water

0 1/16 1/8 1/4 Miles

N

SITE NAME:	Coltons Hub City Centre	CLIENT:	The Altum Group
ADDRESS:	Eucalyptus Avenue/Valley Boulevard Colton CA 92324	CONTACT:	Cheri Flores
LAT/LONG:	34.0724 / 117.3571	INQUIRY #:	3639401.1s
		DATE:	June 17, 2013 5:58 pm

Copyright © 2013 EDR, Inc. © 2010 Tele Atlas Rel. 07/2009.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. The following information is based on Soil Conservation Service SSURGO data.

Soil Map ID: 1

Soil Component Name: DELHI

Soil Surface Texture: fine sand

Hydrologic Group: Class A - High infiltration rates. Soils are deep, well drained to excessively drained sands and gravels.

Soil Drainage Class: Somewhat excessively drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Moderate

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	18 inches	fine sand	Granular materials (35 pct. or less passing No. 200), Silty, or Clayey Gravel and Sand.	COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 141 Min: 42	Max: 7.8 Min: 6.1
2	18 inches	59 inches	sand	Granular materials (35 pct. or less passing No. 200), Silty, or Clayey Gravel and Sand.	COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 141 Min: 42	Max: 7.8 Min: 6.1

Soil Map ID: 2

Soil Component Name: Water

Soil Surface Texture: fine sand

Hydrologic Group: Class A - High infiltration rates. Soils are deep, well drained to excessively drained sands and gravels.

Soil Drainage Class:

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

No Layer Information available.

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 1 mile
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
2	USGS40000140580	1/4 - 1/2 Mile East
A3	USGS40000140548	1/2 - 1 Mile East
4	USGS40000140507	1/2 - 1 Mile WSW
5	USGS40000140645	1/2 - 1 Mile WNW
B6	USGS40000140697	1/2 - 1 Mile NE
B7	USGS40000140710	1/2 - 1 Mile NE
D12	USGS40000140375	1/2 - 1 Mile SE
D13	USGS40000140376	1/2 - 1 Mile SE
D15	USGS40000140369	1/2 - 1 Mile SE
D16	USGS40000140358	1/2 - 1 Mile SE
D17	USGS40000140357	1/2 - 1 Mile SE

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP

No PWS System Found

Note: PWS System location is not always the same as well location.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
A1	CADW50000004191	1/4 - 1/2 Mile ESE
B8	3139	1/2 - 1 Mile NE
C9	1005	1/2 - 1 Mile WSW
C10	1006	1/2 - 1 Mile WSW
14	969	1/2 - 1 Mile SE
18	995	1/2 - 1 Mile NW

OTHER STATE DATABASE INFORMATION

STATE OIL/GAS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
1	CAOG9A000033735	1/2 - 1 Mile ENE
2	CAOG9A000032046	1/2 - 1 Mile South

PHYSICAL SETTING SOURCE MAP - 3639401.1s



- County Boundary
- Major Roads
- Contour Lines
- Earthquake Fault Lines
- Airports
- Earthquake epicenter, Richter 5 or greater
- Water Wells
- Public Water Supply Wells
- Cluster of Multiple Icons
- Groundwater Flow Direction
- GI Indeterminate Groundwater Flow at Location
- GV Groundwater Flow Varies at Location
- HD Closest Hydrogeological Data
- Oil, gas or related wells

SITE NAME:	Coltons Hub City Centre	CLIENT:	The Altum Group
ADDRESS:	Eucalyptus Avenue/Valley Boulevard Colton CA 92324	CONTACT:	Cheri Flores
LAT/LONG:	34.0724 / 117.3571	INQUIRY #:	3639401.1s
		DATE:	June 17, 2013 5:58 pm

Copyright © 2013 EDR, Inc. © 2010 Tele Atlas Rel. 07/2009.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

	Database	EDR ID Number
A1		
ESE	**CA WELLS**	**CADW50000004191**
1/4 - 1/2 Mile		
Lower		

Latitude :	34.0711		
Longitude :	117.3493		
Site code:	340711N1173493W001	Casgem sta:	01S04W19E001S
Local well:	Not Reported	Casgem s 1:	Unknown
County id:	36		
Basin cd:	8-2.03	Basin desc:	Riverside-Arlington
Org unit n:	Southern Region Office	Site id:	CADW50000004191

2		
East	**FED USGS**	**USGS40000140580**
1/4 - 1/2 Mile		
Lower		

Org. Identifier:	USGS-CA		
Formal name:	USGS California Water Science Center		
Monloc Identifier:	USGS-340423117205301		
Monloc name:	001S005W24H002S		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	18070203	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	34.073068
Longitude:	-117.3489337	Sourcemap scale:	24000
Horiz Acc measure:	5	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	1050
Vert measure units:	feet	Vertacc measure val:	20
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	California Coastal Basin aquifers		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	19970422	Welldepth:	700
Welldepth units:	ft	Wellholedepth:	712
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 16

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
2004-10-21	190.78		2004-04-20	187.88	
2003-10-21	184.06		2003-04-22	181.40	
2002-10-29	181.02		2002-04-10	178.70	
2001-10-24	178.85		2001-04-17	176.70	
2000-10-25	175.55		2000-04-18	173.60	
1999-10-19	173.66		1999-04-14	170.59	
1999-04-13					
Note: The site was being pumped.					
1998-10-20	172.38		1998-07-15	172.4	
1997-06-19	175				

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

A3
East
1/2 - 1 Mile
Lower | **FED USGS** | **USGS40000140548**

Org. Identifier:	USGS-CA		
Formal name:	USGS California Water Science Center		
Monloc Identifier:	USGS-340416117205101		
Monloc name:	001S004W19E001S		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	18070203	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	34.0711237
Longitude:	-117.348378	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	1038.90
Vert measure units:	feet	Vertacc measure val:	.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	California Coastal Basin aquifers		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	19640227	Welldepth:	222
Welldepth units:	ft	Wellholedepth:	251
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 91

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1998-04-07					
Note: The well was destroyed (no water level is recorded).					
1997-10-29	162.83		1997-04-15	158.63	
1996-10-09	158.51		1996-04-25	153.60	
1995-10-23	155.10		1995-04-19	154.84	
1994-10-24	157.07		1994-04-19	156.72	
1993-10-18	159.25		1993-04-14	161.81	
1992-10-27	164.15		1992-06-17	162.35	
1991-11-27	163.15		1991-06-24	158.87	
1990-11-28	161.07		1990-06-28	156.87	
1989-11-27	156.52		1989-09-21	155.71	
1988-11-28	151.55		1988-06-29	151.82	
1988-04-12	150.91				
1987-06-18	150.31				
Note: Other conditions existed that would affect the measured water level.					
1987-05-01	149.62				
1986-11-20	149.40				
Note: Other conditions existed that would affect the measured water level.					
1986-09-15	149.58		1986-06-20	148.61	
1986-05-15	148.38				
1985-09-18	149.58				
Note: Other conditions existed that would affect the measured water level.					
1985-05-10	149.85		1984-09-21	150.21	
1984-04-11	149.85		1983-11-30	151.67	

Ground-water levels, continued.

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1983-07-27	152.74		1982-09-15	155.21	
1981-11-20	155.67		1981-10-22	155.87	
1981-09-16	156.32		1981-08-19	158.05	
1981-08-13	156.77		1981-07-22	156.92	
1981-06-11	157.68		1981-05-15	157.74	
1981-04-16	157.87		1981-03-12	158.04	
1981-02-20	158.90		1981-01-15	159.38	
1980-12-19	159.95		1980-12-04	161.28	
1980-11-21	160.59		1980-10-22	160.98	
1980-09-18	161.47		1980-08-14	162.79	
1980-07-23	165.27		1980-06-13	163.57	
1980-06-12	163.92		1980-05-16	166.20	
1980-04-16	168.32		1980-03-14	166.57	
1980-02-13	158.43		1980-01-18	165.87	
1979-12-12	166.22		1979-09-14	167.49	
1979-07-12	167.32		1979-07-06	167.49	
1979-06-14	168.12		1979-05-17	172.42	
1979-03-15	169.82		1979-02-20	169.97	
1979-01-18	170.37		1978-12-15	171.67	
1978-11-16	172.07		1978-08-11	173.88	
1978-07-14	184.73		1978-01-14	182.53	
1977-12-15	182.89		1977-11-15	182.40	
1977-10-11	181.54		1977-09-21	180.13	
1977-08-26	179.19		1977-07-07	179.37	
1970-03-30	173.34		1969-11-20	175.84	
1969-04-28	187.94		1969-01-02	193.94	
1968-05-25	190.44		1967-11-30	192.14	
1964-04-09	189.43		1964-03-16	189.60	
1964-03-04	189.79		1964-03-02	189.82	

4
WSW **FED USGS** **USGS40000140507**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-CA		
Formal name:	USGS California Water Science Center		
Monloc Identifier:	USGS-340411117215301		
Monloc name:	001S005W24M001S		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	18070203	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	34.0697347
Longitude:	-117.3656009	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	Not Reported
Vert measure units:	Not Reported	Vertacc measure val:	Not Reported
Vert accmeasure units:	Not Reported		
Vertcollection method:	Not Reported		
Vert coord refsys:	Not Reported	Countrycode:	US
Aquifername:	California Coastal Basin aquifers		
Formation type:	Not Reported		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	342
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

5
WNW **FED USGS** **USGS40000140645**
1/2 - 1 Mile
Higher

Org. Identifier:	USGS-CA		
Formal name:	USGS California Water Science Center		
Monloc Identifier:	USGS-340433117215801		
Monloc name:	001S005W23A001S		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	34.0758056
Longitude:	-117.3661667	Sourcemap scale:	Not Reported
Horiz Acc measure:	.5	Horiz Acc measure units:	seconds
Horiz Collection method:	Global positioning system (GPS), uncorrected		
Horiz coord refsys:	NAD83	Vert measure val:	Not Reported
Vert measure units:	Not Reported	Vertacc measure val:	Not Reported
Vert accmeasure units:	Not Reported		
Vertcollection method:	Not Reported		
Vert coord refsys:	Not Reported	Countrycode:	US
Aquifername:	California Coastal Basin aquifers		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

B6
NE **FED USGS** **USGS40000140697**
1/2 - 1 Mile
Higher

Org. Identifier:	USGS-CA		
Formal name:	USGS California Water Science Center		
Monloc Identifier:	USGS-340441117205001		
Monloc name:	001S004W18N001S		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	18070203	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	34.0780679
Longitude:	-117.3481004	Sourcemap scale:	Not Reported
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	1085.00
Vert measure units:	feet	Vertacc measure val:	10
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	California Coastal Basin aquifers		
Formation type:	Not Reported		

Aquifer type:	Not Reported		
Construction date:	19430101	Welldepth:	600
Welldepth units:	ft	Wellholedepth:	4015
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

B7
NE
1/2 - 1 Mile
Higher

FED USGS **USGS40000140710**

Org. Identifier:	USGS-CA		
Formal name:	USGS California Water Science Center		
Monloc Identifier:	USGS-340444117205401		
Monloc name:	001S004W18N003S		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	34.0787222
Longitude:	-117.348361	Sourcemap scale:	24000
Horiz Acc measure:	.5	Horiz Acc measure units:	seconds
Horiz Collection method:	Global positioning system (GPS), uncorrected		
Horiz coord refsys:	NAD83	Vert measure val:	1090
Vert measure units:	feet	Vertacc measure val:	10
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	California Coastal Basin aquifers		
Formation type:	Cenozoic Erathem		
Aquifer type:	Unconfined single aquifer		
Construction date:	19940214	Welldepth:	644
Welldepth units:	ft	Wellholedepth:	706
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 2

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
2004-05-04	197		2000-05	197	

B8
NE
1/2 - 1 Mile
Higher

CA WELLS **3139**

Water System Information:

Prime Station Code:	036/014-002	User ID:	TAN
FRDS Number:	3610014021	County:	San Beernardino
District Number:	13	Station Type:	WELL/AMBNT
Water Type:	Well/Groundwater	Well Status:	Active Raw
Source Lat/Long:	340444.0 1172050.0	Precision:	1,000 Feet (10 Seconds)
Source Name:	WELL 24		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

System Number: 3610014
System Name: CITY OF COLTON
Organization That Operates System:
650 N LA CADENA DR
COLTON, CA 92324
Pop Served: 42103 Connections: 8604
Area Served: CITY OF COLTON

Sample Collected:	01/20/2011	Findings:	26. MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	01/20/2011	Findings:	4.5 UG/L
Chemical:	PERCHLORATE		
Sample Collected:	04/12/2011	Findings:	25. MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	04/12/2011	Findings:	5.3 UG/L
Chemical:	PERCHLORATE		
Sample Collected:	07/13/2011	Findings:	23. MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	08/17/2011	Findings:	21.667 C
Chemical:	SOURCE TEMPERATURE C		
Sample Collected:	08/17/2011	Findings:	410. US
Chemical:	SPECIFIC CONDUCTANCE		
Sample Collected:	08/17/2011	Findings:	7.8
Chemical:	PH, LABORATORY		
Sample Collected:	08/17/2011	Findings:	150. MG/L
Chemical:	ALKALINITY (TOTAL) AS CACO3		
Sample Collected:	08/17/2011	Findings:	190. MG/L
Chemical:	BICARBONATE ALKALINITY		
Sample Collected:	08/17/2011	Findings:	180. MG/L
Chemical:	HARDNESS (TOTAL) AS CACO3		
Sample Collected:	08/17/2011	Findings:	65. MG/L
Chemical:	CALCIUM		
Sample Collected:	08/17/2011	Findings:	6.5 MG/L
Chemical:	MAGNESIUM		
Sample Collected:	08/17/2011	Findings:	13. MG/L
Chemical:	SODIUM		
Sample Collected:	08/17/2011	Findings:	2. MG/L
Chemical:	POTASSIUM		
Sample Collected:	08/17/2011	Findings:	7.8 MG/L
Chemical:	CHLORIDE		
Sample Collected:	08/17/2011	Findings:	0.26 MG/L
Chemical:	FLUORIDE (F) (NATURAL-SOURCE)		
Sample Collected:	08/17/2011	Findings:	5.9 UG/L
Chemical:	VANADIUM		
Sample Collected:	08/17/2011	Findings:	260. MG/L
Chemical:	TOTAL DISSOLVED SOLIDS		

Sample Collected:	08/17/2011	Findings:	0.99
Chemical:	LANGELIER INDEX @ 60 C		
Sample Collected:	08/17/2011	Findings:	0.41
Chemical:	LANGELIER INDEX AT SOURCE TEMP.		
Sample Collected:	08/17/2011	Findings:	24. MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	08/17/2011	Findings:	0.4 NTU
Chemical:	TURBIDITY, LABORATORY		
Sample Collected:	08/17/2011	Findings:	12.2
Chemical:	AGGRSSIVE INDEX (CORROSIVITY)		
Sample Collected:	08/17/2011	Findings:	5400. UG/L
Chemical:	NITRATE + NITRITE (AS N)		
Sample Collected:	08/17/2011	Findings:	4.5 UG/L
Chemical:	PERCHLORATE		
Sample Collected:	10/18/2011	Findings:	24. MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	02/01/2012	Findings:	25. MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	05/10/2012	Findings:	22. MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	07/12/2012	Findings:	24. MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	07/12/2012	Findings:	4.2 UG/L
Chemical:	PERCHLORATE		
Sample Collected:	08/30/2012	Findings:	400. US
Chemical:	SPECIFIC CONDUCTANCE		
Sample Collected:	08/30/2012	Findings:	7.9
Chemical:	PH, LABORATORY		
Sample Collected:	08/30/2012	Findings:	150. MG/L
Chemical:	ALKALINITY (TOTAL) AS CACO3		
Sample Collected:	08/30/2012	Findings:	190. MG/L
Chemical:	BICARBONATE ALKALINITY		
Sample Collected:	08/30/2012	Findings:	190. MG/L
Chemical:	HARDNESS (TOTAL) AS CACO3		
Sample Collected:	08/30/2012	Findings:	64. MG/L
Chemical:	CALCIUM		
Sample Collected:	08/30/2012	Findings:	7.3 MG/L
Chemical:	MAGNESIUM		
Sample Collected:	08/30/2012	Findings:	14. MG/L
Chemical:	SODIUM		
Sample Collected:	08/30/2012	Findings:	2.1 MG/L
Chemical:	POTASSIUM		
Sample Collected:	08/30/2012	Findings:	8.7 MG/L
Chemical:	CHLORIDE		

Sample Collected:	08/30/2012	Findings:	0.35 MG/L
Chemical:	FLUORIDE (F) (NATURAL-SOURCE)		
Sample Collected:	08/30/2012	Findings:	260. MG/L
Chemical:	TOTAL DISSOLVED SOLIDS		
Sample Collected:	08/30/2012	Findings:	24. MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	11/08/2012	Findings:	27. MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	11/08/2012	Findings:	4.6 UG/L
Chemical:	PERCHLORATE		

C9
WSW
1/2 - 1 Mile
Lower

CA WELLS **1005**

Water System Information:

Prime Station Code:	01S/05W-23Q01 S	User ID:	TAN
FRDS Number:	3610004023	County:	San Beernardino
District Number:	13	Station Type:	WELL/AMBNT/MUN/INTAKE/SUPPLY
Water Type:	Well/Groundwater	Well Status:	Active Raw
Source Lat/Long:	340400.0 1172200.0	Precision:	Undefined
Source Name:	WELL 29		
System Number:	3610004		
System Name:	WEST SAN BERNARDINO CWD		
Organization That Operates System:			
	PO BOX 920		
	RIALTO, CA 92376-0920		
Pop Served:	41454	Connections:	15052
Area Served:	RIALTO-BLOOMINGTON		

C10
WSW
1/2 - 1 Mile
Lower

CA WELLS **1006**

Water System Information:

Prime Station Code:	01S/05W-24M01 S	User ID:	TAN
FRDS Number:	3610004013	County:	San Beernardino
District Number:	13	Station Type:	WELL/AMBNT/MUN/INTAKE/SUPPLY
Water Type:	Well/Groundwater	Well Status:	Destroyed
Source Lat/Long:	340400.0 1172200.0	Precision:	Undefined
Source Name:	WELL 18 - DESTROYED		
System Number:	3610004		
System Name:	WEST SAN BERNARDINO CWD		
Organization That Operates System:			
	PO BOX 920		
	RIALTO, CA 92376-0920		
Pop Served:	41454	Connections:	15052
Area Served:	RIALTO-BLOOMINGTON		

11
West
1/2 - 1 Mile
Lower

Site ID:	083303059T
Groundwater Flow:	SE
Shallow Water Depth:	Not Reported
Deep Water Depth:	Not Reported
Average Water Depth:	30 ft
Date:	05/21/1999

AQUIFLOW **51030**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

D12
SE
1/2 - 1 Mile
Lower

FED USGS **USGS40000140375**

Org. Identifier:	USGS-CA		
Formal name:	USGS California Water Science Center		
Monloc Identifier:	USGS-340344117205101		
Monloc name:	001S004W30D006S		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	18070203	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	34.0622351
Longitude:	-117.348378	Sourcemap scale:	Not Reported
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	995.00
Vert measure units:	feet	Vertacc measure val:	10
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	California Coastal Basin aquifers		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	19470101	Welldepth:	215
Welldepth units:	ft	Wellholedepth:	300
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

D13
SE
1/2 - 1 Mile
Lower

FED USGS **USGS40000140376**

Org. Identifier:	USGS-CA		
Formal name:	USGS California Water Science Center		
Monloc Identifier:	USGS-340344117205102		
Monloc name:	001S004W30D007S		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	18070203	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	34.0622351
Longitude:	-117.348378	Sourcemap scale:	Not Reported
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	1000.00
Vert measure units:	feet	Vertacc measure val:	10
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	California Coastal Basin aquifers		
Formation type:	Not Reported		

Aquifer type:	Not Reported		
Construction date:	19550101	Welldepth:	189
Welldepth units:	ft	Wellholedepth:	232
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

14
SE **CA WELLS** **969**
1/2 - 1 Mile
Lower

Water System Information:

Prime Station Code:	01S/04W-30D06 S	User ID:	36C
FRDS Number:	3600793001	County:	San Beernardino
District Number:	66	Station Type:	WELL/AMBNT/MUN/INTAKE
Water Type:	Well/Groundwater	Well Status:	Active Raw
Source Lat/Long:	340345.0 1172045.0	Precision:	100 Feet (one Second)
Source Name:	WELL 05		
System Number:	3600793		
System Name:	CA PORTLAND CEMENT		
Organization That Operates System:			
	2025 E FINANCIAL WAY		
	GLENDORA, CA 91740		
Pop Served:	25	Connections:	1
Area Served:	Not Reported		

D15
SE **FED USGS** **USGS40000140369**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-CA		
Formal name:	USGS California Water Science Center		
Monloc Identifier:	USGS-340343117204701		
Monloc name:	001S004W30D004S		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	18070203	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	34.0619573
Longitude:	-117.3472669	Sourcemap scale:	Not Reported
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	988.00
Vert measure units:	feet	Vertacc measure val:	10
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	California Coastal Basin aquifers		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	19450101	Welldepth:	215
Welldepth units:	ft	Wellholedepth:	300
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

D16
SE
1/2 - 1 Mile
Lower

FED USGS **USGS40000140358**

Org. Identifier:	USGS-CA		
Formal name:	USGS California Water Science Center		
Monloc Identifier:	USGS-340341117205001		
Monloc name:	001S004W30D002S		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	18070203	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	34.0614018
Longitude:	-117.3481002	Sourcemap scale:	Not Reported
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	985.00
Vert measure units:	feet	Vertacc measure val:	10
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	California Coastal Basin aquifers		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	150
Welldepth units:	ft	Wellholedepth:	150
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

D17
SE
1/2 - 1 Mile
Lower

FED USGS **USGS40000140357**

Org. Identifier:	USGS-CA		
Formal name:	USGS California Water Science Center		
Monloc Identifier:	USGS-340341117204801		
Monloc name:	001S004W30D003S		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	18070203	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	34.0614018
Longitude:	-117.3475447	Sourcemap scale:	Not Reported
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	987.00
Vert measure units:	feet	Vertacc measure val:	10
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	California Coastal Basin aquifers		
Formation type:	Not Reported		

Aquifer type:	Not Reported		
Construction date:	19370101	Welldepth:	396
Welldepth units:	ft	Wellholedepth:	396
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

18
NW
1/2 - 1 Mile
Higher

CA WELLS **995**

Water System Information:

Prime Station Code:	01S/05W-12N01 S	User ID:	TAN
FRDS Number:	3610004012	County:	San Beernardino
District Number:	13	Station Type:	WELL/AMBNT/MUN/INTAKE/SUPPLY
Water Type:	Well/Groundwater	Well Status:	Active Raw
Source Lat/Long:	340500.0 1172200.0	Precision:	Undefined
Source Name:	WELL 17		
System Number:	3610004		
System Name:	WEST SAN BERNARDINO CWD		
Organization That Operates System:			
	PO BOX 920		
	RIALTO, CA 92376-0920		
Pop Served:	41454	Connections:	15052
Area Served:	RIALTO-BLOOMINGTON		
Sample Collected:	03/07/2011	Findings:	5. UNITS
Chemical:	COLOR		
Sample Collected:	03/07/2011	Findings:	1.3 PCI/L
Chemical:	GROSS ALPHA COUNTING ERROR		
Sample Collected:	03/07/2011	Findings:	3.9 PCI/L
Chemical:	URANIUM (PCI/L)		
Sample Collected:	03/07/2011	Findings:	0.53 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	03/07/2011	Findings:	30. MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	03/07/2011	Findings:	4.1 NTU
Chemical:	TURBIDITY, LABORATORY		
Sample Collected:	03/07/2011	Findings:	0.8 PCI/L
Chemical:	URANIUM COUNTING ERROR		
Sample Collected:	03/07/2011	Findings:	1.2 PCI/L
Chemical:	GROSS ALPHA MDA95		
Sample Collected:	03/07/2011	Findings:	0.87 PCI/L
Chemical:	URANIUM MDA95		
Sample Collected:	03/07/2011	Findings:	0.855 PCI/L
Chemical:	RADIUM 228 COUNTING ERROR		
Sample Collected:	03/07/2011	Findings:	0.295 PCI/L
Chemical:	RADIUM 228 MDA95		

Sample Collected:	03/07/2011	Findings:	0.169 PCI/L
Chemical:	RA-226 OR TOTAL RA BY 903.0 C.E.		
Sample Collected:	03/07/2011	Findings:	0.412 PCI/L
Chemical:	RADIUM, TOTAL, MDA95-NTNC ONLY, BY 903.0		
Sample Collected:	07/21/2011	Findings:	20. C
Chemical:	SOURCE TEMPERATURE C		
Sample Collected:	07/21/2011	Findings:	420. US
Chemical:	SPECIFIC CONDUCTANCE		
Sample Collected:	07/21/2011	Findings:	7.6
Chemical:	PH, LABORATORY		
Sample Collected:	07/21/2011	Findings:	150. MG/L
Chemical:	ALKALINITY (TOTAL) AS CACO3		
Sample Collected:	07/21/2011	Findings:	180. MG/L
Chemical:	BICARBONATE ALKALINITY		
Sample Collected:	07/21/2011	Findings:	190. MG/L
Chemical:	HARDNESS (TOTAL) AS CACO3		
Sample Collected:	07/21/2011	Findings:	70. MG/L
Chemical:	CALCIUM		
Sample Collected:	07/21/2011	Findings:	6.7 MG/L
Chemical:	MAGNESIUM		
Sample Collected:	07/21/2011	Findings:	13. MG/L
Chemical:	SODIUM		
Sample Collected:	07/21/2011	Findings:	2.2 MG/L
Chemical:	POTASSIUM		
Sample Collected:	07/21/2011	Findings:	8.4 MG/L
Chemical:	CHLORIDE		
Sample Collected:	07/21/2011	Findings:	0.31 MG/L
Chemical:	FLUORIDE (F) (NATURAL-SOURCE)		
Sample Collected:	07/21/2011	Findings:	5.8 UG/L
Chemical:	VANADIUM		
Sample Collected:	07/21/2011	Findings:	0.54 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	07/21/2011	Findings:	260. MG/L
Chemical:	TOTAL DISSOLVED SOLIDS		
Sample Collected:	07/21/2011	Findings:	0.82
Chemical:	LANGELIER INDEX @ 60 C		
Sample Collected:	07/21/2011	Findings:	0.21
Chemical:	LANGELIER INDEX AT SOURCE TEMP.		
Sample Collected:	07/21/2011	Findings:	32. MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	07/21/2011	Findings:	0.6 NTU
Chemical:	TURBIDITY, LABORATORY		
Sample Collected:	07/21/2011	Findings:	12.02
Chemical:	AGGRSSIVE INDEX (CORROSIVITY)		

Sample Collected:	07/21/2011	Findings:	7200. UG/L
Chemical:	NITRATE + NITRITE (AS N)		
Sample Collected:	07/21/2011	Findings:	0.428 PCI/L
Chemical:	RADIUM 228 COUNTING ERROR		
Sample Collected:	07/21/2011	Findings:	0.201 PCI/L
Chemical:	RADIUM 228 MDA95		
Sample Collected:	07/21/2011	Findings:	0.435 PCI/L
Chemical:	RA-226 FOR CWS OR TOTAL RA FOR NTNC BY 903.0		
Sample Collected:	07/21/2011	Findings:	0.449 PCI/L
Chemical:	RA-226 OR TOTAL RA BY 903.0 C.E.		
Sample Collected:	07/21/2011	Findings:	0.659 PCI/L
Chemical:	RADIUM, TOTAL, MDA95-NTNC ONLY, BY 903.0		
Sample Collected:	09/28/2011	Findings:	1.4 PCI/L
Chemical:	GROSS ALPHA COUNTING ERROR		
Sample Collected:	09/28/2011	Findings:	3.7 PCI/L
Chemical:	URANIUM (PCI/L)		
Sample Collected:	09/28/2011	Findings:	0.62 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	09/28/2011	Findings:	30. MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	09/28/2011	Findings:	0.88 PCI/L
Chemical:	URANIUM COUNTING ERROR		
Sample Collected:	09/28/2011	Findings:	1.4 PCI/L
Chemical:	GROSS ALPHA MDA95		
Sample Collected:	09/28/2011	Findings:	0.88 PCI/L
Chemical:	URANIUM MDA95		
Sample Collected:	09/28/2011	Findings:	0.62 PCI/L
Chemical:	RADIUM 228 COUNTING ERROR		
Sample Collected:	09/28/2011	Findings:	0.396 PCI/L
Chemical:	RADIUM 228 MDA95		
Sample Collected:	09/28/2011	Findings:	0.423 PCI/L
Chemical:	RA-226 FOR CWS OR TOTAL RA FOR NTNC BY 903.0		
Sample Collected:	09/28/2011	Findings:	0.498 PCI/L
Chemical:	RA-226 OR TOTAL RA BY 903.0 C.E.		
Sample Collected:	09/28/2011	Findings:	0.702 PCI/L
Chemical:	RADIUM, TOTAL, MDA95-NTNC ONLY, BY 903.0		
Sample Collected:	12/15/2011	Findings:	4.1 PCI/L
Chemical:	GROSS ALPHA		
Sample Collected:	12/15/2011	Findings:	1.5 PCI/L
Chemical:	GROSS ALPHA COUNTING ERROR		
Sample Collected:	12/15/2011	Findings:	4.4 PCI/L
Chemical:	URANIUM (PCI/L)		
Sample Collected:	12/15/2011	Findings:	0.54 UG/L
Chemical:	TETRACHLOROETHYLENE		

Sample Collected:	12/15/2011	Findings:	30. MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	12/15/2011	Findings:	0.92 PCI/L
Chemical:	URANIUM COUNTING ERROR		
Sample Collected:	12/15/2011	Findings:	1.2 PCI/L
Chemical:	GROSS ALPHA MDA95		
Sample Collected:	12/15/2011	Findings:	0.88 PCI/L
Chemical:	URANIUM MDA95		
Sample Collected:	12/15/2011	Findings:	0.455 PCI/L
Chemical:	RADIUM 228 COUNTING ERROR		
Sample Collected:	12/15/2011	Findings:	0.205 PCI/L
Chemical:	RADIUM 228 MDA95		
Sample Collected:	12/15/2011	Findings:	0.197 PCI/L
Chemical:	RA-226 OR TOTAL RA BY 903.0 C.E.		
Sample Collected:	12/15/2011	Findings:	0.439 PCI/L
Chemical:	RADIUM, TOTAL, MDA95-NTNC ONLY, BY 903.0		
Sample Collected:	03/06/2012	Findings:	0.62 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	03/06/2012	Findings:	29. MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	04/10/2012	Findings:	0.55 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	06/13/2012	Findings:	0.57 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	06/13/2012	Findings:	30. MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	09/26/2012	Findings:	0.65 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	09/26/2012	Findings:	29. MG/L
Chemical:	NITRATE (AS NO3)		
Sample Collected:	12/13/2012	Findings:	0.53 UG/L
Chemical:	TETRACHLOROETHYLENE		
Sample Collected:	12/13/2012	Findings:	29. MG/L
Chemical:	NITRATE (AS NO3)		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance

Database EDR ID Number

1
ENE
1/2 - 1 Mile

OIL_GAS **CAOG9A000033735**

Districtnu:	1	Apinumber:	07100048
Blmwell:	N	Redrillcan:	Not Reported
Dryhole:	N	Wellstatus:	P
Operatorna:	R. A. Dean & Assoc.		
Countyname:	San Bernardino	Fieldname:	Any Field
Areaname:	Any Area		
Section:	18		
Township:	01S	Range:	04W
Basemeridi:	SB	Elevation:	Not Reported
Locationde:	Not Reported		
Glat:	34.079142		
Glong:	-117.344938		
Gissourcec:	hud		
Comments:	Not Reported		
Leasename:	Higgs	Wellnumber:	1
Epawell:	N	Hydraulica:	N
Confidenti:	N	Spuddate:	12/30/1899
Welldeptha:	Not Reported	Redrillfoo:	Not Reported
Abandonedd:	/ /	Completion:	/ /
Gissymbol:	PDH	Site id:	CAOG9A000033735

2
South
1/2 - 1 Mile

OIL_GAS **CAOG9A000032046**

Districtnu:	1	Apinumber:	07100042
Blmwell:	N	Redrillcan:	Not Reported
Dryhole:	N	Wellstatus:	I
Operatorna:	Colton Terrace Oil Co.		
Countyname:	San Bernardino	Fieldname:	Any Field
Areaname:	Any Area		
Section:	25		
Township:	01S	Range:	05W
Basemeridi:	SB	Elevation:	Not Reported
Locationde:	Not Reported		
Glat:	34.060038		
Glong:	-117.357685		
Gissourcec:	hud		
Comments:	Not Reported		
Leasename:	Not Reported	Wellnumber:	1
Epawell:	N	Hydraulica:	N
Confidenti:	N	Spuddate:	12/30/1899
Welldeptha:	Not Reported	Redrillfoo:	Not Reported
Abandonedd:	/ /	Completion:	/ /
Gissymbol:	AOG	Site id:	CAOG9A000032046

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

State Database: CA Radon

Radon Test Results

Zipcode	Num Tests	> 4 pCi/L
92324	10	0

Federal EPA Radon Zone for SAN BERNARDINO County: 2

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for Zip Code: 92324

Number of sites tested: 1

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area - 1st Floor	0.000 pCi/L	100%	0%	0%
Living Area - 2nd Floor	Not Reported	Not Reported	Not Reported	Not Reported
Basement	Not Reported	Not Reported	Not Reported	Not Reported

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Scanned Digital USGS 7.5' Topographic Map (DRG)
Source: United States Geologic Survey
A digital raster graphic (DRG) is a scanned image of a U.S. Geological Survey topographic map. The map images are made by scanning published paper maps on high-resolution scanners. The raster image is georeferenced and fit to the Universal Transverse Mercator (UTM) projection.

HYDROLOGIC INFORMATION

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 2003 & 2011 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002 and 2005 from the U.S. Fish and Wildlife Service.

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Services
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Services (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Services, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

Water Well Database
Source: Department of Water Resources
Telephone: 916-651-9648

California Drinking Water Quality Database
Source: Department of Health Services
Telephone: 916-324-2319
The database includes all drinking water compliance and special studies monitoring for the state of California since 1984. It consists of over 3,200,000 individual analyses along with well and water system information.

OTHER STATE DATABASE INFORMATION

California Oil and Gas Well Locations
Source: Department of Conservation
Telephone: 916-323-1779
Oil and Gas well locations in the state.

RADON

State Database: CA Radon
Source: Department of Health Services
Telephone: 916-324-2208
Radon Database for California

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

California Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary fault lines, prepared in 1975 by the United State Geological Survey. Additional information (also from 1975) regarding activity at specific fault lines comes from California's Preliminary Fault Activity Map prepared by the California Division of Mines and Geology.

STREET AND ADDRESS INFORMATION

© 2010 Tele Atlas North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.